





|   |                       |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                                |  |   |  |
|---|-----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------------------------|--|---|--|
| 2 | 福建省迎创<br>工程管理有<br>限公司 | 2024-<br>04-23<br>16:32<br>:16.0 | 2C-<br>F0-<br>5D-<br>2C-<br>26-<br>AD@BF<br>EBFBF<br>F0009<br>06EA@<br>W9AL2<br>ZWV,0<br>000_0<br>000_0<br>100_0<br>000_4<br>CEO_0<br>018_D<br>D8C_9<br>084. | 否 | 2024-<br>04-23<br>16:30<br>:49.0 | 2C-<br>F0-<br>5D-<br>2C-<br>26-<br>AD@BF<br>EBFBF<br>F0009<br>06EA@<br>W9AL2<br>ZWV,0<br>000_0<br>000_0<br>100_0<br>000_4<br>CEO_0<br>018_D<br>D8C_9<br>084. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>查<br>检 | 2024-<br>04-24<br>08:35<br>:14 | 2C-<br>F0-<br>5D-<br>2C-<br>26-<br>AD@BF<br>EBFBF<br>F0009<br>06EA@<br>W9AL2<br>ZWV,0<br>000_0<br>000_0<br>100_0<br>000_4<br>CEO_0<br>018_D<br>D8C_9<br>084. | 否 |  |
| 3 | 福建八方缘<br>建设有限公<br>司   | 2024-<br>04-23<br>16:28<br>:02.0 | 40-<br>8D-<br>5C-<br>7A-<br>EA-<br>32@BF<br>EBFBF<br>F0005<br>06E3@<br>TA166<br>01011<br>54,WD<br>-<br>WCC6Y<br>6NVSP<br>7J                                  | 否 | 2024-<br>04-23<br>16:25<br>:51.0 | 40-<br>8D-<br>5C-<br>7A-<br>EA-<br>32@BF<br>EBFBF<br>F0005<br>06E3@<br>TA166<br>01011<br>54,WD<br>-<br>WCC6Y<br>6NVSP<br>7J                                  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>查<br>检 | 2024-<br>04-24<br>08:33<br>:35 | 40-<br>8D-<br>5C-<br>7A-<br>EA-<br>32@BF<br>EBFBF<br>F0005<br>06E3@<br>TA166<br>01011<br>54,WD<br>-<br>WCC6Y<br>6NVSP<br>7J                                  | 否 |  |



|   |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                             |                                |   |   |  |
|---|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|-----------------------------|--------------------------------|---|---|--|
|   |                       |                                  | 0184,<br>58EY0<br>AEMS  |   |                                  | 0184,<br>58EY0<br>AEMS  |   |  |  |  |  |  |  |  |  |  |  |                             | 0184,<br>58EY0<br>AEMS         |   |   |  |
| 5 | 福建省启晟<br>建设发展有<br>限公司 | 2024-<br>04-23<br>15:23<br>:44.0 | A4-<br>AE-<br>12-<br>27-<br>73-<br>50, 2A<br>-39-<br>26-<br>E5-<br>72-<br>39, AA<br>-39-<br>26-<br>E9-<br>74-<br>3A, 28<br>-39-<br>26-<br>D7-<br>E7-<br>3B, 28<br>-39-<br>26-<br>D7-<br>E7-<br>3C@BF<br>EBFBF<br>F0009<br>06EB@<br>W9AJC<br>DFG | 否 | 2024-<br>04-23<br>15:18<br>:10.0 | A4-<br>AE-<br>12-<br>27-<br>73-<br>50, 2A<br>-39-<br>26-<br>E5-<br>72-<br>39, AA<br>-39-<br>26-<br>E9-<br>74-<br>3A, 28<br>-39-<br>26-<br>D7-<br>E7-<br>3B, 28<br>-39-<br>26-<br>D7-<br>E7-<br>3C@BF<br>EBFBF<br>F0009<br>06EB@<br>W9AJC<br>DFG | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>, 请<br>检查 | 2024-<br>04-24<br>08:36<br>:34 | A4-<br>AE-<br>12-<br>27-<br>73-<br>50, 2A<br>-39-<br>26-<br>E5-<br>72-<br>39, AA<br>-39-<br>26-<br>E9-<br>74-<br>3A, 28<br>-39-<br>26-<br>D7-<br>E7-<br>3B, 28<br>-39-<br>26-<br>D7-<br>E7-<br>3C@BF<br>EBFBF<br>F0009<br>06EB@<br>W9AJC<br>DFG | 否 |  |

|   |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|---|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 6 | 福建省湛鑫建设工程有限公司 | 2024-04-23 10:34:28.0 | 00-FF-E1-5C-C5-9A, 24-4B-FE-7C-15-46@BFEBFBFF000906EB@AA2021031397, 217HHXBFS | 否 | 2024-04-23 10:31:55.0 | 00-FF-E1-5C-C5-9A, 24-4B-FE-7C-15-46@BFEBFBFF000906EB@AA2021031397, 217HHXBFS | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:31:36 | 00-FF-E1-5C-C5-9A, 24-4B-FE-7C-15-46@BFEBFBFF000906EB@AA2021031397, 217HHXBFS | 否 |  |
| 7 | 福建锦实建设有限公司    | 2024-04-23 13:54:27.0 | E0-D5-5E-D5-B8-42@BFEBFBFF000906EA@WD-WCC6Y5YHY5ET, 201180803197              | 否 | 2024-04-23 13:52:30.0 | E0-D5-5E-D5-B8-42@BFEBFBFF000906EA@WD-WCC6Y5YHY5ET, 201180803197              | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:39:31 | E0-D5-5E-D5-B8-42@BFEBFBFF000906EA@WD-WCC6Y5YHY5ET, 201180803197              | 否 |  |



|    |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 10 | 福建中海勘察设计院有限公司 | 2024-04-23 16:53:54.0 | 40-B0-76-A2-5E-9B@BFEBFBFF000906E9@WD-WCC6Y4AD3TSD  | 否 | 2024-04-23 09:25:40.0 | 40-B0-76-A2-5E-9B@BFEBFBFF000906E9@WD-WCC6Y4AD3TSD  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:40 | 40-B0-76-A2-5E-9B@BFEBFBFF000906E9@WD-WCC6Y4AD3TSD  | 否 |  |
| 11 | 福建拓峻建设工程有限公司  | 2024-04-17 15:45:21.0 | D8-5E-D3-FC-1B-49@BFEBFBFF000A0653@YS202010000734AA | 否 | 2024-04-17 15:32:56.0 | D8-5E-D3-FC-1B-49@BFEBFBFF000A0653@YS202010000734AA | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:46:14 | D8-5E-D3-FC-1B-49@BFEBFBFF000A0653@YS202010000734AA | 否 |  |
| 12 | 福建省泽君建筑有限公司   | 2024-04-24 02:21:30.0 | 74-56-3C-EC-63-A6@BFEBFBFF000A0653@50026B738284D567 | 否 | 2024-04-23 22:23:48.0 | 74-56-3C-EC-63-A6@BFEBFBFF000A0653@50026B738284D567 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:10 | 74-56-3C-EC-63-A6@BFEBFBFF000A0653@50026B738284D567 | 否 |  |









|    |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |  |   |  |
|----|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|--|---|--|
| 17 | 福建闽筑建设工程有限公司 | 2024-04-23 12:20:22.0 | E0-D5-5E-FB-C7-80@BF EBFBF F0009 06EB@39313 6324a 46343 43036 31312 02020 20202 02020 | 否 | 2024-04-23 12:19:20.0 | E0-D5-5E-FB-C7-80,00 -00-00-00-00-00-00-00 E0,00 -00-00-00-00-00-00 E0@BF EBFBF F0009 06EB@39313 6324a 46343 43036 31312 02020 20202 02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:36:45 | E0-D5-5E-FB-C7-80@BF EBFBF F0009 06EB@39313 6324a 46343 43036 31312 02020 20202 02020 | 否  |   |  |
| 18 | 福建九有建设发展有限公司 | 2024-04-18 15:39:10.0 | 08-BF-B8-A1-EA-73@BF EBFBF F0009 0675@0025_38D6_31A0_E199.                            | 否 | 2024-04-18 15:06:07.0 | 08-BF-B8-A1-EA-73@BF EBFBF F0009 0675@0025_38D6_31A0_E199.   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误差，请检查         | 2024-04-24 08:39:51   | 08-BF-B8-A1-EA-73@BF EBFBF F0009 0675@0025_38D6_31A0_E199. | 否 |  |



|    |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|----|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
| 20 | 福建省发迪<br>建筑工程有<br>限公司 | 2024-<br>04-23<br>16:08<br>:37.0 | 74-<br>56-<br>3C-<br>E7-<br>D2-<br>8A@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>6AED_<br>3E85. | 否 | 2024-<br>04-23<br>15:44<br>:46.0 | 74-<br>56-<br>3C-<br>E7-<br>D2-<br>8A@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>6AED_<br>3E85.   | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:44<br>:18 | 74-<br>56-<br>3C-<br>E7-<br>D2-<br>8A@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>6AED_<br>3E85. | 否 |  |
| 21 | 福建扬展建<br>设工程有限<br>公司  | 2024-<br>04-22<br>15:37<br>:12.0 | 3C-<br>7C-<br>3F-<br>1F-<br>85-<br>2E@BF<br>EBFBF<br>F0009<br>06EB@<br>43523<br>03231<br>39353<br>63936<br>36423<br>53020<br>36202<br>02020 | 否 | 2024-<br>04-22<br>15:11<br>:11.0 | 3C-<br>7C-<br>3F-<br>1F-<br>85-<br>2E, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>43523<br>03231<br>39353<br>63936<br>36423<br>53020<br>36202<br>02020 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:35<br>:40 | 3C-<br>7C-<br>3F-<br>1F-<br>85-<br>2E@BF<br>EBFBF<br>F0009<br>06EB@<br>43523<br>03231<br>39353<br>63936<br>36423<br>53020<br>36202<br>02020 | 否 |  |



|    |                        |                                  |  |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |   |  |   |  |
|----|------------------------|----------------------------------|--|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|---|--|---|--|
| 24 | 中闽瀚博<br>(福建)建<br>设有限公司 | 2024-<br>04-23<br>11:49<br>:00.0 | 50-<br>EB-<br>F6-<br>B6-<br>D4-<br>8E@BF<br>EBFBF<br>F0009<br>0672@<br>P8G7L<br>WJP,0<br>000_0<br>000_0<br>000_0<br>001.   | 否 | 2024-<br>04-22<br>16:29<br>:25.0 | 50-<br>EB-<br>F6-<br>B6-<br>D4-<br>8E@BF<br>EBFBF<br>F0009<br>0672@<br>P8G7L<br>WJP,0<br>000_0<br>000_0<br>000_0<br>001.  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>查<br>查 | 2024-<br>04-24<br>08:33<br>:47  | 50-<br>EB-<br>F6-<br>B6-<br>D4-<br>8E@BF<br>EBFBF<br>F0009<br>0672@<br>P8G7L<br>WJP,0<br>000_0<br>000_0<br>000_0<br>001. | 否 |  |
| 25 | 福建省豪达<br>建筑装饰有<br>限公司  | 2024-<br>04-23<br>10:30<br>:31.0 | B4-<br>2E-<br>99-<br>74-<br>7F-<br>51@BF<br>EBFBF<br>F0009<br>06EB@<br>53593<br>03239<br>31313<br>13939<br>38332<br>02020<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>36595<br>a5244<br>4b4c4<br>b | 否 | 2024-<br>04-23<br>10:29<br>:17.0 | B4-<br>2E-<br>99-<br>74-<br>7F-<br>51,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>53593<br>03239<br>31313<br>13939<br>38332<br>02020<br>20202<br>20205<br>7202d<br>44435<br>73643<br>36595<br>a5244<br>4b4c4<br>b | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>查<br>查 | 2024-<br>04-24<br>08:32<br>:03         | B4-<br>2E-<br>99-<br>74-<br>7F-<br>51@BF<br>EBFBF<br>F0009<br>06EB@<br>53593<br>03239<br>31313<br>13939<br>38332<br>02020<br>20202<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>36595<br>a5244<br>4b4c4<br>b | 否  |   |  |





|    |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 28 | 福建翔悦建设工程有限公司 | 2024-04-23 17:03:15.0 | 00-<br>E0-<br>70-<br>85-<br>1D-<br>FE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>20180<br>70307<br>619 | 否 | 2024-04-23 16:44:49.0 | 00-<br>E0-<br>70-<br>85-<br>1D-<br>FE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>20180<br>70307<br>619  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 09:07:50 | 00-<br>E0-<br>70-<br>85-<br>1D-<br>FE@BF<br>EBFBF<br>F0009<br>06E9@<br>20180<br>70307<br>619  | 否 |  |
| 29 | 福建荣腾市政园林有限公司 | 2024-04-23 09:46:00.0 | 00-<br>E2-<br>69-<br>4D-<br>DE-<br>79@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000.       | 否 | 2024-04-23 09:45:13.0 | 00-<br>E2-<br>69-<br>4D-<br>DE-<br>79@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 09:03:11 | 00-<br>E2-<br>69-<br>4D-<br>DE-<br>79@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000. | 否 |  |

|    |                  |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|----|------------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 30 | 南旭投资集团有限公司       | 2024-04-22 14:42:58.0 | 00-E2-69-59-9B-7E@BF EBFBF F000A 0653@WD-WX52A A26UZ LS, 50 026B7 381A5 F467   | 否 | 2024-04-22 14:29:51.0 | 00-E2-69-59-9B-7E@BF EBFBF F000A 0653@WD-WX52A A26UZ LS, 50 026B7 381A5 F467   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:47 | 00-E2-69-59-9B-7E@BF EBFBF F000A 0653@WD-WX52A A26UZ LS, 50 026B7 381A5 F467   | 否 |  |
| 31 | 福建省建瓯市耀发建筑工程有限公司 | 2024-04-22 17:15:01.0 | 50-EB-F6-BC-41-4D@BF EBFBF F000A 0653@0000_0000_0000_0000_0026_B738_147D_F805. | 否 | 2024-04-22 17:04:58.0 | 50-EB-F6-BC-41-4D@BF EBFBF F000A 0653@0000_0000_0000_0000_0026_B738_147D_F805. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:27 | 50-EB-F6-BC-41-4D@BF EBFBF F000A 0653@0000_0000_0000_0000_0026_B738_147D_F805. | 否 |  |







|    |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 37 | 福建省俭惜建筑工程有限公司 | 2024-04-23 18:54:28.0 | 00-E0-4C-45-89-0F@BF EBFBF F0009 06E9@ RW18C 22087 A1192 , WD-WCC6Y 6LZAC N8           | 否 | 2024-04-23 11:52:53.0 | 00-E0-4C-45-89-0F@BF EBFBF F0009 06E9@ RW18C 22087 A1192 , WD-WCC6Y 6LZAC N8           | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:38:51 | 00-E0-4C-45-89-0F@BF EBFBF F0009 06E9@ RW18C 22087 A1192 , WD-WCC6Y 6LZAC N8           | 否 |  |
| 38 | 福建竣莱建筑工程有限公司  | 2024-04-23 18:45:53.0 | 40-B0-76-61-0E-03@17 8BFBF F0066 0F51@ 20202 02020 20202 04357 36433 05959 4c584 b4654 | 否 | 2024-04-23 18:42:57.0 | 40-B0-76-61-0E-03@17 8BFBF F0066 0F51@ 20202 02020 20202 04357 36433 05959 4c584 b4654 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:41:49 | 40-B0-76-61-0E-03@17 8BFBF F0066 0F51@ 20202 02020 20202 04357 36433 05959 4c584 b4654 | 否 |  |

|    |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |  |                             |   |  |
|----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|-----------------------------|---|--|
| 39 | 福建中辽建设集团有限公司  | 2024-04-23 15:41:22.0 | 00-00-00-00-00,00-FF-99-26-26-26-6A,E0-D5-5E-52-EE-35@BF EBFBF F0009 06E9@ 50026 B7381 A1E54 2, S2A TNHZA | 否 | 2024-04-23 14:58:57.0 | 00-FF-99-26-26-6A,E0-D5-5E-52-EE-35@BF EBFBF F0009 06E9@ 50026 B7381 A1E54 2, S2A TNHZA | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:11 | 00-00-00-00-00,00-FF-99-26-26-6A,E0-D5-5E-52-EE-35@BF EBFBF F0009 06E9@ 50026 B7381 A1E54 2, S2A TNHZA | 否                           |   |  |
| 40 | 福建鹏隆建设发展有限公司  | 2024-04-22 18:56:04.0 | A0-36-BC-04-CD-9C@BF EBFBF F000A 0653@ WD-WCC6Y ONARE R6, TC 21808 OH9B1 424                              | 否 | 2024-04-22 17:27:00.0 | A0-36-BC-04-CD-9C@BF EBFBF F000A 0653@ WD-WCC6Y ONARE R6, TC 21808 OH9B1 424            | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:07 | A0-36-BC-04-CD-9C@BF EBFBF F000A 0653@ WD-WCC6Y ONARE R6, TC 21808 OH9B1 424                           | 否                           |   |  |
| 41 | 福建省富力筑业工程有限公司 | 2024-04-23 10:34:16.0 | 18-C0-4D-92-6B-1C,00-00-00-   | 否 | 2024-04-23 10:29:43.0 | 18-C0-4D-92-6B-1C,00-00-00-   | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:42:16  | 18-C0-4D-92-6B-1C,00-00-00- | 否 |  |



|    |              |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                            |                            |  |   |  |
|----|--------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|--|---|--|
|    |              |                              | 00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36363<br>73438<br>41323<br>04634<br>37202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>50593<br>6314c<br>41435<br>3 |   |                              | 00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36363<br>73438<br>41323<br>04634<br>37202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>50593<br>6314c<br>41435<br>3 |   |  |  |  |  |  |  |  |  |  |                            |                            | 00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36363<br>73438<br>41323<br>04634<br>37202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>50593<br>6314c<br>41435<br>3 |   |  |
| 42 | 福建洹泰建设发展有限公司 | 2024-04-22<br>10:57<br>:52.0 | 18-<br>C0-<br>4D-<br>53-<br>DC-<br>B2@BF<br>EBFBF<br>F0009<br>06EA@<br>MX_20<br>12321<br>563   | 否 | 2024-04-19<br>16:52<br>:08.0 | 18-<br>C0-<br>4D-<br>53-<br>DC-<br>B2@BF<br>EBFBF<br>F0009<br>06EA@<br>MX_20<br>12321<br>563   | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:32<br>:15 | 00-<br>E0-<br>4C-<br>4E-<br>04-<br>1A@BF<br>EBFBF<br>F0003<br>06A9@<br>F7F57<br>03031<br>80103<br>52853<br>, W -<br>DXW1C<br>2CJ22<br>336  | 否 |  |

|    |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |  |  |   |  |
|----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|--|---|--|
| 43 | 福建双德建设发展有限公司 | 2024-04-23 16:38:20.0 | F0-42-1C-1B-F6-10,00-E0-0A-74-30-09@BF EBFBF F0009 06EB@32323 63044 5a523 04733 41353 53037 34202 02020 | 否 | 2024-04-23 16:35:22.0 | F0-42-1C-1B-F6-10,00-E0-0A-74-30-09@BF EBFBF F0009 06EB@32323 63044 5a523 04733 41353 53037 34202 02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:54:08 | 08-BF-B8-1C-C5-3B@BF EBFBF F0009 0675@0000_0000_0000_0026_B738_2A08_FF05.,MX_000000 010204 | 否  |   |  |
| 44 | 福建星晴建设工程有限公司 | 2024-04-23 14:47:19.0 | 58-11-22-8A-CA-EC@BF EBFBF F0009 0675@0000_0000_0000_0000_8CE3_8E03_0074_8EOE.                          | 否 | 2024-04-23 14:45:47.0 | 58-11-22-8A-CA-EC@BF EBFBF F0009 0675@0000_0000_0000_0000_8CE3_8E03_0074_8EOE.                          | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:35:17  | 58-11-22-8A-CA-EC@BF EBFBF F0009 0675@0000_0000_0000_0000_8CE3_8E03_0074_8EOE. | 否 |  |

|    |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 45 | 福建建筑美建设有限公司  | 2024-04-18 16:31:43.0 | 08-BF-B8-04-4A-00@BF EBFBF F0009 0675@0000_0000_0000_0000_0026 B738 2330_40D5. | 否 | 2024-04-18 16:15:18.0 | 08-BF-B8-04-4A-00@BF EBFBF F0009 0675@0000_0000_0000_0000_0026 B738 2330_40D5. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:30 | 08-BF-B8-04-4A-00@BF EBFBF F0009 0675@0000_0000_0000_0000_0026 B738 2330_40D5. | 否 |  |
| 46 | 福建大信建设工程有限公司 | 2024-04-23 11:52:32.0 | 00-E0-70-80-A6-F6@BF EBFBF F0009 06E9@18011 18013 43                           | 否 | 2024-04-22 16:57:56.0 | 00-E0-70-80-A6-F6,00 -00-00-00-00-00-E0@BF EBFBF F0009 06E9@18011 18013 43     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:25 | 00-E0-70-80-A6-F6@BF EBFBF F0009 06E9@18011 18013 43                           | 否 |  |



|    |                   |                              |   |   |                              |  |   |  |  |  |  |  |  |  |  |  |                         |                            |  |   |  |
|----|-------------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------------------|----------------------------|--|---|--|
| 48 | 武汉新冠金<br>建设工程有限公司 | 2024-04-16<br>17:58<br>:52.0 | 58-<br>11-<br>22-<br>C0-<br>70-<br>37@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0006_<br>2210_<br>0045_<br>3A5A_<br>2703_<br>E000_<br>031D.<br>, WD-<br>WCC6Y<br>2X4PX<br>5F                | 否 | 2024-04-16<br>17:58<br>:07.0 | 58-<br>11-<br>22-<br>C0-<br>70-<br>37@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0006_<br>2210_<br>0045_<br>3A5A_<br>2703_<br>E000_<br>031D.<br>, WD-<br>WCC6Y<br>2X4PX<br>5F | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:33<br>:31 | 58-<br>11-<br>22-<br>C0-<br>70-<br>37@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0006_<br>2210_<br>0045_<br>3A5A_<br>2703_<br>E000_<br>031D.<br>, WD-<br>WCC6Y<br>2X4PX<br>5F | 否 |  |
| 49 | 厦门轩丞建<br>设有限公司    | 2024-04-23<br>14:47<br>:18.0 | C8-<br>7F-<br>54-<br>57-<br>35-<br>1B, 00<br>-00-<br>00-<br>00-<br>00-<br>00@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1CD5_<br>35C5. | 否 | 2024-04-23<br>14:45<br>:31.0 | C8-<br>7F-<br>54-<br>57-<br>35-<br>1B@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1CD5_<br>35C5.                                  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:39<br>:40 | C8-<br>7F-<br>54-<br>57-<br>35-<br>1B@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1CD5_<br>35C5.                         | 否 |  |















|    |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|----|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 60 | 福建省新都项目管理咨询有限公司 | 2024-04-18 15:52:03.0 | 58-11-22-97-EA-80@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 45F1_ 67DA. | 否 | 2024-04-18 15:48:32.0 | 58-11-22-97-EA-80@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 45F1_ 67DA.   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:07 | 58-11-22-97-EA-80@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 45F1_ 67DA. | 否 |  |
| 61 | 福建省长航建设发展有限公司   | 2024-04-22 17:36:20.0 | 40-B0-76-DB-14-AD@BF EBFBF F0009 06EA@ 50026 B7381 295FF C, WD- WCC6Y 4XSSR VU         | 否 | 2024-04-22 17:27:45.0 | 40-B0-76-DB-14-AD, 00 -00- 00- 00- 00- 00- 00- E0, 00 -00- 00- 00- 00- 00- E0@BF EBFBF F0009 06EA@ 50026 B7381 295FF C, WD- WCC6Y 4XSSR VU | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:43:50 | 40-B0-76-DB-14-AD@BF EBFBF F0009 06EA@ 50026 B7381 295FF C, WD- WCC6Y 4XSSR VU         | 否 |  |





|    |             |  |   |  |   |  |  |  |  |  |  |  |  |  |  |  |  |            |  |   |  |
|----|-------------|--|---|--|---|--|--|--|--|--|--|--|--|--|--|--|--|------------|--|---|--|
| 64 | 福建红珊瑚建设有限公司 | 2024-04-23 15:13:32.0  | 否 | 2024-04-23 11:19:45.0  | 否 |  |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:39  | 否 |  |
|    |             | 0A-<br>E0-<br>AF-<br>C6-<br>00-<br>32,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@17<br>8BFBF<br>F0063<br>0F01@<br>434d3<br>04331<br>32305<br>43030<br>34355<br>33031<br>34583<br>62020<br>,2020<br>20205<br>7202d<br>44435<br>73243<br>4b453<br>03336<br>36323<br>9 |   | 0A-<br>E0-<br>AF-<br>C6-<br>00-<br>32,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@17<br>8BFBF<br>F0063<br>0F01@<br>434d3<br>04331<br>32305<br>43030<br>34355<br>33031<br>34583<br>62020<br>,2020<br>20205<br>7202d<br>44435<br>73243<br>4b453<br>03336<br>36323<br>9 |   |  |  |  |  |  |  |  |  |  |  |  |  |            | 0A-<br>E0-<br>AF-<br>C6-<br>00-<br>32,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@17<br>8BFBF<br>F0063<br>0F01@<br>434d3<br>04331<br>32305<br>43030<br>34355<br>33031<br>34583<br>62020<br>,2020<br>20205<br>7202d<br>44435<br>73243<br>4b453<br>03336<br>36323<br>9 |   |  |







|    |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |   |  |
|----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|---|--|
|    |              |                       |   |   |                       | Z9  |   |  |  |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |   |  |
| 67 | 福建恒拓建设工程有限公司 | 2024-04-23 15:34:56.0 | 1C-1B-0D-76-A6-EE@BFEBFBF<br>F000506E3@TK1721700360, WD-<br>WCC6YOKKE7YT  | 否 | 2024-04-23 11:03:29.0 | 1C-1B-0D-76-A6-EE@BFEBFBF<br>F000506E3@TK1721700360, WD-<br>WCC6YOKKE7YT  | 否 |  |  |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:37 | 1C-1B-0D-76-A6-EE@BFEBFBF<br>F000506E3@TK1721700360, WD-<br>WCC6YOKKE7YT | 否   |   |  |
| 68 | 万喜(福建)发展有限公司 | 2024-04-22 13:08:34.0 | 30-9C-23-B5-D3-32@BFEBFBF<br>F000906E9@W9AB6Y6K                           | 否 | 2024-04-22 13:05:04.0 | 30-9C-23-B5-D3-32@BFEBFBF<br>F000906E9@W9AB6Y6K                           | 否 |  |  |  |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:41:31  | 30-9C-23-B5-D3-32@BFEBFBF<br>F000906E9@W9AB6Y6K                           | 否 |  |
| 69 | 福建省三安建设有限公司  | 2024-04-17 15:42:05.0 | 00-E0-4C-7D-6A-56@178BFBF<br>F00870F10@6360471016664038157, LFQ5872007173 | 否 | 2024-04-17 15:35:35.0 | 00-E0-4C-7D-6A-56@178BFBF<br>F00870F10@6360471016664038157, LFQ5872007173 | 否 |  |  |  |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:33:47  | 00-E0-4C-7D-6A-56@178BFBF<br>F00870F10@6360471016664038157, LFQ5872007173 | 否 |  |

|    |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|----|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 70 | 福建屹立建设工程有限公司   | 2024-04-18 09:13:01.0 | 58-11-22-CC-9B-B2@BF EBFBF F0009 0672@0000_0000_0000_0000_0000_0100_0000_0000. | 否 | 2024-04-18 09:10:28.0 | 58-11-22-CC-9B-B2@BF EBFBF F0009 0672@0000_0000_0000_0000_0000_0100_0000_0000. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:37 | 58-11-22-CC-9B-B2@BF EBFBF F0009 0672@0000_0000_0000_0000_0000_0100_0000_0000. | 否 |  |
| 71 | 福建鸿杨建筑工程有限公司   | 2024-04-18 14:50:11.0 | E0-D5-5E-D7-86-01@BF EBFBF F0009 06EA@SN201 20891 7766                         | 否 | 2024-04-18 14:49:07.0 | E0-D5-5E-D7-86-01@BF EBFBF F0009 06EA@SN201 20891 7766                         | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:32 | E0-D5-5E-D7-86-01@BF EBFBF F0009 06EA@SN201 20891 7766                         | 否 |  |
| 72 | 福建筑源鑫达建设工程有限公司 | 2024-04-23 10:39:46.0 | D8-5E-D3-44-08-8A@BF EBFBF F000A 0653@WD-WCC6Y 6TV32 27, MG 22083 01691 41     | 否 | 2024-04-23 10:37:57.0 | D8-5E-D3-44-08-8A@BF EBFBF F000A 0653@WD-WCC6Y 6TV32 27, MG 22083 01691 41     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:41:06 | D8-5E-D3-44-08-8A@BF EBFBF F000A 0653@WD-WCC6Y 6TV32 27, MG 22083 01691 41     | 否 |  |

|    |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 73 | 福建沐恩建设发展有限公司 | 2024-04-23 16:48:44.0 | 58-11-22-9A-2A-A7@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>5FE2_<br>8DD5. | 否 | 2024-04-22 16:17:11.0 | 58-11-22-9A-2A-A7@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>5FE2_<br>8DD5. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:38:52 | 58-11-22-9A-2A-A7@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>5FE2_<br>8DD5. | 否 |  |
|----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|













|    |                        |                                  |  |   |                                  |  |  |  |  |  |  |  |  |  |  |  |  |                         |                                       |  |   |  |
|----|------------------------|----------------------------------|--|---|----------------------------------|--|--|--|--|--|--|--|--|--|--|--|--|-------------------------|---------------------------------------|--|---|--|
|    |                        |                                  | 73643<br>30593<br>04832<br>55553<br>4  |   |                                  | 73643<br>30593<br>04832<br>55553<br>4  |  |  |  |  |  |  |  |  |  |  |  |                         | 73643<br>30593<br>04832<br>55553<br>4 |  |   |  |
| 82 | 福建省筑辉<br>工程建设有<br>限公司  | 2024-<br>04-22<br>17:08<br>:51.0 | 08-<br>BF-<br>B8-<br>1D-<br>A0-<br>15@BF<br>EBFBF<br>F000A<br>0653@<br>0025_<br>38A6_<br>21B2_<br>364B.<br>, WD-<br>WCC6Y<br>4W9CS<br>ND                                 | 否 | 2024-<br>04-22<br>17:06<br>:04.0 | 08-<br>BF-<br>B8-<br>1D-<br>A0-<br>15@BF<br>EBFBF<br>F000A<br>0653@<br>0025_<br>38A6_<br>21B2_<br>364B.<br>, WD-<br>WCC6Y<br>4W9CS<br>ND                                 |  |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:34<br>:08        | 08-<br>BF-<br>B8-<br>1D-<br>A0-<br>15@BF<br>EBFBF<br>F000A<br>0653@<br>0025_<br>38A6_<br>21B2_<br>364B.<br>, WD-<br>WCC6Y<br>4W9CS<br>ND | 否 |  |
| 83 | 福建阳一建<br>设(集团)<br>有限公司 | 2024-<br>04-23<br>21:06<br>:32.0 | 28-<br>39-<br>26-<br>56-<br>09-<br>EB, 2A<br>-39-<br>26-<br>C7-<br>63-<br>31, AA<br>-39-<br>26-<br>0F-<br>07-<br>03@BF<br>EBFBF<br>F0008<br>06EC@<br>Optan<br>e_000<br>0 | 否 | 2024-<br>04-23<br>21:05<br>:06.0 | 2A-<br>39-<br>26-<br>C7-<br>63-<br>31, AA<br>-39-<br>26-<br>0F-<br>07-<br>03, 28<br>-39-<br>26-<br>56-<br>09-<br>EB@BF<br>EBFBF<br>F0008<br>06EC@<br>Optan<br>e_000<br>0 |  |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:35<br>:40        | 24-<br>4B-<br>FE-<br>45-<br>A4-<br>A2@17<br>8FBFBF<br>F0081<br>0F11@<br>AA000<br>00000<br>00000<br>02410                                 | 否 |  |



|    |             |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|----|-------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 87 | 福建欣泷建设有限公司  | 2024-04-23 17:41:40.0 | 7C-10-C9-8D-A6-EB@BF<br>EBFBF<br>F000A<br>0653@<br>N9YJ0<br>8A00A<br>02130<br>, AA00<br>00000<br>00000<br>00498<br>8                   | 否 | 2024-04-23 16:15:16.0 | 7C-10-C9-8D-A6-EB@BF<br>EBFBF<br>F000A<br>0653@<br>N9YJ0<br>8A00A<br>02130<br>, AA00<br>00000<br>00000<br>00498<br>8                   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:39 | 7C-10-C9-8D-A6-EB@BF<br>EBFBF<br>F000A<br>0653@<br>N9YJ0<br>8A00A<br>02130<br>, AA00<br>00000<br>00000<br>00498<br>8 | 否 |  |
| 88 | 福建省富丰建设有限公司 | 2024-04-22 16:32:24.0 | 00-E0-4C-52-92-72@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OEDHN<br>Z2, AA<br>00000<br>00000<br>00000<br>674_0<br>00000<br>01. | 否 | 2024-04-22 16:28:29.0 | 00-E0-4C-52-92-72@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OEDHN<br>Z2, AA<br>00000<br>00000<br>00000<br>674_0<br>00000<br>01. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:08 | 00-E0-4C-5A-A4-5B@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A759_<br>F090_<br>0469.                                  | 否 |  |





|    |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 92 | 福建集鼎建设工程有限公司 | 2024-04-23 09:54:29.0 | 88-AE-DD-5D-AB-61@BF EBFBF F0009 0675@WD-WX62D 43277 X8, 5C DF_B8 03_70 CO_OD 8A. | 否 | 2024-04-23 09:51:14.0 | 88-AE-DD-5D-AB-61@BF EBFBF F0009 0675@WD-WX62D 43277 X8, 5C DF_B8 03_70 CO_OD 8A. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:44:10 | 88-AE-DD-5D-AB-61@BF EBFBF F0009 0675@WD-WX62D 43277 X8, 5C DF_B8 03_70 CO_OD 8A. | 否   |   |  |
| 93 | 福建卉森建设有限公司   | 2024-04-23 14:55:02.0 | 04-D4-C4-4E-35-58@BF EBFBF F0009 06EB@S4CKN F0MA0 8415B                           | 否 | 2024-04-23 14:54:02.0 | 04-D4-C4-4E-35-58@BF EBFBF F0009 06EB@S4CKN F0MA0 8415B                           | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:57:53   | 04-D4-C4-4E-35-58@BF EBFBF F0009 06EB@S4CKN F0MA0 8415B | 否 |  |

|    |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 94 | 福建联沃建设工程有限公司 | 2024-04-22 14:08:43.0 | 74-54-27-48-C1-40,74-54-27-48-C1-40,E0-D5-5E-95-A6-A9@BF EBFBF F0009 06E9@ Z9AWS YEY               | 否 | 2024-04-22 14:06:38.0 | 74-54-27-48-C1-40,74-54-27-48-C1-40,E0-D5-5E-95-A6-A9@BF EBFBF F0009 06E9@ Z9AWS YEY               | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:07 | 74-54-27-48-C1-40,74-54-27-48-C1-40,E0-D5-5E-95-A6-A9@BF EBFBF F0009 06E9@ Z9AWS YEY               | 否 |  |
| 95 | 福建金石头建设有限公司  | 2024-04-22 16:19:23.0 | 08-BF-B8-39-F8-69@BF EBFBF F000A 0653@ 0000_0006_2301_2664_CAF2_5B03_D000_0ADB., WD-WCC6Y FDT95 XZ | 否 | 2024-04-19 16:05:10.0 | 08-BF-B8-39-F8-69@BF EBFBF F000A 0653@ 0000_0006_2301_2664_CAF2_5B03_D000_0ADB., WD-WCC6Y FDT95 XZ | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:17 | 08-BF-B8-39-F8-69@BF EBFBF F000A 0653@ 0000_0006_2301_2664_CAF2_5B03_D000_0ADB., WD-WCC6Y FDT95 XZ | 否 |  |











|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 102 | 福建闽悦建设发展有限公司 | 2024-04-22 11:10:22.0 | 00-E0-4C-07-25-AE@BF<br>EBFBF<br>F0003<br>06A9@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>25959<br>414e4<br>a4b45   | 否 | 2024-04-22 10:58:39.0 | 00-E0-4C-07-25-AE@BF<br>EBFBF<br>F0003<br>06A9@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>25959<br>414e4<br>a4b45   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:47 | 00-E0-4C-07-25-AE@BF<br>EBFBF<br>F0003<br>06A9@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>25959<br>414e4<br>a4b45   | 否 |  |
| 103 | 福建汇清建设工程有限公司 | 2024-04-23 09:21:21.0 | 00-E0-4C-42-0E-25,20<br>-0D-<br>B0-<br>CF-<br>9C-<br>F4,20<br>-0D-<br>B0-<br>CF-<br>9C-<br>F5,20<br>-0D-<br>B0-<br>CF-<br>9C-<br>F2@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>6034_<br>2185. | 否 | 2024-04-23 09:19:17.0 | 00-E0-4C-42-0E-25,20<br>-0D-<br>B0-<br>CF-<br>9C-<br>F4,20<br>-0D-<br>B0-<br>CF-<br>9C-<br>F5,20<br>-0D-<br>B0-<br>CF-<br>9C-<br>F2@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>6034_<br>2185. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:46 | 00-E0-4C-42-0E-25,20<br>-0D-<br>B0-<br>CF-<br>9C-<br>F2,20<br>-0D-<br>B0-<br>CF-<br>9C-<br>F4,20<br>-0D-<br>B0-<br>CF-<br>9C-<br>F5@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>6034_<br>2185. | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 104 | 福建浩华建设有限公司    | 2024-04-23 15:45:50.0 | 04-7C-16-CF-83-32@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_233C_A5D5. | 否 | 2024-04-23 15:44:06.0 | 04-7C-16-CF-83-32@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_233C_A5D5. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:46 | 04-7C-16-CF-83-32@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_233C_A5D5. | 否 |  |
| 105 | 福建省展新建设工程有限公司 | 2024-04-23 15:13:04.0 | D8-5E-D3-52-67-25@BF EBFBF F000A 0653@50026 B7381 339C5 C, WD-WCC6Y 4DN4T PD   | 否 | 2024-04-23 15:11:40.0 | D8-5E-D3-52-67-25@BF EBFBF F000A 0653@50026 B7381 339C5 C, WD-WCC6Y 4DN4T PD   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:36 | D8-5E-D3-52-67-25@BF EBFBF F000A 0653@50026 B7381 339C5 C, WD-WCC6Y 4DN4T PD   | 否 |  |



|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 108 | 考工建设有限公司      | 2024-04-23 12:22:26.0 | 04-42-1A-93-4C-AD,00-00-00-00-00-00-0653@30057810297                              | 否 | 2024-04-22 17:20:21.0 | 04-42-1A-93-4C-AD,00-00-00-00-00-00-0653@30057810297                              | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:21 | 04-42-1A-93-4C-AD@BFEBFBF000A0653@30057810297                              | 否 |  |
| 109 | 福建省闽旺建设工程有限公司 | 2024-04-23 22:28:52.0 | F4-6A-92-CD-F6-E8,00-00-00-00-00-00-06EB@5354303233385331303137323731203020202020 | 否 | 2024-04-23 22:27:35.0 | F4-6A-92-CD-F6-E8,00-00-00-00-00-00-06EB@5354303233385331303137323731203020202020 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:47 | F4-6A-92-CD-F6-E8@BFEBFBF000906EB@5354303233385331303137323731203020202020 | 否 |  |



|     |                   |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                            |                            |  |   |  |
|-----|-------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|--|---|--|
| 110 | 福建年可期<br>建设工程有限公司 | 2024-04-23<br>14:08<br>:13.0 | 00-<br>E0-<br>4C-<br>5C-<br>6A-<br>1D@BF<br>EBFBF<br>F000A<br>0653@<br>14619<br>94900<br>337, W<br>9AL4T<br>3X                   | 否 | 2024-04-18<br>10:48<br>:40.0 | 00-<br>E0-<br>4C-<br>5C-<br>6A-<br>1D@BF<br>EBFBF<br>F000A<br>0653@<br>14619<br>94900<br>337, W<br>9AL4T<br>3X                   | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有错<br>，请<br>检查 | 2024-04-24<br>08:34<br>:44 | 00-<br>E0-<br>4C-<br>5C-<br>6A-<br>1D@BF<br>EBFBF<br>F000A<br>0653@<br>14619<br>94900<br>337, W<br>9AL4T<br>3X                   | 否 |  |
| 111 | 福建鹭砦建<br>工有限公司    | 2024-04-23<br>10:35<br>:12.0 | 2C-<br>FD-<br>A1-<br>BA-<br>04-<br>E3@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7782<br>1E792<br>2, WD-<br>WXM1A<br>87NAK<br>6P | 否 | 2024-04-22<br>15:41<br>:28.0 | 2C-<br>FD-<br>A1-<br>BA-<br>04-<br>E3@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7782<br>1E792<br>2, WD-<br>WXM1A<br>87NAK<br>6P | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有错<br>，请<br>检查 | 2024-04-24<br>08:33<br>:07 | 2C-<br>FD-<br>A1-<br>BA-<br>04-<br>E3@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7782<br>1E792<br>2, WD-<br>WXM1A<br>87NAK<br>6P | 否 |  |
| 112 | 河南东邦建<br>设工程有限公司  | 2024-04-18<br>16:03<br>:46.0 | 48-<br>F3-<br>17-<br>11-<br>3F-<br>F2@BF<br>EBFBF<br>F000A<br>0653@<br>30111<br>04616<br>1                                       | 否 | 2024-04-18<br>09:49<br>:26.0 | 48-<br>F3-<br>17-<br>11-<br>3F-<br>F2@BF<br>EBFBF<br>F000A<br>0653@<br>30111<br>04616<br>1                                       | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有错<br>，请<br>检查 | 2024-04-24<br>08:41<br>:26 | 48-<br>F3-<br>17-<br>11-<br>3F-<br>F2@BF<br>EBFBF<br>F000A<br>0653@<br>30111<br>04616<br>1                                       | 否 |  |

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |  |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|--|---|--|
| 113 | 福建广盛建筑工程有限公司  | 2024-04-22 18:10:50.0 | E0-<br>BE-<br>03-<br>75-<br>4D-<br>96@BF<br>EBFBF<br>F000A<br>0653@<br>0025_<br>38D8_<br>21B2_<br>0625.<br>,WD-<br>WCC6Y<br>ANRX1<br>VS | 否 | 2024-04-22 17:58:07.0 | E0-<br>BE-<br>03-<br>75-<br>4D-<br>96@BF<br>EBFBF<br>F000A<br>0653@<br>0025_<br>38D8_<br>21B2_<br>0625.<br>,WD-<br>WCC6Y<br>ANRX1<br>VS | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:37:09 | E0-<br>BE-<br>03-<br>75-<br>4D-<br>96@BF<br>EBFBF<br>F000A<br>0653@<br>0025_<br>38D8_<br>21B2_<br>0625.<br>,WD-<br>WCC6Y<br>ANRX1<br>VS | 否  |   |  |
| 114 | 福建旺达通建设工程有限公司 | 2024-04-23 16:01:40.0 | D4-<br>5D-<br>64-<br>AE-<br>B7-<br>61@BF<br>EBFBF<br>F0009<br>06EB@<br>SCRW2<br>30411<br>05G07<br>73                                    | 否 | 2024-04-23 16:00:02.0 | D4-<br>5D-<br>64-<br>AE-<br>B7-<br>61@BF<br>EBFBF<br>F0009<br>06EB@<br>SCRW2<br>30411<br>05G07<br>73                                    | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:33:22   | D4-<br>5D-<br>64-<br>AE-<br>B7-<br>61@BF<br>EBFBF<br>F0009<br>06EB@<br>SCRW2<br>30411<br>05G07<br>73 | 否 |  |



|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 117 | 福建省伊家建设有限公司  | 2024-04-23 16:24:42.0 | D8-BB-C1-6B-FC-AA@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7784<br>90C5C<br>1   | 否 | 2024-04-22 09:50:06.0 | D8-BB-C1-6B-FC-AA@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7784<br>90C5C<br>1   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:31:06 | D8-BB-C1-6B-FC-AA@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7784<br>90C5C<br>1   | 否 |  |
| 118 | 福建海通宏业工程有限公司 | 2024-04-22 16:56:01.0 | D4-5D-64-43-A3-25,00-1A-7D-DA-71-11@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>1AAJ2<br>S6, J1<br>952J5<br>50111<br>9 | 否 | 2024-04-22 16:53:40.0 | D4-5D-64-43-A3-25,00-1A-7D-DA-71-11@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>1AAJ2<br>S6, J1<br>952J5<br>50111<br>9 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 09:00:34 | D4-5D-64-43-A3-25,00-1A-7D-DA-71-11@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>1AAJ2<br>S6, J1<br>952J5<br>50111<br>9 | 否 |  |





|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 123 | 福建辉硕建设发展有限公司   | 2024-04-23 17:51:37.0 | D8-5E-D3-11-FD-D5@BF EBFBF F000A 0653@50026 B7783 9BE7E F, WD-WCC6Y 6KF8Y ZF                              | 否 | 2024-04-23 15:25:18.0 | D8-5E-D3-11-FD-D5@BF EBFBF F000A 0653@50026 B7783 9BE7E F, WD-WCC6Y 6KF8Y ZF                              | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:02 | D8-5E-D3-11-FD-D5@BF EBFBF F000A 0653@50026 B7783 9BE7E F, WD-WCC6Y 6KF8Y ZF                              | 否 |  |
| 124 | 中建广厦(福建)建设有限公司 | 2024-04-23 08:12:15.0 | 3C-7C-3F-83-0E-B7@BF EBFBF F0009 06ED@WD-WCC6Y MPK48 YS, E8 23_8F A6_BF 53_00 01_00 1B_44 4A_46 D8_AC C2. | 否 | 2024-04-22 18:06:22.0 | 3C-7C-3F-83-0E-B7@BF EBFBF F0009 06ED@WD-WCC6Y MPK48 YS, E8 23_8F A6_BF 53_00 01_00 1B_44 4A_46 D8_AC C2. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:48 | 3C-7C-3F-83-0E-B7@BF EBFBF F0009 06ED@WD-WCC6Y MPK48 YS, E8 23_8F A6_BF 53_00 01_00 1B_44 4A_46 D8_AC C2. | 否 |  |

















|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 134 | 福建省江江建设发展有限公司 | 2024-04-23 15:14:22.0 | A8-5E-45-69-E5-E4,00-00-00-00-00-00@BFEBFBF000906EA@W9AGY11B | 否 | 2024-04-23 12:33:35.0 | A8-5E-45-69-E5-E4,00-00-00-00-00-00@BFEBFBF000906EA@W9AGY11B | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:35:07 | A8-5E-45-69-E5-E4,00-00-00-00-00-00@BFEBFBF000906EA@W9AGY11B | 否 |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|

|     |                 |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 135 | 福建省中闽朝辉建筑工程有限公司 | 2024-04-22 17:01:20.0 | A8-5E-45-A2-BA-20,90-DE-80-E5-A9-98@BF EBFBF F0009 06EA@00000 00000 00000 0,194 65S45 1003, 01234 56789 ABCDE F | 否 | 2024-04-22 16:59:44.0 | A8-5E-45-A2-BA-20,90-DE-80-E5-A9-98@BF EBFBF F0009 06EA@00000 00000 00000 0,194 65S45 1003, 01234 56789 ABCDE F | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:36:13 | A8-5E-45-A2-BA-20,92-DE-80-E5-A9-98,90-DE-80-E5-A9-98,90-DE-80-E5-A9-98@BF EBFBF F0009 06EA@00000 00000 0,194 65S45 1003, 01234 56789 ABCDE F | 否 |  |
|-----|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|









|     |              |                       |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |   |  |  |  |
|-----|--------------|-----------------------|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---|--|--|--|
|     |              |                       | C8-9A, 0C-7A-15-E6-C8-96, 0C-7A-15-E6-C8-97, 0E-7A-15-E6-C8-96@BF EBFBF F0009 06EA@0025_388A_91D3_1933. |                       |  | C8-97, 0E-7A-15-E6-C8-96, A4-AE-11-1D-78-70, 0C-7A-15-E6-C8-9A@BF EBFBF F0009 06EA@0025_388A_91D3_1933. |  |  |  |  |  |  |  |  |  |  |             | C8-97, 0E-7A-15-E6-C8-96, A4-AE-11-1D-78-70, 0C-7A-15-E6-C8-9A@BF EBFBF F0009 06EA@0025_388A_91D3_1933. |  |  |  |
| 142 | 福建广良建设工程有限公司 | 2024-04-19 17:26:23.0 | 00-E0-4C-59-5C-A4@BF EBFBF F000A 0653@120LG LANS, 6479_A752_E050_1EA3. 否                                | 2024-04-19 15:34:19.0 | 00-E0-4C-59-5C-A4@BF EBFBF F000A 0653@120LG LANS, 6479_A752_E050_1EA3. 否 |   |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:34:39   | 00-E0-4C-59-5C-A4@BF EBFBF F000A 0653@120LG LANS, 6479_A752_E050_1EA3. 否 |  |  |

|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 143 | 白马（福建）建设工程有限公司 | 2024-04-23 11:14:59.0 | EC-D6-8A-BA-D7-73, F4-4E-E3-63-7B-C6, F4-4E-E3-63-7B-C6@BFEBFBF00090675@30083134287, W9ASS24J | 否 | 2024-04-23 11:07:31.0 | EC-D6-8A-BA-D7-73, F4-4E-E3-63-7B-C6, F4-4E-E3-63-7B-C6@BFEBFBF00090675@30083134287, W9ASS24J | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:47 | EC-D6-8A-BA-D7-73, F4-4E-E3-63-7B-C6, F4-4E-E3-63-7B-C6@BFEBFBF00090675@30083134287, W9ASS24J | 否 |  |
| 144 | 福建佳宸建设有限公司     | 2024-04-22 09:01:45.0 | 2C-FD-A1-5B-F9-56@BFEBFBF000506E3@AA00000000000089, WCC6YOSAEHY6                              | 否 | 2024-04-19 16:27:42.0 | 2C-FD-A1-5B-F9-56@BFEBFBF000506E3@AA00000000000089, WCC6YOSAEHY6                              | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:11 | 2C-FD-A1-5B-F9-56@BFEBFBF000506E3@AA00000000000089, WCC6YOSAEHY6                              | 否 |  |



|     |                  |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|------------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 147 | 福建华冠达建筑有限公司      | 2024-04-23 11:09:03.0 | A0-36-BC-25-16-D1@BFEBFBFF00090675@0025_38B5_21B6_2D5A.,WD-WX42DB1866D9     | 否 | 2024-04-23 11:06:54.0 | A0-36-BC-25-16-D1@BFEBFBFF00090675@0025_38B5_21B6_2D5A.,WD-WX42DB1866D9     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:38:04 | A0-36-BC-25-16-D1@BFEBFBFF00090675@0025_38B5_21B6_2D5A.,WD-WX42DB1866D9     | 否 |  |
| 148 | 福建拓海建设工程有限公司     | 2024-04-23 19:01:45.0 | 04-D9-F5-D6-EE-B4@BFEBFBFF000906EA@0025_3887_9100_40C6.                     | 否 | 2024-04-23 17:59:38.0 | 04-D9-F5-D6-EE-B4@BFEBFBFF000906EA@0025_3887_9100_40C6.                     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:51 | 04-D9-F5-D6-EE-B4@BFEBFBFF000906EA@0025_3887_9100_40C6.                     | 否 |  |
| 149 | 福建南平江禹水利水电工程有限公司 | 2024-04-22 16:38:12.0 | A0-36-BC-21-36-50@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_16D7_A865. | 否 | 2024-04-22 16:37:16.0 | A0-36-BC-21-36-50@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_16D7_A865. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:41:16 | A0-36-BC-21-36-50@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_16D7_A865. | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 150 | 四川瑞源建筑工程有限公司 | 2024-04-23 19:20:16.0 | 74-56-3C-AB-30-3E@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4CA1_<br>80A7. | 否 | 2024-04-23 19:18:30.0 | 74-56-3C-AB-30-3E@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4CA1_<br>80A7. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:40 | 74-56-3C-AB-30-3E@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4CA1_<br>F646. | 否 |  |
| 151 | 福建晟欧建设工程有限公司 | 2024-04-23 09:23:32.0 | AA-1C-04-0C-C0-7D, 5C-DE-34-2C-2F-7E, 5C-DE-34-2C-2F-7E@BF<br>EBFBF<br>F0003<br>06E4@<br>MG230<br>93000<br>2435     | 否 | 2024-04-23 09:19:55.0 | AA-1C-04-0C-C0-7D, 5C-DE-34-2C-2F-7E, 5C-DE-34-2C-2F-7E@BF<br>EBFBF<br>F0003<br>06E4@<br>MG230<br>93000<br>2435     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:04 | AA-1C-04-0C-C0-7D, 5C-DE-34-2C-2F-7E, 5C-DE-34-2C-2F-7E@BF<br>EBFBF<br>F0003<br>06E4@<br>MG230<br>93000<br>2435     | 否 |  |









|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 156 | 福建武夷鼎泰建设发展有限公司 | 2024-04-23 10:33:29.0 | 88-<br>88-<br>88-<br>88-<br>87-<br>88@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>14E1_<br>3385. | 否 | 2024-04-23 10:29:14.0 | 88-<br>88-<br>88-<br>88-<br>87-<br>88@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>14E1_<br>3385.                           | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:49 | 88-<br>88-<br>88-<br>88-<br>87-<br>88@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>14E1_<br>3385. | 否 |  |
| 157 | 福建省日誉建设集团有限公司  | 2024-04-23 11:03:26.0 | 00-<br>E0-<br>70-<br>84-<br>85-<br>EC@17<br>8BFBF<br>F0063<br>0F01@<br>10006<br>64657<br>5, WD-<br>WCC6Y<br>6AF8K<br>82                     | 否 | 2024-04-23 11:01:17.0 | 00-<br>E0-<br>70-<br>84-<br>85-<br>EC, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@17<br>8BFBF<br>F0063<br>0F01@<br>10006<br>64657<br>5, WD-<br>WCC6Y<br>6AF8K<br>82 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:54 | 00-<br>E0-<br>70-<br>84-<br>85-<br>EC@17<br>8BFBF<br>F0063<br>0F01@<br>10006<br>64657<br>5, WD-<br>WCC6Y<br>6AF8K<br>82                     | 否 |  |



|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 160 | 福建省冠睿建设工程有限公司 | 2024-04-23 15:16:59.0 | E8-9C-25-75-10-3B@BF EBFBF F0009 0675@0025_38D1_30DA_B192.0                | 否 | 2024-04-22 14:46:43.0 | E8-9C-25-75-10-3B@BF EBFBF F0009 0675@0025_38D1_30DA_B192.0                | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:07 | E8-9C-25-75-10-3B@BF EBFBF F0009 0675@0025_38D1_30DA_B192.                 | 否 |  |
| 161 | 福建省东西南北建设有限公司 | 2024-04-23 09:58:41.0 | FC-34-97-C2-34-08@BF EBFBF F000A 0653@TC211 190K6 A1178, WD-WCC6Y OFFR2 7F | 否 | 2024-04-23 09:32:15.0 | FC-34-97-C2-34-08@BF EBFBF F000A 0653@TC211 190K6 A1178, WD-WCC6Y OFFR2 7F | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:07 | FC-34-97-C2-34-08@BF EBFBF F000A 0653@TC211 190K6 A1178, WD-WCC6Y OFFR2 7F | 否 |  |



|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 163 | 福建省巨龙建设工程有限公司 | 2024-04-23 15:50:32.0 | 58-11-22-A0-A3-D2@BF EBFBF F0009 0672@0000_0000_0000_0000_0026_B768_610E_F845.   | 否 | 2024-04-23 15:49:18.0 | 58-11-22-A0-A3-D2@BF EBFBF F0009 0672@0000_0000_0000_0000_0026_B768_610E_F845.   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:11 | 58-11-22-A0-A3-D2@BF EBFBF F0009 0672@0000_0000_0000_0000_0026_B768_610E_F845.   | 否 |  |
| 164 | 福建森融建设有限公司    | 2024-04-19 17:26:19.0 | 18-31-BF-08-35-3D@BF EBFBF F0009 06E9@41413 03030 30303 03030 03030 30303 53836,2020 20205 7202d 44435 73643 31595 05032 48523 9 | 否 | 2024-04-19 17:22:04.0 | 18-31-BF-08-35-3D@BF EBFBF F0009 06E9@41413 03030 30303 03030 03030 30303 53836,2020 20205 7202d 44435 73643 31595 05032 48523 9 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:41:05 | 18-31-BF-08-35-3D@BF EBFBF F0009 06E9@41413 03030 30303 03030 30303 53836,2020 20205 7202d 44435 73643 31595 05032 48523 9 | 否 |  |



|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 165 | 福建省永通建设发展有限公司 | 2024-04-23 15:10:18.0 | 24-4B-FE-DF-98-89@BF EBFBF F0009 06EB@ 20200 90702 82, WD - WX52D 22EJ2 V3 | 否 | 2024-04-23 15:08:57.0 | 24-4B-FE-DF-98-89@BF EBFBF F0009 06EB@ 20200 90702 82, WD - WX52D 22EJ2 V3 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:04 | 08-1F-71-15-E7-1F, 74 -D4-35-50-46-A8@BF EBFBF F0003 06A9@ 30353 23042 36373 73238 36413 23832 39202 02020 | 否 |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|



|     |                      |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |  |                            |  |   |  |
|-----|----------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--|---|--|
| 168 | 福建同得建<br>工集团有限<br>公司 | 2024-04-23<br>18:39<br>:22.0 | 58-<br>11-<br>22-<br>A2-<br>D0-<br>1D, 0C<br>-5B-<br>8F-<br>27-<br>9A-<br>64@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>4885_<br>057A. | 否 | 2024-04-23<br>18:38<br>:01.0 | 58-<br>11-<br>22-<br>A2-<br>D0-<br>1D, 0C<br>-5B-<br>8F-<br>27-<br>9A-<br>64@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>4885_<br>057A. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>查<br>检 | 2024-04-24<br>08:38<br>:35 | 58-<br>11-<br>22-<br>A2-<br>D0-<br>1D, 0C<br>-5B-<br>8F-<br>27-<br>9A-<br>64@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>4885_<br>057A. | 否 |  |
| 169 | 福建凯晏建<br>设工程有限<br>公司 | 2024-04-20<br>16:43<br>:08.0 | C8-<br>7F-<br>54-<br>A0-<br>B0-<br>EF@BF<br>EBFBF<br>F000B<br>06F2@<br>2C3E_<br>BFFF_<br>F000_<br>9C7A.<br>, WD-<br>WCC6Y<br>L2CSC<br>80   | 否 | 2024-04-20<br>16:41<br>:04.0 | C8-<br>7F-<br>54-<br>A0-<br>B0-<br>EF@BF<br>EBFBF<br>F000B<br>06F2@<br>2C3E_<br>BFFF_<br>F000_<br>9C7A.<br>, WD-<br>WCC6Y<br>L2CSC<br>80   | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>查<br>检 | 2024-04-24<br>08:33<br>:07 | C8-<br>7F-<br>54-<br>A0-<br>B0-<br>EF@BF<br>EBFBF<br>F000B<br>06F2@<br>2C3E_<br>BFFF_<br>F000_<br>9C7A.<br>, WD-<br>WCC6Y<br>L2CSC<br>80   | 否 |  |



|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 171 | 福建东瀚建设发展有限公司   | 2024-04-23 16:25:35.0 | B4-2E-99-F6-27-5E@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7684<br>3839C<br>B, Z9A<br>XS607 | 否 | 2024-04-23 14:53:56.0 | B4-2E-99-F6-27-5E@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7684<br>3839C<br>B, Z9A<br>XS607 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请查 | 2024-04-24 08:33:31 | B4-2E-99-F6-27-5E@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7684<br>3839C<br>B, Z9A<br>XS607 | 否 |  |
| 172 | 福建省悦雨市政园林有限公司  | 2024-04-23 10:34:54.0 | 00-E0-4C-36-4B-5A@BF<br>EBFBF<br>F0002<br>0655@<br>WCAW1<br>92YF4<br>00, TW<br>19525<br>06736 | 否 | 2024-04-23 10:33:14.0 | 00-E0-4C-36-4B-5A@BF<br>EBFBF<br>F0002<br>0655@<br>WCAW1<br>92YF4<br>00, TW<br>19525<br>06736 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请查 | 2024-04-24 08:33:27 | 00-E0-4C-36-4B-5A@BF<br>EBFBF<br>F0002<br>0655@<br>WCAW1<br>92YF4<br>00, TW<br>19525<br>06736 | 否 |  |
| 173 | 福建怡景市政园林工程有限公司 | 2024-04-22 10:01:17.0 | D8-BB-C1-62-4D-F8@BF<br>EBFBF<br>F000A<br>0653@<br>0026_<br>B768_<br>4AEF_<br>1FC5.           | 否 | 2024-04-22 09:49:04.0 | D8-BB-C1-62-4D-F8@BF<br>EBFBF<br>F000A<br>0653@<br>0026_<br>B768_<br>4AEF_<br>1FC5.           | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请查 | 2024-04-24 08:45:45 | D8-BB-C1-62-4D-F8@BF<br>EBFBF<br>F000A<br>0653@<br>0026_<br>B768_<br>4AEF_<br>1FC5.           | 否 |  |

|     |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 174 | 福建鸿蕴建设有限公司 | 2024-04-23 19:25:55.0 | 00-E0-4C-9F-C7-61@BF<br>EBFBF<br>F0003<br>06E4,<br>BFEBF<br>BFF00<br>0306E<br>4@GSD<br>MB209<br>17002<br>7, WD-<br>WX42D<br>60NNV<br>XX | 否 | 2024-04-23 15:20:32.0 | 00-E0-4C-9F-C7-61@BF<br>EBFBF<br>F0003<br>06E4,<br>BFEBF<br>BFF00<br>0306E<br>4@GSD<br>MB209<br>17002<br>7, WD-<br>WX42D<br>60NNV<br>XX | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:40 | 00-E0-4C-9F-C7-61@BF<br>EBFBF<br>F0003<br>06E4,<br>BFEBF<br>BFF00<br>0306E<br>4@GSD<br>MB209<br>17002<br>7, WD-<br>WX42D<br>60NNV<br>XX | 否   |   |  |
| 175 | 福建容筑建设有限公司 | 2024-04-23 18:06:36.0 | FC-34-97-BF-78-30@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>F5BE3<br>5, WD-<br>WMC6Y<br>OF2K6<br>NV                            | 否 | 2024-04-23 18:08:23.0 | FC-34-97-BF-78-30@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>F5BE3<br>5, WD-<br>WMC6Y<br>OF2K6<br>NV                            | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:32:03   | 04-42-1A-20-1B-9A@BF<br>EBFBF<br>F000A<br>0653@<br>WXC2A<br>11ATC<br>DA, WD-<br>WCC6Y<br>0AZVV<br>NK, 00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_13<br>16_E1<br>A5. | 否 |  |



|     |                   |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                              |                                |   |   |  |
|-----|-------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|------------------------------|--------------------------------|---|---|--|
| 178 | 福建岩创建<br>建设工程有限公司 | 2024-<br>04-22<br>15:23<br>:04.0 | E0-<br>D5-<br>5E-<br>EA-<br>0B-<br>B6@BF<br>EBFBF<br>F0009<br>06E9@<br>S6PFN<br>XOT34<br>7098L  | 否 | 2024-<br>04-22<br>11:04<br>:21.0 | E0-<br>D5-<br>5E-<br>EA-<br>0B-<br>B6, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>S6PFN<br>XOT34<br>7098L | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:34<br>:07 | E0-<br>D5-<br>5E-<br>EA-<br>0B-<br>B6@BF<br>EBFBF<br>F0009<br>06E9@<br>S6PFN<br>XOT34<br>7098L  | 否 |  |
| 179 | 福建京久建<br>设有限公司    | 2024-<br>04-23<br>14:59<br>:53.0 | B4-<br>2E-<br>99-<br>F6-<br>1E-<br>C7@BF<br>EBFBF<br>F0009<br>06EE@<br>334b3<br>73732<br>39304<br>a3430<br>33312<br>03920<br>20202<br>02020 | 否 | 2024-<br>04-23<br>14:57<br>:29.0 | B4-<br>2E-<br>99-<br>F6-<br>1E-<br>C7@BF<br>EBFBF<br>F0009<br>06EB@<br>334b3<br>73732<br>39304<br>a3430<br>33312<br>03920<br>20202<br>02020         | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:37<br>:49 | B4-<br>2E-<br>99-<br>F6-<br>1E-<br>C7@BF<br>EBFBF<br>F0009<br>06EB@<br>334b3<br>73732<br>39304<br>a3430<br>33312<br>03920<br>20202<br>02020 | 否 |  |





|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 182 | 福建普盈建筑工程有限公司 | 2024-04-22 19:09:24.0 | 00-<br>E0-<br>4C-<br>04-<br>FA-<br>E8@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01035                                | 否 | 2024-04-22 19:06:05.0 | 00-<br>E0-<br>4C-<br>04-<br>FA-<br>E8@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01035                                | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:38:13 | 00-<br>E0-<br>4C-<br>04-<br>FA-<br>E8@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01035  | 否 |  |
| 183 | 福建联昊建设工程有限公司 | 2024-04-23 17:31:02.0 | A0-<br>36-<br>BC-<br>08-<br>02-<br>17@BF<br>EBFBF<br>F000A<br>0653@<br>FM600<br>2S224<br>2H000<br>117, W<br>D-<br>WCC6Y<br>ER54C<br>SA | 否 | 2024-04-23 17:20:28.0 | A0-<br>36-<br>BC-<br>08-<br>02-<br>17@BF<br>EBFBF<br>F000A<br>0653@<br>FM600<br>2S224<br>2H000<br>117, W<br>D-<br>WCC6Y<br>ER54C<br>SA | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:30 | A0-<br>36-<br>BC-<br>08-<br>02-<br>17@BF<br>EBFBF<br>F000A<br>0653@<br>4B038<br>1D051<br>C9, FM<br>6002S<br>2242H<br>00011<br>7, WD-<br>WCC6Y<br>ER54C<br>SA | 否 |  |

|     |                       |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                         |                                |  |   |  |
|-----|-----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|--|---|--|
| 184 | 福建和盛达<br>建筑工程有<br>限公司 | 2024-<br>04-22<br>08:37<br>:00.0 | 7C-<br>10-<br>C9-<br>BB-<br>42-<br>6E@BF<br>EBFBF<br>F000A<br>0671@<br>WD-<br>WCC6Y<br>6HZFF<br>LN, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>4A_49<br>18_FE<br>FD. | 否 | 2024-<br>04-22<br>08:25<br>:42.0 | 7C-<br>10-<br>C9-<br>BB-<br>42-<br>6E@BF<br>EBFBF<br>F000A<br>0671@<br>WD-<br>WCC6Y<br>6HZFF<br>LN, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>4A_49<br>18_FE<br>FD. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:41<br>:33 | 7C-<br>10-<br>C9-<br>BB-<br>42-<br>6E@BF<br>EBFBF<br>F000A<br>0671@<br>WD-<br>WCC6Y<br>6HZFF<br>LN, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>4A_49<br>18_FE<br>FD. | 否 |  |
|-----|-----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|--|---|--|



















|     |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 197 | 福建辉禹建设有限公司 | 2024-04-23 10:44:39.0 | 00-<br>E0-<br>4C-<br>4B-<br>3A-<br>47@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WXB2A<br>71DTX<br>ZL,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 | 2024-04-23 10:03:25.0 | 00-<br>E0-<br>4C-<br>4B-<br>3A-<br>47@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WXB2A<br>71DTX<br>ZL,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:33 | 00-<br>E0-<br>4C-<br>4B-<br>3A-<br>47@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WXB2A<br>71DTX<br>ZL,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00_00<br>00. | 否 |  |
| 198 | 中旗华昊建设有限公司 | 2024-04-23 15:20:09.0 | 0C-<br>9D-<br>92-<br>88-<br>98-<br>89@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>00000<br>00594<br>, WD-<br>WX71A<br>78K5Y<br>JR                                    | 否 | 2024-04-23 09:50:42.0 | 0C-<br>9D-<br>92-<br>88-<br>98-<br>89@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>00000<br>00594<br>, WD-<br>WX71A<br>78K5Y<br>JR                                    | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:35 | 0C-<br>9D-<br>92-<br>88-<br>98-<br>89@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>00000<br>00594<br>, WD-<br>WX71A<br>78K5Y<br>JR   | 否 |  |

|     |                   |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |                              |                              |  |   |   |  |
|-----|-------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|------------------------------|------------------------------|--|---|---|--|
| 199 | 福建安顺兴<br>建筑工程有限公司 | 2024-04-23<br>10:27:00.0 | 18-<br>C0-<br>4D-<br>E1-<br>3C-<br>3B@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>D7875<br>8   | 否 | 2024-04-22<br>17:46:38.0 | 18-<br>C0-<br>4D-<br>E1-<br>3C-<br>3B@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>D7875<br>8   | 否 |  |  |  |  |  |  |  |  |                              | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:34:39   | 18-<br>C0-<br>4D-<br>E1-<br>3C-<br>3B@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>D7875<br>8 | 否 |  |
| 200 | 福建鑫舜建<br>设有限公司    | 2024-04-23<br>18:39:32.0 | 00-<br>E2-<br>69-<br>75-<br>C4-<br>7E, BC<br>-5C-<br>17-<br>EA-<br>9C-<br>DB, BC<br>-5C-<br>17-<br>EA-<br>9C-<br>DC, BC<br>-5C-<br>17-<br>EA-<br>9C-<br>DC, BC<br>-5C-<br>17-<br>EA-<br>9C-<br>DC@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A780_<br>5000_<br>0222. | 否 | 2024-04-23<br>18:38:14.0 | 00-<br>E2-<br>69-<br>75-<br>C4-<br>7E, BC<br>-5C-<br>17-<br>EA-<br>9C-<br>DC, BC<br>-5C-<br>17-<br>EA-<br>9C-<br>DC, FE<br>-5C-<br>17-<br>EA-<br>9C-<br>DC, BC<br>-5C-<br>17-<br>EA-<br>9C-<br>DB@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A780_<br>5000_<br>0222. | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:40:13       | 00-<br>E2-<br>69-<br>75-<br>C4-<br>7E, BC<br>-5C-<br>17-<br>EA-<br>9C-<br>DB, BC<br>-5C-<br>17-<br>EA-<br>9C-<br>DC, BC<br>-5C-<br>17-<br>EA-<br>9C-<br>DC@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A780_<br>5000_<br>0222. | 否   |   |  |
| 201 | 福建华榕筑<br>业建设工程    | 2024-04-23               | 58-<br>11-  | 否 | 2024-04-23               | 58-<br>11-  | 否 |  |  |  |  |  |  |  |  |                              | 校验<br>数据                     | 2024-04-24   | 58-<br>11-  | 否 |  |

|     |              |                       |  |            |  |  |   |  |  |  |  |  |  |  |  |  |  |         |             |  |  |   |  |
|-----|--------------|-----------------------|--|------------|--|--|---|--|--|--|--|--|--|--|--|--|--|---------|-------------|--|--|---|--|
|     | 有限公司         | 15:27:39.0            | 22-A0-AD-5D,00-1A-7D-DA-71-11@BFEBFBF00090672@J2209H5503586,W D-WCC3F3HZVAZU | 14:49:37.0 | 22-A0-AD-5D,00-1A-7D-DA-71-11@BFEBFBF00090672@J2209H5503586,W D-WCC3F3HZVAZU |  |   |  |  |  |  |  |  |  |  |  |  | 有误, 请检查 | 08:47:36    | 22-A0-AD-5D,00-1A-7D-DA-71-11@BFEBFBF00090672@J2209H5503586,W D-WCC3F3HZVAZU |  |   |  |
| 202 | 福建宸翰建设工程有限公司 | 2024-04-23 15:38:34.0 | 2C-4D-54-55-AC-61@BFEBFBF000906E9@4535383230443634393034313131313433342032   | 否          | 2024-04-23 15:37:18.0  | 2C-4D-54-55-AC-61@BFEBFBF000906E9@4535383230443634393034313131313433342032 | 否 |  |  |  |  |  |  |  |  |  |  |         | 校验数据有误, 请检查 | 2024-04-24 08:31:53  | 2C-4D-54-55-AC-61@BFEBFBF000906E9@4535383230443634393034313131313433342032 | 否 |  |











|     |            |                       |   |   |                       |  |   |  |  |  |  |                             |                     |   |   |  |
|-----|------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|-----------------------------|---------------------|---|---|--|
| 210 | 福建岚旭建设有限公司 | 2024-04-22 18:54:17.0 | 00-<br>E0-<br>70-<br>B7-<br>26-<br>2D, 00<br>-00-<br>00-<br>00-<br>00-<br>00@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>3JT06<br>D9, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>4A_44<br>EC_A6<br>28. | 否 | 2024-04-22 12:20:39.0 | 00-<br>E0-<br>70-<br>B7-<br>26-<br>2D@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>3JT06<br>D9, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>4A_44<br>EC_A6<br>28. | 否 |  |  |  |  | 校验<br>数据<br>有错误,<br>请<br>检查 | 2024-04-24 08:35:02 | 00-<br>E0-<br>70-<br>B7-<br>26-<br>2D, 00<br>-00-<br>00-<br>00-<br>00-<br>00@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>3JT06<br>D9, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>4A_44<br>EC_A6<br>28. | 否 |  |
|-----|------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|-----------------------------|---------------------|---|---|--|



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 213 | 宁化恒生建设工程有限公司 | 2024-04-23 16:51:31.0 | 18-CO-4D-CE-7F-66,50-2B-73-CC-9E-7B@BF EBFBF F000A 0653@ EAGET 20210 92980 1013, WD-WCC6Y 7PZC5 PP | 否 | 2024-04-23 16:49:59.0 | 18-CO-4D-CE-7F-66,50-2B-73-CC-9E-7B@BF EBFBF F000A 0653@ EAGET 20210 92980 1013, WD-WCC6Y 7PZC5 PP | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:39 | 18-CO-4D-CE-7F-66,50-2B-73-CC-9E-7B@BF EBFBF F000A 0653@ EAGET 20210 92980 1013, WD-WCC6Y 7PZC5 PP | 否 |  |
| 214 | 福建潭晟建筑工程有限公司 | 2024-04-22 14:57:37.0 | 74-56-3C-2E-8F-B5@BF EBFBF F000A 0653@ WD-WCC6Y 59HNF H5,50 026B7 381E5 E260                       | 否 | 2024-04-22 08:49:15.0 | 74-56-3C-2E-8F-B5@BF EBFBF F000A 0653@ WD-WCC6Y 59HNF H5,50 026B7 381E5 E260                       | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:10 | 74-56-3C-2E-8F-B5@BF EBFBF F000A 0653@ WD-WCC6Y 59HNF H5,50 026B7 381E5 E260                       | 否 |  |

|     |                   |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |                         |                            |   |   |  |
|-----|-------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|-------------------------|----------------------------|---|---|--|
| 215 | 福建省石嵩<br>建筑工程有限公司 | 2024-04-23<br>13:23<br>:14.0 | 00-<br>E0-<br>70-<br>B5-<br>C3-<br>34@BF<br>EBFBF<br>F0009<br>06EB@<br>4E078<br>3D15D<br>C9, 20<br>12964<br>65606   | 否 | 2024-04-23<br>13:21<br>:58.0 | 00-<br>E0-<br>70-<br>B5-<br>C3-<br>34@BF<br>EBFBF<br>F0009<br>06EB@<br>4E078<br>3D15D<br>C9, 20<br>12964<br>65606   | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:38<br>:05 | 00-<br>E0-<br>70-<br>B5-<br>C3-<br>34@BF<br>EBFBF<br>F0009<br>06EB@<br>4E078<br>3D15D<br>C9, 20<br>12964<br>65606   | 否 |  |
| 216 | 福建省鼎鹏<br>建设工程有限公司 | 2024-04-22<br>11:04<br>:48.0 | 0C-<br>9D-<br>92-<br>C0-<br>81-<br>25, 00<br>-07-<br>0A-<br>10-<br>2B-<br>1D@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>7ZN2Z<br>KH, MG<br>19020<br>00000<br>00035<br>621 | 否 | 2024-04-22<br>10:02<br>:52.0 | 00-<br>07-<br>0A-<br>10-<br>2B-<br>1D, 0C<br>-9D-<br>92-<br>C0-<br>81-<br>25@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>7ZN2Z<br>KH, MG<br>19020<br>00000<br>00035<br>621 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:41<br>:26 | 0C-<br>9D-<br>92-<br>C0-<br>81-<br>25, 00<br>-07-<br>0A-<br>10-<br>2B-<br>1D@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>7ZN2Z<br>KH, MG<br>19020<br>00000<br>00035<br>621 | 否 |  |



|     |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |  |                            |   |  |
|-----|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|--|----------------------------|---|--|
| 219 | 武夷山市东晖建设工程有限公司 | 2024-04-23 16:41:48.0 | E0-D5-5E-47-B3-CF@BF EBFBF F0009 06E9@ I1530 8J028 818, Y 76SVL UMS, 1 BC16A F0635 9   | 否 | 2024-04-23 16:39:34.0 | E0-D5-5E-47-B3-CF, 00 -00- 00- 00- 00- 00- 00- 00- 00- E0@BF EBFBF F0009 06E9@ I1530 8J028 818, Y 76SVL UMS, 1 BC16A F0635 9 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:54:10 | E0-D5-5E-47-B3-CF@BF EBFBF F0009 06E9@ I1530 8J028 818, Y 76SVL UMS, 1 BC16A F0635 9 | 否  |                            |   |  |
| 220 | 福建佐寅建设发展有限公司   | 2024-04-23 19:15:10.0 | C8-7F-54-9F-2E-57@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 707C_ 1802_ 0629_ A201. | 否 | 2024-04-23 18:49:24.0 | C8-7F-54-9F-2E-57@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 707C_ 1802_ 0629_ A201.                                       | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:33:16  | C8-7F-54-9F-2E-57@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 707C_ 1802_ 0629_ A201. | 否                          |   |  |
| 221 | 福建尧诚建筑工程有限公司   | 2024-04-23 14:14:43.0 | FC-AA-14-F0-43-F9@BF EBFBF   | 否 | 2024-04-23 14:13:57.0 | FC-AA-14-F0-43-F9, 00 -00-   | 否 |  |  |  |  |  |  |  |  |  |              |                     | 校验数据有错误, 请检查   | 2024-04-24 08:34:19  | FC-AA-14-F0-43-F9@BF EBFBF | 否 |  |





|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 222 | 福建西乾建设工程有限公司 | 2024-04-23 10:43:46.0 | 00-<br>E0-<br>1E-<br>32-<br>90-<br>07@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0062_<br>5603_<br>3556.<br>,WD-<br>WX34P<br>3KN65<br>44 | 否 | 2024-04-19 16:44:35.0 | 00-<br>E0-<br>1E-<br>32-<br>90-<br>07@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0062_<br>5603_<br>3556.<br>,WD-<br>WX34P<br>3KN65<br>44 | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:28 | 00-<br>E0-<br>1E-<br>32-<br>90-<br>07@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0062_<br>5603_<br>3556.<br>,WD-<br>WX34P<br>3KN65<br>44 | 否 |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|









|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 227 | 福建省熊政建设工程有限公司  | 2024-04-23 08:51:39.0 | 0C-9D-92-89-A7-C5@BFEBFBFF000906EA@RW19127259C5013  | 否 | 2024-04-23 08:47:28.0 | 0C-9D-92-89-A7-C5@BFEBFBFF000906EA@RW19127259C5013  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:45 | 0C-9D-92-89-A7-C5@BFEBFBFF000906EA@RW19127259C5013  | 否 |  |
| 228 | 中建天润建设(福建)有限公司 | 2024-04-22 16:49:21.0 | 06-5C-C2-E9-10-95,0A-5C-C2-E9-10-95,A8-5E-45-16-0F-EC,00-5C-C2-E9-10-95@178BFBF00800F82@WD-WCC6Y1NZ9NZS,0100_0000_0000. | 否 | 2024-04-16 10:27:26.0 | 00-5C-C2-E9-10-95,06-5C-C2-E9-10-95,0A-5C-C2-E9-10-95,0A-5C-C2-E9-10-95,A8-5C-C2-E9-10-95,A8-5E-45-16-0F-EC@178BFBF00800F82@WD-WCC6Y1NZ9NZS,0100_0000_0000. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:41:35 | 06-5C-C2-E9-10-95,0A-5C-C2-E9-10-95,A8-5E-45-16-0F-EC,00-5C-C2-E9-10-95@178BFBF00800F82@WD-WCC6Y1NZ9NZS,0100_0000_0000. | 否 |  |







|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 231 | 福建省中兴建设发展有限公司 | 2024-04-23 11:12:58.0 | D8-43-AE-15-82-79@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B778_5603_4775.                    | 否 | 2024-04-23 11:08:12.0 | D8-43-AE-15-82-79@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B778_5603_4775.                    | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:18 | D8-43-AE-15-82-79@BF EBFBF F0009 0675@6,000_0_000_0_000_0_002_6_B77_8_560_3_477_5.                | 否 |  |
| 232 | 福建省腾众建设工程有限公司 | 2024-04-22 17:25:21.0 | 58-11-22-0F-09-9B@BF EBFBF F0009 0672@0000_0000_0000_0000_0026_B738_1812_7665., WD-WCC6Y 4KS5S DK | 否 | 2024-04-22 17:24:03.0 | 58-11-22-0F-09-9B@BF EBFBF F0009 0672@0000_0000_0000_0000_0026_B738_1812_7665., WD-WCC6Y 4KS5S DK | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:31:41 | 58-11-22-0F-09-9B@BF EBFBF F0009 0672@0000_0000_0000_0000_0026_B738_1812_7665., WD-WCC6Y 4KS5S DK | 否 |  |



|     |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|---|--|
| 235 | 福建三明似锦建设有限公司 | 2024-04-23 15:58:41.0 | 00-00-00-00-00-00, E0-D5-5E-C4-33-DC, 00-00-00-00-00-00-00-00-00, E0-D5-5E-C4-33-DC@BF EBFBF F0009 06E9@304b3 23930 34305 23230 33392 03520 20202 02020 | 否 | 2024-04-23 15:57:03.0 | E0-D5-5E-C4-33-DC, 00-00-00-00-00-00-00-00-00, E0-D5-5E-C4-33-DC@BF EBFBF F0009 06E9@304b3 23930 34305 23230 33392 03520 20202 02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:45 | 00-00-00-00-00-00, E0-D5-5E-C4-33-DC@BF EBFBF F0009 06E9@304b3 23930 34305 23230 33392 03520 20202 02020 | 否   |   |  |
| 236 | 福建轩晨建设工程有限公司 | 2024-04-22 17:04:03.0 | A4-0C-66-01-5F-35@BF EBFBF F0009 06EA@WD-WCC6Y 6FN1Y 16, AA 00000 00000 00003 138   | 否 | 2024-04-22 17:00:26.0 | A4-0C-66-01-5F-35@BF EBFBF F0009 06EA@WD-WCC6Y 6FN1Y 16, AA 00000 00000 00003 138  | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:34:44  | A4-0C-66-01-5F-35@BF EBFBF F0009 06EA@WD-WCC6Y 6FN1Y 16, AA 00000 00000 00003 138 | 否 |  |



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|--|
| 239 | 福建同欣建设工程有限公司 | 2024-04-19 18:08:40.0 | E0-D5-5E-2F-8A-5F, 00-00-00-00-00-00-06E9@57523931313730323731354131302034202020, 2020202057202d4443573643365955455a313459 | 否 | 2024-04-19 17:55:33.0 | E0-D5-5E-2F-8A-5F, 00-00-00-00-00-00-06E9@57523931313730323731354131302034202020, 2020202057202d4443573643365955455a313459 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:47 | E0-D5-5E-2F-8A-5F, 00-00-00-00-00-00-06E9@57523931313730323731354131302034202020, 2020202057202d4443573643365955455a313459 | 否 |  |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|--|

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 240 | 福建省擎冠建设工程有限公司 | 2024-04-22 11:20:39.0 | 00-<br>E0-<br>1C-<br>47-<br>80-<br>71, 50<br>-2B-<br>73-<br>DD-<br>DE-<br>F5, 50<br>-2B-<br>73-<br>DD-<br>DE-<br>F4@BF<br>EBFBF<br>F0009<br>06E9@<br>S3YKN<br>XOM23<br>7791B | 否 | 2024-04-22 10:23:49.0 | 00-<br>E0-<br>1C-<br>47-<br>80-<br>71, 50<br>-2B-<br>73-<br>DD-<br>DE-<br>F5, 50<br>-2B-<br>73-<br>DD-<br>DE-<br>F4@BF<br>EBFBF<br>F0009<br>06E9@<br>S3YKN<br>XOM23<br>7791B | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:02 | 00-<br>E0-<br>1C-<br>47-<br>80-<br>71, 50<br>-2B-<br>73-<br>DD-<br>DE-<br>F5, 50<br>-2B-<br>73-<br>DD-<br>DE-<br>F4@BF<br>EBFBF<br>F0009<br>06E9@<br>S3YKN<br>XOM23<br>7791B | 否 |  |
| 241 | 福建仕霆建设工程有限公司  | 2024-04-23 16:36:59.0 | 50-<br>EB-<br>F6-<br>42-<br>69-<br>96@BF<br>EBFBF<br>F000A<br>0653@<br>WCC6Y<br>7VECZ<br>A3, 50<br>026B7<br>7849E<br>C82B  | 否 | 2024-04-23 16:36:09.0 | 50-<br>EB-<br>F6-<br>42-<br>69-<br>96@BF<br>EBFBF<br>F000A<br>0653@<br>WCC6Y<br>7VECZ<br>A3, 50<br>026B7<br>7849E<br>C82B  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:12 | 50-<br>EB-<br>F6-<br>42-<br>69-<br>96@BF<br>EBFBF<br>F000A<br>0653@<br>WCC6Y<br>7VECZ<br>A3, 50<br>026B7<br>7849E<br>C82B  | 否 |  |









|     |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                                   |                                |   |   |  |
|-----|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|-----------------------------------|--------------------------------|---|---|--|
| 246 | 厦门建加顺<br>建筑工程有<br>限公司 | 2024-<br>04-17<br>17:30<br>:52.0 | 04-<br>7C-<br>16-<br>B8-<br>04-<br>B4@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>6561_<br>AEC5. | 否 | 2024-<br>04-16<br>15:38<br>:29.0 | 04-<br>7C-<br>16-<br>B8-<br>04-<br>B4@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>6561_<br>AEC5.                                 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查<br>检 | 2024-<br>04-24<br>08:48<br>:14 | 04-<br>7C-<br>16-<br>B8-<br>04-<br>B4@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>6561_<br>AEC5. | 否 |  |
| 247 | 福建省侨达<br>建筑有限公<br>司   | 2024-<br>04-22<br>08:19<br>:44.0 | 00-<br>E0-<br>70-<br>8D-<br>A3-<br>0F@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCAWF<br>57173<br>58, J2<br>113J5<br>50296<br>5               | 否 | 2024-<br>04-22<br>08:18<br>:16.0 | 00-<br>E0-<br>70-<br>8D-<br>A3-<br>0F, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCAWF<br>57173<br>58, J2<br>113J5<br>50296<br>5 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查<br>检 | 2024-<br>04-24<br>08:31<br>:52 | 00-<br>E0-<br>70-<br>8D-<br>A3-<br>0F@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCAWF<br>57173<br>58, J2<br>113J5<br>50296<br>5               | 否 |  |



|     |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 249 | 福建馨江建设有限公司 | 2024-04-23 11:21:42.0 | 50-EB-F6-1E-70-92@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>2E5FC<br>F | 否 | 2024-04-23 11:12:43.0 | 50-EB-F6-1E-70-92@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>2E5FC<br>F | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:31:02 | 50-EB-F6-1E-70-92@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>2E5FC<br>F | 否 |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|

|     |            |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|-----|------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 250 | 福建一穗建设有限公司 | 2024-04-21 12:04:42.0 | EC-D6-8A-C1-D5-66, F0-42-1C-5E-DD-68, F0-42-1C-5E-DD-64, F0-42-1C-5E-DD-65, F2-42-1C-5E-DD-64@BF EBFBF F000A 0653@ E823_8FA6_ BF53_ 0001_ 001B_ 448B_ 4BCD_ C3AC. | 否 | 2024-04-21 11:57:31.0 | EC-D6-8A-C1-D5-66, F0-42-1C-5E-DD-65, F2-42-1C-5E-DD-64, F0-42-1C-5E-DD-68@BF EBFBF F000A 0653@ E823_8FA6_ BF53_ 0001_ 001B_ 448B_ 4BCD_ C3AC. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:52 | EC-D6-8A-C1-D5-66, F0-42-1C-5E-DD-68, F0-42-1C-5E-DD-64, F0-42-1C-5E-DD-65, F2-42-1C-5E-DD-64@BF EBFBF F000A 0653@ E823_8FA6_ BF53_ 0001_ 001B_ 448B_ 4BCD_ C3AC. | 否   |   |  |
| 251 | 泱楠建设发展有限公司 | 2024-04-22 11:18:18.0 | 4C-ED-FB-6A-E5-07@BF EBFBF F0009 06E9@ 1837A 98039 04   | 否 | 2024-04-22 10:42:12.0 | 4C-ED-FB-6A-E5-07@BF EBFBF F0009 06E9@ 1837A 98039 04  | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:34:07   | 4C-ED-FB-6A-E5-07@BF EBFBF F0009 06E9@ 1837A 98039 04 | 否 |  |

|     |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 252 | 福建省良民乾劲建设工程有限公司 | 2024-04-22 15:58:01.0 | 74-56-3C-69-83-72@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>72WVR<br>L3, 64<br>79_A7<br>73_EA<br>50_03<br>EA. | 否 | 2024-04-22 10:28:48.0 | 74-56-3C-69-83-72@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>72WVR<br>L3, 64<br>79_A7<br>73_EA<br>50_03<br>EA. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:50 | 74-56-3C-69-83-72@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>72WVR<br>L3, 64<br>79_A7<br>73_EA<br>50_03<br>EA. | 否 |  |
| 253 | 福建采梦建设有限公司      | 2024-04-23 08:21:48.0 | F4-B5-20-12-5A-A0@BF<br>EBFBF<br>F0009<br>06EB@<br>DAAFO<br>71417<br>00000<br>82013<br>, AA18<br>12165<br>694        | 否 | 2024-04-23 08:20:32.0 | F4-B5-20-12-5A-A0@BF<br>EBFBF<br>F0009<br>06EB@<br>DAAFO<br>71417<br>00000<br>82013<br>, AA18<br>12165<br>694        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:39:38 | F4-B5-20-12-5A-A0@BF<br>EBFBF<br>F0009<br>06EB@<br>DAAFO<br>71417<br>00000<br>82013<br>, AA18<br>12165<br>694        | 否 |  |





|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 256 | 福建东坤建设有限公司   | 2024-04-22 16:54:35.0 | E8-9C-25-47-0B-B6, 50-2B-73-D5-4E-E4@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B768_6686_AEA5. | 否 | 2024-04-22 16:52:57.0 | E8-9C-25-47-0B-B6, 50-2B-73-D5-4E-E4@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B768_6686_AEA5. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:56:14 | E8-9C-25-47-0B-B6, 50-2B-73-D5-4E-E4@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B768_6686_AEA5. | 否 |  |
| 257 | 福建弘辉建设工程有限公司 | 2024-04-23 08:18:17.0 | B8-97-5A-F8-D6-29@BF EBFBF F0005 06E3@WD-WCC6Y 6CEKPD9  | 否 | 2024-04-22 17:27:56.0 | B8-97-5A-F8-D6-29, 00-00-00-00-00-E0, 00-00-00-00-00-E0@BF EBFBF F0005 06E3@WD-WCC6Y 6CEKPD9      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:41 | B8-97-5A-F8-D6-29@BF EBFBF F0005 06E3@WD-WCC6Y 6CEKPD9  | 否 |  |

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 258 | 福建杰创盛工程咨询有限公司 | 2024-04-23 09:18:29.0 | D8-BB-C1-D8-CB-DB@BF EBFBF F000A 0653@ 0000_0000_0000_0000_0026_B778_4801_46A5.                   | 否 | 2024-04-23 09:13:53.0 | D8-BB-C1-D8-CB-DB@BF EBFBF F000A 0653@ 0000_0000_0000_0000_0026_B778_4801_46A5.             | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:39 | D8-BB-C1-D8-CB-DB@BF EBFBF F000A 0653@ 0000_0000_0000_0000_0026_B778_4801_46A5. , 2207 11154 22727 89520 923 | 否 |  |
| 259 | 福建丰利建设工程有限公司  | 2024-04-23 18:19:06.0 | 74-56-3C-A5-BB-7C@BF EBFBF F0009 0672@ WW61F 3D7,0 000_0 000_0 000_0 000_0 026_B 738_2 457_3 E05. | 否 | 2024-04-18 11:50:15.0 | 74-56-3C-A5-BB-7C@BF EBFBF F0009 0672@ WW61F 3D7,0 000_0 000_0 000_0 026_B 738_2 457_3 E05. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:07 | 74-56-3C-A5-BB-7C@BF EBFBF F0009 0672@ WW61F 3D7,0 000_0 000_0 000_0 026_B 738_2 457_3 E05.                  | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |           |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-----------|---------------------|--|---|--|
| 260 | 福建省元庆建设发展有限公司 | 2024-04-22 17:37:24.0 | F4-B5-20-0D-D3-B6@BF EBFBF F0009 06E9@ 2J102 00755 52, 50 026B7 3809B 3C5D             | 否 | 2024-04-22 17:31:52.0 | F4-B5-20-0D-D3-B6@BF EBFBF F0009 06E9@ 2J102 00755 52, 50 026B7 3809B 3C5D             | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:34:47 | F4-B5-20-0D-D3-B6@BF EBFBF F0009 06E9@ 2J102 00755 52, 50 026B7 3809B 3C5D             | 否 |  |
| 261 | 江西国金建设集团有限公司  | 2024-04-22 08:10:51.0 | 74-56-3C-A8-7A-DD@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 245D_ 4565. | 否 | 2024-04-19 16:08:40.0 | 74-56-3C-A8-7A-DD@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 245D_ 4565. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:32:43 | 74-56-3C-A8-79-55@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 245D_ 4945. | 否 |  |
| 262 | 福建舜晟建设工程有限公司  | 2024-04-23 10:35:17.0 | A4-0C-66-06-74-BD@BF EBFBF F0009 06EB@ WD-WCC3F 33084 66, CN 409BB 13080 76            | 否 | 2024-04-23 10:32:29.0 | A4-0C-66-06-74-BD@BF EBFBF F0009 06EB@ WD-WCC3F 33084 66, CN 409BB 13080 76            | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:31:46 | A4-0C-66-06-74-BD@BF EBFBF F0009 06EB@ WD-WCC3F 33084 66, CN 409BB 13080 76            | 否 |  |



|     |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 264 | 福建坤固建设有限公司 | 2024-04-23 21:43:44.0 | 08-BF-B8-74-65-84@BF<br>EBFBF<br>F00A<br>0655@<br>E823_8FA6_ BF53_0001_001B_448B_4A6E_ E8C4.<br>, WD-<br>WCC6Y<br>OCPA8<br>4J | 否 | 2024-04-23 17:13:58.0 | 08-BF-B8-74-65-84@BF<br>EBFBF<br>F00A<br>0655@<br>E823_8FA6_ BF53_0001_001B_448B_4A6E_ E8C4.<br>, WD-<br>WCC6Y<br>OCPA8<br>4J | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:47 | 08-BF-B8-74-65-84@BF<br>EBFBF<br>F00A<br>0655@<br>E823_8FA6_ BF53_0001_001B_448B_4A6E_ E8C4.<br>, WD-<br>WCC6Y<br>OCPA8<br>4J | 否 |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 266 | 福建当先建设工程有限公司 | 2024-04-23 19:36:34.0 | FC-34-97-12-B3-C8, 50-2B-73-E4-59-0A, 50-2B-73-E4-59-OA@BF EBFBF F000A 0653@0025_3884_0100_681A.                     | 否 | 2024-04-23 19:35:27.0 | FC-34-97-12-B3-C8, 50-2B-73-E4-59-0A, 50-2B-73-E4-59-OA@BF EBFBF F000A 0653@0025_3884_0100_681A.                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:43:34 | FC-34-97-12-B3-C8, 50-2B-73-E4-59-0A, 50-2B-73-E4-59-OA@BF EBFBF F000A 0653@0025_3884_0100_681A.                     | 否 |  |
| 267 | 福建泰舜建工有限公司   | 2024-04-22 15:21:58.0 | 58-11-22-D1-6F-99, 88-00-66-99-CB-DE@BF EBFBF F0009 0672@E823_8FA6_BF53_0001_001B_444A_48ED_3004., WD-WCC6Y 5RMTN 11 | 否 | 2024-04-22 15:20:42.0 | 88-00-66-99-CB-DE, 58-11-22-D1-6F-99@BF EBFBF F0009 0672@E823_8FA6_BF53_0001_001B_444A_48ED_3004., WD-WCC6Y 5RMTN 11 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:16 | 88-00-66-99-CB-DE, 58-11-22-D1-6F-99@BF EBFBF F0009 0672@E823_8FA6_BF53_0001_001B_444A_48ED_3004., WD-WCC6Y 5RMTN 11 | 否 |  |

|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|--|---|--|
| 268 | 福建润柏建设工程有限公司 | 2024-04-23 09:58:01.0 | 74-56-3C-6E-A9-93@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 21E5_ 0795. | 否 | 2024-04-23 09:48:04.0 | 74-56-3C-6E-A9-93@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 21E5_ 0795. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:14 | 74-56-3C-6E-A9-93@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 21E5_ 0795. | 否  |   |  |
| 269 | 福建联威工程建设有限公司 | 2024-04-22 08:27:09.0 | 74-56-3C-7B-9F-32@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4EC9_ A448. | 否 | 2024-04-18 08:52:48.0 | 74-56-3C-7B-9F-32@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4EC9_ A448. | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:31:19  | 74-56-3C-7B-9F-32@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4EC9_ A448. | 否 |  |



|     |                   |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |  |  |                             |                        |  |   |  |
|-----|-------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|--|-----------------------------|------------------------|--|---|--|
| 270 | 福建鑫晟嵘<br>建筑工程有限公司 | 2024-04-23<br>13:07:40.0 | E0-<br>D5-<br>5E-<br>36-<br>A8-<br>24@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01125<br>, WD-<br>WCC6Y<br>5ULKD<br>H4 | 否 | 2024-04-23<br>13:06:25.0 | E0-<br>D5-<br>5E-<br>36-<br>A8-<br>24@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01125<br>, WD-<br>WCC6Y<br>5ULKD<br>H4 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>, 请<br>检查 | 2024-04-24<br>08:36:02 | E0-<br>D5-<br>5E-<br>36-<br>A8-<br>24@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01125<br>, WD-<br>WCC6Y<br>5ULKD<br>H4 | 否 |  |
|-----|-------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|--|-----------------------------|------------------------|--|---|--|



|     |                   |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |                      |                        |  |  |   |  |
|-----|-------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|----------------------|------------------------|--|--|---|--|
| 272 | 福建省本盛<br>建筑工程有限公司 | 2024-04-22<br>15:43:06.0 | 58-11-22-0A-1B-DF@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>MFMEP<br>7U, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4E<br>48_22<br>EC. | 否 | 2024-04-22<br>15:41:43.0 | 58-11-22-0A-1B-DF@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>MFMEP<br>7U, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4E<br>48_22<br>EC. | 否 |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>检查 | 2024-04-24<br>08:35:40 | 58-11-22-0A-1B-DF@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>MFMEP<br>7U, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4E<br>48_22<br>EC. | 否  |   |  |
| 273 | 福建润旭建<br>筑工程有限公司  | 2024-04-22<br>15:34:50.0 | 04-D9-F5-20-B7-1D@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>339D6<br>9, WD-<br>WMC2E<br>20092<br>99   | 否 | 2024-04-22<br>15:31:21.0 | 04-D9-F5-20-B7-1D@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>339D6<br>9, WD-<br>WMC2E<br>20092<br>99   | 否 |  |  |  |  |  |  |  |  |                      | 校验数据有<br>误, 请查<br>检查   | 2024-04-24<br>08:36:34   | 04-D9-F5-20-B7-1D@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>339D6<br>9, WD-<br>WMC2E<br>20092<br>99 | 否 |  |

|     |                       |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
|-----|-----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|
| 274 | 福建省三屿<br>建筑工程有<br>限公司 | 2024-<br>04-23<br>08:58<br>:17.0 | F4-<br>6B-<br>8C-<br>C7-<br>52-<br>0B@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>7DEKP<br>14 | 否 | 2024-<br>04-22<br>10:39<br>:15.0 | F4-<br>6B-<br>8C-<br>C7-<br>52-<br>0B@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>7DEKP<br>14 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:45<br>:19 | F4-<br>6B-<br>8C-<br>C7-<br>52-<br>0B@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>7DEKP<br>14 | 否 |  |
|-----|-----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 276 | 福建田丹建设工程有限公司 | 2024-04-23 09:47:46.0 | 58-11-22-9E-C8-53, 50-2B-73-D8-2E-89, 04-7F-0E-0A-85-07@BF EBFBF F0009 0675@0000_0000_0000_0000_707C_1802_1502_A70D. | 否 | 2024-04-23 09:45:52.0 | 58-11-22-9E-C8-53, 50-2B-73-D8-2E-89, 04-7F-0E-0A-85-07@BF EBFBF F0009 0675@0000_0000_0000_0000_707C_1802_1502_A70D. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:39:47 | 58-11-22-9E-C8-53, 50-2B-73-D8-2E-89, 04-7F-0E-0A-85-07@BF EBFBF F0009 0675@0000_0000_0000_0000_707C_1802_1502_A70D. | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|









|     |                    |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|-----|--------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
|     |                    |                                  | 70890<br>6238   |   |                                  | 70890<br>6238   |   |  |  |  |  |  |  |  |  |  |  |                            | 70890<br>6238                  |   |   |  |
| 282 | 福建省瑞方<br>展建筑工程有限公司 | 2024-<br>04-23<br>09:46<br>:13.0 | 2C-<br>F0-<br>5D-<br>F5-<br>52-<br>AB@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0100_<br>0000_<br>00E0_<br>4C14_<br>4922_<br>BA6C. | 否 | 2024-<br>04-23<br>09:42<br>:22.0 | 2C-<br>F0-<br>5D-<br>F5-<br>52-<br>AB@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0100_<br>0000_<br>00E0_<br>4C14_<br>4922_<br>BA6C. | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:34<br>:07 | 2C-<br>F0-<br>5D-<br>F5-<br>52-<br>AB@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0100_<br>0000_<br>00E0_<br>4C14_<br>4922_<br>BA6C. | 否 |  |
| 283 | 河南道烈建<br>筑工程有限公司   | 2024-<br>04-23<br>15:53<br>:12.0 | 00-<br>E0-<br>1F-<br>4F-<br>53-<br>E4@BF<br>EBFBF<br>F0009<br>0675@<br>A5105<br>12Y23<br>37720<br>1   | 否 | 2024-<br>04-23<br>15:51<br>:50.0 | 00-<br>E0-<br>1F-<br>4F-<br>53-<br>E4@BF<br>EBFBF<br>F0009<br>0675@<br>A5105<br>12Y23<br>37720<br>1   | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:34<br>:07 | 00-<br>E0-<br>1F-<br>4F-<br>53-<br>E4@BF<br>EBFBF<br>F0009<br>0675@<br>A5105<br>12Y23<br>37720<br>1   | 否 |  |















|     |               |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 292 | 福建省君龙建设发展有限公司 | 2024-04-20 19:27:17.0 | 6C-4B-90-56-20-CD, 34-41-5D-9B-CD-95, 34-41-5D-9B-CD-91, 34-41-5D-9B-CD-92, 36-41-5D-9B-CD-91, 34-41-5D-9B-CD-95@BF EBFBF F0009 06E9@Z9AQ4 RGY | 否 | 2024-04-20 19:25:11.0 | 6C-4B-90-56-20-CD, 36-41-5D-9B-CD-91, 34-41-5D-9B-CD-92, 34-41-5D-9B-CD-91, 34-41-5D-9B-CD-95@BF EBFBF F0009 06E9@Z9AQ4 RGY | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:35 | 3C-58-C2-92-FC-29, 2C-F0-5D-40-B2-01, 3C-58-C2-92-FC-25, 3C-58-C2-92-FC-26, 3E-58-C2-92-FC-25@BF EBFBF F000A 0653@50026 B7380 A41797 | 否 |  |
|-----|---------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|







|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|---|--|
| 299 | 福建永畅通建设工程有限公司  | 2024-04-22 09:13:28.0 | 74-56-3C-E7-42-FE@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2645_<br>1975. | 否 | 2024-04-22 08:49:58.0 | 74-56-3C-E7-42-FE@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2645_<br>1975. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:31:54 | 74-56-3C-E7-42-FE@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2645_<br>1975. | 否   |   |   |  |
| 300 | 福建省新长欣建设工程有限公司 | 2024-04-19 11:03:16.0 | 58-11-22-C0-A0-8B@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E90_<br>7AA2. | 否 | 2024-04-19 10:40:15.0 | 58-11-22-C0-A0-8B@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E90_<br>7AA2. | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:33:07   | 58-11-22-C0-A0-8B@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E90_<br>7AA2. | 否   |   |  |
| 301 | 福建创福建建设有限公司    | 2024-04-23 09:43:08.0 | 24-4B-FE-D0-43-44@BF<br>EBFBF<br>F000A<br>0653@<br>MG201<br>05000<br>00000<br>02383<br>,WD-                             | 否 | 2024-04-22 16:32:17.0 | 24-4B-FE-D0-43-44@BF<br>EBFBF<br>F000A<br>0653@<br>MG201<br>05000<br>00000<br>02383<br>,WD-                             | 否 |  |  |  |  |  |  |  |  |  |             |                     | 校验数据有错误，请检查   | 2024-04-24 08:32:15   | 24-4B-FE-D0-43-44@BF<br>EBFBF<br>F000A<br>0653@<br>MG201<br>05000<br>00000<br>02383<br>,WD- | 否 |  |









|     |                        |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                         |                                |   |   |   |  |
|-----|------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|---|---|---|--|
| 307 | 泉州市建祥<br>建筑工程有<br>限公司  | 2024-<br>04-23<br>11:18<br>:17.0 | D8-<br>BB-<br>C1-<br>CB-<br>F1-<br>91@BF<br>EBFBF<br>F000A<br>0653@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>448B<br>41D6<br>89D0.<br>, WD-<br>WCC6Y<br>4XAXN<br>J9 | 否 | 2024-<br>04-23<br>11:13<br>:36.0 | D8-<br>BB-<br>C1-<br>CB-<br>F1-<br>91@BF<br>EBFBF<br>F000A<br>0653@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>448B<br>41D6<br>89D0.<br>, WD-<br>WCC6Y<br>4XAXN<br>J9 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:33<br>:28 | D8-<br>BB-<br>C1-<br>CB-<br>F1-<br>91@BF<br>EBFBF<br>F000A<br>0653@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>448B<br>41D6<br>89D0.<br>, WD-<br>WCC6Y<br>4XAXN<br>J9 | 否   |   |  |
| 308 | 福建天裕卓<br>鼎建设工程<br>有限公司 | 2024-<br>04-22<br>15:26<br>:53.0 | 40-<br>B0-<br>76-<br>5C-<br>74-<br>4E@BF<br>EBFBF<br>F0009<br>06EA@<br>S3UFN<br>XOMBO<br>7116,<br>WD-<br>WCC4J<br>OXCAU<br>H2   | 否 | 2024-<br>04-22<br>14:59<br>:24.0 | 40-<br>B0-<br>76-<br>5C-<br>74-<br>4E@BF<br>EBFBF<br>F0009<br>06EA@<br>S3UFN<br>XOMBO<br>7116,<br>WD-<br>WCC4J<br>OXCAU<br>H2   | 否 |  |  |  |  |  |  |  |  |  |                         | 校验<br>数据有<br>误, 请<br>检查        | 2024-<br>04-24<br>08:58<br>:15  | 40-<br>B0-<br>76-<br>5C-<br>74-<br>4E@BF<br>EBFBF<br>F0009<br>06EA@<br>S3UFN<br>XOMBO<br>7116,<br>WD-<br>WCC4J<br>OXCAU<br>H2 | 否 |  |



|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 310 | 福建省洛然建设发展有限公司 | 2024-04-23 17:12:55.0 | A0-36-BC-0B-1F-9D@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>16D7_<br>A995.<br>,XOMG<br>WE3MS    | 否 | 2024-04-23 17:12:02.0 | A0-36-BC-0B-1F-9D@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>16D7_<br>A995.<br>,XOMG<br>WE3MS    | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:31:37 | A0-36-BC-0B-1F-9D@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>16D7_<br>A995.<br>,XOMG<br>WE3MS    | 否 |  |
| 311 | 河南海马建设工程有限公司  | 2024-04-23 16:17:36.0 | 1E-BF-CE-93-10-CD, 1C-BF-CE-93-10-CD, 3C-7C-3F-24-4B-C6, 1C-BF-CE-93-10-CD@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>82100<br>09141 | 否 | 2024-04-23 16:16:58.0 | 1E-BF-CE-93-10-CD, 1C-BF-CE-93-10-CD, 3C-7C-3F-24-4B-C6, 1C-BF-CE-93-10-CD@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>82100<br>09141 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:41 | 1E-BF-CE-93-10-CD, 1C-BF-CE-93-10-CD, 3C-7C-3F-24-4B-C6, 1C-BF-CE-93-10-CD@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>82100<br>09141 | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 312 | 福建宇赫建筑工程有限公司 | 2024-04-23 08:50:10.0 | 58-11-22-B4-54-53@BFEBFBFF00090675@0000_0000_0000_0000_4868_3400_0000_0000. | 否 | 2024-04-23 08:49:51.0 | 58-11-22-B4-54-53@BFEBFBFF00090675@0000_0000_0000_0000_4868_3400_0000_0000. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:29 | 58-11-22-B4-54-53@BFEBFBFF00090675@0000_0000_0000_0000_4868_3400_0000_0000. | 否 |  |
| 313 | 厦门闽狮建设工程有限公司 | 2024-04-22 16:18:41.0 | 00-E0-70-D7-BE-B1,00-00-00-00-00-00-E0@178BFBF00660F01@SN215208952997       | 否 | 2024-04-22 14:59:28.0 | 00-E0-70-D7-BE-B1,00-00-00-00-00-00-E0@178BFBF00660F01@SN215208952997       | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:57:54 | 00-E0-70-D7-BE-B1,00-00-00-00-00-00-E0@178BFBF00660F01@SN215208952997       | 否 |  |

|     |                       |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |  |                        |                            |   |   |  |
|-----|-----------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------------------|----------------------------|---|---|--|
| 314 | 福建朗月城<br>建设有限公司       | 2024-04-23<br>10:25<br>:38.0 | 04-<br>D9-<br>F5-<br>B0-<br>84-<br>FB@BF<br>EBFBF<br>F0009<br>06EA@<br>AB201<br>90805<br>A0103<br>289                                 | 否 | 2024-04-23<br>10:22<br>:22.0 | 04-<br>D9-<br>F5-<br>B0-<br>84-<br>FB@BF<br>EBFBF<br>F0009<br>06EA@<br>AB201<br>90805<br>A0103<br>289                                 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误，请<br>检查 | 2024-04-24<br>08:36<br>:48 | 3C-<br>7C-<br>3F-<br>C3-<br>A9-<br>67@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7684<br>08339<br>4, 12P<br>J2V8M<br>S                | 否 |  |
| 315 | 福建省嘉億<br>建设发展有<br>限公司 | 2024-04-22<br>11:10<br>:22.0 | 74-<br>56-<br>3C-<br>C4-<br>40-<br>5A@BF<br>EBFBF<br>F0009<br>0675@<br>SCRW2<br>11220<br>08A10<br>57, WD<br>-<br>WCC6Y<br>FDT9U<br>8X | 否 | 2024-04-22<br>10:59<br>:24.0 | 74-<br>56-<br>3C-<br>C4-<br>40-<br>5A@BF<br>EBFBF<br>F0009<br>0675@<br>SCRW2<br>11220<br>08A10<br>57, WD<br>-<br>WCC6Y<br>FDT9U<br>8X | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误，请<br>检查 | 2024-04-24<br>08:32<br>:03 | 74-<br>56-<br>3C-<br>C4-<br>40-<br>5A@BF<br>EBFBF<br>F0009<br>0675@<br>SCRW2<br>11220<br>08A10<br>57, WD<br>-<br>WCC6Y<br>FDT9U<br>8X | 否 |  |
| 316 | 福建宜发建<br>设工程有限<br>公司  | 2024-04-23<br>10:43<br>:02.0 | 08-<br>BF-<br>B8-<br>9A-<br>03-<br>A9@BF<br>EBFBF<br>F0009<br>0672@<br>0025_<br>38B5_<br>31B3_<br>D03D.                               | 否 | 2024-04-23<br>10:42<br>:20.0 | 08-<br>BF-<br>B8-<br>9A-<br>03-<br>A9@BF<br>EBFBF<br>F0009<br>0672@<br>0025_<br>38B5_<br>31B3_<br>D03D.                               | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误，请<br>检查 | 2024-04-24<br>08:31<br>:26 | 08-<br>BF-<br>B8-<br>9A-<br>03-<br>A9@BF<br>EBFBF<br>F0009<br>0672@<br>0025_<br>38B5_<br>31B3_<br>D03D.                               | 否 |  |

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 317 | 福建众屹建设有限公司    | 2024-04-23 11:47:45.0 | 18-CO-4D-B3-1E-96@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7DHX6<br>L3, K4<br>00922<br>E0051<br>4 | 否 | 2024-04-23 11:35:22.0 | 18-CO-4D-B3-1E-96@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7DHX6<br>L3, K4<br>00922<br>E0051<br>4 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:09 | 18-CO-4D-B3-1E-96@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7DHX6<br>L3, K4<br>00922<br>E0051<br>4 | 否 |  |
| 318 | 南平市中润建设工程有限公司 | 2024-04-22 17:31:43.0 | B4-2E-99-42-2A-70,00-00-00-00-00-00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>S3YLN<br>X0KC2<br>0664V       | 否 | 2024-04-22 17:22:35.0 | B4-2E-99-42-2A-70,00-00-00-00-00-00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>S3YLN<br>X0KC2<br>0664V       | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:21 | B4-2E-99-42-2A-70,00-00-00-00-00-00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>S3YLN<br>X0KC2<br>0664V       | 否 |  |
| 319 | 福建强达建设有限公司    | 2024-04-23 16:21:27.0 | E0-D5-5E-D6-E1-AD@BF<br>EBFBF<br>F0009<br>06EA@<br>20472<br>Z8064<br>54                                   | 否 | 2024-04-23 16:20:24.0 | E0-D5-5E-D6-E1-AD@BF<br>EBFBF<br>F0009<br>06EA@<br>20472<br>Z8064<br>54                                   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:02 | E0-D5-5E-D6-E1-AD@BF<br>EBFBF<br>F0009<br>06EA@<br>20472<br>Z8064<br>54                                   | 否 |  |

|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 320 | 大秦建设集团有限公司   | 2024-04-23 15:05:24.0 | 6C-0B-84-DD-09-9E@BF EBFBF F0003 06C3@WD-WCC6Z 6RH63 PX, MG 23034 03483 85     | 否 | 2024-04-23 14:29:13.0 | 6C-0B-84-DD-09-9E@BF EBFBF F0003 06C3@WD-WCC6Z 6RH63 PX, MG 23034 03483 85     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:47 | 6C-0B-84-DD-09-9E@BF EBFBF F0003 06C3@WD-WCC6Z 6RH63 PX, MG 23034 03483 85     | 否 |  |
| 321 | 福建鑫昌建设工程有限公司 | 2024-04-23 15:37:39.0 | E8-9C-25-40-F4-78@BF EBFBF F0009 0675@E823_8FA6_BF53_0001_001B_448B_4E39_22CF. | 否 | 2024-04-22 09:22:06.0 | E8-9C-25-40-F4-78@BF EBFBF F0009 0675@E823_8FA6_BF53_0001_001B_448B_4E39_22CF. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:49 | E8-9C-25-40-F4-78@BF EBFBF F0009 0675@E823_8FA6_BF53_0001_001B_448B_4E39_22CF. | 否 |  |
| 322 | 福建闽源山水建设有限公司 | 2024-04-22 08:13:57.0 | F4-4D-30-12-19-DD@BF EBFBF F0003 06C3@MG220 16000 6264                         | 否 | 2024-04-20 16:26:08.0 | F4-4D-30-12-19-DD@BF EBFBF F0003 06C3@MG220 16000 6264                         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:34 | F4-4D-30-12-19-DD@BF EBFBF F0003 06C3@MG220 16000 6264                         | 否 |  |

|     |               |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |           |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-----------|---------------------|--|---|--|
| 323 | 福建省东利建设有限公司   | 2024-04-23 17:26:39.0 | FC-AA-14-4A-36-DE@BF<br>EBFBF<br>F0003<br>06C3@<br>WD-WCC3F<br>3CTUU<br>S4, SS<br>FB188<br>09006<br>64 | 否 | 2024-04-23 16:20:58.0 | FC-AA-14-4A-36-DE@BF<br>EBFBF<br>F0003<br>06C3@<br>WD-WCC3F<br>3CTUU<br>S4, SS<br>FB188<br>09006<br>64                            | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:35:40 | FC-AA-14-4A-36-DE@BF<br>EBFBF<br>F0003<br>06C3@<br>WD-WCC3F<br>3CTUU<br>S4, SS<br>FB188<br>09006<br>64 | 否 |  |
| 324 | 福建亿嘉鑫建设发展有限公司 | 2024-04-23 15:24:53.0 | D4-5D-64-A5-A7-9D@BF<br>EBFBF<br>F0009<br>06EB@<br>23103<br>L8000<br>27, WD-<br>WCC6Y<br>7ENJJ<br>NC   | 否 | 2024-04-23 15:23:05.0 | D4-5D-64-A5-A7-9D, 00-00-00-00-00-00-00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>23103<br>L8000<br>27, WD-<br>WCC6Y<br>7ENJJ<br>NC | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:31:22 | D4-5D-64-A5-A7-9D@BF<br>EBFBF<br>F0009<br>06EB@<br>23103<br>L8000<br>27, WD-<br>WCC6Y<br>7ENJJ<br>NC   | 否 |  |



|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 325 | 福建拓州建设工程有限公司  | 2024-04-18 16:31:30.0 | B4-2E-99-12-40-57@178BFBF F0066 0F51@WD-WCC6Y ODAOA TE, YS 22128 18RTG I4288      | 否 | 2024-04-18 16:27:09.0 | B4-2E-99-12-40-57@178BFBF F0066 0F51@WD-WCC6Y ODAOA TE, YS 22128 18RTG I4288      | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:47 | B4-2E-99-12-40-57@178BFBF F0066 0F51@WD-WCC6Y ODAOA TE, YS 22128 18RTG I4288      | 否 |  |
| 326 | 福建省利璟建筑工程有限公司 | 2024-04-18 10:25:02.0 | 74-56-3C-09-87-0F@BF EBFBF F0009 0675@WD-WCC6Y 30RUZ R5, 64 79_A7 6E_60 CO_13 31. | 否 | 2024-04-18 10:22:04.0 | 74-56-3C-09-87-0F@BF EBFBF F0009 0675@WD-WCC6Y 30RUZ R5, 64 79_A7 6E_60 CO_13 31. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:18 | 74-56-3C-09-87-0F@BF EBFBF F0009 0675@WD-WCC6Y 30RUZ R5, 64 79_A7 6E_60 CO_13 31. | 否 |  |

|     |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |  |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|--|---|--|
| 327 | 福建灿达建设工程有限公司  | 2024-04-23 15:52:46.0 | 04-42-1A-2B-7D-53@BF<br>EBFBF<br>F000A<br>0653@<br>W9APE<br>PH5,0<br>000_0<br>000_0<br>000_0<br>000_0<br>000_0<br>000_0<br>100_0<br>000_0<br>000. | 否 | 2024-04-23 15:49:36.0 | 04-42-1A-2B-7D-53@BF<br>EBFBF<br>F000A<br>0653@<br>W9APE<br>PH5,0<br>000_0<br>000_0<br>000_0<br>000_0<br>000_0<br>100_0<br>000_0<br>000. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:39 | 04-42-1A-2B-7D-53@BF<br>EBFBF<br>F000A<br>0653@<br>W9APE<br>PH5,0<br>000_0<br>000_0<br>000_0<br>000_0<br>000_0<br>100_0<br>000_0<br>000. | 否  |   |  |
| 328 | 福建省中宏正盛建设有限公司 | 2024-04-23 10:46:48.0 | FC-34-97-C4-D0-2D@BF<br>EBFBF<br>F000A<br>0653@<br>W9AFT<br>SLO,5<br>0026B<br>7380E<br>926BB  | 否 | 2024-04-22 10:54:54.0 | FC-34-97-C4-D0-2D@BF<br>EBFBF<br>F000A<br>0653@<br>W9AFT<br>SLO,5<br>0026B<br>7380E<br>926BB   | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:34:07  | FC-34-97-C4-D0-2D@BF<br>EBFBF<br>F000A<br>0653@<br>W9AFT<br>SLO,5<br>0026B<br>7380E<br>926BB | 否 |  |
| 329 | 福建进棠建设工程有限公司  | 2024-04-23 09:01:11.0 | 08-BF-B8-77-1B-5D@BF<br>EBFBF<br>F0009<br>0675@<br>0025_<br>3843_<br>3140_<br>FAD3.   | 否 | 2024-04-22 09:59:29.0 | 08-BF-B8-77-1B-5D@BF<br>EBFBF<br>F0009<br>0675@<br>0025_<br>3843_<br>3140_<br>FAD3.  | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:36:03  | 08-BF-B8-77-1B-5D@BF<br>EBFBF<br>F0009<br>0675@<br>0025_<br>3843_<br>3140_<br>FAD3.          | 否 |  |

|     |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|-----|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 330 | 福建省吴立建设工程有限公司  | 2024-04-23 17:34:01.0 | 04-42-1A-EC-BA-32@BF EBFBF F0009 0672@WD-WMAZA 8451238   | 否 | 2024-04-23 17:31:43.0 | 04-42-1A-EC-BA-32@BF EBFBF F0009 0672@WD-WMAZA 8451238   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:36:38 | 04-42-1A-EC-BA-32@BF EBFBF F0009 0672@WD-WMAZA 8451238   | 否 |  |
| 331 | 福建振铭佳业建设发展有限公司 | 2024-04-23 20:29:55.0 | 74-56-3C-A1-49-2F@BF EBFBF F000A 0653@WD-WCC6Y 1VFX4 3T,00 00_00 01_22 05_00 17_3A 5A_27 03_B0 01_8C 79. | 否 | 2024-04-23 20:26:12.0 | 74-56-3C-A1-49-2F@BF EBFBF F000A 0653@WD-WCC6Y 1VFX4 3T,00 00_00 01_22 05_00 17_3A 5A_27 03_B0 01_8C 79. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:50:03 | 74-56-3C-A1-49-2F@BF EBFBF F000A 0653@WD-WCC6Y 1VFX4 3T,00 00_00 01_22 05_00 17_3A 5A_27 03_B0 01_8C 79. | 否 |  |

|     |                     |                              |   |   |                              |  |   |  |  |  |  |  |  |  |  |  |                            |                            |   |   |  |
|-----|---------------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|---|--|
| 332 | 中建华兴<br>(福建) 建设有限公司 | 2024-04-23<br>11:30<br>:39.0 | 70-<br>4D-<br>7B-<br>B2-<br>82-<br>79@BF<br>EBFBF<br>F0005<br>06E3@<br>MCC02<br>1T002<br>294S4<br>16X, W<br>524FE<br>GD | 否 | 2024-04-23<br>11:27<br>:16.0 | 70-<br>4D-<br>7B-<br>B2-<br>82-<br>79, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>MCC02<br>1T002<br>294S4<br>16X, W<br>524FE<br>GD | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:33<br>:09 | 70-<br>4D-<br>7B-<br>B2-<br>82-<br>79@BF<br>EBFBF<br>F0005<br>06E3@<br>MCC02<br>1T002<br>294S4<br>16X, W<br>524FE<br>GD | 否 |  |
|-----|---------------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|---|--|

|     |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |  |  |
|-----|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|--|--|
| 333 | 福建益贯建设有限公司 | 2024-04-23 09:49:34.0 | 2C-FD-A1-5B-A7-7A, 00-00-00-00-00-E0@BF EBFBF F0009 06E9@ 44414 13334 32323 13133 32313 53536 31363 72020 , 2020 20205 7202d 44435 73643 36595 44445 46444 5 | 否 | 2024-04-23 09:48:07.0 | 2C-FD-A1-5B-A7-7A, 00-00-00-00-00-E0@BF EBFBF F0009 06E9@ 44414 13334 32323 13133 32313 53536 31363 72020 , 2020 20205 7202d 44435 73643 36595 44445 46444 5 | 否 |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:07 | 2C-FD-A1-5B-A7-7A, 00-00-00-00-00-E0@BF EBFBF F0009 06E9@ 44414 13334 32323 13133 32313 53536 31363 72020 , 2020 20205 7202d 44435 73643 36595 44445 46444 5 | 否 |  |  |  |
|-----|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|--|--|

|     |            |   |   |  |   |  |  |  |  |  |  |  |  |  |  |  |             |  |   |  |
|-----|------------|---|---|--|---|--|--|--|--|--|--|--|--|--|--|--|-------------|--|---|--|
| 334 | 福建源升建设有限公司 | 2024-04-23 15:25:36.0   | 否 | 2024-04-23 10:40:55.0  | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:03  | 否 |  |
|     |            | 00-<br>E0-<br>4C-<br>24-<br>B2-<br>2E, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>20202<br>02057<br>202d4<br>44357<br>36434<br>d5933<br>41504<br>d4543 |   | 00-<br>E0-<br>4C-<br>24-<br>B2-<br>2E, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>20202<br>02057<br>202d4<br>44357<br>36434<br>d5933<br>41504<br>d4543 |   |  |  |  |  |  |  |  |  |  |  |  |             | 00-<br>E0-<br>4C-<br>24-<br>B2-<br>2E, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>20202<br>02057<br>202d4<br>44357<br>36434<br>d5933<br>41504<br>d4543 |   |  |

|     |               |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |                 |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-----------------|---------------------|--|---|--|
| 335 | 福建省领龙建设发展有限公司 | 2024-04-23 09:30:48.0 | 1C-<br>1B-<br>0D-<br>D0-<br>B2-<br>AD@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7784<br>AA4C3<br>3, WD-<br>WCC6Y<br>7XK52<br>LK | 否 | 2024-04-23 09:29:17.0 | 1C-<br>1B-<br>0D-<br>D0-<br>B2-<br>AD, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7784<br>AA4C3<br>3, WD-<br>WCC6Y<br>7XK52<br>LK | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请检查 | 2024-04-24 08:40:17 | 1C-<br>1B-<br>0D-<br>D0-<br>B2-<br>AD@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7784<br>AA4C3<br>3, WD-<br>WCC6Y<br>7XK52<br>LK | 否 |  |
|-----|---------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-----------------|---------------------|--|---|--|

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |  |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|--|---|--|
| 336 | 福建省亚盈建设发展有限公司 | 2024-04-16 16:24:06.0 | 30-32-35-23-30-20,00-E0-70-C5-A4-7C,30-32-35-23-30-1F,30-32-35-23-30-1F,B2-32-35-23-30-1F@BF EBFBF F000A 0653@6E03A 44041 C8,20 1011A 00004 279 | 否 | 2024-04-16 16:23:02.0 | 00-E0-70-C5-A4-7C,30-32-35-23-30-1F,B2-32-35-23-30-1F,30-32-35-23-30-1F,30-32-35-23-30-20@BF EBFBF F000A 0653@6E03A 44041 C8,20 1011A 00004 279 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:39:54 | 00-E0-70-C5-A4-7C,30-32-35-23-30-1F,B2-32-35-23-30-1F,30-32-35-23-30-1F,30-32-35-23-30-20@BF EBFBF F000A 0653@6E03A 44041 C8,20 1011A 00004 279 | 否  |   |  |
| 337 | 福建辰禹建设工程有限公司  | 2024-04-22 16:10:01.0 | 00-E2-69-6D-AD-53@BF EBFBF F0009 0675@0025_38A6_21B2_407B.  | 否 | 2024-04-22 16:00:23.0 | 00-E2-69-6D-AD-53@BF EBFBF F0009 0675@0025_38A6_21B2_407B.  | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:39:06   | 00-E2-69-6D-AD-53@BF EBFBF F0009 0675@0025_38A6_21B2_407B. | 否 |  |





|     |                   |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                        |                            |  |   |  |
|-----|-------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------|----------------------------|--|---|--|
| 339 | 福建省弘博<br>建设工程有限公司 | 2024-04-22<br>16:56<br>:33.0 | C8-<br>7F-<br>54-<br>16-<br>FF-<br>C6@BF<br>EBFBF<br>F000A<br>0671@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>448B<br>45D3<br>88ED.<br>,WD-<br>WCC6Y<br>OZVAR<br>1Z | 否 | 2024-04-22<br>16:25<br>:03.0 | C8-<br>7F-<br>54-<br>16-<br>FF-<br>C6@BF<br>EBFBF<br>F000A<br>0671@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>448B<br>45D3<br>88ED.<br>,WD-<br>WCC6Y<br>OZVAR<br>1Z | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-04-24<br>08:31<br>:34 | C8-<br>7F-<br>54-<br>16-<br>FF-<br>C6@BF<br>EBFBF<br>F000A<br>0671@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>448B<br>45D3<br>88ED.<br>,WD-<br>WCC6Y<br>OZVAR<br>1Z | 否 |  |
|-----|-------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------|----------------------------|--|---|--|

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 340 | 福建佳钰建设工程有限公司  | 2024-04-23 17:14:44.0 | 00-E0-4C-76-15-2D,00-E0-70-C0-C6-90,00-E0-4C-76-15-2D,00-E0-4C-76-15-2D@BFEBFBF000906EA@058F63666438,50026B7382275C70 | 否 | 2024-04-23 17:12:59.0 | 00-E0-70-C0-C6-90,00-E0-4C-76-15-2D,82-E0-4C-76-15-2D,00-E0-4C-76-15-2D@BFEBFBF000906EA@058F63666438,50026B7382275C70 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:38:31 | 00-E0-4C-76-15-2D,00-E0-4C-76-15-2D,82-E0-4C-76-15-2D@BFEBFBF000906EA@058F63666438,50026B7382275C70 | 否   |   |  |
| 341 | 永泰县顺通公路养护有限公司 | 2024-04-22 20:01:41.0 | F0-2F-74-DA-AF-95@BFEBFBF000906EB@GV210316SG00002471,W9AP17   | 否 | 2024-04-22 17:23:33.0 | F0-2F-74-DA-AF-95@BFEBFBF000906EB@GV210316SG00002471,W9AP17   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:34:07   | F0-2F-74-DA-AF-95@BFEBFBF000906EB@GV210316SG00002471,W9AP17 | 否 |  |

|     |                 |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|-----|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
|     |                 |                       | 90  |   |                       | 90  |   |  |  |  |  |  |  |  |  |  |  |             | 90                  |   |   |   |  |
| 342 | 湖南联合城市建设集团有限公司  | 2024-04-23 14:59:53.0 | D8-43-AE-27-D1-D5@BFEBFBFF00090675@0000_0000_0000_0000_0026_B738_2908_2095. | 否 | 2024-04-22 18:32:37.0 | D8-43-AE-27-D1-D5@BFEBFBFF00090675@0000_0000_0000_0000_0026_B738_2908_2095. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:35:48 | D8-43-AE-27-D1-D5@BFEBFBFF00090675@0000_0000_0000_0000_0026_B738_2908_2095. | 否   |   |  |
| 343 | 福建省中建佳铸建设发展有限公司 | 2024-04-23 10:44:33.0 | D8-5E-D3-28-92-66@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_1229_29E5. | 否 | 2024-04-23 10:31:38.0 | D8-5E-D3-28-92-66@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_1229_29E5. | 否 |  |  |  |  |  |  |  |  |  |  |             | 校验数据有误差，请检查         | 2024-04-24 08:37:20   | D8-5E-D3-28-92-66@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_1229_29E5. | 否 |  |

|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 344 | 福建涇建建设发展有限公司 | 2024-04-23 15:13:30.0 | 58-11-22-99-97-98@BF EBFBF F000A 0653@30080 98263 0 _0000 0001.            | 否 | 2024-04-23 15:11:10.0 | 58-11-22-99-97-98@BF EBFBF F000A 0653@30080 98263 0 _0000 0001.            | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:44:44 | 58-11-22-99-97-98@BF EBFBF F000A 0653@30080 98263 0 _0000 0001.            | 否 |  |
| 345 | 福建省鑫方至建设有限公司 | 2024-04-23 09:01:05.0 | 08-BF-B8-9F-0B-2C@BF EBFBF F000A 0653@ KW238 210A4 A0279                   | 否 | 2024-04-23 08:22:00.0 | 08-BF-B8-9F-0B-2C@BF EBFBF F000A 0653@ KW238 210A4 A0279                   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:25 | 08-BF-B8-9F-0B-2C@BF EBFBF F000A 0653@ KW238 210A4 A0279                   | 否 |  |
| 346 | 辽宁星发建设有限公司   | 2024-04-23 13:26:44.0 | 40-8D-5C-0D-BC-37@BF EBFBF F0003 06C3@ YS002 34604 66, WD - WCC6Y 2AF1P JN | 否 | 2024-04-23 13:22:57.0 | 40-8D-5C-0D-BC-37@BF EBFBF F0003 06C3@ YS002 34604 66, WD - WCC6Y 2AF1P JN | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:31:44 | 40-8D-5C-0D-BC-37@BF EBFBF F0003 06C3@ YS002 34604 66, WD - WCC6Y 2AF1P JN | 否 |  |

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |           |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-----------|---------------------|---|---|--|
| 347 | 福建瑞联建设有限公司    | 2024-04-19 19:23:11.0 | B4-2E-99-7B-F1-88@BF<br>EBFBF<br>F0009<br>06EB@<br>23183<br>A1951<br>E2, 19<br>321M4<br>41102<br>, W2AX<br>8PGZ | 否 | 2024-04-18 14:13:00.0 | B4-2E-99-7B-F1-88@BF<br>EBFBF<br>F0009<br>06EB@<br>23183<br>A1951<br>E2, 19<br>321M4<br>41102<br>, W2AX<br>8PGZ | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:32:41 | B4-2E-99-7B-F1-88@BF<br>EBFBF<br>F0009<br>06EB@<br>23183<br>A1951<br>E2, 19<br>321M4<br>41102<br>, W2AX<br>8PGZ | 否 |  |
| 348 | 湖南中亿电力工程有限公司  | 2024-04-23 11:57:33.0 | 00-E0-4C-42-99-D3@BF<br>EBFBF<br>F000A<br>0653@<br>2HT10<br>07B11<br>R4S01<br>B77                               | 否 | 2024-04-23 11:55:25.0 | 00-E0-4C-42-99-D3@BF<br>EBFBF<br>F000A<br>0653@<br>2HT10<br>07B11<br>R4S01<br>B77                               | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:52:28 | 00-E0-4C-42-99-D3@BF<br>EBFBF<br>F000A<br>0653@<br>2HT10<br>07B11<br>R4S01<br>B77                               | 否 |  |
| 349 | 江西省联丰建设工程有限公司 | 2024-04-23 19:23:30.0 | 7C-10-C9-BD-94-F3@BF<br>EBFBF<br>F000A<br>0653@<br>MG220<br>65068<br>6287                                       | 否 | 2024-04-23 18:29:03.0 | 7C-10-C9-BD-94-F3@BF<br>EBFBF<br>F000A<br>0653@<br>MG220<br>65068<br>6287                                       | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:44:38 | 7C-10-C9-BD-94-F3@BF<br>EBFBF<br>F000A<br>0653@<br>MG220<br>65068<br>6287                                       | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 350 | 四川创海建筑工程有限公司 | 2024-04-23 18:30:51.0 | D8-5E-D3-44-94-B8@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_183E_4135., WD-WCC6Y 2FZE8 V5 | 否 | 2024-04-19 10:24:26.0 | D8-5E-D3-44-94-B8@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_183E_4135., WD-WCC6Y 2FZE8 V5 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:53:53 | D8-5E-D3-44-94-B8@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_183E_4135., WD-WCC6Y 2FZE8 V5 | 否 |  |
| 351 | 福建丰成建设有限公司   | 2024-04-23 11:33:50.0 | 58-11-22-D1-5A-F7@BF EBFBF F0009 0675@8EFA0 7651F E7045 87998, WD-WCC6Y RXAN2 J1                  | 否 | 2024-04-23 11:18:22.0 | 58-11-22-D1-5A-F7@BF EBFBF F0009 0675@8EFA0 7651F E7045 87998, WD-WCC6Y RXAN2 J1                  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:36:45 | 58-11-22-D1-5A-F7@BF EBFBF F0009 0675@8EFA0 7651F E7045 87998, WD-WCC6Y RXAN2 J1                  | 否 |  |

|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 352 | 福建如通建设工程有限公司   | 2024-04-19 13:33:39.0 | D4-5D-64-A7-FA-39@BFEBFBFF000906EB@TW2204090034                             | 否 | 2024-04-19 13:32:25.0 | D4-5D-64-A7-FA-39@BFEBFBFF000906EB@TW2204090034                             | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:12 | D4-5D-64-A7-FA-39@BFEBFBFF000906EB@TW2204090034                             | 否 |  |
| 353 | 福建运发建筑工程有限公司   | 2024-04-23 16:11:34.0 | 7C-10-C9-9E-90-16@BFEBFBFF000A0653@50026B738118D17A                         | 否 | 2024-04-23 16:11:22.0 | 7C-10-C9-9E-90-16@BFEBFBFF000A0653@50026B738118D17A                         | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:39:37 | 7C-10-C9-9E-90-16@BFEBFBFF000A0653@50026B738118D17A                         | 否 |  |
| 354 | 中建泷耀（福建）建设有限公司 | 2024-04-23 16:42:45.0 | 90-6F-18-02-30-21@BFEBFBFF00090675@0000_0000_0000_0000_00E0_4C15_6B84_7C90. | 否 | 2024-04-23 10:23:31.0 | 90-6F-18-02-30-21@BFEBFBFF00090675@0000_0000_0000_0000_00E0_4C15_6B84_7C90. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:50:48 | 90-6F-18-02-30-21@BFEBFBFF00090675@0000_0000_0000_0000_00E0_4C15_6B84_7C90. | 否 |  |



|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 355 | 福建饮源建设工程有限公司  | 2024-04-23 11:02:48.0 | 48-0F-CF-4D-A4-34@BFEBFBFF000506E3@50026B7380A37D80                     | 否 | 2024-04-23 11:01:16.0 | 48-0F-CF-4D-A4-34@BFEBFBFF000506E3@50026B7380A37D80                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:33:07 | 48-0F-CF-4D-A4-34@BFEBFBFF000506E3@50026B7380A37D80                     | 否 |  |
| 356 | 福建省丽宏建设工程有限公司 | 2024-04-23 17:54:16.0 | F0-2F-74-51-C7-4C@BFEBFBFF000906EA@NDG674R0002440S30C,50026B76842ADDE2  | 否 | 2024-04-23 17:50:34.0 | F0-2F-74-51-C7-4C@BFEBFBFF000906EA@NDG674R0002440S30C,50026B76842ADDE2  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:34:52 | F0-2F-74-51-C7-4C@BFEBFBFF000906EA@NDG674R0002440S30C,50026B76842ADDE2  | 否 |  |
| 357 | 福建省闽建建设工程有限公司 | 2024-04-23 11:08:15.0 | D8-5E-D3-73-4F-70@BFEBFBFF000A0653@6479_A75C_60C0_2875.,WD-WCC6Y5NL9H3N | 否 | 2024-04-23 11:07:17.0 | D8-5E-D3-73-4F-70@BFEBFBFF000A0653@6479_A75C_60C0_2875.,WD-WCC6Y5NL9H3N | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:37:28 | D8-5E-D3-73-4F-70@BFEBFBFF000A0653@6479_A75C_60C0_2875.,WD-WCC6Y5NL9H3N | 否 |  |

|     |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 358 | 福建荣乾建设有限公司 | 2024-04-22 10:25:54.0 | 30-B4-9E-C0-8F-DA, E0-D5-5E-76-65-A0@178BFBF F0063 0F01@CVTR6 06200 HF480 EGN | 否 | 2024-04-22 10:16:51.0 | 30-B4-9E-C0-8F-DA, E0-D5-5E-76-65-A0@178BFBF F0063 0F01@CVTR6 06200 HF480 EGN | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:14 | 30-B4-9E-C0-8F-DA, E0-D5-5E-76-65-A0@178BFBF F0063 0F01@CVTR6 06200 HF480 EGN | 否 |  |
| 359 | 福建羽林建筑有限公司 | 2024-04-23 09:26:36.0 | A0-36-BC-0A-75-D3@BFEBFBF F000A 0653@0000_0000_0000_0000_0026_B778_4F22_0E45. | 否 | 2024-04-23 09:26:01.0 | A0-36-BC-0A-75-D3@BFEBFBF F000A 0653@0000_0000_0000_0000_0026_B778_4F22_0E45. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:31 | A0-36-BC-0A-75-D3@BFEBFBF F000A 0653@0000_0000_0000_0000_0026_B778_4F22_0E45. | 否 |  |



|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 362 | 福建省泰谭建设工程有限公司 | 2024-04-22 16:56:14.0 | 00-00-00-00-00-00,FC-AA-14-24-C7-51,00-00-00-00-00-00-00,FC-AA-14-24-C7-51@BFEBFBFF000306C3@2020202057202d44435732434b45504b3455524a | 否 | 2024-04-22 16:52:44.0 | FC-AA-14-24-C7-51,00-00-00-00-00-00-00,FC-AA-14-24-C7-51,00-00-00-00-00-00,FC-AA-14-24-C7-51@BFEBFBFF000306C3@2020202057202d44435732434b45504b3455524a | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:07 | 00-00-00-00-00-00,FC-AA-14-24-C7-51@BFEBFBFF000306C3@2020202057202d44435732434b45504b3455524a | 否   |   |  |
| 363 | 河南骄发建筑工程有限公司  | 2024-04-23 16:47:51.0 | 00-E0-1F-4C-04-4D@BFEBFBFF00090675@A510512Y23377296  | 否 | 2024-04-22 15:21:54.0 | 00-E0-1F-4C-04-4D@BFEBFBFF00090675@A510512Y23377296  | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:37:28   | 00-E0-1F-4C-04-4D@BFEBFBFF00090675@A510512Y23377296 | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 364 | 莱克建设集团有限公司    | 2024-04-23 09:49:52.0 | 22-24-4D-02-16-6E@BFEBFBFF00090675@50026B7436002586  | 否 | 2024-04-23 09:49:08.0 | 22-24-4D-02-16-6E@BFEBFBFF00090675@50026B7436002586  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:38:24 | 22-24-4D-02-16-6E@BFEBFBFF00090675@50026B7436002586  | 否 |  |
| 365 | 厦门市华舫建筑工程有限公司 | 2024-04-23 15:34:16.0 | 88-D7-F6-E1-AF-39@BFEBFBFF000906E9@30303030313030303030338303035313135,34534b43474e4d30343834313333205220202020,2020202057202d4443573443314d49334c474335 | 否 | 2024-04-23 10:11:35.0 | 88-D7-F6-E1-AF-39@BFEBFBFF000906E9@30303030313030303030338303035313135,34534b43474e4d30343834313333205220202020,2020202057202d4443573443314d49334c474335 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:44 | 88-D7-F6-E1-AF-39@BFEBFBFF000906E9@30303030313030303030338303035313135,34534b43474e4d30343834313333205220202020,2020202057202d4443573443314d49334c474335 | 否 |  |









|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 371 | 福建省唐韵建筑工程有限公司 | 2024-04-23 09:10:28.0 | D8-BB-C1-6D-37-A6@BF EBFBF F000A 0653@ ZOE1S 1GWSN 3H, CN 092BH 26087 35, 50 026B7 3813B CB74  | 否 | 2024-04-19 08:59:09.0 | D8-BB-C1-6D-37-A6@BF EBFBF F000A 0653@ ZOE1S 1GWSN 3H, CN 092BH 26087 35, 50 026B7 3813B CB74  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:40 | D8-BB-C1-6D-37-A6@BF EBFBF F000A 0653@ ZOE1S 1GWSN 3H, CN 092BH 26087 35, 50 026B7 3813B CB74                      | 否 |  |
| 372 | 福建省大东建筑工程有限公司 | 2024-04-22 15:52:19.0 | 04-42-1A-23-7A-32, 90 -76-9F-90-A2-D0, 92 -76-9F-90-A2-D0, 90 -76-9F-90-A2-D0@BF EBFBF F000A 0653@ K2706 38E29 015, W D-WCC6Y OZVJP JS | 否 | 2024-04-22 15:35:37.0 | 04-42-1A-23-7A-32, 92 -76-9F-90-A2-D0, 90 -76-9F-90-A2-D0, 90 -76-9F-90-A2-D0@BF EBFBF F000A 0653@ K2706 38E29 015, W D-WCC6Y OZVJP JS | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:47 | 04-42-1A-23-7A-32, 90 -76-9F-90-A2-D0, 90 -76-9F-90-A2-D0@BF EBFBF F000A 0653@ K2706 38E29 015, W D-WCC6Y OZVJP JS | 否 |  |

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 373 | 福建津远建设工程有限公司  | 2024-04-23 12:02:23.0 | 40-B0-76-46-7D-21@BF EBFBF F0009 06EA@ 97905 06910 36                               | 否 | 2024-04-16 17:11:09.0 | 40-B0-76-46-7D-21@BF EBFBF F0009 06EA@ 97905 06910 36                               | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:07 | 40-B0-76-46-7D-21@BF EBFBF F0009 06EA@ 97905 06910 36                               | 否 |  |
| 374 | 福建省宏益路桥建设有限公司 | 2024-04-22 20:18:47.0 | 74-56-3C-81-8D-E7@BF EBFBF F0009 0675@ 6479_ A778_ DOCO_ 030A. , WD- WXB2A 13793 26 | 否 | 2024-04-22 20:17:28.0 | 74-56-3C-81-8D-E7@BF EBFBF F0009 0675@ 6479_ A778_ DOCO_ 030A. , WD- WXB2A 13793 26 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:31 | 74-56-3C-81-8D-E7@BF EBFBF F0009 0675@ 6479_ A778_ DOCO_ 030A. , WD- WXB2A 13793 26 | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 375 | 福建涵海建设工程有限公司  | 2024-04-22 18:06:08.0 | 04-42-1A-93-85-8B@BF<br>EBFBF<br>F000A<br>0653@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>448B<br>4188<br>ACB9.<br>, WXE2<br>A63D8<br>9LE | 否 | 2024-04-22 16:35:59.0 | 04-42-1A-93-85-8B@BF<br>EBFBF<br>F000A<br>0653@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>448B<br>4188<br>ACB9.<br>, WXE2<br>A63D8<br>9LE | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:32 | 04-42-1A-93-85-8B@BF<br>EBFBF<br>F000A<br>0653@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>448B<br>4188<br>ACB9.<br>, WXE2<br>A63D8<br>9LE | 否 |  |
| 376 | 福建省芳何建筑工程有限公司 | 2024-04-23 17:10:04.0 | E0-D5-5E-BF-A0-83@BF<br>EBFBF<br>F0009<br>06EB@<br>08302<br>018A0<br>622, W<br>D-<br>WCC6Y<br>4SLHK<br>XF                                  | 否 | 2024-04-23 17:06:17.0 | E0-D5-5E-BF-A0-83@BF<br>EBFBF<br>F0009<br>06EB@<br>08302<br>018A0<br>622, W<br>D-<br>WCC6Y<br>4SLHK<br>XF                                  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:31 | E0-D5-5E-BF-A0-83@BF<br>EBFBF<br>F0009<br>06EB@<br>08302<br>018A0<br>622, W<br>D-<br>WCC6Y<br>4SLHK<br>XF                                  | 否 |  |

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 377 | 华鑫（福建）建设有限公司  | 2024-04-23 16:46:02.0 | A0-36-BC-BA-9C-98@BF<br>EBFBF<br>F0009<br>0672@<br>0000_<br>0006_<br>2210_<br>0007_<br>3A5A_<br>2703_<br>E000_<br>0052. | 否 | 2024-04-23 16:42:30.0 | A0-36-BC-BA-9C-98@BF<br>EBFBF<br>F0009<br>0672@<br>0000_<br>0006_<br>2210_<br>0007_<br>3A5A_<br>2703_<br>E000_<br>0052. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:39 | A0-36-BC-BA-9C-98@BF<br>EBFBF<br>F0009<br>0672@<br>0000_<br>0006_<br>2210_<br>0007_<br>3A5A_<br>2703_<br>E000_<br>0052. | 否   |   |  |
| 378 | 福建省茂佳建设工程有限公司 | 2024-04-23 09:07:16.0 | 50-EB-F6-82-15-72@BF<br>EBFBF<br>F000A<br>0653@<br>22366<br>68020<br>55   | 否 | 2024-04-22 11:33:42.0 | 50-EB-F6-82-15-72@BF<br>EBFBF<br>F000A<br>0653@<br>22366<br>68020<br>55   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:35:40   | 50-EB-F6-82-15-72@BF<br>EBFBF<br>F000A<br>0653@<br>22366<br>68020<br>55 | 否 |  |



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |   |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|--|---|--|
| 380 | 福建定柏建设工程有限公司 | 2024-04-23 16:13:55.0 | 00-<br>E0-<br>4C-<br>9A-<br>3D-<br>55,00<br>-E0-<br>4C-<br>9A-<br>3D-<br>55,00<br>-E0-<br>70-<br>C3-<br>97-<br>D6,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>35535<br>25246<br>4e543<br>13334<br>33323<br>73920<br>56202<br>02020<br>,3032<br>30323<br>03132<br>31333<br>23738<br>20202<br>02020<br>20202<br>0 | 否 | 2024-04-22 17:30:28.0 | 00-<br>E0-<br>4C-<br>9A-<br>3D-<br>55,00<br>-E0-<br>4C-<br>9A-<br>3D-<br>55,00<br>-E0-<br>70-<br>C3-<br>97-<br>D6,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>35535<br>25246<br>4e543<br>13334<br>33323<br>73920<br>56202<br>02020<br>,3032<br>30323<br>03132<br>31333<br>23738<br>20202<br>02020<br>20202<br>0 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误,请检查 | 2024-04-24 08:35:40 | 00-<br>5C-<br>C2-<br>5C-<br>3C-<br>18,00<br>-5C-<br>C2-<br>5C-<br>3C-<br>18,D8<br>-5E-<br>D3-<br>C4-<br>C1-<br>15@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WXW2A<br>B23A6<br>6U,AA<br>00000<br>00112<br>60012<br>559 | 否  |   |  |
| 381 | 福建振业建设发展有限公司 | 2024-04-23 16:18:52.0 | A0-<br>36-<br>BC-<br>26-<br>18-<br>89@BF   | 否 | 2024-04-23 16:17:06.0 | A0-<br>36-<br>BC-<br>26-<br>18-<br>89@BF   | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误,请检查          | 2024-04-24 08:33:47   | A0-<br>36-<br>BC-<br>26-<br>18-<br>89@BF | 否 |  |

|     |                       |                                  |   |   |                                  |   |  |  |  |  |  |  |  |  |  |  |                         |   |   |   |  |
|-----|-----------------------|----------------------------------|---|---|----------------------------------|---|--|--|--|--|--|--|--|--|--|--|-------------------------|---|---|---|--|
|     |                       |                                  | EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4CA5_<br>4D65.   |   |                                  | EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4CA5_<br>4D65.   |  |  |  |  |  |  |  |  |  |  |                         | EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4CA5_<br>4D65. |   |   |  |
| 382 | 福建省吴炎<br>建设发展有<br>限公司 | 2024-<br>04-22<br>15:35<br>:45.0 | 00-<br>E0-<br>4C-<br>89-<br>82-<br>A5@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0040_<br>4000_<br>4839.<br>, AB20<br>19010<br>8A010<br>1848 | 否 | 2024-<br>04-22<br>15:17<br>:53.0 | 00-<br>E0-<br>4C-<br>89-<br>82-<br>A5@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0040_<br>4000_<br>4839.<br>, AB20<br>19010<br>8A010<br>1848 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:41<br>:29  | 00-<br>E0-<br>4C-<br>89-<br>82-<br>A5@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0040_<br>4000_<br>4839.<br>, AB20<br>19010<br>8A010<br>1848 | 否 |  |

|     |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 383 | 中福轩丞建设有限公司 | 2024-04-23 15:04:15.0 | 00-<br>E0-<br>70-<br>6B-<br>00-<br>15,00<br>-00-<br>00-<br>00-<br>00-<br>00@BF<br>EBFBF<br>F0009<br>06E9@<br>18HB7<br>3CIK4<br>6S | 否 | 2024-04-23 15:01:29.0 | 00-<br>E0-<br>70-<br>6B-<br>00-<br>15@BF<br>EBFBF<br>F0009<br>06E9@<br>18HB7<br>3CIK4<br>6S | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:40:04 | 00-<br>E0-<br>70-<br>6B-<br>00-<br>15,00<br>-00-<br>00-<br>00-<br>00-<br>00@BF<br>EBFBF<br>F0009<br>06E9@<br>18HB7<br>3CIK4<br>6S | 否 |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|







|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 386 | 福建省润青建设发展有限公司 | 2024-04-22 11:27:57.0 | 00-D8-61-BD-EE-34@BF EBFBF F0009 06EB@ SCRW1 90713 03G17 21, WD - WXW2A AOLUU UP, WD - WCC6Y 2HHNE XL | 否 | 2024-04-22 11:02:44.0 | 00-D8-61-BD-EE-34@BF EBFBF F0009 06EB@ SCRW1 90713 03G17 21, WD - WXW2A AOLUU UP, WD - WCC6Y 2HHNE XL | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:39:29 | 00-D8-61-BD-EE-34@BF EBFBF F0009 06EB@ SCRW1 90713 03G17 21, WD - WXW2A AOLUU UP, WD - WCC6Y 2HHNE XL | 否 |  |
| 387 | 福建兆鼎建设发展有限公司  | 2024-04-23 17:15:43.0 | 04-42-1A-2D-B4-59@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 49DF_ 7774.                | 否 | 2024-04-23 09:53:48.0 | 04-42-1A-2D-B4-59@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 49DF_ 7774.                | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:45 | 04-42-1A-2D-B4-59@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 49DF_ 7774.                | 否 |  |

|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 388 | 福建省鼎宏旺建设工程有限公司 | 2024-04-23 09:46:52.0 | A0-36-BC-2B-F3-06, F4-6A-92-F5-1A-F0@BF EBFBF F000A 0653@WD-WCC6Y 5LX9Z 46, CM 317BH 15406 41 | 否 | 2024-04-23 09:45:38.0 | F4-6A-92-F5-1A-F0, A0-36-BC-2B-F3-06@BF EBFBF F000A 0653@WD-WCC6Y 5LX9Z 46, CM 317BH 15406 41 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:35:44 | A0-36-BC-2B-F3-06, F4-6A-92-F5-1A-F0@BF EBFBF F000A 0653@WD-WCC6Y 5LX9Z 46, CM 317BH 15406 41 | 否 |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|







|     |             |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|-------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 393 | 福建锦益建设有限公司  | 2024-04-22 13:03:02.0 | 4C-<br>ED-<br>FB-<br>62-<br>0B-<br>DD@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>4RNHE<br>8S, AA<br>00000<br>00000<br>00001<br>692                                     | 否 | 2024-04-22 13:00:14.0 | 4C-<br>ED-<br>FB-<br>62-<br>0B-<br>DD@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>4RNHE<br>8S, AA<br>00000<br>00000<br>00001<br>692                                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:35:03 | 4C-<br>ED-<br>FB-<br>62-<br>0B-<br>DD@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>4RNHE<br>8S, AA<br>00000<br>00000<br>00001<br>692                                     | 否 |  |
| 394 | 福建中吉龙工程有限公司 | 2024-04-23 14:59:03.0 | 08-<br>BF-<br>B8-<br>BB-<br>56-<br>CA@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0006_<br>2309_<br>0018_<br>3A5A_<br>2703_<br>2000_<br>01D2.<br>, WD-<br>WCC6Y<br>46PKN<br>34 | 否 | 2024-04-22 10:54:53.0 | 08-<br>BF-<br>B8-<br>BB-<br>56-<br>CA@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0006_<br>2309_<br>0018_<br>3A5A_<br>2703_<br>2000_<br>01D2.<br>, WD-<br>WCC6Y<br>46PKN<br>34 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:40:30 | 08-<br>BF-<br>B8-<br>BB-<br>56-<br>CA@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0006_<br>2309_<br>0018_<br>3A5A_<br>2703_<br>2000_<br>01D2.<br>, WD-<br>WCC6Y<br>46PKN<br>34 | 否 |  |



|     |             |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|-------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 395 | 福建弘征昌建设有限公司 | 2024-04-17 16:57:34.0 | 50-EB-F6-BC-0F-10@BF<br>EBFBF<br>F000A<br>0671@<br>50026<br>B7381<br>4A5FB<br>E, WD-<br>WCC4J<br>OXY74<br>6Z  | 否 | 2024-04-17 16:55:37.0 | 50-EB-F6-BC-0F-10@BF<br>EBFBF<br>F000A<br>0671@<br>50026<br>B7381<br>4A5FB<br>E, WD-<br>WCC4J<br>OXY74<br>6Z  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:20 | 50-EB-F6-BC-0F-10@BF<br>EBFBF<br>F000A<br>0671@<br>50026<br>B7381<br>4A5FB<br>E, WD-<br>WCC4J<br>OXY74<br>6Z  | 否 |  |
| 396 | 鑫中坤建设工程有限公司 | 2024-04-22 17:36:58.0 | 40-8D-5C-65-BC-76@BF<br>EBFBF<br>F0003<br>06C3@<br>41543<br>63130<br>37303<br>63931<br>39352<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>36593<br>35234<br>53383<br>7 | 否 | 2024-04-22 17:29:07.0 | 40-8D-5C-65-BC-76@BF<br>EBFBF<br>F0003<br>06C3@<br>41543<br>63130<br>37303<br>63931<br>39352<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>36593<br>35234<br>53383<br>7 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:39 | 40-8D-5C-65-BC-76@BF<br>EBFBF<br>F0003<br>06C3@<br>41543<br>63130<br>37303<br>63931<br>39352<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>36593<br>35234<br>53383<br>7 | 否 |  |



|     |                  |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|------------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 398 | 福建省嘉升园林工程有限公司    | 2024-04-18 15:14:32.0 | 1C-1B-0D-CE-48-78@BFEBFBFF000906E9@ZL20230711000000320,WD-WMAYUR038810 | 否 | 2024-04-18 15:12:16.0 | 1C-1B-0D-CE-48-78@BFEBFBFF000906E9@ZL20230711000000320,WD-WMAYUR038810 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:36:51 | 1C-1B-0D-CE-48-78@BFEBFBFF000906E9@ZL20230711000000320,WD-WMAYUR038810 | 否 |  |
| 399 | 福建金亿辉建设工程有限公司    | 2024-04-24 00:44:17.0 | C8-7F-54-51-32-CD@178BFBFF00A50F00@WD-WCC6Y7VK23H0                     | 否 | 2024-04-24 00:35:49.0 | C8-7F-54-51-32-CD@178BFBFF00A50F00@WD-WCC6Y7VK23H0                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 09:00:13 | C8-7F-54-51-32-CD@178BFBFF00A50F00@WD-WCC6Y7VK23H0                     | 否 |  |
| 400 | 闽源国建(厦门)建设工程有限公司 | 2024-04-22 11:38:13.0 | 3C-7C-3F-D5-7A-67@BFEBFBFF000A0653@ZN1JD6H7,30027664164                | 否 | 2024-04-22 11:17:41.0 | 3C-7C-3F-D5-7A-67@BFEBFBFF000A0653@ZN1JD6H7,30027664164                | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:24 | 3C-7C-3F-D5-7A-67@BFEBFBFF000A0653@ZN1JD6H7,30027664164                | 否 |  |
| 401 | 福建中岸建设有限公司       | 2024-04-23 23:54:11.0 | 40-B0-76-45-7A-  | 否 | 2024-04-23 23:51:56.0 | 40-B0-76-45-7A-  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:34:07 | 40-B0-76-45-7A-  | 否 |  |







|     |                         |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |                        |                            |   |   |   |  |
|-----|-------------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|------------------------|----------------------------|---|---|---|--|
| 405 | 河南省安海<br>建筑工程有限公司       | 2024-04-23<br>16:57<br>:45.0 | F0-<br>2F-<br>74-<br>88-<br>87-<br>D1@BF<br>EBFBF<br>F000A<br>0653@<br>30006<br>47365<br>3,WD-<br>WCC6Y<br>0JX5N<br>1Y                      | 否 | 2024-04-23<br>16:55<br>:46.0 | F0-<br>2F-<br>74-<br>88-<br>87-<br>D1@BF<br>EBFBF<br>F000A<br>0653@<br>30006<br>47365<br>3,WD-<br>WCC6Y<br>0JX5N<br>1Y                      | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-04-24<br>08:34<br>:15 | F0-<br>2F-<br>74-<br>88-<br>87-<br>D1@BF<br>EBFBF<br>F000A<br>0653@<br>30006<br>47365<br>3,WD-<br>WCC6Y<br>0JX5N<br>1Y                      | 否   |   |  |
| 406 | 厦门仙森园<br>园林景观工程<br>有限公司 | 2024-04-17<br>16:04<br>:49.0 | 58-<br>11-<br>22-<br>90-<br>DF-<br>D8@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1743_<br>A3A5. | 否 | 2024-04-17<br>15:36<br>:10.0 | 58-<br>11-<br>22-<br>90-<br>DF-<br>D8@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1743_<br>A3A5. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-04-24<br>08:32<br>:44 | 58-<br>11-<br>22-<br>90-<br>DF-<br>D8@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1743_<br>A3A5. | 否   |   |  |
| 407 | 林恒建设有<br>限公司            | 2024-04-23<br>09:00<br>:28.0 | 00-<br>E2-<br>69-<br>69-<br>8A-<br>1E@BF<br>EBFBF<br>F0009<br>0675@<br>7391K<br>23234<br>0420   | 否 | 2024-04-22<br>17:31<br>:29.0 | 00-<br>E2-<br>69-<br>69-<br>8A-<br>1E@BF<br>EBFBF<br>F0009<br>0675@<br>7391K<br>23234<br>0420   | 否 |  |  |  |  |  |  |  |  |  |                        | 校验<br>数据有<br>误,请<br>检查     | 2024-04-24<br>08:32<br>:31  | 00-<br>E2-<br>69-<br>69-<br>8A-<br>1E@BF<br>EBFBF<br>F0009<br>0675@<br>7391K<br>23234<br>0420 | 否 |  |

|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|---|--|
| 408 | 福建盛腾达建设有限公司  | 2024-04-22 09:01:50.0 | 00-<br>E0-<br>1D-<br>E4-<br>61-<br>26@BF<br>EBFBF<br>F0003<br>06E4@<br>WD-<br>WCC6Y<br>2KTAV<br>7L, L1<br>70106<br>481                   | 否 | 2024-04-22 08:53:33.0 | 00-<br>E0-<br>1D-<br>E4-<br>61-<br>26@BF<br>EBFBF<br>F0003<br>06E4@<br>WD-<br>WCC6Y<br>2KTAV<br>7L, L1<br>70106<br>481                   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查  | 2024-04-24 08:37:44 | 00-<br>E0-<br>1D-<br>E4-<br>61-<br>26@BF<br>EBFBF<br>F0003<br>06E4@<br>WD-<br>WCC6Y<br>2KTAV<br>7L, L1<br>70106<br>481                   | 否   |   |  |
| 409 | 福建六鑫建设有限公司   | 2024-04-23 16:46:35.0 | D8-<br>5E-<br>D3-<br>C1-<br>E2-<br>1D@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>4NR29<br>CL, 64<br>79_A7<br>5E_10<br>C0_26<br>F7. | 否 | 2024-04-23 15:39:44.0 | D8-<br>5E-<br>D3-<br>C1-<br>E2-<br>1D@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>4NR29<br>CL, 64<br>79_A7<br>5E_10<br>C0_26<br>F7. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:42:25 | D8-<br>5E-<br>D3-<br>C1-<br>E2-<br>1D@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>4NR29<br>CL, 64<br>79_A7<br>5E_10<br>C0_26<br>F7. | 否   |   |  |
| 410 | 福建嘉优建设工程有限公司 | 2024-04-23 16:34:34.0 | 58-<br>11-<br>22-<br>8A-<br>CD-<br>DB@BF<br>EBFBF<br>F0009<br>0675@<br>50026<br>B7685<br>C93E2<br>1                                      | 否 | 2024-04-23 16:36:00.0 | 58-<br>11-<br>22-<br>8A-<br>CD-<br>DB@BF<br>EBFBF<br>F0009<br>0675@<br>50026<br>B7685<br>C93E2<br>1                                      | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:33:36  | 58-<br>11-<br>22-<br>8A-<br>CD-<br>DB@BF<br>EBFBF<br>F0009<br>0675@<br>50026<br>B7685<br>C93E2<br>1 | 否 |  |





|     |                         |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                        |                                |  |   |  |
|-----|-------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------|--------------------------------|--|---|--|
| 413 | 福建恒达通<br>工程项目管<br>理有限公司 | 2024-<br>04-17<br>16:01<br>:00.0 | 74-<br>56-<br>3C-<br>0D-<br>8B-<br>98@BF<br>EBFBF<br>F0009<br>0675@<br>E823<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E8B_<br>3B44.<br>,WD-<br>WXF2A<br>31E36<br>CL | 否 | 2024-<br>04-17<br>15:45<br>:13.0 | 74-<br>56-<br>3C-<br>0D-<br>8B-<br>98@BF<br>EBFBF<br>F0009<br>0675@<br>E823<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E8B_<br>3B44.<br>,WD-<br>WXF2A<br>31E36<br>CL | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:37<br>:34 | 74-<br>56-<br>3C-<br>0D-<br>8B-<br>98@BF<br>EBFBF<br>F0009<br>0675@<br>E823<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E8B_<br>3B44.<br>,WD-<br>WXF2A<br>31E36<br>CL | 否 |  |
|-----|-------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------|--------------------------------|--|---|--|





|     |                 |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 416 | 水玲珑（福建）建设工程有限公司 | 2024-04-23 11:49:45.0 | 00-<br>E0-<br>4C-<br>2B-<br>20-<br>3D@BF<br>EBFBF<br>F0009<br>0675@<br>0000-<br>0000-<br>0000-<br>0000-<br>0026-<br>B768-<br>687E-<br>55E5.<br>,WD-<br>WCC3F<br>57338<br>24 | 否 | 2024-04-23 11:48:34.0 | 00-<br>E0-<br>4C-<br>2B-<br>20-<br>3D@BF<br>EBFBF<br>F0009<br>0675@<br>0000-<br>0000-<br>0000-<br>0000-<br>0026-<br>B768-<br>687E-<br>55E5.<br>,WD-<br>WCC3F<br>57338<br>24 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:47 | 00-<br>E0-<br>4C-<br>2B-<br>20-<br>3D@BF<br>EBFBF<br>F0009<br>0675@<br>0000-<br>0000-<br>0000-<br>0000-<br>0026-<br>B768-<br>687E-<br>55E5.<br>,WD-<br>WCC3F<br>57338<br>24 | 否 |  |
| 417 | 福建子尧建设有限公司      | 2024-04-22 11:27:25.0 | 08-<br>BF-<br>B8-<br>01-<br>B0-<br>3E@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4NT02<br>8C,00<br>00_00<br>06_34<br>56_78<br>90_3A<br>5A_27<br>02_30<br>00_13<br>02. | 否 | 2024-04-22 11:01:10.0 | 08-<br>BF-<br>B8-<br>01-<br>B0-<br>3E@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4NT02<br>8C,00<br>00_00<br>06_34<br>56_78<br>90_3A<br>5A_27<br>02_30<br>00_13<br>02. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:03 | 08-<br>BF-<br>B8-<br>01-<br>B0-<br>3E@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4NT02<br>8C,00<br>00_00<br>06_34<br>56_78<br>90_3A<br>5A_27<br>02_30<br>00_13<br>02. | 否 |  |



|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 420 | 福建钦焱建设有限公司   | 2024-04-23 15:03:30.0 | B0-83-FE-79-06-A6@BFEBFBFF000306C3@MG221060189677       | 否 | 2024-04-23 11:43:55.0 | B0-83-FE-79-06-A6@BFEBFBFF000306C3@MG221060189677       | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:15 | B0-83-FE-79-06-A6@BFEBFBFF000306C3@MG221060189677       | 否 |  |
| 421 | 福建省永恒达建设有限公司 | 2024-04-22 11:07:36.0 | 04-92-26-57-9D-A8@BFEBFBFF000906EB@2018072601672        | 否 | 2024-04-22 10:54:03.0 | 04-92-26-57-9D-A8@BFEBFBFF000906EB@2018072601672        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:39 | 04-92-26-57-9D-A8@BFEBFBFF000906EB@2018072601672        | 否 |  |
| 422 | 福建云创建工有限公司   | 2024-04-23 11:59:41.0 | E8-9C-25-A4-09-7E@BFEBFBFF00090675@0025_38DC_3140_2DDF. | 否 | 2024-04-23 10:13:16.0 | E8-9C-25-A4-09-7E@BFEBFBFF00090675@0025_38DC_3140_2DDF. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:23 | E8-9C-25-A4-09-7E@BFEBFBFF00090675@0025_38DC_3140_2DDF. | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |             |                     |  |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|-------------|---------------------|--|--|---|--|
| 423 | 福建日居建设工程有限公司  | 2024-04-22 10:55:46.0 | 18-C0-4D-50-CC-63@BF EBFBF F0009 06EB@S9T60 K8093 27   | 否 | 2024-04-22 10:47:11.0 | 18-C0-4D-50-CC-63@BF EBFBF F0009 06EB@S9T60 K8093 27   | 否 |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:33:07  | 18-C0-4D-50-CC-63@BF EBFBF F0009 06EB@S9T60 K8093 27 | 否 |  |
| 424 | 福建省峻壹建设工程有限公司 | 2024-04-22 11:13:17.0 | 7C-57-58-3F-C2-CD, BE -F4-D4-6D-BE-F9, FE -F4-D4-6D-BE-F9, FE -F4-D4-6D-BE-F9@BF EBFBF F0009 0672@ ACE4_ 2E00_ 2A55_ 6DC5_ 2EE4_ AC00_ 0000_ 0001. | 否 | 2024-04-19 16:03:07.0 | BE-F4-D4-6D-BE-F9, FE -F4-D4-6D-BE-F9, 7C -57-58-3F-C2-CD, BC -F4-D4-6D-BE-F9@BF EBFBF F0009 0672@ ACE4_ 2E00_ 2A55_ 6DC5_ 2EE4_ AC00_ 0000_ 0001. | 否 |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:30 | 7C-57-58-3F-C2-CD, BE -F4-D4-6D-BE-F9, FE -F4-D4-6D-BE-F9@BF EBFBF F0009 0672@ ACE4_ 2E00_ 2A55_ 6DC5_ 2EE4_ AC00_ 0000_ 0001. | 否  |   |  |





|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 427 | 弘筑（福建）建设集团有限公司 | 2024-04-23 18:24:31.0 | EC-D6-8A-ED-D2-F0@BF EBFBF F0009 0675@ 2C3E_ BFFF_ F000_ OB74. , WD- WCC6Y 2NT83 JU | 否 | 2024-04-23 17:36:14.0 | EC-D6-8A-ED-D2-F0@BF EBFBF F0009 0675@ 2C3E_ BFFF_ F000_ OB74. , WD- WCC6Y 2NT83 JU | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:41:16 | EC-D6-8A-ED-D2-F0@BF EBFBF F0009 0675@ 2C3E_ BFFF_ F000_ OB74. , WD- WCC6Y 2NT83 JU | 否 |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|





|     |                    |                          |   |   |                          |  |   |  |  |  |  |  |  |  |  |                     |                        |  |   |   |  |
|-----|--------------------|--------------------------|---|---|--------------------------|--|---|--|--|--|--|--|--|--|--|---------------------|------------------------|--|---|---|--|
| 430 | 中正锦鑫<br>(福建)建设有限公司 | 2024-04-23<br>10:11:00.0 | F0-<br>2F-<br>74-<br>8A-<br>E3-<br>6E@BF<br>EBFBF<br>F000A<br>0653@<br>30006<br>47366<br>5, WD-<br>WCC6Y<br>3UDNV<br>LD | 否 | 2024-04-23<br>10:09:51.0 | F0-<br>2F-<br>74-<br>8A-<br>E3-<br>6E@BF<br>EBFBF<br>F000A<br>0653@<br>30006<br>47366<br>5, WD-<br>WCC6Y<br>3UDNV<br>LD  | 否 |  |  |  |  |  |  |  |  |                     | 校验数据有<br>误, 请<br>检查    | 2024-04-24<br>08:34:23   | F0-<br>2F-<br>74-<br>8A-<br>E3-<br>6E@BF<br>EBFBF<br>F000A<br>0653@<br>30006<br>47366<br>5, WD-<br>WCC6Y<br>3UDNV<br>LD | 否 |  |
| 431 | 福建兆亿建<br>设工程有限公司   | 2024-04-23<br>16:03:41.0 | 00-<br>E0-<br>70-<br>51-<br>02-<br>EE@BF<br>EBFBF<br>F0003<br>06C3@<br>20161<br>03100<br>714, W<br>OVJLQ<br>ZC          | 否 | 2024-04-23<br>15:43:06.0 | 00-<br>E0-<br>70-<br>51-<br>02-<br>EE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>20161<br>03100<br>714, W<br>OVJLQ<br>ZC | 否 |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请<br>检查 | 2024-04-24<br>08:33:34 | 00-<br>E0-<br>70-<br>51-<br>02-<br>EE@BF<br>EBFBF<br>F0003<br>06C3@<br>20161<br>03100<br>714, W<br>OVJLQ<br>ZC | 否   |   |  |





|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 435 | 中建富林集团有限公司   | 2024-04-22 09:42:48.0 | 7C-10-C9-84-BD-41@BF EBFBF F0009 06EB@30044 82274 8, WD-WCC6Y 4VRCN ON         | 否 | 2024-04-19 17:30:50.0 | 7C-10-C9-84-BD-41@BF EBFBF F0009 06EB@30044 82274 8, WD-WCC6Y 4VRCN ON         | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:47 | 7C-10-C9-84-BD-41@BF EBFBF F0009 06EB@30044 82274 8, WD-WCC6Y 4VRCN ON         | 否 |  |
| 436 | 福建友拓建筑工程有限公司 | 2024-04-23 11:15:18.0 | 50-EB-F6-BC-A2-BE, 8C-88-2B-60-41-13@BF EBFBF F0009 0672@B2390 0389, W9AR6 T6W | 否 | 2024-04-23 11:13:59.0 | 50-EB-F6-BC-A2-BE, 8C-88-2B-60-41-13@BF EBFBF F0009 0672@B2390 0389, W9AR6 T6W | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:07 | 50-EB-F6-BC-A2-BE, 8C-88-2B-60-41-13@BF EBFBF F0009 0672@B2390 0389, W9AR6 T6W | 否 |  |







|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 440 | 福建创博建设发展有限公司 | 2024-04-22 09:47:38.0 | D8-5E-D3-49-35-9D,00-E0-4C-68-10-4C@BFEBFBF00090675@E823_8FA6_BF53_0001_001B_448B_4BFE_8FBE. | 否 | 2024-04-22 09:43:16.0 | D8-5E-D3-49-35-9D,00-E0-4C-68-10-4C@BFEBFBF00090675@E823_8FA6_BF53_0001_001B_448B_4BFE_8FBE. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误,请检查 | 2024-04-24 08:36:21 | D8-5E-D3-49-35-9D,00-E0-4C-68-10-4C,00-00-00-00-00@BFEBFBF00090675@E823_8FA6_BF53_0001_001B_448B_4BFE_8FBE. | 否 |  |
| 441 | 福建欣益丰建设有限公司  | 2024-04-23 11:14:50.0 | 58-11-22-2A-F9-FB@BFEBFBF000A0653@5239072B196200764913,WD-WCC4J2DFJ2L6                       | 否 | 2024-04-23 11:13:16.0 | 58-11-22-2A-F9-FB@BFEBFBF000A0653@5239072B196200764913,WD-WCC4J2DFJ2L6                       | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误,请检查 | 2024-04-24 08:37:04 | 58-11-22-2A-F9-FB@BFEBFBF000A0653@5239072B196200764913,WD-WCC4J2DFJ2L6                                      | 否 |  |



|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |           |                     |  |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-----------|---------------------|--|---|--|
| 443 | 福建瑞泰远建设工程有限公司 | 2024-04-23 17:30:32.0 | D4-5D-64-EF-30-30@BF<br>EBFBF<br>F0009<br>06ED@<br>2017E<br>3F834<br>AC, WD<br>-<br>WCC6Y<br>ODUE2<br>SZ  | 否 | 2024-04-23 17:27:48.0 | D4-5D-64-EF-30-30@BF<br>EBFBF<br>F0009<br>06ED@<br>2017E<br>3F834<br>AC, WD<br>-<br>WCC6Y<br>ODUE2<br>SZ  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:51:38 | D4-5D-64-EF-30-30@BF<br>EBFBF<br>F0009<br>06ED@<br>2017E<br>3F834<br>AC, WD<br>-<br>WCC6Y<br>ODUE2<br>SZ                                     | 否 |  |
| 444 | 福建骏坤建设有限公司    | 2024-04-23 09:41:01.0 | FC-34-97-71-F0-BA, 64-79-F0-A9-14-14, 64-79-F0-A9-14-10, 64-79-F0-A9-14-10, 64-79-F0-A9-14-10@BF<br>EBFBF<br>F0008<br>06C1@<br>0025_<br>38AA_<br>01D0_<br>7EF1. | 否 | 2024-04-23 09:39:25.0 | 64-79-F0-A9-14-10, 64-79-F0-A9-14-11, 66-79-F0-A9-14-10, FC-34-97-71-F0-BA, 64-79-F0-A9-14-14@BF<br>EBFBF<br>F0008<br>06C1@<br>0025_<br>38AA_<br>01D0_<br>7EF1. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:32:22 | FC-34-97-71-F0-BA, 64-79-F0-A9-14-14, 64-79-F0-A9-14-10, 64-79-F0-A9-14-10@BF<br>EBFBF<br>F0008<br>06C1@<br>0025_<br>38AA_<br>01D0_<br>7EF1. | 否 |  |



|     |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 447 | 福建六松建设有限公司 | 2024-04-23 11:37:27.0 | 00-E0-4C-59-AC-C4@178BFBF F00A50F00@0000_0006_2303_0006_3A5A_2703_E000_0070. | 否 | 2024-04-23 11:36:25.0 | 00-E0-4C-59-AC-C4@178BFBF F00A50F00@0000_0006_2303_0006_3A5A_2703_E000_0070. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:02 | 00-E0-4C-59-AC-C4@178BFBF F00A50F00@0000_0006_2303_0006_3A5A_2703_E000_0070. | 否 |  |
| 448 | 大勇集团有限公司   | 2024-04-23 17:14:39.0 | 08-BF-B8-2B-2E-BA@BF EBFBF F00090675@0000_0000_0000_0026_B778_58D5_E815.     | 否 | 2024-04-23 15:51:18.0 | 08-BF-B8-2B-2E-BA@BF EBFBF F00090675@0000_0000_0000_0026_B778_58D5_E815.     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:40:27 | 08-BF-B8-2B-2E-BA@BF EBFBF F00090675@0000_0000_0000_0026_B778_58D5_E815.     | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|---|--|
| 449 | 福建省百盛建设发展有限公司 | 2024-04-23 17:21:44.0 | B0-FC-36-C3-CA-F9, B2-FC-36-C3-CA-F9, F2-FC-36-C3-CA-F9, 30-9C-23-ED-93-A8@178BFBF F0081 OF10@411B73AGKA93, ACE4_2E81_5002_D588. | 否 | 2024-04-23 16:04:18.0 | B0-FC-36-C3-CA-F9, B2-FC-36-C3-CA-F9, F2-FC-36-C3-CA-F9, 30-9C-23-ED-93-A8@178BFBF F0081 OF10@411B73AGKA93, ACE4_2E81_5002_D588. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:10 | B0-FC-36-C3-CA-F9, B2-FC-36-C3-CA-F9, F2-FC-36-C3-CA-F9, 30-9C-23-ED-93-A8@178BFBF F0081 OF10@411B73AGKA93, ACE4_2E81_5002_D588. | 否   |   |  |
| 450 | 福建省冠先建设有限公司   | 2024-04-19 20:12:25.0 | 08-BF-B8-3A-40-56@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_444A_48E6_5BD7.  | 否 | 2024-04-19 20:11:31.0 | 08-BF-B8-3A-40-56@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_444A_48E6_5BD7.  | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:32:11  | 08-BF-B8-3A-40-56@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_444A_48E6_5BD7. | 否 |  |





|     |              |   |   |   |   |  |  |  |  |  |  |  |  |  |  |  |  |   |            |   |  |
|-----|--------------|---|---|---|---|--|--|--|--|--|--|--|--|--|--|--|--|---|------------|---|--|
| 452 | 福建阁恒建设工程有限公司 | 2024-04-23 10:17:20.0   | 否 | 2024-04-23 09:55:58.0   | 否 |  |  |  |  |  |  |  |  |  |  |  |  | 2024-04-24 08:47:36   | 校验数据有误，请检查 | 否 |  |
|     |              | EC-<br>D6-<br>8A-<br>D5-<br>C6-<br>FF, F4<br>-C8-<br>8A-<br>CF-<br>79-<br>3D, F4<br>-C8-<br>8A-<br>CF-<br>79-<br>39, F4<br>-C8-<br>8A-<br>CF-<br>79-<br>39, F4<br>-C8-<br>8A-<br>CF-<br>79-<br>39@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>4868_<br>3400_<br>0000_<br>0000. |   | F4-<br>C8-<br>8A-<br>CF-<br>79-<br>39, F4<br>-C8-<br>8A-<br>CF-<br>79-<br>3A, F6<br>-C8-<br>8A-<br>CF-<br>79-<br>39, EC<br>-D6-<br>8A-<br>D5-<br>C6-<br>FF, F4<br>-C8-<br>8A-<br>CF-<br>79-<br>3D@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>4868_<br>3400_<br>0000_<br>0000. |   |  |  |  |  |  |  |  |  |  |  |  |  | EC-<br>D6-<br>8A-<br>D5-<br>C6-<br>FF, F4<br>-C8-<br>8A-<br>CF-<br>79-<br>3D, F4<br>-C8-<br>8A-<br>CF-<br>79-<br>39, F4<br>-C8-<br>8A-<br>CF-<br>79-<br>39, F4<br>-C8-<br>8A-<br>CF-<br>79-<br>39@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>4868_<br>3400_<br>0000_<br>0000. |            |   |  |

|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 453 | 福建安居宝建设集团有限公司  | 2024-04-23 17:33:10.0 | 22-16-5C-01-0B-05@BF<br>EBFBF<br>F0005<br>06E3@<br>MG230<br>54058<br>4934,<br>19489<br>68057<br>52  | 否 | 2024-04-23 17:32:10.0 | 22-16-5C-01-0B-05@BF<br>EBFBF<br>F0005<br>06E3@<br>MG230<br>54058<br>4934,<br>19489<br>68057<br>52  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:36:02 | 22-16-5C-01-0B-05@BF<br>EBFBF<br>F0005<br>06E3@<br>MG230<br>54058<br>4934,<br>19489<br>68057<br>52  | 否 |  |
| 454 | 福建省吉福源建设工程有限公司 | 2024-04-19 17:35:29.0 | E8-9C-25-73-B4-B1@BF<br>EBFBF<br>F000A<br>0653@<br>30111<br>04583<br>5, WD-<br>WCC6Y<br>7JTZ6<br>RE | 否 | 2024-04-18 19:16:15.0 | E8-9C-25-73-B4-B1@BF<br>EBFBF<br>F000A<br>0653@<br>30111<br>04583<br>5, WD-<br>WCC6Y<br>7JTZ6<br>RE | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:40 | E8-9C-25-73-B4-B1@BF<br>EBFBF<br>F000A<br>0653@<br>30111<br>04583<br>5, WD-<br>WCC6Y<br>7JTZ6<br>RE | 否 |  |





|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 459 | 福建光磊建设有限公司   | 2024-04-23 10:13:52.0 | 58-11-22-09-AC-7A@BF<br>EBFBF<br>F000A<br>0653@<br>9VMKD<br>DV5, G<br>V2012<br>03SG0<br>00012<br>40          | 否 | 2024-04-23 09:36:25.0 | 58-11-22-09-AC-7A@BF<br>EBFBF<br>F000A<br>0653@<br>9VMKD<br>DV5, G<br>V2012<br>03SG0<br>00012<br>40          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:47 | 00-E0-4C-3C-CA-FF@BF<br>EBFBF<br>F0003<br>06C3@<br>Z2A0W<br>HM8, 1<br>931D8<br>44201<br>5                    | 否 |  |
| 460 | 福建诺乾企业管理有限公司 | 2024-04-22 17:09:36.0 | 4C-ED-FB-62-B3-51@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7782<br>51837<br>3, WD-<br>WCC6Y<br>OFNAA<br>SE | 否 | 2024-04-22 17:03:05.0 | 4C-ED-FB-62-B3-51@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7782<br>51837<br>3, WD-<br>WCC6Y<br>OFNAA<br>SE | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:42:02 | 4C-ED-FB-62-B3-51@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7782<br>51837<br>3, WD-<br>WCC6Y<br>OFNAA<br>SE | 否 |  |
| 461 | 江西景态园林艺术有限公司 | 2024-04-23 15:12:00.0 | D8-5E-D3-C3-3B-EF@BF<br>EBFBF<br>F000A<br>0653@<br>CM48B<br>BH200<br>3295                                    | 否 | 2024-04-23 15:12:20.0 | D8-5E-D3-C3-3B-EF@BF<br>EBFBF<br>F000A<br>0653@<br>CM48B<br>BH200<br>3295                                    | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:39:04 | D8-5E-D3-C3-3B-EF@BF<br>EBFBF<br>F000A<br>0653@<br>CM48B<br>BH200<br>3295                                    | 否 |  |













|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 470 | 福建侨联建设有限公司    | 2024-04-23 16:50:12.0 | 22-46-5C-03-02-4D, 0C-5B-8F-27-9A-64@BF EBFBF F0005 06E3@ YS202 30604 69478 0          | 否 | 2024-04-22 10:58:20.0 | 22-46-5C-03-02-4D, 0C-5B-8F-27-9A-64@BF EBFBF F0005 06E3@ YS202 30604 69478 0          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:52 | 22-46-5C-03-02-4D, 0C-5B-8F-27-9A-64@BF EBFBF F0005 06E3@ YS202 30604 69478 0          | 否 |  |
| 471 | 福建省富星建设工程有限公司 | 2024-04-23 16:11:32.0 | 58-11-22-D1-6C-90@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 48E4_ D759. | 否 | 2024-04-23 16:07:47.0 | 58-11-22-D1-6C-90@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 48E4_ D759. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:15 | 58-11-22-D1-6C-90@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 48E4_ D759. | 否 |  |

|     |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 472 | 福建省腾昌建设有限公司     | 2024-04-22 09:51:43.0 | 94-C6-91-90-61-67,00-E0-4A-37-AD-E0,B4-6B-FC-56-AF-B2@BF-EBFBF-F0009-06EA@WD-WCC6Y-OPZ2TU8 | 否 | 2024-04-22 09:52:23.0 | 94-C6-91-90-61-67,00-E0-4A-37-AD-E0,B4-6B-FC-56-AF-B2@BF-EBFBF-F0009-06EA@WD-WCC6Y-OPZ2TU8 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误,请检查 | 2024-04-24 08:33:10 | 94-C6-91-90-61-67,00-E0-4A-37-AD-E0,B4-6B-FC-56-AF-B2@BF-EBFBF-F0009-06EA@WD-WCC6Y-OPZ2TU8 | 否 |  |
| 473 | 福建省顺禾园林建筑工程有限公司 | 2024-04-23 17:12:49.0 | 00-E0-4C-79-0E-74@BF-EBFBF-F0009-0675@0000_0000_0000_0000_0000_0054_7000_0449.             | 否 | 2024-04-23 16:03:35.0 | 00-E0-4C-79-0E-74@BF-EBFBF-F0009-0675@0000_0000_0000_0000_0000_0054_7000_0449.             | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误,请检查 | 2024-04-24 08:41:02 | 00-E0-4C-79-0E-74@BF-EBFBF-F0009-0675@0000_0000_0000_0000_0000_0054_7000_0449.             | 否 |  |

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 474 | 福建省诺铭建筑工程有限公司 | 2024-04-23 17:47:23.0 | 00-E0-1A-B9-50-C3@BF EBFBF F0003 06F2@YS215 1202S BHM00360                          | 否 | 2024-04-23 17:45:31.0 | 00-E0-1A-B9-50-C3@BF EBFBF F0003 06F2@YS215 1202S BHM00360                          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:29 | 00-E0-1A-B9-50-C3@BF EBFBF F0003 06F2@YS215 1202S BHM00360                          | 否 |  |
| 475 | 福建省黎宾建筑工程有限公司 | 2024-04-22 17:24:19.0 | A0-36-BC-AA-DF-7D@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0000_0100_0000_0000. | 否 | 2024-04-22 17:10:39.0 | A0-36-BC-AA-DF-7D@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0000_0100_0000_0000. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:41 | A0-36-BC-AA-DF-7D@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0000_0100_0000_0000. | 否 |  |
| 476 | 福建顺驰建设工程有限公司  | 2024-04-22 15:34:28.0 | 60-45-CB-9B-E1-7B@BF EBFBF F0005 06E3@WD-WCC3F 3LCUL DP, 50 026B7 682C2 5F9F        | 否 | 2024-04-22 15:25:04.0 | 60-45-CB-9B-E1-7B@BF EBFBF F0005 06E3@WD-WCC3F 3LCUL DP, 50 026B7 682C2 5F9F        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:07 | 60-45-CB-9B-E1-7B@BF EBFBF F0005 06E3@WD-WCC3F 3LCUL DP, 50 026B7 682C2 5F9F        | 否 |  |

|     |                  |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|------------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 477 | 福建省驰城建设工程有限公司    | 2024-04-23 12:07:37.0 | 00-E0-4C-55-8B-03@BF EBFBF F000A 0653@WD-WCC6Y 3KZLH L4, 30 07021 7205                               | 否 | 2024-04-23 12:02:22.0 | 00-E0-4C-55-8B-03@BF EBFBF F000A 0653@WD-WCC6Y 3KZLH L4, 30 07021 7205                               | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:40 | 00-E0-4C-55-8B-03@BF EBFBF F000A 0653@WD-WCC6Y 3KZLH L4, 30 07021 7205                               | 否 |  |
| 478 | 杨帆起航（福建）建设工程有限公司 | 2024-04-23 12:28:14.0 | 00-FF-03-F2-D2-4E, 00 -E0-4C-41-D5-E1@BF EBFBF F0002 06C2@CSWRO 24092 302A0 0 4, W - DCW6C 4YNU1 5PP | 否 | 2024-04-23 12:25:59.0 | 00-FF-03-F2-D2-4E, 00 -E0-4C-41-D5-E1@BF EBFBF F0002 06C2@CSWRO 24092 302A0 0 4, W - DCW6C 4YNU1 5PP | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:53 | 00-FF-03-F2-D2-4E, 00 -E0-4C-41-D5-E1@BF EBFBF F0002 06C2@CSWRO 24092 302A0 0 4, W - DCW6C 4YNU1 5PP | 否 |  |









|     |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 483 | 福建通乾建设有限公司 | 2024-04-23 18:50:35.0 | 74-56-3C-A5-58-EB@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A785_<br>D000_<br>022A.   | 否 | 2024-04-23 18:46:42.0 | 74-56-3C-A5-58-EB@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A785_<br>D000_<br>022A.   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:07 | 74-56-3C-A5-58-EB@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A785_<br>D000_<br>022A.   | 否 |  |
| 484 | 福建华尚建设有限公司 | 2024-04-22 14:50:14.0 | 74-56-3C-19-82-A6@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>ONAY2<br>UV,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_64<br>C9_52<br>E5. | 否 | 2024-04-22 12:01:46.0 | 74-56-3C-19-82-A6@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>ONAY2<br>UV,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_64<br>C9_52<br>E5. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:51:52 | 74-56-3C-19-82-A6@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>ONAY2<br>UV,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_64<br>C9_52<br>E5. | 否 |  |

|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 485 | 福建德成工程项目管理有限公司 | 2024-04-23 14:52:35.0 | 2C-F0-5D-A1-17-C4@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_1EOF_0645. | 否 | 2024-04-23 14:50:14.0 | 2C-F0-5D-A1-17-C4@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_1EOF_0645. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:47 | 2C-F0-5D-A1-17-C4@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_1EOF_0645. | 否 |  |
| 486 | 福建丰本建设工程有限公司   | 2024-04-24 08:03:28.0 | F0-2F-74-4F-79-D0@BFEBFBFF000A0653@30031891552                              | 否 | 2024-04-24 08:02:45.0 | F0-2F-74-4F-79-D0@BFEBFBFF000A0653@30031891552                              | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:15 | F0-2F-74-4F-79-D0@BFEBFBFF000A0653@30031891552                              | 否 |  |











|     |                  |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|-----|------------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 492 | 福建省古田县凤埔建筑工程有限公司 | 2024-04-22 14:07:25.0 | 34-97-F6-28-45-A1,00-00-00-00-00-00-E0@BFEBFBFF000306C3@4d46303635303253303348383030363135372020,2020202057202d4443573643345a4b5a56365246 | 否 | 2024-04-19 16:58:30.0 | 34-97-F6-28-45-A1,00-00-00-00-00-00-E0@BFEBFBFF000306C3@4d46303635303253303348383030363135372020,2020202057202d4443573643345a4b5a56365246 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:31:15 | 34-97-F6-28-45-A1,00-00-00-00-00-00-E0@BFEBFBFF000306C3@4d46303635303253303348383030363135372020,2020202057202d4443573643345a4b5a56365246 | 否   |   |  |
| 493 | 中正置润(福建)建设发展有限公司 | 2024-04-23 17:38:52.0 | F0-2F-74-FA-0A-50@BFEBFBFF000A0653@50026B7380E27729   | 否 | 2024-04-23 17:37:05.0 | F0-2F-74-FA-0A-50@BFEBFBFF000A0653@50026B7380E27729   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:36:17   | F0-2F-74-FA-0A-50@BFEBFBFF000A0653@50026B7380E27729 | 否 |  |



|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 495 | 福建省闽清四建建工有限公司 | 2024-04-18 17:50:37.0 | 74-56-3C-04-C6-OD@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0026_ B728_ 2CA0_ 1615. , WD- WCC6Y NW2AL 25 | 否 | 2024-04-18 17:49:45.0 | 74-56-3C-04-C6-OD@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0026_ B728_ 2CA0_ 1615. , WD- WCC6Y NW2AL 25 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:41:07 | 74-56-3C-04-C6-OD, CO -A5-DD-69-2E-FF@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0026_ B728_ 2CA0_ 1615. , WD- WCC6Y NW2AL 25 | 否 |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 497 | 福建望城建设工程有限公司 | 2024-04-23 19:37:28.0 | 74-56-3C-D1-1C-0B,44-F9-71-D2-38-34@BF EBFBF F0009 0675@WD-WCC3F 1EA5F KC,NA YA18A 36A00 776 _0000 0001. | 否 | 2024-04-23 18:19:14.0 | 74-56-3C-D1-1C-0B,44-F9-71-D2-38-34@BF EBFBF F0009 0675@WD-WCC3F 1EA5F KC,NA YA18A 36A00 776 _0000 0001. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:40:33 | 44-F9-71-D2-38-34,74-56-3C-D1-1C-0B@BF EBFBF F0009 0675@WD-WCC3F 1EA5F KC,NA YA18A 36A00 776 _0000 0001. | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|

|     |                |  |   |  |   |  |  |  |  |  |  |  |  |  |  |  |  |            |  |   |  |
|-----|----------------|--|---|--|---|--|--|--|--|--|--|--|--|--|--|--|--|------------|--|---|--|
| 498 | 长衢（福建）建设集团有限公司 | 2024-04-23 16:13:15.0  | 否 | 2024-04-23 08:46:34.0  | 否 |  |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:38:26  | 否 |  |
|     |                | F4-<br>B5-<br>20-<br>46-<br>58-<br>9D, 50<br>-2B-<br>73-<br>A9-<br>02-<br>E3, 50<br>-2B-<br>73-<br>A9-<br>02-<br>E3, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>WX202<br>21128<br>4305H<br>P, WD-<br>WMC65<br>OD9WS<br>H9 |   | F4-<br>B5-<br>20-<br>46-<br>58-<br>9D, 50<br>-2B-<br>73-<br>A9-<br>02-<br>E3, 50<br>-2B-<br>73-<br>A9-<br>02-<br>E3, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>WX202<br>21128<br>4305H<br>P, WD-<br>WMC65<br>OD9WS<br>H9 |   |  |  |  |  |  |  |  |  |  |  |  |  |            | F4-<br>B5-<br>20-<br>46-<br>58-<br>9D, 50<br>-2B-<br>73-<br>A9-<br>02-<br>E3, 50<br>-2B-<br>73-<br>A9-<br>02-<br>E3, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>WX202<br>21128<br>4305H<br>P, WD-<br>WMC65<br>OD9WS<br>H9 |   |  |

|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|---|--|
| 499 | 福建省峰豪建设有限公司  | 2024-04-22 11:55:09.0 | 18-C0-4D-23-33-9C,00-E0-4C-68-58-8E@178BFBF F00810F81@WD-WCC6Y6HPYS60,E823_8FA6_BF53_0001_001B_448B_4941_9393. | 否 | 2024-04-22 11:41:49.0 | 18-C0-4D-23-33-9C,00-E0-4C-68-58-8E@178BFBF F00810F81@WD-WCC6Y6HPYS60,E823_8FA6_BF53_0001_001B_448B_4941_9393. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:42:32 | 18-C0-4D-23-33-9C,00-E0-4C-68-58-8E@178BFBF F00810F81@WD-WCC6Y6HPYS60,E823_8FA6_BF53_0001_001B_448B_4941_9393. | 否   |   |  |
| 500 | 腾越时代建设有限公司   | 2024-04-23 09:04:22.0 | 18-C0-4D-49-22-6E@BFEBFBFF000A0653@WD-WCC6Y3UNNESK,20439F448102  | 否 | 2024-04-23 09:03:03.0 | 18-C0-4D-49-22-6E@BFEBFBFF000A0653@WD-WCC6Y3UNNESK,20439F448102  | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:35:06  | 18-C0-4D-49-22-6E@BFEBFBFF000A0653@WD-WCC6Y3UNNESK,20439F448102 | 否 |  |
| 501 | 福建志锐建设工程有限公司 | 2024-04-23 15:38:58.0 | 00-CF-E0-50-5C-DA,00-00-   | 否 | 2024-04-19 13:57:28.0 | 00-CF-E0-50-5C-DA,00-00-   | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:41:33  | 00-CF-E0-50-5C-DA,00-00-  | 否 |  |

|     |                      |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                           |   |  |   |  |
|-----|----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|---------------------------|---|--|---|--|
|     |                      |                                  | 00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>SCRW1<br>90507<br>02F23<br>96, WD<br>-<br>WCC6Y<br>7LTVN<br>6D                            |   |                                  | 00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>SCRW1<br>90507<br>02F23<br>96, WD<br>-<br>WCC6Y<br>7LTVN<br>6D                            |   |  |  |  |  |  |  |  |  |  |                           | 00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>SCRW1<br>90507<br>02F23<br>96, WD<br>-<br>WCC6Y<br>7LTVN<br>6D |  |   |  |
| 502 | 福建日顺建<br>工发展有限<br>公司 | 2024-<br>04-23<br>10:57<br>:33.0 | 00-<br>E0-<br>4C-<br>0A-<br>25-<br>71, 00<br>-FF-<br>10-<br>28-<br>11-<br>B7@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>14338<br>B, 125<br>D2014<br>0310 | 否 | 2024-<br>04-23<br>10:43<br>:36.0 | 00-<br>E0-<br>4C-<br>0A-<br>25-<br>71, 00<br>-FF-<br>10-<br>28-<br>11-<br>B7@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>14338<br>B, 125<br>D2014<br>0310 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>查 | 2024-<br>04-24<br>08:36<br>:10  | 00-<br>E0-<br>4C-<br>0A-<br>25-<br>71, 00<br>-FF-<br>10-<br>28-<br>11-<br>B7@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>14338<br>B, 125<br>D2014<br>0310 | 否 |  |



|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 503 | 福建省百花建设集团有限公司 | 2024-04-23 17:58:36.0 | B4-2E-99-B3-AB-DF, 00-00-00-00-00-00-06EB@50026B770526662F | 否 | 2024-04-23 17:56:30.0 | B4-2E-99-B3-AB-DF, 00-00-00-00-00-00-06EB@50026B770526662F | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:43:00 | B4-2E-99-B3-AB-DF@BFEBFBF000906EB@50026B770526662F | 否 |  |
| 504 | 福建天江建设工程有限公司  | 2024-04-20 13:51:14.0 | 18-31-BF-93-6E-FF, 00-00-00-00-00-00-06E9@Z9ASB11E         | 否 | 2024-04-20 13:40:42.0 | 18-31-BF-93-6E-FF, 00-00-00-00-00-00-06E9@Z9ASB11E         | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:09 | 18-31-BF-93-6E-FF@BFEBFBF000906E9@Z9ASB11E         | 否 |  |

|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 505 | 福建省益丰建设工程有限公司  | 2024-04-23 17:01:24.0 | 2C-F0-5D-A1-12-5D@BF<br>EBFBF<br>F000A<br>0653@<br>00000<br>00005<br>,E823<br>_8FA6<br>_BF53<br>_0001<br>_001B<br>_448B<br>_49BC<br>_C233<br>.,JR1<br>0006P<br>0J6B6<br>F | 否 | 2024-04-22 14:52:12.0 | 2C-F0-5D-A1-12-5D@BF<br>EBFBF<br>F000A<br>0653@<br>00000<br>00005<br>,E823<br>_8FA6<br>_BF53<br>_0001<br>_001B<br>_448B<br>_49BC<br>_C233<br>.,JR1<br>0006P<br>0J6B6<br>F | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:40:15 | 2C-F0-5D-A1-12-5D@BF<br>EBFBF<br>F000A<br>0653@<br>00000<br>00005<br>,E823<br>_8FA6<br>_BF53<br>_0001<br>_001B<br>_448B<br>_49BC<br>_C233<br>.,JR1<br>0006P<br>0J6B6<br>F | 否   |   |  |
| 506 | 安徽中栋建筑项目管理有限公司 | 2024-04-23 13:50:24.0 | 00-E0-4F-14-74-D0@BF<br>EBFBF<br>F0003<br>06A9@<br>AA000<br>00000<br>00000<br>00000   | 否 | 2024-04-23 13:47:51.0 | 00-E0-4F-14-74-D0@BF<br>EBFBF<br>F0003<br>06A9@<br>AA000<br>00000<br>00000<br>00000   | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:39:13   | 00-E0-4F-14-74-D0@BF<br>EBFBF<br>F0003<br>06A9@<br>AA000<br>00000<br>00000<br>00000 | 否 |  |









|     |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 513 | 厦门金腾装饰集团有限公司   | 2024-04-19 15:58:23.0 | 08-BF-04-49-FD@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_2330_4125.,2570 32124 60821 62027 | 否 | 2024-04-19 15:29:25.0 | 08-BF-04-49-FD@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_2330_4125.,2570 32124 60821 62027 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:55 | 08-BF-04-49-FD@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_2330_4125.    | 否 |  |
| 514 | 陕西中天丽达建设工程有限公司 | 2024-04-17 09:48:23.0 | 04-7C-16-CD-39-06@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_2361_0745.                     | 否 | 2024-04-16 09:20:14.0 | 04-7C-16-CD-39-06@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_2361_0745.                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:40 | 04-7C-16-CD-39-06@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_2361_0745. | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 515 | 湖南省园景生态园林有限公司 | 2024-04-23 21:15:29.0 | FA-54-F6-09-E0-03, FE-54-F6-09-E0-03, F8-54-F6-09-E0-03@BF EBFBF F000B 06A2@ 0025_ 38E5_ 31A1_ 123A. | 否 | 2024-04-23 21:05:56.0 | FA-54-F6-09-E0-03, FE-54-F6-09-E0-03, F8-54-F6-09-E0-03@BF EBFBF F000B 06A2@ 0025_ 38E5_ 31A1_ 123A. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:23 | D8-43-AE-75-20-CD@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 2AF8_ A605.      | 否 |  |
| 516 | 福建盈万利建设工程有限公司 | 2024-04-22 11:56:03.0 | 48-8A-D2-F5-AA-FC, 00-CF-E0-47-31-93@BF EBFBF F0009 06E9@ WD-WCC6Y 3EYA7 YT, 19 12524 59602          | 否 | 2024-04-22 11:52:36.0 | 48-8A-D2-F5-AA-FC, 00-CF-E0-47-31-93@BF EBFBF F0009 06E9@ WD-WCC6Y 3EYA7 YT, 19 12524 59602          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:07 | 48-8A-D2-F5-AA-FC, 00-CF-E0-47-31-93@BF EBFBF F0009 06E9@ WD-WCC6Y 3EYA7 YT, 19 12524 59602 | 否 |  |





|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 519 | 福建华进建设工程有限公司  | 2024-04-23 10:03:15.0 | 04-D9-F5-CA-AF-8D@BFEBFBFF000906EA@30092727678                        | 否 | 2024-04-23 10:01:38.0 | 04-D9-F5-CA-AF-8D@BFEBFBFF000906EA@30092727678                        | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:04 | 04-D9-F5-CA-AF-8D@BFEBFBFF000906EA@30092727678                        | 否 |  |
| 520 | 福建源联鑫建设工程有限公司 | 2024-04-22 10:13:15.0 | D8-5E-D3-AA-9E-E9@BFEBFBFF00090672@W9AROYFV,0025_38BA_1100_931C.      | 否 | 2024-04-22 09:56:46.0 | D8-5E-D3-AA-9E-E9@BFEBFBFF00090672@W9AROYFV,0025_38BA_1100_931C.      | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:14 | D8-5E-D3-AA-9E-E9@BFEBFBFF00090672@W9AROYFV,0025_38BA_1100_931C.      | 否 |  |
| 521 | 福建建驰建筑工程有限公司  | 2024-04-23 15:21:44.0 | 00-E0-4C-3C-CB-5A@BFEBFBFF000A0653@AA000000000000006,W D-WCCEAF5B5859 | 否 | 2024-04-23 15:17:37.0 | 00-E0-4C-3C-CB-5A@BFEBFBFF000A0653@AA000000000000006,W D-WCCEAF5B5859 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:04 | 00-E0-4C-3C-CB-5A@BFEBFBFF000A0653@AA000000000000006,W D-WCCEAF5B5859 | 否 |  |

|     |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 522 | 莆田市融辉建设工程有限公司   | 2024-04-22 16:20:59.0 | 08-BF-B8-70-68-CF@BF EBFBF F000A 0653@WD-WCC6Y 6R3SZ ZK, AA 20230 20000 63 | 否 | 2024-04-22 12:11:00.0 | 08-BF-B8-70-68-CF@BF EBFBF F000A 0653@WD-WCC6Y 6R3SZ ZK, AA 20230 20000 63 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:43:10 | 08-BF-B8-70-68-CF@BF EBFBF F000A 0653@WD-WCC6Y 6R3SZ ZK, AA 20230 20000 63 | 否 |  |
| 523 | 福建卓昌建设工程有限公司    | 2024-04-23 17:08:39.0 | D8-BB-C1-D9-3C-88@BF EBFBF F000A 0653@12PK5 3BMS, CM133 BH090 1003         | 否 | 2024-04-22 16:05:27.0 | D8-BB-C1-D9-3C-88@BF EBFBF F000A 0653@12PK5 3BMS, CM133 BH090 1003         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:12 | D8-BB-C1-D9-3C-88@BF EBFBF F000A 0653@12PK5 3BMS, CM133 BH090 1003         | 否 |  |
| 524 | 亿曼德（福建）建设集团有限公司 | 2024-04-22 14:55:43.0 | E0-D5-5E-57-A7-1C@BF EBFBF F0009 06E9@10006 63407 8, WD-WCC6Y 2FNUX 4V     | 否 | 2024-04-22 11:19:03.0 | E0-D5-5E-57-A7-1C@BF EBFBF F0009 06E9@10006 63407 8, WD-WCC6Y 2FNUX 4V     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:33 | E0-D5-5E-57-A7-1C@BF EBFBF F0009 06E9@10006 63407 8, WD-WCC6Y 2FNUX 4V     | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 525 | 福建省众点建设有限公司   | 2024-04-19 20:52:56.0 | 00-E0-0B-28-E0-09, 52-2B-73-E8-09-7A, 50-2B-73-E8-09-7A@BFEBFBFF000206D7@2110JPDD25600006030 | 否 | 2024-04-19 20:50:17.0 | 00-E0-0B-28-E0-09, 52-2B-73-E8-09-7A, 50-2B-73-E8-09-7A@BFEBFBFF000206D7@2110JPDD25600006030 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 09:08:31 | 00-E0-0B-28-E0-09, 52-2B-73-E8-09-7A, 50-2B-73-E8-09-7A@BFEBFBFF000206D7@2110JPDD25600006030 | 否 |  |
| 526 | 福建鼎炸鑫建设工程有限公司 | 2024-04-23 17:47:39.0 | 00-E0-4C-02-D5-C7@BFEBFBFF000506E3@YS2048039SBVS0363   | 否 | 2024-04-23 10:07:06.0 | 00-E0-4C-02-D5-C7@BFEBFBFF000506E3@YS2048039SBVS0363   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:47 | 00-E0-4C-02-D5-C7@BFEBFBFF000506E3@YS2048039SBVS0363   | 否 |  |



|     |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 529 | 福建象环建设有限公司 | 2024-04-23 11:01:56.0 | 58-11-22-C6-79-BB@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 207D_ 3F35. , WD- WCC6Y 5URXT Z8 | 否 | 2024-04-23 09:24:35.0 | 58-11-22-C6-79-BB@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 207D_ 3F35. , WD- WCC6Y 5URXT Z8 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:38:06 | 00- E0- 4C- DB- D0- 52@BF EBFBF F0003 06A9@ 584d3 25f30 30323 53136 30382 03120 20202 02020 , 2020 20202 02020 20202 02020 4e5a4 7314a 515a4 b | 否 |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|













|     |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |           |                     |  |   |   |  |
|-----|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-----------|---------------------|--|---|---|--|
| 535 | 福建恒禹建设有限公司      | 2024-04-23 09:21:26.0 | F0-2F-74-CC-17-14@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>2LY4P<br>DZ, CM<br>317BH<br>15057<br>45 | 否 | 2024-04-22 10:07:23.0 | F0-2F-74-CC-17-14@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>2LY4P<br>DZ, CM<br>317BH<br>15057<br>45 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:33:08 | F0-2F-74-CC-17-14@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>2LY4P<br>DZ, CM<br>317BH<br>15057<br>45 | 否   |   |  |
| 536 | 中盛旭峰(福建)建设有限公司  | 2024-04-23 11:17:13.0 | 00-E2-69-5E-54-BA@BF<br>EBFBF<br>F000A<br>0653@<br>CM379<br>BH113<br>9314                                  | 否 | 2024-04-23 10:10:22.0 | 00-E2-69-5E-54-BA@BF<br>EBFBF<br>F000A<br>0653@<br>CM379<br>BH113<br>9314                                  | 否 |  |  |  |  |  |  |  |  |  |           | 校验数据有, 请查           | 2024-04-24 08:31:43  | 00-E2-69-5E-54-BA@BF<br>EBFBF<br>F000A<br>0653@<br>CM379<br>BH113<br>9314             | 否 |  |
| 537 | 福建省夏洛朗特建筑工程有限公司 | 2024-04-22 16:38:16.0 | 1C-83-41-77-AA-AC@BF<br>EBFBF<br>F000A<br>0653@<br>A428<br>B700_1E28_0088.<br>, Z1IH<br>99DMS              | 否 | 2024-04-22 16:30:03.0 | 1C-83-41-77-AA-AC@BF<br>EBFBF<br>F000A<br>0653@<br>A428<br>B700_1E28_0088.<br>, Z1IH<br>99DMS              | 否 |  |  |  |  |  |  |  |  |  |           | 校验数据有, 请查           | 2024-04-24 08:35:46  | 1C-83-41-77-AA-AC@BF<br>EBFBF<br>F000A<br>0653@<br>A428_1E28_0088.<br>, Z1IH<br>99DMS | 否 |  |



|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 540 | 海峡建工集团有限公司     | 2024-04-23 16:21:35.0 | C8-7F-54-AA-57-A7@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC4J<br>1XSZP<br>KT,00<br>00_00<br>00_00<br>00_00<br>00_A4<br>28_B7<br>02_47<br>31_00<br>C2. | 否 | 2024-04-23 10:13:34.0 | C8-7F-54-AA-57-A7@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC4J<br>1XSZP<br>KT,00<br>00_00<br>00_00<br>00_00<br>00_A4<br>28_B7<br>02_47<br>31_00<br>C2. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:39:02 | C8-7F-54-AA-57-A7@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC4J<br>1XSZP<br>KT,00<br>00_00<br>00_00<br>00_00<br>00_A4<br>28_B7<br>02_47<br>31_00<br>C2. | 否   |   |  |
| 541 | 福建峰华工程项目管理有限公司 | 2024-04-23 14:39:16.0 | 74-56-3C-43-16-CO@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1CAC_<br>36C5.                                 | 否 | 2024-04-23 14:36:58.0 | 74-56-3C-43-16-CO@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1CAC_<br>36C5.                                 | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:31:08   | 74-56-3C-43-16-CO@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1CAC_<br>36C5. | 否 |  |













|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 549 | 福建东益建设工程有限公司 | 2024-04-23 10:47:31.0 | 9C-7B-EF-57-C5-FE, DA-12-65-89-FE-ED, FA-12-65-89-FE-ED, D8-12-65-89-FE-EE@BF EBFBF F0009 06EA@ 0025_ 388C_ 91D0_ E9AC. , 20NJ 8RXMS | 否 | 2024-04-23 10:44:50.0 | 9C-7B-EF-57-C5-FE, DA-12-65-89-FE-ED, FA-12-65-89-FE-ED, D8-12-65-89-FE-EE@BF EBFBF F0009 06EA@ 0025_ 388C_ 91D0_ E9AC. , 20NJ 8RXMS | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:04 | 9C-7B-EF-57-C5-FE, DA-12-65-89-FE-ED, FA-12-65-89-FE-ED, D8-12-65-89-FE-EE@BF EBFBF F0009 06EA@ 0025_ 388C_ 91D0_ E9AC. , 20NJ 8RXMS | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|

|     |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                            |                                |   |   |   |  |
|-----|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|---|--|
| 550 | 福建省双源<br>工程技术有<br>限公司 | 2024-<br>04-22<br>11:09<br>:25.0 | C0-<br>25-<br>A5-<br>CE-<br>91-<br>C7@BF<br>EBFBF<br>F000A<br>0653@<br>FSB2N<br>52431<br>0402B<br>4P_00<br>00000<br>1.,ZN<br>1WA6W<br>C | 否 | 2024-<br>04-22<br>10:52<br>:28.0 | C0-<br>25-<br>A5-<br>CE-<br>91-<br>C7@BF<br>EBFBF<br>F000A<br>0653@<br>FSB2N<br>52431<br>0402B<br>4P_00<br>00000<br>1.,ZN<br>1WA6W<br>C | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:32<br>:03 | C0-<br>25-<br>A5-<br>CE-<br>91-<br>C7@BF<br>EBFBF<br>F000A<br>0653@<br>FSB2N<br>52431<br>0402B<br>4P_00<br>00000<br>1.,ZN<br>1WA6W<br>C | 否   |   |  |
| 551 | 福建億兴建<br>设有限公司        | 2024-<br>04-23<br>08:54<br>:01.0 | E8-<br>9C-<br>25-<br>32-<br>D4-<br>C9@BF<br>EBFBF<br>F0009<br>0672@<br>2C3E_<br>BFFF_<br>F000_<br>052C.                                 | 否 | 2024-<br>04-23<br>08:52<br>:50.0 | E8-<br>9C-<br>25-<br>32-<br>D4-<br>C9@BF<br>EBFBF<br>F0009<br>0672@<br>2C3E_<br>BFFF_<br>F000_<br>052C.                                 | 否 |  |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>，请<br>检查     | 2024-<br>04-24<br>08:31<br>:08  | E8-<br>9C-<br>25-<br>32-<br>D4-<br>C9@BF<br>EBFBF<br>F0009<br>0672@<br>2C3E_<br>BFFF_<br>F000_<br>052C. | 否 |  |





|     |                      |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|-----|----------------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 555 | 中亿路航<br>(福建)建设发展有限公司 | 2024-04-23 10:08:27.0 | 00-<br>E0-<br>4C-<br>76-<br>B6-<br>ED@BF<br>EBFBF<br>F000A<br>0653@<br>41413<br>03030<br>30303<br>03030<br>30393<br>23133<br>, 2020<br>20205<br>7202d<br>44435<br>73243<br>44453<br>43934<br>30353<br>5 | 否 | 2024-04-22 16:17:10.0 | 00-<br>E0-<br>4C-<br>76-<br>B6-<br>ED, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>41413<br>03030<br>30303<br>03030<br>30303<br>30303<br>03030<br>23133<br>, 2020<br>03030<br>30393<br>23133<br>, 2020<br>20205<br>7202d<br>44435<br>73243<br>20205<br>7202d<br>44435<br>73243<br>44453<br>43934<br>30353<br>5 | 否 |  |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:34:21   | 00-<br>E0-<br>4C-<br>76-<br>B6-<br>ED@BF<br>EBFBF<br>F000A<br>0653@<br>41413<br>03030<br>30303<br>03030<br>30393<br>23133<br>, 2020<br>20205<br>7202d<br>44435<br>73243<br>44453<br>43934<br>30353<br>5 | 否 |  |
| 556 | 南平鸿睿建设工程有限公司         | 2024-04-17 09:34:14.0 | 18-<br>C0-<br>4D-<br>DE-<br>DD-<br>36@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>DEB35<br>D   | 否 | 2024-04-16 10:06:34.0 | 18-<br>C0-<br>4D-<br>DE-<br>DD-<br>36@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>DEB35<br>D  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:16 | 18-<br>C0-<br>4D-<br>DE-<br>DD-<br>36@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>DEB35<br>D | 否   |   |  |



|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 557 | 林航建设有限公司      | 2024-04-23 11:25:31.0 | 04-7C-16-7E-93-AD, OA-61-10-11-14-89@BFEBFBFF000A0653@SCRW23050302G0357          | 否 | 2024-04-19 15:35:00.0 | 04-7C-16-7E-93-AD, OA-61-10-11-14-89@BFEBFBFF000A0653@SCRW23050302G0357          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:31 | 04-7C-16-7E-93-AD, OA-61-10-11-14-89@BFEBFBFF000A0653@SCRW23050302G0357          | 否 |  |
| 558 | 福建源利兴建筑工程有限公司 | 2024-04-23 09:08:55.0 | 58-11-22-CC-8F-EB@BFEBFBFF00090672@0000_0000_0000_0000_0000_0000_0100_0000_0000. | 否 | 2024-04-23 09:06:29.0 | 58-11-22-CC-8F-EB@BFEBFBFF00090672@0000_0000_0000_0000_0000_0000_0100_0000_0000. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:06 | 58-11-22-CC-8F-EB@BFEBFBFF00090672@0000_0000_0000_0000_0000_0000_0100_0000_0000. | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 559 | 福建新东南建设工程有限公司 | 2024-04-22 20:29:28.0 | 7C-10-C9-D2-DD-C4@BF EBFBF F000A 0671@4B0187D053C9, AA00000012150006097, WD-WCC6Y7SKVHC6 | 否 | 2024-04-22 20:27:32.0 | 7C-10-C9-D2-DD-C4@BF EBFBF F000A 0671@4B0187D053C9, AA00000012150006097, WD-WCC6Y7SKVHC6 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:07 | 7C-10-C9-D2-DD-C4@BF EBFBF F000A 0671@4B0187D053C9, AA00000012150006097, WD-WCC6Y7SKVHC6 | 否 |  |
| 560 | 福建旭业建设工程有限公司  | 2024-04-23 18:23:56.0 | 74-56-3C-C2-33-65@BF EBFBF F000A 0653@50026B738255AD0C                                   | 否 | 2024-04-23 18:21:44.0 | 74-56-3C-C2-33-65@BF EBFBF F000A 0653@50026B738255AD0C                                   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:39 | 74-56-3C-C2-33-65@BF EBFBF F000A 0653@50026B738255AD0C                                   | 否 |  |
| 561 | 福建省三众建筑工程有限公司 | 2024-04-23 11:23:53.0 | 94-DE-80-40-79-1C@BF EBFBF F0000 06F6@2020202057202d44435732434a4533                     | 否 | 2024-04-23 11:15:24.0 | 94-DE-80-40-79-1C, 00-00-00-00-00-00-EO@BF EBFBF F0000                                   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:39 | 94-DE-80-40-79-1C@BF EBFBF F0000 06F6@2020202057202d44435732434a4533                     | 否 |  |











|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 569 | 福建评禹水利水电工程有限公司 | 2024-04-23 09:45:54.0 | 00-<br>E2-<br>69-<br>55-<br>59-<br>AD, 00<br>-AF-<br>AE-<br>68-<br>A8-<br>E7@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>5VT76<br>T4, JS<br>MC214<br>16806<br>23 | 否 | 2024-04-23 09:43:29.0 | 00-<br>E2-<br>69-<br>55-<br>59-<br>AD, 00<br>-AF-<br>AE-<br>68-<br>A8-<br>E7@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>5VT76<br>T4, JS<br>MC214<br>16806<br>23 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:38:04 | 00-<br>E2-<br>69-<br>55-<br>59-<br>AD, 00<br>-AF-<br>AE-<br>68-<br>A8-<br>E7@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>5VT76<br>T4, JS<br>MC214<br>16806<br>23 | 否 |  |
| 570 | 四川蜀元建筑集团有限公司   | 2024-04-23 17:32:52.0 | E8-<br>9C-<br>25-<br>A5-<br>9D-<br>59@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>267F_<br>6BD5.                  | 否 | 2024-04-23 14:11:20.0 | E8-<br>9C-<br>25-<br>A5-<br>9D-<br>59@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>267F_<br>6BD5.                  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:54 | E8-<br>9C-<br>25-<br>A5-<br>9D-<br>59@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>267F_<br>6BD5.                  | 否 |  |



|     |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|-----|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 571 | 闽通盛（福建）建设发展有限公司 | 2024-04-23 12:08:27.0 | 3C-7C-3F-50-67-D9,00-00-00-00-00@BF EBFBF F000A 0653@30027 29646 6         | 否 | 2024-04-23 12:07:01.0 | 3C-7C-3F-50-67-D9@BF EBFBF F000A 0653@30027 29646 6                        | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:50 | 3C-7C-3F-50-67-D9,00-00-00-00-00@BF EBFBF F000A 0653@30027 29646 6         | 否 |  |
| 572 | 福建信联建设工程有限公司    | 2024-04-16 14:55:14.0 | F4-B5-20-3E-43-CO@BF EBFBF F000A 0653@01234 56789 ABCDE F, LKD 240R0 12934 | 否 | 2024-04-16 14:46:39.0 | F4-B5-20-3E-43-CO@BF EBFBF F000A 0653@01234 56789 ABCDE F, LKD 240R0 12934 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:38 | F4-B5-20-3E-43-CO@BF EBFBF F000A 0653@01234 56789 ABCDE F, LKD 240R0 12934 | 否 |  |

|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 573 | 福建闽耀建筑有限公司   | 2024-04-22 08:12:22.0 | E0-D5-5E-C8-12-23@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>3CEC6<br>0A, AA<br>00000<br>00000<br>00001<br>546 | 否 | 2024-04-19 10:42:25.0 | E0-D5-5E-C8-12-23@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>3CEC6<br>0A, AA<br>00000<br>00000<br>00001<br>546 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:07 | E0-D5-5E-C8-12-23@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>3CEC6<br>0A, AA<br>00000<br>00000<br>00001<br>546 | 否 |  |
| 574 | 福建厚禹建设工程有限公司 | 2024-04-22 11:38:57.0 | 1C-1B-0D-45-4A-24@BF<br>EBFBF<br>F0005<br>06E3@<br>TL16C<br>26091<br>52, WD<br>-<br>WCC6Y<br>OPU04<br>LJ             | 否 | 2024-04-22 11:37:06.0 | 1C-1B-0D-45-4A-24@BF<br>EBFBF<br>F0005<br>06E3@<br>TL16C<br>26091<br>52, WD<br>-<br>WCC6Y<br>OPU04<br>LJ             | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:07 | 1C-1B-0D-45-4A-24@BF<br>EBFBF<br>F0005<br>06E3@<br>TL16C<br>26091<br>52, WD<br>-<br>WCC6Y<br>OPU04<br>LJ             | 否 |  |







|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 579 | 福建利骄工程机械有限公司  | 2024-04-23 09:15:27.0 | 74-56-3C-8E-94-75@BF<br>EBFBF<br>F000B<br>06F2@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C6F_<br>E671_<br>3EC4. | 否 | 2024-04-23 09:11:46.0 | 74-56-3C-8E-94-75@BF<br>EBFBF<br>F000B<br>06F2@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C6F_<br>E671_<br>3EC4. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:14 | 74-56-3C-8E-94-75@BF<br>EBFBF<br>F000B<br>06F2@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C6F_<br>E671_<br>3EC4. | 否 |  |
| 580 | 福建鑫顺鼎建设工程有限公司 | 2024-04-23 21:55:18.0 | 74-56-3C-C3-AB-AC@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4A0E_<br>6A79. | 否 | 2024-04-23 21:54:29.0 | 74-56-3C-C3-AB-AC@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4A0E_<br>6A79. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:18 | 74-56-3C-C3-AB-AC@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4A0E_<br>6A79. | 否 |  |
| 581 | 东卓建设(福建)有限公司  | 2024-04-23 14:49:08.0 | 14-DD-A9-28-9D-74@BF<br>EBFBF<br>F0003<br>06C3@<br>30353<br>23042<br>36373<br>73338<br>38373                            | 否 | 2024-04-22 10:17:40.0 | 14-DD-A9-28-9D-74,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>EQ@BF<br>EBFBF                                       | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:14 | 14-DD-A9-28-9D-74@BF<br>EBFBF<br>F0003<br>06C3@<br>30353<br>23042<br>36373<br>73338<br>38373                            | 否 |  |

|     |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|-----|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
|     |                       |                                  | 04230<br>44202<br>02020   |   |                                  | F0003<br>06C3@<br>30353<br>23042<br>36373<br>73338<br>38373<br>04230<br>44202<br>02020  |   |  |  |  |  |  |  |  |  |  |  | 04230<br>44202<br>02020    |                                |   |   |  |
| 582 | 龙岩兴鼎旺<br>建筑工程有<br>限公司 | 2024-<br>04-23<br>13:54<br>:46.0 | 08-<br>BF-<br>B8-<br>40-<br>CE-<br>CA@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0001.   | 否 | 2024-<br>04-23<br>13:53<br>:32.0 | 08-<br>BF-<br>B8-<br>40-<br>CE-<br>CA@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0001.   | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:31<br>:16 | 08-<br>BF-<br>B8-<br>40-<br>CE-<br>CA@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0001.   | 否 |  |
| 583 | 福建卓驰工<br>程管理有限<br>公司  | 2024-<br>04-22<br>11:09<br>:36.0 | 3C-<br>7C-<br>3F-<br>1F-<br>85-<br>70,00<br>-FF-<br>AE-<br>6B-<br>10-<br>E6@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>1YR39<br>8T,50<br>026B7<br>78381<br>8A25 | 否 | 2024-<br>04-22<br>10:54<br>:18.0 | 3C-<br>7C-<br>3F-<br>1F-<br>85-<br>70,00<br>-FF-<br>AE-<br>6B-<br>10-<br>E6@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>1YR39<br>8T,50<br>026B7<br>78381<br>8A25 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:35<br>:05 | 3C-<br>7C-<br>3F-<br>1F-<br>85-<br>70,00<br>-FF-<br>AE-<br>6B-<br>10-<br>E6@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>1YR39<br>8T,50<br>026B7<br>78381<br>8A25 | 否 |  |

|     |                      |                          |  |   |                          |   |   |  |  |  |  |  |  |  |  |                |                        |  |   |  |
|-----|----------------------|--------------------------|--|---|--------------------------|---|---|--|--|--|--|--|--|--|--|----------------|------------------------|--|---|--|
| 584 | 中昌核工<br>(福建)建设发展有限公司 | 2024-04-23<br>17:27:18.0 | 18-<br>C0-<br>4D-<br>46-<br>00-<br>AD@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WMC6Y<br>OP404<br>2F,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_22<br>00_89<br>65.            | 否 | 2024-04-23<br>17:20:19.0 | 18-<br>C0-<br>4D-<br>46-<br>00-<br>AD@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WMC6Y<br>OP404<br>2F,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_22<br>00_89<br>65. | 否 |  |  |  |  |  |  |  |  | 校验数据有<br>误,请检查 | 2024-04-24<br>08:31:20 | 18-<br>C0-<br>4D-<br>46-<br>00-<br>AD@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WMC6Y<br>OP404<br>2F,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_22<br>00_89<br>65.            | 否 |  |
| 585 | 河南宝业建设工程有限公司         | 2024-04-23<br>17:21:09.0 | 74-<br>56-<br>3C-<br>0B-<br>A3-<br>E4,00<br>-00-<br>00-<br>00-<br>00-<br>00@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A77D_<br>2ACO_<br>2459.<br>,VP02<br>10855<br>5VP23<br>01122<br>1 | 否 | 2024-04-22<br>20:49:47.0 | 74-<br>56-<br>3C-<br>0B-<br>A3-<br>E4@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A77D_<br>2ACO_<br>2459.<br>,VP02<br>10855<br>5VP23<br>01122<br>1                            | 否 |  |  |  |  |  |  |  |  | 校验数据有<br>误,请检查 | 2024-04-24<br>08:31:46 | 74-<br>56-<br>3C-<br>0B-<br>A3-<br>E4,00<br>-00-<br>00-<br>00-<br>00-<br>00@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A77D_<br>2ACO_<br>2459.<br>,VP02<br>10855<br>5VP23<br>01122<br>1 | 否 |  |











|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 593 | 福建隆坤建设工程有限公司  | 2024-04-24 08:23:24.0 | 58-11-22-DA-5F-44@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>7M1D8<br>3Z, 30<br>09164<br>2651    | 否 | 2024-04-24 08:22:13.0 | 58-11-22-DA-5F-44@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>7M1D8<br>3Z, 30<br>09164<br>2651  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:02 | 58-11-22-DA-5F-44@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>7M1D8<br>3Z, 30<br>09164<br>2651                  | 否 |  |
| 594 | 福建省华水水利工程有限公司 | 2024-04-22 16:11:29.0 | 00-E0-4C-58-C4-12@BF<br>EBFBF<br>F0009<br>06E9@<br>DA5A0<br>78C07<br>08054<br>90598<br>, 98M3<br>2PXNS | 否 | 2024-04-22 16:07:53.0 | 00-E0-4C-58-C4-12, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>DA5A0<br>78C07<br>08054<br>90598<br>, 98M3<br>2PXNS | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:12 | 2C-FD-A1-BD-47-F9@BF<br>EBFBF<br>F0009<br>06E9@<br>1B060<br>77C1B<br>08001<br>99359<br>, WD-<br>WCAP9<br>04508<br>85 | 否 |  |



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 597 | 福建海拓建设发展有限公司 | 2024-04-22 15:00:03.0 | 18-C0-4D-57-99-D4,00-00-00-00-00-00-E0@BFEBFBFF000906EA@2020202057202d4443573643305955554a43364e,3032333435423534363838302020202020200 | 否 | 2024-04-22 14:40:03.0 | 18-C0-4D-57-99-D4,00-00-00-00-00-00-E0@BFEBFBFF000906EA@2020202057202d4443573643305955554a43364e,3032333435423534363838302020202020200 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误,请检查 | 2024-04-24 08:41:37 | 18-C0-4D-57-99-D4,00-00-00-00-00-00-E0@BFEBFBFF000906EA@2020202057202d4443573643305955554a43364e,3032333435423534363838302020202020200 | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 598 | 福建中天源建设发展有限公司 | 2024-04-22 16:27:12.0 | D8-5E-D3-6B-DA-8C,00-E0-4C-38-07-67@BFEBFBF000A0653@202112200618,WD-WXR1A8862EFH | 否 | 2024-04-22 16:05:56.0 | D8-5E-D3-6B-DA-8C,00-E0-4C-38-07-67@BFEBFBF000A0653@202112200618,WD-WXR1A8862EFH | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:42:51 | D8-5E-D3-6B-DA-8C,00-E0-4C-38-07-67,00-00-00-00-00@BFEBFBF000A0653@202112200618,WD-WXR1A8862EFH | 否 |  |
| 599 | 福建南工建设工程有限公司  | 2024-04-23 16:36:31.0 | 74-56-3C-21-5C-65@BFEBFBF000A0653@0000_0000_0000_0000_0026B738_2093_BA45.        | 否 | 2024-04-23 16:25:33.0 | 74-56-3C-21-5C-65@BFEBFBF000A0653@0000_0000_0000_0000_0026B738_2093_BA45.        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:43 | 74-56-3C-21-5C-65@BFEBFBF000A0653@0000_0000_0000_0000_0026B738_2093_BA45.                       | 否 |  |



|     |                   |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |                              |                              |   |   |   |  |
|-----|-------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|------------------------------|------------------------------|---|---|---|--|
| 600 | 福建鼎瑞信<br>建设工程有限公司 | 2024-04-23<br>17:24<br>:46.0 | D8-<br>5E-<br>D3-<br>20-<br>E4-<br>43@BF<br>EBFBF<br>F000A<br>0653@<br>CN51C<br>AC212<br>1610,<br>L0601<br>13E27<br>882   | 否 | 2024-04-17<br>11:42<br>:29.0 | D8-<br>5E-<br>D3-<br>20-<br>E4-<br>43@BF<br>EBFBF<br>F000A<br>0653@<br>CN51C<br>AC212<br>1610,<br>L0601<br>13E27<br>882   | 否 |  |  |  |  |  |  |  |  |                              | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:46<br>:20  | D8-<br>5E-<br>D3-<br>20-<br>E4-<br>43@BF<br>EBFBF<br>F000A<br>0653@<br>CN51C<br>AC212<br>1610,<br>L0601<br>13E27<br>882 | 否 |  |
| 601 | 福建优铭瑞<br>建设工程有限公司 | 2024-04-23<br>16:41<br>:07.0 | 2C-<br>F0-<br>5D-<br>A1-<br>11-<br>4C@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>49BC_<br>EA21.<br>, JR10<br>046P2<br>JUA3N | 否 | 2024-04-23<br>16:17<br>:17.0 | 2C-<br>F0-<br>5D-<br>A1-<br>11-<br>4C@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>49BC_<br>EA21.<br>, JR10<br>046P2<br>JUA3N | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:37<br>:43   | 2C-<br>F0-<br>5D-<br>A1-<br>11-<br>4C@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>49BC_<br>EA21.<br>, JR10<br>046P2<br>JUA3N | 否   |   |  |





|     |                  |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                            |                            |  |   |  |
|-----|------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|--|---|--|
| 605 | 辉煌建设<br>(福建)有限公司 | 2024-04-23<br>14:56<br>:24.0 | D8-<br>5E-<br>D3-<br>1B-<br>E3-<br>B0@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>4980_<br>29C9.  | 否 | 2024-04-19<br>16:31<br>:08.0 | D8-<br>5E-<br>D3-<br>1B-<br>E3-<br>B0@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>4980_<br>29C9.  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:32<br>:19 | D8-<br>5E-<br>D3-<br>1B-<br>E3-<br>B0@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>4980_<br>29C9.  | 否 |  |
| 606 | 福建特力建<br>设集团有限公司 | 2024-04-23<br>09:03<br>:51.0 | 90-<br>76-<br>9F-<br>D9-<br>77-<br>B0, 90<br>-76-<br>9F-<br>D9-<br>77-<br>B0, 00<br>-E2-<br>69-<br>21-<br>0A-<br>35@BF<br>EBFBF<br>F0009<br>06EA@<br>AA006<br>00000<br>12340<br>09881<br>, WD-<br>WCC2E<br>AEC27<br>32 | 否 | 2024-04-23<br>09:00<br>:38.0 | 90-<br>76-<br>9F-<br>D9-<br>77-<br>B0, 90<br>-76-<br>9F-<br>D9-<br>77-<br>B0, 00<br>-E2-<br>69-<br>21-<br>0A-<br>35@BF<br>EBFBF<br>F0009<br>06EA@<br>AA006<br>00000<br>12340<br>09881<br>, WD-<br>WCC2E<br>AEC27<br>32 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:42<br>:02 | 90-<br>76-<br>9F-<br>D9-<br>77-<br>B0, 90<br>-76-<br>9F-<br>D9-<br>77-<br>B0, 00<br>-E2-<br>69-<br>21-<br>0A-<br>35@BF<br>EBFBF<br>F0009<br>06EA@<br>AA006<br>00000<br>12340<br>09881<br>, WD-<br>WCC2E<br>AEC27<br>32 | 否 |  |







|     |                   |                                  |   |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
|-----|-------------------|----------------------------------|---|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|
|     |                   |                                  | 00-<br>E0@17<br>8BFBF<br>F0063<br>0F01@<br>FEB40<br>74A1C<br>08008<br>23096   |   |                                  | 00-<br>E0@17<br>8BFBF<br>F0063<br>0F01@<br>FEB40<br>74A1C<br>08008<br>23096  |   |  |  |  |  |  |  |  |  |  |                            |                                | 00-<br>E0@17<br>8BFBF<br>F0063<br>0F01@<br>FEB40<br>74A1C<br>08008<br>23096  |   |  |
| 612 | 福建省天章<br>建筑工程有限公司 | 2024-<br>04-23<br>11:57<br>:23.0 | F0-<br>2F-<br>74-<br>D9-<br>38-<br>11@BF<br>EBFBF<br>F0009<br>06EB@<br>41413<br>03030<br>30303<br>03030<br>03032<br>30383<br>63236<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>32594<br>c5554<br>50553<br>3 | 否 | 2024-<br>04-23<br>11:55<br>:54.0 | F0-<br>2F-<br>74-<br>D9-<br>38-<br>11,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>41413<br>03030<br>30303<br>03030<br>03030<br>03030<br>03032<br>30383<br>63236<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>32594<br>c5554<br>50553<br>3 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:33<br>:10 | F0-<br>2F-<br>74-<br>D9-<br>38-<br>11@BF<br>EBFBF<br>F0009<br>06EB@<br>41413<br>03030<br>30303<br>03030<br>30383<br>63236<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>32594<br>c5554<br>50553<br>3 | 否 |  |



|     |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |             |                     |  |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|---|--|
| 613 | 长铁建设集团有限公司    | 2024-04-18 18:21:35.0 | 00-<br>E0-<br>4C-<br>E2-<br>02-<br>CB@BF<br>EBFBF<br>F000A<br>0653@<br>YS202<br>01022<br>3673H<br>P   | 否 | 2024-04-18 18:19:41.0 | 00-<br>E0-<br>4C-<br>E2-<br>02-<br>CB@BF<br>EBFBF<br>F000A<br>0653@<br>YS202<br>01022<br>3673H<br>P  | 否 |  |  |  |  |  |  |  |  |             | 校验数据有误差，请检查         | 2024-04-24 08:35:05  | 00-<br>E0-<br>4C-<br>E2-<br>02-<br>CB@BF<br>EBFBF<br>F000A<br>0653@<br>YS202<br>01022<br>3673H<br>P | 否 |  |
| 614 | 福建省国筑建设工程有限公司 | 2024-04-23 15:35:32.0 | E0-<br>D5-<br>5E-<br>54-<br>6B-<br>D4,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>33483<br>43034<br>38304<br>a3031<br>35312<br>03320<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>30594<br>55430<br>43464<br>b | 否 | 2024-04-23 11:26:14.0 | E0-<br>D5-<br>5E-<br>54-<br>6B-<br>D4,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>33483<br>43034<br>38304<br>a3031<br>35312<br>03320<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>30594<br>55430<br>43464<br>b | 否 |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:36:34 | E0-<br>D5-<br>5E-<br>54-<br>6B-<br>D4,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>33483<br>43034<br>38304<br>a3031<br>35312<br>03320<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>30594<br>55430<br>43464<br>b | 否   |   |  |

|     |                 |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 615 | 福建省安江生态环境建设有限公司 | 2024-04-23 17:24:35.0 | 00-<br>E0-<br>1F-<br>93-<br>02-<br>28@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WC81Y<br>76932<br>62, LC<br>RY822<br>3ABT6<br>404 | 否 | 2024-04-23 15:33:25.0 | 00-<br>E0-<br>1F-<br>93-<br>02-<br>28@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WC81Y<br>76932<br>62, LC<br>RY822<br>3ABT6<br>404 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:40:27 | 00-<br>E0-<br>1F-<br>93-<br>02-<br>28@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WC81Y<br>76932<br>62, LC<br>RY822<br>3ABT6<br>404 | 否 |  |
|-----|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|



|     |                              |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |                               |                                |   |  |   |  |
|-----|------------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|-------------------------------|--------------------------------|---|--|---|--|
| 617 | 中盛天韵<br>(福建)建<br>设工程有限<br>公司 | 2024-<br>04-19<br>10:50<br>:50.0 | 2C-<br>F0-<br>5D-<br>10-<br>5E-<br>50@BF<br>EBFBF<br>F0009<br>06EB@<br>20113<br>A8002<br>21, WD<br>-<br>WCC6Y<br>0AC67<br>9E                | 否 | 2024-<br>04-19<br>10:24<br>:16.0 | 2C-<br>F0-<br>5D-<br>10-<br>5E-<br>50@BF<br>EBFBF<br>F0009<br>06EB@<br>20113<br>A8002<br>21, WD<br>-<br>WCC6Y<br>0AC67<br>9E  | 否 |  |  |  |  |  |  |  |  |                               | 校验<br>数据<br>有,<br>请<br>查<br>检  | 2024-<br>04-24<br>08:34<br>:39  | 2C-<br>F0-<br>5D-<br>10-<br>5E-<br>50@BF<br>EBFBF<br>F0009<br>06EB@<br>20113<br>A8002<br>21, WD<br>-<br>WCC6Y<br>0AC67<br>9E | 否 |  |
| 618 | 中城国金工<br>程技术集团<br>有限公司       | 2024-<br>04-23<br>10:02<br>:27.0 | D8-<br>5E-<br>D3-<br>62-<br>53-<br>64@BF<br>EBFBF<br>F0009<br>06EB@<br>20202<br>02020<br>20202<br>02020<br>20203<br>95747<br>41535<br>35044 | 否 | 2024-<br>04-23<br>08:59<br>:41.0 | D8-<br>5E-<br>D3-<br>62-<br>53-<br>64@BF<br>EBFBF<br>F0009<br>06EB@<br>30353<br>23042<br>36323<br>73238<br>43334<br>63337<br>43202<br>02020<br>, 2020<br>20202<br>02020<br>20202<br>02020<br>20202<br>02020<br>20202<br>02020<br>39574<br>74153<br>53504<br>4 | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有,<br>请<br>查<br>检 | 2024-<br>04-24<br>08:33<br>:47 | D8-<br>5E-<br>D3-<br>62-<br>53-<br>64@BF<br>EBFBF<br>F0009<br>06EB@<br>30353<br>23042<br>36323<br>73238<br>43334<br>63337<br>43202<br>02020<br>, 2020<br>20202<br>02020<br>20202<br>02020<br>20202<br>02020<br>20202<br>02020<br>39574<br>74153<br>53504<br>4 | 否  |   |  |



|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 620 | 福建盟众建设工程有限公司  | 2024-04-22 15:31:18.0 | 50-EB-F6-B5-17-6A@BF<br>EBFBF<br>F000A<br>0653@<br>21486<br>G8010<br>31,YS<br>22512<br>51RTG<br>I0133                   | 否 | 2024-04-22 15:19:23.0 | 50-EB-F6-B5-17-6A@BF<br>EBFBF<br>F000A<br>0653@<br>21486<br>G8010<br>31,YS<br>22512<br>51RTG<br>I0133                   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:40 | 50-EB-F6-B5-17-6A@BF<br>EBFBF<br>F000A<br>0653@<br>21486<br>G8010<br>31,YS<br>22512<br>51RTG<br>I0133                   | 否 |  |
| 621 | 福建永晟达建设工程有限公司 | 2024-04-23 19:18:47.0 | 04-42-1A-23-6D-FD@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>498E_<br>7C92. | 否 | 2024-04-23 19:23:17.0 | 04-42-1A-23-6D-FD@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>498E_<br>7C92. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:39 | 04-42-1A-23-6D-FD@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>498E_<br>7C92. | 否 |  |







|     |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 625 | 四川中铭建设有限公司 | 2024-04-23 17:11:58.0 | A8-5E-45-9F-A1-AE@BF<br>EBFBBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>6YZRX<br>A1, 10<br>01736<br>0561 | 否 | 2024-04-23 17:06:28.0 | A8-5E-45-9F-A1-AE@BF<br>EBFBBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>6YZRX<br>A1, 10<br>01736<br>0561 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:37 | A0-36-BC-05-08-DA@BF<br>EBFBBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7RYC7<br>H9, 50<br>026B7<br>784B5<br>6E40 | 否 |  |
|-----|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|







|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 631 | 福建共赢建设工程有限公司 | 2024-04-23 11:16:46.0 | 04-D9-F5-D0-E0-FF,00-00-00-00-00-06EB@RC19813097H0043            | 否 | 2024-04-22 15:47:00.0 | 04-D9-F5-D0-E0-FF,00-00-00-00-00-06EB@RC19813097H0043            | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:23 | 04-D9-F5-D0-E0-FF@BFEBFBF000906EB@RC19813097H0043                | 否 |  |
| 632 | 福建宇跃建筑工程有限公司 | 2024-04-23 16:47:13.0 | D4-5D-64-23-96-77@BFEBFBF000906EB@WD-WCC6Y2HK7LNN,AA000000000826 | 否 | 2024-04-23 16:36:55.0 | D4-5D-64-23-96-77@BFEBFBF000906EB@WD-WCC6Y2HK7LNN,AA000000000826 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:37 | D4-5D-64-23-96-77@BFEBFBF000906EB@WD-WCC6Y2HK7LNN,AA000000000826 | 否 |  |
| 633 | 福建麟鸿建设工程有限公司 | 2024-04-23 15:44:09.0 | 00-E2-69-45-34-0E@BFEBFBF000A0671@0026_B768_4F86_2FB5.           | 否 | 2024-04-23 10:42:47.0 | 00-E2-69-45-34-0E@BFEBFBF000A0671@0026_B768_4F86_2FB5.           | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:54 | 00-E2-69-45-34-0E@BFEBFBF000A0671@0026_B768_4F86_2FB5.           | 否 |  |

|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 634 | 福建兔然建设工程有限公司 | 2024-04-23 12:27:33.0 | 08-BF-B8-3A-25-8B@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>1492.<br>,WD-<br>WCC2E<br>WW341<br>48 | 否 | 2024-04-22 09:13:36.0 | 08-BF-B8-3A-25-8B@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>1492.<br>,WD-<br>WCC2E<br>WW341<br>48 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:22 | 08-BF-B8-3A-25-8B@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>1492.<br>,WD-<br>WCC2E<br>WW341<br>48 | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|



|     |              |                        |  |   |                        |   |   |  |  |  |  |  |  |  |  |  |              |                      |   |   |  |
|-----|--------------|------------------------|--|---|------------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|----------------------|---|---|--|
| 636 | 福建卓泰建设工程有限公司 | 2024-04-23 10:30 :33.0 | 48-21-0B-3D-D4-72, C4-D0-E3-D7-E8-FC, C4-D0-E3-D7-E8-F8, C4-D0-E3-D7-E8-F8, C4-D0-E3-D7-E8-F8@BF EBFBF F0009 06A3@ 0000_ 0007_ 2210_ 1858_ 3A5A_ 2702_ 4000_ 0009. | 否 | 2024-04-23 10:29 :11.0 | 48-21-0B-3D-D4-72, C4-D0-E3-D7-E8-F9, C6-D0-E3-D7-E8-F8, C4-D0-E3-D7-E8-F8@BF EBFBF F0009 06A3@ 0000_ 0007_ 2210_ 1858_ 3A5A_ 2702_ 4000_ 0009. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:42 :12 | 48-21-0B-3D-D4-72, C4-D0-E3-D7-E8-FC, C4-D0-E3-D7-E8-F8, C4-D0-E3-D7-E8-F9@BF EBFBF F0009 06A3@ 0000_ 0007_ 2210_ 1858_ 3A5A_ 2702_ 4000_ 0009. | 否 |  |
|-----|--------------|------------------------|--|---|------------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|----------------------|---|---|--|



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 637 | 贵州晟垣建设工程有限公司 | 2024-04-23 11:00:16.0 | 58-11-22-CE-D8-F9@BF EBFBF F000A 0653@50026 B7381 EA4F69                                     | 否 | 2024-04-23 10:54:01.0 | 58-11-22-CE-D8-F9@BF EBFBF F000A 0653@50026 B7381 EA4F69                                     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:21 | 58-11-22-CE-D8-F9@BF EBFBF F000A 0653@50026 B7381 EA4F69                  | 否 |  |
| 638 | 凯天建设发展集团有限公司 | 2024-04-22 21:43:29.0 | 38-00-25-E1-B5-CC, 3A-00-25-E1-B5-CC, 38-00-25-E1-B5-CD@BF EBFBF F0008 06EB@S3TRN XOM31 1858 | 否 | 2024-04-22 21:42:18.0 | 3A-00-25-E1-B5-CC, 38-00-25-E1-B5-CD, 38-00-25-E1-B5-CC@BF EBFBF F0008 06EB@S3TRN XOM31 1858 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:43:12 | 3A-00-25-E1-B5-CC, 38-00-25-E1-B5-CC@BF EBFBF F0008 06EB@S3TRN XOM31 1858 | 否 |  |

|     |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|-----|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 639 | 福建沈华建设有限公司 | 2024-04-22 19:46:24.0 | 18-C0-4D-40-31-6A@BF<br>EBFBF<br>F0009<br>06EA@<br>A428_<br>B703_<br>0556_<br>0081.<br>, WD-<br>WCC4J<br>6JUCC<br>NR | 否 | 2024-04-22 16:56:01.0 | 18-C0-4D-40-31-6A@BF<br>EBFBF<br>F0009<br>06EA@<br>A428_<br>B703_<br>0556_<br>0081.<br>, WD-<br>WCC4J<br>6JUCC<br>NR | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:54 | 18-C0-4D-40-31-6A@BF<br>EBFBF<br>F0009<br>06EA@<br>A428_<br>B703_<br>0556_<br>0081.<br>, WD-<br>WCC4J<br>6JUCC<br>NR | 否 |  |
|-----|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|



|     |              |                       |   |   |                       |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
|     |              |                       | 50026<br>B7784<br>90DF1<br>7  |   |                       | 50026<br>B7784<br>90DF1<br>7  |  |  |  |  |  |  |  |  |  |  |             |                     | 50026<br>B7784<br>90DF1<br>7  |   |   |  |
| 642 | 福建隆耀建设工程有限公司 | 2024-04-22 15:00:01.0 | A0-36-BC-2B-F7-CB@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>73033<br>30353<br>43931<br>20382<br>02020<br>20202<br>02020<br>, 3232<br>32355<br>04234<br>34353<br>83830<br>20202<br>02020<br>20202<br>0 | 否 | 2024-04-22 14:57:46.0 | A0-36-BC-2B-F7-CB@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>73033<br>30353<br>43931<br>20382<br>02020<br>20202<br>02020<br>, 3232<br>32355<br>04234<br>34353<br>83830<br>20202<br>02020<br>20202<br>0 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:18 | A0-36-BC-2B-F7-CB@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>73033<br>30353<br>43931<br>20382<br>02020<br>20202<br>02020<br>, 3232<br>32355<br>04234<br>34353<br>83830<br>20202<br>02020<br>20202<br>0 | 否   |   |  |
| 643 | 福建国昂建设工程有限公司 | 2024-04-23 08:39:24.0 | 74-56-3C-50-4B-C2@BF<br>EBFBF<br>F0009<br>0672@<br>0025_38BB_2104_10BE.   | 否 | 2024-04-22 15:49:41.0 | 74-56-3C-50-4B-C2@BF<br>EBFBF<br>F0009<br>0672@<br>0025_38BB_2104_10BE.   |  |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:34:27   | 74-56-3C-50-4B-C2@BF<br>EBFBF<br>F0009<br>0672@<br>0025_38BB_2104_10BE. | 否 |  |

|     |                  |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |  |   |  |
|-----|------------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|--|---|--|
| 644 | 福建源顺建设工程有限公司     | 2024-04-23 15:28:32.0 | 00-<br>E0-<br>4C-<br>68-<br>07-<br>C3@BF<br>EBFBF<br>F0005<br>06E3@<br>30353<br>23042<br>36363<br>73238<br>34454<br>64631<br>42202<br>02020<br>, 2020<br>20202<br>02020<br>20202<br>02020<br>41573<br>13433<br>35545<br>a | 否 | 2024-04-23 15:26:53.0 | 00-<br>E0-<br>4C-<br>68-<br>07-<br>C3@BF<br>EBFBF<br>F0005<br>06E3@<br>30353<br>23042<br>36363<br>73238<br>34454<br>64631<br>42202<br>02020<br>, 2020<br>20202<br>02020<br>20202<br>02020<br>41573<br>13433<br>35545<br>a | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:40 | 00-<br>E0-<br>4C-<br>68-<br>07-<br>C3@BF<br>EBFBF<br>F0005<br>06E3@<br>30353<br>23042<br>36363<br>73238<br>34454<br>64631<br>42202<br>02020<br>, 2020<br>20202<br>02020<br>20202<br>02020<br>41573<br>13433<br>35545<br>a | 否  |   |  |
| 645 | 众源建设发展(福建)有限责任公司 | 2024-04-23 11:27:35.0 | 90-<br>6F-<br>18-<br>02-<br>31-<br>B2@BF<br>EBFBF<br>F0009<br>0675@<br>YS232<br>5631R<br>TGI16<br>05, Z9<br>AXRSV<br>8  | 否 | 2024-04-23 11:25:46.0 | 90-<br>6F-<br>18-<br>02-<br>31-<br>B2@BF<br>EBFBF<br>F0009<br>0675@<br>YS232<br>5631R<br>TGI16<br>05, Z9<br>AXRSV<br>8  | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:33:52   | 90-<br>6F-<br>18-<br>02-<br>31-<br>B2@BF<br>EBFBF<br>F0009<br>0675@<br>YS232<br>5631R<br>TGI16<br>05, Z9<br>AXRSV<br>8 | 否 |  |



|     |                   |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |                        |                        |   |   |  |
|-----|-------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|------------------------|------------------------|---|---|--|
| 647 | 福建富舜铎<br>建筑有限公司   | 2024-04-22<br>09:55:03.0 | 2C-<br>F0-<br>5D-<br>E7-<br>AE-<br>B5@BF<br>EBFBF<br>F000A<br>0653@<br>SSMB2<br>0A110<br>4287,<br>FJ87N<br>41571<br>3207G<br>5J<br>_0000<br>0001. | 否 | 2024-04-22<br>09:29:57.0 | 2C-<br>F0-<br>5D-<br>E7-<br>AE-<br>B5@BF<br>EBFBF<br>F000A<br>0653@<br>SSMB2<br>0A110<br>4287,<br>FJ87N<br>41571<br>3207G<br>5J<br>_0000<br>0001. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-04-24<br>08:31:46 | 2C-<br>F0-<br>5D-<br>E7-<br>AE-<br>B5@BF<br>EBFBF<br>F000A<br>0653@<br>SSMB2<br>0A110<br>4287,<br>FJ87N<br>41571<br>3207G<br>5J<br>_0000<br>0001. | 否 |  |
| 648 | 福建省安鑫<br>建设工程有限公司 | 2024-04-24<br>00:49:58.0 | 18-<br>C0-<br>4D-<br>F6-<br>65-<br>A4@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>482A_<br>4628.       | 否 | 2024-04-24<br>00:49:56.0 | 18-<br>C0-<br>4D-<br>F6-<br>65-<br>A4@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>482A_<br>4628.       | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-04-24<br>08:37:49 | 18-<br>C0-<br>4D-<br>F6-<br>65-<br>A4@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>482A_<br>4628.       | 否 |  |

|     |                  |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|------------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 649 | 福建森焱建设有限公司       | 2024-04-23 10:02:38.0 | D4-5D-64-02-D2-85@BF<br>EBFBF<br>F0009<br>06EB@<br>E823_8FA6_ BF53_0001_001B_448B_4EOA_58BA.                       | 否 | 2024-04-23 10:01:50.0 | D4-5D-64-02-D2-85@BF<br>EBFBF<br>F0009<br>06EB@<br>E823_8FA6_ BF53_0001_001B_448B_4EOA_58BA.                       | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:31 | D4-5D-64-02-D2-85@BF<br>EBFBF<br>F0009<br>06EB@<br>E823_8FA6_ BF53_0001_001B_448B_4EOA_58BA.                       | 否 |  |
| 650 | 福建省福清市鑫辉建筑工程有限公司 | 2024-04-23 11:12:53.0 | 40-8D-5C-92-51-A4@BF<br>EBFBF<br>F0003<br>06C3@<br>EAGET<br>20180<br>626I0<br>6233,<br>WD-<br>WCC2E<br>AE431<br>15 | 否 | 2024-04-23 11:10:00.0 | 40-8D-5C-92-51-A4@BF<br>EBFBF<br>F0003<br>06C3@<br>EAGET<br>20180<br>626I0<br>6233,<br>WD-<br>WCC2E<br>AE431<br>15 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:46:02 | 40-8D-5C-92-51-A4@BF<br>EBFBF<br>F0003<br>06C3@<br>EAGET<br>20180<br>626I0<br>6233,<br>WD-<br>WCC2E<br>AE431<br>15 | 否 |  |







|     |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 653 | 福建省英城建设工程有限公司   | 2024-04-23 09:57:43.0 | B4-2E-99-B2-8F-44@BF<br>EBFBF<br>F0009<br>06E9@<br>EAGET<br>20191<br>231R0<br>0260 | 否 | 2024-04-23 09:49:00.0 | B4-2E-99-B2-8F-44@BF<br>EBFBF<br>F0009<br>06E9@<br>EAGET<br>20191<br>231R0<br>0260 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:37:33 | 04-42-1A-21-92-E4@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>451C_<br>3E09. | 否 |  |
| 654 | 福建省博成园林景观建设有限公司 | 2024-04-16 10:11:14.0 | 18-CO-4D-F7-EC-1A@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>E8194<br>9    | 否 | 2024-04-16 10:10:00.0 | 18-CO-4D-F7-EC-1A@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>E8194<br>9    | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:46 | 18-CO-4D-F7-EC-1A@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>E8194<br>9   | 否 |  |



|     |                   |                                  |   |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|-----|-------------------|----------------------------------|---|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
| 657 | 福建省奕群<br>建筑工程有限公司 | 2024-<br>04-23<br>14:09<br>:15.0 | 74-<br>56-<br>3C-<br>17-<br>44-<br>1B@BF<br>EBFBF<br>F0009<br>0672@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C15_<br>OD84_<br>7C95. | 否 | 2024-<br>04-23<br>10:59<br>:07.0 | 74-<br>56-<br>3C-<br>17-<br>44-<br>1B@BF<br>EBFBF<br>F0009<br>0672@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C15_<br>OD84_<br>7C95.  | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:33<br>:47 | 74-<br>56-<br>3C-<br>17-<br>44-<br>1B@BF<br>EBFBF<br>F0009<br>0672@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C15_<br>OD84_<br>7C95. | 否 |  |
| 658 | 福建鼎拓建<br>设工程有限公司  | 2024-<br>04-23<br>14:22<br>:31.0 | 2C-<br>FD-<br>A1-<br>59-<br>0D-<br>8F@BF<br>EBFBF<br>F0009<br>06E9@<br>SN215<br>20895<br>5242,<br>WD-<br>WCC6Y<br>2ZHV9<br>E5               | 否 | 2024-<br>04-23<br>10:50<br>:24.0 | 2C-<br>FD-<br>A1-<br>59-<br>0D-<br>8F, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>SN215<br>20895<br>5242,<br>WD-<br>WCC6Y<br>2ZHV9<br>E5 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:31<br>:03 | 2C-<br>FD-<br>A1-<br>59-<br>0D-<br>8F@BF<br>EBFBF<br>F0009<br>06E9@<br>SN215<br>20895<br>5242,<br>WD-<br>WCC6Y<br>2ZHV9<br>E5               | 否 |  |

|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 659 | 福建泽滨建设工程有限公司 | 2024-04-23 10:58:39.0 | 18-C0-4D-4B-BF-B4@BF<br>EBFBF<br>F000A<br>0653@<br>20090<br>9A000<br>17004<br>,WD-<br>WCC6Y<br>3CA53<br>8A | 否 | 2024-04-23 10:57:29.0 | 18-C0-4D-4B-BF-B4@BF<br>EBFBF<br>F000A<br>0653@<br>20090<br>9A000<br>17004<br>,WD-<br>WCC6Y<br>3CA53<br>8A | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误,请检查 | 2024-04-24 08:43:39 | 18-C0-4D-4B-BF-B4@BF<br>EBFBF<br>F000A<br>0653@<br>20090<br>9A000<br>17004<br>,WD-<br>WCC6Y<br>3CA53<br>8A | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|







|     |              |                       |   |                       |   |   |  |   |   |
|-----|--------------|-----------------------|---|-----------------------|---|---|--|---|---|
| 662 | 福建兴腾建设工程有限公司 | 2024-04-17 11:14:07.0 | 否 | 2024-04-17 11:08:40.0 | 否 | OC-<br>5B-<br>8F-<br>27-<br>9A-<br>64, 2C<br>-FD-<br>A1-<br>BA-<br>13-<br>4C, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>57543<br>83131<br>37353<br>13936<br>32323<br>03220<br>34202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>41593<br>45348<br>464a5<br>9 | OC-<br>5B-<br>8F-<br>27-<br>9A-<br>64, 2C<br>-FD-<br>A1-<br>BA-<br>13-<br>4C, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>57543<br>83131<br>37353<br>13936<br>32323<br>03220<br>34202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>41593 | OC-<br>5B-<br>8F-<br>27-<br>9A-<br>64, 2C<br>-FD-<br>A1-<br>BA-<br>13-<br>4C@BF<br>EBFBF<br>F0009<br>06E9@<br>57543<br>83131<br>37353<br>13936<br>32323<br>03220<br>34202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>41593 | 否 |
|-----|--------------|-----------------------|---|-----------------------|---|---|--|---|---|

校验数据有误，请检查

2024-04-24 08:34:55

否

|     |              |                              |   |   |                              |  |   |  |  |  |  |  |  |  |  |  |  |                            |                            |   |   |  |
|-----|--------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|---|--|
|     |              |                              |   |   |                              | 45348<br>464a5<br>9  |   |  |  |  |  |  |  |  |  |  |  |                            |                            |   |   |  |
| 663 | 福建弘协建设工程有限公司 | 2024-04-23<br>10:57<br>:13.0 | 3C-<br>7C-<br>3F-<br>BF-<br>7F-<br>52,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00@BF<br>EBFBF<br>F000A<br>0653@<br>K3919<br>6R002<br>683,W<br>D-<br>WCC6Y<br>OLE8K<br>FF | 否 | 2024-04-22<br>09:25<br>:47.0 | 3C-<br>7C-<br>3F-<br>BF-<br>7F-<br>52@BF<br>EBFBF<br>F000A<br>0653@<br>K3919<br>6R002<br>683,W<br>D-<br>WCC6Y<br>OLE8K<br>FF               | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:34<br>:08 | 3C-<br>7C-<br>3F-<br>BF-<br>7F-<br>52,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00@BF<br>EBFBF<br>F000A<br>0653@<br>K3919<br>6R002<br>683,W<br>D-<br>WCC6Y<br>OLE8K<br>FF | 否 |  |
| 664 | 驻马店市建筑公司     | 2024-04-23<br>16:17<br>:42.0 | E8-<br>9C-<br>25-<br>43-<br>7C-<br>5E@BF<br>EBFBF<br>F0009<br>0675@<br>E823<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>48EC_<br>79D1.                                | 否 | 2024-04-23<br>16:12<br>:55.0 | E8-<br>9C-<br>25-<br>43-<br>7C-<br>5E@BF<br>EBFBF<br>F0009<br>0675@<br>E823<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>48EC_<br>79D1. | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:31<br>:42 | E8-<br>9C-<br>25-<br>43-<br>7C-<br>5E@BF<br>EBFBF<br>F0009<br>0675@<br>E823<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>48EC_<br>79D1.                                | 否 |  |

|     |                         |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |                              |                              |   |   |   |  |
|-----|-------------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|------------------------------|------------------------------|---|---|---|--|
| 665 | 福建省润儒<br>建筑工程有限公司       | 2024-04-23<br>16:41<br>:15.0 | 00-<br>E2-<br>69-<br>5D-<br>9A-<br>E6@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>8CE3_<br>8E05_<br>00C0_<br>B654. | 否 | 2024-04-23<br>16:31<br>:04.0 | 00-<br>E2-<br>69-<br>5D-<br>9A-<br>E6@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>8CE3_<br>8E05_<br>00C0_<br>B654. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有错误<br>，请查<br>检查 | 2024-04-24<br>08:43<br>:09   | 00-<br>E2-<br>69-<br>5D-<br>9A-<br>E6@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>8CE3_<br>8E05_<br>00C0_<br>B654. | 否   |   |  |
| 666 | 坤皇建工<br>(河南) 实<br>业有限公司 | 2024-04-22<br>15:22<br>:18.0 | AA-<br>1C-<br>04-<br>0F-<br>A0-<br>D7@BF<br>EBFBF<br>F0003<br>06F2@<br>MG240<br>14061<br>3967   | 否 | 2024-04-22<br>15:14<br>:06.0 | AA-<br>1C-<br>04-<br>0F-<br>A0-<br>D7@BF<br>EBFBF<br>F0003<br>06F2@<br>MG240<br>14061<br>3967   | 否 |  |  |  |  |  |  |  |  |  |                              | 校验<br>数据<br>有错误<br>，请查<br>检查 | 2024-04-24<br>08:33<br>:07  | AA-<br>1C-<br>04-<br>0F-<br>A0-<br>D7@BF<br>EBFBF<br>F0003<br>06F2@<br>MG240<br>14061<br>3967 | 否 |  |

|     |                         |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                              |                                |  |   |  |
|-----|-------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------------|--------------------------------|--|---|--|
| 667 | 福建中建交<br>建设工程集<br>团有限公司 | 2024-<br>04-23<br>16:28<br>:19.0 | 48-<br>F3-<br>17-<br>02-<br>86-<br>45@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36333<br>73138<br>34444<br>33536<br>37202<br>02020<br>,2020<br>20202<br>02020<br>20202<br>02020<br>39573<br>7415a<br>44314<br>e | 否 | 2024-<br>04-23<br>16:26<br>:17.0 | 48-<br>F3-<br>17-<br>02-<br>86-<br>45@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36333<br>73138<br>34444<br>33536<br>37202<br>02020<br>,2020<br>20202<br>02020<br>20202<br>02020<br>39573<br>7415a<br>44314<br>e | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:36<br>:34 | 48-<br>F3-<br>17-<br>02-<br>86-<br>45@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36333<br>73138<br>34444<br>33536<br>37202<br>02020<br>,2020<br>20202<br>02020<br>20202<br>02020<br>39573<br>7415a<br>44314<br>e | 否 |  |
| 668 | 福建省盛佰<br>益建设发展<br>有限公司  | 2024-<br>04-23<br>15:21<br>:13.0 | 00-<br>E0-<br>4C-<br>7C-<br>7C-<br>E2@17<br>8BFBF<br>F00A5<br>0F00@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000.  | 否 | 2024-<br>04-23<br>10:40<br>:28.0 | 00-<br>E0-<br>4C-<br>7C-<br>7C-<br>E2@17<br>8BFBF<br>F00A5<br>0F00@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000.  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:32<br>:15 | 00-<br>E0-<br>4C-<br>7C-<br>7C-<br>E2@17<br>8BFBF<br>F00A5<br>0F00@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000.  | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |              |                     |  |   |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|---|--|
| 669 | 福建省坤亿建设集团有限公司 | 2024-04-23 15:26:11.0 | 3C-7C-3F-84-15-EF@BF EBFBF F000A 0653@ 0000_0000_0000_0000_0100_0000_0000. ,WD-WCC6Y 3NZ88 J1                            | 否 | 2024-04-23 10:48:09.0 | 3C-7C-3F-84-15-EF@BF EBFBF F000A 0653@ 0000_0000_0000_0000_0100_0000_0000. ,WD-WCC6Y 3NZ88 J1                            | 否 |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:32:43  | 3C-7C-3F-84-15-EF@BF EBFBF F000A 0653@ 0000_0000_0000_0000_0100_0000_0000. ,WD-WCC6Y 3NZ88 J1 | 否 |  |
| 670 | 福建旭皓建设工程有限公司  | 2024-04-22 17:07:36.0 | B4-2E-99-9A-CD-3A,00 -00-00-00-00-00-00-00-00-00-E0@BF EBFBF F0009 06EB@ 30353 23042 36333 73038 41363 63836 46202 02020 | 否 | 2024-04-22 17:04:12.0 | B4-2E-99-9A-CD-3A,00 -00-00-00-00-00-00-00-00-00-E0@BF EBFBF F0009 06EB@ 30353 23042 36333 73038 41363 63836 46202 02020 | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:58:54 | B4-2E-99-9A-CD-3A,00 -00-00-00-00-00-00-00-00-00-E0@BF EBFBF F0009 06EB@ 30353 23042 36333 73038 41363 63836 46202 02020 | 否   |   |  |

|     |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|-----|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
| 671 | 厦门裕金东<br>建筑工程有<br>限公司 | 2024-<br>04-23<br>10:42<br>:17.0 | C8-<br>7F-<br>54-<br>51-<br>3F-<br>AF@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C6C_<br>9745_<br>3E27. | 否 | 2024-<br>04-23<br>10:40<br>:22.0 | C8-<br>7F-<br>54-<br>51-<br>3F-<br>AF@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C6C_<br>9745_<br>3E27. | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:35<br>:08 | C8-<br>7F-<br>54-<br>51-<br>3F-<br>AF@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C6C_<br>9745_<br>3E27. | 否 |  |
| 672 | 福建长昌建<br>设工程有限<br>公司  | 2024-<br>04-23<br>15:52<br>:00.0 | D8-<br>5E-<br>D3-<br>27-<br>D0-<br>45@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OHTCJ<br>XS, 50<br>026B7<br>684A2<br>9780            | 否 | 2024-<br>04-23<br>15:45<br>:19.0 | D8-<br>5E-<br>D3-<br>27-<br>D0-<br>45@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OHTCJ<br>XS, 50<br>026B7<br>684A2<br>9780            | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:37<br>:42 | D8-<br>5E-<br>D3-<br>27-<br>D0-<br>45@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OHTCJ<br>XS, 50<br>026B7<br>684A2<br>9780            | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 673 | 福建凌浩建筑工程有限公司 | 2024-04-23 08:50:17.0 | DA-80-83-8D-86-87, FA-80-83-8D-86-87, 84-69-93-78-27-9E, D8-80-83-8D-86-87@BF EBFBF F0009 0675@421RJ TBMS | 否 | 2024-04-23 08:46:45.0 | DA-80-83-8D-86-87, FA-80-83-8D-86-87, 84-69-93-78-27-9E, D8-80-83-8D-86-87@BF EBFBF F0009 0675@421RJ TBMS | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:14 | 84-69-93-78-27-9E, D8-80-83-8D-86-87, DA-80-83-8D-86-87@BF EBFBF F0009 0675@421RJ TBMS | 否 |  |
| 674 | 福建双莉建筑工程有限公司 | 2024-04-23 15:03:39.0 | C8-7F-54-9F-72-70@BF EBFBF F0009 0675@50026 B7381 9F9C6 C, WD-WCC6Y ESACO 7C                              | 否 | 2024-04-23 10:38:31.0 | C8-7F-54-9F-72-70@BF EBFBF F0009 0675@50026 B7381 9F9C6 C, WD-WCC6Y ESACO 7C                              | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:06 | C8-7F-54-9F-72-70@BF EBFBF F0009 0675@50026 B7381 9F9C6 C, WD-WCC6Y ESACO 7C           | 否 |  |

|     |                   |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |                    |                        |   |   |  |
|-----|-------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|--------------------|------------------------|---|---|--|
| 675 | 华浩建设<br>(福建)有限公司  | 2024-04-22<br>09:39:52.0 | E0-<br>D5-<br>5E-<br>66-<br>4A-<br>06@BF<br>EBFBF<br>F0009<br>06E9@<br>30009<br>61444<br>8,WD-<br>WCC6Y<br>J9AHD<br>C1          | 否 | 2024-04-19<br>17:25:11.0 | E0-<br>D5-<br>5E-<br>66-<br>4A-<br>06@BF<br>EBFBF<br>F0009<br>06E9@<br>30009<br>61444<br>8,WD-<br>WCC6Y<br>J9AHD<br>C1          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误,请查<br>查 | 2024-04-24<br>08:41:41 | E0-<br>D5-<br>5E-<br>66-<br>4A-<br>06@BF<br>EBFBF<br>F0009<br>06E9@<br>30009<br>61444<br>8,WD-<br>WCC6Y<br>J9AHD<br>C1          | 否 |  |
| 676 | 福建省远乾<br>建设有限公司   | 2024-04-23<br>14:03:43.0 | 7C-<br>10-<br>C9-<br>A2-<br>1E-<br>14@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>DF2C8<br>C,WD-<br>WCC6Y<br>2ENA6<br>1H | 否 | 2024-04-23<br>14:02:26.0 | 7C-<br>10-<br>C9-<br>A2-<br>1E-<br>14@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>DF2C8<br>C,WD-<br>WCC6Y<br>2ENA6<br>1H | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误,请查<br>查 | 2024-04-24<br>08:34:22 | 7C-<br>10-<br>C9-<br>A2-<br>1E-<br>14@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>DF2C8<br>C,WD-<br>WCC6Y<br>2ENA6<br>1H | 否 |  |
| 677 | 福建省安丰<br>建设发展有限公司 | 2024-04-23<br>18:12:57.0 | 18-<br>C0-<br>4D-<br>E7-<br>CF-<br>0B@BF<br>EBFBF<br>F000A<br>0653@<br>30054<br>65918<br>9                                      | 否 | 2024-04-23<br>18:11:49.0 | 18-<br>C0-<br>4D-<br>E7-<br>CF-<br>0B@BF<br>EBFBF<br>F000A<br>0653@<br>30054<br>65918<br>9                                      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误,请查<br>查 | 2024-04-24<br>08:33:49 | 18-<br>C0-<br>4D-<br>E7-<br>CF-<br>0B@BF<br>EBFBF<br>F000A<br>0653@<br>30054<br>65918<br>9                                      | 否 |  |



|     |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 678 | 福建鼎熙路桥建设工程有限公司 | 2024-04-23 16:36:29.0 | F4-B5-20-5C-BC-06@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>24A5_<br>99B5.                                  | 否 | 2024-04-23 16:34:46.0 | F4-B5-20-5C-BC-06@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>24A5_<br>99B5.                                  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:31:43 | F4-B5-20-5C-BC-06@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>24A5_<br>99B5. | 否 |  |
| 679 | 福建兴昌荣建设有限公司    | 2024-04-23 15:09:40.0 | 08-BF-9B-A0-FC@BF<br>EBFBF<br>F0009<br>0675@<br>82910<br>11303<br>74636<br>7710,<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>24B6_<br>7625. | 否 | 2024-04-23 15:06:47.0 | 08-BF-9B-A0-FC@BF<br>EBFBF<br>F0009<br>0675@<br>82910<br>11303<br>74636<br>7710,<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>24B6_<br>7625. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:41:50 | 08-BF-9B-A0-FC@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>24B6_<br>7625.             | 否 |  |



|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
|     |               |                       | OD_16<br>C5.  |   |                       | OD_16<br>C5.  |   |  |  |  |  |  |  |  |  |  |              |                     | OD_16<br>C5.  |   |  |
| 682 | 福建省汀鹏建设发展有限公司 | 2024-04-23 16:30:13.0 | D8-<br>5E-<br>D3-<br>9E-<br>F7-<br>1D@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2NXC3<br>NK,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>78_4B<br>00_3E<br>55. | 否 | 2024-04-23 09:20:17.0 | D8-<br>5E-<br>D3-<br>9E-<br>F7-<br>1D@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2NXC3<br>NK,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>78_4B<br>00_3E<br>55. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:19 | D8-<br>5E-<br>D3-<br>9E-<br>F7-<br>1D@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2NXC3<br>NK,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>78_4B<br>00_3E<br>55. | 否 |  |
| 683 | 福建双收建设有限公司    | 2024-04-22 14:45:29.0 | A8-<br>5E-<br>45-<br>B2-<br>7B-<br>78@17<br>8BFBF<br>F0066<br>0F51@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>8CE3_<br>8E03_<br>0021_<br>E2E4.                        | 否 | 2024-04-22 11:40:23.0 | A8-<br>5E-<br>45-<br>B2-<br>7B-<br>78@17<br>8BFBF<br>F0066<br>0F51@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>8CE3_<br>8E03_<br>0021_<br>E2E4.                        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:40:27 | A8-<br>5E-<br>45-<br>B2-<br>7B-<br>78@17<br>8BFBF<br>F0066<br>0F51@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>8CE3_<br>8E03_<br>0021_<br>E2E4.                        | 否 |  |

|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 684 | 福建其峰建设发展有限公司 | 2024-04-23 10:32:48.0 | 18-C0-4D-CE-88-72@BF EBFBF F000A 0653@WD-WCC6Y 5THRE 7U, EA GET20 21092 98027 50 | 否 | 2024-04-23 10:31:47.0 | 18-C0-4D-CE-88-72@BF EBFBF F000A 0653@WD-WCC6Y 5THRE 7U, EA GET20 21092 98027 50 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:47 | 18-C0-4D-CE-88-72@BF EBFBF F000A 0653@WD-WCC6Y 5THRE 7U, EA GET20 21092 98027 50 | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|



|     |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 687 | 福建子衿建设有限公司     | 2024-04-23 14:34:41.0 | 48-F3-17-07-55-62@BFEBFBFF000A0653@AA000000008060030364  | 否 | 2024-04-23 14:31:45.0 | 48-F3-17-07-55-62@BFEBFBFF000A0653@AA000000008060030364  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:34:46 | 48-F3-17-07-55-62@BFEBFBFF000A0653@AA000000008060030364   | 否 |  |
| 688 | 厦门市卓力源建设工程有限公司 | 2024-04-22 18:25:35.0 | 74-27-EA-CA-BD-48@178BFBF00610F01@5353424d393132353033323931312020202020,20202020202020202020,20202020202020202020523643414b51314c | 否 | 2024-04-22 18:23:36.0 | 74-27-EA-CA-BD-48,00-00-00-00-00-00-00-00-E0@178BFBF00610F01@5353424d393132353033323931312020202020,202020202020202020205236402020202020202020523643414b51314c | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:34:12 | 74-27-EA-CA-BD-48@178BFBF00610F01@5353424d393132353033323931312020202020,20202020202020202020523643414b51314c | 否 |  |



|     |                |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|-----|----------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 691 | 福建聚强建设发展有限公司   | 2024-04-23 09:16:24.0 | A8-<br>A1-<br>59-<br>DD-<br>AC-<br>01,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>TA19C<br>16093<br>Q0488 | 否 | 2024-04-23 09:12:18.0 | A8-<br>A1-<br>59-<br>DD-<br>AC-<br>01,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>TA19C<br>16093<br>Q0488 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:07 | A8-<br>A1-<br>59-<br>DD-<br>AC-<br>01,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>TA19C<br>16093<br>Q0488 | 否   |   |  |
| 692 | 盛世金鼎(福建)建设有限公司 | 2024-04-23 09:46:58.0 | 50-<br>EB-<br>F6-<br>1F-<br>75-<br>96@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7EF4V<br>3E,22<br>166H8<br>03006  | 否 | 2024-04-23 09:44:40.0 | 50-<br>EB-<br>F6-<br>1F-<br>75-<br>96@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7EF4V<br>3E,22<br>166H8<br>03006                                   | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:35:26   | 50-<br>EB-<br>F6-<br>1F-<br>75-<br>96@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7EF4V<br>3E,22<br>166H8<br>03006 | 否 |  |



|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 693 | 福建省湛盛建设工程有限公司 | 2024-04-22 16:23:38.0 | 18-C0-4D-E6-6F-5E@BF EBFBF F000A 0653@ YS201 91185 31, WD - WCC6Y 4ZCD8 6K  | 否 | 2024-04-22 15:53:30.0 | 18-C0-4D-E6-6F-5E@BF EBFBF F000A 0653@ YS201 91185 31, WD - WCC6Y 4ZCD8 6K  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:17 | 18-C0-4D-E6-6F-5E@BF EBFBF F000A 0653@ YS201 91185 31, WD - WCC6Y 4ZCD8 6K  | 否 |  |
| 694 | 福建久振远建设工程有限公司 | 2024-04-23 09:07:36.0 | 24-1C-04-09-63-B4@BF EBFBF F0003 06A9@ 32483 83033 35304 a3731 31392 03520 20202 02020 , 314a 31393 13830 4a353 43935 20362 02020 20202 0 | 否 | 2024-04-23 09:05:34.0 | 24-1C-04-09-63-B4, 00 -00-00-00-00-00-00-00-00-00-00-06A9@ EBFBF F0003 06A9@ 32483 83033 35304 a3731 31392 03520 20202 , 314a 31393 13830 4a353 43935 20362 02020 20202 0 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:40 | 24-1C-04-09-63-B4@BF EBFBF F0003 06A9@ 32483 83033 35304 a3731 31392 03520 20202 02020 , 314a 31393 13830 4a353 43935 20362 02020 20202 0 | 否 |  |

|     |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 695 | 福建省垒鼎建设有限公司  | 2024-04-23 08:57:59.0 | 7C-10-C9-9D-DE-BD@BF EBFBF F000A 0653@ AA000 00000 00000 07250 ,WD-WCC6Y HJYE5 JV                          | 否 | 2024-04-22 11:12:57.0 | 7C-10-C9-9D-DE-BD@BF EBFBF F000A 0653@ AA000 00000 00000 07250 ,WD-WCC6Y HJYE5 JV                         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:31:23 | 7C-10-C9-9D-DE-BD@BF EBFBF F000A 0653@ AA000 00000 00000 07250 ,WD-WCC6Y HJYE5 JV                          | 否 |  |
| 696 | 福建英煌建设工程有限公司 | 2024-04-23 16:46:33.0 | 74-56-3C-19-B2-D8,00 -FF- DE-6C-00-78@BF EBFBF F000A 0671@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 29BE_ D5C5. | 否 | 2024-04-23 16:45:46.0 | 00-FF-DE-6C-00-78,74 -56-3C-19-B2-D8@BF EBFBF F000A 0671@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 29BE_ D5C5. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:33:33 | 74-56-3C-19-B2-D8,00 -FF- DE-6C-00-78@BF EBFBF F000A 0671@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 29BE_ D5C5. | 否 |  |







|     |                   |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                         |                                |  |   |  |
|-----|-------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|--|---|--|
|     |                   |                                  |  |   |                                  | F0005<br>06E3@<br>20202<br>02057<br>202d4<br>44d57<br>36433<br>05933<br>4e505<br>43450                         |   |  |  |  |  |  |  |  |  |  |  |                         |                                |  |   |  |
| 702 | 福建鑫福泰<br>建设工程有限公司 | 2024-<br>04-23<br>15:23<br>:17.0 | E0-<br>D5-<br>5E-<br>52-<br>6B-<br>CE@BF<br>EBFBF<br>F0009<br>06E9@<br>341A1<br>A76, 3<br>00143<br>49671       | 否 | 2024-<br>04-23<br>15:16<br>:38.0 | E0-<br>D5-<br>5E-<br>52-<br>6B-<br>CE@BF<br>EBFBF<br>F0009<br>06E9@<br>341A1<br>A76, 3<br>00143<br>49671       | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:40<br>:04 | E0-<br>D5-<br>5E-<br>52-<br>6B-<br>CE@BF<br>EBFBF<br>F0009<br>06E9@<br>30014<br>34967<br>1                     | 否 |  |
| 703 | 福建启喆建<br>设工程有限公司  | 2024-<br>04-23<br>11:44<br>:55.0 | 00-<br>E0-<br>4C-<br>5C-<br>6B-<br>02@BF<br>EBFBF<br>F000A<br>0653@<br>120KU<br>YNMS,<br>14619<br>94900<br>016 | 否 | 2024-<br>04-19<br>11:38<br>:59.0 | 00-<br>E0-<br>4C-<br>5C-<br>6B-<br>02@BF<br>EBFBF<br>F000A<br>0653@<br>120KU<br>YNMS,<br>14619<br>94900<br>016 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:32<br>:23 | 00-<br>E0-<br>4C-<br>5C-<br>6B-<br>02@BF<br>EBFBF<br>F000A<br>0653@<br>120KU<br>YNMS,<br>14619<br>94900<br>016 | 否 |  |

|     |                   |                          |   |   |                          |  |   |  |  |  |  |  |  |  |  |  |                            |                        |   |   |  |
|-----|-------------------|--------------------------|---|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|---|---|--|
| 704 | 福建省森隆<br>建设工程有限公司 | 2024-04-22<br>21:04:01.0 | 18-<br>C0-<br>4D-<br>F8-<br>DA-<br>03@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>43036<br>32353<br>23138<br>20312<br>02020<br>20202<br>02020 | 否 | 2024-04-22<br>21:03:37.0 | 18-<br>C0-<br>4D-<br>F8-<br>DA-<br>03, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>43036<br>32353<br>23138<br>20312<br>02020<br>20202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:35:40 | 18-<br>C0-<br>4D-<br>F8-<br>DA-<br>03@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>43036<br>32353<br>23138<br>20312<br>02020<br>20202<br>02020 | 否 |  |
|-----|-------------------|--------------------------|---|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|---|---|--|







|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 708 | 福建越亨建设工程有限公司 | 2024-04-19 09:36:55.0 | 50-EB-F6-1B-7D-4E@BF<br>EBFBF<br>F000A<br>0653@<br>WCC6Y<br>6CHVJ<br>9R, 50<br>026B7<br>78477<br>A7A6 | 否 | 2024-04-19 09:33:32.0 | 50-EB-F6-1B-7D-4E@BF<br>EBFBF<br>F000A<br>0653@<br>WCC6Y<br>6CHVJ<br>9R, 50<br>026B7<br>78477<br>A7A6 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:36:48 | 50-EB-F6-1B-7D-4E@BF<br>EBFBF<br>F000A<br>0653@<br>WCC6Y<br>6CHVJ<br>9R, 50<br>026B7<br>78477<br>A7A6 | 否 |  |
| 709 | 福建财大建设工程有限公司 | 2024-04-23 09:27:17.0 | A8-5E-45-5E-A6-0A@BF<br>EBFBF<br>F0009<br>06EB@<br>SCRW2<br>00605<br>07G03<br>48                      | 否 | 2024-04-22 17:35:49.0 | A8-5E-45-5E-A6-0A@BF<br>EBFBF<br>F0009<br>06EB@<br>SCRW2<br>00605<br>07G03<br>48                      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:17 | A8-5E-45-5E-A6-0A@BF<br>EBFBF<br>F0009<br>06EB@<br>SCRW2<br>00605<br>07G03<br>48                      | 否 |  |

|     |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
|-----|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|
| 710 | 福建迅腾辉<br>建设工程有<br>限公司 | 2024-<br>04-23<br>10:20<br>:33.0 | 00-<br>E0-<br>4D-<br>7F-<br>10-<br>26,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>ZTB15<br>12KA2<br>04100<br>0JR | 否 | 2024-<br>04-22<br>11:00<br>:02.0 | 00-<br>E0-<br>4D-<br>7F-<br>10-<br>26,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>ZTB15<br>12KA2<br>04100<br>0JR | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:32<br>:08 | 00-<br>E0-<br>4D-<br>7F-<br>10-<br>26,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>ZTB15<br>12KA2<br>04100<br>0JR | 否 |  |
| 711 | 福建鑫顺祥<br>建设发展有<br>限公司 | 2024-<br>04-23<br>14:18<br>:39.0 | D8-<br>5E-<br>D3-<br>FD-<br>E0-<br>A1@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>197E_<br>8855.   | 否 | 2024-<br>04-23<br>11:45<br>:57.0 | D8-<br>5E-<br>D3-<br>FD-<br>E0-<br>A1@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>197E_<br>8855.   | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:31<br>:15 | D8-<br>5E-<br>D3-<br>FD-<br>E0-<br>A1@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>197E_<br>8855.  | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 712 | 厦门市仁得建设工程有限公司 | 2024-04-20 10:55:23.0 | 00-1A-7D-DA-71-11,7C-10-C9-9D-9A-4F@BF EBFBF F000A 0655@WD-WCC6Y 4FJ8U TT, 50 026B7 6847A F47E | 否 | 2024-04-20 10:51:44.0 | 00-1A-7D-DA-71-11,7C-10-C9-9D-9A-4F@BF EBFBF F000A 0655@WD-WCC6Y 4FJ8U TT, 50 026B7 6847A F47E | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:28 | 00-1A-7D-DA-71-11,7C-10-C9-9D-9A-4F@BF EBFBF F000A 0655@WD-WCC6Y 4FJ8U TT, 50 026B7 6847A F47E | 否 |  |
| 713 | 福建晋恒建设工程有限公司  | 2024-04-23 16:32:59.0 | D8-5E-D3-4F-1B-2D@BF EBFBF F0009 0675@WD-WX52D B1F9J 32, 50 026B7 784AB 1612                   | 否 | 2024-04-23 16:32:22.0 | D8-5E-D3-4F-1B-2D@BF EBFBF F0009 0675@WD-WX52D B1F9J 32, 50 026B7 784AB 1612                   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:49 | D8-5E-D3-4F-1B-2D@BF EBFBF F0009 0675@WD-WX52D B1F9J 32, 50 026B7 784AB 1612                   | 否 |  |

|     |          |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|-----|----------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 714 | 有生集团有限公司 | 2024-04-22 10:16:47.0 | 04-7C-16-CD-32-78@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_1FB3_5B75. | 否 | 2024-04-17 15:43:50.0 | 04-7C-16-CD-32-78@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_1FB3_5B75. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:36:02 | 04-7C-16-CD-32-78@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_1FB3_5B75. | 否 |  |
|-----|----------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|





|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 717 | 厦门广名建设有限公司   | 2024-04-23 11:47:33.0 | 0C-<br>9D-<br>92-<br>7A-<br>BC-<br>EB@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>7EDE1<br>D, 1B8<br>7E93D<br>3090                   | 否 | 2024-04-23 11:45:31.0 | 0C-<br>9D-<br>92-<br>7A-<br>BC-<br>EB@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>7EDE1<br>D, 1B8<br>7E93D<br>3090   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:57:46 | 0C-<br>9D-<br>92-<br>7A-<br>BC-<br>EB@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>7EDE1<br>D, 1B8<br>7E93D<br>3090                   | 否 |  |
| 718 | 福建佳叶建设工程有限公司 | 2024-04-23 10:12:01.0 | 04-<br>D4-<br>C4-<br>4D-<br>21-<br>BF@BF<br>EBFBF<br>F0009<br>06EA@<br>30323<br>93038<br>35303<br>83433<br>31362<br>02020<br>20202<br>02020 | 否 | 2024-04-23 09:56:32.0 | 04-<br>D4-<br>C4-<br>4D-<br>21-<br>BF, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30323<br>93038<br>35303<br>83433<br>31362<br>02020<br>20202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:37 | 04-<br>D4-<br>C4-<br>4D-<br>21-<br>BF@BF<br>EBFBF<br>F0009<br>06EA@<br>30323<br>93038<br>35303<br>83433<br>31362<br>02020<br>20202<br>02020 | 否 |  |



|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 719 | 四川宝鑫建设有限公司   | 2024-04-22 14:14:12.0 | 00-E0-4C-7B-85-A9@178BFBF F0080 0F82@A843_9700_0000_9199.                   | 否 | 2024-04-22 14:12:04.0 | 00-E0-4C-7B-85-A9@178BFBF F0080 0F82@A843_9700_0000_9199.                   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:08 | 00-E0-4C-7B-85-A9@178BFBF F0080 0F82@A843_9700_0000_9199.                   | 否 |  |
| 720 | 豪和建设集团有限公司   | 2024-04-22 15:24:02.0 | 22-24-4D-02-16-6D@BFEBFBF F0009 0675@50026 B7436 0022A2                     | 否 | 2024-04-22 15:04:42.0 | 22-24-4D-02-16-6D@BFEBFBF F0009 0675@50026 B7436 0022A2                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:36:07 | 22-24-4D-02-16-6D@BFEBFBF F0009 0675@50026 B7436 0022A2                     | 否 |  |
| 721 | 河南十地建筑工程有限公司 | 2024-04-23 21:28:43.0 | F4-B5-20-5C-91-75,62-56-59-C2-BD-65@178BFBF F00A5 0F00@2C3E_BFFF_F000_4B26. | 否 | 2024-04-23 21:23:51.0 | F4-B5-20-5C-91-75,62-56-59-C2-BD-65@178BFBF F00A5 0F00@2C3E_BFFF_F000_4B26. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:38:31 | F4-B5-20-5C-91-75,62-56-59-C2-BD-65@178BFBF F00A5 0F00@2C3E_BFFF_F000_4B26. | 否 |  |

|     |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 722 | 福建淮祥建设有限公司   | 2024-04-22 16:32:02.0 | 00-<br>E0-<br>70-<br>B1-<br>27-<br>B9, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>4b323<br>53239<br>32375<br>13145<br>52582<br>02020<br>20202<br>02020 | 否 | 2024-04-22 16:08:33.0 | 00-<br>E0-<br>70-<br>B1-<br>27-<br>B9, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>4b323<br>53239<br>32375<br>13145<br>52582<br>02020<br>20202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:07 | 00-<br>E0-<br>70-<br>B1-<br>27-<br>B9, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>4b323<br>53239<br>32375<br>13145<br>52582<br>02020<br>20202<br>02020 | 否 |  |
| 723 | 福建鹏泰建设发展有限公司 | 2024-04-23 10:24:49.0 | B8-<br>97-<br>5A-<br>E1-<br>5C-<br>23, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>TC217<br>070P1<br>B0085<br>, WD-<br>WCC6Y<br>5UR2K<br>2S                    | 否 | 2024-04-23 10:23:18.0 | B8-<br>97-<br>5A-<br>E1-<br>5C-<br>23, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>TC217<br>070P1<br>B0085<br>, WD-<br>WCC6Y<br>5UR2K<br>2S             | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:49 | B8-<br>97-<br>5A-<br>E1-<br>5C-<br>23, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>TC217<br>070P1<br>B0085<br>, WD-<br>WCC6Y<br>5UR2K<br>2S                    | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 724 | 福建智鸿建设发展有限公司 | 2024-04-23 18:27:55.0 | 8C-32-23-05-DA-CB, 00-FF-15-BE-DB-18@BFEBFBFF00090675@6479_A75A_3090_1BB2., WD-WMC6Y0J6ZDE4 | 否 | 2024-04-23 12:14:25.0 | 8C-32-23-05-DA-CB, 00-FF-15-BE-DB-18@BFEBFBFF00090675@6479_A75A_3090_1BB2., WD-WMC6Y0J6ZDE4 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:48:38 | 8C-32-23-05-DA-CB, 00-FF-15-BE-DB-18@BFEBFBFF00090675@6479_A75A_3090_1BB2., WD-WMC6Y0J6ZDE4 | 否 |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|









|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|--|
| 730 | 福建鑫武夷建设工程有限公司 | 2024-04-23 11:22:23.0 | 58-11-22-06-40-BB,00-00-00-00-00-00-00-00-00-0653@30333530383735363834203720202020,2020202057202d444357364337594a595541554a | 否 | 2024-04-23 11:19:49.0 | 58-11-22-06-40-BB,00-00-00-00-00-00-00-00-00-0653@30333530383735363834203720202020,2020202057202d444357364337594a595541554a | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误,请检查 | 2024-04-24 08:33:47 | 58-11-22-06-40-BB@BFEBFBFF000A0653@3033353038373536383420372020,2020202057202d444357364337594a595541554a | 否 |  |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|--|





|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |  |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|--|---|--|
| 733 | 福建勤托建设工程有限公司 | 2024-04-19 09:53:59.0 | 4C-<br>CC-<br>6A-<br>67-<br>AB-<br>F7@BF<br>EBFBF<br>F0005<br>06E3@<br>WCC6Y<br>2ADDX<br>13, S3<br>3LNB1<br>H6098<br>74V                    | 否 | 2024-04-19 09:44:19.0 | 4C-<br>CC-<br>6A-<br>67-<br>AB-<br>F7@BF<br>EBFBF<br>F0005<br>06E3@<br>WCC6Y<br>2ADDX<br>13, S3<br>3LNB1<br>H6098<br>74V                    | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:39:11 | 4C-<br>CC-<br>6A-<br>67-<br>AB-<br>F7@BF<br>EBFBF<br>F0005<br>06E3@<br>WCC6Y<br>2ADDX<br>13, S3<br>3LNB1<br>H6098<br>74V                    | 否  |   |  |
| 734 | 福建省十三建建设有限公司 | 2024-04-23 10:48:38.0 | D4-<br>5D-<br>64-<br>43-<br>AF-<br>8D@BF<br>EBFBF<br>F0009<br>06EB@<br>474d3<br>33233<br>30303<br>33433<br>36363<br>53620<br>20202<br>02020 | 否 | 2024-04-19 12:00:34.0 | D4-<br>5D-<br>64-<br>43-<br>AF-<br>8D@BF<br>EBFBF<br>F0009<br>06EB@<br>474d3<br>33233<br>30303<br>33433<br>36363<br>53620<br>20202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:23 | D4-<br>5D-<br>64-<br>43-<br>AF-<br>8D@BF<br>EBFBF<br>F0009<br>06EB@<br>474d3<br>33233<br>30303<br>33433<br>36363<br>53620<br>20202<br>02020 | 否  |   |  |
| 735 | 福建同坤建设有限公司   | 2024-04-23 15:49:36.0 | 04-<br>D9-<br>F5-<br>1D-<br>85-<br>OE@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>4TRS6<br>44, 19<br>21BE4<br>42811                    | 否 | 2024-04-23 15:45:01.0 | 04-<br>D9-<br>F5-<br>1D-<br>85-<br>OE@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>4TRS6<br>44, 19<br>21BE4<br>42811                    | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:51:52   | 04-<br>D9-<br>F5-<br>1D-<br>85-<br>OE@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>4TRS6<br>44, 19<br>21BE4<br>42811 | 否 |  |



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 737 | 榕煜建设工程有限公司   | 2024-04-15 16:44:27.0 | 58-11-22-9A-26-EF@BF<br>EBFBFB<br>F0009<br>0675@<br>ZFM4C<br>SMC, 0<br>000_0<br>000_0<br>000_0<br>000_0<br>000_0<br>026_B<br>778_4<br>F58_A<br>D95.  | 否 | 2024-04-15 16:40:37.0 | 58-11-22-9A-26-EF@BF<br>EBFBFB<br>F0009<br>0675@<br>ZFM4C<br>SMC, 0<br>000_0<br>000_0<br>000_0<br>000_0<br>000_0<br>026_B<br>778_4<br>F58_A<br>D95.  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:11 | 58-11-22-9A-26-EF@BF<br>EBFBFB<br>F0009<br>0675@<br>ZFM4C<br>SMC, 0<br>000_0<br>000_0<br>000_0<br>000_0<br>000_0<br>026_B<br>778_4<br>F58_A<br>D95.  | 否 |  |
| 738 | 福建结远建筑工程有限公司 | 2024-04-23 09:57:34.0 | 08-BF-B8-BB-5C-73@BF<br>EBFBFB<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2E33_<br>5DF5.<br>, SCRW<br>21020<br>206A0<br>044, W<br>D-<br>WCC3F<br>6ZXZ4<br>KL | 否 | 2024-04-23 09:56:31.0 | 08-BF-B8-BB-5C-73@BF<br>EBFBFB<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2E33_<br>5DF5.<br>, SCRW<br>21020<br>206A0<br>044, W<br>D-<br>WCC3F<br>6ZXZ4<br>KL | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:11 | 08-BF-B8-BB-5C-73@BF<br>EBFBFB<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2E33_<br>5DF5.<br>, SCRW<br>21020<br>206A0<br>044, W<br>D-<br>WCC3F<br>6ZXZ4<br>KL | 否 |  |



|     |                  |                       |   |   |                       |  |   |  |  |  |  |            |                     |  |   |
|-----|------------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|------------|---------------------|--|---|
| 740 | 福建晟铭建设工程有限公司     | 2024-04-22 16:40:53.0 | 6C-<br>3C-<br>8C-<br>27-<br>8E-<br>E1, BC<br>-F4-<br>D4-<br>6F-<br>EE-<br>2A, BC<br>-F4-<br>D4-<br>6F-<br>EE-<br>29, BE<br>-F4-<br>D4-<br>6F-<br>EE-<br>29, BE<br>-F4-<br>D4-<br>6F-<br>EE-<br>29, B2<br>-F4-<br>D4-<br>6F-<br>EE-<br>29@BF<br>EBFBF<br>F000B<br>06F2@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>8CE3_<br>8E10_<br>00F0_<br>69CC.<br>, W9AT<br>9HYF | 否 | 2024-04-22 16:05:40.0 | BC-<br>F4-<br>D4-<br>6F-<br>EE-<br>29, BE<br>-F4-<br>D4-<br>6F-<br>EE-<br>29, B2<br>-F4-<br>D4-<br>6F-<br>EE-<br>29, 6C<br>-3C-<br>8C-<br>27-<br>8E-<br>E1, BC<br>-F4-<br>D4-<br>6F-<br>EE-<br>2A@BF<br>EBFBF<br>F000B<br>06F2@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>8CE3_<br>8E10_<br>00F0_<br>69CC.<br>, W9AT<br>9HYF | 否 |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:11 | BC-<br>F4-<br>D4-<br>6F-<br>EE-<br>29, BE<br>-F4-<br>D4-<br>6F-<br>EE-<br>29, B2<br>-F4-<br>D4-<br>6F-<br>EE-<br>29, 6C<br>-3C-<br>8C-<br>27-<br>8E-<br>E1, BC<br>-F4-<br>D4-<br>6F-<br>EE-<br>2A@BF<br>EBFBF<br>F000B<br>06F2@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>8CE3_<br>8E10_<br>00F0_<br>69CC.<br>, W9AT<br>9HYF | 否 |
| 741 | 嘉裕中闽(福建)建设发展有限公司 | 2024-04-22 16:48:08.0 | A0-<br>36-<br>BC-<br>2B-<br>02-<br>07@BF<br>EBFBF<br>F000A<br>0653@<br>E823_  | 否 | 2024-04-22 15:29:09.0 | A0-<br>36-<br>BC-<br>2B-<br>02-<br>07@BF<br>EBFBF<br>F000A<br>0653@<br>E823_   | 否 |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:54:59 | A0-<br>36-<br>BC-<br>2B-<br>02-<br>07@BF<br>EBFBF<br>F000A<br>0653@<br>E823_   | 否 |

|     |                   |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |                            |   |   |   |  |
|-----|-------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|---|---|---|--|
|     |                   |                              | 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E4F_ 8AEB.   |   |                              | 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E4F_ 8AEB.   |   |  |  |  |  |  |  |  |  |  |                            | 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E4F_ 8AEB. |   |   |  |
| 742 | 福建鑫易发<br>建设工程有限公司 | 2024-04-22<br>18:49<br>:16.0 | 70-<br>4D-<br>7B-<br>67-<br>AD-<br>BD@BF<br>EBFBF<br>F0005<br>06E3@<br>30105<br>53586<br>4, WD-<br>WCC6Y<br>OPD8K<br>6U                     | 否 | 2024-04-22<br>18:43<br>:06.0 | 70-<br>4D-<br>7B-<br>67-<br>AD-<br>BD@BF<br>EBFBF<br>F0005<br>06E3@<br>30105<br>53586<br>4, WD-<br>WCC6Y<br>OPD8K<br>6U                     | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>09:01<br>:55                | 70-<br>4D-<br>7B-<br>67-<br>AD-<br>BD@BF<br>EBFBF<br>F0005<br>06E3@<br>30105<br>53586<br>4, WD-<br>WCC6Y<br>OPD8K<br>6U                     | 否 |  |
| 743 | 海颐建工集<br>团有限公司    | 2024-04-23<br>13:16<br>:25.0 | 04-<br>7C-<br>16-<br>3F-<br>B1-<br>70@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0006_<br>2206_<br>1769_<br>CAF2_<br>5B02_<br>2000_<br>09E3. | 否 | 2024-04-23<br>13:13<br>:45.0 | 04-<br>7C-<br>16-<br>3F-<br>B1-<br>70@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0006_<br>2206_<br>1769_<br>CAF2_<br>5B02_<br>2000_<br>09E3. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:41<br>:06                | 04-<br>7C-<br>16-<br>3F-<br>B1-<br>70@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0006_<br>2206_<br>1769_<br>CAF2_<br>5B02_<br>2000_<br>09E3. | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 744 | 福建德凯建设工程有限公司 | 2024-04-22 18:19:24.0 | 1C-1B-0D-3A-81-21@BF EBFBF F0005 06E3@36535831464e5230324134353933204120202020,202020202020202020203957344141524242 | 否 | 2024-04-22 18:06:49.0 | 1C-1B-0D-3A-81-21@BF EBFBF F0005 06E3@36535831464e5230324134353933204120202020,20202020202020203957344141524242 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 09:10:59 | 1C-1B-0D-3A-81-21@BF EBFBF F0005 06E3@36535831464e5230324134353933204120202020,20202020202020203957344141524242 | 否 |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|





|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 746 | 福建鑫浩建设工程有限公司 | 2024-04-17 16:22:46.0 | 30333<br>84630<br>30383<br>03035<br>33373<br>23837<br>,5752<br>38313<br>24130<br>32303<br>33541<br>32322<br>03120<br>20202<br>0 | 否 | 2024-04-17 16:21:00.0 | E0@BF<br>EBFBF<br>F0005<br>06E3@<br>34414<br>53537<br>30333<br>84630<br>30383<br>03035<br>33373<br>23837<br>,5752<br>38313<br>24130<br>32303<br>33541<br>32322<br>03120<br>20202<br>0 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:33:25 | F0-<br>2F-<br>74-<br>CC-<br>16-<br>C4@BF<br>EBFBF<br>F0009<br>06E9@<br>RC211<br>110M5<br>H1526<br>,WD-<br>WCC6Y<br>7SYCX<br>NU | 否 |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|

|     |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 747 | 福建德财建设工程发展有限公司 | 2024-04-23 10:11:22.0 | C8-5B-76-51-09-B5@BF<br>EBFBF<br>F0003<br>06C3@<br>AA202<br>00311<br>00000<br>00098<br>,W3TJ<br>36XJ         | 否 | 2024-04-23 10:04:54.0 | C8-5B-76-51-09-B5@BF<br>EBFBF<br>F0003<br>06C3@<br>AA202<br>00311<br>00000<br>00098<br>,W3TJ<br>36XJ         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:28 | C8-5B-76-51-09-B5@BF<br>EBFBF<br>F0003<br>06C3@<br>AA202<br>00311<br>00000<br>00098<br>,W3TJ<br>36XJ         | 否 |  |
| 748 | 宇宸建设有限公司       | 2024-04-23 14:03:13.0 | F0-2F-74-DA-ED-38@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC4J<br>OAS9P<br>J4, 50<br>026B7<br>38217<br>73FB | 否 | 2024-04-23 14:01:47.0 | F0-2F-74-DA-ED-38@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC4J<br>OAS9P<br>J4, 50<br>026B7<br>38217<br>73FB | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:53 | F0-2F-74-DA-ED-38@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC4J<br>OAS9P<br>J4, 50<br>026B7<br>38217<br>73FB | 否 |  |
| 749 | 福建彦阳建设有限公司     | 2024-04-23 08:53:19.0 | 0C-9D-92-C0-34-96@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>2AHKN<br>ZZ, 50<br>026B7<br>38179<br>09DE | 否 | 2024-04-23 08:50:21.0 | 0C-9D-92-C0-34-96@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>2AHKN<br>ZZ, 50<br>026B7<br>38179<br>09DE | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:47 | 0C-9D-92-C0-34-96@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>2AHKN<br>ZZ, 50<br>026B7<br>38179<br>09DE | 否 |  |





|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |                     |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|---------------------|---------------------|--|---|--|
| 752 | 上海九安建设集团有限公司 | 2024-04-22 17:52:26.0 | 00-<br>FF-<br>D9-<br>2D-<br>FC-<br>49, D8<br>-5E-<br>D3-<br>26-<br>9E-<br>29@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>416F_<br>B694. | 否 | 2024-04-22 17:32:13.0 | 00-<br>FF-<br>D9-<br>2D-<br>FC-<br>49, D8<br>-5E-<br>D3-<br>26-<br>9E-<br>29@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>416F_<br>B694. | 否 |  |  |  |  |  |  |  |  |  | 校验数据<br>有误, 请<br>检查 | 2024-04-24 08:35:10 | 00-<br>FF-<br>D9-<br>2D-<br>FC-<br>49, D8<br>-5E-<br>D3-<br>26-<br>9E-<br>29@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>416F_<br>B694. | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|---------------------|---------------------|--|---|--|

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |             |                     |   |   |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|
| 753 | 福建省佳鑫鼎业建设有限公司 | 2024-04-23 14:30:35.0 | D8-5E-D3-13-BA-4A, 3C-06-A7-72-3D-B6, 3E-06-A7-72-3D-B6, 3C-06-A7-72-3D-B6@BF EBFBF F000A 0671@WD-WCC6Y 7YYE8 P3, 50 026B7 380ED E983 | 否 | 2024-04-23 14:27:17.0 | D8-5E-D3-13-BA-4A, 3E-06-A7-72-3D-B6, 3C-06-A7-72-3D-B6, 3C-06-A7-72-3D-B6@BF EBFBF F000A 0671@WD-WCC6Y 7YYE8 P3, 50 026B7 380ED E983 | 否 |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:35 | D8-5E-D3-13-BA-4A, 3C-06-A7-72-3D-B6, 3E-06-A7-72-3D-B6, 3C-06-A7-72-3D-B6@BF EBFBF F000A 0671@WD-WCC6Y 7YYE8 P3, 50 026B7 380ED E983 | 否 |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|











|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 759 | 福建开都建设发展有限公司 | 2024-04-22 16:43:34.0 | 68-DA-73-A3-61-59, 12-68-38-92-0A-3E, 92-68-38-92-0A-3E, 10-68-38-92-0A-3F@BFEBFBFF000B06A2@0025_38EA_21BD_7B70. | 否 | 2024-04-22 16:41:51.0 | 68-DA-73-A3-61-59, 12-68-38-92-0A-3E, 92-68-38-92-0A-3E, 10-68-38-92-0A-3F@BFEBFBFF000B06A2@0025_38EA_21BD_7B70. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:40:54 | 68-DA-73-A3-61-59, 12-68-38-92-0A-3E, 92-68-38-92-0A-3E, 10-68-38-92-0A-3F@BFEBFBFF000B06A2@0025_38EA_21BD_7B70. | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|



|     |                       |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                             |                                |   |   |  |  |  |  |
|-----|-----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|-----------------------------|--------------------------------|---|---|--|--|--|--|
|     |                       |                                  |  |   |                                  | E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>20233<br>74702<br>08  |   |  |  |  |  |  |  |  |  |  |                             |                                |   |   |  |  |  |  |
| 762 | 福建省恒通<br>路桥工程有<br>限公司 | 2024-<br>04-23<br>14:47<br>:18.0 | 4C-<br>ED-<br>FB-<br>C9-<br>3C-<br>73@BF<br>EBFBF<br>F0009<br>06E9@<br>31493<br>73138<br>37305<br>23030<br>33352<br>03020<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>35595<br>0414e<br>35313<br>9 | 否 | 2024-<br>04-23<br>14:44<br>:16.0 | 4C-<br>ED-<br>FB-<br>C9-<br>3C-<br>73, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>31493<br>73138<br>37305<br>23030<br>33352<br>03020<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>35595<br>0414e<br>35313<br>9 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>, 请<br>检查 | 2024-<br>04-24<br>08:37<br>:04 | 58-<br>11-<br>22-<br>0B-<br>2F-<br>A9@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4LZSV<br>AK, 30<br>09167<br>3223 | 否 |  |  |  |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 763 | 福建赛邦建设工程有限公司 | 2024-04-17 16:20:03.0 | 7C-10-C9-D1-3B-6C,00-1A-7D-DA-71-03@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 415A_ OEC8. ,A510 512Y2 34934 94 | 否 | 2024-04-17 16:13:56.0 | 7C-10-C9-D1-3B-6C,00-1A-7D-DA-71-03@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 415A_ OEC8. ,A510 512Y2 34934 94 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:11 | 7C-10-C9-D1-3B-6C,00-1A-7D-DA-71-03@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 415A_ OEC8. ,A510 512Y2 34934 94 | 否 |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|







|     |                  |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|------------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 766 | 星玖（福建）建设发展集团有限公司 | 2024-04-23 16:36:14.0 | 00-<br>E2-<br>69-<br>4C-<br>08-<br>36@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>02216 | 否 | 2024-04-23 16:34:38.0 | 00-<br>E2-<br>69-<br>4C-<br>08-<br>36@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>02216 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:52:28 | 00-<br>E2-<br>69-<br>4C-<br>08-<br>36@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>02216 | 否 |  |
|-----|------------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|



|     |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |                    |                     |  |   |  |  |
|-----|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------------|---------------------|--|---|--|--|
| 768 | 福建威恒建设工程有限公司 | 2024-04-23 17:10:47.0 | 10-7B-44-50-BE-F4@BF<br>EBFBF<br>F0009<br>06E9@<br>68711<br>16500<br>83, WD<br>-<br>WCC6Y<br>1XJJD<br>HJ | 否 | 2024-04-23 17:01:42.0 | 10-7B-44-50-BE-F4,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>68711<br>16500<br>83, WD<br>-<br>WCC6Y<br>1XJJD<br>HJ | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有<br>误，请<br>检查 | 2024-04-24 08:36:02 | 10-7B-44-50-BE-F4@BF<br>EBFBF<br>F0009<br>06E9@<br>68711<br>16500<br>83, WD<br>-<br>WCC6Y<br>1XJJD<br>HJ | 否 |  |  |
|-----|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------------|---------------------|--|---|--|--|



|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 770 | 中发腾龙建设有限公司   | 2024-04-22 10:50:10.0 | 74-56-3C-1E-52-4A@BF<br>EBFBF<br>F000A<br>0653@<br>0000-<br>0000-<br>0000-<br>0000-<br>0026-<br>B738-<br>200F-<br>EFE5.<br>, WD-<br>WCC6Y<br>5JLX9<br>3V  | 否 | 2024-04-22 10:44:17.0 | 74-56-3C-1E-52-4A@BF<br>EBFBF<br>F000A<br>0653@<br>0000-<br>0000-<br>0000-<br>0000-<br>0026-<br>B738-<br>200F-<br>EFE5.<br>, WD-<br>WCC6Y<br>5JLX9<br>3V  | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:43:44 | 74-56-3C-1E-52-4A@BF<br>EBFBF<br>F000A<br>0653@<br>0000-<br>0000-<br>0000-<br>0000-<br>0026-<br>B738-<br>200F-<br>EFE5.<br>, WD-<br>WCC6Y<br>5JLX9<br>3V  | 否 |  |
| 771 | 福建永益建设工程有限公司 | 2024-04-18 16:07:08.0 | 58-11-22-8C-71-F8@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>83035<br>34393<br>13539<br>20372<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>46593<br>33248<br>5a554<br>1 | 否 | 2024-04-18 16:00:18.0 | 58-11-22-8C-71-F8@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>83035<br>34393<br>13539<br>20372<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>46593<br>33248<br>5a554<br>1 | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:07 | 58-11-22-8C-71-F8@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>83035<br>34393<br>13539<br>20372<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>46593<br>33248<br>5a554<br>1 | 否 |  |

|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 772 | 福建省汇恒达建筑工程有限公司 | 2024-04-18 17:30:57.0 | 18-C0-4D-C6-53-43@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OC6A3<br>LL,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1D<br>D2_D0<br>55. | 否 | 2024-04-18 17:26:25.0 | 18-C0-4D-C6-53-43@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OC6A3<br>LL,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1D<br>D2_D0<br>55. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:36:21 | 18-C0-4D-C6-53-43@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OC6A3<br>LL,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1D<br>D2_D0<br>55. | 否   |   |  |
| 773 | 福建锦润源建筑工程有限公司  | 2024-04-23 08:42:11.0 | E8-9C-25-40-F2-F5@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>707C_<br>1802_<br>2829_<br>0209.                                 | 否 | 2024-04-23 08:41:57.0 | E8-9C-25-40-F2-F5@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>707C_<br>1802_<br>2829_<br>0209.                                 | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:37:28   | E8-9C-25-40-F2-F5@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>707C_<br>1802_<br>2829_<br>0209. | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|--|
| 774 | 福建水武建设有限公司   | 2024-04-23 15:39:07.0 | 30-<br>B4-<br>9E-<br>E3-<br>B6-<br>7C, 30<br>-B4-<br>9E-<br>E3-<br>B6-<br>7C, 00<br>-E0-<br>70-<br>8B-<br>2F-<br>F7@BF<br>EBFBF<br>F0009<br>06E9@<br>18526<br>34236<br>95 | 否 | 2024-04-23 15:37:30.0 | 30-<br>B4-<br>9E-<br>E3-<br>B6-<br>7C, 30<br>-B4-<br>9E-<br>E3-<br>B6-<br>7C, 00<br>-E0-<br>70-<br>8B-<br>2F-<br>F7, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>18526<br>34236<br>95 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:41:42 | 30-<br>B4-<br>9E-<br>E3-<br>B6-<br>7C, 30<br>-B4-<br>9E-<br>E3-<br>B6-<br>7C, 00<br>-E0-<br>70-<br>8B-<br>2F-<br>F7@BF<br>EBFBF<br>F0009<br>06E9@<br>18526<br>34236<br>95 | 否 |  |  |
| 775 | 福建正祥建设工程有限公司 | 2024-04-23 09:47:51.0 | 94-<br>DE-<br>80-<br>AA-<br>7D-<br>AB@BF<br>EBFBF<br>F0003<br>06A9@<br>0520B<br>67728<br>OBAD6<br>1   | 否 | 2024-04-15 15:10:05.0 | 94-<br>DE-<br>80-<br>AA-<br>7D-<br>AB, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06A9@<br>0520B<br>67728<br>OBAD6<br>1  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:35:02 | 94-<br>DE-<br>80-<br>AA-<br>7D-<br>AB@BF<br>EBFBF<br>F0003<br>06A9@<br>0520B<br>67728<br>OBAD6<br>1   | 否 |  |  |



|     |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 776 | 福建泽佳建设工程有限公司 | 2024-04-23 15:59:31.0 | 00-25-F2-6A-DC-D4, 4E-77-66-13-C9-DD, 4C-77-66-13-C9-DD@BF EBFBF F0009 06EA@MX_20 07210 923 | 否 | 2024-04-23 09:22:29.0 | 00-25-F2-6A-DC-D4, 4E-77-66-13-C9-DD, 4C-77-66-13-C9-DD, 4C-77-66-13-C9-DD@BF EBFBF F0009 06EA@MX_20 07210 923 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 09:00:08 | 00-25-F2-6A-DC-D4, 4C-77-66-13-C9-DD, 4E-77-66-13-C9-DD, 4C-77-66-13-C9-DD@BF EBFBF F0009 06EA@MX_20 07210 923 | 否 |  |
| 777 | 福建屹凌建筑工程有限公司 | 2024-04-23 16:08:42.0 | D8-5E-D3-10-1B-94@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0000_0100_0000_0000.         | 否 | 2024-04-23 16:07:44.0 | D8-5E-D3-10-1B-94@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0000_0100_0000_0000.                            | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:51:19 | D8-5E-D3-10-1B-94@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0000_0100_0000_0000.                            | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 778 | 福建景琛建设工程有限公司 | 2024-04-23 17:09:34.0 | 50-EB-F6-B3-73-FF@BFEBFBFF000A0653@TA2161905210066,Z9ARZ7ZZ                 | 否 | 2024-04-23 10:33:08.0 | 50-EB-F6-B3-73-FF@BFEBFBFF000A0653@TA2161905210066,Z9ARZ7ZZ                 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:41:18 | 50-EB-F6-B3-73-FF@BFEBFBFF000A0653@TA2161905210066,Z9ARZ7ZZ                 | 否 |  |
| 779 | 福建安建建筑工程有限公司 | 2024-04-18 10:05:14.0 | A4-0C-66-02-09-98@BFEBFBFF000906EB@314b303230334534363039352039202020202020 | 否 | 2024-04-18 09:51:39.0 | A4-0C-66-02-09-98@BFEBFBFF000906EB@314b303230334534363039352039202020202020 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:54:24 | A4-0C-66-02-09-98@BFEBFBFF000906EB@314b303230334534363039352039202020202020 | 否 |  |

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 780 | 福建新广盛建设工程有限公司 | 2024-04-18 10:50:36.0 | EC-D6-8A-C1-01-28, F4-C8-8A-74-7C-04@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_1E60_2F25. | 否 | 2024-04-18 10:48:14.0 | EC-D6-8A-C1-01-28, F4-C8-8A-74-7C-04@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_1E60_2F25. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:07 | EC-D6-8A-C1-01-28, F4-C8-8A-74-7C-04@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_1E60_2F25. | 否 |  |
| 781 | 福建祯晖建设工程有限公司  | 2024-04-18 11:00:15.0 | 08-BF-B8-A2-63-0F@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_2549_94B5.                    | 否 | 2024-04-18 09:29:06.0 | 08-BF-B8-A2-63-0F@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_2549_94B5.                    | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:45:24 | 08-BF-B8-A2-63-0F@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_2549_94B5.                    | 否 |  |

|     |                        |                                  |   |                                  |   |  |  |  |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|-----|------------------------|----------------------------------|---|----------------------------------|---|--|--|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
| 782 | 海峡九龙<br>(福建)建<br>工有限公司 | 2024-<br>04-23<br>17:17<br>:56.0 | 否 | 2024-<br>04-23<br>17:14<br>:59.0 | 否 | E0-<br>D5-<br>5E-<br>1D-<br>CA-<br>88,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBB<br>F0005<br>06E3@<br>20202<br>02020<br>20202<br>04357<br>36433<br>65954<br>584c4<br>63139 |  |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:35<br>:40 | 58-<br>11-<br>22-<br>8C-<br>36-<br>7F@BF<br>EBFBB<br>F000A<br>0653@<br>30353<br>23042<br>36333<br>73138<br>37393<br>03744<br>44202<br>02020<br>, 2020<br>20205<br>7202d<br>444d5<br>73243<br>34453<br>63038<br>35363<br>0 | 否 |  |
|-----|------------------------|----------------------------------|---|----------------------------------|---|--|--|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|



|     |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 784 | 福建卓久建筑工程有限公司 | 2024-04-23 15:02:29.0 | 00-<br>E0-<br>4C-<br>84-<br>E8-<br>42@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WXB2D<br>909PJ<br>JZ, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_13<br>44_DC<br>25. | 否 | 2024-04-23 15:01:20.0 | 00-<br>E0-<br>4C-<br>84-<br>E8-<br>42@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WXB2D<br>909PJ<br>JZ, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_13<br>44_DC<br>25.                            | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:43:26 | 00-<br>E0-<br>4C-<br>84-<br>E8-<br>42@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WXB2D<br>909PJ<br>JZ, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_13<br>44_DC<br>25. | 否 |  |
| 785 | 福建荣筑建设工程有限公司 | 2024-04-23 16:54:43.0 | 00-<br>E0-<br>4D-<br>A3-<br>53-<br>F3@BF<br>EBFBF<br>F0003<br>06A9@<br>30353<br>23042<br>36373<br>73438<br>39383<br>84235<br>46202<br>02020                                  | 否 | 2024-04-23 16:51:19.0 | 00-<br>E0-<br>4D-<br>A3-<br>53-<br>F3, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06A9@<br>30353<br>23042<br>36373<br>73438<br>39383<br>84235<br>46202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:34:39 | 00-<br>E0-<br>4D-<br>A3-<br>53-<br>F3@BF<br>EBFBF<br>F0003<br>06A9@<br>30353<br>23042<br>36373<br>73438<br>39383<br>84235<br>46202<br>02020                                  | 否 |  |



|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 787 | 福建华颖建设工程有限公司   | 2024-04-23 15:50:56.0 | A4-0C-66-04-1B-C8@BF EBFBF F0009 06EB@314b3632373130523130383920312020202002020,202020202002020204357364337594b5634345039 | 否 | 2024-04-23 15:31:03.0 | A4-0C-66-04-1B-C8,00-00-00-00-00-00-00-00-00-06EB@314b3632373130523130383920312020202002020,20202020200202020435,202020202020204357364302020b5634345039 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误,请检查 | 2024-04-24 08:31:50 | A4-0C-66-04-1B-C8@BF EBFBF F0009 06EB@314b36323731305231303839203120202020,202020202002020204357364337594b5634345039 | 否 |  |
| 788 | 福建中睿通达建筑工程有限公司 | 2024-04-23 16:36:39.0 | 70-85-C2-9F-97-11@178BFBF F0081 0F10@202004260399,WD-WCC2E YM92147  | 否 | 2024-04-23 16:24:12.0 | 70-85-C2-9F-97-11@178BFBF F0081 0F10@202004260399,WD-WCC2E YM92147  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误,请检查 | 2024-04-24 08:33:08 | 70-85-C2-9F-97-11@178BFBF F0081 0F10@202004260399,WD-WCC2E YM92147   | 否 |  |





|     |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |  |
|-----|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|--|
| 790 | 福建省长隆景观建设工程有限公司 | 2024-04-23 17:36:40.0 | 00-E2-69-60-32-28@BFEBFBF000A0653@MG220950700479,W2ALZEK2            | 否 | 2024-04-23 17:35:25.0 | 00-E2-69-60-32-28@BFEBFBF000A0653@MG220950700479,W2ALZEK2                                    | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误,请查 | 2024-04-24 08:34:18 | 00-E2-69-60-32-28@BFEBFBF000A0653@MG220950700479,W2ALZEK2            | 否 |  |  |
| 791 | 福建省众安泰建设工程有限公司  | 2024-04-22 15:22:22.0 | 74-46-A0-BF-FO-OC@BFEBFBF000306A9@W-DCW2C5ELKJUAZ,TZ1B52K62A123060MN | 否 | 2024-04-22 15:01:34.0 | 74-46-A0-BF-FO-OC,00-00-00-00-00-00-00-EO@BFEBFBF000306A9@W-DCW2C5ELKJUAZ,TZ1B52K62A123060MN | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误,请查 | 2024-04-24 08:33:12 | 74-46-A0-BF-FO-OC@BFEBFBF000306A9@W-DCW2C5ELKJUAZ,TZ1B52K62A123060MN | 否 |  |  |

|     |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                         |                                |   |   |  |
|-----|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|---|---|--|
| 792 | 福建省升创<br>建设工程有<br>限公司 | 2024-<br>04-23<br>18:59<br>:51.0 | A0-<br>36-<br>BC-<br>25-<br>15-<br>3D, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>0675@<br>23132<br>F8075<br>71, 22<br>395C8<br>02829 | 否 | 2024-<br>04-23<br>18:59<br>:02.0 | A0-<br>36-<br>BC-<br>25-<br>15-<br>3D, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>0675@<br>23132<br>F8075<br>71, 22<br>395C8<br>02829 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:39<br>:51 | A0-<br>36-<br>BC-<br>25-<br>15-<br>3D, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>0675@<br>23132<br>F8075<br>71, 22<br>395C8<br>02829 | 否 |  |
| 793 | 福建恒裕昇<br>建设工程有<br>限公司 | 2024-<br>04-23<br>11:38<br>:41.0 | 00-<br>E0-<br>4C-<br>0B-<br>81-<br>7A@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>5ZNF3<br>06, EA<br>GET20<br>22011<br>8R009<br>43   | 否 | 2024-<br>04-23<br>11:35<br>:33.0 | 00-<br>E0-<br>4C-<br>0B-<br>81-<br>7A@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>5ZNF3<br>06, EA<br>GET20<br>22011<br>8R009<br>43   | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:33<br>:07 | 00-<br>E0-<br>4C-<br>0B-<br>81-<br>7A@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>5ZNF3<br>06, EA<br>GET20<br>22011<br>8R009<br>43   | 否 |  |

|     |                      |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|----------------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 794 | 海峡众源<br>(福建)建设发展有限公司 | 2024-04-23 09:46:32.0 | 74-56-3C-A4-16-90@BF<br>EBFBF<br>F0009<br>0675@01019<br>cf545<br>16c94<br>b8996<br>,WD-<br>WCC6Y<br>14AL2<br>20,00<br>25_38<br>A6_21<br>B1_B9<br>A2.   | 否 | 2024-04-23 09:44:13.0 | 74-56-3C-A4-16-90@BF<br>EBFBF<br>F0009<br>0675@01019<br>cf545<br>16c94<br>b8996<br>,WD-<br>WCC6Y<br>14AL2<br>20,00<br>25_38<br>A6_21<br>B1_B9<br>A2.   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:48:59 | 74-56-3C-A4-16-90@BF<br>EBFBF<br>F0009<br>0675@WD-<br>WCC6Y<br>14AL2<br>20,00<br>25_38<br>A6_21<br>B1_B9<br>A2.  | 否 |  |
| 795 | 福建省鑫祥隆建设工程有限公司       | 2024-04-23 11:06:30.0 | 88-D7-F6-3E-AF-CF,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>YS201<br>91181<br>52,WD<br>-<br>WCC4J<br>1NF77<br>CU | 否 | 2024-04-23 11:05:08.0 | 88-D7-F6-3E-AF-CF,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>YS201<br>91181<br>52,WD<br>-<br>WCC4J<br>1NF77<br>CU | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:26 | 88-D7-F6-3E-AF-CF,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>YS201<br>91181<br>52,WD<br>-<br>WCC4J<br>1NF77<br>CU | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 796 | 福建省东方精工建设有限公司 | 2024-04-22 10:11:21.0 | 58-11-22-44-83-C8,00-00-00-00-00-00@BFEBFBF000A0653@E823_8FA6_BF53_0001_001B_448B_4177_76EA. | 否 | 2024-04-22 10:01:15.0 | 58-11-22-44-83-C8@BFEBFBF000A0653@E823_8FA6_BF53_0001_001B_448B_4177_76EA. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:36:20 | 58-11-22-44-83-C8,00-00-00-00-00-00@BFEBFBF000A0653@E823_8FA6_BF53_0001_001B_448B_4177_76EA. | 否 |  |
| 797 | 福建省城川建设工程有限公司 | 2024-04-19 14:35:34.0 | 00-E2-69-3B-DE-80@BFEBFBF000906E9@3035323042363737323830363935423820202020                   | 否 | 2024-04-19 11:34:46.0 | 00-E2-69-3B-DE-80@BFEBFBF000906E9@3035323042363737323830363935423820202020 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:37:19 | 00-E2-69-3B-DE-80@BFEBFBF000906E9@3035323042363737323830363935423820202020                   | 否 |  |





|     |                       |                                  |  |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |  |                |  |  |
|-----|-----------------------|----------------------------------|--|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|----------------|--|--|
|     |                       |                                  | 30303<br>73635   |   |                                  | 30303<br>73635  |   |  |  |  |  |  |  |  |  |  |  |  | 30303<br>73635 |  |  |
| 802 | 福建省典弈<br>建筑工程有<br>限公司 | 2024-<br>04-23<br>11:08<br>:11.0 | E0-<br>CB-<br>1D-<br>00-<br>09-<br>FC@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36333<br>73038<br>41423<br>53232<br>31202<br>02020<br>, 2020<br>20202<br>02020<br>20202<br>02020<br>02020<br>31573<br>14447<br>56373<br>1 | 否 | 2024-<br>04-23<br>10:20<br>:52.0 | E0-<br>CB-<br>1D-<br>00-<br>09-<br>FC, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>06EA@<br>EBFBF<br>F0009<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36333<br>73038<br>41423<br>53232<br>31202<br>02020<br>, 2020<br>20202<br>02020<br>20202<br>02020<br>20202<br>02020<br>31573<br>14447<br>56373<br>1 | 否 |  |  |  |  |  |  |  |  |  |  | E0-<br>CB-<br>1D-<br>00-<br>09-<br>FC@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36333<br>73038<br>41423<br>53232<br>31202<br>02020<br>, 2020<br>20202<br>02020<br>20202<br>02020<br>02020<br>31573<br>14447<br>56373<br>1 | 否              |  |  |



|     |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 803 | 福建赫铨建设工程有限公司    | 2024-04-23 15:21:33.0 | D8-BB-C1-D9-16-D4@BF EBFBF F000A 0653@12PNE Z7MS, CM133 BH090 1259           | 否 | 2024-04-23 15:19:33.0 | D8-BB-C1-D9-16-D4@BF EBFBF F000A 0653@12PNE Z7MS, CM133 BH090 1259           | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:41:35 | D8-BB-C1-D9-16-D4@BF EBFBF F000A 0653@12PNE Z7MS, CM133 BH090 1259           | 否 |  |
| 804 | 筑良佳建设工程(厦门)有限公司 | 2024-04-23 09:43:28.0 | 18-C0-4D-D4-12-E3@BF EBFBF F000A 0653@WD-WCC6Y 5LPON C9, 50 026B7 3812E 4325 | 否 | 2024-04-23 09:42:23.0 | 18-C0-4D-D4-12-E3@BF EBFBF F000A 0653@WD-WCC6Y 5LPON C9, 50 026B7 3812E 4325 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:42 | 18-C0-4D-D4-12-E3@BF EBFBF F000A 0653@WD-WCC6Y 5LPON C9, 50 026B7 3812E 4325 | 否 |  |





|     |                    |                          |   |   |                          |  |   |  |  |  |  |  |  |  |  |                   |                        |  |   |   |  |
|-----|--------------------|--------------------------|---|---|--------------------------|--|---|--|--|--|--|--|--|--|--|-------------------|------------------------|--|---|---|--|
| 808 | 中谊建设<br>(福建)有限公司   | 2024-04-23<br>15:41:06.0 | D8-<br>5E-<br>D3-<br>49-<br>B0-<br>01@BF<br>EBFBF<br>F0009<br>0675@<br>0025_<br>38D5_<br>21A2_<br>E0D3.   | 否 | 2024-04-23<br>15:39:24.0 | D8-<br>5E-<br>D3-<br>49-<br>B0-<br>01@BF<br>EBFBF<br>F0009<br>0675@<br>0025_<br>38D5_<br>21A2_<br>E0D3.  | 否 |  |  |  |  |  |  |  |  |                   | 校验数据<br>有,请查<br>检      | 2024-04-24<br>08:39:39   | D8-<br>5E-<br>D3-<br>49-<br>B0-<br>01@BF<br>EBFBF<br>F0009<br>0675@<br>0025_<br>38D5_<br>21A2_<br>E0D3. | 否 |  |
| 809 | 中闽众建<br>(福建)建设有限公司 | 2024-04-23<br>10:41:50.0 | A8-<br>5E-<br>45-<br>18-<br>19-<br>CA, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>ZFM3K<br>F7K, R<br>W1981<br>7034A<br>2753 | 否 | 2024-04-23<br>10:40:27.0 | A8-<br>5E-<br>45-<br>18-<br>19-<br>CA, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>ZFM3K<br>F7K, R<br>W1981<br>7034A<br>2753 | 否 |  |  |  |  |  |  |  |  | 校验数据<br>有,请查<br>检 | 2024-04-24<br>08:33:30 | A8-<br>5E-<br>45-<br>18-<br>19-<br>CA@BF<br>EBFBF<br>F0009<br>06EB@<br>ZFM3K<br>F7K, R<br>W1981<br>7034A<br>2753 | 否   |   |  |

|     |                              |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                        |                                |   |   |  |
|-----|------------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------|--------------------------------|---|---|--|
| 810 | 中工永大<br>(福建)建<br>设发展有限<br>公司 | 2024-<br>04-22<br>13:43<br>:39.0 | C8-<br>60-<br>00-<br>88-<br>AE-<br>1F@BF<br>EBFBF<br>F0003<br>06A9@<br>AEEG2<br>T2002<br>25856<br>986<br>8, W -<br>DCWYA<br>KU3Z3<br>011 | 否 | 2024-<br>04-22<br>13:38<br>:50.0 | C8-<br>60-<br>00-<br>88-<br>AE-<br>1F@BF<br>EBFBF<br>F0003<br>06A9@<br>AEEG2<br>T2002<br>25856<br>986<br>8, W -<br>DCWYA<br>KU3Z3<br>011 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:35<br>:40 | 9C-<br>5C-<br>8E-<br>D0-<br>15-<br>7B@BF<br>EBFBF<br>F0003<br>06C3@<br>30353<br>23042<br>36333<br>74135<br>36373<br>03032<br>39202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>35594<br>e4a4c<br>48524<br>e | 否 |  |
| 811 | 福建隆工建<br>设工程有限<br>公司         | 2024-<br>04-24<br>08:27<br>:26.0 | C8-<br>7F-<br>54-<br>9F-<br>70-<br>35@BF<br>EBFBF<br>F0009<br>0675@<br>9C1C_<br>6D00_<br>0001_<br>47D0.                                  | 否 | 2024-<br>04-23<br>10:52<br>:11.0 | C8-<br>7F-<br>54-<br>9F-<br>70-<br>35@BF<br>EBFBF<br>F0009<br>0675@<br>9C1C_<br>6D00_<br>0001_<br>47D0.                                  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:40<br>:46 | C8-<br>7F-<br>54-<br>9F-<br>70-<br>35@BF<br>EBFBF<br>F0009<br>0675@<br>9C1C_<br>6D00_<br>0001_<br>47D0.   | 否 |  |





|     |                 |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|-----------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 816 | 深圳市天海建设科技集团有限公司 | 2024-04-23 18:01:02.0 | 08-BF-B8-31-EC-AB, 0C-5B-8F-27-9A-64@BFEBFBFF00090675@0000_0000_0000_0000_0026_B778_5375_BD75. | 否 | 2024-04-19 09:29:42.0 | 08-BF-B8-31-EC-AB, 0C-5B-8F-27-9A-64@BFEBFBFF00090675@0000_0000_0000_0000_0026_B778_5375_BD75.                | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:41:16 | 08-BF-B8-31-EC-AB, 0C-5B-8F-27-9A-64@BFEBFBFF00090675@0000_0000_0000_0000_0026_B778_5375_BD75. | 否 |  |
| 817 | 福建互联建设有限公司      | 2024-04-23 16:57:23.0 | 0C-9D-92-87-2F-A0@BFEBFBFF000906E9@2020202057202d44585732323844483358305635                    | 否 | 2024-04-23 15:22:13.0 | 0C-9D-92-87-2F-A0, 00-00-00-00-00-00-00-00-00-00-E0@BFEBFBFF000906E9@2020202057202d44585732323844483358305635 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:52 | 0C-9D-92-87-2F-A0@BFEBFBFF000906E9@2020202057202d44585732323844483358305635                    | 否 |  |



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 818 | 福建意众建设工程有限公司 | 2024-04-23 15:58:19.0 | 74-56-3C-10-27-BB, D4-84-09-57-E9-74, D4-84-09-57-E9-75, D4-84-09-57-E9-76@BFEBFBF000A0653@0000_0000_0000_0000_0026_B768_5FE1_2995., WD-WCC6Y1APY19J | 否 | 2024-04-23 15:55:33.0 | 74-56-3C-10-27-BB, D4-84-09-57-E9-74, D4-84-09-57-E9-75, D4-84-09-57-E9-76@BFEBFBF000A0653@0000_0000_0000_0000_0026_B768_5FE1_2995., WD-WCC6Y1APY19J | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:39:03 | 74-56-3C-10-27-BB, D4-84-09-57-E9-74, D4-84-09-57-E9-75, D4-84-09-57-E9-76@BFEBFBF000A0653@0000_0000_0000_0000_0026_B768_5FE1_2995., WD-WCC6Y1APY19J | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|

|     |                 |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |   |  |
|-----|-----------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|---|--|
| 819 | 福建省一叶凡成建设工程有限公司 | 2024-04-23 11:34:38.0 | 00-<br>E0-<br>4C-<br>17-<br>FC-<br>BA@BF<br>EBFBF<br>F0009<br>06EA@<br>SCRW2<br>00811<br>08A23<br>78, WD<br>-<br>WCC6Y<br>OHLCN<br>PH       | 否 | 2024-04-18 16:22:45.0 | 00-<br>E0-<br>4C-<br>17-<br>FC-<br>BA, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>SCRW2<br>00811<br>08A23<br>78, WD<br>-<br>WCC6Y<br>OHLCN<br>PH | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:42 | 00-<br>E0-<br>4C-<br>17-<br>FC-<br>BA@BF<br>EBFBF<br>F0009<br>06EA@<br>SCRW2<br>00811<br>08A23<br>78, WD<br>-<br>WCC6Y<br>OHLCN<br>PH       | 否   |   |  |
| 820 | 万利安（福建）建设有限公司   | 2024-04-23 16:13:42.0 | 7C-<br>10-<br>C9-<br>A2-<br>1C-<br>CA@BF<br>EBFBF<br>F000A<br>0671@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1344_<br>2D65. | 否 | 2024-04-23 11:57:34.0 | 7C-<br>10-<br>C9-<br>A2-<br>1C-<br>CA@BF<br>EBFBF<br>F000A<br>0671@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1344_<br>2D65.  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:07 | 7C-<br>10-<br>C9-<br>A2-<br>1C-<br>CA@BF<br>EBFBF<br>F000A<br>0671@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1344_<br>2D65. | 否   |   |  |
| 821 | 福建闽万华水利水电工程有限公司 | 2024-04-22 17:29:04.0 | 00-<br>E0-<br>4C-<br>E9-<br>A6-<br>BE@BF<br>EBFBF   | 否 | 2024-04-18 11:43:45.0 | 00-<br>E0-<br>4C-<br>E9-<br>A6-<br>BE, 00<br>-00-  | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:34:39   | 00-<br>E0-<br>4C-<br>E9-<br>A6-<br>BE@BF<br>EBFBF | 否 |  |

|     |                        |                                  |   |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |  |   |                                |   |   |  |
|-----|------------------------|----------------------------------|---|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|---|--------------------------------|---|---|--|
|     |                        |                                  | F0002<br>06D7@<br>3I059<br>10B80<br>52<br>6, 2SP<br>AA2HV   |   |                                  | 00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0002<br>06D7@<br>3I059<br>10B80<br>52<br>6, 2SP<br>AA2HV |   |  |  |  |  |  |  |  |  |  |  |  | F0002<br>06D7@<br>3I059<br>10B80<br>52<br>6, 2SP<br>AA2HV |                                |   |   |  |
| 822 | 福建闽清一<br>建建设发展<br>有限公司 | 2024-<br>04-23<br>16:52<br>:45.0 | B8-<br>97-<br>5A-<br>E1-<br>4E-<br>AA@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7382<br>3ED95<br>F | 否 | 2024-<br>04-23<br>16:51<br>:15.0 | B8-<br>97-<br>5A-<br>E1-<br>4E-<br>AA@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7382<br>3ED95<br>F            | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查                                | 2024-<br>04-24<br>08:31<br>:53 | B8-<br>97-<br>5A-<br>E1-<br>4E-<br>AA@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7382<br>3ED95<br>F | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 823 | 福建晋旗建设有限公司   | 2024-04-23 10:42:14.0 | 58-11-22-0D-2D-7A, 0A-61-12-06-4B-66@BF EBFBF F000A 0653@0000_0000_0000_0000_0026_B768_5FA0_72F5. | 否 | 2024-04-23 10:40:46.0 | 58-11-22-0D-2D-7A, 0A-61-12-06-4B-66@BF EBFBF F000A 0653@0000_0000_0000_0000_0026_B768_5FA0_72F5. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:12 | 58-11-22-8B-B7-F0, 00-1A-7D-DA-71-11@BF EBFBF F000A 0653@0000_0000_0000_0000_0026_B738_172C_FC55. | 否 |  |
| 824 | 福建骏恒建设发展有限公司 | 2024-04-23 15:52:37.0 | 3C-7C-3F-BC-D8-4C@BF EBFBF F000A 0653@TH208 25408 30656, WD-WCC6Y 3FEZR 2A, WD-WCAV9 01349 76     | 否 | 2024-04-23 15:50:27.0 | 3C-7C-3F-BC-D8-4C@BF EBFBF F000A 0653@TH208 25408 30656, WD-WCC6Y 3FEZR 2A, WD-WCAV9 01349 76     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:40:15 | 3C-7C-3F-BC-D8-4C@BF EBFBF F000A 0653@TH208 25408 30656, WD-WCC6Y 3FEZR 2A, WD-WCAV9 01349 76     | 否 |  |

|     |                        |                              |   |   |                              |  |   |  |  |  |  |  |  |  |  |  |                            |                            |   |   |  |
|-----|------------------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|---|--|
| 825 | 中建华林<br>(福建)建设<br>有限公司 | 2024-04-23<br>15:43<br>:51.0 | B8-<br>97-<br>5A-<br>EA-<br>EC-<br>62,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>RHD22<br>DDFH8<br>D0000<br>28107<br>,WD-<br>WCC6Z<br>5LFPO<br>52 | 否 | 2024-04-22<br>15:24<br>:46.0 | B8-<br>97-<br>5A-<br>EA-<br>EC-<br>62,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>RHD22<br>DDFH8<br>D0000<br>28107<br>,WD-<br>WCC6Z<br>5LFPO<br>52 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>,请<br>检查 | 2024-04-24<br>08:39<br>:47 | B8-<br>97-<br>5A-<br>EA-<br>EC-<br>62@BF<br>EBFBF<br>F0009<br>06E9@<br>RHD22<br>DDFH8<br>D0000<br>28107<br>,WD-<br>WCC6Z<br>5LFPO<br>52     | 否 |  |
| 826 | 福建省同特<br>建设工程有<br>限公司  | 2024-04-22<br>14:40<br>:32.0 | 08-<br>BF-<br>B8-<br>2B-<br>39-<br>A2@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2488_<br>1D45.   | 否 | 2024-04-22<br>14:34<br>:16.0 | 08-<br>BF-<br>B8-<br>2B-<br>39-<br>A2@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2488_<br>1D45.  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>,请<br>检查 | 2024-04-24<br>08:32<br>:33 | 08-<br>BF-<br>B8-<br>2B-<br>39-<br>A2@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2488_<br>1D45. | 否 |  |

|     |                   |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |  |                     |                        |   |   |  |
|-----|-------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|--|---------------------|------------------------|---|---|--|
| 827 | 福建新禹丰<br>建设工程有限公司 | 2024-04-23<br>19:42:48.0 | A0-36-BC-05-0B-01@BF<br>EBFBF<br>F000A<br>0653@<br>22518<br>W4542<br>14 | 否 | 2024-04-23<br>19:30:55.0 | A0-36-BC-05-0B-01@BF<br>EBFBF<br>F000A<br>0653@<br>22518<br>W4542<br>14 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>检 | 2024-04-24<br>08:41:03 | A0-36-BC-05-0B-01@BF<br>EBFBF<br>F000A<br>0653@<br>22518<br>W4542<br>14 | 否 |  |
|-----|-------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|--|---------------------|------------------------|---|---|--|



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |  |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|--|--|
| 829 | 福建福龙建设工程有限公司 | 2024-04-23 10:27:11.0 | D4-84-09-57-CB-22, D4-84-09-57-CB-23, D4-84-09-57-CB-20, 74-56-3C-24-4F-5A@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 1A6D_ 7565. , WD- WCC6Y 02ART 0L | 否 | 2024-04-19 15:50:29.0 | D4-84-09-57-CB-22, D4-84-09-57-CB-23, D4-84-09-57-CB-20, 74-56-3C-24-4F-5A@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 1A6D_ 7565. , WD- WCC6Y 02ART 0L | 否 |  |  |  |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:07 | D4-84-09-57-CB-22, D4-84-09-57-CB-23, D4-84-09-57-CB-20, 74-56-3C-24-4F-5A@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 1A6D_ 7565. , WD- WCC6Y 02ART 0L | 否 |  |  |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|--|--|



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 830 | 福建本宏建筑工程有限公司 | 2024-04-23 10:39:24.0 | A4-<br>AE-<br>12-<br>FC-<br>49-<br>5B, 30<br>-C9-<br>AB-<br>F0-<br>A1-<br>2F, 32<br>-C9-<br>AB-<br>F0-<br>A1-<br>2F, B2<br>-C9-<br>AB-<br>F0-<br>A1-<br>2F@BF<br>EBFBF<br>F000A<br>0653@<br>YS000<br>55667<br>77777<br>00652<br>, W9AM<br>YG6M | 否 | 2024-04-23 10:36:42.0 | A4-<br>AE-<br>12-<br>FC-<br>49-<br>5B, 30<br>-C9-<br>AB-<br>F0-<br>A1-<br>2F, 32<br>-C9-<br>AB-<br>F0-<br>A1-<br>2F, B2<br>-C9-<br>AB-<br>F0-<br>A1-<br>2F@BF<br>EBFBF<br>F000A<br>0653@<br>YS000<br>55667<br>77777<br>00652<br>, W9AM<br>YG6M | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:31:34 | A4-<br>AE-<br>12-<br>FC-<br>49-<br>5B, 30<br>-C9-<br>AB-<br>F0-<br>A1-<br>2F, 32<br>-C9-<br>AB-<br>F0-<br>A1-<br>2F, B2<br>-C9-<br>AB-<br>F0-<br>A1-<br>2F@BF<br>EBFBF<br>F000A<br>0653@<br>YS000<br>55667<br>77777<br>00652<br>, W9AM<br>YG6M | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|

|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 831 | 福建武夷剑津建设发展有限公司 | 2024-04-23 14:12:22.0 | 08-BF-B8-3A-55-42@BF<br>EBFBF<br>F000A<br>0653@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>444A<br>49DF<br>F86E.<br>, WD-<br>WCC6Y<br>3RVDJ<br>9S | 否 | 2024-04-20 11:17:44.0 | 08-BF-B8-3A-55-42@BF<br>EBFBF<br>F000A<br>0653@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>444A<br>49DF<br>F86E.<br>, WD-<br>WCC6Y<br>3RVDJ<br>9S | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:33:07 | 08-BF-B8-3A-55-42@BF<br>EBFBF<br>F000A<br>0653@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>444A<br>49DF<br>F86E.<br>, WD-<br>WCC6Y<br>3RVDJ<br>9S | 否 |  |
| 832 | 福建耀途盛世建筑工程有限公司 | 2024-04-23 10:25:29.0 | 00-E0-70-76-5E-B9,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>MDE28<br>2Q000<br>045        | 否 | 2024-04-23 10:15:20.0 | 00-E0-70-76-5E-B9,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>MDE28<br>2Q000<br>045        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 09:00:08 | 00-E0-70-76-5E-B9,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>MDE28<br>2Q000<br>045        | 否 |  |



|     |                       |                                  |   |                                  |   |  |  |  |  |  |  |  |  |  |  |  |                        |                                |   |  |
|-----|-----------------------|----------------------------------|---|----------------------------------|---|--|--|--|--|--|--|--|--|--|--|--|------------------------|--------------------------------|---|--|
| 835 | 福建省东驰<br>建筑工程有<br>限公司 | 2024-<br>04-23<br>13:02<br>:37.0 | 否 | 2024-<br>04-18<br>15:41<br>:20.0 | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误，请<br>检查 | 2024-<br>04-24<br>08:33<br>:09 | 否 |  |
|     |                       |                                  |   |                                  |   |  |  |  |  |  |  |  |  |  |  |  |                        |                                |   |  |

00-  
E0-  
4C-  
5F-  
1F-  
A5,00  
-E0-  
4C-  
68-  
E6-  
6B,00  
-00-  
00-  
00-  
00-  
00-  
2024-  
04-23  
13:02  
:37.0

否

00-  
E0-  
4C-  
84-  
24-  
4A,00  
-C0-  
3A-  
68-  
90-  
8D,00  
-00-  
00-  
00-  
00-  
2024-  
04-18  
15:41  
:20.0

否

校验  
数据有  
误，请  
检查

00-  
E0-  
4C-  
5F-  
1F-  
A5,00  
-E0-  
4C-  
68-  
E6-  
6B,00  
-00-  
00-  
00-  
00-  
00-  
2024-  
04-24  
08:33  
:09

否

|     |                        |                              |  |   |                              |   |   |  |  |  |  |  |  |  |  |  |                         |                            |  |  |   |  |
|-----|------------------------|------------------------------|--|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|-------------------------|----------------------------|--|--|---|--|
| 836 | 福建鑫齐誉<br>建设工程有限公司      | 2024-04-23<br>15:56<br>:22.0 | 00-<br>E0-<br>4C-<br>62-<br>20-<br>90@BF<br>EBFBF<br>F0009<br>06E9@<br>22350<br>2A003<br>B4, WD<br>-<br>WCC6Y<br>5UFFJ<br>83 | 否 | 2024-04-23<br>15:54<br>:35.0 | 00-<br>E0-<br>4C-<br>62-<br>20-<br>90, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>22350<br>2A003<br>B4, WD<br>-<br>WCC6Y<br>5UFFJ<br>83 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:33<br>:07 | 00-<br>E0-<br>4C-<br>62-<br>20-<br>90@BF<br>EBFBF<br>F0009<br>06E9@<br>22350<br>2A003<br>B4, WD<br>-<br>WCC6Y<br>5UFFJ<br>83 | 否  |   |  |
| 837 | 福建省秦明<br>越工程建设<br>有限公司 | 2024-04-23<br>16:42<br>:28.0 | 00-<br>E0-<br>0B-<br>09-<br>61-<br>EE@BF<br>EBFBF<br>F0003<br>06E4@<br>2109J<br>PDC25<br>60000<br>2619                       | 否 | 2024-04-23<br>10:43<br>:47.0 | 00-<br>E0-<br>0B-<br>09-<br>61-<br>EE@BF<br>EBFBF<br>F0003<br>06E4@<br>2109J<br>PDC25<br>60000<br>2619  | 否 |  |  |  |  |  |  |  |  |  |                         | 校验<br>数据有<br>误, 请<br>检查    | 2024-04-24<br>08:35<br>:11   | 00-<br>E0-<br>0B-<br>09-<br>61-<br>EE@BF<br>EBFBF<br>F0003<br>06E4@<br>2109J<br>PDC25<br>60000<br>2619 | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 838 | 福建鑫宏建设有限公司   | 2024-04-23 16:52:45.0 | D4-5D-64-48-A6-20@BFEBFBFF000906ED@MYJ20051200103                                   | 否 | 2024-04-23 16:53:34.0 | D4-5D-64-48-A6-20@BFEBFBFF000906ED@MYJ20051200103                                   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:46:49 | 00-0B-E2-B0-D9-55@BFEBFBFF000A0671@6479_A75A_BOCO_0292.                             | 否 |  |
| 839 | 福建纳源建设工程有限公司 | 2024-04-23 09:03:34.0 | D4-5D-64-81-B0-9A@BFEBFBFF000906EA@30092727688,0000_0000_0000_000E0_4C12_5B50_8065. | 否 | 2024-04-23 09:00:34.0 | D4-5D-64-81-B0-9A@BFEBFBFF000906EA@30092727688,0000_0000_0000_000E0_4C12_5B50_8065. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:04 | D4-5D-64-81-B0-9A@BFEBFBFF000906EA@30092727688,0000_0000_0000_000E0_4C12_5B50_8065. | 否 |  |
| 840 | 福建省垚金建设有限公司  | 2024-04-23 16:32:44.0 | E4-54-E8-C8-9F-53@BFEBFBFF000906EB@ZN1C5V14,30013505679                             | 否 | 2024-04-23 16:23:04.0 | E4-54-E8-C8-9F-53@BFEBFBFF000906EB@ZN1C5V14,30013505679                             | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:40 | E4-54-E8-C8-9F-53@BFEBFBFF000906EB@ZN1C5V14,30013505679                             | 否 |  |
| 841 | 福建联山建设工程有限公司 | 2024-04-23            | 18-C0-  | 否 | 2024-04-23            | 18-C0-  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据        | 2024-04-24          | 18-C0-  | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |                           |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|---------------------------|---------------------|---|---|--|
|     | 公司           | 15:31:25.0            | 4D-BF-7A-FD@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>CCEAD<br>8                             |   | 15:29:28.0            | 4D-BF-7A-FD@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>CCEAD<br>8                             |   |  |  |  |  |  |  |  |  |  |  | 有误<br>请<br>检查             | 08:35:05            | 4D-BF-7A-FD@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>CCEAD<br>8                             |   |  |
| 842 | 福建长宽建设工程有限公司 | 2024-04-23 15:09:56.0 | D8-5E-D3-7B-8B-43@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_444A_481B_8E5F.          | 否 | 2024-04-23 15:07:24.0 | D8-5E-D3-7B-8B-43@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_444A_481B_8E5F.          | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>请<br>检查 | 2024-04-24 08:36:34 | D8-5E-D3-7B-8B-43@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_444A_481B_8E5F.          | 否 |  |
| 843 | 福建昌鑫建设工程有限公司 | 2024-04-22 14:28:41.0 | 40-8D-5C-19-BA-81@BF<br>EBFBF<br>F0003<br>06C3@<br>6RYCX<br>DDN, E<br>9DF07<br>540EC<br>80029<br>4892 | 否 | 2024-04-22 14:23:09.0 | 40-8D-5C-19-BA-81@BF<br>EBFBF<br>F0003<br>06C3@<br>6RYCX<br>DDN, E<br>9DF07<br>540EC<br>80029<br>4892 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>请<br>检查 | 2024-04-24 08:33:32 | 40-8D-5C-19-BA-81@BF<br>EBFBF<br>F0003<br>06C3@<br>6RYCX<br>DDN, E<br>9DF07<br>540EC<br>80029<br>4892 | 否 |  |

|     |                   |                        |   |   |                        |  |   |  |  |  |  |  |  |  |  |                    |                      |   |   |  |
|-----|-------------------|------------------------|---|---|------------------------|--|---|--|--|--|--|--|--|--|--|--------------------|----------------------|---|---|--|
| 844 | 福建众鑫隆<br>建设发展有限公司 | 2024-04-22 17:16 :54.0 | 00-<br>E2-<br>69-<br>21-<br>82-<br>BE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>4VNR3<br>C4, 23<br>16424<br>89905 | 否 | 2024-04-22 17:15 :04.0 | 00-<br>E2-<br>69-<br>21-<br>82-<br>BE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>4VNR3<br>C4, 23<br>16424<br>89905 | 否 |  |  |  |  |  |  |  |  | 校验数据<br>有误，请<br>检查 | 2024-04-24 08:32 :06 | 00-<br>E2-<br>69-<br>21-<br>82-<br>BE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>4VNR3<br>C4, 23<br>16424<br>89905 | 否 |  |
|-----|-------------------|------------------------|---|---|------------------------|--|---|--|--|--|--|--|--|--|--|--------------------|----------------------|---|---|--|



|     |                |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |  |                     |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|---------------------|---------------------|---|---|--|
| 845 | 福建省富利康建设发展有限公司 | 2024-04-23 15:34:09.0 | E0-<br>D5-<br>5E-<br>D6-<br>D2-<br>54@BF<br>EBFBF<br>F0009<br>06EB@<br>K1154<br>2R015<br>487, W<br>D-<br>WCC6Y<br>2UJ9D<br>74 | 否 | 2024-04-23 11:39:16.0 | E0-<br>D5-<br>5E-<br>D6-<br>D2-<br>54, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>K1154<br>2R015<br>487, W<br>D-<br>WCC6Y<br>2UJ9D<br>74 | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据<br>有错误,<br>请检查 | 2024-04-24 08:33:07 | E0-<br>D5-<br>5E-<br>D6-<br>D2-<br>54@BF<br>EBFBF<br>F0009<br>06EB@<br>K1154<br>2R015<br>487, W<br>D-<br>WCC6Y<br>2UJ9D<br>74 | 否 |  |
|-----|----------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|---------------------|---------------------|---|---|--|

|     |              |                          |   |   |                          |  |   |  |  |  |  |  |  |  |  |                    |                        |   |  |   |  |
|-----|--------------|--------------------------|---|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--------------------|------------------------|---|--|---|--|
| 846 | 福建冉天建设有限公司   | 2024-04-23<br>10:39:49.0 | E0-<br>D5-<br>5E-<br>71-<br>8F-<br>3F,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>97801<br>11600<br>85,21<br>08V83<br>C2C06<br>071 | 否 | 2024-04-23<br>10:38:03.0 | E0-<br>D5-<br>5E-<br>71-<br>8F-<br>3F,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>97801<br>11600<br>85,21<br>08V83<br>C2C06<br>071 | 否 |  |  |  |  |  |  |  |  | 校验数据<br>有误,请<br>检查 | 2024-04-24<br>08:32:23 | E0-<br>D5-<br>5E-<br>71-<br>8F-<br>3F@BF<br>EBFBF<br>F0009<br>06E9@<br>97801<br>11600<br>85,21<br>08V83<br>C2C06<br>071 | 否  |   |  |
| 847 | 中盛闽展建工集团有限公司 | 2024-04-23<br>14:57:40.0 | 0C-<br>9D-<br>92-<br>61-<br>D4-<br>FD@BF<br>EBFBF<br>F0009<br>06EB@<br>RW194<br>17216<br>A0768<br>,RW19<br>72711<br>2A024<br>8  | 否 | 2024-04-23<br>09:36:54.0 | 0C-<br>9D-<br>92-<br>61-<br>D4-<br>FD@BF<br>EBFBF<br>F0009<br>06EB@<br>RW194<br>17216<br>A0768<br>,RW19<br>72711<br>2A024<br>8   | 否 |  |  |  |  |  |  |  |  |                    | 校验数据<br>有误,请<br>检查     | 2024-04-24<br>08:34:39  | 0C-<br>9D-<br>92-<br>61-<br>D4-<br>FD@BF<br>EBFBF<br>F0009<br>06EB@<br>RW194<br>17216<br>A0768<br>,RW19<br>72711<br>2A024<br>8 | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 848 | 福建禹拓建设工程有限公司 | 2024-04-23 14:48:46.0 | 60-45-CB-9A-DD-7A@BFEBFBFF000906E9@S6PFNJOWAO2349M                      | 否 | 2024-04-23 11:17:49.0 | 60-45-CB-9A-DD-7A@BFEBFBFF000906E9@S6PFNJOWAO2349M                      | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:06 | 60-45-CB-9A-DD-7A@BFEBFBFF000906E9@S6PFNJOWAO2349M                      | 否 |  |
| 849 | 福建新九州建筑有限公司  | 2024-04-23 15:26:46.0 | D8-5E-D3-41-56-56@BFEBFBFF000A0653@2022101100405                        | 否 | 2024-04-23 15:08:19.0 | D8-5E-D3-41-56-56@BFEBFBFF000A0653@2022101100405                        | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:26 | D8-5E-D3-41-56-56@BFEBFBFF000A0653@2022101100405                        | 否 |  |
| 850 | 福建集旭建设工程有限公司 | 2024-04-23 11:28:46.0 | 2C-F0-5D-ED-1D-A3@BFEBFBFF000A0653@WD-WCC6Y4RK4CZ3,85F0070B063000619968 | 否 | 2024-04-23 11:24:33.0 | 2C-F0-5D-ED-1D-A3@BFEBFBFF000A0653@WD-WCC6Y4RK4CZ3,85F0070B063000619968 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:47 | 2C-F0-5D-ED-1D-A3@BFEBFBFF000A0653@WD-WCC6Y4RK4CZ3,85F0070B063000619968 | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 851 | 福建屹轩建设工程有限公司 | 2024-04-23 09:57:39.0 | 00-12-C3-22-05-15@BFEBFBF000906EA@RW19817034A2917,6VVMR1ZF    | 否 | 2024-04-23 09:54:41.0 | 00-12-C3-22-05-15@BFEBFBF000906EA@RW19817034A2917,6VVMR1ZF    | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:13 | 00-12-C3-22-05-15@BFEBFBF000906EA@RW19817034A2917,6VVMR1ZF    | 否 |  |
| 852 | 福建锦辉建设工程有限公司 | 2024-04-23 09:49:28.0 | A0-36-BC-25-07-01@BFEBFBF00090675@30080512663,WD-WCC6Y5TNHSP5 | 否 | 2024-04-22 11:01:20.0 | A0-36-BC-25-07-01@BFEBFBF00090675@30080512663,WD-WCC6Y5TNHSP5 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:43 | A0-36-BC-25-07-01@BFEBFBF00090675@30080512663,WD-WCC6Y5TNHSP5 | 否 |  |
| 853 | 福建天宸建设工程有限公司 | 2024-04-22 16:17:11.0 | 74-56-3C-A4-0D-55@BFEBFBF00090675@50026B73821069DF            | 否 | 2024-04-22 15:36:46.0 | 74-56-3C-A4-0D-55@BFEBFBF00090675@50026B73821069DF            | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:38:50 | 74-56-3C-A4-0D-55@BFEBFBF00090675@50026B73821069DF            | 否 |  |

|     |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|-----|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 854 | 福建昊辰建设有限公司 | 2024-04-23 15:43:31.0 | 00-<br>E0-<br>70-<br>62-<br>95-<br>FB@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WXV1A<br>97D4Y<br>EY | 否 | 2024-04-23 14:13:29.0 | 00-<br>E0-<br>70-<br>62-<br>95-<br>FB, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WXV1A<br>97D4Y<br>EY | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:18 | 00-<br>E0-<br>70-<br>62-<br>95-<br>FB@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WXV1A<br>97D4Y<br>EY | 否 |  |
|-----|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|

|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|---|--|
| 855 | 福建省万弘耀建设工程有限公司 | 2024-04-23 16:37:52.0 | 4C-ED-FB-63-F2-5B,00-00-00-00-00-00-E0@BFEBFBFF000906E9@303130303238323835362033202020202020,2020202057202d44435736433559534853375835 | 否 | 2024-04-23 16:30:43.0 | 4C-ED-FB-63-F2-5B,00-00-00-00-00-00-E0@BFEBFBFF000906E9@303130303238323835362033202020202020,2020202057202d44435736433559534853375835 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误,请检查 | 2024-04-24 08:34:39 | 4C-ED-FB-63-F2-5B,00-00-00-00-00-00-E0@BFEBFBFF000906E9@303130303238323835362033202020202020,2020202057202d44435736433559534853375835 | 否   |   |  |
| 856 | 福建鼎万建设有限公司     | 2024-04-23 10:23:49.0 | 04-D9-F5-20-B7-8F@BFEBFBFF000906EB@50026B7782B0D883   | 否 | 2024-04-23 10:14:34.0 | 04-D9-F5-20-B7-8F@BFEBFBFF000906EB@50026B7782B0D883   | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误,请检查          | 2024-04-24 08:34:39   | 04-D9-F5-20-B7-8F@BFEBFBFF000906EB@50026B7782B0D883 | 否 |  |

|     |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 857 | 福建世纪亿达建设有限公司 | 2024-04-23 11:32:50.0 | 1C-87-2C-D1-9B-51@BF EBFBF F0003 06C3@22175 S8047 53, WD - WCC6Y 5NH62 3U | 否 | 2024-04-23 11:30:39.0 | 1C-87-2C-D1-9B-51@BF EBFBF F0003 06C3@22175 S8047 53, WD - WCC6Y 5NH62 3U                    | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:39 | 1C-87-2C-D1-9B-51@BF EBFBF F0003 06C3@22175 S8047 53, WD - WCC6Y 5NH62 3U | 否 |  |
| 858 | 中东基建科技集团有限公司 | 2024-04-23 16:55:27.0 | FC-34-97-6A-4D-F0@BF EBFBF F000A 0653@50026 B7380 F094C 4                 | 否 | 2024-04-23 09:55:32.0 | 94-DE-80-5F-0A-1C@BF EBFBF F0003 06A9@WX31A B3719 61, BT WL340 0088Y 160MG N, 461 1K1A2 FVLC | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:41:42 | FC-34-97-6A-4D-F0@BF EBFBF F000A 0653@50026 B7380 F094C 4                 | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |  |              |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|--|--------------|---|--|
| 859 | 福建中聚隆建设工程有限公司 | 2024-04-18 10:36:05.0 | C8-7F-54-A0-B0-A6, 8C-78-D7-D7-3F-6C, 8C-78-D7-D7-3F-6C@BF EBFBF F0009 0672@ 0000_ 0000_ 0000_ 0000_ 0026_ B768_ 64F6_ 6085. | 否 | 2024-04-18 10:33:36.0 | C8-7F-54-A0-B0-A6, 8C-78-D7-D7-3F-6C, 8C-78-D7-D7-3F-6C@BF EBFBF F0009 0672@ 0000_ 0000_ 0000_ 0000_ 0026_ B768_ 64F6_ 6085. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:52 | C8-7F-54-A0-B0-A6, 8C-78-D7-D7-3F-6C@BF EBFBF F0009 0672@ 0000_ 0000_ 0000_ 0000_ 0026_ B768_ 64F6_ 6085. | 否  |              |   |  |
| 860 | 福建鑫泷昇建设工程有限公司 | 2024-04-19 12:05:01.0 | 00-E2-69-52-21-BC@BF EBFBF F000A 0653@ WD-WCC6Y 5DHHP N6, AA 00000 00121 80000 139   | 否 | 2024-04-19 11:50:37.0 | 00-E2-69-52-21-BC@BF EBFBF F000A 0653@ WD-WCC6Y 5DHHP N6, AA 00000 00121 80000 139   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:38:11   | 84-E0-58-B0-CA-44@BF EBFBF F0009 06EB@ CM133 BH150 4039, WD-WCC6Y 2TXJA J2 | 否            |   |  |
| 861 | 福建黎旭建筑有限公司    | 2024-04-23 17:31:16.0 | F0-2F-74-B2-   | 否 | 2024-04-23 17:30:12.0 | F0-2F-74-B2-   | 否 |  |  |  |  |  |  |  |  |  |             |                     | 校验数据有误, 请   | 2024-04-24 08:33:47  | F0-2F-74-B2- | 否 |  |



|  |  |  |   |  |   |  |  |  |  |  |  |  |  |  |  |  |    |  |   |  |  |
|--|--|--|---|--|---|--|--|--|--|--|--|--|--|--|--|--|----|--|---|--|--|
|  |  |  | A9-<br>86@BF<br>EBFBF<br>F000A<br>0653@<br>30353<br>23042<br>36333<br>73038<br>46443<br>93434<br>31202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>30595<br>65039<br>4c4c4<br>c |  | A9-<br>86, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>30353<br>23042<br>36333<br>73038<br>46443<br>93434<br>31202<br>02020<br>23042<br>36333<br>73038<br>46443<br>93434<br>31202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>30595<br>65039<br>4c4c4<br>c |  |  |  |  |  |  |  |  |  |  |  | 检查 |  | A9-<br>86@BF<br>EBFBF<br>F000A<br>0653@<br>30353<br>23042<br>36333<br>73038<br>46443<br>93434<br>31202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>30595<br>65039<br>4c4c4<br>c |  |  |
|--|--|--|---|--|---|--|--|--|--|--|--|--|--|--|--|--|----|--|---|--|--|

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|--|
| 862 | 福建省鑫业建设发展有限公司 | 2024-04-22 11:19:39.0 | C8-7F-54-08-61-C6,00-00-00-00-00-00-00-00-0653@2020202057202d4443573643305946584a505244,3232313443303038343136312020202020202020200 | 否 | 2024-04-22 10:58:51.0 | C8-7F-54-08-61-C6,00-00-00-00-00-00-00-00-0653@2020202057202d4443573643305946584a505244,32323134433030383431363120202020202020200 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误,请检查 | 2024-04-24 08:34:07 | C8-7F-54-08-61-C6,00-00-00-00-00-00-00-00-0653@2020202057202d4443573643305946584a505244,323231344330303834313631202020202020200 | 否 |  |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|--|

|     |              |   |   |   |   |  |  |  |  |  |  |  |  |  |  |  |  |                     |   |   |  |
|-----|--------------|---|---|---|---|--|--|--|--|--|--|--|--|--|--|--|--|---------------------|---|---|--|
| 863 | 福建昌达工程技术有限公司 | 2024-04-23 15:16:12.0   | 否 | 2024-04-23 15:15:22.0   | 否 |  |  |  |  |  |  |  |  |  |  |  |  | 2024-04-24 08:37:15 | 校验数据有误，请检查  | 否 |  |
|     |              | EC-<br>D6-<br>8A-<br>BA-<br>97-<br>AA, 38<br>-C8-<br>04-<br>12-<br>B3-<br>D0, 38<br>-C8-<br>04-<br>12-<br>B3-<br>CF, 38<br>-C8-<br>04-<br>12-<br>B3-<br>CF, 38<br>-C8-<br>04-<br>12-<br>B3-<br>CF@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>197F_<br>1665. |   | 38-<br>C8-<br>04-<br>12-<br>B3-<br>CF, 38<br>-C8-<br>04-<br>12-<br>B3-<br>CF, BA<br>-C8-<br>04-<br>12-<br>B3-<br>CF, EC<br>-D6-<br>8A-<br>BA-<br>97-<br>AA, 38<br>-C8-<br>04-<br>12-<br>B3-<br>D0@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>197F_<br>1665. |   |  |  |  |  |  |  |  |  |  |  |  |  |                     | EC-<br>D6-<br>8A-<br>BA-<br>97-<br>AA, 38<br>-C8-<br>04-<br>12-<br>B3-<br>D0, 38<br>-C8-<br>04-<br>12-<br>B3-<br>CF, 38<br>-C8-<br>04-<br>12-<br>B3-<br>CF, 38<br>-C8-<br>04-<br>12-<br>B3-<br>CF@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>197F_<br>1665. |   |  |

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 864 | 福建朝日建设有限公司    | 2024-04-23 14:38:24.0 | 08-BF-B8-87-88-FE@BF EBFBF F000A 0653@WD-WCC6Y FKZ2E 26, KL 23829 OD5B1 944       | 否 | 2024-04-23 14:37:19.0 | 08-BF-B8-87-88-FE@BF EBFBF F000A 0653@WD-WCC6Y FKZ2E 26, KL 23829 OD5B1 944       | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:13 | 08-BF-B8-87-88-FE@BF EBFBF F000A 0653@WD-WCC6Y FKZ2E 26, KL 23829 OD5B1 944 | 否 |  |
| 865 | 福建省润秦建筑工程有限公司 | 2024-04-23 16:03:49.0 | E0-D5-5E-9B-DD-DF@BF EBFBF F0009 06E9@WD-WCC6Y 5XF57 SS, AA 00000 00000 00001 699 | 否 | 2024-04-23 15:13:33.0 | E0-D5-5E-9B-DD-DF@BF EBFBF F0009 06E9@WD-WCC6Y 5XF57 SS, AA 00000 00000 00001 699 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:34:39 | E0-D5-5E-9B-DD-DF@BF EBFBF F0009 06E9@WD-WCC6Y 5XF57 SS                     | 否 |  |

|     |                   |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |  |  |                            |                        |  |   |  |
|-----|-------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|--|---|--|
| 866 | 福建省富衢<br>建筑工程有限公司 | 2024-04-23<br>16:24:58.0 | B4-<br>2E-<br>99-<br>F1-<br>64-<br>02@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WC81Y<br>30347<br>89, 50<br>026B7<br>3809D<br>670B | 否 | 2024-04-23<br>16:23:22.0 | B4-<br>2E-<br>99-<br>F1-<br>64-<br>02@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WC81Y<br>30347<br>89, 50<br>026B7<br>3809D<br>670B | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:52:19 | B4-<br>2E-<br>99-<br>F1-<br>64-<br>02@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WC81Y<br>30347<br>89, 50<br>026B7<br>3809D<br>670B | 否 |  |
|-----|-------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|--|---|--|



|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |  |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|--|---|--|
| 868 | 福建金捷工程建设有限公司 | 2024-04-23 17:45:17.0 | 94-DE-80-BD-CC-40@BF<br>EBFBF<br>F0003<br>06A9@<br>MX_00<br>00000<br>00000<br>15415<br>,WD-<br>WCC3F<br>2FTZF<br>D6 | 否 | 2024-04-23 17:43:28.0 | 94-DE-80-BD-CC-40@BF<br>EBFBF<br>F0003<br>06A9@<br>MX_00<br>00000<br>00000<br>15415<br>,WD-<br>WCC3F<br>2FTZF<br>D6 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:41:28 | 94-DE-80-BD-CC-40@BF<br>EBFBF<br>F0003<br>06A9@<br>MX_00<br>00000<br>00000<br>15415<br>,WD-<br>WCC3F<br>2FTZF<br>D6 | 否  |   |  |
| 869 | 福建中巧建设工程有限公司 | 2024-04-23 11:28:24.0 | 04-92-26-BF-FB-A9@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>2ZL57<br>YJ                                      | 否 | 2024-04-23 11:26:24.0 | 04-92-26-BF-FB-A9@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>2ZL57<br>YJ                                      | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:40:27   | 04-92-26-BF-FB-A9@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>2ZL57<br>YJ | 否 |  |

|     |                   |                               |   |   |                               |  |   |  |  |  |  |  |  |  |  |                             |                             |   |   |  |  |  |  |
|-----|-------------------|-------------------------------|---|---|-------------------------------|--|---|--|--|--|--|--|--|--|--|-----------------------------|-----------------------------|---|---|--|--|--|--|
| 870 | 福建省筑明<br>建设工程有限公司 | 2024-04-19<br>15:35:<br>:55.0 | 00-<br>E0-<br>4C-<br>68-<br>3D-<br>11, 74<br>-D4-<br>35-<br>A0-<br>44-<br>CB@BF<br>EBFBF<br>F0003<br>06C3@<br>50026<br>B7380<br>63AAD<br>3, WD-<br>WCC6Y<br>2ZDJ8<br>7P | 否 | 2024-04-19<br>15:20:<br>:46.0 | 00-<br>E0-<br>4C-<br>68-<br>3D-<br>11, 74<br>-D4-<br>35-<br>A0-<br>44-<br>CB, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>50026<br>B7380<br>63AAD<br>3, WD-<br>WCC6Y<br>2ZDJ8<br>7P | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>, 请<br>检查 | 2024-04-24<br>08:33:<br>:34 | 00-<br>E0-<br>4C-<br>68-<br>3D-<br>11, 74<br>-D4-<br>35-<br>A0-<br>44-<br>CB@BF<br>EBFBF<br>F0003<br>06C3@<br>50026<br>B7380<br>63AAD<br>3, WD-<br>WCC6Y<br>2ZDJ8<br>7P | 否 |  |  |  |  |
|-----|-------------------|-------------------------------|---|---|-------------------------------|--|---|--|--|--|--|--|--|--|--|-----------------------------|-----------------------------|---|---|--|--|--|--|



|     |                         |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |  |                         |                                |   |   |  |
|-----|-------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|---|---|--|
| 871 | 中建弘锐<br>(福建) 建<br>设有限公司 | 2024-<br>04-22<br>16:02<br>:37.0 | 18-<br>31-<br>BF-<br>B9-<br>CB-<br>F9@BF<br>EBFBF<br>F0009<br>06E9@<br>57543<br>83132<br>35353<br>43734<br>36333<br>23820<br>34202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>35594<br>65a58<br>5a5a4<br>8 | 否 | 2024-<br>04-22<br>15:59<br>:42.0 | 18-<br>31-<br>BF-<br>B9-<br>CB-<br>F9, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>57543<br>83132<br>35353<br>43734<br>36333<br>23820<br>34202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>35594<br>65a58<br>5a5a4<br>8 | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:34<br>:42 | 18-<br>31-<br>BF-<br>B9-<br>CB-<br>F9@BF<br>EBFBF<br>F0009<br>06E9@<br>57543<br>83132<br>35353<br>43734<br>36333<br>23820<br>34202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>35594<br>65a58<br>5a5a4<br>8 | 否 |  |
|-----|-------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|---|---|--|

|     |                       |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |                         |                            |   |   |  |
|-----|-----------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|-------------------------|----------------------------|---|---|--|
| 872 | 福建省万吉<br>工程管理有<br>限公司 | 2024-04-23<br>17:18<br>:35.0 | 8C-<br>17-<br>59-<br>7C-<br>54-<br>CF, 8C<br>-17-<br>59-<br>7C-<br>54-<br>D0, 8E<br>-17-<br>59-<br>7C-<br>54-<br>D0, 8E<br>-17-<br>59-<br>7C-<br>54-<br>CF, F4<br>-6B-<br>8C-<br>D1-<br>0E-<br>C9@BF<br>EBFBF<br>F0009<br>0675@<br>5CDF_<br>B802_<br>B0F0_<br>053D. | 否 | 2024-04-23<br>09:57<br>:53.0 | 8C-<br>17-<br>59-<br>7C-<br>54-<br>CF, 8C<br>-17-<br>59-<br>7C-<br>54-<br>D0, 8E<br>-17-<br>59-<br>7C-<br>54-<br>D0, 8E<br>-17-<br>59-<br>7C-<br>54-<br>CF, F4<br>-6B-<br>8C-<br>D1-<br>0E-<br>C9@BF<br>EBFBF<br>F0009<br>0675@<br>5CDF_<br>B802_<br>B0F0_<br>053D. | 否 |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:59<br>:48 | F4-<br>6B-<br>8C-<br>D1-<br>0E-<br>C9, 8C<br>-17-<br>59-<br>7C-<br>54-<br>CF, 8C<br>-17-<br>59-<br>7C-<br>54-<br>CF@BF<br>EBFBF<br>F0009<br>0675@<br>5CDF_<br>B802_<br>B0F0_<br>053D. | 否 |  |
| 873 | 福建旭之茂<br>建筑工程有<br>限公司 | 2024-04-22<br>17:26<br>:26.0 | A8-<br>5E-<br>45-<br>31-<br>2F-<br>00@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>6JX6U<br>ZF  | 否 | 2024-04-22<br>17:11<br>:47.0 | A8-<br>5E-<br>45-<br>31-<br>2F-<br>00, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>6JX6U<br>ZF   | 否 |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:39<br>:45 | A8-<br>5E-<br>45-<br>31-<br>2F-<br>00@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>6JX6U<br>ZF  | 否 |  |

|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 874 | 福建省德融建设有限公司  | 2024-04-23 12:59:15.0 | B4-2E-99-9F-7F-4D@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>3HPVP<br>DP, AA<br>00000<br>00000<br>00006<br>148 | 否 | 2024-04-23 12:57:56.0 | B4-2E-99-9F-7F-4D@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>3HPVP<br>DP, AA<br>00000<br>00000<br>00006<br>148 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:36:54 | B4-2E-99-9F-7F-4D@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>3HPVP<br>DP, AA<br>00000<br>00000<br>00006<br>148 | 否 |  |
| 875 | 福建茂裕建设工程有限公司 | 2024-04-23 10:45:52.0 | D8-5E-D3-69-86-AF@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7VL8F<br>FE, HX<br>D0011<br>6515                  | 否 | 2024-04-23 10:44:35.0 | D8-5E-D3-69-86-AF@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7VL8F<br>FE, HX<br>D0011<br>6515                  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:45:47 | D8-5E-D3-69-86-AF@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7VL8F<br>FE, HX<br>D0011<br>6515                  | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 876 | 福建国辉建设工程有限公司  | 2024-04-23 17:32:37.0 | 00-E0-4C-6A-60-FC@BF EBFBF F000A 0653@ 6479_ A75B_ 00CO_ 100F. ,WD- WCC6Y OZEPJ Z1     | 否 | 2024-04-23 17:30:41.0 | 00-E0-4C-6A-60-FC@BF EBFBF F000A 0653@ 6479_ A75B_ 00CO_ 100F. ,WD- WCC6Y OZEPJ Z1     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:23 | 00-E0-4C-6A-60-FC@BF EBFBF F000A 0653@ 6479_ A75B_ 00CO_ 100F. ,WD- WCC6Y OZEPJ Z1     | 否 |  |
| 877 | 福建恒鼎信建设发展有限公司 | 2024-04-22 11:19:39.0 | 00-E0-70-E7-6E-E5@BF EBFBF F000A 0653@ 20211 02700 274                                 | 否 | 2024-04-22 09:45:10.0 | 00-E0-70-E7-6E-E5@BF EBFBF F000A 0653@ 20211 02700 274                                 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:40:17 | 00-E0-70-E7-6E-E5@BF EBFBF F000A 0653@ 20211 02700 274                                 | 否 |  |
| 878 | 福建承颂建设工程有限公司  | 2024-04-22 09:56:25.0 | 58-11-22-0F-B5-DC@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E04_ 580A. | 否 | 2024-04-19 08:53:23.0 | 58-11-22-0F-B5-DC@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E04_ 580A. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:15 | 58-11-22-0F-B5-DC@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E04_ 580A. | 否 |  |

|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 879 | 福建誉丰建设工程有限公司 | 2024-04-23 11:30:08.0 | E0-<br>D5-<br>5E-<br>52-<br>0B-<br>C0@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01580<br>, WD-<br>WCANM<br>H2151<br>79 | 否 | 2024-04-23 11:26:46.0 | E0-<br>D5-<br>5E-<br>52-<br>0B-<br>C0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01580<br>, WD-<br>WCANM<br>H2151<br>79 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:31:42 | E0-<br>D5-<br>5E-<br>52-<br>0B-<br>C0@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01580<br>, WD-<br>WCANM<br>H2151<br>79 | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|



|     |                |                                  |  |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |  |                                |  |   |  |
|-----|----------------|----------------------------------|--|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|--------------------------------|--|---|--|
|     |                |                                  | 36303<br>54637<br>30383<br>54131<br>39363<br>03030<br>30373<br>13034   |   |                                  | 00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>36303<br>54637<br>30383<br>54131<br>39363<br>03030<br>30373<br>13034 |   |  |  |  |  |  |  |  |  |  |  | 36303<br>54637<br>30383<br>54131<br>39363<br>03030<br>30373<br>13034 |                                |  |   |  |
| 882 | 安徽敬泽建<br>设有限公司 | 2024-<br>04-18<br>08:32<br>:29.0 | 30-<br>5A-<br>3A-<br>4A-<br>EC-<br>DA@BF<br>EBFBF<br>F0003<br>06C3@<br>50026<br>B7380<br>E0B31<br>C, WD-<br>WMC2E<br>OM9M3<br>CX | 否 | 2024-<br>04-17<br>11:46<br>:37.0 | 30-<br>5A-<br>3A-<br>4A-<br>EC-<br>DA@BF<br>EBFBF<br>F0003<br>06C3@<br>50026<br>B7380<br>E0B31<br>C, WD-<br>WMC2E<br>OM9M3<br>CX  | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有错<br>误，<br>请<br>查<br>检                                  | 2024-<br>04-24<br>08:31<br>:53 | 30-<br>5A-<br>3A-<br>4A-<br>EC-<br>DA@BF<br>EBFBF<br>F0003<br>06C3@<br>50026<br>B7380<br>E0B31<br>C, WD-<br>WMC2E<br>OM9M3<br>CX | 否 |  |

|     |                         |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                              |                                |  |   |  |
|-----|-------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------------------------|--------------------------------|--|---|--|
| 883 | 福建省亿洲<br>工程建设发<br>展有限公司 | 2024-<br>04-23<br>19:26<br>:50.0 | 58-<br>11-<br>22-<br>0F-<br>B4-<br>91@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Z<br>2NT81<br>R1, 50<br>026B7<br>3816B<br>5A1D | 否 | 2024-<br>04-23<br>19:24<br>:34.0 | 58-<br>11-<br>22-<br>0F-<br>B4-<br>91@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Z<br>2NT81<br>R1, 50<br>026B7<br>3816B<br>5A1D | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:34<br>:07 | 58-<br>11-<br>22-<br>0F-<br>B4-<br>91@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Z<br>2NT81<br>R1, 50<br>026B7<br>3816B<br>5A1D | 否 |  |
| 884 | 新通路桥建<br>设有限公司          | 2024-<br>04-23<br>10:25<br>:22.0 | 58-<br>11-<br>22-<br>07-<br>65-<br>3C@BF<br>EBFBF<br>F000A<br>0653@<br>W9AS2<br>E6P, 2<br>02204<br>16015<br>72                   | 否 | 2024-<br>04-22<br>08:41<br>:42.0 | 58-<br>11-<br>22-<br>07-<br>65-<br>3C@BF<br>EBFBF<br>F000A<br>0653@<br>W9AS2<br>E6P, 2<br>02204<br>16015<br>72                   | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:32<br>:09 | 58-<br>11-<br>22-<br>07-<br>65-<br>3C@BF<br>EBFBF<br>F000A<br>0653@<br>W9AS2<br>E6P, 2<br>02204<br>16015<br>72                   | 否 |  |



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 885 | 四川鼎恒建设工程有限公司 | 2024-04-23 17:23:32.0 | 08-BF-B8-82-96-50@BF EBFBF F0009 0675@ 20051 73882 02975 27BA3 ,0000 _0000 _0000 _0000 _0026 _B738 _245B _61A5 . | 否 | 2024-04-23 17:20:22.0 | 08-BF-B8-82-96-50@BF EBFBF F0009 0675@ 20051 73882 02975 27BA3 ,0000 _0000 _0000 _0000 _0026 _B738 _245B _61A5 . | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:17 | 08-BF-B8-82-96-50@BF EBFBF F0009 0675@ 20051 73882 02975 27BA3 ,0000 _0000 _0000 _0000 _0026 _B738 _245B _61A5 . | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|---|--|
| 886 | 福建润川建设工程有限公司  | 2024-04-23 10:50:23.0 | 8C-1D-96-96-DA-1F, EC-D6-8A-B1-33-14, 8C-1D-96-96-DA-1B, 8C-1D-96-96-DA-1B@BF-EBFBF-F0009-0675@12NMY-3AMS, 30083-13340-1 | 否 | 2024-04-23 10:47:52.0 | 8C-1D-96-96-DA-1B, 8C-1D-96-96-DA-1B, EC-D6-8A-B1-33-14, 8C-1D-96-96-DA-1F@BF-EBFBF-F0009-0675@12NMY-3AMS, 30083-13340-1 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:35:06 | 8C-1D-96-96-DA-1F, EC-D6-8A-B1-33-14, 8C-1D-96-96-DA-1B, 8C-1D-96-96-DA-1B@BF-EBFBF-F0009-0675@12NMY-3AMS, 30083-13340-1 | 否   |   |  |
| 887 | 福建新发字建设工程有限公司 | 2024-04-19 11:45:36.0 | 0C-9D-92-77-8C-8F@BF-EBFBF-F0009-06EA@WD-WCC6Y-1HCSZ-32  | 否 | 2024-04-19 09:44:03.0 | 0C-9D-92-77-8C-8F@BF-EBFBF-F0009-06EA@WD-WCC6Y-1HCSZ-32  | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:55:23  | 0C-9D-92-77-8C-8F@BF-EBFBF-F0009-06EA@WD-WCC6Y-1HCSZ-32 | 否 |  |

|     |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|--|
| 888 | 福建凯能电力有限公司 | 2024-04-23 09:49:18.0 | 30-<br>9C-<br>23-<br>5E-<br>5C-<br>7A@BF<br>EBFBF<br>F0009<br>06E9@<br>41413<br>03030<br>30303<br>03030<br>30333<br>03435<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>31595<br>5455a<br>48413<br>5 | 否 | 2024-04-23 09:45:28.0 | 30-<br>9C-<br>23-<br>5E-<br>5C-<br>7A, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>06E9@<br>41413<br>03030<br>03030<br>03030<br>03030<br>30303<br>03030<br>03435<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>31595<br>5455a<br>48413<br>5 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:31:47 | 30-<br>9C-<br>23-<br>5E-<br>5C-<br>7A@BF<br>EBFBF<br>F0009<br>06E9@<br>41413<br>03030<br>30303<br>03030<br>30333<br>03435<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>31595<br>5455a<br>48413<br>5 | 否 |  |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|--|

|     |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |  |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|--|---|--|
| 889 | 福建隆捷建设有限公司   | 2024-04-23 09:12:28.0 | 00-E2-69-57-22-46@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7DCT0<br>47,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 | 2024-04-23 09:11:22.0 | 00-E2-69-57-22-46@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7DCT0<br>47,00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:53 | 00-E2-69-57-22-46@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7DCT0<br>47,00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否  |   |  |
| 890 | 福建邗昌建设工程有限公司 | 2024-04-23 16:41:40.0 | 00-E0-4C-0B-7B-1C@BF<br>EBFBF<br>F000A<br>0653@<br>EAGET<br>20220<br>118R0<br>1718,<br>WD-<br>WCC6Y<br>5ATH1<br>E2                                      | 否 | 2024-04-23 16:40:19.0 | 00-E0-4C-0B-7B-1C@BF<br>EBFBF<br>F000A<br>0653@<br>EAGET<br>20220<br>118R0<br>1718,<br>WD-<br>WCC6Y<br>5ATH1<br>E2                             | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:33:27  | 00-E0-4C-0B-7B-1C@BF<br>EBFBF<br>F000A<br>0653@<br>EAGET<br>20220<br>118R0<br>1718,<br>WD-<br>WCC6Y<br>5ATH1<br>E2 | 否 |  |

|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 891 | 福建省赐成建筑工程有限公司  | 2024-04-23 15:05:35.0 | 00-<br>E0-<br>1F-<br>44-<br>00-<br>E3@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WC81Y<br>76933<br>74, LC<br>RS582<br>3BBT0<br>286 | 否 | 2024-04-23 15:04:39.0 | 00-<br>E0-<br>1F-<br>44-<br>00-<br>E3@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WC81Y<br>76933<br>74, LC<br>RS582<br>3BBT0<br>286 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:23 | 00-<br>E0-<br>1F-<br>44-<br>00-<br>E3@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WC81Y<br>76933<br>74, LC<br>RS582<br>3BBT0<br>286 | 否 |  |
| 892 | 福建金祥鼎业建设工程有限公司 | 2024-04-23 15:11:29.0 | 2C-<br>FD-<br>A1-<br>E3-<br>57-<br>97@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>6HN2U<br>7R, MG<br>23084<br>07360<br>29  | 否 | 2024-04-23 15:07:08.0 | 2C-<br>FD-<br>A1-<br>E3-<br>57-<br>97@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>6HN2U<br>7R, MG<br>23084<br>07360<br>29  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:40:37 | 2C-<br>FD-<br>A1-<br>E3-<br>57-<br>97@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>6HN2U<br>7R, MG<br>23084<br>07360<br>29  | 否 |  |



|     |            |                       |   |   |                       |   |   |  |  |  |            |                     |   |  |   |  |  |
|-----|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|------------|---------------------|---|--|---|--|--|
| 894 | 福建联博建设有限公司 | 2024-04-19 08:55:54.0 | 48-F3-17-01-92-DF@BFBFBFF000A0653@CM317BH1538963,626S27XMS  | 否 | 2024-04-19 08:53:31.0 | 48-F3-17-01-92-DF@BFBFBFF000A0653@CM317BH1538963,626S27XMS  | 否 |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:37:39   | 48-F3-17-01-92-DF@BFBFBFF000A0653@CM317BH1538963,626S27XMS | 否 |  |  |
| 895 | 福建丰投建设有限公司 | 2024-04-19 11:31:31.0 | 24-4B-FE-8B-18-1C@BFBFBFF000906EB@43523032323731333336314133382033202020,2020202057202d444357364336594e43384e5945 | 否 | 2024-04-19 10:37:59.0 | 24-4B-FE-8B-18-1C,00-00-00-00-00-00-00-00-00-06EB@43523032323731333336314133382033202020,2020202057202d44435,2020202057202d444357364336594e43384e5945 | 否 |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:46 | 24-4B-FE-8B-18-1C@BFBFBFF000906EB@43523032323731333336314133382033202020,2020202057202d444357364336594e43384e5945 | 否  |   |  |  |

|     |                        |                                  |  |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                        |                                |   |   |  |
|-----|------------------------|----------------------------------|--|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------------------|--------------------------------|---|---|--|
| 896 | 福建九九路<br>桥建设发展<br>有限公司 | 2024-<br>04-23<br>14:40<br>:21.0 | FC-<br>34-<br>97-<br>C6-<br>00-<br>59@BF<br>EBFBF<br>F000A<br>0653@<br>30044<br>34609<br>8   | 否 | 2024-<br>04-23<br>10:23<br>:36.0 | FC-<br>34-<br>97-<br>C6-<br>00-<br>59@BF<br>EBFBF<br>F000A<br>0653@<br>30044<br>34609<br>8                                      | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:35<br>:24 | FC-<br>34-<br>97-<br>C6-<br>00-<br>59@BF<br>EBFBF<br>F000A<br>0653@<br>30044<br>34609<br>8                                      | 否 |  |
| 897 | 福建京港建<br>工有限公司         | 2024-<br>04-23<br>11:57<br>:14.0 | B4-<br>2E-<br>99-<br>DD-<br>1E-<br>C3@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>9A1B9<br>4,51C<br>50C7D<br>1608,<br>WD-<br>WCC6Y<br>7RE59<br>0S | 否 | 2024-<br>04-22<br>14:13<br>:35.0 | B4-<br>2E-<br>99-<br>DD-<br>1E-<br>C3@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>9A1B9<br>4,WD-<br>WCC6Y<br>7RE59<br>0S | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:34<br>:13 | B4-<br>2E-<br>99-<br>DD-<br>1E-<br>C3@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>9A1B9<br>4,WD-<br>WCC6Y<br>7RE59<br>0S | 否 |  |



|     |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 898 | 福建丁亚建设工程有限公司 | 2024-04-22 14:57:52.0 | 24-4B-FE-48-10-33,00-00-00-00-00-33@BF EBFBF F0009 06EA@ 41543 03230 38353 53833 30313 43920 37202 02020,2020 20205 7202d 44435 73643 37594 5524e 35583 1 | 否 | 2024-04-22 14:43:43.0 | 24-4B-FE-48-10-33,00-00-00-00-00-E0,00 -00-00-00-00-00-00-00-00-E0@BF EBFBF F0009 06EA@ 41543 03230 38353 53833 30313 43920 37202 02020,2020 20205 7202d 44435 73643 37594 5524e 35583 1 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:31:07 | 24-4B-FE-48-10-33@BF EBFBF F0009 06EA@ 41543 03230 38353 53833 30313 43920 37202 02020,2020 20205 7202d 44435 73643 37594 5524e 35583 1 | 否 |  |
|-----|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|--|---|--|
| 899 | 福建恒舟建筑工程有限公司  | 2024-04-21 14:03:27.0 | 2C-F0-5D-EE-48-E0@BF EBFBF F000A 0671@ 0000_ 0000_ 0000_ 0000_ 0000_ 0100_ 0000_ 0000. | 否 | 2024-04-21 14:02:03.0 | 2C-F0-5D-EE-48-E0@BF EBFBF F000A 0671@ 0000_ 0000_ 0000_ 0000_ 0000_ 0100_ 0000_ 0000. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:39:07 | 2C-F0-5D-EE-48-E0@BF EBFBF F000A 0671@ 0000_ 0000_ 0000_ 0000_ 0000_ 0100_ 0000_ 0000. | 否  |   |  |
| 900 | 福建省易灿建设工程有限公司 | 2024-04-22 12:04:17.0 | 04-7C-16-DD-46-D7@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E1C_ F31D. | 否 | 2024-04-22 11:50:37.0 | 04-7C-16-DD-46-D7@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E1C_ F31D. | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:43:04  | 04-7C-16-DD-46-D7@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E1C_ F31D. | 否 |  |
| 901 | 福建汇航建设有限公司    | 2024-04-22 10:32:34.0 | F4-B5-20-59-61-B0@17 8BFBF F00A5 0F00@ 0000_ 0000_ 0000_ 0000_ 0000_                   | 否 | 2024-04-22 10:10:36.0 | F4-B5-20-59-61-B0@17 8BFBF F00A5 0F00@ 0000_ 0000_ 0000_ 0000_ 0000_                   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:42:46  | F4-B5-20-59-61-B0@17 8BFBF F00A5 0F00@ 0000_ 0000_ 0000_ 0000_ 0000_                   | 否 |  |

|     |                |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                            |  |   |  |
|-----|----------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|----------------------------|--|---|--|
|     |                |                       | 0000_0000_0832.,0000000005   |   |                       | 0000_0000_0832.,0000000005  |   |  |  |  |  |  |  |  |  |  |  |             | 0000_0000_0832.,0000000005 |  |   |  |
| 902 | 福建鑫中泓瑞建设工程有限公司 | 2024-04-23 16:11:57.0 | 7C-10-C9-23-72-55@BFEBFBFF000906EB@303334303334313533342036202020202020,2020202057202d4443573643375953534e48445a | 否 | 2024-04-22 14:40:38.0 | 7C-10-C9-23-72-55,00-00-00-00-00-00-06EB@E0@BFEBFBFF000906EB@3033343033343135333420362020202020,2020202057202d44435,202073643202057202d4443573643375953534e48445a | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误,请检查 | 2024-04-24 08:31:51        | 7C-10-C9-23-72-55@BFEBFBFF000906EB@303334303334313533342036202020202020,2020202057202d4443573643375953534e48445a | 否 |  |

|     |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 903 | 福建华凌建设工程发展有限公司 | 2024-04-23 15:58:02.0 | 88-D7-F6-3E-AF-7E,00-00-00-00-00-06E3@WCC6Y4XHSEFK                         | 否 | 2024-04-23 15:55:19.0 | 88-D7-F6-3E-AF-7E,00-00-00-00-00-06E3@WCC6Y4XHSEFK                         | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:54:37 | 88-D7-F6-3E-AF-7E@BFEBFBF000506E3@WCC6Y4XHSEFK                             | 否 |  |
| 904 | 福建中隳建设发展有限公司   | 2024-04-22 16:27:42.0 | 74-56-3C-A9-E1-CD@BFEBFBF00090675@0000_0000_0000_0000_0026_B738_245B_AC15. | 否 | 2024-04-22 16:19:25.0 | 74-56-3C-A9-E1-CD@BFEBFBF00090675@0000_0000_0000_0000_0026_B738_245B_AC15. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:31:36 | 74-56-3C-A9-E1-CD@BFEBFBF00090675@0000_0000_0000_0000_0026_B738_245B_AC15. | 否 |  |



|     |            |   |   |   |   |  |  |  |  |  |  |  |  |  |  |  |             |   |   |  |
|-----|------------|---|---|---|---|--|--|--|--|--|--|--|--|--|--|--|-------------|---|---|--|
| 908 | 福建鑫盛建设有限公司 | 2024-04-22 14:14:44.0<br>00- E2- 69- 75- CD- D6, BC -5C- 17- EA- 9A- D8, BE -5C- 17- EA- 9A- D8, FE -5C- 17- EA- 9A- D7@BF EBFBF F0009 0675@ WX82A 71J9H R2, 64 79_A7 80_50 00_02 19. | 否 | 2024-04-19 16:02:06.0<br>00- E2- 69- 75- CD- D6, BC -5C- 17- EA- 9A- D8, BE -5C- 17- EA- 9A- D8, FE -5C- 17- EA- 9A- D7@BF EBFBF F0009 0675@ WX82A 71J9H R2, 64 79_A7 80_50 00_02 19. | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:40<br>00- E2- 69- 75- CD- D6, BC -5C- 17- EA- 9A- D7, BC -5C- 17- EA- 9A- D8, BE -5C- 17- EA- 9A- D8, BE -5C- 17- EA- 9A- D8@BF EBFBF F0009 0675@ WX82A 71J9H R2, 64 79_A7 80_50 00_02 19. | 否 |  |
|-----|------------|---|---|---|---|--|--|--|--|--|--|--|--|--|--|--|-------------|---|---|--|

|     |              |                          |   |   |                          |  |   |  |  |  |  |  |  |  |  |  |  |                     |                        |  |   |   |  |
|-----|--------------|--------------------------|---|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|--|---------------------|------------------------|--|---|---|--|
| 909 | 福建晟鑫建设工程有限公司 | 2024-04-23<br>10:26:50.0 | F4-<br>B5-<br>20-<br>25-<br>78-<br>61@BF<br>EBFBF<br>F0009<br>06EB@<br>K3919<br>6R003<br>927, W<br>D-<br>WCAYU<br>KT449<br>94 | 否 | 2024-04-22<br>16:34:00.0 | F4-<br>B5-<br>20-<br>25-<br>78-<br>61, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>K3919<br>6R003<br>927, W<br>D-<br>WCAYU<br>KT449<br>94 | 否 |  |  |  |  |  |  |  |  |  |  |                     | 校验数据有<br>误, 请查<br>查    | 2024-04-24<br>08:37:28   | F4-<br>B5-<br>20-<br>25-<br>78-<br>61@BF<br>EBFBF<br>F0009<br>06EB@<br>K3919<br>6R003<br>927, W<br>D-<br>WCAYU<br>KT449<br>94 | 否 |  |
| 910 | 福建上亿建筑工程有限公司 | 2024-04-23<br>10:02:40.0 | FC-<br>34-<br>97-<br>BF-<br>79-<br>E4@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>3FANR<br>YA, A1<br>90115<br>01469      | 否 | 2024-04-23<br>09:59:35.0 | FC-<br>34-<br>97-<br>BF-<br>79-<br>E4@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>3FANR<br>YA, A1<br>90115<br>01469   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>查 | 2024-04-24<br>08:39:42 | FC-<br>34-<br>97-<br>BF-<br>79-<br>E4@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>3FANR<br>YA, A1<br>90115<br>01469 | 否   |   |  |

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 911 | 福建省森城建设有限公司   | 2024-04-23 18:29:44.0 | 00-<br>E0-<br>4C-<br>70-<br>7A-<br>CE@BF<br>EBFBF<br>F000A<br>0653@<br>22051<br>21700<br>00001<br>255, E<br>E03DC<br>5151E<br>8, 93S<br>B701A<br>K0Z5 | 否 | 2024-04-23 12:24:47.0 | 00-<br>E0-<br>4C-<br>70-<br>7A-<br>CE@BF<br>EBFBF<br>F000A<br>0653@<br>22051<br>21700<br>00001<br>255, E<br>E03DC<br>5151E<br>8, 93S<br>B701A<br>K0Z5   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:44:49 | 00-<br>E0-<br>4C-<br>70-<br>7A-<br>CE@BF<br>EBFBF<br>F000A<br>0653@<br>22051<br>21700<br>00001<br>255, E<br>E03DC<br>5151E<br>8, 93S<br>B701A<br>K0Z5 | 否 |  |
| 912 | 河南省强基建筑工程有限公司 | 2024-04-23 10:22:09.0 | F0-<br>2F-<br>74-<br>16-<br>F6-<br>40@BF<br>EBFBF<br>F0009<br>06EA@<br>30333<br>13033<br>34343<br>63830<br>20332<br>02020<br>20202<br>02020           | 否 | 2024-04-23 10:20:38.0 | F0-<br>2F-<br>74-<br>16-<br>F6-<br>40, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30333<br>13033<br>34343<br>63830<br>20332<br>02020<br>20202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:31:46 | F0-<br>2F-<br>74-<br>16-<br>F6-<br>40@BF<br>EBFBF<br>F0009<br>06EA@<br>30333<br>13033<br>34343<br>63830<br>20332<br>02020<br>20202<br>02020           | 否 |  |



|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 913 | 福建楚坤建设发展有限公司 | 2024-04-22 15:04:05.0 | C8-7F-54-OB-AD-AA@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E1C_ 24A8.                    | 否 | 2024-04-22 14:46:08.0 | C8-7F-54-OB-AD-AA@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E1C_ 24A8.                    | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:19 | C8-7F-54-OB-AD-AA@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E1C_ 24A8.  | 否 |  |
| 914 | 八闽建设有限公司     | 2024-04-23 17:01:02.0 | 08-6A-C5-12-6C-A3, 08 -6A-C5-12-6C-9F, 08 -6A-C5-12-6C-AO@BF EBFBF F0008 06C1@ LEA56 72002 694_0000 0001. | 否 | 2024-04-22 16:46:43.0 | 08-6A-C5-12-6C-A0, 0A -6A-C5-12-6C-9F, 08 -6A-C5-12-6C-A3@BF EBFBF F0008 06C1@ LEA56 72002 694_0000 0001. | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:13 | 08-6A-C5-12-6C-A3, 08 -6A-C5-12-6C-9F, 08 -6A-C5-12-6C-A0, 0A -6A-C5-12-6C-9F@BF EBFBF F0008 06C1@ LEA56 72002 694_0000 0001. | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 915 | 福建省五洲建设集团有限公司 | 2024-04-23 23:30:15.0 | 38-2C-4A-64-5C-A0@BF EBFBF F0003 06C3@50026 B774A 0A4B9 9, WD-WCC6Y 5YL1X D1 | 否 | 2024-04-23 21:00:33.0 | 38-2C-4A-64-5C-A0@BF EBFBF F0003 06C3@50026 B774A 0A4B9 9, WD-WCC6Y 5YL1X D1 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:47 | 38-2C-4A-64-5C-A0@BF EBFBF F0003 06C3@50026 B774A 0A4B9 9, WD-WCC6Y 5YL1X D1 | 否 |  |
| 916 | 福建腾祥建设工程有限公司  | 2024-04-23 14:28:45.0 | 40-B0-76-7D-5B-D1@BF EBFBF F0009 06EA@WCC6Y 4SERT 74, 19 207S4 47609         | 否 | 2024-04-22 11:20:59.0 | 40-B0-76-7D-5B-D1@BF EBFBF F0009 06EA@WCC6Y 4SERT 74, 19 207S4 47609         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:17 | 40-B0-76-7D-5B-D1@BF EBFBF F0009 06EA@WCC6Y 4SERT 74, 19 207S4 47609         | 否 |  |
| 917 | 福建鼎轩建设有限公司    | 2024-04-23 23:42:39.0 | 48-F3-17-01-D4-F2@BF EBFBF F000A 0653@50026 B7380 CC37E 6, WD-WCC6Y 3FE1F 9P | 否 | 2024-04-23 23:40:38.0 | 48-F3-17-01-D4-F2@BF EBFBF F000A 0653@50026 B7380 CC37E 6, WD-WCC6Y 3FE1F 9P | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:43 | 48-F3-17-01-D4-F2@BF EBFBF F000A 0653@50026 B7380 CC37E 6, WD-WCC6Y 3FE1F 9P | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|---|--|
| 918 | 福建东易建设工程有限公司  | 2024-04-22 14:37:12.0 | 24-4B-FE-5D-7F-9D@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>2XKDH<br>HY, AA<br>00000<br>00000<br>00003<br>046 | 否 | 2024-04-22 11:04:54.0 | 24-4B-FE-5D-7F-9D@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>2XKDH<br>HY, AA<br>00000<br>00000<br>00003<br>046 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:34:10 | 24-4B-FE-5D-7F-9D@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>2XKDH<br>HY, AA<br>00000<br>00000<br>00003<br>046 | 否   |   |  |
| 919 | 福建远涯通建设工程有限公司 | 2024-04-22 16:33:23.0 | 50-EB-F6-1F-6B-20@BF<br>EBFBF<br>F000A<br>0653@<br>ML288<br>5R015<br>9180S<br>58C                                    | 否 | 2024-04-22 16:32:22.0 | 50-EB-F6-1F-6B-20@BF<br>EBFBF<br>F000A<br>0653@<br>ML288<br>5R015<br>9180S<br>58C                                    | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:35:40  | 50-EB-F6-1F-6B-20@BF<br>EBFBF<br>F000A<br>0653@<br>ML288<br>5R015<br>9180S<br>58C | 否 |  |

|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|--|
| 920 | 福建欣时代建设工程有限公司 | 2024-04-23 14:47:00.0 | D8-<br>BB-<br>C1-<br>4D-<br>71-<br>F0@BF<br>EBFBF<br>F000A<br>0653@<br>30353<br>23042<br>36333<br>73138<br>34333<br>63541<br>33202<br>02020 | 否 | 2024-04-23 14:44:39.0 | D8-<br>BB-<br>C1-<br>4D-<br>71-<br>F0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>30353<br>23042<br>36333<br>73138<br>34333<br>63541<br>33202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:51 | D8-<br>BB-<br>C1-<br>4D-<br>71-<br>F0@BF<br>EBFBF<br>F000A<br>0653@<br>30353<br>23042<br>36333<br>73138<br>34333<br>63541<br>33202<br>02020 | 否 |  |  |
| 921 | 福建谦益工程管理有限公司  | 2024-04-23 09:57:44.0 | 58-<br>11-<br>22-<br>C0-<br>8B-<br>ED@BF<br>EBFBF<br>F0009<br>0672@<br>WD-<br>WCC6Y<br>H3DRA<br>J2, 50<br>026B7<br>381AC<br>9C28            | 否 | 2024-04-23 09:56:11.0 | 58-<br>11-<br>22-<br>C0-<br>8B-<br>ED@BF<br>EBFBF<br>F0009<br>0672@<br>WD-<br>WCC6Y<br>H3DRA<br>J2, 50<br>026B7<br>381AC<br>9C28  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:39:15 | 58-<br>11-<br>22-<br>C0-<br>8B-<br>ED@BF<br>EBFBF<br>F0009<br>0672@<br>WD-<br>WCC6Y<br>H3DRA<br>J2, 50<br>026B7<br>381AC<br>9C28            | 否 |  |  |



|     |                      |                              |   |   |                              |  |   |  |  |  |  |  |  |  |  |  |                         |                            |   |  |   |  |
|-----|----------------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------------------|----------------------------|---|--|---|--|
| 925 | 国中建筑<br>(福建)有限公司     | 2024-04-24<br>08:13<br>:21.0 | B4-<br>2E-<br>99-<br>98-<br>F1-<br>6B@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>1JXKK<br>AF, 19<br>35A98<br>04562            | 否 | 2024-04-24<br>08:11<br>:15.0 | B4-<br>2E-<br>99-<br>98-<br>F1-<br>6B@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>1JXKK<br>AF, 19<br>35A98<br>04562   | 否 |  |  |  |  |  |  |  |  |  |                         | 校验<br>数据有<br>误, 请<br>检查    | 2024-04-24<br>08:34<br>:41  | B4-<br>2E-<br>99-<br>98-<br>F1-<br>6B@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>1JXKK<br>AF, 19<br>35A98<br>04562 | 否 |  |
| 926 | 中建凯茂建<br>设发展有限<br>公司 | 2024-04-23<br>16:25<br>:59.0 | C0-<br>A5-<br>DD-<br>91-<br>63-<br>25, 00<br>-E0-<br>4C-<br>52-<br>1C-<br>D3@BF<br>EBFBF<br>F0009<br>06E9@<br>I3000<br>5B001<br>822 | 否 | 2024-04-23<br>16:25<br>:13.0 | C0-<br>A5-<br>DD-<br>91-<br>63-<br>25, 00<br>-E0-<br>4C-<br>52-<br>1C-<br>D3, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>I3000<br>5B001<br>822 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:32<br>:19 | C0-<br>A5-<br>DD-<br>91-<br>63-<br>25, 00<br>-E0-<br>4C-<br>52-<br>1C-<br>D3@BF<br>EBFBF<br>F0009<br>06E9@<br>I3000<br>5B001<br>822 | 否  |   |  |



|     |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 929 | 福建熙菱建设工程有限公司 | 2024-04-23 11:14:58.0 | A8-5E-45-A2-9F-41@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WMC6Y<br>ONAA<br>Y6A, 19<br>33788<br>02836 | 否 | 2024-04-23 11:13:33.0 | A8-5E-45-A2-9F-41@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WMC6Y<br>ONAA<br>Y6A, 19<br>33788<br>02836 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:35:40 | A8-5E-45-A2-9F-41@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WMC6Y<br>ONAA<br>Y6A, 19<br>33788<br>02836 | 否 |  |
|-----|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|





|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 931 | 福建省文海建设工程有限公司 | 2024-04-23 17:00:34.0 | 18-CO-4D-B0-F6-FA@BF EBFBF F000A 0653@ I3200 1B011 631, W D- WCC6Y 1SSR6 4C         | 否 | 2024-04-23 16:56:00.0 | 18-CO-4D-B0-F6-FA@BF EBFBF F000A 0653@ I3200 1B011 631, W D- WCC6Y 1SSR6 4C         | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:43 | 18-CO-4D-B0-F6-FA@BF EBFBF F000A 0653@ I3200 1B011 631, W D- WCC6Y 1SSR6 4C         | 否 |  |
| 932 | 福建省笔架建设发展有限公司 | 2024-04-23 17:29:41.0 | D4-5D-64-AA-6D-CA@BF EBFBF F0009 06EB@ WD- WCC6Y 7UV9D PV, AE F8070 3149C 00072 689 | 否 | 2024-04-23 17:28:54.0 | D4-5D-64-AA-6D-CA@BF EBFBF F0009 06EB@ WD- WCC6Y 7UV9D PV, AE F8070 3149C 00072 689 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:45 | D4-5D-64-AA-6D-CA@BF EBFBF F0009 06EB@ WD- WCC6Y 7UV9D PV, AE F8070 3149C 00072 689 | 否 |  |

|     |                   |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |  |                            |                        |   |   |  |
|-----|-------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|---|---|--|
| 933 | 福建省旺福<br>建设工程有限公司 | 2024-04-23<br>15:14:21.0 | B4-<br>2E-<br>99-<br>E1-<br>39-<br>84@BF<br>EBFBF<br>F0009<br>06EA@<br>K0201<br>02J03<br>039, W<br>D-<br>WCC6Y<br>7TVP1<br>HZ | 否 | 2024-04-23<br>15:12:19.0 | B4-<br>2E-<br>99-<br>E1-<br>39-<br>84@BF<br>EBFBF<br>F0009<br>06EA@<br>K0201<br>02J03<br>039, W<br>D-<br>WCC6Y<br>7TVP1<br>HZ | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:47:04 | B4-<br>2E-<br>99-<br>E1-<br>39-<br>84@BF<br>EBFBF<br>F0009<br>06EA@<br>K0201<br>02J03<br>039, W<br>D-<br>WCC6Y<br>7TVP1<br>HZ | 否 |  |
|-----|-------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|---|---|--|



|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 935 | 福建不凡建设工程有限公司  | 2024-04-23 17:05:56.0 | 00-25-90-3C-CF-48,00-25-90-3C-CF-49@BFEBFBF000206C2,BFEFBFF000206C2@Z1Z4H7FB,DSDC1862000574 | 否 | 2024-04-23 10:42:58.0 | 00-25-90-3C-CF-48,00-25-90-3C-CF-49@BFEBFBF000206C2,BFEFBFF000206C2@Z1Z4H7FB,DSDC1862000574 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误,请检查 | 2024-04-24 08:43:09 | 00-25-90-3C-CF-48,00-25-90-3C-CF-49@BFEBFBF000206C2,BFEFBFF000206C2@Z1Z4H7FB,DSDC1862000574 | 否 |  |
| 936 | 福建新海洋建设工程有限公司 | 2024-04-18 17:13:14.0 | 74-56-3C-C0-6F-40@BFEBFBF000A0653@0000_0006_2306_0486_CAF2_5B04_3703_5100.                  | 否 | 2024-04-18 17:10:42.0 | 74-56-3C-C0-6F-40@BFEBFBF000A0653@0000_0006_2306_0486_CAF2_5B04_3703_5100.                  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误,请检查 | 2024-04-24 08:33:27 | 74-56-3C-C0-6F-40@BFEBFBF000A0653@0000_0006_2306_0486_CAF2_5B04_3703_5100.                  | 否 |  |



|     |            |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |  |  |             |                        |  |   |
|-----|------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|------------------------|--|---|
| 938 | 贵州七建建设有限公司 | 2024-04-23<br>17:04:16.0 | 08-BF-B8-A3-C2-92, F8-6F-B0-D6-CA-4F, F8-6F-B0-D6-CA-4E@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>A428_<br>B703_<br>0B37_<br>00C2. | 否 | 2024-04-23<br>15:37:20.0 | 08-BF-B8-A3-C2-92, F8-6F-B0-D6-CA-4F, F8-6F-B0-D6-CA-4E@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>A428_<br>B703_<br>0B37_<br>00C2. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24<br>08:42:04 | 08-BF-B8-A3-C2-92, F8-6F-B0-D6-CA-4F, F8-6F-B0-D6-CA-4E@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>A428_<br>B703_<br>0B37_<br>00C2. | 否 |
|-----|------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|------------------------|--|---|

|     |                |                       |   |  |                       |   |  |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |
|-----|----------------|-----------------------|---|--|-----------------------|---|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|
| 939 | 福建省松溪县玖宇建设有限公司 | 2024-04-23 11:13:07.0 | 否 | CC-5E-F8-B5-F3-F5, CE-5E-F8-B5-F3-F5, C2-5E-F8-B5-F3-F5, CC-96-E5-37-19-AA, CC-5E-F8-B5-F3-F6@BF-EBFBF-F000B-06F5@-ZN1YT-BLY, 0-000_0-000_0-000_0-000_8-CE3_8-E10_0-150_B-236. | 2024-04-23 11:12:13.0 | 否 | CC-5E-F8-B5-F3-F5, CE-5E-F8-B5-F3-F5, C2-5E-F8-B5-F3-F5, CC-96-E5-37-19-AA, CC-5E-F8-B5-F3-F6@BF-EBFBF-F000B-06F5@-ZN1YT-BLY, 0-000_0-000_0-000_0-000_8-CE3_8-E10_0-150_B-236. |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:04 | 否 | CC-96-E5-37-19-AA, CC-5E-F8-B5-F3-F6, CC-5E-F8-B5-F3-F5, CE-5E-F8-B5-F3-F5@BF-EBFBF-F000B-06F5@-ZN1YT-BLY, 0-000_0-000_0-000_8-CE3_8-E10_0-150_B-236. |
|-----|----------------|-----------------------|---|--|-----------------------|---|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|



|     |               |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |  |
|-----|---------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|--|
| 940 | 福建省美筑建设发展有限公司 | 2024-04-23 11:25:35.0 | E0-D5-5E-92-F3-3C@BFBFBFF000306C3@MG18030000000219534,W9A1N90H   | 否 | 2024-04-23 11:23:50.0 | E0-D5-5E-92-F3-3C@BFBFBFF000306C3@MG18030000000219534,W9A1N90H  | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:39 | E0-D5-5E-92-F3-3C@BFBFBFF000306C3@MG18030000000219534,W9A1N90H   | 否 |  |  |
| 941 | 福建鸿光建设发展有限公司  | 2024-04-23 09:31:07.0 | 4C-ED-FB-CO-25-07@178BFBF00080F11@2020202057202d44435736433159584830564343,333232315135303833353731202020202020200 | 否 | 2024-04-22 18:04:40.0 | 4C-ED-FB-CO-25-07,00-00-00-00-00-00-00-00-E0,00-00-00-00-00-00-00-00-00-00-E0@178BFBF00080F11@2020202057202d44435736433159584830564343,33323231513530 | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:40:33 | 4C-ED-FB-CO-25-07@178BFBF00080F11@2020202057202d44435736433159584830564343,333232315135303833353731202020202020200 | 否 |  |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|--|---|--|
|     |               |                       |  |   |                       | 38333<br>53731<br>20202<br>02020<br>20202<br>0   |   |  |  |  |  |  |  |  |  |  |            |                     |  |  |   |  |
| 942 | 广东裕达建设集团有限公司  | 2024-04-23 16:15:22.0 | 00-E0-4C-52-84-C2,34-4B-50-00-00-00@BF EBFBF F000A 0653@1234567890 ABCDE 1,E82 3_8FA 6_BF5 3_000 1_001 B_448 B_45F C_CEF 3.,22 5103A 00164 | 否 | 2024-04-23 16:13:50.0 | 00-E0-4C-52-84-C2,34-4B-50-00-00-00@BF EBFBF F000A 0653@1234567890 ABCDE 1,E82 3_8FA 6_BF5 3_000 1_001 B_448 B_45F C_CEF 3.,22 5103A 00164 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:02 | 00-E0-4C-52-84-C2,34-4B-50-00-00-00@BF EBFBF F000A 0653@1234567890 ABCDE 1,E82 3_8FA 6_BF5 3_000 1_001 B_448 B_45F C_CEF 3.,22 5103A 00164 | 否  |   |  |
| 943 | 福建省汇语建筑工程有限公司 | 2024-04-23 16:21:35.0 | 18-C0-4D-F7-F5-82@BF EBFBF F000A 0653@202308030011   | 否 | 2024-04-23 16:20:45.0 | 18-C0-4D-F7-F5-82@BF EBFBF F000A 0653@202308030011   | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:33:53  | 18-C0-4D-F7-F5-82@BF EBFBF F000A 0653@202308030011 | 否 |  |

|     |             |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |  |             |                     |  |  |   |  |  |
|-----|-------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|--|---|--|--|
| 944 | 福建省创诚建设有限公司 | 2024-04-23 09:32:14.0 | 00-<br>E0-<br>4C-<br>2D-<br>16-<br>A0@BF<br>EBFBF<br>F0003<br>06A9@<br>BAOCO<br>00090<br>T3<br>A, W -<br>DMWYA<br>OPAJ4<br>L2D | 否 | 2024-04-23 09:30:52.0 | 00-<br>E0-<br>4C-<br>2D-<br>16-<br>A0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06A9@<br>BAOCO<br>00090<br>T3<br>A, W -<br>DMWYA<br>OPAJ4<br>L2D | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:02 | 00-<br>E0-<br>4C-<br>2D-<br>16-<br>A0@BF<br>EBFBF<br>F0003<br>06A9@<br>BAOCO<br>00090<br>T3<br>A, W -<br>DMWYA<br>OPAJ4<br>L2D | 否  |   |  |  |
| 945 | 福建九岩建筑有限公司  | 2024-04-23 16:56:21.0 | 04-<br>42-<br>1A-<br>AE-<br>84-<br>10@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>1LURP<br>XP, JS<br>MB211<br>00935<br>77 | 否 | 2024-04-23 16:54:39.0 | 04-<br>42-<br>1A-<br>AE-<br>84-<br>10@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>1LURP<br>XP, JS<br>MB211<br>00935<br>77   | 否 |  |  |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:41:54  | 04-<br>42-<br>1A-<br>99-<br>3D-<br>25@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>3ND9P<br>AZ, 50<br>026B7<br>38149<br>199F | 否 |  |  |

|     |                   |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|-------------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 946 | 福建省耀丰建设发展有限公司     | 2024-04-22 11:05:51.0 | 58-11-22-07-F4-CA@BF EBFBF F000A 0653@ 0025_ 38B1_ 21C5_ 681A.             | 否 | 2024-04-22 11:04:54.0 | 58-11-22-07-F4-CA@BF EBFBF F000A 0653@ 0025_ 38B1_ 21C5_ 681A.             | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:35:16 | 58-11-22-07-F4-CA@BF EBFBF F000A 0653@ 0025_ 38B1_ 21C5_ 681A.             | 否 |  |
| 947 | 信嵘宣(厦门)市政园林工程有限公司 | 2024-04-22 17:45:32.0 | A8-5E-45-A2-D9-20@BF EBFBF F0009 06ED@ 20230 31112 68, WD - WCC6Y 7LHU7 EA | 否 | 2024-04-22 17:35:40.0 | A8-5E-45-A2-D9-20@BF EBFBF F0009 06ED@ 20230 31112 68, WD - WCC6Y 7LHU7 EA | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 09:00:13 | A8-5E-45-A2-D9-20@BF EBFBF F0009 06ED@ 20230 31112 68, WD - WCC6Y 7LHU7 EA | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|
| 948 | 福建永三建设发展有限公司 | 2024-04-23 18:39:06.0 | 60-45-CB-82-93-0A@BF EBFBF F0009 06E9@ 2G162 00340 68 | 否 | 2024-04-23 18:37:36.0 | 60-45-CB-82-93-0A@BF EBFBF F0009 06E9@ 2G162 00340 68 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:34:20 | E8-9C-25-78-7D-1F, 90-65-84-D6-DF-57, 90-65-84-D6-DF-53, 92-65-84-D6-DF-53, 90-65-84-D6-DF-53, 90-65-84-D6-DF-54@BF EBFBF F000B 0671@ AA000 00000 00000 00117 _0000 0001. , WD- WCC6Y 2PP03 C2, WD - WCC6Y 2AF6N 4T, 00 00_00 00_00 00_00 01. | 否 |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|

|     |                |                        |   |   |                        |   |   |  |  |  |  |  |  |  |  |  |  |  |            |                      |   |   |  |
|-----|----------------|------------------------|---|---|------------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|------------|----------------------|---|---|--|
| 949 | 福建远阔建设工程有限公司   | 2024-04-23 15:52 :43.0 | D4-5D-64-B4-A7-68@BFEBFBFF000A0655@0025_3884_01D8_4C57.,ZFM1COAY        | 否 | 2024-04-23 15:50 :27.0 | D4-5D-64-B4-A7-68@BFEBFBFF000A0655@0025_3884_01D8_4C57.,ZFM1COAY        | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:33 :16 | D4-5D-64-B4-A7-68@BFEBFBFF000A0655@0025_3884_01D8_4C57.,ZFM1COAY        | 否 |  |
| 950 | 福建旭嘉建设工程有限公司   | 2024-04-16 15:05 :53.0 | 00-E0-3A-36-0A-6A,00-00-00-00-00-00-00-E0@BFEBFBFF000206A7@020220228032 | 否 | 2024-04-16 15:04 :57.0 | 00-E0-3A-36-0A-6A,00-00-00-00-00-00-00-E0@BFEBFBFF000206A7@020220228032 | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:37 :31 | 00-E0-3A-36-0A-6A,00-00-00-00-00-00-00-E0@BFEBFBFF000206A7@020220228032 | 否 |  |
| 951 | 福建世纪蓝天建设工程有限公司 | 2024-04-22 17:25 :15.0 | 04-D9-F5-85-03-20@BFEBFBFF000906EA@50026B7685C9A554                     | 否 | 2024-04-22 17:13 :28.0 | 04-D9-F5-85-03-20@BFEBFBFF000906EA@50026B7685C9A554                     | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:35 :08 | 04-D9-F5-85-03-20@BFEBFBFF000906EA@50026B7685C9A554                     | 否 |  |

|     |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|-----|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 952 | 福建省璟琪建筑工程有限公司  | 2024-04-23 12:05:53.0 | E8-9C-25-40-E1-C6@BF<br>EBFBF<br>F0009<br>0675@<br>Z4Y73<br>D44,6<br>479_A<br>78A_3<br>000_0<br>1EB.         | 否 | 2024-04-23 12:04:48.0 | E8-9C-25-40-E1-C6@BF<br>EBFBF<br>F0009<br>0675@<br>Z4Y73<br>D44,6<br>479_A<br>78A_3<br>000_0<br>1EB.         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:36:21 | E0-D5-5E-C1-06-4C@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WMC2E<br>OF8DZ<br>EJ, RC<br>21111<br>0M8F0<br>659  | 否 |  |
| 953 | 福建本森建设有限公司     | 2024-04-18 15:32:34.0 | 00-E0-4C-36-65-02@BF<br>EBFBF<br>F0009<br>06E9@<br>1706B<br>Q0526<br>AWM34<br>2, WD-<br>WCC6Y<br>OSH4H<br>81 | 否 | 2024-04-18 15:29:59.0 | 00-E0-4C-36-65-02@BF<br>EBFBF<br>F0009<br>06E9@<br>1706B<br>Q0526<br>AWM34<br>2, WD-<br>WCC6Y<br>OSH4H<br>81 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:27 | 00-E0-4C-36-65-02@BF<br>EBFBF<br>F0009<br>06E9@<br>1706B<br>Q0526<br>AWM34<br>2, WD-<br>WCC6Y<br>OSH4H<br>81 | 否 |  |
| 954 | 厦门市兴邦园建设工程有限公司 | 2024-04-18 11:33:45.0 | 04-D9-F5-5E-63-16@BF<br>EBFBF<br>F0009<br>06EB@<br>ZN17V<br>1CY, 2<br>01907<br>10103<br>73                   | 否 | 2024-04-18 11:31:46.0 | 04-D9-F5-5E-63-16@BF<br>EBFBF<br>F0009<br>06EB@<br>ZN17V<br>1CY, 2<br>01907<br>10103<br>73                   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:52 | 04-D9-F5-5E-63-16@BF<br>EBFBF<br>F0009<br>06EB@<br>ZN17V<br>1CY, 2<br>01907<br>10103<br>73                   | 否 |  |

|     |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 955 | 福建跃启元通建筑工程有限公司 | 2024-04-22 17:17:54.0 | 00-<br>E0-<br>1D-<br>6A-<br>09-<br>DB@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0001_<br>6479_<br>A786_<br>8A30_<br>30FC.  | 否 | 2024-04-22 17:02:36.0 | 00-<br>E0-<br>1D-<br>6A-<br>09-<br>DB@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0001_<br>6479_<br>A786_<br>8A30_<br>30FC.  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:34:16 | 00-<br>E0-<br>1D-<br>6A-<br>09-<br>DB@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0001_<br>6479_<br>A786_<br>8A30_<br>30FC.  | 否 |  |
| 956 | 福建山水建设工程有限公司   | 2024-04-23 18:37:24.0 | 00-<br>E0-<br>70-<br>7D-<br>5A-<br>93,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>H3508<br>7J014<br>513 | 否 | 2024-04-23 18:35:46.0 | 00-<br>E0-<br>70-<br>7D-<br>5A-<br>93,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>H3508<br>7J014<br>513 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:35:48 | 00-<br>E0-<br>70-<br>7D-<br>5A-<br>93,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>H3508<br>7J014<br>513 | 否 |  |



|     |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|-----|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 957 | 武夷龙辉建设（福建）有限公司 | 2024-04-23 10:11:33.0 | F0-2F-74-FA-0B-0E@BF EBFBF F000A 0653@50026 B7783 C6883 7  | 否 | 2024-04-23 10:08:23.0 | F0-2F-74-FA-0B-0E@BF EBFBF F000A 0653@50026 B7783 C6883 7  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:40 | F0-2F-74-FA-0B-0E@BF EBFBF F000A 0653@50026 B7783 C6883 7  | 否 |  |
| 958 | 厦门明运建筑有限公司     | 2024-04-22 11:12:48.0 | 7C-10-C9-D1-78-EA, 00 -FF-F7-7B-9E-72@BF EBFBF F000A 0653@ YX211 4JS12 0A006 63, 50 026B7 3811E 34B4 | 否 | 2024-04-22 10:58:21.0 | 7C-10-C9-D1-78-EA, 00 -FF-F7-7B-9E-72@BF EBFBF F000A 0653@ YX211 4JS12 0A006 63, 50 026B7 3811E 34B4 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:47 | 7C-10-C9-D1-78-EA, 00 -FF-F7-7B-9E-72@BF EBFBF F000A 0653@ YX211 4JS12 0A006 63, 50 026B7 3811E 34B4 | 否 |  |

|     |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |  |   |  |
|-----|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|--|---|--|
| 959 | 福建省利友建筑工程有限公司 | 2024-04-23 10:55:49.0 | A4-0C-66-03-B6-1B,00-E0-4C-99-08-73@BF EBFBF F0009 06EA@WD-WCC6Y 1KAUC 7S,AA 00000 00000 00000 161 | 否 | 2024-04-23 10:16:39.0 | A4-0C-66-03-B6-1B,00-E0-4C-99-08-73@BF EBFBF F0009 06EA@WD-WCC6Y 1KAUC 7S,AA 00000 00000 00000 161 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:58:13 | A4-0C-66-03-B6-1B,00-E0-4C-99-08-73@BF EBFBF F0009 06EA@WD-WCC6Y 1KAUC 7S,AA 00000 00000 00000 161 | 否  |   |  |
| 960 | 福建益长中建设有限公司   | 2024-04-22 15:07:21.0 | 04-42-1A-03-5C-FA,00-00-00-00-00-00-00-00-00-E0@BF EBFBF F000A 0653@30046 074808                   | 否 | 2024-04-22 15:06:16.0 | 04-42-1A-03-5C-FA,00-00-00-00-00-00-00-00-00-E0@BF EBFBF F000A 0653@30046 074808                   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误差，请检查         | 2024-04-24 08:34:24  | 04-42-1A-03-5C-FA,00-00-00-00-00-00-00-00-00-E0@BF EBFBF F000A 0653@30046 074808 | 否 |  |
| 961 | 福建卓诚建设有限公司    | 2024-04-19 08:58:52.0 | 00-E0-70-ED-0F-84@BF EBFBF   | 否 | 2024-04-19 08:57:12.0 | 00-E0-70-ED-0F-84@BF EBFBF   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误差，请检查         | 2024-04-24 08:32:26  | 00-E0-70-ED-0F-84@BF EBFBF   | 否 |  |

|     |               |                              |  |   |  |  |   |  |  |  |  |  |  |  |  |                            |                            |  |   |  |
|-----|---------------|------------------------------|--|---|--|--|---|--|--|--|--|--|--|--|--|----------------------------|----------------------------|--|---|--|
|     |               |                              | F000A<br>0671@<br>LCRY8<br>223AB<br>T6500<br>,W1D3<br>D4M7   |   | F000A<br>0671@<br>LCRY8<br>223AB<br>T6500<br>,W1D3<br>D4M7 |  |   |  |  |  |  |  |  |  |  |                            |                            | F000A<br>0671@<br>LCRY8<br>223AB<br>T6500<br>,W1D3<br>D4M7   |   |  |
| 962 | 福建赫威建设工程有限公司  | 2024-04-23<br>10:22<br>:06.0 | A0-<br>36-<br>BC-<br>2A-<br>04-<br>E2@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1A08_<br>7915.          | 否 | 2024-04-23<br>10:14<br>:54.0                               | A0-<br>36-<br>BC-<br>2A-<br>04-<br>E2@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1A08_<br>7915.          | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:35<br>:40 | A0-<br>36-<br>BC-<br>2A-<br>04-<br>E2@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1A08_<br>7915.          | 否 |  |
| 963 | 福建省玺帆建设工程有限公司 | 2024-04-23<br>09:12<br>:45.0 | 00-<br>E0-<br>4C-<br>6A-<br>1E-<br>7B@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0967. | 否 | 2024-04-23<br>09:08<br>:50.0                               | 00-<br>E0-<br>4C-<br>6A-<br>1E-<br>7B@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0967. | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:35<br>:06 | 00-<br>E0-<br>4C-<br>6A-<br>1E-<br>7B@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0967. | 否 |  |

|     |                   |                              |  |   |                              |   |   |  |  |  |  |  |  |  |  |                         |                            |  |   |  |
|-----|-------------------|------------------------------|--|---|------------------------------|---|---|--|--|--|--|--|--|--|--|-------------------------|----------------------------|--|---|--|
| 964 | 福建富立宸<br>建设工程有限公司 | 2024-04-23<br>08:25<br>:59.0 | FC-<br>34-<br>97-<br>C2-<br>34-<br>91@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OCEEX<br>VT, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 | 2024-04-22<br>16:30<br>:53.0 | FC-<br>34-<br>97-<br>C2-<br>34-<br>91@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OCEEX<br>VT, 00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:37<br>:04 | FC-<br>34-<br>97-<br>C2-<br>34-<br>91@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OCEEX<br>VT, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 |  |
| 965 | 福建景洲建<br>设工程有限公司  | 2024-04-22<br>10:51<br>:07.0 | B4-<br>2E-<br>99-<br>7C-<br>0E-<br>89@BF<br>EBFBF<br>F0009<br>06EB@<br>23090<br>21301<br>44036<br>09171<br>07, 16<br>02174<br>03404<br>, WD-<br>WCC6Y<br>2APAU<br>U4         | 否 | 2024-04-18<br>15:35<br>:54.0 | B4-<br>2E-<br>99-<br>7C-<br>0E-<br>89@BF<br>EBFBF<br>F0009<br>06EB@<br>16021<br>74034<br>04, WD<br>-<br>WCC6Y<br>2APAU<br>U4  | 否 |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:31<br>:42 | B4-<br>2E-<br>99-<br>7C-<br>0E-<br>89@BF<br>EBFBF<br>F0009<br>06EB@<br>23090<br>21301<br>44036<br>09171<br>07, 16<br>02174<br>03404<br>, WD-<br>WCC6Y<br>2APAU<br>U4         | 否 |  |

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 966 | 福建皓禹建设工程有限公司 | 2024-04-23 09:24:15.0 | 74-56-3C-EB-3E-3E@BF EBFBF F000A 0653@0000_0000_0000_0000_0026_B768_6AEC_2155., ZTB1 512KA 20380 08W3 | 否 | 2024-04-23 09:22:23.0 | 74-56-3C-EB-3E-3E@BF EBFBF F000A 0653@0000_0000_0000_0000_0026_B768_6AEC_2155., ZTB1 512KA 20380 08W3 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:42:18 | 74-56-3C-EB-3E-3E@BF EBFBF F000A 0653@0000_0000_0000_0000_0026_B768_6AEC_2155., ZTB1 512KA 20380 08W3 | 否 |  |
| 967 | 福建卓铸建设发展有限公司 | 2024-04-23 14:51:32.0 | D8-BB-C1-62-47-C2@BF EBFBF F000A 0653@50026 B7381 13ADAD  | 否 | 2024-04-23 14:46:40.0 | D8-BB-C1-62-47-C2@BF EBFBF F000A 0653@50026 B7381 13ADAD  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:33:27 | D8-BB-C1-62-47-C2@BF EBFBF F000A 0653@50026 B7381 13ADAD  | 否 |  |

|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|--|
| 968 | 福建省新海鑫建设工程有限公司 | 2024-04-23 11:44:26.0 | 00-<br>E0-<br>70-<br>8C-<br>D9-<br>88, E8<br>-4E-<br>06-<br>6A-<br>00-<br>6E, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>88, E8<br>-4E-<br>06-<br>6A-<br>00-<br>6E@17<br>8BFBF<br>F0061<br>0F31@<br>324d3<br>13031<br>30303<br>83734<br>39312<br>02020<br>20202<br>02020 | 否 | 2024-04-23 11:09:57.0 | 00-<br>E0-<br>70-<br>8C-<br>D9-<br>88, E8<br>-4E-<br>06-<br>6A-<br>00-<br>6E, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@17<br>8BFBF<br>F0061<br>0F31@<br>324d3<br>13031<br>30303<br>83734<br>39312<br>02020<br>20202<br>02020 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:36 | 00-<br>E0-<br>70-<br>8C-<br>D9-<br>88, E8<br>-4E-<br>06-<br>6A-<br>00-<br>6E@17<br>8BFBF<br>F0061<br>0F31@<br>324d3<br>13031<br>30303<br>83734<br>39312<br>02020<br>20202<br>02020 | 否 |  |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|--|

|     |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|-----|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 969 | 福建晟焱建设工程有限公司 | 2024-04-23 09:46:51.0 | D8-5E-D3-51-0E-A1@BFEBFBFF000A0653@50026B73812D2A72                         | 否 | 2024-04-23 09:42:41.0 | D8-5E-D3-51-0E-A1@BFEBFBFF000A0653@50026B73812D2A72                         | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:36:22 | D8-5E-D3-51-0E-A1@BFEBFBFF000A0653@50026B73812D2A72                         | 否 |  |
| 970 | 炬阳建设集团有限公司   | 2024-04-23 17:30:38.0 | 00-E0-97-20-3C-65@BFEBFBFF00090675@A428_B701_2D47_0041.                     | 否 | 2024-04-23 17:29:17.0 | 00-E0-97-20-3C-65@BFEBFBFF00090675@A428_B701_2D47_0041.                     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:42:51 | 00-E0-97-20-3C-65@BFEBFBFF00090675@A428_B701_2D47_0041.                     | 否 |  |
| 971 | 福建亿盛智能工程有限公司 | 2024-04-23 10:11:42.0 | C8-7F-54-52-FD-23@BFEBFBFF000B06F2@E823_8FA6_BF53_0001_001B_444A_48B7_E589. | 否 | 2024-04-23 10:10:14.0 | C8-7F-54-52-FD-23@BFEBFBFF000B06F2@E823_8FA6_BF53_0001_001B_444A_48B7_E589. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:19 | C8-7F-54-52-FD-23@BFEBFBFF000B06F2@E823_8FA6_BF53_0001_001B_444A_48B7_E589. | 否 |  |

|     |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 972 | 福建伟业公路建设工程有限公司 | 2024-04-23 10:40:22.0 | 18-C0-4D-18-04-25@BF<br>EBFBF<br>F0009<br>06ED@<br>MG000<br>00000<br>678,2<br>00600<br>000C4<br>55,11<br>8D862<br>NS    | 否 | 2024-04-23 10:31:28.0 | 18-C0-4D-18-04-25@BF<br>EBFBF<br>F0009<br>06ED@<br>MG000<br>00000<br>678,2<br>00600<br>000C4<br>55,11<br>8D862<br>NS  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:37:50 | 18-C0-4D-18-04-25@BF<br>EBFBF<br>F0009<br>06ED@<br>MG000<br>00000<br>678,2<br>00600<br>000C4<br>55,11<br>8D862<br>NS    | 否 |  |
| 973 | 福建登华建设工程有限公司   | 2024-04-23 11:54:52.0 | D4-5D-64-49-E1-88@BF<br>EBFBF<br>F0009<br>06EA@<br>314b3<br>23337<br>30304<br>a3530<br>31312<br>03320<br>20202<br>02020 | 否 | 2024-04-23 11:54:33.0 | D4-5D-64-49-E1-88,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>314b3<br>23337<br>30304<br>a3530<br>31312<br>03320<br>20202<br>02020 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:48:38 | D4-5D-64-49-E1-88@BF<br>EBFBF<br>F0009<br>06EA@<br>314b3<br>23337<br>30304<br>a3530<br>31312<br>03320<br>20202<br>02020 | 否 |  |





|     |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |                     |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|---------------------|---------------------|---|---|--|
| 976 | 福建省中茂鼎侨建设有限公司 | 2024-04-23 17:22:40.0 | 00-<br>E0-<br>4C-<br>5A-<br>5C-<br>46, 0A<br>-62-<br>21-<br>20-<br>16-<br>19, 48<br>-8A-<br>D2-<br>A6-<br>5B-<br>CC, 48<br>-8A-<br>D2-<br>A6-<br>5B-<br>CC, 48<br>-8A-<br>D2-<br>A6-<br>5B-<br>CC@BF<br>EBFBF<br>F0005<br>06E3@<br>AA000<br>00000<br>00000<br>00351 | 否 | 2024-04-23 17:21:26.0 | 00-<br>E0-<br>4C-<br>5A-<br>5C-<br>46, 48<br>-8A-<br>D2-<br>A6-<br>5B-<br>CC, 48<br>-8A-<br>D2-<br>A6-<br>5B-<br>CC, 0A<br>-62-<br>21-<br>20-<br>16-<br>19@BF<br>EBFBF<br>F0005<br>06E3@<br>AA000<br>00000<br>00000<br>00351 | 否 |  |  |  |  |  |  |  |  | 校验数据<br>有误, 请<br>检查 | 2024-04-24 08:43:00 | 8C-<br>EC-<br>4B-<br>14-<br>FF-<br>01, B2<br>-52-<br>16-<br>61-<br>B7-<br>BB, C2<br>-52-<br>16-<br>61-<br>B7-<br>BB, B0<br>-52-<br>16-<br>61-<br>B7-<br>BC@BF<br>EBFBF<br>F0008<br>06EA@<br>MI7AN<br>11411<br>270B4<br>6C, WD<br>ER6GD<br>8 | 否 |  |
|-----|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|---------------------|---------------------|---|---|--|

|     |                 |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|-----|-----------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 977 | 福建省政和龙轩建设工程有限公司 | 2024-04-22 16:37:24.0 | B1@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7381<br>A9EBB<br>E,6VM<br>RAXKF  | 否 | 2024-04-22 16:31:30.0 | 00-<br>E0-<br>4C-<br>49-<br>60-<br>B1,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7381<br>A9EBB<br>E,6VM<br>RAXKF | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误,请检查 | 2024-04-24 08:39:22 | 00-<br>E0-<br>4C-<br>49-<br>60-<br>B1@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7381<br>A9EBB<br>E,6VM<br>RAXKF   | 否 |  |
| 978 | 福建园禾友建设工程有限公司   | 2024-04-23 17:37:48.0 | 74-<br>56-<br>3C-<br>A4-<br>F2-<br>B6@BF<br>EBFBF<br>F0009<br>0675@<br>0000<br>0000<br>0000<br>0000<br>0026<br>B738<br>2484<br>A8B5.<br>,WD-<br>WCC6Y<br>4Z42J<br>U8 | 否 | 2024-04-23 16:04:25.0 | 74-<br>56-<br>3C-<br>A4-<br>F2-<br>B6@BF<br>EBFBF<br>F0009<br>0675@<br>0000<br>0000<br>0000<br>0000<br>0026<br>B738<br>2484<br>A8B5.<br>,WD-<br>WCC6Y<br>4Z42J<br>U8  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误,请检查 | 2024-04-24 08:39:02 | 74-<br>56-<br>3C-<br>A4-<br>F2-<br>B6@BF<br>EBFBF<br>F0009<br>0675@<br>0000<br>0000<br>0000<br>0000<br>0026<br>B738<br>2484<br>A8B5.<br>,WD-<br>WCC6Y<br>4Z42J<br>U8 | 否 |  |



|     |              |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |  |            |                        |  |   |  |
|-----|--------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|------------|------------------------|--|---|--|
| 980 | 福建焯焯建设工程有限公司 | 2024-04-23<br>16:28:24.0 | 40-<br>B0-<br>76-<br>7D-<br>CC-<br>A9@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>4PA40<br>47                           | 否 | 2024-04-23<br>16:25:15.0 | 40-<br>B0-<br>76-<br>7D-<br>CC-<br>A9,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>4PA40<br>47 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24<br>08:37:12 | 40-<br>B0-<br>76-<br>7D-<br>CC-<br>A9@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>4PA40<br>47                           | 否 |  |
| 981 | 福建大七建设发展有限公司 | 2024-04-23<br>14:31:18.0 | 38-<br>D5-<br>47-<br>26-<br>DF-<br>84@BF<br>EBFBF<br>F0003<br>06C3@<br>TA168<br>24505<br>37, WD<br>-<br>WCC4J<br>2TNFR<br>3C | 否 | 2024-04-23<br>11:49:46.0 | 38-<br>D5-<br>47-<br>26-<br>DF-<br>84,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003                                  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24<br>08:34:42 | 38-<br>D5-<br>47-<br>26-<br>DF-<br>84@BF<br>EBFBF<br>F0003<br>06C3@<br>TA168<br>24505<br>37, WD<br>-<br>WCC4J<br>2TNFR<br>3C | 否 |  |

|     |                   |                                  |  |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
|-----|-------------------|----------------------------------|--|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|
|     |                   |                                  |  |   |                                  | 06C3@<br>TA168<br>24505<br>37, WD<br>-<br>WCC4J<br>2TNFR<br>3C  |   |  |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
| 982 | 福建省佳泰<br>建设工程有限公司 | 2024-<br>04-18<br>11:34<br>:38.0 | 00-<br>00-<br>00-<br>00-<br>00-<br>00, 04<br>-D9-<br>F5-<br>20-<br>D7-<br>70@BF<br>EBFBF<br>F0009<br>06E9@<br>J2707<br>02F00<br>676, W<br>D-<br>WCC6Y<br>6SVF6<br>SN | 否 | 2024-<br>04-18<br>11:21<br>:27.0 | 04-<br>D9-<br>F5-<br>20-<br>D7-<br>70, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00, 04<br>-D9-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>J2707<br>02F00<br>676, W<br>D-<br>WCC6Y<br>6SVF6<br>SN | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:40<br>:04 | 00-<br>00-<br>00-<br>00-<br>00-<br>00, 04<br>-D9-<br>F5-<br>20-<br>D7-<br>70@BF<br>EBFBF<br>F0009<br>06E9@<br>J2707<br>02F00<br>676, W<br>D-<br>WCC6Y<br>6SVF6<br>SN | 否 |  |

|     |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |  |
|-----|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|--|
| 983 | 福建春望建设有限公司 | 2024-04-23 14:42:51.0 | 2C-F0-5D-F5-A5-F8@BF EBFBF F00A0653@E823_8FA6_ BF53_ 0001_ 001B_ 448B_ 4A75_ 1141. | 否 | 2024-04-23 09:12:18.0 | 2C-F0-5D-F5-A5-F8@BF EBFBF F00A0653@E823_8FA6_ BF53_ 0001_ 001B_ 448B_ 4A75_ 1141. | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:29 | 2C-F0-5D-F5-A5-F8@BF EBFBF F00A0653@E823_8FA6_ BF53_ 0001_ 001B_ 448B_ 4A75_ 1141. | 否 |  |  |
|-----|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|--|











|     |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|-----|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 990 | 福建聚鑫恒建设工程有限公司 | 2024-04-22 10:50:31.0 | 2C-FD-A1-BA-1B-A8@BFEBFBFF000906E9@TW1860758450299      | 否 | 2024-04-22 10:13:49.0 | 2C-FD-A1-BA-1B-A8@BFEBFBFF000906E9@TW1860758450299      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:31:47 | 2C-FD-A1-BA-1B-A8@BFEBFBFF000906E9@TW1860758450299      | 否 |  |
| 991 | 福建凡通建设工程有限公司  | 2024-04-23 17:02:03.0 | 50-EB-F6-B4-9F-D2@BFEBFBFF000A0653@50026B73813146FA     | 否 | 2024-04-23 10:06:31.0 | 50-EB-F6-B4-9F-D2@BFEBFBFF000A0653@50026B73813146FA     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:49 | 50-EB-F6-B4-9F-D2@BFEBFBFF000A0653@50026B73813146FA     | 否 |  |
| 992 | 福建淘金建设有限公司    | 2024-04-23 16:50:27.0 | E8-9C-25-9B-72-8D@BFEBFBFF00090675@0025_38B5_31A4_E16B. | 否 | 2024-04-23 16:51:37.0 | E8-9C-25-9B-72-8D@BFEBFBFF00090675@0025_38B5_31A4_E16B. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:45 | E8-9C-25-9B-72-8D@BFEBFBFF00090675@0025_38B5_31A4_E16B. | 否 |  |





|     |                   |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |                         |                            |   |   |   |  |
|-----|-------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|-------------------------|----------------------------|---|---|---|--|
| 996 | 福建新华泰<br>建筑工程有限公司 | 2024-04-23<br>12:36<br>:14.0 | E0-<br>D5-<br>5E-<br>D7-<br>DD-<br>AB@BF<br>EBFBF<br>F0009<br>06EB@<br>22510<br>3A007<br>0D, 20<br>50468<br>03539   | 否 | 2024-04-23<br>12:35<br>:09.0 | E0-<br>D5-<br>5E-<br>D7-<br>DD-<br>AB@BF<br>EBFBF<br>F0009<br>06EB@<br>22510<br>3A007<br>0D, 20<br>50468<br>03539   | 否 |  |  |  |  |  |  |  |  |                         | 校验<br>数据有<br>误, 请<br>检查    | 2024-04-24<br>08:34<br>:16  | E0-<br>D5-<br>5E-<br>D7-<br>DD-<br>AB@BF<br>EBFBF<br>F0009<br>06EB@<br>22510<br>3A007<br>0D, 20<br>50468<br>03539 | 否 |  |
| 997 | 福建速方建<br>筑工程有限公司  | 2024-04-23<br>16:41<br>:51.0 | 08-<br>BF-<br>B8-<br>87-<br>7E-<br>D1@BF<br>EBFBF<br>F000A<br>0653@<br>S4CKN<br>XONA2<br>1165H<br>, E823<br>_8FA6<br>_BF53<br>_0001<br>_001B<br>_444A<br>_48ED<br>_2531 | 否 | 2024-04-23<br>11:20<br>:37.0 | 08-<br>BF-<br>B8-<br>87-<br>7E-<br>D1@BF<br>EBFBF<br>F000A<br>0653@<br>S4CKN<br>XONA2<br>1165H<br>, E823<br>_8FA6<br>_BF53<br>_0001<br>_001B<br>_444A<br>_48ED<br>_2531 | 否 |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:32<br>:35 | 08-<br>BF-<br>B8-<br>87-<br>7E-<br>D1@BF<br>EBFBF<br>F000A<br>0653@<br>S4CKN<br>XONA2<br>1165H<br>, E823<br>_8FA6<br>_BF53<br>_0001<br>_001B<br>_444A<br>_48ED<br>_2531 | 否   |   |  |

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 998  | 福建鑫延顺建设工程有限公司  | 2024-04-19 09:52:25.0 | E0-D5-5E-62-E3-4C@BFEBFBFF000906E9@WD-WCC6Y7HSE1TA, 10006615447             | 否 | 2024-04-19 09:47:32.0 | E0-D5-5E-62-E3-4C@BFEBFBFF000906E9@WD-WCC6Y7HSE1TA, 10006615447             | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:52 | E0-D5-5E-62-E3-4C@BFEBFBFF000906E9@WD-WCC6Y7HSE1TA, 10006615447             | 否 |  |
| 999  | 福建煜明建设有限公司     | 2024-04-23 10:58:38.0 | B4-2E-99-0F-71-C8@BFEBFBFF000906E9@50026B7682E30238                         | 否 | 2024-04-23 10:55:19.0 | B4-2E-99-0F-71-C8@BFEBFBFF000906E9@50026B7682E30238                         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:36:14 | B4-2E-99-0F-71-C8@BFEBFBFF000906E9@50026B7682E30238                         | 否 |  |
| 1000 | 龙岩龙创盛业建设工程有限公司 | 2024-04-22 16:23:26.0 | 08-BF-B8-87-88-52@BFEBFBFF000A0653@0000_0000_0000_0000_0000_0001_1616_1504. | 否 | 2024-04-22 16:20:10.0 | 08-BF-B8-87-88-52@BFEBFBFF000A0653@0000_0000_0000_0000_0000_0001_1616_1504. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:53:15 | 08-BF-B8-87-88-52@BFEBFBFF000A0653@0000_0000_0000_0000_0000_0001_1616_1504. | 否 |  |
| 1001 | 福建警声市政园林集团有限公司 | 2024-04-23 09:08      | 08-BF-B8-   | 否 | 2024-04-23 09:04      | 08-BF-B8-   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误      | 2024-04-24 08:31    | 08-BF-B8-   | 否 |  |



|      |              |                        |  |   |                        |  |   |  |  |  |  |  |  |  |  |  |  |              |                      |  |   |  |  |
|------|--------------|------------------------|--|---|------------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|----------------------|--|---|--|--|
|      |              | :02.0                  | 02-D8-63@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>6JLAN<br>JP,00<br>25_38<br>D3_31<br>AF_08<br>DF.                           |   | :52.0                  | 02-D8-63@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>6JLAN<br>JP,00<br>25_38<br>D3_31<br>AF_08<br>DF.                           |   |  |  |  |  |  |  |  |  |  |  | , 请检查        | :19                  | 02-D8-63@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>6JLAN<br>JP,00<br>25_38<br>D3_31<br>AF_08<br>DF.                           |   |  |  |
| 1002 | 福建邦达建设工程有限公司 | 2024-04-17 15:32 :22.0 | 04-CF-4B-34-FB-16,04 -CF-4B-34-FB-17,06 -CF-4B-34-FB-16, EC -D6-8A-EE-2B-8A@BF<br>EBFBF<br>F0009<br>0675@<br>6479_ A77B_ 2000_ 00AA. | 否 | 2024-04-17 15:31 :03.0 | 04-CF-4B-34-FB-16,04 -CF-4B-34-FB-17,06 -CF-4B-34-FB-16, EC -D6-8A-EE-2B-8A@BF<br>EBFBF<br>F0009<br>0675@<br>6479_ A77B_ 2000_ 00AA. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:52 :11 | 04-CF-4B-34-FB-16,04 -CF-4B-34-FB-17,06 -CF-4B-34-FB-16, EC -D6-8A-EE-2B-8A@BF<br>EBFBF<br>F0009<br>0675@<br>6479_ A77B_ 2000_ 00AA. | 否 |  |  |

|      |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |            |                     |  |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|------------|---------------------|--|--|---|--|
| 1003 | 福建兴邦建设工程有限公司 | 2024-04-23 10:27:25.0 | 18-31-BF-DD-57-14@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01278<br>, WD-<br>WCC6Y<br>4TP2R<br>XF         | 否 | 2024-04-23 10:08:50.0 | 18-31-BF-DD-57-14,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01278<br>, WD-<br>WCC6Y<br>4TP2R<br>XF | 否 |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:32:03 | 18-31-BF-DD-57-14@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01278<br>, WD-<br>WCC6Y<br>4TP2R<br>XF | 否  |   |  |
| 1004 | 福建齐庆建设工程有限公司 | 2024-04-23 14:46:51.0 | 18-C0-4D-C4-82-AC@BF<br>EBFBF<br>F000A<br>0653@<br>LD712<br>1R011<br>564<br>_0000<br>_0001.<br>, WD-<br>WCC6Y<br>2RE9A<br>FF | 否 | 2024-04-23 14:44:39.0 | 18-C0-4D-C4-82-AC@BF<br>EBFBF<br>F000A<br>0653@<br>LD712<br>1R011<br>564<br>_0000<br>_0001.<br>, WD-<br>WCC6Y<br>2RE9A<br>FF  | 否 |  |  |  |  |  |  |  |  |            | 校验数据有, 请检查          | 2024-04-24 08:44:10  | 18-C0-4D-C4-82-AC@BF<br>EBFBF<br>F000A<br>0653@<br>LD712<br>1R011<br>564<br>_0000<br>_0001.<br>, WD-<br>WCC6Y<br>2RE9A<br>FF | 否 |  |

|      |            |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |            |                     |   |   |
|------|------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|------------|---------------------|---|---|
| 1005 | 福建冠泉建设有限公司 | 2024-04-23 10:24:43.0 | D8-5E-D3-C6-73-F5,00-00-00-00-00-00-E0@BFEBFBF000A0653@3035323042363337313833434241434320202020,2020202057202d4443573643305941444e5a5830 | 否 | 2024-04-23 10:16:51.0 | D8-5E-D3-C6-73-F5,00-00-00-00-00-E0@BFEBFBF000A0653@303532304236333731383343424143432020,2020202057202d4443573643305941444e5a5830 | 否 |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:36:34 | D8-5E-D3-C6-73-F5,00-00-00-00-00-E0@BFEBFBF000A0653@303532304236333731383343424143432020,2020202057202d4443573643305941444e5a5830 | 否 |
|------|------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|------------|---------------------|---|---|

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1006 | 中建厚德建设有限公司    | 2024-04-23 20:06:19.0 | 88-AE-DD-45-1C-3E@BF EBFBF F000A 0671@WD-WCC6Y 4HY7A VL, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4B 2E_02 65.     | 否 | 2024-04-23 20:02:54.0 | 88-AE-DD-45-1C-3E@BF EBFBF F000A 0671@WD-WCC6Y 4HY7A VL, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4B 2E_02 65.     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:03 | 88-AE-DD-45-1C-3E@BF EBFBF F000A 0671@WD-WCC6Y 4HY7A VL, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4B 2E_02 65. | 否 |  |
| 1007 | 福建省君晟建设工程有限公司 | 2024-04-23 16:08:29.0 | 04-7C-16-57-5C-87,00 -FF- B1- F2- 71- 17@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B768_ 5B41_ 1485. | 否 | 2024-04-23 14:22:24.0 | 04-7C-16-57-5C-87,00 -FF- B1- F2- 71- 17@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B768_ 5B41_ 1485. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:04 | 2C-F0-5D-32-B2-1E,00 -FF- CC-9E-B4-57@BF EBFBF F0009 06ED@ 50026 B7380 94C56 F                            | 否 |  |

|      |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1008 | 卓辉（福建）建设工程有限公司  | 2024-04-23 14:57:16.0 | 18-31-BF-93-6E-5C@BFEBFBF000906E9@Z9AS8VWL   | 否 | 2024-04-23 14:55:42.0 | 18-31-BF-93-6E-5C,00-00-00-00-00-E0@BFEBFBF000906E9@Z9AS8VWL                                 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:10 | 18-31-BF-93-6E-5C@BFEBFBF000906E9@Z9AS8VWL   | 否 |  |
| 1009 | 福建省武夷鸿三建工发展有限公司 | 2024-04-22 15:23:51.0 | C8-5B-76-E0-2C-86,00-50-56-C0-00-01,00-50-56-C0-00-08@BFEBFBF000506E3@2N182LACG7LU,276T739NS | 否 | 2024-04-22 15:19:17.0 | C8-5B-76-E0-2C-86,00-50-56-C0-00-01,00-50-56-C0-00-08@BFEBFBF000506E3@2N182LACG7LU,276T739NS | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:51:33 | C8-5B-76-E0-2C-86,00-50-56-C0-00-01,00-50-56-C0-00-08@BFEBFBF000506E3@2N182LACG7LU,276T739NS | 否 |  |

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1010 | 福建省亿顺园林绿化工有限公司 | 2024-04-22 11:35:35.0 | 9C-5C-8E-94-FA-83@BF EBFBF F0003 06C3@S2TUN WAH13 7655T | 否 | 2024-04-22 11:12:56.0 | 9C-5C-8E-94-FA-83@BF EBFBF F0003 06C3@S2TUN WAH13 7655T                                     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:37 | 9C-5C-8E-94-FA-83@BF EBFBF F0003 06C3@S2TUN WAH13 7655T , Z9C5 3WMW | 否 |  |
| 1011 | 福建恒菲建设发展有限公司   | 2024-04-19 11:20:35.0 | F4-B5-20-17-C3-94@BF EBFBF F0009 06EB@WD-WCC6Y 1UVDL L9 | 否 | 2024-04-19 10:42:10.0 | F4-B5-20-17-C3-94,00-00-00-00-00-E0,00-00-00-00-00-E0@BF EBFBF F0009 06EB@WD-WCC6Y 1UVDL L9 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:13 | F4-B5-20-17-C3-94@BF EBFBF F0009 06EB@WD-WCC6Y 1UVDL L9             | 否 |  |

|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1012 | 福建京浩建设工程有限公司  | 2024-04-23 15:43:27.0 | E0-<br>D5-<br>5E-<br>CC-<br>71-<br>83@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7381<br>3DD24<br>1,AA0<br>00000<br>01009<br>00000<br>51 | 否 | 2024-04-23 15:39:01.0 | E0-<br>D5-<br>5E-<br>CC-<br>71-<br>83@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7381<br>3DD24<br>1,AA0<br>00000<br>01009<br>00000<br>51 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:46 | B4-<br>2E-<br>99-<br>03-<br>42-<br>9F,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7380<br>0E16C<br>5,500<br>26B73<br>80F07<br>828 | 否 |  |
| 1013 | 福建省莆生建设集团有限公司 | 2024-04-18 15:23:45.0 | 94-<br>DE-<br>80-<br>EB-<br>1E-<br>74@BF<br>EBFBF<br>F0003<br>06A9@<br>03406<br>02374<br>6,W -<br>DCW2C<br>NE5H5<br>487                  | 否 | 2024-04-18 15:21:47.0 | 94-<br>DE-<br>80-<br>EB-<br>1E-<br>74@BF<br>EBFBF<br>F0003<br>06A9@<br>03406<br>02374<br>6,W -<br>DCW2C<br>NE5H5<br>487                  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:24 | 94-<br>DE-<br>80-<br>EB-<br>1E-<br>74@BF<br>EBFBF<br>F0003<br>06A9@<br>03406<br>02374<br>6,W -<br>DCW2C<br>NE5H5<br>487   | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1014 | 中民经开建设有限公司   | 2024-04-23 20:15:30.0 | 48-F3-17-10-FE-58@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7382<br>1EDOF<br>C                                | 否 | 2024-04-23 11:43:04.0 | 48-F3-17-10-FE-58@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7382<br>1EDOF<br>C                                | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:42 | 48-F3-17-10-FE-58@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7382<br>1EDOF<br>C                                | 否 |  |
| 1015 | 福建田昆建设发展有限公司 | 2024-04-23 10:21:46.0 | 2C-F0-5D-00-5B-7C, 44-F9-71-18-58-A7@BF<br>EBFBF<br>F0009<br>06EA@<br>WK300<br>VQ7, C<br>M297A<br>C6301<br>996 | 否 | 2024-04-22 10:28:16.0 | 2C-F0-5D-00-5B-7C, 44-F9-71-18-58-A7@BF<br>EBFBF<br>F0009<br>06EA@<br>WK300<br>VQ7, C<br>M297A<br>C6301<br>996 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:10 | 2C-F0-5D-00-5B-7C, 44-F9-71-18-58-A7@BF<br>EBFBF<br>F0009<br>06EA@<br>WK300<br>VQ7, C<br>M297A<br>C6301<br>996 | 否 |  |



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1016 | 福建鑫九鼎建设有限公司  | 2024-04-20 10:22:34.0 | 58-11-22-C0-70-22@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 4926_ E098. | 否 | 2024-04-20 10:20:58.0 | 58-11-22-C0-70-22@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 4926_ E098. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:38 | 58-11-22-C0-70-22@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 4926_ E098. | 否 |  |
| 1017 | 福建晶石建设工程有限公司 | 2024-04-23 09:26:46.0 | D4-5D-64-01-D1-20@BF EBFBF F0009 06EB@ WD- WCC6Y 4JT8N AT, RC 20318 027D1 045          | 否 | 2024-04-23 09:25:21.0 | D4-5D-64-01-D1-20@BF EBFBF F0009 06EB@ WD- WCC6Y 4JT8N AT, RC 20318 027D1 045          | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:41:48 | D4-5D-64-01-D1-20@BF EBFBF F0009 06EB@ WD- WCC6Y 4JT8N AT, RC 20318 027D1 045          | 否 |  |

|      |               |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|--|---|--|
| 1018 | 龙岩市钰康建设发展有限公司 | 2024-04-23 18:56:14.0 | B4-2E-99-12-F4-49,00-00-00-00-00-00-06E9@978091892833                      | 否 | 2024-04-23 18:53:55.0 | B4-2E-99-12-F4-49,00-00-00-00-00-00-E0@BFEBFBF000906E9@978091892833                           | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:07 | B4-2E-99-12-F4-49@BFEBFBF000906E9@978091892833 | 否  |   |  |
| 1019 | 福建迈智建设工程有限公司  | 2024-04-23 15:17:57.0 | 3C-7C-3F-29-D3-C2@BFEBFBF000906EA@4a46343030393030343044362045202020202020 | 否 | 2024-04-23 15:15:49.0 | 3C-7C-3F-29-D3-C2,00-00-00-00-00-00-E0@BFEBFBF000906EA@4a463430303930303430443620452020202020 | 否 |  |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:32:52                            | 3C-7C-3F-29-D3-C2@BFEBFBF000906EA@4a463430303930303430443620452020202020 | 否 |  |

|      |              |                          |  |   |                          |   |   |  |  |  |  |  |  |  |  |                     |                        |   |   |   |  |
|------|--------------|--------------------------|--|---|--------------------------|---|---|--|--|--|--|--|--|--|--|---------------------|------------------------|---|---|---|--|
| 1020 | 江苏淮顺建设工程有限公司 | 2024-04-23<br>15:56:26.0 | B4-2E-99-02-<br>B1-7A@BF<br>EBFBF<br>F0009<br>06E9@<br>SN204<br>80890<br>9639  | 否 | 2024-04-23<br>10:55:59.0 | B4-2E-99-02-<br>B1-7A@BF<br>EBFBF<br>F0009<br>06E9@<br>SN204<br>80890<br>9639   | 否 |  |  |  |  |  |  |  |  |                     | 校验数据有<br>误, 请查<br>检    | 2024-04-24<br>08:37:46  | B4-2E-99-02-<br>B1-7A@BF<br>EBFBF<br>F0009<br>06E9@<br>SN204<br>80890<br>9639 | 否 |  |
| 1021 | 福建众禹建设工程有限公司 | 2024-04-22<br>11:27:14.0 | 44-F9-71-98-<br>E3-B3, 44<br>-F9-71-<br>98-E3-<br>B3, B4<br>-2E-99-<br>03-0A-<br>D9@BF<br>EBFBF<br>F0009<br>06EA@<br>41413<br>03030<br>30303<br>03030<br>30303<br>03030<br>03537<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>33594<br>44833<br>30304<br>1 | 否 | 2024-04-22<br>11:20:27.0 | 44-F9-71-98-<br>E3-B3, 44<br>-F9-71-<br>98-E3-<br>B3, B4<br>-2E-99-<br>03-0A-<br>D9, 00<br>-00-<br>00-00-<br>00-00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>41413<br>03030<br>30303<br>03030<br>30303<br>03537<br>, 2020<br>20205<br>7202d<br>44435<br>03030<br>30303<br>03537<br>, 2020<br>20205<br>7202d | 否 |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>检 | 2024-04-24<br>08:32:03 | 44-F9-71-98-<br>E3-B3, 44<br>-F9-71-<br>98-E3-<br>B3, B4<br>-2E-99-<br>03-0A-<br>D9@BF<br>EBFBF<br>F0009<br>06EA@<br>41413<br>03030<br>30303<br>03030<br>30303<br>03537<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>33594<br>44833<br>30304<br>1 | 否   |   |  |

|      |              |                       |   |                       |  |  |  |  |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |
|------|--------------|-----------------------|---|-----------------------|--|--|--|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|
|      |              |                       |   |                       | 44435<br>73643<br>33594<br>44833<br>30304<br>1 |  |  |  |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |
| 1022 | 武平闽禹建设发展有限公司 | 2024-04-23 16:13:17.0 | 否 | 2024-04-23 10:27:51.0 | 否  |  |  |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:31:40 | 否 | B4-<br>2E-<br>99-<br>7B-<br>15-<br>8D, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>SN193<br>40894<br>5465,<br>WD-<br>WCC6Y<br>1RAZD<br>2F |

|      |                 |                              |   |   |                              |  |   |  |  |  |  |  |  |  |  |                     |                            |   |   |
|------|-----------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|---------------------|----------------------------|---|---|
| 1023 | 福建煌金旺<br>建设有限公司 | 2024-04-23<br>11:22<br>:26.0 | 00-<br>E0-<br>70-<br>C0-<br>F4-<br>F2, 30<br>-32-<br>35-<br>10-<br>9C-<br>16, 30<br>-32-<br>35-<br>10-<br>9C-<br>15, 32<br>-32-<br>35-<br>10-<br>9C-<br>15, 32<br>-32-<br>35-<br>10-<br>9C-<br>15, B2<br>-32-<br>35-<br>10-<br>9C-<br>15@BF<br>EBFBF<br>F0009<br>06EB@<br>K3632<br>0J018<br>679 | 否 | 2024-04-23<br>11:21<br>:31.0 | 30-<br>32-<br>35-<br>10-<br>9C-<br>15, 32<br>-32-<br>35-<br>10-<br>9C-<br>15, B2<br>-32-<br>35-<br>10-<br>9C-<br>15, 00<br>-E0-<br>70-<br>C0-<br>F4-<br>F2, 30<br>-32-<br>35-<br>10-<br>9C-<br>16@BF<br>EBFBF<br>F0009<br>06EB@<br>K3632<br>0J018<br>679 | 否 |  |  |  |  |  |  |  |  | 校验数据<br>有错误，<br>请检查 | 2024-04-24<br>08:32<br>:03 | 00-<br>E0-<br>70-<br>C0-<br>F4-<br>F2, 30<br>-32-<br>35-<br>10-<br>9C-<br>16, 30<br>-32-<br>35-<br>10-<br>9C-<br>15, 32<br>-32-<br>35-<br>10-<br>9C-<br>15, 32<br>-32-<br>35-<br>10-<br>9C-<br>15, B2<br>-32-<br>35-<br>10-<br>9C-<br>15@BF<br>EBFBF<br>F0009<br>06EB@<br>K3632<br>0J018<br>679 | 否 |
|------|-----------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|---------------------|----------------------------|---|---|

|      |                 |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|-----------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1024 | 福建猎翔建设有限公司      | 2024-04-23 10:29:14.0 | EA-EB@BF<br>E0-EBFBF<br>AF-F0002<br>E9-06D7@<br>03-SY021<br>00-23000<br>00-00309<br>0,3W6<br>TRCL8       | 否 | 2024-04-23 10:23:29.0 | EA-EB,00<br>E0--00-<br>AF-00-<br>E9-00-<br>03-00-<br>EB,00-00-<br>E0,00-00-<br>EBFBF<br>F0002<br>06D7@<br>SY021<br>23000<br>00309<br>0,3W6<br>TRCL8 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:50 | EA-EB@BF<br>E0-EBFBF<br>AF-F0002<br>E9-06D7@<br>03-SY021<br>00-23000<br>00-00309<br>0,3W6<br>TRCL8       | 否 |  |
| 1025 | 福建省建信工程管理集团有限公司 | 2024-04-23 12:05:16.0 | A8-5E-45-9F-23-C5@BF<br>EBFBF<br>F0009<br>06EB@<br>20200<br>10601<br>800,W<br>D-<br>WCC6Y<br>6LYHU<br>CE | 否 | 2024-04-23 12:03:46.0 | A8-5E-45-9F-23-C5@BF<br>EBFBF<br>F0009<br>06EB@<br>20200<br>10601<br>800,W<br>D-<br>WCC6Y<br>6LYHU<br>CE  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:15 | A8-5E-45-9F-23-C5@BF<br>EBFBF<br>F0009<br>06EB@<br>20200<br>10601<br>800,W<br>D-<br>WCC6Y<br>6LYHU<br>CE | 否 |  |

|      |                      |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |              |                            |  |   |   |  |
|------|----------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|----------------------------|--|---|---|--|
| 1026 | 海峡曙光<br>(福建)建设发展有限公司 | 2024-04-23<br>16:23<br>:56.0 | 74-<br>56-<br>3C-<br>90-<br>FF-<br>A3, D4<br>-84-<br>09-<br>14-<br>CA-<br>82@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WX52D<br>53FHX<br>CD, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1F<br>7E_11<br>F5. | 否 | 2024-04-22<br>12:29<br>:01.0 | 74-<br>56-<br>3C-<br>90-<br>FF-<br>A3, D4<br>-84-<br>09-<br>14-<br>CA-<br>82@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WX52D<br>53FHX<br>CD, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1F<br>7E_11<br>F5. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24<br>09:00<br>:48 | 74-<br>56-<br>3C-<br>90-<br>FF-<br>A3, D4<br>-84-<br>09-<br>14-<br>CA-<br>82@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WX52D<br>53FHX<br>CD, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1F<br>7E_11<br>F5. | 否   |   |  |
| 1027 | 福建省邵武市润宇建设工程有限公司     | 2024-04-23<br>10:55<br>:45.0 | 00-<br>E2-<br>69-<br>63-<br>BF-<br>F8@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0001.   | 否 | 2024-04-23<br>10:51<br>:59.0 | 00-<br>E2-<br>69-<br>63-<br>BF-<br>F8@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0001.   | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有误差, 请检查               | 2024-04-24<br>08:47<br>:08   | 00-<br>E2-<br>69-<br>63-<br>BF-<br>F8@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0001. | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1028 | 福建中尔建设有限公司   | 2024-04-22 11:05:28.0 | D8-5E-D3-17-8E-A1@BF EBFBF F000A 0653@ 0025_38B1_11B2_2695. ,WD-WCC6Y KT03U VY | 否 | 2024-04-22 10:55:19.0 | D8-5E-D3-17-8E-A1@BF EBFBF F000A 0653@ 0025_38B1_11B2_2695. ,WD-WCC6Y KT03U VY | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:07 | D8-5E-D3-17-8E-A1@BF EBFBF F000A 0653@ 0025_38B1_11B2_2695. ,WD-WCC6Y KT03U VY | 否 |  |
| 1029 | 福建梦龙建设工程有限公司 | 2024-04-23 14:03:54.0 | 9C-5C-8E-CE-2D-D7@BF EBFBF F0003 06C3@ 50026 B7381 D45C7 7,WD-WCC6Y QJA9S EL   | 否 | 2024-04-23 10:27:38.0 | 9C-5C-8E-CE-2D-D7@BF EBFBF F0003 06C3@ 50026 B7381 D45C7 7                     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:05 | 9C-5C-8E-CE-2D-D7@BF EBFBF F0003 06C3@ 50026 B7381 D45C7 7,WD-WCC6Y QJA9S EL   | 否 |  |



|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|---|--|
| 1030 | 福建省凡澈建设发展有限公司 | 2024-04-23 11:17:50.0 | 24-4B-FE-78-EA-30@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>1ARJK<br>79, AA<br>00000<br>00000<br>00004<br>717_0<br>00000<br>01. | 否 | 2024-04-19 16:44:57.0 | 24-4B-FE-78-EA-30@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>1ARJK<br>79, AA<br>00000<br>00000<br>00004<br>717_0<br>00000<br>01. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:39 | 24-4B-FE-78-EA-30@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>1ARJK<br>79, AA<br>00000<br>00000<br>00004<br>717_0<br>00000<br>01. | 否   |   |  |
| 1031 | 福建上澳建设有限公司    | 2024-04-23 17:41:27.0 | 70-85-C2-90-63-73@17<br>8BFBF<br>F0081<br>0F10@<br>6479_<br>A74B_<br>F000_<br>007D.  | 否 | 2024-04-23 17:39:15.0 | 70-85-C2-90-63-73@17<br>8BFBF<br>F0081<br>0F10@<br>6479_<br>A74B_<br>F000_<br>007D.  | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:50:55  | 70-85-C2-90-63-73@17<br>8BFBF<br>F0081<br>0F10@<br>6479_<br>A74B_<br>F000_<br>007D. | 否 |  |



|      |              |                       |   |                       |   |  |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|--------------|-----------------------|---|-----------------------|---|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1033 | 福建佳翔建设工程有限公司 | 2024-04-22 18:06:01.0 | 否 | 2024-04-22 17:52:39.0 | 否 | 2C-F0-5D-5B-A4-C5,00-00-00-00-00-E0,00-00-00-00-06EA@3035323042363337303836413745413520202020,2020202057202d4443573643305945594a314430 | 2C-F0-5D-5B-A4-C5,00-00-00-00-00-E0,00-00-00-00-06EA@3035323042363337303836413745413520202020,2020202057202d4443573643305945594a314430 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:47 | 2C-F0-5D-5B-A4-C5@BFEBFBFF000906EA@3035323042363337303836413745413520202020,2020202057202d4443573643305945594a314430 | 否 |  |
|------|--------------|-----------------------|---|-----------------------|---|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1034 | 福州四建建筑工程有限公司 | 2024-04-22 16:18:37.0 | 50-EB-F6-7C-52-D3@BFEBFBFF000A0653@GV211127SG00002683   | 否 | 2024-04-22 16:15:30.0 | 50-EB-F6-7C-52-D3@BFEBFBFF000A0653@GV211127SG00002683   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:40:04 | 50-EB-F6-7C-52-D3@BFEBFBFF000A0653@GV211127SG00002683   | 否 |  |
| 1035 | 福建中耀铭筑建设有限公司 | 2024-04-22 08:38:15.0 | 1C-1B-0D-44-9C-FB@BFEBFBFF000506E3@414130303030303032383037303034333533, 2020202057202d444357364335594a53434b5241 | 否 | 2024-04-22 08:23:21.0 | 1C-1B-0D-44-9C-FB@BFEBFBFF000506E3@414130303030303032383037303034333533, 2020202057202d444357364335594a53434b5241 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:33:12 | 1C-1B-0D-44-9C-FB@BFEBFBFF000506E3@414130303030303032383037303034333533, 2020202057202d444357364335594a53434b5241 | 否 |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1036 | 福建众德建设股份有限公司  | 2024-04-23 11:14:37.0 | 00-<br>E0-<br>4C-<br>83-<br>92-<br>20@17<br>8BFBF<br>F00A2<br>0F12@<br>6479_<br>A76D_<br>3F00_<br>5FC6. | 否 | 2024-04-23 09:07:01.0 | 00-<br>E0-<br>4C-<br>83-<br>92-<br>20@17<br>8BFBF<br>F00A2<br>0F12@<br>6479_<br>A76D_<br>3F00_<br>5FC6. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:18 | 00-<br>E0-<br>4C-<br>83-<br>92-<br>20@17<br>8BFBF<br>F00A2<br>0F12@<br>6479_<br>A76D_<br>3F00_<br>5FC6. | 否 |  |
| 1037 | 中城鼎（厦门）建设有限公司 | 2024-04-23 16:33:17.0 | 50-<br>EB-<br>F6-<br>EE-<br>96-<br>7D@BF<br>EBFBF<br>F000A<br>0653@<br>FM300<br>4S204<br>9G000<br>954   | 否 | 2024-04-23 16:32:20.0 | 50-<br>EB-<br>F6-<br>EE-<br>96-<br>7D@BF<br>EBFBF<br>F000A<br>0653@<br>FM300<br>4S204<br>9G000<br>954   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:15 | 50-<br>EB-<br>F6-<br>EE-<br>96-<br>7D@BF<br>EBFBF<br>F000A<br>0653@<br>FM300<br>4S204<br>9G000<br>954   | 否 |  |

|      |                |                              |   |   |                              |  |   |  |  |  |  |  |  |  |  |                                |                            |  |   |  |
|------|----------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--------------------------------|----------------------------|--|---|--|
| 1038 | 天逸建设集<br>团有限公司 | 2024-04-23<br>18:59<br>:57.0 | 74-<br>56-<br>3C-<br>9C-<br>D0-<br>FD, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>0026_<br>B738_<br>294A_<br>BF45. | 否 | 2024-04-23<br>18:54<br>:42.0 | 74-<br>56-<br>3C-<br>9C-<br>D0-<br>FD, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>0026_<br>B738_<br>294A_<br>BF45. | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，<br>请<br>检查 | 2024-04-24<br>08:45<br>:08 | 74-<br>56-<br>3C-<br>9C-<br>D0-<br>FD, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>0026_<br>B738_<br>294A_<br>BF45. | 否 |  |
|------|----------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--------------------------------|----------------------------|--|---|--|

|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1039 | 福建强翔建筑有限公司 | 2024-04-23 15:01:06.0 | 74-D4-35-04-2D-61@BFEBFBF000306C3@SN234008914947 | 否 | 2024-04-23 14:59:33.0 | 74-D4-35-04-2D-61@BFEBFBF000306C3@SN234008914947 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:18 | 08-60-6E-7F-B6-60,00-00-00-00-00-00-00-00-00-00-00-00-EQ@BFEBFBF000306A9@3035323042363337313831414536464620202020 | 否 |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|

|      |                    |                              |   |   |                              |  |   |  |  |  |  |  |  |  |  |  |  |   |  |   |  |
|------|--------------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|---|--|---|--|
| 1040 | 福建省环睿<br>建设工程有限公司  | 2024-04-19<br>15:47<br>:56.0 | B4-<br>2E-<br>99-<br>20-<br>1D-<br>B9, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@17<br>8BFBF<br>F0066<br>0F01@<br>43383<br>53045<br>39503<br>04a41<br>34303<br>53120<br>33202<br>02020<br>, 3032<br>32313<br>73130<br>41303<br>03330<br>34322<br>03720<br>20202<br>0, 303<br>23931<br>32303<br>73234<br>30353<br>12033<br>20202<br>02020<br>20 | 否 | 2024-04-19<br>15:08<br>:01.0 | B4-<br>2E-<br>99-<br>20-<br>1D-<br>B9, 00<br>-00-<br>00-<br>00-<br>00-<br>E0@17<br>8BFBF<br>F0066<br>0F01@<br>43383<br>53045<br>39503<br>04a41<br>34303<br>53120<br>33202<br>02020<br>, 3032<br>32313<br>73130<br>41303<br>03330<br>34322<br>03720<br>20202<br>0, 303<br>23931<br>32303<br>73234<br>30353<br>12033<br>20202<br>02020<br>20 | 否 |  |  |  |  |  |  |  |  |  |  | 74-<br>5D-<br>22-<br>F5-<br>9E-<br>7D, D4<br>-E9-<br>8A-<br>CF-<br>92-<br>42, D4<br>-E9-<br>8A-<br>CF-<br>92-<br>3E, D4<br>-E9-<br>8A-<br>CF-<br>92-<br>3F, D6<br>-E9-<br>8A-<br>CF-<br>92-<br>3E@BF<br>EBFBF<br>F000B<br>0671@<br>43303<br>63636<br>39312<br>E, 5CD<br>F_B80<br>3_AOA<br>0_259<br>0. | 否  |   |  |
| 1041 | 福建省鑫福<br>洋建设工程有限公司 | 2024-04-23<br>10:32<br>:47.0 | 00-<br>E0-<br>4C-<br>59-<br>27-<br>16@BF<br>EBFBF<br>F000A  | 否 | 2024-04-23<br>10:24<br>:20.0 | 00-<br>E0-<br>4C-<br>59-<br>27-<br>16@BF<br>EBFBF<br>F000A   | 否 |  |  |  |  |  |  |  |  |  |  |   | 00-<br>E0-<br>4C-<br>59-<br>27-<br>16@BF<br>EBFBF<br>F000A | 否 |  |



|      |                   |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
|------|-------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|
|      |                   |                                  | 0653@<br>23082<br>N8051<br>44, WQ<br>91PMY<br>T   |   |                                  | 0653@<br>23082<br>N8051<br>44, WQ<br>91PMY<br>T   |   |  |  |  |  |  |  |  |  |                            |                                | 0653@<br>23082<br>N8051<br>44, WQ<br>91PMY<br>T  |   |  |
| 1042 | 福建省卓为<br>建设工程有限公司 | 2024-<br>04-22<br>17:40<br>:29.0 | 00-<br>E0-<br>70-<br>CC-<br>C4-<br>BA, 02<br>-E0-<br>4C-<br>9B-<br>47-<br>46, 82<br>-E0-<br>4C-<br>9B-<br>47-<br>46, 00<br>-E0-<br>4C-<br>9B-<br>47-<br>46, 00<br>-E0-<br>4C-<br>9B-<br>47-<br>46@BF<br>EBFBF<br>F000A<br>0653@<br>058F6<br>36664<br>38, 30<br>05951<br>7334,<br>001CC<br>0EC34<br>E1BB7<br>OD715<br>004D | 否 | 2024-<br>04-22<br>17:38<br>:51.0 | 00-<br>E0-<br>70-<br>CC-<br>C4-<br>BA, 02<br>-E0-<br>4C-<br>9B-<br>47-<br>46, 82<br>-E0-<br>4C-<br>9B-<br>47-<br>46, 00<br>-E0-<br>4C-<br>9B-<br>47-<br>46, 00<br>-E0-<br>4C-<br>9B-<br>47-<br>46@BF<br>EBFBF<br>F000A<br>0653@<br>058F6<br>36664<br>38, 30<br>05951<br>7334,<br>001CC<br>0EC34<br>E1BB7<br>OD715<br>004D | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:34<br>:15 | 00-<br>E0-<br>4C-<br>9B-<br>47-<br>46, 00<br>-E0-<br>70-<br>CC-<br>C4-<br>BA, 00<br>-E0-<br>4C-<br>9B-<br>47-<br>46, 02<br>-E0-<br>4C-<br>9B-<br>47-<br>46, 82<br>-E0-<br>4C-<br>9B-<br>47-<br>46@BF<br>EBFBF<br>F000A<br>0653@<br>058F6<br>36664<br>38, 30<br>05951<br>7334 | 否 |  |







|      |            |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |           |                     |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-----------|---------------------|--|---|--|
| 1048 | 福建其佑建设有限公司 | 2024-04-23 11:18:41.0 | E0-D5-5E-FC-97-25@BF EBFBF F0009 06EB@786546283274,ZTB4500BA234820B2B                        | 否 | 2024-04-23 11:16:26.0 | E0-D5-5E-FC-97-25@BF EBFBF F0009 06EB@786546283274,ZTB4500BA234820B2B   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:36:02 | E0-D5-5E-FC-97-25@BF EBFBF F0009 06EB@786546283274,ZTB4500BA234820B2B                        | 否 |  |
| 1049 | 福建务科建设有限公司 | 2024-04-23 08:25:00.0 | 08-BF-B8-9C-C6-81@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0100_0000_0000. ,WX22A735AA90 | 否 | 2024-04-22 16:13:50.0 | 08-BF-B8-9C-C6-81@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0100_0000_0000. ,3727125557311494,WX22A735AA90 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:31:49 | 08-BF-B8-9C-C6-81@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0100_0000_0000. ,WX22A735AA90 | 否 |  |

|      |                      |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |                            |                            |   |  |   |  |
|------|----------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|--|---|--|
| 1050 | 福建鸿瑞祥<br>建设工程有限公司    | 2024-04-23<br>15:06<br>:19.0 | 58-<br>11-<br>22-<br>A0-<br>AD-<br>7D@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>199A_<br>7565. | 否 | 2024-04-23<br>15:04<br>:17.0 | 58-<br>11-<br>22-<br>A0-<br>AD-<br>7D@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>199A_<br>7565. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:31<br>:49 | 58-<br>11-<br>22-<br>A0-<br>AD-<br>7D@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>199A_<br>7565. | 否  |   |  |
| 1051 | 天中建设<br>(福建)有<br>限公司 | 2024-04-23<br>08:26<br>:14.0 | 04-<br>D9-<br>F5-<br>D0-<br>4B-<br>B8@BF<br>EBFBF<br>F0009<br>06EB@<br>30088<br>20873<br>7,WD-<br>WCC6Y<br>1VRDD<br>LZ                      | 否 | 2024-04-23<br>08:24<br>:20.0 | 04-<br>D9-<br>F5-<br>D0-<br>4B-<br>B8@BF<br>EBFBF<br>F0009<br>06EB@<br>30088<br>20873<br>7,WD-<br>WCC6Y<br>1VRDD<br>LZ                      | 否 |  |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:34<br>:11  | 04-<br>D9-<br>F5-<br>D0-<br>4B-<br>B8@BF<br>EBFBF<br>F0009<br>06EB@<br>30088<br>20873<br>7,WD-<br>WCC6Y<br>1VRDD<br>LZ | 否 |  |
| 1052 | 安徽楚兴建<br>设有限公司       | 2024-04-23<br>15:05<br>:45.0 | 74-<br>56-<br>3C-<br>83-<br>E6-<br>06@BF<br>EBFBF<br>F0009<br>06EA@<br>NKC99<br>22024<br>2400S<br>304                                       | 否 | 2024-04-22<br>13:05<br>:41.0 | 74-<br>56-<br>3C-<br>83-<br>E6-<br>06@BF<br>EBFBF<br>F0009<br>06EA@<br>NKC99<br>22024<br>2400S<br>304                                       | 否 |  |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:34<br>:47  | 74-<br>56-<br>3C-<br>83-<br>E6-<br>06@BF<br>EBFBF<br>F0009<br>06EA@<br>NKC99<br>22024<br>2400S<br>304                  | 否 |  |

|      |                  |                          |  |   |                          |   |   |  |  |  |  |  |  |  |  |  |                            |                        |   |   |  |  |
|------|------------------|--------------------------|--|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|---|---|--|--|
| 1053 | 福建大唐天<br>下建设有限公司 | 2024-04-17<br>09:15:48.0 | 18-31-<br>BF-<br>BD-<br>A0-<br>57,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>4c4b3<br>33230<br>42303<br>33841<br>32413<br>43120<br>32202<br>02020<br>,5359<br>30323<br>23132<br>38533<br>34842<br>304d3<br>53420<br>36202<br>0 | 否 | 2024-04-17<br>09:12:52.0 | 18-31-<br>BF-<br>BD-<br>A0-<br>57,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>4c4b3<br>33230<br>42303<br>33841<br>32413<br>43120<br>32202<br>02020<br>,5359<br>30323<br>23132<br>38533<br>34842<br>304d3<br>53420<br>36202<br>0 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>,请<br>检查 | 2024-04-24<br>08:35:02 | 18-31-<br>BF-<br>BD-<br>A0-<br>57,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>4c4b3<br>33230<br>42303<br>33841<br>32413<br>43120<br>32202<br>02020<br>,5359<br>30323<br>23132<br>38533<br>34842<br>304d3<br>53420<br>36202<br>0 | 否 |  |  |
|------|------------------|--------------------------|--|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|---|---|--|--|

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |  |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|--|---|--|
| 1054 | 林明建设有限公司     | 2024-04-23 10:04:44.0 | 20-88-10-7B-1B-B8, A0-59-50-E4-CC-DA, A0-59-50-E4-CC-DB, A2-59-50-E4-CC-DA@BFEBFBF00090675@0000_0000_0100_0000_E4D2_5C5C_2C5D_5501. | 否 | 2024-04-23 10:03:16.0 | 20-88-10-7B-1B-B8, A0-59-50-E4-CC-DA, A0-59-50-E4-CC-DB, A2-59-50-E4-CC-DA@BFEBFBF00090675@0000_0000_0100_0000_E4D2_5C5C_2C5D_5501. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:52 | 20-88-10-7B-1B-B8, A0-59-50-E4-CC-DA, A0-59-50-E4-CC-DB, A2-59-50-E4-CC-DA@BFEBFBF00090675@0000_0000_0100_0000_E4D2_5C5C_2C5D_5501. | 否  |   |  |
| 1055 | 福建硕源建设发展有限公司 | 2024-04-23 17:47:03.0 | C8-7F-54-A8-F0-6F@BFEBFBF000A0653@E823_8FA6_BF53_0001_001B_444A_49DF_BF21.  | 否 | 2024-04-23 16:13:19.0 | C8-7F-54-A8-F0-6F@BFEBFBF000A0653@E823_8FA6_BF53_0001_001B_444A_49DF_BF21.  | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:34:27   | C8-7F-54-A8-F0-6F@BFEBFBF000A0653@E823_8FA6_BF53_0001_001B_444A_49DF_BF21. | 否 |  |



|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|---|--|
| 1056 | 林孚建设有限公司      | 2024-04-19 16:49:09.0 | 48-F3-17-11-3E-E2@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 00E0_ 4C19_ 2D9B_ 574B. | 否 | 2024-04-19 15:13:17.0 | 48-F3-17-11-3E-E2@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 00E0_ 4C19_ 2D9B_ 574B. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:18 | 48-F3-17-11-3E-E2@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 00E0_ 4C19_ 2D9B_ 574B. | 否   |   |  |
| 1057 | 福建省为民建设工程有限公司 | 2024-04-22 18:29:51.0 | 18-C0-4D-C8-9F-73@BF EBFBF F000A 0653@ WD-WCC6Y 5VAN2 27, SN 21030 89721 78            | 否 | 2024-04-22 18:28:41.0 | 18-C0-4D-C8-9F-73@BF EBFBF F000A 0653@ WD-WCC6Y 5VAN2 27, SN 21030 89721 78            | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:33:07  | 18-C0-4D-C8-9F-73@BF EBFBF F000A 0653@ WD-WCC6Y 5VAN2 27, SN 21030 89721 78 | 否 |  |

|      |                   |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |                         |                         |   |   |   |  |
|------|-------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|-------------------------|-------------------------|---|---|---|--|
| 1058 | 福建鑫华筑<br>建设工程有限公司 | 2024-04-23<br>08:47:55.0 | 04-<br>D9-<br>F5-<br>21-<br>50-<br>B3@BF<br>EBFBF<br>F0009<br>06EB@<br>SAZ19<br>07160<br>2468,<br>WD-<br>WMC3F<br>21749<br>32 | 否 | 2024-04-22<br>11:32:17.0 | 04-<br>D9-<br>F5-<br>21-<br>50-<br>B3, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>SAZ19<br>07160<br>2468,<br>WD-<br>WMC3F<br>21749<br>32 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:37:46  | 04-<br>D9-<br>F5-<br>21-<br>50-<br>B3@BF<br>EBFBF<br>F0009<br>06EB@<br>SAZ19<br>07160<br>2468,<br>WD-<br>WMC3F<br>21749<br>32 | 否   |   |  |
| 1059 | 福建省荣联<br>建筑工程有限公司 | 2024-04-22<br>16:08:25.0 | 74-<br>56-<br>3C-<br>15-<br>01-<br>AD@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A779_<br>10C0_<br>OAC2.                       | 否 | 2024-04-22<br>15:33:17.0 | 74-<br>56-<br>3C-<br>15-<br>01-<br>AD@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A779_<br>10C0_<br>OAC2.   | 否 |  |  |  |  |  |  |  |  |  |                         | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:32:50  | 74-<br>56-<br>3C-<br>15-<br>01-<br>AD@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A779_<br>10C0_<br>OAC2. | 否 |  |





|      |                   |                              |   |   |                              |  |   |  |  |  |  |  |  |  |  |  |                               |                            |   |   |
|------|-------------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------------------------|----------------------------|---|---|
| 1063 | 福建隈研吾<br>建设工程有限公司 | 2024-04-23<br>13:51<br>:48.0 | A4-<br>AE-<br>12-<br>F3-<br>73-<br>96, E8<br>-F4-<br>08-<br>EC-<br>70-<br>51, 00<br>-FF-<br>F9-<br>31-<br>1A-<br>CD, E8<br>-F4-<br>08-<br>EC-<br>70-<br>4D, E8<br>-F4-<br>08-<br>EC-<br>70-<br>4E, EA<br>-F4-<br>08-<br>EC-<br>70-<br>4D@BF<br>EBFBF<br>F000A<br>0653@<br>044A_<br>5001_<br>1150_<br>1661.<br>, 11IX<br>6PGMS | 否 | 2024-04-23<br>11:23<br>:49.0 | A4-<br>AE-<br>12-<br>F3-<br>73-<br>96, E8<br>-F4-<br>08-<br>EC-<br>70-<br>4E, EA<br>-F4-<br>08-<br>EC-<br>70-<br>4D, 00<br>-FF-<br>F9-<br>31-<br>1A-<br>CD, E8<br>-F4-<br>08-<br>EC-<br>70-<br>4D, E8<br>-F4-<br>08-<br>EC-<br>70-<br>4D, E8<br>-F4-<br>08-<br>EC-<br>70-<br>51@BF<br>EBFBF<br>F000A<br>0653@<br>044A_<br>5001_<br>1150_<br>1661.<br>, 11IX<br>6PGMS | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>检查 | 2024-04-24<br>09:00<br>:08 | A4-<br>AE-<br>12-<br>F3-<br>73-<br>96, E8<br>-F4-<br>08-<br>EC-<br>70-<br>51, 00<br>-FF-<br>F9-<br>31-<br>1A-<br>CD, E8<br>-F4-<br>08-<br>EC-<br>70-<br>4D, E8<br>-F4-<br>08-<br>EC-<br>70-<br>4E, EA<br>-F4-<br>08-<br>EC-<br>70-<br>4D@BF<br>EBFBF<br>F000A<br>0653@<br>044A_<br>5001_<br>1150_<br>1661.<br>, 11IX<br>6PGMS | 否 |
|------|-------------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------------------------|----------------------------|---|---|

|      |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1064 | 福建省八隆建设工程有限公司 | 2024-04-22 18:49:30.0 | 00-<br>E0-<br>4C-<br>5F-<br>69-<br>44@17<br>8BFBF<br>F0061<br>OF31@<br>YX214<br>9JS12<br>0A089<br>33                          | 否 | 2024-04-22 18:44:09.0 | 00-<br>E0-<br>4C-<br>5F-<br>69-<br>44,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@17<br>8BFBF<br>F0061<br>OF31@<br>YX214<br>9JS12<br>0A089<br>33 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:39:18 | 00-<br>E0-<br>4C-<br>5F-<br>69-<br>44@17<br>8BFBF<br>F0061<br>OF31@<br>YX214<br>9JS12<br>0A089<br>33                          | 否 |  |
| 1065 | 福建拓元建设有限公司    | 2024-04-23 10:31:42.0 | D4-<br>5D-<br>64-<br>07-<br>03-<br>DD@BF<br>EBFBB<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>2JVYL<br>50, MX<br>_2005<br>61341<br>7 | 否 | 2024-04-23 10:25:21.0 | D4-<br>5D-<br>64-<br>07-<br>03-<br>DD@BF<br>EBFBB<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>2JVYL<br>50, MX<br>_2005<br>61341<br>7                            | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:37:30 | D4-<br>5D-<br>64-<br>07-<br>03-<br>DD@BF<br>EBFBB<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>2JVYL<br>50, MX<br>_2005<br>61341<br>7 | 否 |  |

|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|
| 1066 | 福建强禹建设有限公司 | 2024-04-23 10:36:00.0 | A0-36-BC-AB-98-DE@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>53036<br>34353<br>53837<br>20322<br>02020<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73243<br>36455<br>a4e35<br>34354<br>8 | 否 | 2024-04-23 09:06:46.0 | A0-36-BC-AB-98-DE,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>53036<br>34353<br>53837<br>20322<br>02020<br>20202<br>,2020<br>20205<br>7202d<br>44435<br>,2020<br>20205<br>7202d<br>44435<br>73243<br>36455<br>a4e35<br>34354<br>8 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:10 | A0-36-BC-AB-98-DE@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>53036<br>34353<br>53837<br>20322<br>02020<br>20202<br>,2020<br>20205<br>7202d<br>44435<br>73243<br>36455<br>a4e35<br>34354<br>8 | 否 |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|





|      |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |                     |  |   |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|---------------------|--|---|
| 1068 | 福建宁越建设工程有限公司 | 2024-04-23 16:44:38.0 | 1C-<br>A0-<br>B8-<br>7E-<br>F7-<br>BA, 08<br>-71-<br>90-<br>DB-<br>11-<br>13, 08<br>-71-<br>90-<br>DB-<br>11-<br>14, 0A<br>-71-<br>90-<br>DB-<br>11-<br>13@BF<br>EBFBF<br>F0009<br>06EB@<br>822BV<br>9HNS,<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>513E_<br>E025. | 否 | 2024-04-23 10:10:49.0 | B4-<br>2E-<br>99-<br>7A-<br>9E-<br>26, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>11-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>ODHRK<br>EJ | 否 |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  | 2024-04-24 08:43:00 | 1C-<br>A0-<br>B8-<br>7E-<br>F7-<br>BA, 08<br>-71-<br>90-<br>DB-<br>11-<br>13, 08<br>-71-<br>90-<br>DB-<br>11-<br>14, 0A<br>-71-<br>90-<br>DB-<br>11-<br>13@BF<br>EBFBF<br>F0009<br>06EB@<br>822BV<br>9HNS,<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>513E_<br>E025. | 否 |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|---------------------|--|---|

校验数据有误, 请检查

|      |                 |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1069 | 中立冠建设集团(福建)有限公司 | 2024-04-23 10:31:52.0 | A0-36-BC-22-72-BF@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>45FC_<br>CB28.     | 否 | 2024-04-23 10:30:53.0 | A0-36-BC-22-72-BF@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>45FC_<br>CB28.     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:54 | A0-36-BC-22-72-BF@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>45FC_<br>CB28.     | 否 |  |
| 1070 | 中创国际建设集团有限公司    | 2024-04-22 11:58:42.0 | D8-5E-D3-C5-94-4B@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2210_<br>0042_<br>3A5A_<br>2703_<br>5000_<br>150D. | 否 | 2024-04-22 11:43:43.0 | D8-5E-D3-C5-94-4B@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2210_<br>0042_<br>3A5A_<br>2703_<br>5000_<br>150D. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:47:54 | D8-5E-D3-C5-94-23@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2210_<br>0042_<br>3A5A_<br>2703_<br>6000_<br>157E. | 否 |  |
| 1071 | 福建荣科建设有限公司      | 2024-04-23 12:52:27.0 | D8-5E-D3-71-67-23@BF<br>EBFBF<br>F000A<br>0653@<br>30051<br>54294<br>8  | 否 | 2024-04-23 12:50:37.0 | D8-5E-D3-71-67-23@BF<br>EBFBF<br>F000A<br>0653@<br>30051<br>54294<br>8  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:14 | D8-5E-D3-71-67-23@BF<br>EBFBF<br>F000A<br>0653@<br>30051<br>54294<br>8  | 否 |  |

|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1072 | 正禹建设有限公司   | 2024-04-22 16:05:48.0 | B4-2E-99-E2-FF-37@178BFBF F00870F10@WD-WCC6Y6XAVE7D, J36389J014863 | 否 | 2024-04-22 15:43:39.0 | B4-2E-99-E2-FF-37@178BFBF F00870F10@WD-WCC6Y6XAVE7D, J36389J014863 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:42 | B4-2E-99-E2-FF-37@178BFBF F00870F10@WD-WCC6Y6XAVE7D, J36389J014863 | 否 |  |
| 1073 | 福建豪赫实业有限公司 | 2024-04-23 11:01:47.0 | 04-D9-F5-F3-69-87@BFEBFBF F000906EB@WD-WCC6Y6RS7VAS, P23050701363  | 否 | 2024-04-22 10:23:15.0 | 04-D9-F5-F3-69-87@BFEBFBF F000906EB@WD-WCC6Y6RS7VAS, P23050701363  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:22 | 04-D9-F5-F3-69-87@BFEBFBF F000906EB@WD-WCC6Y6RS7VAS, P23050701363  | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1074 | 福建天固建设工程有限公司 | 2024-04-23 11:01:41.0 | 74-D4-35-22-7B-14@BF EBFBF F0003 06A9@ 4a323 03130 32393 03338 32382 02020 20202 02020 , 3035 32304 23633 37313 84234 39384 23220 20202 0 | 否 | 2024-04-23 10:59:38.0 | 74-D4-35-22-7B-14, 00 -00- 00- 00- 00- 00- 00- 00- 06A9@ 4a323 03130 32393 03338 32382 02020 20202 , 3035 32304 23633 37313 84234 39384 23220 20202 0 | 否 |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:49 | 74-D4-35-22-7B-14@BF EBFBF F0003 06A9@ 4a323 03130 32393 03338 32382 02020 20202 02020 , 3035 32304 23633 37313 84234 39384 23220 20202 0 | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1075 | 河南酬安建设工程有限公司 | 2024-04-24 00:16:42.0 | 00-<br>E0-<br>4C-<br>F5-<br>03-<br>AD@BF<br>EBFBF<br>F000B<br>06F5@<br>0000_<br>0006_<br>0000_<br>0000_<br>0000_<br>3A5A_<br>2702_<br>3000_<br>1124. | 否 | 2024-04-23 23:12:44.0 | 00-<br>E0-<br>4C-<br>F5-<br>03-<br>AD@BF<br>EBFBF<br>F000B<br>06F5@<br>0000_<br>0006_<br>0000_<br>0000_<br>0000_<br>3A5A_<br>2702_<br>3000_<br>1124. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:44:01 | 00-<br>E0-<br>4C-<br>F5-<br>03-<br>AD@BF<br>EBFBF<br>F000B<br>06F5@<br>0000_<br>0006_<br>0000_<br>0000_<br>0000_<br>3A5A_<br>2702_<br>3000_<br>1124. | 否 |  |
| 1076 | 笙凌建设有限公司     | 2024-04-23 20:45:28.0 | 08-<br>BF-<br>B8-<br>BB-<br>24-<br>5C@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2856_<br>52A5.          | 否 | 2024-04-23 20:37:06.0 | 08-<br>BF-<br>B8-<br>BB-<br>24-<br>5C@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2856_<br>52A5.          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:15 | 08-<br>BF-<br>B8-<br>BB-<br>24-<br>5C@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2856_<br>52A5.          | 否 |  |

|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1077 | 福建省中诚永固建筑有限公司 | 2024-04-22 08:58:29.0 | 74-56-3C-04-D4-E3, F4-84-8D-83-92-5E, F6-84-8D-83-92-5E@BFEBFBF000A0653@FM6005N2249H000081_00000001. | 否 | 2024-04-22 08:29:35.0 | 74-56-3C-04-D4-E3, F6-84-8D-83-92-5E, F4-84-8D-83-92-5E@BFEBFBF000A0653@FM6005N2249H000081_00000001. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:46 | 74-56-3C-04-D4-E3, F6-84-8D-83-92-5E, F4-84-8D-83-92-5E@BFEBFBF000A0653@FM6005N2249H000081_00000001. | 否 |  |
| 1078 | 福建宏运建设工程有限公司  | 2024-04-23 20:10:02.0 | 00-E2-69-4E-E9-53@BFEBFBF000A0653@3679R213906304,Z9ATM70V  | 否 | 2024-04-23 20:08:06.0 | 00-E2-69-4E-E9-53@BFEBFBF000A0653@3679R213906304,Z9ATM70V  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:39:37 | 00-E2-69-4E-E9-53@BFEBFBF000A0653@3679R213906304,Z9ATM70V  | 否 |  |

|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |           |                     |  |                      |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-----------|---------------------|--|----------------------|---|--|
| 1079 | 福建吴润建设工程有限公司  | 2024-04-23 17:35:43.0 | 04-D4-C4-EF-07-01@BF EBFBF F0009 06EB@RZ196 29225 A0838, WD-WCC6Y 1CRLZ J1   | 否 | 2024-04-23 17:34:54.0 | 04-D4-C4-EF-07-01@BF EBFBF F0009 06EB@RZ196 29225 A0838, WD-WCC6Y 1CRLZ J1   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:48:35 | 04-D4-C4-EF-07-01@BF EBFBF F0009 06EB@RZ196 29225 A0838, WD-WCC6Y 1CRLZ J1   | 否                    |   |  |
| 1080 | 福建省高鹏建设工程有限公司 | 2024-04-23 15:03:32.0 | 00-E0-70-D6-A1-C4, 00-E0-4C-89-B8-52@BF EBFBF F000A 0653@E823_8FA6_BF53_0001_001B_448B_452C_0B40., 4150 32543 13038 0A | 否 | 2024-04-23 15:01:02.0 | 00-E0-70-D6-A1-C4, 00-E0-4C-89-B8-52@BF EBFBF F000A 0653@E823_8FA6_BF53_0001_001B_448B_452C_0B40., 4150 32543 13038 0A | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:38:39 | 00-E0-70-D6-A1-C4, 00-E0-4C-89-B8-52@BF EBFBF F000A 0653@E823_8FA6_BF53_0001_001B_448B_452C_0B40., 4150 32543 13038 0A | 否                    |   |  |
| 1081 | 南平三建建筑工程有限公司  | 2024-04-22 17:09:02.0 | A0-36-BC-2B-F2-6A@BF   | 否 | 2024-04-22 17:07:06.0 | A0-36-BC-2B-F2-6A, 00  | 否 |  |  |  |  |  |  |  |  |  |           | 校验数据有, 请查           | 2024-04-24 08:34:17  | A0-36-BC-2B-F2-6A@BF | 否 |  |

|  |  |  |   |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |   |  |  |
|--|--|--|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|---|--|--|
|  |  |  | EBFBF<br>F000A<br>0653@<br>30313<br>13033<br>37393<br>53336<br>20382<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>30594<br>64353<br>39303<br>2 |  | -00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>30313<br>13033<br>37393<br>53336<br>20382<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>30594<br>64353<br>39303<br>2 |  |  |  |  |  |  |  |  |  |  |  |  |  | EBFBF<br>F000A<br>0653@<br>30313<br>13033<br>37393<br>53336<br>20382<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>30594<br>64353<br>39303<br>2 |  |  |
|--|--|--|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|---|--|--|



|      |                |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1082 | 厦门市聚齐兴建筑工程有限公司 | 2024-04-22 12:20:47.0 | 70-07-6F-12-00-05,00-00-00-00-00-00-00-E0@BFEBFBFF000206D7@5647323239303130435930303030383336382020,2020202057202d44435736434d59354445565343 | 否 | 2024-04-22 12:06:31.0 | 70-07-6F-12-00-05,00-00-00-00-00-00-E0@BFEBFBFF000206D7@5647323239303130435930303030383336382020,2020202057202d44435736434d59354445565343 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:38:14 | 70-07-6F-12-00-05@BFEBFBFF000206D7@5647323239303130435930303030383336382020,2020202057202d44435736434d59354445565343 | 否 |  |
|------|----------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|

|      |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |   |  |   |  |  |
|------|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|--|---|--|--|
| 1083 | 福建闽基建设工程有限公司 | 2024-04-23 15:14:37.0 | 3C-7C-3F-BE-AE-2D@BF EBFBF F0009 06EA@30333 53036 34383 43236 20302 02020 20202 02020 ,2020 20205 7202d 44435 73643 35594 64e46 414a3 8 | 否 | 2024-04-22 09:41:01.0 | 3C-7C-3F-BE-AE-2D, 00 -00- 00- 00- 00- 00- 00- 06EA@ 30333 53036 34383 43236 20302 02020 20202 02020 ,2020 7202d 44435 ,2020 20205 7202d 44435 73643 35594 64e46 414a3 8 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:47 | 3C-7C-3F-BE-AE-2D@BF EBFBF F0009 06EA@30333 53036 34383 43236 20302 02020 20202 02020 ,2020 20205 7202d 44435 73643 35594 64e46 414a3 8 | 否  |   |  |  |
| 1084 | 福建望涔建设发展有限公司 | 2024-04-22 15:52:02.0 | 00-E0-4C-58-B0-26@BF EBFBF F000A 0653@ L1050 OR009 412  | 否 | 2024-04-22 15:39:01.0 | 00-E0-4C-58-B0-26@BF EBFBF F000A 0653@ L1050 OR009 412   | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:36:14   | 00-E0-4C-58-B0-26@BF EBFBF F000A 0653@ L1050 OR009 412 | 否 |  |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1085 | 福建其昇建设工程有限公司  | 2024-04-23 17:28:33.0 | E0-D5-5E-CC-8E-13,00-00-00-00-00-06E9@TC219200E1E0725 | 否 | 2024-04-23 16:27:34.0 | E0-D5-5E-CC-8E-13,00-00-00-00-00-06E9@TC219200E1E0725 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:14 | E0-D5-5E-CC-8E-13@BFEBFBF000906E9@TC219200E1E0725  | 否 |  |
| 1086 | 湖南省一建园林建设有限公司 | 2024-04-23 18:20:08.0 | 22-02-4D-05-19-93@BFEBFBF00090675@50026B7382125758    | 否 | 2024-04-23 18:18:33.0 | 22-02-4D-05-19-93@BFEBFBF00090675@50026B7382125758    | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:40:04 | 22-02-4D-05-19-93@BFEBFBF00090675@50026B7382125758 | 否 |  |
| 1087 | 福建宇诺达建设工程有限公司 | 2024-04-23 09:56:58.0 | F4-B5-20-38-C6-79@BFEBFBF000A0653@2022110400328       | 否 | 2024-04-23 09:54:42.0 | F4-B5-20-38-C6-79@BFEBFBF000A0653@2022110400328       | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:20 | F4-B5-20-38-C6-79@BFEBFBF000A0653@2022110400328    | 否 |  |

|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1088 | 福建住建建设有限公司     | 2024-04-22 12:50:52.0 | 3C-7C-3F-BC-BE-3C@BF<br>EBFBF<br>F000A<br>0653@<br>S3Z3N<br>BONB3<br>8046L   | 否 | 2024-04-22 12:42:56.0 | 3C-7C-3F-BC-BE-3C@BF<br>EBFBF<br>F000A<br>0653@<br>S3Z3N<br>BONB3<br>8046L   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:43:15 | 24-4B-FE-50-2F-44@17<br>8FBFBF<br>F0087<br>0F10@<br>S6PZN<br>FOR60<br>1332B  | 否 |  |
| 1089 | 福建省锦利福建设工程有限公司 | 2024-04-23 17:47:30.0 | E0-D5-5E-FB-67-7D@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>00000<br>00827<br>, WD-<br>WCC6Y<br>7ENKP<br>VP | 否 | 2024-04-23 17:43:22.0 | E0-D5-5E-FB-67-7D@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>00000<br>00827<br>, WD-<br>WCC6Y<br>7ENKP<br>VP | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:47 | E0-D5-5E-FB-67-7D@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>00000<br>00827<br>, WD-<br>WCC6Y<br>7ENKP<br>VP | 否 |  |
| 1090 | 福建世纪荣福实业有限公司   | 2024-04-23 15:21:18.0 | 58-11-22-0C-F9-F7@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2FFAL<br>69,00<br>00_00<br>00_00<br>00_00<br>01.  | 否 | 2024-04-23 10:49:42.0 | 58-11-22-0C-F9-F7@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2FFAL<br>69,00<br>00_00<br>00_00<br>00_00<br>01.  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:39 | 58-11-22-0C-F9-F7@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2FFAL<br>69,00<br>00_00<br>00_00<br>00_00<br>01.  | 否 |  |



|      |                      |                              |   |   |                              |  |   |  |  |  |  |  |  |  |  |  |                            |                            |   |   |   |  |
|------|----------------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|---|---|--|
| 1092 | 福建晟兴隆<br>建设工程有限公司    | 2024-04-23<br>16:03<br>:47.0 | 18-<br>C0-<br>4D-<br>54-<br>43-<br>52,00<br>-00-<br>00-<br>00-<br>4D-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>B7AC3<br>8 | 否 | 2024-04-19<br>19:02<br>:02.0 | 18-<br>C0-<br>4D-<br>54-<br>43-<br>52,00<br>-00-<br>00-<br>00-<br>4D-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>B7AC3<br>8 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:34<br>:39 | 18-<br>C0-<br>4D-<br>54-<br>43-<br>52@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>B7AC3<br>8 | 否   |   |  |
| 1093 | 福建飞禹建<br>设工程有限<br>公司 | 2024-04-22<br>10:08<br>:46.0 | 08-<br>BF-<br>B8-<br>6F-<br>F4-<br>60@BF<br>EBFBF<br>F000A<br>0653@<br>23103<br>J8035<br>46,WD<br>-<br>WXJ2D<br>33MF3<br>PD   | 否 | 2024-04-22<br>10:04<br>:38.0 | 08-<br>BF-<br>B8-<br>6F-<br>F4-<br>60@BF<br>EBFBF<br>F000A<br>0653@<br>23103<br>J8035<br>46,WD<br>-<br>WXJ2D<br>33MF3<br>PD  | 否 |  |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:32<br>:17  | 08-<br>BF-<br>B8-<br>6F-<br>F4-<br>60@BF<br>EBFBF<br>F000A<br>0653@<br>23103<br>J8035<br>46,WD<br>-<br>WXJ2D<br>33MF3<br>PD | 否 |  |

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1094 | 福建海峡金岸建设工程有限公司 | 2024-04-19 18:11:28.0 | D4-5D-64-46-F9-57@BFEBFBFF000906EB@50026B7381A74398       | 否 | 2024-04-19 15:22:41.0 | D4-5D-64-46-F9-57@BFEBFBFF000906EB@50026B7381A74398       | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:38:45 | D4-5D-64-46-F9-57@BFEBFBFF000906EB@50026B7381A74398       | 否 |  |
| 1095 | 河南普识建筑工程有限公司   | 2024-04-23 12:19:50.0 | 70-4D-7B-2B-2E-9C@BFEBFBFF000906E9@K180418E02944,Z4Z9G0LS | 否 | 2024-04-23 11:59:08.0 | 70-4D-7B-2B-2E-9C@BFEBFBFF000906E9@K180418E02944,Z4Z9G0LS | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:57:10 | 70-4D-7B-2B-2E-9C@BFEBFBFF000906E9@K180418E02944,Z4Z9G0LS | 否 |  |

|      |              |                        |  |   |                        |  |   |  |  |  |  |  |  |  |  |  |  |            |                      |  |   |  |
|------|--------------|------------------------|--|---|------------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|----------------------|--|---|--|
| 1096 | 福建宽野建设工程有限公司 | 2024-04-23 17:12 :21.0 | 2C-<br>F0-<br>5D-<br>A5-<br>2E-<br>0A@17<br>8BFBF<br>F0081<br>0F81@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>22CC_<br>8715.<br>, WD-<br>WCC6Y<br>H4JTY<br>HN | 否 | 2024-04-23 16:52 :03.0 | 2C-<br>F0-<br>5D-<br>A5-<br>2E-<br>0A, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@17<br>8BFBF<br>F0081<br>0F81@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>22CC_<br>0000_<br>0026_<br>B738_<br>22CC_<br>8715.<br>, WD-<br>WCC6Y<br>H4JTY<br>HN | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:40 :36 | 2C-<br>F0-<br>5D-<br>A5-<br>2E-<br>0A@17<br>8BFBF<br>F0081<br>0F81@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>22CC_<br>8715.<br>, WD-<br>WCC6Y<br>H4JTY<br>HN | 否 |  |
|------|--------------|------------------------|--|---|------------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|----------------------|--|---|--|





|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 1098 | 福建科远建筑工程有限公司 | 2024-04-22 15:41:31.0 | 50-EB-F6-79-09-A7@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B778_58D5_FE45.                 | 否 | 2024-04-22 15:23:19.0 | 50-EB-F6-79-09-A7@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B778_58D5_FE45.                 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:29 | 50-EB-F6-79-09-A7@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B778_58D5_FE45. | 否   |   |  |
| 1099 | 福建鑫融菁发展有限公司  | 2024-04-23 15:49:37.0 | 58-11-22-9A-3E-B9@BFEBFBFF00090675@WD-WCC6Y3VY6P77,E823_8FA6_BF53_0001_001B_448B_4B02_D7A3. | 否 | 2024-04-23 15:46:44.0 | 58-11-22-9A-3E-B9@BFEBFBFF00090675@WD-WCC6Y3VY6P77,E823_8FA6_BF53_0001_001B_448B_4B02_D7A3. | 否 |  |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:35:04   | 58-11-22-9A-3E-B9@BFEBFBFF00090675@WD-WCC6Y3VY6P77,E823_8FA6_BF53_0001_001B_448B_4B02_D7A3. | 否 |  |

|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1100 | 福建永聚鑫建筑有限公司    | 2024-04-23 11:06:22.0 | 00-E0-4C-5E-B3-D8@BF<br>EBFBF<br>F0009<br>06EA@<br>NGD20<br>OR011<br>6450S<br>30W, 8<br>4332A<br>90A08<br>0                          | 否 | 2024-04-23 11:04:02.0 | 00-E0-4C-5E-B3-D8@BF<br>EBFBF<br>F0009<br>06EA@<br>NGD20<br>OR011<br>6450S<br>30W, 8<br>4332A<br>90A08<br>0                          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:47 | 00-E0-4C-5E-B3-D8@BF<br>EBFBF<br>F0009<br>06EA@<br>NGD20<br>OR011<br>6450S<br>30W  | 否 |  |
| 1101 | 福建省置和晟建设发展有限公司 | 2024-04-23 09:58:13.0 | 24-77-03-0F-96-21, 24-77-03-0F-96-20, 0A-E0-AF-FF-01-11, 00-00-00-00-00-00-00-E0, 00-00-00-00-00-00-E0@BF<br>EBFBF<br>F0003<br>06A9@ | 否 | 2024-04-23 09:55:54.0 | 24-77-03-0F-96-21, 24-77-03-0F-96-20, 0A-E0-AF-FF-01-11, 00-00-00-00-00-00-00-E0, 00-00-00-00-00-00-E0@BF<br>EBFBF<br>F0003<br>06A9@ | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:12 | 24-77-03-0F-96-21, 24-77-03-0F-96-20, 0A-E0-AF-FF-01-11, 00-00-00-00-00-00-00-E0, 00-00-00-00-00-00-E0@BF<br>EBFBF<br>F0003<br>06A9@ | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                                |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|--------------------------------|---|---|--|
|      |              |                       | HKAS9<br>12426<br>1Z085<br>387  |   |                       | HKAS9<br>12426<br>1Z085<br>387  |   |  |  |  |  |  |  |  |  |  |  |             | HKAS9<br>12426<br>1Z085<br>387 |   |   |  |
| 1102 | 福建正心建设工程有限公司 | 2024-04-23 18:46:38.0 | 00-<br>E0-<br>0B-<br>1D-<br>C3-<br>38@BF<br>EBFBF<br>F0003<br>06E4@<br>34534<br>45846<br>4e4d3<br>03137<br>33333<br>13920<br>42202<br>02020 | 否 | 2024-04-23 18:44:48.0 | 00-<br>E0-<br>0B-<br>1D-<br>C3-<br>38,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06E4@<br>34534<br>45846<br>4e4d3<br>03137<br>33333<br>13920<br>42202<br>02020 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:41:01            | 00-<br>E0-<br>0B-<br>1D-<br>C3-<br>38@BF<br>EBFBF<br>F0003<br>06E4@<br>34534<br>45846<br>4e4d3<br>03137<br>33333<br>13920<br>42202<br>02020 | 否 |  |
| 1103 | 福建鑫晟泽建设有限公司  | 2024-04-23 11:29:06.0 | 00-<br>E0-<br>4C-<br>50-<br>9F-<br>77@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000. | 否 | 2024-04-23 11:26:54.0 | 00-<br>E0-<br>4C-<br>50-<br>9F-<br>77@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000.   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:09            | 00-<br>E0-<br>4C-<br>50-<br>C5-<br>5C@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000. | 否 |  |

|      |                 |                       |  |   |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|-----------------|-----------------------|--|---|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1104 | 福建省松溪卓越建设工程有限公司 | 2024-04-23 08:11:32.0 | 00-<br>F1-<br>F5-<br>1C-<br>53-<br>36, A4<br>-4E-<br>31-<br>26-<br>9E-<br>88, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>2024-04-23 08:10:11.0 | 否 | 00-<br>F1-<br>F5-<br>1C-<br>53-<br>36, A4<br>-4E-<br>31-<br>26-<br>9E-<br>88, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>2024-04-23 08:10:11.0 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:36:25 | 00-<br>F1-<br>F5-<br>1C-<br>53-<br>36, A4<br>-4E-<br>31-<br>26-<br>9E-<br>88@BF<br>EBFBF<br>F0009<br>06E9@<br>43535<br>75230<br>32353<br>03431<br>32313<br>34731<br>36203<br>72020 | 否 |  |
|------|-----------------|-----------------------|--|---|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1105 | 福建汤金建设有限公司   | 2024-04-22 16:37:43.0 | F0-2F-74-F7-16-BB,00-00-00-00-00-00-00-00@178BFBF F0081 0F10@30006 55290 6,WD-WCC6Y 1EF23 47              | 否 | 2024-04-22 16:29:41.0 | F0-2F-74-F7-16-BB@178BFBF F0081 0F10@30006 55290 6,WD-WCC6Y 1EF23 47                                      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:41:08 | F0-2F-74-F7-16-BB@178BFBF F0081 0F10@30006 55290 6,WD-WCC6Y 1EF23 47         | 否 |  |
| 1106 | 福建卓创工程管理有限公司 | 2024-04-23 16:37:43.0 | D8-5E-D3-1D-99-A1@BF EBFBF F000A 0653@WD-WCC6Y 4PV4J 6R, E8 23_8F A6_BF 53_00 01_00 1B_44 4A_49 13_FE 83. | 否 | 2024-04-23 16:36:06.0 | D8-5E-D3-1D-99-A1@BF EBFBF F000A 0653@WD-WCC6Y 4PV4J 6R, E8 23_8F A6_BF 53_00 01_00 1B_44 4A_49 13_FE 83. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:17 | E0-D5-5E-96-66-26@BF EBFBF F0009 06E9@WD-WCC6Y 4UX5R 5E, 50 026B7 3821A 17D8 | 否 |  |

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1107 | 华虔建设集团有限公司     | 2024-04-24 00:15:14.0 | 00-E0-4C-5D-5A-5A@178BFBF F00800F11@2C3E_BFFF_F000_0476.  | 否 | 2024-04-23 22:23:04.0 | 00-E0-4C-5D-5A-5A@178BFBF F00800F11@2C3E_BFFF_F000_0476.  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:25 | 00-E0-4C-5D-5A-5A@178BFBF F00800F11@2C3E_BFFF_F000_0476.  | 否 |  |
| 1108 | 福建省坤特建筑工程有限公司  | 2024-04-23 15:08:12.0 | 00-E2-69-63-BF-F1@BFEBFBF F00090675@0000_0000_0000_0001.  | 否 | 2024-04-22 11:15:02.0 | 00-E2-69-63-BF-F1@BFEBFBF F00090675@0000_0000_0000_0001.  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:41:04 | 00-E2-69-63-BF-F1@BFEBFBF F00090675@0000_0000_0000_0001.  | 否 |  |
| 1109 | 江夏（福建）建设工程有限公司 | 2024-04-23 14:58:34.0 | 00-FF-61-7D-5C-56, E8-9C-25-DC-F2-8C@BFEBFBF F000B06F2@0000_0000_0000_0000_00E0_4C6C_EA64_27C6. | 否 | 2024-04-23 14:22:45.0 | 00-FF-61-7D-5C-56, E8-9C-25-DC-F2-8C@BFEBFBF F000B06F2@0000_0000_0000_0000_00E0_4C6C_EA64_27C6. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:23 | 00-FF-61-7D-5C-56, E8-9C-25-DC-F2-8C@BFEBFBF F000B06F2@0000_0000_0000_0000_00E0_4C6C_EA64_27C6. | 否 |  |

|      |                |                                  |   |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|------|----------------|----------------------------------|---|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
| 1110 | 福建嘉灿建<br>工有限公司 | 2024-<br>04-23<br>10:15<br>:07.0 | E0-<br>3F-<br>49-<br>A1-<br>55-<br>2E@BF<br>EBFBF<br>F0003<br>06A9@<br>0520B<br>63756<br>3025A<br>8 | 否 | 2024-<br>04-23<br>10:11<br>:26.0 | E0-<br>3F-<br>49-<br>A1-<br>55-<br>2E,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06A9@<br>0520B<br>63756<br>3025A<br>8 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:34<br>:23 | E0-<br>3F-<br>49-<br>A1-<br>55-<br>2E@BF<br>EBFBF<br>F0003<br>06A9@<br>0520B<br>63756<br>3025A<br>8 | 否 |  |
|------|----------------|----------------------------------|---|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|





|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1112 | 福建省博盛旺建设工程有限公司 | 2024-04-23 09:44:46.0 | FC-34-97-A3-E4-68, 5C-DE-34-46-1C-7D@BF EBFBF F0009 06EB@ ZN1S6 9RN, 2 L2129 1BN2Y 9 | 否 | 2024-04-23 09:43:24.0 | 5C-DE-34-46-1C-7D, FC-34-97-A3-E4-68@BF EBFBF F0009 06EB@ ZN1S6 9RN, 2 L2129 1BN2Y 9 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:46:20 | FC-34-97-A3-E4-68, 5C-DE-34-46-1C-7D@BF EBFBF F0009 06EB@ ZN1S6 9RN, 2 L2129 1BN2Y 9 | 否 |  |
| 1113 | 湖南汉达电力建设有限公司   | 2024-04-23 09:12:32.0 | 00-E0-4C-41-16-1C@BF EBFBF F000A 0653@ 2HT10 07B11 R4S01 B84                         | 否 | 2024-04-23 09:10:48.0 | 00-E0-4C-41-16-1C@BF EBFBF F000A 0653@ 2HT10 07B11 R4S01 B84                         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:47:10 | 00-E0-4C-41-16-1C@BF EBFBF F000A 0653@ 2HT10 07B11 R4S01 B84                         | 否 |  |

|      |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1114 | 福建省华翼建设工程有限公司 | 2024-04-22 16:53:34.0 | 8C-16-45-23-D1-B9@BFEBFBF000906E9@2897E XXNS  | 否 | 2024-04-22 16:18:39.0 | 8C-16-45-23-D1-B9,00-00-00-00-00-00-06E9@EQ@BFEBFBF000906E9@2897E XXNS               | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:22 | 8C-16-45-23-D1-B9@BFEBFBF000906E9@2897E XXNS                                    | 否 |  |
| 1115 | 福建前程建设有限公司    | 2024-04-22 17:58:10.0 | 58-11-22-2A-4D-86@BFEBFBF000A0653@0000_0000_0000_0000_0026_B738_152E_F855.,WD-WCC6Y6JF5D RU | 否 | 2024-04-22 17:56:16.0 | A0-36-BC-26-18-6E@BFEBFBF00090675@0000_0000_0000_0000_0000_0000_0026_B778_4CA5_ED15. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:07 | A0-36-BC-26-18-6E@BFEBFBF00090675@0000_0000_0000_0000_0000_0026_B778_4CA5_ED15. | 否 |  |

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1116 | 福建鼎贵建筑有限公司     | 2024-04-23 09:45:26.0 | 00-<br>E0-<br>4C-<br>57-<br>E0-<br>52@BF<br>EBFBF<br>F000A<br>0653@<br>30353<br>23042<br>36373<br>73438<br>46313<br>14237<br>43202<br>02020 | 否 | 2024-04-23 09:43:53.0 | 00-<br>E0-<br>4C-<br>57-<br>E0-<br>52, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>30353<br>23042<br>36373<br>73438<br>46313<br>14237<br>43202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:34 | 00-<br>E0-<br>4C-<br>57-<br>BC-<br>4D@BF<br>EBFBF<br>F000A<br>0653@<br>30353<br>23042<br>36373<br>73438<br>46313<br>24241<br>31202<br>02020 | 否 |  |
| 1117 | 福建鑫智通达建设发展有限公司 | 2024-04-23 15:42:10.0 | B4-<br>2E-<br>99-<br>2B-<br>CB-<br>5E@BF<br>EBFBF<br>F0005<br>06E3@<br>6479_<br>A779_<br>10C0_<br>2546.<br>, WD-<br>WCC6Y<br>PWYC5<br>19    | 否 | 2024-04-23 15:37:04.0 | B4-<br>2E-<br>99-<br>2B-<br>CB-<br>5E@BF<br>EBFBF<br>F0005<br>06E3@<br>6479_<br>A779_<br>10C0_<br>2546.<br>, WD-<br>WCC6Y<br>PWYC5<br>19  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:59:29 | B4-<br>2E-<br>99-<br>2B-<br>CB-<br>5E@BF<br>EBFBF<br>F0005<br>06E3@<br>6479_<br>A779_<br>10C0_<br>2546.<br>, WD-<br>WCC6Y<br>PWYC5<br>19    | 否 |  |

|      |            |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |
|------|------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|
| 1118 | 福建鼎亿建设有限公司 | 2024-04-19 10:59:25.0 | 3C-<br>7C-<br>3F-<br>4F-<br>43-<br>B2@17<br>8BFBF<br>F0066<br>0F51@<br>30333<br>73039<br>36313<br>73830<br>20342<br>02020<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>30595<br>25254<br>58463<br>5 | 否 | 2024-04-19 10:49:35.0 | 3C-<br>7C-<br>3F-<br>4F-<br>43-<br>B2, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@17<br>8BFBF<br>F0066<br>0F51@<br>30333<br>73039<br>36313<br>73830<br>20342<br>02020<br>20202<br>,2020<br>20205<br>7202d<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>30595<br>25254<br>58463<br>5 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:34 | 3C-<br>7C-<br>3F-<br>4F-<br>43-<br>B2@17<br>8BFBF<br>F0066<br>0F51@<br>30333<br>73039<br>36313<br>73830<br>20342<br>02020<br>20202<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>30595<br>25254<br>58463<br>5 | 否 |
|------|------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1119 | 福建兴田工程管理有限公司 | 2024-04-23 16:54:41.0 | 58-11-22-99-97-77@BF<br>EBFBF<br>F000A<br>0653@<br>W9AK8<br>7LB, E<br>823_8<br>FA6_B<br>F53_0<br>001_0<br>01B_4<br>48B_4<br>E87_3<br>CEF. | 否 | 2024-04-23 16:52:35.0 | 58-11-22-99-97-77@BF<br>EBFBF<br>F000A<br>0653@<br>W9AK8<br>7LB, E<br>823_8<br>FA6_B<br>F53_0<br>001_0<br>01B_4<br>48B_4<br>E87_3<br>CEF. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:39 | 58-11-22-99-97-77@BF<br>EBFBF<br>F000A<br>0653@<br>W9AK8<br>7LB, E<br>823_8<br>FA6_B<br>F53_0<br>001_0<br>01B_4<br>48B_4<br>E87_3<br>CEF. | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|



|      |                 |                                  |   |   |  |   |   |  |  |  |  |  |  |  |  |  |  |   |                                |   |   |  |
|------|-----------------|----------------------------------|---|---|--|---|---|--|--|--|--|--|--|--|--|--|--|---|--------------------------------|---|---|--|
|      |                 |                                  | 202d4<br>44357<br>36433<br>25946<br>504c4<br>63956<br>,001B<br>_448B<br>_48F9<br>_3A06<br>.                                     |   | 00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>25946<br>504c4<br>63956<br>,001B<br>_448B<br>_48F9<br>_3A06<br>. |   |   |  |  |  |  |  |  |  |  |  |  | 202d4<br>44357<br>36433<br>25946<br>504c4<br>63956<br>,001B<br>_448B<br>_48F9<br>_3A06<br>. |                                |   |   |  |
| 1122 | 福建易生原<br>建设有限公司 | 2024-<br>04-23<br>18:51<br>:15.0 | 00-<br>CF-<br>E0-<br>54-<br>E2-<br>B4@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>48242<br>D,WD-<br>WCC6Y<br>OHESY<br>4P | 否 | 2024-<br>04-23<br>18:42<br>:43.0   | 00-<br>CF-<br>E0-<br>54-<br>E2-<br>B4@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>48242<br>D,WD-<br>WCC6Y<br>OHESY<br>4P | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查  | 2024-<br>04-24<br>08:35<br>:54 | 00-<br>CF-<br>E0-<br>54-<br>E2-<br>B4@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>48242<br>D,WD-<br>WCC6Y<br>OHESY<br>4P | 否 |  |



|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1123 | 福建华景市政园林工程有限公司 | 2024-04-23 09:55:11.0 | 00-E2-69-69-67-49@BFEBFBFF00090675@0000_0000_0000_0001_00A0_7522_3A9C_2F86. | 否 | 2024-04-23 09:52:21.0 | 00-E2-69-69-67-49@BFEBFBFF00090675@0000_0000_0000_0001_00A0_7522_3A9C_2F86. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:13 | 00-E2-69-69-67-49@BFEBFBFF00090675@0000_0000_0000_0001_00A0_7522_3A9C_2F86. | 否 |  |
| 1124 | 福建汉风建设工程有限公司   | 2024-04-22 11:50:14.0 | B8-97-5A-E2-33-B0@178BFBF00610F31@50026B778243D111                          | 否 | 2024-04-22 11:43:27.0 | B8-97-5A-E2-33-B0@178BFBF00610F31@50026B778243D111                          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 09:00:49 | B8-97-5A-E2-33-B0@178BFBF00610F31@50026B778243D111                          | 否 |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 1125 | 福建麦丽合建设有限公司   | 2024-04-23 14:54:25.0 | 50-EB-F6-EA-4A-2B@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 4925_ 8C41. , YX23 10JS2 56F00 776 | 否 | 2024-04-23 14:50:38.0 | 50-EB-F6-EA-4A-2B@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 4925_ 8C41. , YX23 10JS2 56F00 776 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:09 | 50-EB-F6-EA-4A-2B@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 4925_ 8C41. , YX23 10JS2 56F00 776 | 否   |   |  |
| 1126 | 福建省康筑工程管理有限公司 | 2024-04-23 11:14:45.0 | F0-2F-74-87-1D-45@BF EBFBF F000A 0653@ WD- WCC6Y OTJR2 S2, S2 DKNXA G6388 41N                                 | 否 | 2024-04-23 11:13:40.0 | F0-2F-74-87-1D-45@BF EBFBF F000A 0653@ WD- WCC6Y OTJR2 S2, S2 DKNXA G6388 41N                                 | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:31:53   | F0-2F-74-87-1D-45@BF EBFBF F000A 0653@ WD- WCC6Y OTJR2 S2, S2 DKNXA G6388 41N | 否 |  |

|      |                   |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |                         |                        |   |   |  |
|------|-------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|-------------------------|------------------------|---|---|--|
| 1127 | 福建省傲秦<br>建筑工程有限公司 | 2024-04-23<br>16:38:09.0 | B4-<br>2E-<br>99-<br>0F-<br>D5-<br>95@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7782<br>COD90<br>2, WD-<br>WCC6Y<br>9CS8U<br>FS  | 否 | 2024-04-23<br>16:36:13.0 | B4-<br>2E-<br>99-<br>0F-<br>D5-<br>95@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7782<br>COD90<br>2, WD-<br>WCC6Y<br>9CS8U<br>FS  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:33:52 | B4-<br>2E-<br>99-<br>0F-<br>D5-<br>95@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7782<br>COD90<br>2, WD-<br>WCC6Y<br>9CS8U<br>FS  | 否 |  |
| 1128 | 中建晟宏建<br>设开发有限公司  | 2024-04-22<br>15:36:29.0 | B4-<br>2E-<br>99-<br>D0-<br>0D-<br>EA, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36323<br>73238<br>41333<br>14337<br>32202<br>02020 | 否 | 2024-04-22<br>15:24:13.0 | B4-<br>2E-<br>99-<br>D0-<br>0D-<br>EA, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36323<br>73238<br>41333<br>14337<br>32202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:33:07 | B4-<br>2E-<br>99-<br>D0-<br>0D-<br>EA, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36323<br>73238<br>41333<br>14337<br>32202<br>02020 | 否 |  |

|      |               |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |   |  |
|------|---------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|---|--|
| 1129 | 福建省力普建设工程有限公司 | 2024-04-19 18:29:30.0 | 00-<br>E0-<br>4C-<br>1E-<br>15-<br>54,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>2YC36<br>86 | 否 | 2024-04-19 18:22:20.0 | 00-<br>E0-<br>4C-<br>1E-<br>15-<br>54,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>2YC36<br>86 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:11 | 00-<br>E0-<br>4C-<br>1E-<br>15-<br>54,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>2YC36<br>86 | 否   |   |  |
| 1130 | 福建芝成建设有限公司    | 2024-04-22 10:43:09.0 | 18-<br>C0-<br>4D-<br>47-<br>59-<br>FA@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC4J<br>7XUNP<br>E0,50<br>026B7<br>38142<br>6F5F                        | 否 | 2024-04-22 10:42:24.0 | 18-<br>C0-<br>4D-<br>47-<br>59-<br>FA@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC4J<br>7XUNP<br>E0,50<br>026B7<br>38142<br>6F5F                 | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:34:27  | 18-<br>C0-<br>4D-<br>47-<br>59-<br>FA@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC4J<br>7XUNP<br>E0,50<br>026B7<br>38142<br>6F5F | 否 |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 1131 | 福建省闽恒建设工程有限公司 | 2024-04-23 08:56:46.0 | 58-11-22-0F-14-03@BF<br>EBFBF<br>F0009<br>0672@<br>0000_0000_0000_0000_0026_ B768_ 5F7F_ 9145. , WD- WCC6Y 6UZ2C CR | 否 | 2024-04-23 08:42:54.0 | 58-11-22-0F-14-03@BF<br>EBFBF<br>F0009<br>0672@<br>0000_0000_0000_0000_0026_ B768_ 5F7F_ 9145. , WD- WCC6Y 6UZ2C CR | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:53 | 58-11-22-0F-14-03@BF<br>EBFBF<br>F0009<br>0672@<br>0000_0000_0000_0000_0026_ B768_ 5F7F_ 9145. , WD- WCC6Y 6UZ2C CR | 否   |   |  |
| 1132 | 福建富偕建设有限公司    | 2024-04-23 17:09:36.0 | 74-56-3C-2F-42- F9@BF<br>EBFBF<br>F000A<br>0653@<br>A428_ B702_ B4DE_ 0081.   | 否 | 2024-04-23 17:09:33.0 | 74-56-3C-2F-42- F9@BF<br>EBFBF<br>F000A<br>0653@<br>A428_ B702_ B4DE_ 0081.   | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:34:11   | 74-56-3C-2F-42- F9@BF<br>EBFBF<br>F000A<br>0653@<br>A428_ B702_ B4DE_ 0081. | 否 |  |

|      |                 |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|------|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 1133 | 福建龙宸建筑工程有限公司    | 2024-04-23 08:50:31.0 | B4-<br>2E-<br>99-<br>7E-<br>21-<br>A1@BF<br>EBFBF<br>F0009<br>06EB@<br>N9YE2<br>5A00A<br>04359  | 否 | 2024-04-17 10:53:03.0 | B4-<br>2E-<br>99-<br>7E-<br>21-<br>A1@BF<br>EBFBF<br>F0009<br>06EB@<br>N9YE2<br>5A00A<br>04359  | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误差，请检查         | 2024-04-24 08:42:23   | F8-<br>BC-<br>12-<br>94-<br>81-<br>8C@BF<br>EBFBF<br>F0003<br>06C3@<br>314a3<br>03531<br>34453<br>23431<br>36392<br>03920<br>20202<br>02020<br>, 2020<br>20202<br>02020<br>20202<br>03520<br>43345<br>8444e<br>39534<br>b | 否 |  |
| 1134 | 福建省顺昌新业电力工程有限公司 | 2024-04-23 16:59:18.0 | 0A-<br>E0-<br>AF-<br>A2-<br>2B-<br>42, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0002<br>06A7@<br>NS329<br>28039<br>6706,<br>4<br>P4SAY<br>6SF | 否 | 2024-04-23 16:57:50.0 | 0A-<br>E0-<br>AF-<br>A2-<br>2B-<br>42, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0002<br>06A7@<br>NS329<br>28039<br>6706,<br>4<br>P4SAY<br>6SF | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 09:06:49 | 0A-<br>E0-<br>AF-<br>A2-<br>2B-<br>42@BF<br>EBFBF<br>F0002<br>06A7@<br>NS329<br>28039<br>6706,<br>4<br>P4SAY<br>6SF | 否   |   |  |



|      |                      |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |                    |                     |   |   |  |  |  |  |  |  |  |
|------|----------------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------------|---------------------|---|---|--|--|--|--|--|--|--|
| 1136 | 中闽坤明<br>(福建)建设发展有限公司 | 2024-04-19 17:04:45.0 | 24-4B-<br>FE-97-<br>F2-<br>B9,00<br>-00-<br>00-<br>00-<br>FE-<br>00-<br>97-<br>00-<br>F2-<br>00-<br>B9@BF<br>E0,00<br>-00-<br>EBFBF<br>F0009<br>00-<br>06EB@<br>00-<br>30353<br>00-<br>23042<br>00-<br>36333<br>73138<br>42364<br>13241<br>38202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>36594<br>1534b<br>46564<br>a | 否 | 2024-04-19 17:02:08.0 | 24-4B-<br>FE-97-<br>F2-<br>B9,00<br>-00-<br>00-<br>00-<br>FE-<br>00-<br>97-<br>00-<br>F2-<br>00-<br>E0,00<br>-00-<br>EBFBF<br>F0009<br>00-<br>06EB@<br>00-<br>30353<br>00-<br>23042<br>00-<br>36333<br>73138<br>42364<br>13241<br>38202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>36594<br>1534b<br>46564<br>a | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误,请查<br>检 | 2024-04-24 08:34:39 | 24-4B-<br>FE-97-<br>F2-<br>B9@BF<br>EBFBF<br>F0009<br>06EB@<br>30353<br>30353<br>23042<br>36333<br>73138<br>42364<br>13241<br>38202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>36594<br>1534b<br>46564<br>a | 否 |  |  |  |  |  |  |  |
|------|----------------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------------|---------------------|---|---|--|--|--|--|--|--|--|





|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1138 | 福建省凌秀建设工程有限公司 | 2024-04-23 18:12:49.0 | 04-D9-F5-86-B8-12@BFF000306C3@000000000410135114,WD-WCC6Y5AFY2KH      | 否 | 2024-04-23 11:54:03.0 | 04-D9-F5-86-B8-12,00-00-00-00-00-00-00-00-00-00-E0@BFF000306C3@000000000410135114,WD-WCC6Y5AFY2KH | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误,请检查 | 2024-04-24 08:48:01 | 04-D9-F5-86-B8-12@BFF000306C3@000000000410135114,WD-WCC6Y5AFY2KH      | 否 |  |
| 1139 | 福建鑫恒润建设发展有限公司 | 2024-04-23 14:29:51.0 | 74-56-3C-24-2C-CC@BFF00090675@9Q30909002970_00000001.,WD-WCC6YJEWf32S | 否 | 2024-04-23 14:27:18.0 | 74-56-3C-24-2C-CC@BFF00090675@9Q30909002970_00000001.,WD-WCC6YJEWf32S                             | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误,请检查 | 2024-04-24 08:34:13 | 74-56-3C-24-2C-CC@BFF00090675@9Q30909002970_00000001.,WD-WCC6YJEWf32S | 否 |  |

|      |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1140 | 福建省固雅建设工程有限公司 | 2024-04-23 11:01:33.0 | 00-E0-4C-52-23-EF@BF<br>EBFBF<br>F0009<br>06E9@<br>SCRW2<br>10219<br>05G01<br>29, I3<br>0005B<br>000919   | 否 | 2024-04-23 11:01:59.0 | 00-E0-4C-52-23-EF, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>SCRW2<br>10219<br>05G01<br>29, I3<br>0005B<br>000919                                | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:29 | 00-E0-4C-52-23-EF@BF<br>EBFBF<br>F0009<br>06E9@<br>SCRW2<br>10219<br>05G01<br>29, I3<br>0005B<br>000919 | 否 |  |
| 1141 | 福建正韵建设有限公司    | 2024-04-23 09:55:09.0 | 00-25-F2-6B-FF-C1, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>AEF80<br>7031B<br>9C000<br>78334 | 否 | 2024-04-23 09:53:49.0 | 00-25-F2-6B-FF-C1, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>AEF80<br>7031B<br>9C000 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:03 | 00-25-F2-6B-FF-C1@BF<br>EBFBF<br>F0009<br>06EA@<br>AEF80<br>7031B<br>9C000<br>78334                     | 否 |  |



|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1143 | 福建元亨工程管理有限公司  | 2024-04-23 09:26:26.0 | 00-E0-4C-54-A1-4B@BF<br>EBFBF<br>F000A<br>0655@<br>00000<br>00000<br>01000<br>4070,<br>Z9LS4<br>9CS | 否 | 2024-04-23 09:24:32.0 | 00-E0-4C-54-A1-4B@BF<br>EBFBF<br>F000A<br>0655@<br>00000<br>00000<br>01000<br>4070,<br>Z9LS4<br>9CS | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:18 | 00-E0-4C-54-A1-4B@BF<br>EBFBF<br>F000A<br>0655@<br>00000<br>00000<br>01000<br>4070,<br>Z9LS4<br>9CS | 否 |  |
| 1144 | 福建省秦溪建设工程有限公司 | 2024-04-23 15:22:12.0 | 00-E0-4C-69-7E-1C@BF<br>EBFBF<br>F000A<br>0653@<br>WCC6Y<br>1CRLD<br>67, 30<br>07254<br>7299        | 否 | 2024-04-22 10:25:35.0 | 00-E0-4C-69-7E-1C@BF<br>EBFBF<br>F000A<br>0653@<br>WCC6Y<br>1CRLD<br>67, 30<br>07254<br>7299        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:39 | 00-E0-4C-69-7E-1C@BF<br>EBFBF<br>F000A<br>0653@<br>WCC6Y<br>1CRLD<br>67, 30<br>07254<br>7299        | 否 |  |
| 1145 | 福建力群建设发展有限公司  | 2024-04-22 17:25:38.0 | 00-E0-4C-89-31-F6@BF<br>EBFBF<br>F0005<br>06E3@<br>30115<br>49112<br>6                              | 否 | 2024-04-22 17:16:24.0 | 00-E0-4C-89-31-F6@BF<br>EBFBF<br>F0005<br>06E3@<br>30115<br>49112<br>6                              | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:11 | 00-E0-4C-89-31-F6@BF<br>EBFBF<br>F0005<br>06E3@<br>30115<br>49112<br>6                              | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1146 | 福建连源建设发展有限公司 | 2024-04-23 17:55:37.0 | F4-<br>B5-<br>20-<br>23-<br>F8-<br>BF, 4C<br>-77-<br>66-<br>A1-<br>46-<br>6B@BF<br>EBFBF<br>F0009<br>06EB@<br>J42FH<br>S0700<br>484   | 否 | 2024-04-23 12:45:39.0 | F4-<br>B5-<br>20-<br>23-<br>F8-<br>BF, 4C<br>-77-<br>66-<br>A1-<br>46-<br>6B@BF<br>EBFBF<br>F0009<br>06EB@<br>J42FH<br>S0700<br>484   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:39:15 | F4-<br>B5-<br>20-<br>23-<br>F8-<br>BF, 4C<br>-77-<br>66-<br>A1-<br>46-<br>6B@BF<br>EBFBF<br>F0009<br>06EB@<br>J42FH<br>S0700<br>484   | 否 |  |
| 1147 | 福建盛怡建设有限公司   | 2024-04-23 17:49:12.0 | D8-<br>BB-<br>C1-<br>5C-<br>AE-<br>35@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2ZDAD<br>16,00<br>00_00<br>00_01<br>00_00<br>00_00<br>E0_4C<br>OD_A8<br>C5_F7<br>11. | 否 | 2024-04-23 10:43:29.0 | D8-<br>BB-<br>C1-<br>5C-<br>AE-<br>35@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2ZDAD<br>16,00<br>00_00<br>00_01<br>00_00<br>00_00<br>E0_4C<br>OD_A8<br>C5_F7<br>11. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:31:34 | D8-<br>BB-<br>C1-<br>5C-<br>AE-<br>35@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2ZDAD<br>16,00<br>00_00<br>00_01<br>00_00<br>00_00<br>E0_4C<br>OD_A8<br>C5_F7<br>11. | 否 |  |



|      |                 |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|-----------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1149 | 福建省文然建筑有限公司     | 2024-04-23 10:53:52.0 | 00-00-00-00-00-00, 2C-4D-54-12-65-96@BFEBFBF000906E9@50026B73801616B5, 6VM1T4EL | 否 | 2024-04-23 10:51:31.0 | 2C-4D-54-65-12-96@BFEBFBF000906E9@50026B73801616B5, 6VM1T4EL               | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:36:51 | 00-00-00-00-00-00, 2C-4D-54-12-65-96@BFEBFBF000906E9@50026B73801616B5, 6VM1T4EL | 否 |  |
| 1150 | 福建省盛阳工程项目管理有限公司 | 2024-04-23 17:05:51.0 | 58-11-22-90-A9-76@BFEBFBF00090675@E823_8FA6_BF53_0001_001B_448B_45FC_CC35.      | 否 | 2024-04-23 17:03:33.0 | 58-11-22-90-A9-76@BFEBFBF00090675@E823_8FA6_BF53_0001_001B_448B_45FC_CC35. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:34:07 | 58-11-22-90-A9-76@BFEBFBF00090675@E823_8FA6_BF53_0001_001B_448B_45FC_CC35.      | 否 |  |



|      |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |  |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|--|
| 1151 | 福建诚宇工程咨询有限公司 | 2024-04-23 10:00:49.0 | 10-<br>C3-<br>7B-<br>6E-<br>E1-<br>0F@BF<br>EBFBF<br>F0003<br>06C3@<br>43535<br>75231<br>32323<br>03230<br>36303<br>04134<br>30203<br>72020<br>,2020<br>20205<br>7202d<br>44435<br>73243<br>30455<br>35244<br>44553<br>2 | 否 | 2024-04-23 09:59:26.0 | 10-<br>C3-<br>7B-<br>6E-<br>E1-<br>0F, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>43535<br>75231<br>32323<br>03230<br>36303<br>F0003<br>06C3@<br>43535<br>75231<br>32323<br>03230<br>36303<br>04134<br>30203<br>72020<br>,2020<br>20205<br>7202d<br>44435<br>73243<br>30455<br>35244<br>,2020<br>20205<br>7202d<br>44435<br>73243<br>30455<br>35244<br>44553<br>2 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:03 | 10-<br>C3-<br>7B-<br>6E-<br>E1-<br>0F@BF<br>EBFBF<br>F0003<br>06C3@<br>43535<br>75231<br>32323<br>03230<br>36303<br>04134<br>30203<br>72020<br>,2020<br>20205<br>7202d<br>44435<br>73243<br>30455<br>35244<br>44553<br>2 | 否 |  |  |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|--|



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1154 | 福建增宏建设工程有限公司 | 2024-04-23 10:50:53.0 | 00-E0-4C-4D-BD-9C@BF EBFBF F000A 0653@ AA000 00001 22500 02321 ,WD- WCC6Y 3LLLF ZT | 否 | 2024-04-23 10:48:21.0 | 00-E0-4C-4D-BD-9C@BF EBFBF F000A 0653@ AA000 00001 22500 02321 ,WD- WCC6Y 3LLLF ZT | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:44:35 | 00-E0-4C-4D-BD-9C@BF EBFBF F000A 0653@ AA000 00001 22500 02321 ,WD- WCC6Y 3LLLF ZT | 否 |  |
| 1155 | 唐立工程技术有限公司   | 2024-04-23 10:02:12.0 | 00-E0-4C-5D-64-44@BF EBFBF F0002 06D7@ 2F172 00600 50, WD - WCC2E EW958 05         | 否 | 2024-04-23 10:01:01.0 | 00-E0-4C-5D-64-44@BF EBFBF F0002 06D7@ 2F172 00600 50, WD - WCC2E EW958 05         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:42:03 | 00-E0-4C-5D-64-44@BF EBFBF F0002 06D7@ 2F172 00600 50, WD - WCC2E EW958 05         | 否 |  |

|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |   |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|--|---|--|
| 1156 | 福建晟仕建筑有限公司 | 2024-04-15 08:28:12.0 | 18-C0-4D-C4-BB-74, 68-DD-B7-38-80-6F, 68-DD-B7-38-80-6F@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4A93_ 953D. | 否 | 2024-04-15 08:19:16.0 | 18-C0-4D-C4-BB-74, 68-DD-B7-38-80-6F, 68-DD-B7-38-80-6F@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4A93_ 953D. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:38:10 | D8-43-AE-18-50-73, E4-OD-36-73-EF-C0, E4-OD-36-73-EF-BF, E4-OD-36-73-EF-C3@BF EBFBF F000B 06F2@ AA000 00000 00048 9, 647 9_A78 3_FF0 0_7BA 2. | 否  |   |  |
| 1157 | 丰昌建设有限公司   | 2024-04-18 11:09:27.0 | 24-4B-FE-53-02-62@BF EBFBF F0009 06EA@ 30018 18406 3   | 否 | 2024-04-18 11:00:51.0 | 24-4B-FE-53-02-62@BF EBFBF F0009 06EA@ 30018 18406 3   | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:32:13   | 24-4B-FE-53-02-62@BF EBFBF F0009 06EA@ 30018 18406 3 | 否 |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1158 | 福建省中湖建设工程有限公司 | 2024-04-23 11:30:20.0 | A0-36-BC-23-8C-E8, D4-84-09-1F-73-61, D4-84-09-1F-73-61@BFEBFBFF00090675@0000_0000_0000_0001. | 否 | 2024-04-22 18:25:31.0 | A0-36-BC-23-8C-E8, D4-84-09-1F-73-61, D4-84-09-1F-73-61@BFEBFBFF00090675@0000_0000_0000_0001. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:03 | A0-36-BC-23-8C-E8, D4-84-09-1F-73-61, D4-84-09-1F-73-61@BFEBFBFF00090675@0000_0000_0000_0001. | 否 |  |
| 1159 | 福建鼎立诚建设工程有限公司 | 2024-04-23 16:59:29.0 | B4-2E-99-98-BC-C3@178BFBF00800F11@AA0000000000249, WD-WCC6Y6USYVYY                            | 否 | 2024-04-23 10:35:44.0 | B4-2E-99-98-BC-C3@178BFBF00800F11@AA0000000000249, WD-WCC6Y6USYVYY                            | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:10 | B4-2E-99-98-BC-C3@178BFBF00800F11@AA0000000000249, WD-WCC6Y6USYVYY                            | 否 |  |

|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1160 | 福建裕航建设有限公司 | 2024-04-23 15:08:46.0 | 00-E0-4C-16-E9-DA@BF EBFBF F000A 0653@ 19299 38043 15                      | 否 | 2024-04-23 15:05:25.0 | 00-E0-4C-16-E9-DA@BF EBFBF F000A 0653@ 19299 38043 15                      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:53 | 00-E0-4C-16-E9-DA@BF EBFBF F000A 0653@ 19299 38043 15                      | 否 |  |
| 1161 | 福建桑鼎建设有限公司 | 2024-04-23 09:46:20.0 | A8-5E-45-68-DB-B2@BF EBFBF F0009 06EB@ 1943D 04844 10, WD - WCC6Y 7NEH1 J8 | 否 | 2024-04-23 09:44:00.0 | A8-5E-45-68-DB-B2@BF EBFBF F0009 06EB@ 1943D 04844 10, WD - WCC6Y 7NEH1 J8 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:52:12 | A8-5E-45-68-DB-B2@BF EBFBF F0009 06EB@ 1943D 04844 10, WD - WCC6Y 7NEH1 J8 | 否 |  |

|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1162 | 中锦骏业建设有限公司 | 2024-04-23 16:26:50.0 | 3341383131373132323532030,2020202057202d445857315138415238564c4c36 | 否 | 2024-04-23 15:15:50.0 | 0C-9D-92-88-7F-34,00-00-00-00-00-00-00-06EA@EQ@BFEBFBF000936363238353341383131373132323532030,2020202057202d445857315138415238564c4c36 | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:47 | 3341383131373132323532030,2020202057202d445857315138415238564c4c36 | 否 | 0C-9D-92-88-7F-34@BFEBFBF000906EA@36363238353341383131373132323532030,2020202057202d445857315138415238564c4c36 |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|

|      |                        |                                  |   |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|--|
| 1163 | 名城三建<br>(福建)发<br>展有限公司 | 2024-<br>04-22<br>15:37<br>:52.0 | D4-<br>5D-<br>64-<br>4A-<br>03-<br>0E@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>91A27<br>1 | 否 | 2024-<br>04-22<br>15:32<br>:04.0 | D4-<br>5D-<br>64-<br>4A-<br>03-<br>0E, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>EQ@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>91A27<br>1 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:33<br>:47 | D4-<br>5D-<br>64-<br>4A-<br>03-<br>0E@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>91A27<br>1 | 否 |  |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|--|



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|
| 1164 | 福建海丝建设工程有限公司 | 2024-04-23 11:23:26.0 | 20-0D-B0-4C-86-EA, 20-0D-B0-4C-86-EB, 18-C0-4D-ED-C4-9B, 20-0D-B0-4C-86-E8@BFE8@BFEBFBFF000A0655@583445353038373276, WD-WCC6Y5HU7KYA, 0000000001000424 | 否 | 2024-04-23 11:22:24.0 | 20-0D-B0-4C-86-EA, 20-0D-B0-4C-86-EB, 18-C0-4D-ED-C4-9B, 20-0D-B0-4C-86-E8@BFE8@BFEBFBFF000A0655@583445353038373276, WD-WCC6Y5HU7KYA, 0000000001000424 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:46:12 | 20-0D-B0-4C-86-E8, 20-0D-B0-4C-86-EB, 18-C0-4D-ED-C4-9B@BFE8@BFEBFBFF000A0655@583445353038373276, WD-WCC6Y5HU7KYA, 0000000001000424 | 否 |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|

|      |              |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |  |             |                        |   |   |  |
|------|--------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|------------------------|---|---|--|
| 1165 | 福建灼华建设工程有限公司 | 2024-04-23<br>15:03:22.0 | 4C-<br>ED-<br>FB-<br>45-<br>89-<br>50,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>TA18A<br>19027<br>01801<br>,WD-<br>WCC6Y<br>7XFZR<br>3R | 否 | 2024-04-23<br>10:04:15.0 | 4C-<br>ED-<br>FB-<br>45-<br>89-<br>50,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>TA18A<br>19027<br>01801<br>,WD-<br>WCC6Y<br>7XFZR<br>3R | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差,请检查 | 2024-04-24<br>08:38:04 | 4C-<br>ED-<br>FB-<br>45-<br>89-<br>50,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>TA18A<br>19027<br>01801<br>,WD-<br>WCC6Y<br>7XFZR<br>3R | 否 |  |
|------|--------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|------------------------|---|---|--|

|      |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1166 | 福建泓洲建设工程有限公司 | 2024-04-23 14:49:18.0 | 4C-ED-FB-65-C8-19,00-00-00-00-00-00-00@BFEBFBFF000906EA@4d433734414237433033333136312020202020,202020202020202020204e5a573157484a4d | 否 | 2024-04-23 14:47:40.0 | 4C-ED-FB-65-C8-19,00-00-00-00-00-00-00-00@BFEBFBFF000906EA@4d433734414237433033333136312020202020,202020202020202020204e5a573157484a4d | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:37:28 | 4C-ED-FB-65-C8-19,00-00-00-00-00-00-00-00@BFEBFBFF000906EA@4d4337344142374330333331363120202020,202020202020202020204e5a573157484a4d | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|

|      |                   |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |                        |                            |   |   |  |
|------|-------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|------------------------|----------------------------|---|---|--|
| 1167 | 福建省交泰<br>建设工程有限公司 | 2024-04-23<br>18:25<br>:33.0 | 74-<br>56-<br>3C-<br>23-<br>1D-<br>99@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2JHUN<br>UC,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1A<br>87_04<br>95. | 否 | 2024-04-23<br>18:24<br>:29.0 | 74-<br>56-<br>3C-<br>23-<br>1D-<br>99@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2JHUN<br>UC,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1A<br>87_04<br>95. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-04-24<br>08:43<br>:52 | 74-<br>56-<br>3C-<br>23-<br>1D-<br>99@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2JHUN<br>UC,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1A<br>87_04<br>95. | 否 |  |
| 1168 | 福建欧也建<br>设工程有限公司  | 2024-04-23<br>09:19<br>:17.0 | F0-<br>2F-<br>74-<br>89-<br>EC-<br>12@BF<br>EBFBF<br>F000A<br>0653@<br>20200<br>72402<br>713,7<br>063B9<br>45,WD<br>-<br>WCC6Y<br>OLU91<br>27                               | 否 | 2024-04-22<br>12:00<br>:12.0 | F0-<br>2F-<br>74-<br>89-<br>EC-<br>12@BF<br>EBFBF<br>F000A<br>0653@<br>20200<br>72402<br>713,7<br>063B9<br>45,WD<br>-<br>WCC6Y<br>OLU91<br>27                               | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-04-24<br>08:39<br>:12 | F0-<br>2F-<br>74-<br>89-<br>EC-<br>12@BF<br>EBFBF<br>F000A<br>0653@<br>20200<br>72402<br>713,7<br>063B9<br>45,WD<br>-<br>WCC6Y<br>OLU91<br>27                               | 否 |  |

|      |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1169 | 福建君亿发展有限公司      | 2024-04-23 11:02:21.0 | 18-CO-4D-7E-BF-5E@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7UEHP<br>1X, AA<br>00000<br>00082<br>10015<br>204 | 否 | 2024-04-23 10:55:02.0 | 18-CO-4D-7E-BF-5E@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7UEHP<br>1X, AA<br>00000<br>00082<br>10015<br>204 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:47 | 18-CO-4D-7E-BF-5E@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7UEHP<br>1X, AA<br>00000<br>00082<br>10015<br>204 | 否 |  |
| 1170 | 福建省三明磐基建设工程有限公司 | 2024-04-17 09:12:32.0 | E8-9C-25-42-84-E5@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>485A_<br>568B.  | 否 | 2024-04-17 09:09:41.0 | E8-9C-25-42-84-E5@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>485A_<br>568B.  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:02 | E8-9C-25-42-84-E5@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>485A_<br>568B.  | 否 |  |

|      |                  |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |  |   |  |
|------|------------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|--|---|--|
| 1171 | 福建省六六洲建设工程有限公司   | 2024-04-22 16:22:20.0 | 08-BF-B8-9E-DA-32@BF EBFBF F000A 0653@WD-WCC2E 5PAH7 2A, 50 026B7 66802 66FD, SCRW2 30228 01A00 06, 00 25_38 DA_11 40_85 92. | 否 | 2024-04-22 15:00:20.0 | 08-BF-B8-9E-DA-32@BF EBFBF F000A 0653@WD-WCC2E 5PAH7 2A, 50 026B7 66802 66FD, SCRW2 30228 01A00 06, 00 25_38 DA_11 40_85 92. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:30:50 | 08-BF-B8-9E-DA-32@BF EBFBF F000A 0653@WD-WCC2E 5PAH7 2A, 50 026B7 66802 66FD, SCRW2 30228 01A00 06, 00 25_38 DA_11 40_85 92. | 否  |   |  |
| 1172 | 中闽路航(福建)建设发展有限公司 | 2024-04-23 10:42:46.0 | E8-9C-25-43-BE-00@BF EBFBF F0009 0675@E823_8FA6_BF53_0001_001B_444A_4884_652C.   | 否 | 2024-04-22 16:14:20.0 | E8-9C-25-43-BE-00@BF EBFBF F0009 0675@E823_8FA6_BF53_0001_001B_444A_4884_652C.   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:32:41  | E8-9C-25-43-BE-00@BF EBFBF F0009 0675@E823_8FA6_BF53_0001_001B_444A_4884_652C. | 否 |  |

|      |               |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |   |  |  |
|------|---------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|---|--|--|
| 1173 | 福建世联鑫建设发展有限公司 | 2024-04-23 11:38:36.0 | 60-45-CB-9B-6E-2F, C8-E7-D8-ED-8E-9B, 00-00-00-00-00-00-06E9@50026B73809204D6, AA000000000060135 | 否 | 2024-04-22 15:25:21.0 | 60-45-CB-9B-6E-2F, C8-E7-D8-ED-8E-9B, 00-00-00-00-00-00-E0@BFEBFBFF000906E9@50026B73809204D6, AA000000000060135 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:07 | 60-45-CB-9B-6E-2F, C8-E7-D8-ED-8E-9B@BFEBFBFF000906E9@50026B73809204D6, AA000000000060135 | 否   |   |  |  |
| 1174 | 江苏鹏达建设集团有限公司  | 2024-04-23 16:06:14.0 | 00-E2-69-77-67-5B@BFEBFBFF00090675@0000_0000_0000_0000_00E0_4C60_2563_D938.                      | 否 | 2024-04-23 16:01:05.0 | 00-E2-69-77-67-5B@BFEBFBFF00090675@0000_0000_0000_0000_00E0_4C60_2563_D938.                                     | 否 |  |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:34:41   | 00-E2-69-77-67-5B@BFEBFBFF00090675@0000_0000_0000_0000_00E0_4C60_2563_D938. | 否 |  |  |

|      |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 1175 | 福建筑天城建设工程有限公司 | 2024-04-23 11:33:43.0 | 4C-<br>CC-<br>6A-<br>65-<br>65-<br>D4@BF<br>EBFBF<br>F0009<br>06E9@<br>SSMC2<br>13040<br>0802   | 否 | 2024-04-23 11:32:02.0 | 4C-<br>CC-<br>6A-<br>65-<br>65-<br>D4@BF<br>EBFBF<br>F0009<br>06E9@<br>SSMC2<br>13040<br>0802  | 否 |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:36:07   | 4C-<br>CC-<br>6A-<br>65-<br>65-<br>D4@BF<br>EBFBF<br>F0009<br>06E9@<br>SSMC2<br>13040<br>0802 | 否 |  |
| 1176 | 福建聚秦建设发展有限公司  | 2024-04-23 17:09:11.0 | 18-<br>C0-<br>4D-<br>15-<br>5F-<br>A1@BF<br>EBFBF<br>F0009<br>06ED@<br>20202<br>02020<br>20202<br>04357<br>36433<br>55955<br>45585<br>35936 | 否 | 2024-04-23 16:57:22.0 | 18-<br>C0-<br>4D-<br>15-<br>5F-<br>A1, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>EQ@BF<br>EBFBF<br>F0009<br>06ED@<br>20202<br>02020<br>20202<br>04357<br>36433<br>55955<br>45585<br>35936 | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:42:42 | 18-<br>C0-<br>4D-<br>15-<br>5F-<br>A1@BF<br>EBFBF<br>F0009<br>06ED@<br>20202<br>02020<br>20202<br>04357<br>36433<br>55955<br>45585<br>35936 | 否   |   |  |



|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|--|
| 1177 | 福建兴美达建设工程有限公司 | 2024-04-23 10:49:00.0 | 83-01@BF<br>EBFBF<br>F0003<br>06C3@4d463<br>03635<br>30325<br>33133<br>51383<br>03038<br>31333<br>82020 | 否 | 2024-04-23 10:44:12.0 | 00-E0-4C-96-45-B6,00-E0-4C-C0-83-01,00-00-00-00-C0-00-E0,00-00-00-00-E0@BF<br>EBFBF<br>F0003<br>06C3@4d463<br>03635<br>30325<br>33133<br>51383<br>03038<br>31333<br>82020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:36:18 | 83-01@BF<br>EBFBF<br>F0003<br>06C3@4d463<br>03635<br>30325<br>33133<br>51383<br>03038<br>31333<br>82020 | 否 |  |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|--|



|      |                      |                                  |  |   |                                  |  |   |  |  |  |                        |                                |  |  |   |  |
|------|----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|------------------------|--------------------------------|--|--|---|--|
| 1179 | 福建创至达<br>建设有限公司      | 2024-<br>04-23<br>11:17<br>:13.0 | 04-<br>42-<br>1A-<br>21-<br>93-<br>EB@BF<br>EBFBFB<br>F000A<br>0653@<br>ZN1PC<br>46B,0<br>000_0<br>000_0<br>000_0<br>000_0<br>100_0<br>000_0<br>000. | 否 | 2024-<br>04-23<br>11:04<br>:20.0 | 04-<br>42-<br>1A-<br>21-<br>93-<br>EB@BF<br>EBFBFB<br>F000A<br>0653@<br>ZN1PC<br>46B,0<br>000_0<br>000_0<br>000_0<br>000_0<br>100_0<br>000_0<br>000. | 否 |  |  |  |                        | 校验<br>数据有<br>误,请<br>检查         | 2024-<br>04-24<br>08:34<br>:12   | 04-<br>42-<br>1A-<br>21-<br>93-<br>EB@BF<br>EBFBFB<br>F000A<br>0653@<br>ZN1PC<br>46B,0<br>000_0<br>000_0<br>000_0<br>000_0<br>100_0<br>000_0<br>000. | 否 |  |
| 1180 | 福建北极洋<br>建设有限公司      | 2024-<br>04-22<br>16:05<br>:53.0 | B8-<br>97-<br>5A-<br>F5-<br>91-<br>13,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBFB<br>F0009<br>06E9@<br>WCC6Y<br>7UFFS<br>HJ     | 否 | 2024-<br>04-22<br>15:52<br>:39.0 | B8-<br>97-<br>5A-<br>F5-<br>91-<br>13,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBFB<br>F0009<br>06E9@<br>WCC6Y<br>7UFFS<br>HJ     | 否 |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:31<br>:40 | B8-<br>97-<br>5A-<br>F5-<br>91-<br>13@BF<br>EBFBFB<br>F0009<br>06E9@<br>WCC6Y<br>7UFFS<br>HJ | 否  |   |  |
| 1181 | 厦门市大方<br>舟建设有限<br>公司 | 2024-<br>04-23<br>20:19<br>:06.0 | 00-<br>FF-<br>E1-<br>86-<br>BD-<br>62,48<br>-F3-<br>17-<br>07-<br>87-  | 否 | 2024-<br>04-23<br>19:02<br>:47.0 | 00-<br>FF-<br>E1-<br>86-<br>BD-<br>62,48<br>-F3-<br>17-<br>07-<br>87-  | 否 |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:37<br>:36 | 00-<br>FF-<br>E1-<br>86-<br>BD-<br>62,48<br>-F3-<br>17-<br>07-<br>87-                        | 否  |   |  |

|      |            |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |                     |   |   |   |  |
|------|------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|---------------------|---|---|---|--|
|      |            |                              | BC, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0671@<br>125D2<br>01403<br>10, 21<br>09111<br>6-<br>00032<br>7   |   |                              | BC, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0671@<br>125D2<br>01403<br>10, 21<br>09111<br>6-<br>00032<br>7   |   |  |  |  |  |  |  |  |  |                     | BC, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0671@<br>125D2<br>01403<br>10, 21<br>09111<br>6-<br>00032<br>7 |   |   |  |
| 1182 | 福建永飞建设有限公司 | 2024-04-23<br>14:46<br>:38.0 | 50-<br>EB-<br>F6-<br>B4-<br>96-<br>E1, 00<br>-5C-<br>C2-<br>DC-<br>80-<br>72, 02<br>-5C-<br>C2-<br>DC-<br>80-<br>72, 00<br>-5C-<br>C2-<br>DC-<br>80-<br>72@BF<br>EBFBF<br>F000A<br>0653@<br>30057<br>80543<br>5 | 否 | 2024-04-23<br>14:45<br>:18.0 | 50-<br>EB-<br>F6-<br>B4-<br>96-<br>E1, 02<br>-5C-<br>C2-<br>DC-<br>80-<br>72, 00<br>-5C-<br>C2-<br>DC-<br>80-<br>72, 00<br>-5C-<br>C2-<br>DC-<br>80-<br>72@BF<br>EBFBF<br>F000A<br>0653@<br>30057<br>80543<br>5 | 否 |  |  |  |  |  |  |  |  | 校验数据<br>有误, 请<br>检查 | 2024-04-24<br>08:31<br>:12  | 50-<br>EB-<br>F6-<br>B4-<br>96-<br>E1, 00<br>-5C-<br>C2-<br>DC-<br>80-<br>72, 02<br>-5C-<br>C2-<br>DC-<br>80-<br>72, 00<br>-5C-<br>C2-<br>DC-<br>80-<br>72@BF<br>EBFBF<br>F000A<br>0653@<br>30057<br>80543<br>5 | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1183 | 福建航正建设工程有限公司 | 2024-04-23 16:44:14.0 | D8-BB-C1-16-20-04@BFEBFBFF000A0653@50026B7380E48E48                                     | 否 | 2024-04-23 16:43:19.0 | D8-BB-C1-16-20-04@BFEBFBFF000A0653@50026B7380E48E48                                     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:39:29 | D8-BB-C1-16-20-04@BFEBFBFF000A0653@50026B7380E48E48                                     | 否 |  |
| 1184 | 福建晶耘建设工程有限公司 | 2024-04-23 11:06:22.0 | D8-5E-D3-7C-AF-F9@BFEBFBFF00090675@CM163BH2304597                                       | 否 | 2024-04-23 11:01:34.0 | D8-5E-D3-7C-AF-F9@BFEBFBFF00090675@CM163BH2304597                                       | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:41:01 | D8-5E-D3-7C-AF-F9@BFEBFBFF00090675@CM163BH2304597                                       | 否 |  |
| 1185 | 厦门中天九州建设有限公司 | 2024-04-22 16:48:08.0 | 08-BF-B8-15-C4-A6@BFEBFBFF000A0653@WD-WCC6Y4AX1139,0000_0000_00_0000_0000_00_0000_0992. | 否 | 2024-04-22 16:03:21.0 | 08-BF-B8-15-C4-A6@BFEBFBFF000A0653@WD-WCC6Y4AX1139,0000_0000_00_0000_0000_00_0000_0992. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:05 | 08-BF-B8-15-C4-A6@BFEBFBFF000A0653@WD-WCC6Y4AX1139,0000_0000_00_0000_0000_00_0000_0992. | 否 |  |

|      |                        |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
| 1186 | 名城一建<br>(福建)发<br>展有限公司 | 2024-<br>04-23<br>16:24<br>:14.0 | 74-<br>56-<br>3C-<br>62-<br>AF-<br>C3@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC4J<br>J37L4<br>5Y,00<br>00_00<br>06_23<br>01_00<br>03_3A<br>5A_27<br>03_F0<br>00_01<br>93. | 否 | 2024-<br>04-23<br>11:36<br>:18.0 | 74-<br>56-<br>3C-<br>62-<br>AF-<br>C3@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC4J<br>J37L4<br>5Y,00<br>00_00<br>06_23<br>01_00<br>03_3A<br>5A_27<br>03_F0<br>00_01<br>93. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:34<br>:07 | 74-<br>56-<br>3C-<br>62-<br>AF-<br>C3@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC4J<br>J37L4<br>5Y,00<br>00_00<br>06_23<br>01_00<br>03_3A<br>5A_27<br>03_F0<br>00_01<br>93. | 否 |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|

|      |                   |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |  |                    |                        |  |   |  |  |
|------|-------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|--------------------|------------------------|--|---|--|--|
| 1187 | 福建汇千峰<br>建设工程有限公司 | 2024-04-22<br>16:38:06.0 | 18-<br>C0-<br>4D-<br>56-<br>21-<br>D9@BF<br>EBFBF<br>F0009<br>06EB@<br>30353<br>23042<br>36333<br>73038<br>42413<br>53136<br>35202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>33594<br>44432<br>45353<br>8 | 否 | 2024-04-22<br>16:27:21.0 | 18-<br>C0-<br>4D-<br>56-<br>21-<br>D9,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>06EB@<br>EBFBF<br>F0009<br>06EB@<br>30353<br>23042<br>36333<br>73038<br>42413<br>53136<br>35202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>33594<br>44432<br>45353<br>8 | 否 |  |  |  |  |  |  |  |  |  | 校验数据<br>有误,请<br>检查 | 2024-04-24<br>08:31:41 | 18-<br>C0-<br>4D-<br>56-<br>21-<br>D9@BF<br>EBFBF<br>F0009<br>06EB@<br>30353<br>23042<br>36333<br>73038<br>42413<br>53136<br>35202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>33594<br>44432<br>45353<br>8 | 否 |  |  |
|------|-------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|--------------------|------------------------|--|---|--|--|





|      |                       |                                  |   |                                  |   |  |  |  |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
|------|-----------------------|----------------------------------|---|----------------------------------|---|--|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|
| 1189 | 福建祥兴胜<br>建设发展有<br>限公司 | 2024-<br>04-22<br>10:25<br>:55.0 | 否 | 2024-<br>04-22<br>10:18<br>:05.0 | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:59<br>:18 | 70-<br>B5-<br>E8-<br>25-<br>EB-<br>C4, DC<br>-1B-<br>A1-<br>80-<br>32-<br>7E, DC<br>-1B-<br>A1-<br>80-<br>32-<br>7A, DC<br>-1B-<br>A1-<br>80-<br>32-<br>7B, DE<br>-1B-<br>A1-<br>80-<br>32-<br>7A@BF<br>EBFBF<br>F000A<br>0653@<br>106TA<br>N6MS | 否 |  |
|------|-----------------------|----------------------------------|---|----------------------------------|---|--|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |             |                     |  |   |  |  |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|--|--|
|      |                |                       | 18_11<br>C6.,Z<br>9AVR4<br>TQ   |   |                       | 18_11<br>C6.,Z<br>9AVR4<br>TQ   |   |  |  |  |  |  |  |  |  |             |                     |  |   |  |  |  |
| 1190 | 中标福顺建设(福建)有限公司 | 2024-04-22 11:24:22.0 | 48-8A-D2-6D-F7-FF, 48-8A-D2-6D-F7-FE, F8-32-E4-6E-B1-92, 00-00-00-00-00-EO@BF EBFBF F0003 06C3@ 30353 23042 36333 73238 37333 33233 42202 02020 | 否 | 2024-04-22 11:14:22.0 | 48-8A-D2-6D-F7-FF, 48-8A-D2-6D-F7-FE, F8-32-E4-6E-B1-92, 00-00-00-00-00-EO@BF EBFBF F0003 06C3@ 30353 23042 36333 73238 37333 33233 42202 02020 | 否 |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:55:51 | 48-8A-D2-6D-F7-FF, 48-8A-D2-6D-F7-FE, F8-32-E4-6E-B1-92@BF EBFBF F0003 06C3@ 30353 23042 36333 73238 37333 33233 42202 02020 | 否 |  |  |  |

|      |                       |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |  |  |                                   |                            |  |   |  |
|------|-----------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|-----------------------------------|----------------------------|--|---|--|
| 1191 | 福建省旭司<br>建设发展有<br>限公司 | 2024-04-23<br>14:44<br>:34.0 | 14-<br>DD-<br>A9-<br>EE-<br>ID-<br>05@BF<br>EBFBF<br>F0003<br>06C3@<br>58573<br>03233<br>32383<br>03430<br>31303<br>23032<br>34202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73443<br>304d4<br>64143<br>48504<br>a | 否 | 2024-04-23<br>14:42<br>:42.0 | 14-<br>DD-<br>A9-<br>EE-<br>ID-<br>05@BF<br>EBFBF<br>F0003<br>06C3@<br>58573<br>03233<br>32383<br>03430<br>31303<br>23032<br>34202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73443<br>304d4<br>64143<br>48504<br>a | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>检<br>查 | 2024-04-24<br>08:41<br>:16 | 14-<br>DD-<br>A9-<br>EE-<br>ID-<br>05@BF<br>EBFBF<br>F0003<br>06C3@<br>58573<br>03233<br>32383<br>03430<br>31303<br>23032<br>34202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73443<br>304d4<br>64143<br>48504<br>a | 否 |  |
|------|-----------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|-----------------------------------|----------------------------|--|---|--|







|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1196 | 四川杰欣建筑工程有限公司 | 2024-04-23 15:55:39.0 | 48-F3-17-11-31-CE@BF EBFBF F000A 0653@50026 B7382 1ED103                        | 否 | 2024-04-23 15:54:23.0 | 48-F3-17-11-31-CE@BF EBFBF F000A 0653@50026 B7382 1ED103                        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:39 | 48-F3-17-11-31-CE@BF EBFBF F000A 0653@50026 B7382 1ED103                        | 否 |  |
| 1197 | 福建鑫鸿城建设有限公司  | 2024-04-23 14:58:59.0 | AC-22-0B-C9-0C-OB@BF EBFBF F0002 06A7@WD-WCC2E XZ071 60, ZT B1256 KA220 6516M X | 否 | 2024-04-23 14:59:06.0 | AC-22-0B-C9-0C-OB@BF EBFBF F0002 06A7@WD-WCC2E XZ071 60, ZT B1256 KA220 6516M X | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:40    | AC-22-0B-C9-0C-OB@BF EBFBF F0002 06A7@WD-WCC2E XZ071 60, ZT B1256 KA220 6516M X | 否 |  |
| 1198 | 广西联友建设工程有限公司 | 2024-04-24 08:13:50.0 | 0A-E0-AF-B5-06-DA@BF EBFBF F0003 06E4@9WSA6 SQX, 0 254X0 54890 1                | 否 | 2024-04-24 08:12:21.0 | 0A-E0-AF-B5-06-DA@BF EBFBF F0003 06E4@9WSA6 SQX, 0 254X0 54890 1                | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:07 | 0A-E0-AF-B5-06-DA@BF EBFBF F0003 06E4@9WSA6 SQX, 0 254X0 54890 1                | 否 |  |

|      |               |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |  |             |                        |  |   |  |
|------|---------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|------------------------|--|---|--|
| 1199 | 福建成蛟建设发展有限公司  | 2024-04-23<br>13:50:27.0 | E8-9C-25-C3-04-AF@BFBFBF00090675@0000_0000_0000_0000_0026B73822FF4A25. | 否 | 2024-04-23<br>13:50:55.0 | E8-9C-25-C3-04-AF@BFBFBF00090675@0000_0000_0000_0000_0026B73822FF4A25.             | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24<br>08:35:14 | E8-9C-25-C3-04-AF@BFBFBF00090675@0000_0000_0000_0000_0026B73822FF4A25. | 否 |  |
| 1200 | 福建天佳源建设工程有限公司 | 2024-04-23<br>10:41:01.0 | D4-5D-64-4A-4D-27@BFBFBF000906EB@50026B73808602EA                      | 否 | 2024-04-23<br>10:38:21.0 | D4-5D-64-4A-4D-27,00-00-00-00-00-00-00-00-00-00-E0@BFBFBF000906EB@50026B73808602EA | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24<br>08:34:43 | D4-5D-64-4A-4D-27@BFBFBF000906EB@50026B73808602EA                      | 否 |  |
| 1201 | 福建闽延兴建设发展有限公司 | 2024-04-23<br>16:56:57.0 | 58-11-22-99-97-79@BFBFBF000A0655@WD-WCC6Y                              | 否 | 2024-04-23<br>08:51:15.0 | 58-11-22-99-97-79@BFBFBF000A0655@WD-WCC6Y  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24<br>08:35:02 | 58-11-22-99-97-79@BFBFBF000A0655@WD-WCC6Y                              | 否 |  |



|      |                    |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |                            |                        |   |   |  |
|------|--------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|----------------------------|------------------------|---|---|--|
|      |                    |                          | 1HZD7<br>UJ, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4E<br>87_3A<br>EF.  |   |                          | 1HZD7<br>UJ, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4E<br>87_3A<br>EF.  |   |  |  |  |  |  |  |  |  |                            |                        | 1HZD7<br>UJ, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4E<br>87_3A<br>EF.                   |   |  |
| 1202 | 创融建设<br>(福建)集团有限公司 | 2024-04-23<br>16:07:06.0 | B4-<br>2E-<br>99-<br>26-<br>42-<br>E9@BF<br>EBFBF<br>F0009<br>06EB@<br>00147<br>85448<br>B4F09<br>07788<br>136C,<br>NGL51<br>3R009<br>6890S<br>30W, A<br>D2A24<br>11908<br>08014<br>96 | 否 | 2024-04-23<br>16:00:31.0 | B4-<br>2E-<br>99-<br>26-<br>42-<br>E9@BF<br>EBFBF<br>F0009<br>06EB@<br>00147<br>85448<br>B4F09<br>07788<br>136C,<br>NGL51<br>3R009<br>6890S<br>30W, A<br>D2A24<br>11908<br>08014<br>96 | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:57:42 | 00-<br>D3-<br>F2-<br>1A-<br>55-<br>92@BF<br>EBFBF<br>F0005<br>06E3@<br>MX_2B<br>093DA<br>00000<br>00096 | 否 |  |

|      |             |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|-------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1203 | 福建省鸿飞建设有限公司 | 2024-04-17 13:31:59.0 | 54-E1-AD-B8-90-8E, 60-14-B3-BF-85-50, 60-14-B3-BF-85-4F, 62-14-B3-BF-85-4F, 60-14-B3-BF-85-4F@BF-EBFBF-F0008-06E9@WD-WX61A-87HHH-6P, YS-20191-16264 | 否 | 2024-04-17 13:30:20.0 | 62-14-B3-BF-85-4F, 60-14-B3-BF-85-4F, 54-E1-AD-B8-90-8E, 60-14-B3-BF-85-4F, 60-14-B3-BF-85-50@BF-EBFBF-F0008-06E9@WD-WX61A-87HHH-6P, YS-20191-16264 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 09:02:47 | 54-E1-AD-B8-90-8E, 60-14-B3-BF-85-50, 60-14-B3-BF-85-4F, 62-14-B3-BF-85-4F@BF-EBFBF-F0008-06E9@WD-WX61A-87HHH-6P, YS-20191-16264 | 否 |  |
|------|-------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|

|      |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1204 | 福建海川建设工程有限公司 | 2024-04-18 10:44:01.0 | 18-31-BF-BE-13-D0,00-00-00-00-00-13-D0@BF EBFBF F0009 06E9@ TA211 24127 40175 | 否 | 2024-04-18 10:42:46.0 | 18-31-BF-BE-13-D0,00-00-00-00-00-13-E0,00-00-00-00-00-00-E0@BF EBFBF F0009 06E9@ TA211 24127 40175 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:40 | 18-31-BF-BE-13-D0@BF EBFBF F0009 06E9@ TA211 24127 40175 | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|





|      |            |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1207 | 福建英唐建设有限公司 | 2024-04-23 09:51:12.0 | B4-<br>2E-<br>99-<br>0E-<br>29-<br>5E@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>OHS8<br>K4, 19<br>21BE4<br>45715 | 否 | 2024-04-22 16:50:16.0 | B4-<br>2E-<br>99-<br>0E-<br>29-<br>5E, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>OHS8<br>K4, 19<br>21BE4<br>45715 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:35:50 | B4-<br>2E-<br>99-<br>0E-<br>29-<br>5E@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>OHS8<br>K4, 19<br>21BE4<br>45715 | 否 |  |
|------|------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|

|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1208 | 福建省大闽路桥工程有限公司 | 2024-04-23 21:24:54.0 | 24-4B-FE-48-24-DC, 00-15-83-02-4A-19@BF EBFBF F0009 06EA@WD-WCC6Y 1AX8P 9D, 00 25_38 8A_01 07_A8 49., 0 00000 0005 | 否 | 2024-04-23 21:23:09.0 | 24-4B-FE-48-24-DC, 00-15-83-02-4A-19@BF EBFBF F0009 06EA@WD-WCC6Y 1AX8P 9D, 00 25_38 8A_01 07_A8 49., 0 00000 0005 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:49:52 | 24-4B-FE-48-24-DC, 00-15-83-02-4A-19@BF EBFBF F0009 06EA@WD-WCC6Y 1AX8P 9D, 00 25_38 8A_01 07_A8 49., 0 00000 0005 | 否 |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1209 | 厦门尊鑫建筑工程有限公司 | 2024-04-23 10:47:42.0 | 30-5A-3A-75-BE-82@BF EBFBF F0003 06C3@TA215 14614 B0500,0101 laebc fc54a 65d6ae, AU6 479 | 否 | 2024-04-23 10:39:56.0 | 30-5A-3A-75-BE-82@BF EBFBF F0003 06C3@TA215 14614 B0500,0101 laebc fc54a 65d6ae, AU6 479 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:54 | 70-8B-CD-05-0F-33, 74-DF-BF-CB-A7-B4, 76-DF-BF-CB-A7-B4, 74-DF-BF-CB-A7-B4@BF EBFBF F0005 06E3@S32XJ 9EH30 2806, C4420 7691C EE036 37603 | 否 |  |
| 1210 | 福建万增建设有限公司   | 2024-04-23 10:21:13.0 | FC-34-97-A7-A2-47@BF EBFBF F0009 06EA@4e533 33235 33383 03139 31343 53720 20202 02020    | 否 | 2024-04-23 09:54:38.0 | FC-34-97-A7-A2-47@BF EBFBF F0009 06EA@4e533 33235 33383 03139 31343 53720 20202 02020    | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:47 | F4-B5-20-13-51-B0@BF EBFBF F0009 06EA@ 20221 11100 323   | 否 |  |



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1211 | 湖南恒宇电力建设有限公司 | 2024-04-19 16:25:00.0 | 00-<br>E0-<br>4C-<br>3F-<br>36-<br>6B@BF<br>EBFBF<br>F000A<br>0653@<br>2HT10<br>07907<br>10W01<br>4C0 | 否 | 2024-04-19 15:48:17.0 | 00-<br>E0-<br>4C-<br>3F-<br>36-<br>6B@BF<br>EBFBF<br>F000A<br>0653@<br>2HT10<br>07907<br>10W01<br>4C0 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:48:55 | 00-<br>E0-<br>4C-<br>3F-<br>36-<br>6B@BF<br>EBFBF<br>F000A<br>0653@<br>2HT10<br>07907<br>10W01<br>4C0 | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|

|      |              |   |   |  |   |  |  |  |  |  |  |  |  |  |  |  |                        |   |  |
|------|--------------|---|---|--|---|--|--|--|--|--|--|--|--|--|--|--|------------------------|---|--|
| 1212 | 福州庭佳建设工程有限公司 | 2024-04-23<br>09:25:18.0  | 否 | 2024-04-22<br>11:23:04.0   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查   | 2024-04-24<br>08:34:39 | 否 |  |
|      |              | 04-7C-16-44-A1-BA, 0A-1F-71-5C-F8-34, 08-1F-71-5C-F8-34, 08-1F-71-5C-F8-34, 08-1F-71-5C-F8-34, 00-00-00-00-00-00-00-00-00-00-00-E0@BF-EBFBF-F0009-0675@-E823_-8FA6_-BF53_-0001_-001B_-448B_-4B3F_-526C. |   | 04-7C-16-44-A1-BA, 0A-1F-71-5C-F8-34, 08-1F-71-5C-F8-34, 08-1F-71-5C-F8-34, 00-00-00-00-00-00-00-00-00-00-00-E0@BF-EBFBF-F0009-0675@-E823_-8FA6_-BF53_-0001_-001B_-448B_-4B3F_-526C. |   |  |  |  |  |  |  |  |  |  |  | 04-7C-16-44-A1-BA, 0A-1F-71-5C-F8-34, 08-1F-71-5C-F8-34, 08-1F-71-5C-F8-34, 00-00-00-00-00-00-00-00-00-00-00-E0@BF-EBFBF-F0009-0675@-E823_-8FA6_-BF53_-0001_-001B_-448B_-4B3F_-526C. |                        |   |  |

|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |  |  |  |  |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|--|--|--|--|--|
| 1213 | 厦门泓兆建设有限公司 | 2024-04-23 15:58:38.0 | 40-8D-5C-6A-84-E5,00-00-00-00-00-00-E0,00-00-00-00-00-00-E0,00 | 否 | 2024-04-22 16:34:47.0 | 40-8D-5C-6A-84-E5,00-00-00-00-00-00-E0,00-00-00-00-00-00-E0,00 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误,请检查 | 2024-04-24 08:48:36 | 40-8D-5C-6A-84-E5,00-00-00-00-00-00-E0,00-00-00-00-00-00-E0,00 | 否 |  |  |  |  |  |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|--|--|--|--|--|

|      |            |  |   |  |   |  |  |  |  |  |  |  |  |  |  |  |  |                     |             |  |   |
|------|------------|--|---|--|---|--|--|--|--|--|--|--|--|--|--|--|--|---------------------|-------------|--|---|
| 1214 | 贵州九通建设有限公司 | 2024-04-23 16:45:57.0  | 否 | 2024-04-17 16:14:33.0  | 否 |  |  |  |  |  |  |  |  |  |  |  |  | 2024-04-24 08:56:27 | 校验数据有误, 请检查 | 2024-04-24 08:56:27  | 否 |
|      |            | 00-<br>E0-<br>4C-<br>DB-<br>13-<br>DE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>53534<br>34d30<br>32313<br>33035<br>35313<br>33520<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>75341<br>32323<br>13830<br>30393<br>1 |   | 00-<br>E0-<br>4C-<br>DB-<br>13-<br>DE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>53534<br>34d30<br>32313<br>33035<br>35313<br>33520<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>75341<br>32323<br>13830<br>30393<br>1 |   |  |  |  |  |  |  |  |  |  |  |  |  |                     |             | 00-<br>E0-<br>4C-<br>DB-<br>13-<br>DE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>53534<br>34d30<br>32313<br>33035<br>35313<br>33520<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>75341<br>32323<br>13830<br>30393<br>1 |   |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1215 | 中州万基城市建设有限公司 | 2024-04-23 10:31:59.0 | 04-7C-16-D4-43-39@BFEBFBFF00090675@0000_0000_0000_0000_00E0_4C12_D994_7F9B.                    | 否 | 2024-04-23 10:30:34.0 | 04-7C-16-D4-43-39@BFEBFBFF00090675@0000_0000_0000_0000_00E0_4C12_D994_7F9B.                    | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:31:39 | 04-7C-16-D4-43-39@BFEBFBFF00090675@0000_0000_0000_0000_00E0_4C12_D994_7F9B.                    | 否 |  |
| 1216 | 福建川耀建设工程有限公司 | 2024-04-22 22:09:23.0 | 08-BF-B8-84-6F-24@BFEBFBFF000A0671@E823_8FA6_BF53_0001_001B_444A_48E8_A9D1.,222222222222220138 | 否 | 2024-04-22 22:02:10.0 | 08-BF-B8-84-6F-24@BFEBFBFF000A0671@E823_8FA6_BF53_0001_001B_444A_48E8_A9D1.,222222222222220138 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:39:36 | 08-BF-B8-84-6F-24@BFEBFBFF000A0671@E823_8FA6_BF53_0001_001B_444A_48E8_A9D1.,222222222222220138 | 否 |  |

|      |                        |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |  |                            |                                |  |   |   |  |
|------|------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|---|--|
| 1217 | 福建鹏飞宇<br>建筑工程有<br>限公司  | 2024-<br>04-23<br>15:48<br>:51.0 | 74-<br>56-<br>3C-<br>C2-<br>33-<br>85@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>A47R1<br>LS, 00<br>25_38<br>A7_21<br>B0_79<br>1E. | 否 | 2024-<br>04-23<br>15:47<br>:54.0 | 74-<br>56-<br>3C-<br>C2-<br>33-<br>85@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>A47R1<br>LS, 00<br>25_38<br>A7_21<br>B0_79<br>1E. | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>09:03<br>:34 | 74-<br>56-<br>3C-<br>C2-<br>33-<br>85@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>A47R1<br>LS, 00<br>25_38<br>A7_21<br>B0_79<br>1E. | 否   |   |  |
| 1218 | 福建越重建<br>设工程发展<br>有限公司 | 2024-<br>04-23<br>17:43<br>:11.0 | 18-<br>C0-<br>4D-<br>19-<br>A6-<br>E8@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>6B07C<br>D                                      | 否 | 2024-<br>04-23<br>17:37<br>:46.0 | 18-<br>C0-<br>4D-<br>19-<br>A6-<br>E8@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>6B07C<br>D                                      | 否 |  |  |  |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>，请<br>检查     | 2024-<br>04-24<br>08:43<br>:54   | 18-<br>C0-<br>4D-<br>19-<br>A6-<br>E8@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>6B07C<br>D | 否 |  |



|      |                        |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                            |                                |   |   |   |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|---|--|
| 1220 | 中建九洲<br>(福建)建<br>设有限公司 | 2024-<br>04-19<br>11:31<br>:56.0 | D8-<br>5E-<br>D3-<br>17-<br>A0-<br>2B@BF<br>EBFBF<br>F000A<br>0653@<br>4e533<br>03231<br>35383<br>03239<br>31313<br>73620<br>20202<br>02020 | 否 | 2024-<br>04-19<br>11:14<br>:37.0 | D8-<br>5E-<br>D3-<br>17-<br>A0-<br>2B,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>4e533<br>03231<br>35383<br>03239<br>31313<br>73620<br>20202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>,请<br>检查 | 2024-<br>04-24<br>08:31<br>:44 | D8-<br>5E-<br>D3-<br>17-<br>A0-<br>2B@BF<br>EBFBF<br>F000A<br>0653@<br>4e533<br>03231<br>35383<br>03239<br>31313<br>73620<br>20202<br>02020 | 否   |   |  |
| 1221 | 福建中聚德<br>建设工程有<br>限公司  | 2024-<br>04-23<br>11:45<br>:13.0 | 00-<br>E2-<br>69-<br>47-<br>6A-<br>F2@BF<br>EBFBF<br>F0009<br>06EA@<br>YS222<br>5618R<br>TGI02<br>24,YS<br>20201<br>08821<br>87AA           | 否 | 2024-<br>04-23<br>11:42<br>:35.0 | 00-<br>E2-<br>69-<br>47-<br>6A-<br>F2@BF<br>EBFBF<br>F0009<br>06EA@<br>YS222<br>5618R<br>TGI02<br>24,YS<br>20201<br>08821<br>87AA   | 否 |  |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>,请<br>检查     | 2024-<br>04-24<br>08:45<br>:11  | 00-<br>E2-<br>69-<br>47-<br>6A-<br>F2@BF<br>EBFBF<br>F0009<br>06EA@<br>YS222<br>5618R<br>TGI02<br>24,YS<br>20201<br>08821<br>87AA | 否 |  |



|      |                |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|----------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1222 | 福建交大建设发展有限公司   | 2024-04-23 11:46:23.0 | 10-62-E5-0E-5D-4E, 90-32-4B-40-F4-BD, 92-32-4B-40-F4-BD, D2-32-4B-40-F4-BD, 90-32-4B-40-F4-BE@BF EBFBF F0009 06EB@Z9ATX E83 | 否 | 2024-04-23 11:41:01.0 | 10-62-E5-0E-5D-4E, 90-32-4B-40-F4-BD, 92-32-4B-40-F4-BD, D2-32-4B-40-F4-BE@BF EBFBF F0009 06EB@Z9ATX E83 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:47 | 10-62-E5-0E-5D-4E, 90-32-4B-40-F4-BD, 92-32-4B-40-F4-BD, 90-32-4B-40-F4-BE@BF EBFBF F0009 06EB@Z9ATX E83 | 否 |  |
| 1223 | 海峡建工(北京)建设有限公司 | 2024-04-19 18:01:21.0 | 08-BF-B8-A6-51-1C@BF EBFBF F0009 0675@0000_0000_0000_0000_0000_0000_ A428_ B702_ D3D6_ 0082.                                | 否 | 2024-04-19 17:55:17.0 | 08-BF-B8-A6-51-1C@BF EBFBF F0009 0675@0000_0000_0000_0000_0000_0000_ A428_ B702_ D3D6_ 0082.             | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 09:00:16 | 08-BF-B8-A6-51-1C@BF EBFBF F0009 0675@0000_0000_0000_0000_0000_0000_ A428_ B702_ D3D6_ 0082.             | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |  |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|--|---|--|
| 1224 | 福建达铭建设有限公司   | 2024-04-23 15:46:18.0 | 24-4B-FE-D0-41-D4@BF<br>EBFBF<br>F000A<br>0653@<br>MG201<br>05000<br>00000<br>02355<br>,WD-<br>WCC6Y<br>OCX4Z<br>EV | 否 | 2024-04-23 15:41:51.0 | 24-4B-FE-D0-41-D4@BF<br>EBFBF<br>F000A<br>0653@<br>MG201<br>05000<br>00000<br>02355<br>,WD-<br>WCC6Y<br>OCX4Z<br>EV | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:44:10 | 24-4B-FE-D0-41-D4@BF<br>EBFBF<br>F000A<br>0653@<br>MG201<br>05000<br>00000<br>02355<br>,WD-<br>WCC6Y<br>OCX4Z<br>EV | 否  |   |  |
| 1225 | 福建竣强建设工程有限公司 | 2024-04-23 13:01:18.0 | 74-56-3C-8C-E1-2E@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A781_<br>AAD0_<br>031A.                                 | 否 | 2024-04-23 12:55:03.0 | 74-56-3C-8C-E1-2E@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A781_<br>AAD0_<br>031A.                                 | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:32:47   | 74-56-3C-8C-E1-2E@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A781_<br>AAD0_<br>031A.                | 否 |  |
| 1226 | 福建宝山建设发展有限公司 | 2024-04-18 10:33:45.0 | E0-D5-5E-61-EC-1F@BF<br>EBFBF<br>F0009<br>06E9@<br>10016<br>42564<br>8,WD-<br>WCC6Y<br>7HSED<br>FU                  | 否 | 2024-04-18 10:32:34.0 | E0-D5-5E-61-EC-1F@BF<br>EBFBF<br>F0009<br>06E9@<br>10016<br>42564<br>8,WD-<br>WCC6Y<br>7HSED<br>FU                  | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:35:02   | E0-D5-5E-61-EC-1F@BF<br>EBFBF<br>F0009<br>06E9@<br>10016<br>42564<br>8,WD-<br>WCC6Y<br>7HSED<br>FU | 否 |  |





|      |                 |                              |  |   |                              |   |   |  |  |  |  |  |  |  |  |                        |                            |  |   |  |  |
|------|-----------------|------------------------------|--|---|------------------------------|---|---|--|--|--|--|--|--|--|--|------------------------|----------------------------|--|---|--|--|
| 1229 | 福建隆腾悦<br>建设有限公司 | 2024-04-23<br>10:53<br>:36.0 | F4-<br>B5-<br>20-<br>0F-<br>51-<br>72, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>2024-04-23<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36333<br>73038<br>45414<br>53934<br>32202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>365a5<br>94454<br>39524<br>1 | 否 | 2024-04-22<br>16:56<br>:24.0 | F4-<br>B5-<br>20-<br>0F-<br>51-<br>72, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>2024-04-22<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36333<br>73038<br>45414<br>53934<br>32202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>365a5<br>94454<br>39524<br>1 | 否 |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误，请<br>检查 | 2024-04-24<br>08:31<br>:40 | F4-<br>B5-<br>20-<br>0F-<br>51-<br>72, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>2024-04-24<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36333<br>73038<br>45414<br>53934<br>32202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>365a5<br>94454<br>39524<br>1 | 否 |  |  |
|------|-----------------|------------------------------|--|---|------------------------------|---|---|--|--|--|--|--|--|--|--|------------------------|----------------------------|--|---|--|--|

|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1230 | 福建矿泉建设有限公司     | 2024-04-22 14:41:13.0 | D8-BB-C1-90-38-38@BF EBFBF F000A 0653@50026 B7381 4156A 0                      | 否 | 2024-04-22 11:27:59.0 | D8-BB-C1-90-38-38@BF EBFBF F000A 0653@50026 B7381 4156A 0                      | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:13 | D8-BB-C1-6B-94-50@BF EBFBF F000A 0653@50026 B7784 8BAF3 E                      | 否 |  |
| 1231 | 福建中锐联信建设发展有限公司 | 2024-04-23 16:57:44.0 | C8-7F-54-9E-37-E5@BF EBFBF F000A 0653@E823_8FA6_BF53_0001_001B_444A_49DF_0745. | 否 | 2024-04-22 17:17:37.0 | C8-7F-54-9E-37-E5@BF EBFBF F000A 0653@E823_8FA6_BF53_0001_001B_444A_49DF_0745. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:07 | C8-7F-54-9E-37-E5@BF EBFBF F000A 0653@E823_8FA6_BF53_0001_001B_444A_49DF_0745. | 否 |  |
| 1232 | 福建杭大建设工程有限公司   | 2024-04-23 16:56:41.0 | C8-7F-54-9F-6B-BB@BF EBFBF F0009 0675@S6PZN XOW30 0906V                        | 否 | 2024-04-22 11:38:09.0 | C8-7F-54-9F-6B-BB@BF EBFBF F0009 0675@S6PZN XOW30 0906V                        | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:31:34 | C8-7F-54-9F-6B-BB@BF EBFBF F0009 0675@S6PZN XOW30 0906V                        | 否 |  |



|      |                   |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|------|-------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
| 1234 | 福建省繁荣<br>建筑工程有限公司 | 2024-<br>04-23<br>11:16<br>:07.0 | A0-<br>36-<br>BC-<br>22-<br>00-<br>48@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4C87_<br>0B75. | 否 | 2024-<br>04-19<br>10:10<br>:36.0 | A0-<br>36-<br>BC-<br>22-<br>00-<br>48@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4C87_<br>0B75. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:34<br>:07 | A0-<br>36-<br>BC-<br>22-<br>00-<br>48@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4C87_<br>0B75. | 否 |  |
|------|-------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|





|      |               |                       |   |                       |   |  |  |  |  |  |  |  |  |  |  |  |            |                     |   |  |  |
|------|---------------|-----------------------|---|-----------------------|---|--|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|--|--|
| 1237 | 福建闽造建设发展有限公司  | 2024-04-23 11:49:02.0 | 否 | 2024-04-22 17:08:04.0 | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:30 | 否 |  |  |
|      | 福建省天钧建设集团有限公司 | 2024-04-22 17:25:16.0 | 否 | 2024-04-22 17:23:07.0 | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:07 | 否 |  |  |

|      |                 |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1239 | 福建兴洛建设有限公司      | 2024-04-23 09:47:38.0 | A0-36-BC-25-17-CD@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_448B_4E4A_1112.          | 否 | 2024-04-23 09:45:44.0 | A0-36-BC-25-17-CD@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_448B_4E4A_1112.          | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:22 | A0-36-BC-25-17-CD@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_448B_4E4A_1112.          | 否 |  |
| 1240 | 福建省华鑫皓筑建筑工程有限公司 | 2024-04-23 10:53:14.0 | 00-E2-69-60-F6-65@BF<br>EBFBF<br>F000A<br>0653@<br>WW000<br>00000<br>00000<br>00016<br>_0000<br>0001. | 否 | 2024-04-23 10:43:53.0 | 00-E2-69-60-F6-65@BF<br>EBFBF<br>F000A<br>0653@<br>WW000<br>00000<br>00000<br>00016<br>_0000<br>0001. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:40:27 | 00-E2-69-60-F6-65@BF<br>EBFBF<br>F000A<br>0653@<br>WW000<br>00000<br>00000<br>00016<br>_0000<br>0001. | 否 |  |
| 1241 | 福建标建建设工程有限公司    | 2024-04-23 09:23:59.0 | 08-1F-71-1D-08-EA,00<br>-E0-4C-0D-A2-F9@BF<br>EBFBF<br>F0009<br>06EA@<br>41413<br>03030               | 否 | 2024-04-23 09:24:54.0 | 08-1F-71-1D-08-EA,00<br>-E0-4C-0D-A2-F9,00<br>-00-00-00-00-   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:34 | 08-1F-71-1D-08-EA,00<br>-E0-4C-0D-A2-F9@BF<br>EBFBF<br>F0009<br>06EA@<br>41413<br>03030               | 否 |  |



|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1242 | 福建森航建设有限公司    | 2024-04-23 17:07:45.0 | 60-EE-5C-2D-AA-DF, 60-EE-5C-2D-AA-D8, 70-4D-7B-32-5A-7F, 60-EE-5C-2D-AA-DD@BFEBFBFF000906E9@50026B73822D67FB | 否 | 2024-04-23 12:03:25.0 | 60-EE-5C-2D-AA-DF, 60-EE-5C-2D-AA-D8, 70-4D-7B-32-5A-7F, 60-EE-5C-2D-AA-DD@BFEBFBFF000906E9@50026B73822D67FB | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:06 | 60-EE-5C-2D-AA-DF, 60-EE-5C-2D-AA-D8, 70-4D-7B-32-5A-7F, 60-EE-5C-2D-AA-DD@BFEBFBFF000906E9@50026B73822D67FB | 否 |  |
| 1243 | 福建省展志建设发展有限公司 | 2024-04-23 11:04:44.0 | D8-5E-D3-C1-BF-4D@BFEBFBFF00090675@6479_A75E_10C0_26F2., WD-WCC6Y2XCZDS1                                     | 否 | 2024-04-23 11:03:33.0 | D8-5E-D3-C1-BF-4D@BFEBFBFF00090675@6479_A75E_10C0_26F2., WD-WCC6Y2XCZDS1                                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:53 | D8-5E-D3-C1-BF-4D@BFEBFBFF00090675@6479_A75E_10C0_26F2., WD-WCC6Y2XCZDS1                                     | 否 |  |

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1244 | 福建绿湾园林景观工程有限公司 | 2024-04-22 16:21:14.0 | 50-EB-F6-2C-29-71@BFEBFBF000A0653@3035323042363337313837314338313220202020,2020202057202d444357364334594e4334344a4e | 否 | 2024-04-22 16:19:59.0 | 50-EB-F6-2C-29-71,00-00-00-00-00-00-71@BFEBFBF000A0653@30353230423633373138E0@BFEBFBF000A0653@30353230423633373138373143383132202020,2020202057202d444357364334594e4334344a4e | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:56:27 | 50-EB-F6-2C-29-71@BFEBFBF000A0653@30353230423633373138373143383132202020,2020202057202d444357364334594e4334344a4e | 否 |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|

|      |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1245 | 福建千正建设工程有限公司 | 2024-04-23 11:48:14.0 | 00-E0-70-C2-17-98,00-00-00-00-00@BFEBFBFF000A0653@MG20090004615,ZN1JD5EV | 否 | 2024-04-23 11:45:08.0 | 00-E0-70-C2-17-98@BFEBFBFF000A0653@MG20090004615,ZN1JD5EV           | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:55 | 00-E0-70-C2-17-98,00-00-00-00-00@BFEBFBFF000A0653@MG20090004615,ZN1JD5EV | 否 |  |
| 1246 | 浙江辉华建设有限公司   | 2024-04-23 19:09:52.0 | D8-5E-D3-DB-AB-61@BFEBFBFF000A0653@50026B7784B43C34,WD-WCC6Y1KXJJ93      | 否 | 2024-04-23 19:08:22.0 | D8-5E-D3-DB-AB-61@BFEBFBFF000A0653@50026B7784B43C34,WD-WCC6Y1KXJJ93 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:34:39 | D8-5E-D3-DB-AB-61@BFEBFBFF000A0653@50026B7784B43C34,WD-WCC6Y1KXJJ93      | 否 |  |

|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|--|---|--|
| 1247 | 福建汇和建设发展有限公司  | 2024-04-23 14:08:35.0 | E0-D5-5E-D8-32-6E@BF EBFBF F0009 06EB@WD-WCC6Y 2KR5EH1, WD-WCC6Y 1LH74 NT, 50 02607 12B00 0456 | 否 | 2024-04-23 14:03:34.0 | E0-D5-5E-D8-32-6E@BF EBFBF F0009 06EB@WD-WCC6Y 2KR5EH1, WD-WCC6Y 1LH74 NT, 50 02607 12B00 0456 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:36:44 | E0-D5-5E-D8-32-6E@BF EBFBF F0009 06EB@WD-WCC6Y 2KR5EH1, WD-WCC6Y 1LH74 NT, 50 02607 12B00 0456 | 否  |   |  |
| 1248 | 福建省枫煊建设工程有限公司 | 2024-04-22 16:27:17.0 | A8-A1-59-23-82-DD@BF EBFBF F0009 06EB@W9AK9 P3P, 5 0026B 73806 B081B                           | 否 | 2024-04-22 15:16:31.0 | A8-A1-59-23-82-DD@BF EBFBF F0009 06EB@W9AK9 P3P, 5 0026B 73806 B081B                           | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:32:25  | A8-A1-59-23-82-DD@BF EBFBF F0009 06EB@W9AK9 P3P, 5 0026B 73806 B081B | 否 |  |



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|--|
| 1249 | 福建一成建设工程有限公司 | 2024-04-22 13:07:43.0 | D8-5E-D3-74-60-91, 52-2B-73-2C-02-60, 50-2B-73-2C-02-60, 50-2B-73-2C-02-60@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4126_ 4E65. | 否 | 2024-04-22 13:05:54.0 | D8-5E-D3-74-60-91, 52-2B-73-2C-02-60, 50-2B-73-2C-02-60, 50-2B-73-2C-02-60@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4126_ 4E65. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:35:06 | D8-5E-D3-74-60-91, 52-2B-73-2C-02-60, 50-2B-73-2C-02-60, 50-2B-73-2C-02-60@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4126_ 4E65. | 否 |  |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|--|



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1251 | 江西林皓装饰设计有限公司 | 2024-04-23 16:22:01.0 | F8-94-C2-BE-2C-11, FA-94-C2-BE-2C-10, F8-94-C2-BE-2C-10@BF EBFBF F0008 06EA@0025_38B8_71B9-C631. | 否 | 2024-04-23 16:20:16.0 | F8-94-C2-BE-2C-11, FA-94-C2-BE-2C-10, F8-94-C2-BE-2C-10@BF EBFBF F0008 06EA@0025_38B8_71B9-C631. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:23 | F8-94-C2-BE-2C-11, FA-94-C2-BE-2C-10, F8-94-C2-BE-2C-10@BF EBFBF F0008 06EA@0025_38B8_71B9-C631. | 否 |  |
| 1252 | 福建三桐建设有限公司   | 2024-04-23 09:46:26.0 | 18-C0-4D-CA-42-10@BF EBFBF F000A 0653@50026 B7382 1ED11 2, 202 20211 02959                       | 否 | 2024-04-23 09:16:18.0 | 18-C0-4D-CA-42-10@BF EBFBF F000A 0653@50026 B7382 1ED11 2, 202 20211 02959                       | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:51 | 18-C0-4D-CA-42-10@BF EBFBF F000A 0653@50026 B7382 1ED11 2, 202 20211 02959                       | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1253 | 泓天建设有限公司     | 2024-04-23 11:00:35.0 | 90-6F-18-02-39-39@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2016_<br>80F5.                          | 否 | 2024-04-23 10:59:21.0 | 90-6F-18-02-39-39@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2016_<br>80F5.  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:41:24 | 90-6F-18-02-39-39@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2016_<br>80F5. | 否 |  |
| 1254 | 福建峰正工程管理有限公司 | 2024-04-23 14:39:41.0 | 00-<br>E0-<br>67-<br>0B-<br>FA-<br>3F,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>FA-<br>3F@BF<br>EBFBF<br>F0005<br>06E3@<br>06262<br>220M0<br>021 | 否 | 2024-04-23 14:33:38.0 | 00-<br>E0-<br>67-<br>0B-<br>FA-<br>3F,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>06262<br>220M0<br>021 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:31:33 | 00-<br>E0-<br>67-<br>0B-<br>FA-<br>3F@BF<br>EBFBF<br>F0005<br>06E3@<br>06262<br>220M0<br>021                            | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1255 | 福建辰川建设发展有限公司 | 2024-04-23 09:44:05.0 | E0-D5-5E-D7-53-A5@BF EBFBF F0009 06EA@WD-WCC6Y HCX63 81, 50 026B7 3821E D102                      | 否 | 2024-04-23 09:42:13.0 | E0-D5-5E-D7-53-A5@BF EBFBF F0009 06EA@WD-WCC6Y HCX63 81, 50 026B7 3821E D102                      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:26 | E0-D5-5E-D7-53-A5@BF EBFBF F0009 06EA@WD-WCC6Y HCX63 81, 50 026B7 3821E D102                      | 否 |  |
| 1256 | 福建致远工程管理有限公司 | 2024-04-18 16:37:52.0 | 08-BF-B8-6F-F4-43@BF EBFBF F000A 0655@E823_8FA6_BF53_0001_001B_444A_485A_BA50., WD-WCC6Y 4TY5H 4C | 否 | 2024-04-18 16:33:40.0 | 08-BF-B8-6F-F4-43@BF EBFBF F000A 0655@E823_8FA6_BF53_0001_001B_444A_485A_BA50., WD-WCC6Y 4TY5H 4C | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:39 | 08-BF-B8-6F-F4-43@BF EBFBF F000A 0655@E823_8FA6_BF53_0001_001B_444A_485A_BA50., WD-WCC6Y 4TY5H 4C | 否 |  |



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1258 | 福建万旭市政工程有限公司 | 2024-04-22 17:24:15.0 | 00-<br>E0-<br>4C-<br>51-<br>FF-<br>C1, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>4AU2C<br>05 | 否 | 2024-04-22 17:22:07.0 | 00-<br>E0-<br>4C-<br>51-<br>FF-<br>C1, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>4AU2C<br>05 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:32 | 00-<br>E0-<br>4C-<br>51-<br>FF-<br>C1, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>4AU2C<br>05 | 否 |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|





|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 1260 | 福建鑫联众建设发展有限公司 | 2024-04-23 14:46:11.0 | 00-<br>CF-<br>E0-<br>52-<br>4E-<br>6D@BF<br>EBFBF<br>F0009<br>06EA@<br>9AA80<br>71208<br>16001<br>77831<br>,WD-<br>WCC6Y<br>5JJ7X<br>F1 | 否 | 2024-04-22 14:33:06.0 | 00-<br>CF-<br>E0-<br>52-<br>4E-<br>6D@BF<br>EBFBF<br>F0009<br>06EA@<br>9AA80<br>71208<br>16001<br>77831<br>,WD-<br>WCC6Y<br>5JJ7X<br>F1 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:18 | 00-<br>CF-<br>E0-<br>52-<br>4E-<br>6D@BF<br>EBFBF<br>F0009<br>06EA@<br>9AA80<br>71208<br>16001<br>77831<br>,WD-<br>WCC6Y<br>5JJ7X<br>F1 | 否   |   |  |
| 1261 | 福建坤筑建设有限公司    | 2024-04-23 11:39:51.0 | 04-<br>42-<br>1A-<br>AB-<br>03-<br>B3@BF<br>EBFBF<br>F000A<br>0653@<br>2013E<br>A4459<br>07   | 否 | 2024-04-23 11:36:08.0 | 04-<br>42-<br>1A-<br>AB-<br>03-<br>B3@BF<br>EBFBF<br>F000A<br>0653@<br>2013E<br>A4459<br>07   | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:32:03   | 04-<br>42-<br>1A-<br>AB-<br>03-<br>B3@BF<br>EBFBF<br>F000A<br>0653@<br>2013E<br>A4459<br>07 | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1262 | 福建宇航建设管理有限公司 | 2024-04-23 13:44:40.0 | 0C-9D-92-66-F6-8F@BF EBFBF F0009 06EA@ 30353 23042 36333 73138 34443 53644 38202 02020 , 2020 20205 7202d 44435 73643 33595 6505a 30545 5 | 否 | 2024-04-23 11:20:44.0 | 0C-9D-92-66-F6-8F@BF EBFBF F0009 06EA@ 30353 23042 36333 73138 34443 53644 38202 02020 , 2020 20205 7202d 44435 73643 33595 6505a 30545 5 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:32 | 0C-9D-92-66-F6-8F@BF EBFBF F0009 06EA@ 30353 23042 36333 73138 34443 53644 38202 02020 , 2020 20205 7202d 44435 73643 33595 6505a 30545 5 | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|



|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |   |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|--|---|--|
| 1264 | 福建省融悦腾建设工程有限公司 | 2024-04-23 10:40:17.0 | F0-2F-74-CC-14-26@BF<br>EBFBF<br>F0009<br>06EA@<br>SCRW2<br>00916<br>05G10<br>60, WD<br>-<br>WCC6Y<br>5DSN4<br>12                      | 否 | 2024-04-23 10:38:57.0 | F0-2F-74-CC-14-26, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>SCRW2<br>00916<br>05G10<br>60, WD<br>-<br>WCC6Y<br>5DSN4<br>12 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:25 | F0-2F-74-CC-14-26@BF<br>EBFBF<br>F0009<br>06EA@<br>SCRW2<br>00916<br>05G10<br>60, WD<br>-<br>WCC6Y<br>5DSN4<br>12 | 否  |   |  |
| 1265 | 湖南乐立保电力建设有限公司  | 2024-04-23 13:59:05.0 | 00-<br>E0-<br>4C-<br>3F-<br>43-<br>40@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCAYU<br>Y3789<br>28, 2H<br>T1007<br>90845<br>00006<br>E | 否 | 2024-04-23 13:57:25.0 | 00-<br>E0-<br>4C-<br>3F-<br>43-<br>40@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCAYU<br>Y3789<br>28, 2H<br>T1007<br>90845<br>00006<br>E   | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:51:09   | 00-<br>E0-<br>4C-<br>3F-<br>43-<br>40@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCAYU<br>Y3789<br>28, 2H<br>T1007<br>90845<br>00006<br>E | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1266 | 福建择熠建设有限公司   | 2024-04-17 16:45:40.0 | E8-9C-25-40-F4-F2@BFEBFBFF00090675@0000_0000_0000_0000_0026_B738_2451_2CB5. | 否 | 2024-04-17 16:44:46.0 | E8-9C-25-40-F4-F2@BFEBFBFF00090675@0000_0000_0000_0000_0026_B738_2451_2CB5. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:07 | E8-9C-25-40-F4-F2@BFEBFBFF00090675@0000_0000_0000_0000_0026_B738_2451_2CB5. | 否 |  |
| 1267 | 福建毕重建设工程有限公司 | 2024-04-23 10:14:47.0 | E0-D5-5E-C3-CB-B4@BFEBFBFF000906EB@K190405J05527                            | 否 | 2024-04-23 10:07:56.0 | E0-D5-5E-C3-CB-B4@BFEBFBFF000906EB@K190405J05527                            | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:29 | E0-D5-5E-C3-CB-B4@BFEBFBFF000906EB@K190405J05527                            | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|
| 1268 | 福建欣万建设工程有限公司 | 2024-04-23 15:38:01.0 | 00-<br>CF-<br>E0-<br>5A-<br>D5-<br>00,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36333<br>73038<br>43433<br>04642<br>30202<br>02020 | 否 | 2024-04-23 15:29:21.0 | 00-<br>CF-<br>E0-<br>5A-<br>D5-<br>00,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36333<br>73038<br>43433<br>04642<br>30202<br>02020 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:41:39 | 00-<br>CF-<br>E0-<br>5A-<br>D5-<br>00,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36333<br>73038<br>43433<br>04642<br>30202<br>02020 | 否 |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|



|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1270 | 福建中崛建设有限责任公司  | 2024-04-23 11:52:32.0 | 18-C0-4D-53-66-78@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>AB178<br>A, WD-<br>WCC6Y<br>7HUXT<br>7J | 否 | 2024-04-23 11:50:14.0 | 18-C0-4D-53-66-78@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>AB178<br>A, WD-<br>WCC6Y<br>7HUXT<br>7J | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:12 | 18-C0-4D-53-66-78@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>AB178<br>A, WD-<br>WCC6Y<br>7HUXT<br>7J | 否 |  |
| 1271 | 福建省福山建筑工程有限公司 | 2024-04-23 17:51:54.0 | A8-5E-45-A2-8D-73@BF<br>EBFBF<br>F0009<br>06EA@<br>TA203<br>28259<br>40096<br>_0000<br>0001.                 | 否 | 2024-04-23 17:50:09.0 | A8-5E-45-A2-8D-73@BF<br>EBFBF<br>F0009<br>06EA@<br>TA203<br>28259<br>40096<br>_0000<br>0001.                 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:11 | A8-5E-45-A2-8D-73@BF<br>EBFBF<br>F0009<br>06EA@<br>TA203<br>28259<br>40096<br>_0000<br>0001.                 | 否 |  |



|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |  |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|--|---|--|
| 1272 | 福建瓴安建设工程有限公司   | 2024-04-23 14:52:40.0 | 18-31-BF-70-8E-BF@BF EBFBF F0005 06E3@5290R 21390 3322, 23021 93000 80, WD - WCC6Y 5RUEJ YN | 否 | 2024-04-23 14:47:19.0 | 18-31-BF-70-8E-BF@BF EBFBF F0005 06E3@5290R 21390 3322, 23021 93000 80, WD - WCC6Y 5RUEJ YN | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:22 | 18-31-BF-70-8E-BF@BF EBFBF F0005 06E3@5290R 21390 3322, WD-WCC6Y 5RUEJ YN | 否  |   |  |
| 1273 | 中闽远昇(福建)建设有限公司 | 2024-04-22 14:51:24.0 | 24-4B-FE-79-EB-77@BF EBFBF F0009 06EB@2036E G4659 10, WX J2A43 334A1                        | 否 | 2024-04-22 14:50:36.0 | 24-4B-FE-79-EB-77@BF EBFBF F0009 06EB@2036E G4659 10, WX J2A43 334A1                        | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:34:07   | 24-4B-FE-79-EB-77@BF EBFBF F0009 06EB@2036E G4659 10, WX J2A43 334A1 | 否 |  |
| 1274 | 贺丰建设集团有限公司     | 2024-04-22 10:29:37.0 | 00-E0-5E-01-29-A2@BF EBFBF F0003 06F2@MG240 14061 2945                                      | 否 | 2024-04-22 10:00:27.0 | 00-E0-5E-01-29-A2@BF EBFBF F0003 06F2@MG240 14061 2945                                      | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:36:20   | 00-E0-5E-01-29-A2@BF EBFBF F0003 06F2@MG240 14061 2945               | 否 |  |

|      |                   |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|------|-------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
| 1275 | 福建省建成<br>建设工程有限公司 | 2024-<br>04-23<br>09:08<br>:28.0 | 08-<br>BF-<br>B8-<br>31-<br>08-<br>A8@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>23C3_<br>C135.   | 否 | 2024-<br>04-23<br>09:07<br>:13.0 | 08-<br>BF-<br>B8-<br>31-<br>08-<br>A8@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>23C3_<br>C135.   | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:35<br>:40 | 08-<br>BF-<br>B8-<br>31-<br>08-<br>A8@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>23C3_<br>C135.   | 否 |  |
| 1276 | 福建省鑫多<br>利建设有限公司  | 2024-<br>04-23<br>11:44<br>:44.0 | 74-<br>56-<br>3C-<br>7D-<br>1E-<br>41,00<br>-5C-<br>C2-<br>C7-<br>FA-<br>80,90<br>-76-<br>9F-<br>8F-<br>13-<br>73@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7382<br>3EBBD<br>2,000<br>00000<br>00000 | 否 | 2024-<br>04-23<br>11:40<br>:34.0 | 74-<br>56-<br>3C-<br>7D-<br>1E-<br>41,00<br>-5C-<br>C2-<br>C7-<br>FA-<br>80,90<br>-76-<br>9F-<br>8F-<br>13-<br>73@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7382<br>3EBBD<br>2,000<br>00000<br>00000 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:36<br>:47 | 74-<br>56-<br>3C-<br>7D-<br>1E-<br>41,00<br>-5C-<br>C2-<br>C7-<br>FA-<br>80,90<br>-76-<br>9F-<br>8F-<br>13-<br>73@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7382<br>3EBBD<br>2,000<br>00000<br>00000 | 否 |  |





|  |  |  |   |  |  |   |  |  |  |  |  |  |  |  |  |  |  |   |  |  |
|--|--|--|---|--|--|---|--|--|--|--|--|--|--|--|--|--|--|---|--|--|
|  |  |  | PSF41<br>42010<br>0291<br>_0000<br>0001.<br>, I460<br>01B00<br>0754 |  |  | PSF41<br>42010<br>0291<br>_0000<br>0001.<br>, I460<br>01B00<br>0754 |  |  |  |  |  |  |  |  |  |  |  | PSF41<br>42010<br>0291<br>_0000<br>0001.<br>, I460<br>01B00<br>0754 |  |  |
|--|--|--|---|--|--|---|--|--|--|--|--|--|--|--|--|--|--|---|--|--|



|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1283 | 福建隆廷鑫建设有限公司   | 2024-04-23 16:33:51.0 | 2C-F0-5D-A0-D1-05@BF EBFBF F000A 0653@ MG230 74075 7329, 20201 01501 710                                 | 否 | 2024-04-23 09:41:32.0 | 2C-F0-5D-A0-D1-05@BF EBFBF F000A 0653@ MG230 74075 7329, 20201 01501 710                                 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:17 | 2C-F0-5D-A0-D1-05@BF EBFBF F000A 0653@ MG230 74075 7329, 20201 01501 710                                 | 否 |  |
| 1284 | 山东金正阳建筑工程有限公司 | 2024-04-23 17:14:32.0 | D8-5E-D3-C3-3B-EC@BF EBFBF F000A 0653@ CM48B BH200 2970, 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 21F4_ 1915. | 否 | 2024-04-23 09:41:49.0 | D8-5E-D3-C3-3B-EC@BF EBFBF F000A 0653@ CM48B BH200 2970, 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 21F4_ 1915. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:25 | D8-5E-D3-C3-3B-EC@BF EBFBF F000A 0653@ CM48B BH200 2970, 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 21F4_ 1915. | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 1285 | 福建捷雄建筑工程有限公司 | 2024-04-22 16:23:05.0 | 00-<br>E0-<br>4C-<br>0B-<br>80-<br>3E@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC3F<br>4XHL2<br>KK, EA<br>GET20<br>22011<br>8R018<br>41  | 否 | 2024-04-22 16:21:54.0 | 00-<br>E0-<br>4C-<br>0B-<br>80-<br>3E@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC3F<br>4XHL2<br>KK, EA<br>GET20<br>22011<br>8R018<br>41  | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:47:04   | 00-<br>E0-<br>4C-<br>0B-<br>80-<br>3E@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC3F<br>4XHL2<br>KK, EA<br>GET20<br>22011<br>8R018<br>41 | 否 |  |
| 1286 | 福建龙岩融冠建设有限公司 | 2024-04-19 11:55:44.0 | 2C-<br>F0-<br>5D-<br>1F-<br>C0-<br>0A, 00<br>-00-<br>00-<br>00-<br>00-<br>1F-<br>C0-<br>0A@BF<br>EBFBF<br>F0009<br>06EB@<br>SSMB2<br>02270<br>9420,<br>WD-<br>WCC6Y<br>OXJEX<br>R2 | 否 | 2024-04-19 11:43:53.0 | 2C-<br>F0-<br>5D-<br>1F-<br>C0-<br>0A, 00<br>-00-<br>00-<br>00-<br>00-<br>1F-<br>C0-<br>0A, 00<br>-00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>SSMB2<br>02270<br>9420,<br>WD-<br>WCC6Y<br>OXJEX<br>R2 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:49 | 2C-<br>F0-<br>5D-<br>1F-<br>C0-<br>0A@BF<br>EBFBF<br>F0009<br>06EB@<br>SSMB2<br>02270<br>9420,<br>WD-<br>WCC6Y<br>OXJEX<br>R2 | 否   |   |  |



|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1287 | 福建省天轩建设发展有限公司 | 2024-04-22 16:24:35.0 | A8-5E-45-6D-CD-FF@BF EBFBF F0009 06EA@Z9CBF Q39, 5 0026B 74350 0019B                        | 否 | 2024-04-22 16:21:51.0 | A8-5E-45-6D-CD-FF@BF EBFBF F0009 06EA@Z9CBF Q39, 5 0026B 74350 0019B                        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:43:47 | A8-5E-45-6D-CD-FF@BF EBFBF F0009 06EA@Z9CBF Q39, 5 0026B 74350 0019B                        | 否 |  |
| 1288 | 中坤龙达市政工程有限公司  | 2024-04-23 09:42:14.0 | 84-5C-F3-7A-62-5A, 70-B5-E8-52-DC-1E@BF EBFBF F000A 0653@AA000 00000 00000 06483, ZN1M 84F7 | 否 | 2024-04-23 09:39:27.0 | 84-5C-F3-7A-62-5A, 70-B5-E8-52-DC-1E@BF EBFBF F000A 0653@AA000 00000 00000 06483, ZN1M 84F7 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:41 | 84-5C-F3-7A-62-5A, 70-B5-E8-52-DC-1E@BF EBFBF F000A 0653@AA000 00000 00000 06483, ZN1M 84F7 | 否 |  |







|      |                       |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                              |                            |  |   |  |
|------|-----------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------------|----------------------------|--|---|--|
| 1293 | 福建中诺信<br>建筑工程有限公司     | 2024-04-23<br>17:44<br>:50.0 | 18-<br>C0-<br>4D-<br>CB-<br>AF-<br>83@BF<br>EBFBF<br>F000A<br>0653@<br>19359<br>C8043<br>14, WD<br>-<br>WX92A<br>51N87<br>HT             | 否 | 2024-04-23<br>17:39<br>:08.0 | 18-<br>C0-<br>4D-<br>CB-<br>AF-<br>83@BF<br>EBFBF<br>F000A<br>0653@<br>19359<br>C8043<br>14, WD<br>-<br>WX92A<br>51N87<br>HT             | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:36<br>:34 | 18-<br>C0-<br>4D-<br>CB-<br>AF-<br>83@BF<br>EBFBF<br>F000A<br>0653@<br>19359<br>C8043<br>14, WD<br>-<br>WX92A<br>51N87<br>HT             | 否 |  |
| 1294 | 福建顺宇建<br>筑工程有限<br>公司  | 2024-04-19<br>11:23<br>:33.0 | C4-<br>17-<br>OE-<br>FB-<br>07-<br>E1@BF<br>EBFBF<br>F000A<br>0653@<br>6479_<br>A766_<br>1090_<br>20D4.<br>, ZN1R<br>30JV                | 否 | 2024-04-19<br>11:06<br>:55.0 | C4-<br>17-<br>OE-<br>FB-<br>07-<br>E1@BF<br>EBFBF<br>F000A<br>0653@<br>6479_<br>A766_<br>1090_<br>20D4.<br>, ZN1R<br>30JV                | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:50<br>:12 | C4-<br>17-<br>OE-<br>FB-<br>07-<br>E1@BF<br>EBFBF<br>F000A<br>0653@<br>6479_<br>A766_<br>1090_<br>20D4.<br>, ZN1R<br>30JV                | 否 |  |
| 1295 | 福建省旭凯<br>建设工程有<br>限公司 | 2024-04-19<br>19:51<br>:25.0 | F4-<br>B5-<br>20-<br>14-<br>BA-<br>52@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC4J<br>3ATP7<br>4V, MX<br>_3237<br>C1E00<br>00000<br>002 | 否 | 2024-04-19<br>19:50<br>:09.0 | F4-<br>B5-<br>20-<br>14-<br>BA-<br>52@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC4J<br>3ATP7<br>4V, MX<br>_3237<br>C1E00<br>00000<br>002 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:33<br>:10 | F4-<br>B5-<br>20-<br>14-<br>BA-<br>52@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC4J<br>3ATP7<br>4V, MX<br>_3237<br>C1E00<br>00000<br>002 | 否 |  |

|      |             |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|-------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1296 | 福建中闽昇建设有限公司 | 2024-04-23 17:17:39.0 | 04-42-1A-23-62-97@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7684<br>B919C<br>E, WD-<br>WCC6Y<br>3JV8K<br>9V | 否 | 2024-04-23 17:07:45.0 | 04-42-1A-23-62-97@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7684<br>B919C<br>E, WD-<br>WCC6Y<br>3JV8K<br>9V | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:40 | 04-42-1A-23-62-97@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7684<br>B919C<br>E, WD-<br>WCC6Y<br>3JV8K<br>9V | 否 |  |
| 1297 | 豫兴建筑工程有限公司  | 2024-04-23 13:06:00.0 | 00-E0-4C-73-56-7D@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WX34P<br>3KN34<br>20, 22<br>07VA0<br>01CBU<br>2023 | 否 | 2024-04-18 10:02:51.0 | 00-E0-4C-73-56-7D@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WX34P<br>3KN34<br>20, 22<br>07VA0<br>01CBU<br>2023 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:53 | 00-E0-4C-73-56-7D@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WX34P<br>3KN34<br>20, 22<br>07VA0<br>01CBU<br>2023 | 否 |  |

|      |                   |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |                            |                            |   |   |  |
|------|-------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|---|--|
| 1298 | 福建省驰宝<br>建筑工程有限公司 | 2024-04-22<br>10:38<br>:27.0 | 00-<br>E0-<br>70-<br>81-<br>05-<br>A5,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7382<br>38408<br>B,WCC<br>1S480<br>6017 | 否 | 2024-04-22<br>10:27<br>:49.0 | 00-<br>E0-<br>70-<br>81-<br>05-<br>A5,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7382<br>38408<br>B,WCC<br>1S480<br>6017 | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:34<br>:39 | 00-<br>E0-<br>70-<br>81-<br>05-<br>A5,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7382<br>38408<br>B,WCC<br>1S480<br>6017 | 否 |  |
| 1299 | 江西省同欣<br>建设工程有限公司 | 2024-04-23<br>15:16<br>:22.0 | 00-<br>CF-<br>BD-<br>69-<br>9A-<br>8B@BF<br>EBFBF<br>F0005<br>06E3@<br>AA000<br>00000<br>00000<br>09006<br>，WD-<br>WCC6Y<br>5AL13<br>67                                      | 否 | 2024-04-23<br>15:15<br>:08.0 | 00-<br>CF-<br>BD-<br>69-<br>9A-<br>8B@BF<br>EBFBF<br>F0005<br>06E3@<br>AA000<br>00000<br>00000<br>09006<br>，WD-<br>WCC6Y<br>5AL13<br>67                                      | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:33<br>:09 | 00-<br>CF-<br>BD-<br>69-<br>9A-<br>8B@BF<br>EBFBF<br>F0005<br>06E3@<br>AA000<br>00000<br>00000<br>09006<br>，WD-<br>WCC6Y<br>5AL13<br>67   | 否 |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1300 | 福建宏昇源建设发展有限公司 | 2024-04-23 14:50:18.0 | E0-D5-5E-52-5D-91@BF EBFBF F0009 06E9@30014 34967 2,341 A1A76                       | 否 | 2024-04-21 17:30:09.0 | E0-D5-5E-52-5D-91@BF EBFBF F0009 06E9@30014 34967 2                                 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:42:15 | E0-D5-5E-52-5D-91@BF EBFBF F0009 06E9@30014 34967 2                         | 否 |  |
| 1301 | 中狮华高建设有限公司    | 2024-04-23 14:34:30.0 | 48-F3-17-02-8B-88@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0026_B778_4E0A_9D85. | 否 | 2024-04-23 13:27:27.0 | 48-F3-17-02-8B-88@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0026_B778_4E0A_9D85. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:10 | A8-5E-45-61-02-1A@BF EBFBF F0009 06EA@50026 B7282 300FD 2,WD-WCC6Y OUZKH HO | 否 |  |
| 1302 | 福建衡兴建工有限公司    | 2024-04-18 11:21:41.0 | 08-BF-B8-86-19-55@BF EBFBF F000A 0653@WD-WCC4J 1YK76 OR, RW 18C14 012B5 480         | 否 | 2024-04-18 11:17:02.0 | 08-BF-B8-86-19-55@BF EBFBF F000A 0653@WD-WCC4J 1YK76 OR, RW 18C14 012B5 480         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:39 | 08-BF-B8-86-19-55@BF EBFBF F000A 0653@WD-WCC4J 1YK76 OR, RW 18C14 012B5 480 | 否 |  |





|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1305 | 福建点尚建设发展有限公司  | 2024-04-19 16:35:16.0 | 58-11-22-C0-6E-02@BFEBFBFF00090672@E823_8FA6_BF53_0001_001B_444A_49DF_C23B. | 否 | 2024-04-19 16:34:07.0 | 58-11-22-C0-6E-02@BFEBFBFF00090672@E823_8FA6_BF53_0001_001B_444A_49DF_C23B. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:39:02 | 58-11-22-C0-6E-02@BFEBFBFF00090672@E823_8FA6_BF53_0001_001B_444A_49DF_C23B. | 否 |  |
| 1306 | 福建众悦鑫建设工程有限公司 | 2024-04-23 09:52:58.0 | E8-9C-25-C3-07-2E@BFEBFBFF00090675@E823_8FA6_BF53_0001_001B_444A_485D_7D91. | 否 | 2024-04-23 09:48:50.0 | E8-9C-25-C3-07-2E@BFEBFBFF00090675@E823_8FA6_BF53_0001_001B_444A_485D_7D91. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:38:53 | E8-9C-25-C3-07-2E@BFEBFBFF00090675@E823_8FA6_BF53_0001_001B_444A_485D_7D91. | 否 |  |



















|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|--|
| 1318 | 福建鑫亿鑫建设发展有限公司 | 2024-04-24 08:13:10.0 | E0-D5-5E-33-80-28,00-00-00-00-00-00-00@BFEBFBF000906E9@4454313232323038394134433739203620202020,2020202057202d444357334334464a5458304658 | 否 | 2024-04-24 08:11:44.0 | E0-D5-5E-33-80-28,00-00-00-00-00-00-00@BFEBFBF000906E9@4454313232323038394134433739203620202020,2020202057202d444357334334464a5458304658 | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:35:40 | E0-D5-5E-33-80-28,00-00-00-00-00-00-00@BFEBFBF000906E9@4454313232323038394134433739203620202020,2020202057202d444357334334464a5458304658 | 否 |  |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|--|



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1320 | 福建中诺建设工程有限公司 | 2024-04-22 19:12:13.0 | 4C-77-66-69-6D-EB, 90-6F-18-03-94-87, 4C-77-66-69-6D-EB@BF EBFBF F0009 0675@ 2C3E_ BFFF_ F000_ 9CE2.          | 否 | 2024-04-22 16:57:58.0 | 4C-77-66-69-6D-EB, 90-6F-18-03-94-87, 4C-77-66-69-6D-EB@BF EBFBF F0009 0675@ 2C3E_ BFFF_ F000_ 9CE2.          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:44:51 | 4C-77-66-69-6D-EB, 90-6F-18-03-94-87, 4C-77-66-69-6D-EB@BF EBFBF F0009 0675@ 2C3E_ BFFF_ F000_ 9CE2.          | 否 |  |
| 1321 | 福建三拓建设有限公司   | 2024-04-23 15:47:19.0 | B4-2E-99-D4-16-60, 00-00-00-00-00-00-00-00-00-00-EO@BF EBFBF F0009 06EA@ 20200 10401 193, W D- WCC6Y OXJE2 CK | 否 | 2024-04-23 15:46:01.0 | B4-2E-99-D4-16-60, 00-00-00-00-00-00-00-00-00-00-EO@BF EBFBF F0009 06EA@ 20200 10401 193, W D- WCC6Y OXJE2 CK | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:36:13 | B4-2E-99-D4-16-60, 00-00-00-00-00-00-00-00-00-00-EO@BF EBFBF F0009 06EA@ 20200 10401 193, W D- WCC6Y OXJE2 CK | 否 |  |











|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1330 | 福建锦港建设工程有限公司 | 2024-04-23 09:08:40.0 | D8-5E-D3-6C-09-74@BF<br>EBFBF<br>F000A<br>0653@<br>91SB1<br>ORFS,<br>0025_<br>38D3_<br>2181_<br>OACA. | 否 | 2024-04-23 08:59:52.0 | D8-5E-D3-6C-09-74@BF<br>EBFBF<br>F000A<br>0653@<br>91SB1<br>ORFS,<br>0025_<br>38D3_<br>2181_<br>OACA. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:20 | D8-5E-D3-6C-09-74@BF<br>EBFBF<br>F000A<br>0653@<br>91SB1<br>ORFS,<br>0025_<br>38D3_<br>2181_<br>OACA. | 否 |  |
| 1331 | 福建中建投资有限公司   | 2024-04-23 09:57:19.0 | 18-C0-4D-54-2B-01@BF<br>EBFBF<br>F0009<br>06ED@<br>WCC6Y<br>2PFF2<br>D5, 20<br>1023A<br>00005<br>175  | 否 | 2024-04-22 15:05:16.0 | 18-C0-4D-54-2B-01@BF<br>EBFBF<br>F0009<br>06ED@<br>WCC6Y<br>2PFF2<br>D5, 20<br>1023A<br>00005<br>175  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:47 | 18-C0-4D-54-2B-01@BF<br>EBFBF<br>F0009<br>06ED@<br>WCC6Y<br>2PFF2<br>D5, 20<br>1023A<br>00005<br>175  | 否 |  |
| 1332 | 福建金基建建设有限公司  | 2024-04-22 11:38:51.0 | B4-2E-99-85-CB-79@BF<br>EBFBF<br>F0009<br>06EB@<br>TC21A<br>280D8<br>A0010                            | 否 | 2024-04-22 11:21:49.0 | B4-2E-99-85-CB-79@BF<br>EBFBF<br>F0009<br>06EB@<br>TC21A<br>280D8<br>A0010                            | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:45:03 | B4-2E-99-85-CB-79@BF<br>EBFBF<br>F0009<br>06EB@<br>TC21A<br>280D8<br>A0010                            | 否 |  |



|      |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|------|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
| 1335 | 福建省联庆<br>工程建设有<br>限公司 | 2024-<br>04-19<br>12:10<br>:46.0 | 00-<br>E2-<br>69-<br>60-<br>86-<br>40@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>5F6A_<br>AC95.<br>,ZGY6<br>DS61                | 否 | 2024-<br>04-19<br>11:15<br>:48.0 | 00-<br>E2-<br>69-<br>60-<br>86-<br>40@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>5F6A_<br>AC95.<br>,ZGY6<br>DS61                | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:32<br>:03 | 00-<br>E2-<br>69-<br>60-<br>86-<br>40@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>5F6A_<br>AC95.<br>,ZGY6<br>DS61                | 否 |  |
| 1336 | 南平峻宇建<br>设工程有限<br>公司  | 2024-<br>04-22<br>16:51<br>:12.0 | 10-<br>7C-<br>61-<br>72-<br>B2-<br>BA@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C12_<br>5FB9_<br>5356.<br>,WD-<br>WX72D<br>63HA2<br>4P | 否 | 2024-<br>04-19<br>15:28<br>:33.0 | 10-<br>7C-<br>61-<br>72-<br>B2-<br>BA@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C12_<br>5FB9_<br>5356.<br>,WD-<br>WX72D<br>63HA2<br>4P | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:36<br>:10 | 10-<br>7C-<br>61-<br>72-<br>B2-<br>BA@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C12_<br>5FB9_<br>5356.<br>,WD-<br>WX72D<br>63HA2<br>4P | 否 |  |

|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1337 | 福建九州众泰建筑工程有限公司 | 2024-04-22 15:41:31.0 | 18-C0-4D-84-6C-EE@BF EBFBF F000A 0653@ 50026 B7783 BA17F D, W4Y 4W015  | 否 | 2024-04-22 15:40:29.0 | 18-C0-4D-84-6C-EE@BF EBFBF F000A 0653@ 50026 B7783 BA17F D, W4Y 4W015  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:03 | 18-C0-4D-84-6C-EE@BF EBFBF F000A 0653@ 50026 B7783 BA17F D, W4Y 4W015  | 否 |  |
| 1338 | 福建省宇翔建设工程有限公司  | 2024-04-23 11:13:34.0 | 08-BF-B8-2B-2F-5C@BF EBFBF F0009 0675@ WD-WCC3F 7RYDR ZV, 50 026B7 38204 B5E1, 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 2069_ 9175. | 否 | 2024-04-23 11:08:24.0 | 08-BF-B8-2B-2F-5C@BF EBFBF F0009 0675@ WD-WCC3F 7RYDR ZV, 50 026B7 38204 B5E1, 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 2069_ 9175. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:08 | 08-BF-B8-2B-2F-5C@BF EBFBF F0009 0675@ WD-WCC3F 7RYDR ZV, 50 026B7 38204 B5E1, 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 2069_ 9175. | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1339 | 林汇建设有限公司     | 2024-04-23 10:01:04.0 | 48-F3-17-11-3F-F6@BF EBFBF F000A 0653@ KL237 140B3 I4336  | 否 | 2024-04-23 09:59:23.0 | 48-F3-17-11-3F-F6@BF EBFBF F000A 0653@ KL237 140B3 I4336  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:39 | 48-F3-17-11-3F-F6@BF EBFBF F000A 0653@ KL237 140B3 I4336  | 否 |  |
| 1340 | 福建汀顺建筑工程有限公司 | 2024-04-22 16:56:09.0 | 08-BF-B8-40-C7-1D@BF EBFBF F0009 0675@ E823 8FA6 BF53 0001 001B 448B 4E3B E240. , WD-WCC6Y 8AZWA J2 | 否 | 2024-04-22 16:53:53.0 | 08-BF-B8-40-C7-1D@BF EBFBF F0009 0675@ E823 8FA6 BF53 0001 001B 448B 4E3B E240. , WD-WCC6Y 8AZWA J2 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:39 | 08-BF-B8-40-C7-1D@BF EBFBF F0009 0675@ E823 8FA6 BF53 0001 001B 448B 4E3B E240. , WD-WCC6Y 8AZWA J2 | 否 |  |
| 1341 | 福建上洋建设有限公司   | 2024-04-23 15:31:55.0 | 00-25-F2-69-BD-6F@BF EBFBF F0009 06EB@ 334a3 03932 39453 23631 30382 03320                          | 否 | 2024-04-17 16:33:50.0 | 00-25-F2-69-BD-6F, 00 -00-00-00-00-00-EO@BF EBFBF F0009   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:49 | 00-25-F2-69-BD-6F@BF EBFBF F0009 06EB@ 334a3 03932 39453 23631 30382 03320                          | 否 |  |

|      |                       |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |  |                         |                                |  |   |  |
|------|-----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|--|---|--|
|      |                       |                                  | 20202<br>02020   |   |                                  | 06EB@<br>334a3<br>03932<br>39453<br>23631<br>30382<br>03320<br>20202<br>02020  |   |  |  |  |  |  |  |  |  |  |  |  | 20202<br>02020          |                                |  |   |  |
| 1342 | 福建省中天<br>元利建设有<br>限公司 | 2024-<br>04-23<br>16:39<br>:23.0 | 04-<br>D9-<br>F5-<br>F4-<br>57-<br>38@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>5ED58<br>8, WD-<br>WCC6Y<br>3XY8X<br>FP | 否 | 2024-<br>04-23<br>16:37<br>:55.0 | 04-<br>D9-<br>F5-<br>F4-<br>57-<br>38@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>5ED58<br>8, WD-<br>WCC6Y<br>3XY8X<br>FP | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:35<br>:40 | 04-<br>D9-<br>F5-<br>F4-<br>57-<br>38@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>5ED58<br>8, WD-<br>WCC6Y<br>3XY8X<br>FP | 否 |  |









|      |                        |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
|------|------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|
| 1347 | 阿拉善盟云<br>峰道桥有限<br>责任公司 | 2024-<br>04-23<br>16:20<br>:26.0 | 04-<br>D9-<br>C8-<br>BB-<br>CF-<br>69@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4CEE_<br>4480.  | 否 | 2024-<br>04-23<br>16:18<br>:29.0 | 04-<br>D9-<br>C8-<br>BB-<br>CF-<br>69@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4CEE_<br>4480.  | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:33<br>:54 | 04-<br>D9-<br>C8-<br>BB-<br>CF-<br>69@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4CEE_<br>4480.  | 否 |  |
| 1348 | 丽水乾润建<br>设有限公司         | 2024-<br>04-23<br>21:45<br>:15.0 | 74-<br>56-<br>3C-<br>E5-<br>43-<br>72@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2592_<br>3EA5.<br>,0302<br>17040<br>21621<br>16125<br>4 | 否 | 2024-<br>04-23<br>11:40<br>:22.0 | 74-<br>56-<br>3C-<br>E5-<br>43-<br>72@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2592_<br>3EA5.<br>,0302<br>17040<br>21621<br>16125<br>4 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:39<br>:33 | 74-<br>56-<br>3C-<br>E5-<br>43-<br>72@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2592_<br>3EA5.<br>,0302<br>17040<br>21621<br>16125<br>4 | 否 |  |

|      |                        |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                            |                                |   |  |   |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|--|---|--|
| 1349 | 福建中闽首<br>艺建设发展<br>有限公司 | 2024-<br>04-23<br>15:41<br>:18.0 | D8-<br>5E-<br>D3-<br>D2-<br>BC-<br>A5@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4RK08<br>X2,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 | 2024-<br>04-23<br>15:37<br>:24.0 | D8-<br>5E-<br>D3-<br>D2-<br>BC-<br>A5@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4RK08<br>X2,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:34<br>:07 | D8-<br>5E-<br>D3-<br>D2-<br>BC-<br>A5@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4RK08<br>X2,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否  |   |  |
| 1350 | 福建省北禹<br>建设工程有<br>限公司  | 2024-<br>04-22<br>08:19<br>:19.0 | 7C-<br>10-<br>C9-<br>9E-<br>8B-<br>89@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OVJNY<br>HH  | 否 | 2024-<br>04-22<br>08:15<br>:35.0 | 7C-<br>10-<br>C9-<br>9E-<br>8B-<br>89@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OVJNY<br>HH  | 否 |  |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>，请<br>检查     | 2024-<br>04-24<br>08:32<br>:03  | 7C-<br>10-<br>C9-<br>9E-<br>8B-<br>89@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>OVJNY<br>HH | 否 |  |





|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|---|--|
| 1355 | 福建路通工程管理有限公司 | 2024-04-22 15:17:54.0 | 0A-E0-AF-F8-01-18@BF<br>EBFBF<br>F0003<br>06C3@<br>WD-<br>WCC6Y<br>OUZEO<br>FJ, AA<br>00000<br>00000<br>00012<br>679 | 否 | 2024-04-22 11:36:53.0 | 0A-E0-AF-F8-01-18@BF<br>EBFBF<br>F0003<br>06C3@<br>WD-<br>WCC6Y<br>OUZEO<br>FJ, AA<br>00000<br>00000<br>00012<br>679 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:38 | 0A-E0-AF-F8-01-18@BF<br>EBFBF<br>F0003<br>06C3@<br>WD-<br>WCC6Y<br>OUZEO<br>FJ, AA<br>00000<br>00000<br>00012<br>679 | 否   |   |  |
| 1356 | 福建升巨满建设有限公司  | 2024-04-23 15:25:40.0 | 00-E0-0B-32-62-0B@BF<br>EBFBF<br>F0003<br>06E4@<br>YS202<br>10727<br>44773<br>5                                      | 否 | 2024-04-23 15:09:14.0 | 00-E0-0B-32-62-0B@BF<br>EBFBF<br>F0003<br>06E4@<br>YS202<br>10727<br>44773<br>5                                      | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:32:07  | 00-E0-0B-32-62-0B@BF<br>EBFBF<br>F0003<br>06E4@<br>YS202<br>10727<br>44773<br>5                                     | 否 |  |
| 1357 | 河南兰秉建筑工程有限公司 | 2024-04-23 10:59:43.0 | E8-9C-25-40-E3-7E@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4A6B_<br>8EBE.  | 否 | 2024-04-23 10:55:12.0 | E8-9C-25-40-E3-7E@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4A6B_<br>8EBE.  | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:33:25  | E8-9C-25-40-E3-7E@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4A6B_<br>8EBE. | 否 |  |





|      |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1359 | 福建乐达建筑工程有限公司 | 2024-04-23 09:41:33.0 | 08-BF-B8-BC-AC-DC@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_444A_48E8_18E7.   | 否 | 2024-04-23 09:40:04.0 | 08-BF-B8-BC-AC-DC@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_444A_48E8_18E7.  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:19 | 08-BF-B8-BC-AC-DC@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_444A_48E8_18E7.  | 否 |  |
| 1360 | 福建泰焯建设有限公司   | 2024-04-17 11:10:54.0 | F8-E4-3B-78-F1-89, 34-6F-24-89-1E-5D, 36-6F-24-89-1E-5D, 36-6F-24-89-1E-5D, B6-6F-24-89-1E-5D@BF<br>EBFBF<br>F0008<br>06C1@<br>0000_0000_0100_0000_ E4D2_5C19_9813_5501. | 否 | 2024-04-17 11:08:35.0 | 34-6F-24-89-1E-5D, 36-6F-24-89-1E-5D, B6-6F-24-89-1E-5D, F8-E4-3B-78-F1-89@BF<br>EBFBF<br>F0008<br>06C1@<br>0000_0000_0100_0000_ E4D2_5C19_9813_5501. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:41:02 | F8-E4-3B-78-F1-89, 34-6F-24-89-1E-5D, 36-6F-24-89-1E-5D, B6-6F-24-89-1E-5D@BF<br>EBFBF<br>F0008<br>06C1@<br>0000_0000_0100_0000_ E4D2_5C19_9813_5501. | 否 |  |

|      |                       |                                  |   |   |                                  |  |   |  |  |  |  |  |  |  |  |                            |                                |   |   |   |  |
|------|-----------------------|----------------------------------|---|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|---|--|
| 1361 | 福建省金玖<br>建筑工程有<br>限公司 | 2024-<br>04-23<br>11:56<br>:48.0 | D8-<br>43-<br>AE-<br>15-<br>44-<br>C9@17<br>8BFBF<br>F00A5<br>0F00@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E78_<br>85B3. | 否 | 2024-<br>04-23<br>11:55<br>:25.0 | D8-<br>43-<br>AE-<br>15-<br>44-<br>C9@17<br>8BFBF<br>F00A5<br>0F00@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E78_<br>85B3.  | 否 |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>，请<br>检查     | 2024-<br>04-24<br>08:35<br>:40  | D8-<br>43-<br>AE-<br>15-<br>44-<br>C9@17<br>8BFBF<br>F00A5<br>0F00@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E78_<br>85B3. | 否 |  |
| 1362 | 福建省临垚<br>建设工程有<br>限公司 | 2024-<br>04-23<br>11:10<br>:27.0 | B4-<br>2E-<br>99-<br>E0-<br>93-<br>16@BF<br>EBFBF<br>F0009<br>06EB@<br>41413<br>03030<br>30303<br>03030<br>30303<br>03030<br>30323<br>13430 | 否 | 2024-<br>04-23<br>11:08<br>:38.0 | B4-<br>2E-<br>99-<br>E0-<br>93-<br>16,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>41413<br>03030<br>30303<br>03030<br>30303<br>03030<br>30323<br>13430 | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:35<br>:48 | B4-<br>2E-<br>99-<br>E0-<br>93-<br>16@BF<br>EBFBF<br>F0009<br>06EB@<br>41413<br>03030<br>30303<br>03030<br>30303<br>03030<br>30323<br>13430 | 否   |   |  |



|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|---|--|
| 1365 | 福建云工建筑工程有限公司  | 2024-04-23 11:57:28.0 | 7C-10-C9-8E-86-1F@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 1344_ AB25. | 否 | 2024-04-23 11:56:38.0 | 7C-10-C9-8E-86-1F@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 1344_ AB25. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:31:33 | 7C-10-C9-8E-86-1F@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 1344_ AB25. | 否   |   |  |
| 1366 | 福建省芊华建设工程有限公司 | 2024-04-23 17:08:37.0 | 7C-10-C9-8C-6B-E6@BF EBFBF F000A 0653@ WD- WCC6Y 2FJTY JE, 21 294B8 00897              | 否 | 2024-04-23 17:07:32.0 | 7C-10-C9-8C-6B-E6@BF EBFBF F000A 0653@ WD- WCC6Y 2FJTY JE, 21 294B8 00897              | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:35:49  | 7C-10-C9-8C-6B-E6@BF EBFBF F000A 0653@ WD- WCC6Y 2FJTY JE, 21 294B8 00897 | 否 |  |





|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1369 | 福建远拓建设工程有限公司 | 2024-04-19 09:58:33.0 | B4-2E-99-DD-64-A7,00-00-00-00-00-06EB@50026B738076D630          | 否 | 2024-04-17 17:24:12.0 | B4-2E-99-DD-64-A7,00-00-00-00-00-06EB@50026B738076D630          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:35:40 | B4-2E-99-DD-64-A7@BFEBFBF000906EB@50026B738076D630              | 否 |  |
| 1370 | 福建勾壁建设工程有限公司 | 2024-04-23 15:12:34.0 | 74-56-3C-81-83-66@BFEBFBF00090675@WD-WCC6Y4XPCZ48,L090204E10822 | 否 | 2024-04-23 09:27:34.0 | 74-56-3C-81-83-66@BFEBFBF00090675@WD-WCC6Y4XPCZ48,L090204E10822 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:35:40 | 74-56-3C-81-83-66@BFEBFBF00090675@WD-WCC6Y4XPCZ48,L090204E10822 | 否 |  |

|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1371 | 福建省高聚建设工程有限公司 | 2024-04-23 16:50:02.0 | 7C-10-C9-9E-33-8F@BF EBFBF F000A 0653@WD-WCC6Y OTS62 KZ, 50 026B7 684FB 9C9B | 否 | 2024-04-18 10:08:00.0 | 7C-10-C9-9E-33-8F@BF EBFBF F000A 0653@WD-WCC6Y OTS62 KZ, 50 026B7 684FB 9C9B | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:36:08 | 7C-10-C9-9E-33-8F@BF EBFBF F000A 0653@WD-WCC6Y OTS62 KZ, 50 026B7 684FB 9C9B | 否 |  |
| 1372 | 福建省轩庭建筑有限公司   | 2024-04-23 16:33:34.0 | 74-56-3C-C2-35-59@BF EBFBF F000A 0653@50026 B7382 55AD6 F                    | 否 | 2024-04-23 08:47:50.0 | 74-56-3C-C2-35-59@BF EBFBF F000A 0653@50026 B7382 55AD6 F                    | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:26 | 74-56-3C-C2-35-59@BF EBFBF F000A 0653@50026 B7382 55AD6 F                    | 否 |  |



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1373 | 福建闽雄建设工程有限公司 | 2024-04-23 13:36:27.0 | 0C-9D-92-66-FA-1F, 48-8A-D2-8D-95-92, 48-8A-D2-8D-95-93, 48-8A-D2-8D-95-90@BFEBFBF000906EA@WD-WCC6Y5NC6CN6 | 否 | 2024-04-23 11:30:33.0 | 0C-9D-92-66-FA-1F, 48-8A-D2-8D-95-92, 48-8A-D2-8D-95-93, 48-8A-D2-8D-95-90@BFEBFBF000906EA@WD-WCC6Y5NC6CN6 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:40 | 0C-9D-92-66-FA-1F, 48-8A-D2-8D-95-92, 48-8A-D2-8D-95-90, 48-8A-D2-8D-95-93@BFEBFBF000906EA@WD-WCC6Y5NC6CN6 | 否 |  |
| 1374 | 福建建莆市政园林有限公司 | 2024-04-23 09:59:16.0 | 18-C0-4D-54-28-A8@BFEBFBF000906EA@WDC-DISK SN# XYZ-- , 201015A00013631                                     | 否 | 2024-04-22 09:59:26.0 | 18-C0-4D-54-28-A8@BFEBFBF000906EA@WDC-DISK SN# XYZ-- , 201015A00013631                                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:28 | 18-C0-4D-54-28-A8@BFEBFBF000906EA@WDC-DISK SN# XYZ-- , 201015A00013631                                     | 否 |  |





|      |                   |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |  |                            |                        |   |   |  |
|------|-------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|---|---|--|
| 1377 | 福建鑫誉鼎<br>建设工程有限公司 | 2024-04-23<br>15:21:21.0 | 3C-<br>7C-<br>3F-<br>51-<br>DB-<br>61@BF<br>EBFBF<br>F000A<br>0653@<br>F5182<br>20010<br>11202<br>,5002<br>6B738<br>1255B<br>14,20<br>04432<br>17308<br>02B38<br>52C | 否 | 2024-04-23<br>15:06:43.0 | 3C-<br>7C-<br>3F-<br>51-<br>DB-<br>61@BF<br>EBFBF<br>F000A<br>0653@<br>F5182<br>20010<br>11202<br>,5002<br>6B738<br>1255B<br>14,20<br>04432<br>17308<br>02B38<br>52C | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:40:31 | 3C-<br>7C-<br>3F-<br>51-<br>DB-<br>61@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>255B1<br>4     | 否 |  |
| 1378 | 闽卓建设集<br>团有限公司    | 2024-04-23<br>14:26:48.0 | D8-<br>5E-<br>D3-<br>1B-<br>DA-<br>34@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>00076<br>,0  | 否 | 2024-04-23<br>14:25:41.0 | D8-<br>5E-<br>D3-<br>1B-<br>DA-<br>34@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>00076<br>,0  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:48:26 | D8-<br>5E-<br>D3-<br>1B-<br>DA-<br>34@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>00076 | 否 |  |

|      |                       |                                  |   |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                        |                                |  |   |  |
|------|-----------------------|----------------------------------|---|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------|--------------------------------|--|---|--|
| 1379 | 福建省嘉宸<br>建筑工程有<br>限公司 | 2024-<br>04-23<br>10:54<br>:40.0 | 58-<br>11-<br>22-<br>AD-<br>AE-<br>78@BF<br>EBFBF<br>F0009<br>0672@<br>WD-<br>WCC6Y<br>DH90L<br>RT,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 | 2024-<br>04-23<br>10:53<br>:13.0 | 58-<br>11-<br>22-<br>AD-<br>AE-<br>78@BF<br>EBFBF<br>F0009<br>0672@<br>WD-<br>WCC6Y<br>DH90L<br>RT,00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:49<br>:49 | 58-<br>11-<br>22-<br>AD-<br>AE-<br>78@BF<br>EBFBF<br>F0009<br>0672@<br>WD-<br>WCC6Y<br>DH90L<br>RT,00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 |  |
| 1380 | 三明市八建<br>建设有限公司       | 2024-<br>04-23<br>17:17<br>:22.0 | 00-<br>E0-<br>1D-<br>66-<br>F9-<br>8E@BF<br>EBFBF<br>F000A<br>0653@<br>LCRS5<br>823BB<br>T0430<br>,WD-<br>WMB5G<br>93588<br>86  | 否 | 2024-<br>04-22<br>18:33<br>:08.0 | 00-<br>E0-<br>1D-<br>66-<br>F9-<br>8E@BF<br>EBFBF<br>F000A<br>0653@<br>LCRS5<br>823BB<br>T0430<br>,WD-<br>WMB5G<br>93588<br>86                                     | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:35<br>:46 | 00-<br>E0-<br>1D-<br>66-<br>F9-<br>8E@BF<br>EBFBF<br>F000A<br>0653@<br>LCRS5<br>823BB<br>T0430<br>,WD-<br>WMB5G<br>93588<br>86                                     | 否 |  |
| 1381 | 福建铭瑞建<br>设工程有限<br>公司  | 2024-<br>04-23<br>17:06<br>:34.0 | 58-<br>11-<br>22-<br>C6-<br>8B-<br>4D@BF<br>EBFBF<br>F0009<br>0672@<br>E823_<br>8FA6_   | 否 | 2024-<br>04-22<br>11:37<br>:49.0 | 58-<br>11-<br>22-<br>C6-<br>8B-<br>4D@BF<br>EBFBF<br>F0009<br>0672@<br>E823_<br>8FA6_  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:37<br>:28 | 58-<br>11-<br>22-<br>C6-<br>8B-<br>4D@BF<br>EBFBF<br>F0009<br>0672@<br>E823_<br>8FA6_  | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |   |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---|--|---|--|
|      |              |                       | BF53_0001_001B_448B_4540_0CD9., W9AT TRHJ  |   |                       | BF53_0001_001B_448B_4540_0CD9., W9AT TRHJ  |   |  |  |  |  |  |  |  |  |  |             | BF53_0001_001B_448B_4540_0CD9., W9AT TRHJ |  |   |  |
| 1382 | 福建互维建设工程有限公司 | 2024-04-23 17:15:52.0 | 00-EO-1E-0B-80-45@BF EBFBF F0004 06F1, BFEFB BFF00 0406F 1@Z9L QNBOS, 2C3E_BFFF_F000_004E. | 否 | 2024-04-23 17:15:03.0 | 00-EO-1E-0B-80-45@BF EBFBF F0004 06F1, BFEFB BFF00 0406F 1@Z9L QNBOS, 2C3E_BFFF_F000_004E. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:40:40                       | 00-EO-1E-0B-80-45@BF EBFBF F0004 06F1, BFEFB BFF00 0406F 1@Z9L QNBOS, 2C3E_BFFF_F000_004E. | 否 |  |
| 1383 | 福建永强岩土股份有限公司 | 2024-04-23 17:11:17.0 | 50-EB-F6-2E-FB-3C@BF EBFBF F0009 0675@673UT RZ8T, 0000_0000_0000_0001_0000_0000_0000_0001. | 否 | 2024-04-23 17:09:57.0 | 50-EB-F6-2E-FB-3C@BF EBFBF F0009 0675@673UT RZ8T, 0000_0000_0000_0001_0000_0000_0000_0001. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:36:34                       | 50-EB-F6-2E-FB-3C@BF EBFBF F0009 0675@673UT RZ8T, 0000_0000_0000_0001_0000_0000_0000_0001. | 否 |  |

|      |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 1384 | 福建赤港建设有限公司    | 2024-04-23 17:28:08.0 | 00-<br>E0-<br>1D-<br>6F-<br>9B-<br>29@BF<br>EBFBF<br>F000A<br>0653@<br>LCRS5<br>823BB<br>T0293<br>,W9A7<br>LZ3Y                             | 否 | 2024-04-23 15:17:02.0 | 00-<br>E0-<br>1D-<br>6F-<br>9B-<br>29@BF<br>EBFBF<br>F000A<br>0653@<br>LCRS5<br>823BB<br>T0293<br>,W9A7<br>LZ3Y  | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:34:07   | 00-<br>E0-<br>1D-<br>6F-<br>9B-<br>29@BF<br>EBFBF<br>F000A<br>0653@<br>LCRS5<br>823BB<br>T0293<br>,W9A7<br>LZ3Y | 否 |  |
| 1385 | 福建省榕信建设工程有限公司 | 2024-04-23 10:43:11.0 | 1C-<br>1B-<br>0D-<br>D1-<br>17-<br>EA@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36333<br>73138<br>43374<br>54135<br>43202<br>02020 | 否 | 2024-04-23 10:35:21.0 | 1C-<br>1B-<br>0D-<br>D1-<br>17-<br>EA, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36333<br>73138<br>43374<br>54135<br>43202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:44:12 | 1C-<br>1B-<br>0D-<br>D1-<br>17-<br>EA@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36333<br>73138<br>43374<br>54135<br>43202<br>02020 | 否   |   |  |

|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1386 | 福建正月建设有限公司     | 2024-04-23 14:49:20.0 | 00-E0-4C-EB-01-06@BFEBFBFF000906EA@2C3E_BFFF_F000_0031.  | 否 | 2024-04-23 11:28:43.0 | 00-E0-4C-EB-01-06@BFEBFBFF000906EA@2C3E_BFFF_F000_0031.  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:52:34 | 00-E0-4C-EB-01-06@BFEBFBFF000906EA@2C3E_BFFF_F000_0031.  | 否 |  |
| 1387 | 中通南信建设(福建)有限公司 | 2024-04-23 16:03:32.0 | 00-E0-66-D9-31-D1@178BFBF00610F01@3035323042363737343842413834363220202020,2020202020202020035203431393035545346 | 否 | 2024-04-23 09:00:38.0 | 00-E0-66-D9-31-D1@178BFBF00610F01@3035323042363737343842413834363220202020,2020202020202020035203431393035545346 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:33:25 | 00-E0-66-D9-31-D1@178BFBF00610F01@3035323042363737343842413834363220202020,2020202020202020035203431393035545346 | 否 |  |



|      |                              |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |                         |                                |  |   |   |  |
|------|------------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|--|---|---|--|
| 1388 | 中建路航<br>(福建)建<br>设发展有限<br>公司 | 2024-<br>04-23<br>10:21<br>:56.0 | 58-<br>11-<br>22-<br>07-<br>F6-<br>61@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7TLCN<br>DV, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>78_49<br>FB_A8<br>A5. | 否 | 2024-<br>04-22<br>17:37<br>:18.0 | 58-<br>11-<br>22-<br>07-<br>F6-<br>61@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7TLCN<br>DV, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>78_49<br>FB_A8<br>A5. | 否 |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:33<br>:07 | 58-<br>11-<br>22-<br>07-<br>F6-<br>61@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7TLCN<br>DV, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>78_49<br>FB_A8<br>A5. | 否   |   |  |
| 1389 | 福建品卓建<br>设工程有限<br>公司         | 2024-<br>04-23<br>17:02<br>:07.0 | FC-<br>34-<br>97-<br>68-<br>42-<br>3C@BF<br>EBFBF<br>F000A<br>0653@<br>TA217<br>01652<br>A3187<br>, 61F7<br>884MS  | 否 | 2024-<br>04-23<br>14:47<br>:52.0 | FC-<br>34-<br>97-<br>68-<br>42-<br>3C@BF<br>EBFBF<br>F000A<br>0653@<br>TA217<br>01652<br>A3187<br>, 61F7<br>884MS  | 否 |  |  |  |  |  |  |  |  |                         | 校验<br>数据有<br>误, 请<br>检查        | 2024-<br>04-24<br>08:36<br>:08   | FC-<br>34-<br>97-<br>68-<br>42-<br>3C@BF<br>EBFBF<br>F000A<br>0653@<br>TA217<br>01652<br>A3187<br>, 61F7<br>884MS | 否 |  |

|      |                    |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                         |                                |   |   |  |
|------|--------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|---|---|--|
| 1390 | 福建省祥实<br>建设工程有限公司  | 2024-<br>04-23<br>10:42<br>:09.0 | 7C-<br>10-<br>C9-<br>D1-<br>AD-<br>11@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7FNPO<br>4N, 30<br>04938<br>8099                   | 否 | 2024-<br>04-23<br>10:40<br>:15.0 | 7C-<br>10-<br>C9-<br>D1-<br>AD-<br>11@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7FNPO<br>4N, 30<br>04938<br>8099                   | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:31<br>:45 | 7C-<br>10-<br>C9-<br>D1-<br>AD-<br>11@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>7FNPO<br>4N, 30<br>04938<br>8099                   | 否 |  |
| 1391 | 福建骋铭昇<br>发建设工程有限公司 | 2024-<br>04-23<br>17:20<br>:28.0 | 00-<br>E2-<br>69-<br>5D-<br>2F-<br>20@BF<br>EBFBF<br>F000A<br>0653@<br>CB4F2<br>F3BA0<br>E0, 82<br>3D8Y7<br>NS, 20<br>21110<br>10012<br>1 | 否 | 2024-<br>04-23<br>17:18<br>:15.0 | 00-<br>E2-<br>69-<br>5D-<br>2F-<br>20@BF<br>EBFBF<br>F000A<br>0653@<br>CB4F2<br>F3BA0<br>E0, 82<br>3D8Y7<br>NS, 20<br>21110<br>10012<br>1 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:37<br>:47 | 00-<br>E2-<br>69-<br>5D-<br>2F-<br>20@BF<br>EBFBF<br>F000A<br>0653@<br>CB4F2<br>F3BA0<br>E0, 82<br>3D8Y7<br>NS, 20<br>21110<br>10012<br>1 | 否 |  |

|      |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1392 | 江西九鼎建设集团有限公司 | 2024-04-23 17:30:58.0 | 74-86-E2-20-37-AE, 00-00-00-00-00-00@BF EBFBF F0009 0675@ 0100_ 0000_ 0000_ 0000_ 8CE3_ 8E04_ 035A_ DC26. , W9AR WVAP | 否 | 2024-04-23 17:29:36.0 | 74-86-E2-20-37-AE@BF EBFBF F0009 0675@ 0100_ 0000_ 0000_ 8CE3_ 8E04_ 035A_ DC26. , W9AR WVAP | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:48:16 | 74-86-E2-20-37-AE, 00-00-00-00-00-00@BF EBFBF F0009 0675@ 0100_ 0000_ 0000_ 0000_ 8CE3_ 8E04_ 035A_ DC26. , W9AR WVAP | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|



|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1394 | 福建恒业建筑工程有限公司  | 2024-04-23 14:37:35.0 | 00-<br>E0-<br>97-<br>20-<br>09-<br>B4@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>6866_<br>B595. | 否 | 2024-04-23 14:35:53.0 | 00-<br>E0-<br>97-<br>20-<br>09-<br>B4@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>6866_<br>B595. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:48 | 00-<br>E0-<br>97-<br>20-<br>09-<br>B4@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>6866_<br>B595. | 否 |  |
| 1395 | 福建省晋顺建筑工程有限公司 | 2024-04-23 10:47:05.0 | 74-<br>56-<br>3C-<br>88-<br>C4-<br>8F@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2306_<br>0486_<br>CAF2_<br>5B04_<br>3705_<br>5500. | 否 | 2024-04-23 10:41:09.0 | 74-<br>56-<br>3C-<br>88-<br>C4-<br>8F@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2306_<br>0486_<br>CAF2_<br>5B04_<br>3705_<br>5500. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:33 | 74-<br>56-<br>3C-<br>88-<br>C4-<br>8F@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2306_<br>0486_<br>CAF2_<br>5B04_<br>3705_<br>5500. | 否 |  |





|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1400 | 福建金禾建设工程有限公司 | 2024-04-23 09:46:51.0 | 00-<br>E2-<br>69-<br>71-<br>A9-<br>24@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>00066 | 否 | 2024-04-18 17:37:04.0 | 00-<br>E2-<br>69-<br>71-<br>A9-<br>24@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>00066 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:42 | 00-<br>E2-<br>69-<br>71-<br>A9-<br>24@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>00066 | 否 |  |
| 1401 | 福建华统建设工程有限公司 | 2024-04-22 15:38:46.0 | F0-<br>2F-<br>74-<br>AF-<br>E2-<br>B3@BF<br>EBFBF<br>F000A<br>0653@<br>0026_<br>B768_<br>4750_<br>E595. | 否 | 2024-04-22 15:38:33.0 | F0-<br>2F-<br>74-<br>AF-<br>E2-<br>B3@BF<br>EBFBF<br>F000A<br>0653@<br>0026_<br>B768_<br>4750_<br>E595. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:37:36 | A8-<br>A1-<br>59-<br>42-<br>F2-<br>35@17<br>8FBFB<br>F0081<br>0F81@<br>2K222<br>9AKJC<br>PP             | 否 |  |





|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |                     |                     |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|---------------------|---------------------|---|---|--|
| 1403 | 福建恒乐建设有限公司   | 2024-04-23 13:36:42.0 | 00-<br>E0-<br>4C-<br>49-<br>1C-<br>72, 24<br>-69-<br>8E-<br>4E-<br>ED-<br>E5@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000. | 否 | 2024-04-23 13:35:21.0 | 00-<br>E0-<br>4C-<br>49-<br>1C-<br>72, 24<br>-69-<br>8E-<br>4E-<br>ED-<br>E5@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000. | 否 |  |  |  |  |  |  |  |  |  | 校验数据<br>有误, 请<br>检查 | 2024-04-24 08:32:45 | 24-<br>69-<br>8E-<br>4E-<br>ED-<br>E5, 00<br>-E0-<br>4C-<br>49-<br>1C-<br>72@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000. | 否 |  |
| 1404 | 龙岩冠德建设工程有限公司 | 2024-04-23 15:01:37.0 | F0-<br>2F-<br>74-<br>4E-<br>D5-<br>0E@BF<br>EBFBF<br>F0009<br>06EB@<br>30013<br>50432<br>7, WD-<br>WCC6Y<br>4LRJF<br>13  | 否 | 2024-04-23 14:59:10.0 | F0-<br>2F-<br>74-<br>4E-<br>D5-<br>0E, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>30013<br>50432<br>7, WD-<br>WCC6Y<br>4LRJF<br>13              | 否 |  |  |  |  |  |  |  |  |  | 校验数据<br>有误, 请<br>检查 | 2024-04-24 08:34:50 | F0-<br>2F-<br>74-<br>4E-<br>D6-<br>CD@BF<br>EBFBF<br>F0009<br>06EB@<br>30013<br>89688<br>0, WD-<br>WCC6Y<br>5DSNR<br>T9   | 否 |  |















|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |  |                     |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|---------------------|--|---|--|
| 1413 | 福建中庚建设有限公司 | 2024-04-23 16:14:36.0 | 90-DE-80-E1-A0-79, 92-DE-80-E1-A0-79, 90-DE-80-E1-A0-79, D8-BB-C1-4F-1B-E5@BFEBFBF000A0671@E823_8FA6_BF53_0001_001B_448B_4156_2902., 0 | 否 | 2024-04-23 16:13:40.0 | 90-DE-80-E1-A0-79, 92-DE-80-E1-A0-79, 90-DE-80-E1-A0-79, D8-BB-C1-4F-1B-E5@BFEBFBF000A0671@E823_8FA6_BF53_0001_001B_448B_4156_2902., 0 | 否 |  |  |  |  |  |  |  |  |  |  |  | 2024-04-24 08:38:12 | 92-DE-80-E1-A0-79, 90-DE-80-E1-A0-79, D8-BB-C1-4F-1B-E5, 90-DE-80-E1-A0-79@BFEBFBF000A0671@E823_8FA6_BF53_0001_001B_448B_4156_2902., 0 | 否 |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|---------------------|--|---|--|

校验数据有误，请检查



|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1415 | 福建省永舜建设发展有限公司  | 2024-04-23 15:45:58.0 | 58-11-22-C6-68-0F@BF EBFBF F0009 0675@0000_0006_2302_0006_3A5A_2703_6000_0192., W9AT A7K7 | 否 | 2024-04-23 08:53:40.0 | 58-11-22-C6-68-0F@BF EBFBF F0009 0675@0000_0006_2302_0006_3A5A_2703_6000_0192., W9AT A7K7 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:34 | 58-11-22-C6-68-0F@BF EBFBF F0009 0675@0000_0006_2302_0006_3A5A_2703_6000_0192., W9AT A7K7 | 否 |  |
| 1416 | 杭州临安宏瑞建设工程有限公司 | 2024-04-23 09:47:18.0 | E0-D5-5E-D7-8A-DC@BF EBFBF F0009 06E9@FDCK4 80178 2                                       | 否 | 2024-04-23 09:45:09.0 | E0-D5-5E-D7-8A-DC@BF EBFBF F0009 06E9@FDCK4 80178 2                                       | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:10 | E0-D5-5E-D7-8A-DC@BF EBFBF F0009 06E9@FDCK4 80178 2                                       | 否 |  |

|      |                  |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |                            |                        |  |   |  |
|------|------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|--|---|--|
| 1417 | 远志建设<br>(厦门)有限公司 | 2024-04-19<br>15:27:09.0 | 08-<br>BF-<br>B8-<br>04-<br>49-<br>F6@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2330_<br>47A5. | 否 | 2024-04-19<br>14:51:26.0 | 08-<br>BF-<br>B8-<br>04-<br>49-<br>F6@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2330_<br>47A5. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:36:20 | 08-<br>BF-<br>B8-<br>04-<br>49-<br>F6@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2330_<br>47A5.<br>,OB02<br>18A04<br>6D9 | 否 |  |
| 1418 | 林邦建设有<br>限公司     | 2024-04-23<br>15:50:33.0 | 74-<br>56-<br>3C-<br>A9-<br>DE-<br>DB@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4A37_<br>E582. | 否 | 2024-04-23<br>15:47:29.0 | 74-<br>56-<br>3C-<br>A9-<br>DE-<br>DB@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4A37_<br>E582. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:31:15 | 74-<br>56-<br>3C-<br>A9-<br>DE-<br>DB@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4A37_<br>E582.                          | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1419 | 福建庆山建设工程有限公司 | 2024-04-23 10:09:27.0 | D4-5D-64-A7-FA-06@BF<br>EBFBF<br>F0009<br>06EA@<br>TA203<br>17004<br>20091                                   | 否 | 2024-04-23 09:44:42.0 | D4-5D-64-A7-FA-06@BF<br>EBFBF<br>F0009<br>06EA@<br>TA203<br>17004<br>20091                                   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:28 | D4-5D-64-A7-FA-06@BF<br>EBFBF<br>F0009<br>06EA@<br>TA203<br>17004<br>20091                                   | 否 |  |
| 1420 | 福建亿申工程建设有限公司 | 2024-04-23 15:39:30.0 | 18-C0-4D-50-BB-FC@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>5CLUV<br>F4, 50<br>026B7<br>7841B<br>CAF4 | 否 | 2024-04-23 15:37:13.0 | 18-C0-4D-50-BB-FC@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>5CLUV<br>F4, 50<br>026B7<br>7841B<br>CAF4 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:13 | 18-C0-4D-50-BB-FC@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>5CLUV<br>F4, 50<br>026B7<br>7841B<br>CAF4 | 否 |  |
| 1421 | 福建翰如建设工程有限公司 | 2024-04-23 10:48:02.0 | D8-5E-D3-F8-64-4B@BF<br>EBFBF<br>F000A<br>0653@<br>0000_0000_0000_0000_0026_B768_56EE_7045.                  | 否 | 2024-04-23 10:47:00.0 | D8-5E-D3-F8-64-4B@BF<br>EBFBF<br>F000A<br>0653@<br>0000_0000_0000_0000_0026_B768_56EE_7045.                  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:35 | D8-5E-D3-F8-64-4B@BF<br>EBFBF<br>F000A<br>0653@<br>0000_0000_0000_0000_0026_B768_56EE_7045.                  | 否 |  |



|      |                   |                              |  |   |                              |   |   |  |  |  |  |  |  |  |  |  |                            |                            |   |   |  |
|------|-------------------|------------------------------|--|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|---|--|
| 1424 | 福建省天都<br>建筑工程有限公司 | 2024-04-23<br>15:30<br>:32.0 | F4-<br>B5-<br>20-<br>36-<br>25-<br>EE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>MG210<br>86191<br>3987 | 否 | 2024-04-23<br>15:29<br>:44.0 | F4-<br>B5-<br>20-<br>36-<br>25-<br>EE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>MG210<br>86191<br>3987 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:35<br>:53 | F4-<br>B5-<br>20-<br>36-<br>25-<br>EE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>MG210<br>86191<br>3987 | 否 |  |
| 1425 | 福建富埤科<br>技有限公司    | 2024-04-23<br>16:01<br>:42.0 | A4-<br>0C-<br>66-<br>0D-<br>72-<br>C8@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>5383_<br>1565.        | 否 | 2024-04-23<br>15:59<br>:40.0 | A4-<br>0C-<br>66-<br>0D-<br>72-<br>C8@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>5383_<br>1565. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:44<br>:10 | A4-<br>0C-<br>66-<br>0D-<br>72-<br>C8@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>5383_<br>1565. | 否 |  |









|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 1430 | 福建南平旗盛建设工程有限公司 | 2024-04-22 21:22:48.0 | 08-BF-B8-6F-F2-CF@BF EBFBF F000A 0653@WD-WCC6Y K3XMA RD, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4E 7F_A5 B2. | 否 | 2024-04-22 21:20:54.0 | 08-BF-B8-6F-F2-CF@BF EBFBF F000A 0653@WD-WCC6Y K3XMA RD, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4E 7F_A5 B2. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:43:49 | 08-BF-B8-6F-F2-CF@BF EBFBF F000A 0653@WD-WCC6Y K3XMA RD, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4E 7F_A5 B2. | 否   |   |  |
| 1431 | 厦门市同安区第一建筑工程公司 | 2024-04-23 20:39:15.0 | 58-11-22-C3-52-45@BF EBFBF F000A 0653@50026 B7381 A693C C, WCC 6Y2UE YV4H                                 | 否 | 2024-04-23 20:33:57.0 | 58-11-22-C3-52-45@BF EBFBF F000A 0653@50026 B7381 A693C C, WCC 6Y2UE YV4H                                 | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:32:50   | 58-11-22-C3-52-45@BF EBFBF F000A 0653@50026 B7381 A693C C, WCC 6Y2UE YV4H | 否 |  |

|      |               |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |             |                     |   |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|-------------|---------------------|---|--|---|--|
| 1432 | 福建采宝建设科技有限公司  | 2024-04-23 15:54:49.0 | D8-5E-D3-93-63-9C@BF<br>EBFBF<br>F000A<br>0653@<br>6479_<br>A75F_<br>A050_<br>08BE.<br>, WD-<br>WCC6Y<br>5VFAP<br>26   | 否 | 2024-04-23 15:52:34.0 | D8-5E-D3-93-63-9C@BF<br>EBFBF<br>F000A<br>0653@<br>6479_<br>A75F_<br>A050_<br>08BE.<br>, WD-<br>WCC6Y<br>5VFAP<br>26  | 否 |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:40:41   | D8-5E-D3-5F-70-C8@BF<br>EBFBF<br>F000A<br>0653@<br>6479_<br>A75F_<br>40CO_<br>03E4.<br>, WD-<br>WCC6Y<br>3ND9T<br>HU | 否 |  |
| 1433 | 福建金极地建筑工程有限公司 | 2024-04-22 12:58:48.0 | 04-BF-1B-74-24-B2, B0<br>-DC-<br>EF-<br>14-<br>23-<br>AA, B0<br>-DC-<br>EF-<br>14-<br>23-<br>AA, B0<br>-DC-<br>EF-<br>14-<br>23-<br>AB, B2<br>-DC-<br>EF-<br>14-<br>23-<br>AA@BF<br>EBFBF<br>F0009<br>06A3@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>ACE4_<br>2E00_<br>3A34_<br>98C7. | 否 | 2024-04-22 12:56:08.0 | B0-DC-EF-14-23-AB, B2<br>-DC-<br>EF-<br>14-<br>23-<br>AA, 04<br>-BF-<br>1B-<br>74-<br>24-<br>B2, B0<br>-DC-<br>EF-<br>14-<br>23-<br>AA@BF<br>EBFBF<br>F0009<br>06A3@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>ACE4_<br>2E00_<br>3A34_<br>98C7. | 否 |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:46:34 | B0-DC-EF-14-23-AB, B2<br>-DC-<br>EF-<br>14-<br>23-<br>AA, 04<br>-BF-<br>1B-<br>74-<br>24-<br>B2, B0<br>-DC-<br>EF-<br>14-<br>23-<br>AA@BF<br>EBFBF<br>F0009<br>06A3@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>ACE4_<br>2E00_<br>3A34_<br>98C7. | 否  |   |  |





|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1436 | 福建佳航建设工程有限公司  | 2024-04-23 11:02:54.0 | 58-11-22-9E-C8-2D@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B778_52E7_OCB5. | 否 | 2024-04-23 11:01:14.0 | 58-11-22-9E-C8-2D@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B778_52E7_OCB5. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:37:28 | 58-11-22-9E-C8-2D@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B778_52E7_OCB5. | 否 |  |
| 1437 | 福建中鑫屹建设发展有限公司 | 2024-04-23 18:08:28.0 | 0A-E0-AF-F2-02-6F@BF EBFBF F0002 06A7@02328 01110 44 5                         | 否 | 2024-04-22 22:37:40.0 | 0A-E0-AF-F2-02-6F@BF EBFBF F0002 06A7@02328 01110 44 5                         | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:34:20 | 0A-E0-AF-F2-02-6F@BF EBFBF F0002 06A7@02328 01110 44 5                         | 否 |  |
| 1438 | 福建省正发建设发展有限公司 | 2024-04-23 10:22:40.0 | A0-36-BC-26-02-BE@BF EBFBF F0009 0675@50026 B7381 69CBD B                      | 否 | 2024-04-23 10:16:24.0 | A0-36-BC-26-02-BE@BF EBFBF F0009 0675@50026 B7381 69CBD B                      | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:35:21 | A0-36-BC-26-02-BE@BF EBFBF F0009 0675@50026 B7381 69CBD B                      | 否 |  |











|      |              |                              |   |   |                              |   |  |  |  |  |  |  |  |  |  |  |                      |                            |   |   |  |  |
|------|--------------|------------------------------|---|---|------------------------------|---|--|--|--|--|--|--|--|--|--|--|----------------------|----------------------------|---|---|--|--|
|      |              |                              | 38484<br>24a4b<br>32342<br>02020<br>20202<br>02020  |   |                              | 38484<br>24a4b<br>32342<br>02020<br>20202<br>02020  |  |  |  |  |  |  |  |  |  |  |                      |                            |   |   |  |  |
| 1445 | 福建霖松建设发展有限公司 | 2024-04-23<br>15:46<br>:26.0 | 0A-<br>E0-<br>AF-<br>A6-<br>15-<br>7F@BF<br>EBFBF<br>F0003<br>06A9@<br>40620<br>2610B<br>31<br>6,Q95<br>G75DC | 否 | 2024-04-23<br>15:39<br>:39.0 | 0A-<br>E0-<br>AF-<br>A6-<br>15-<br>7F, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06A9@<br>40620<br>2610B<br>31<br>6,Q95<br>G75DC |  |  |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>检查 | 2024-04-24<br>08:37<br>:47 | 0A-<br>E0-<br>AF-<br>A6-<br>15-<br>7F@BF<br>EBFBF<br>F0003<br>06A9@<br>40620<br>2610B<br>31<br>6,Q95<br>G75DC | 否 |  |  |





|      |                      |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |                            |                            |  |  |   |  |
|------|----------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|----------------------------|----------------------------|--|--|---|--|
| 1449 | 中建永腾<br>(福建)集团有限公司   | 2024-04-23<br>14:36<br>:34.0 | 08-<br>BF-<br>B8-<br>8B-<br>A7-<br>19@BF<br>EBFBF<br>F000B<br>06F2@<br>MG230<br>88001<br>1372  | 否 | 2024-04-23<br>14:35<br>:26.0 | 08-<br>BF-<br>B8-<br>8B-<br>A7-<br>19@BF<br>EBFBF<br>F000B<br>06F2@<br>MG230<br>88001<br>1372  | 否 |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:42<br>:12   | F4-<br>A8-<br>0D-<br>14-<br>37-<br>7C, 14<br>-18-<br>C3-<br>4E-<br>70-<br>3D, 16<br>-18-<br>C3-<br>4E-<br>70-<br>3C, 14<br>-18-<br>C3-<br>4E-<br>70-<br>3C@BF<br>EBFBF<br>F0008<br>06EC@<br>001B_<br>444A_<br>4959_<br>0ABE. | 否 |  |
| 1450 | 福建岚彩建<br>筑工程有限<br>公司 | 2024-04-23<br>15:06<br>:50.0 | AC-<br>9E-<br>17-<br>F0-<br>7C-<br>A0, 24<br>-69-<br>8E-<br>E0-<br>81-<br>AF@BF<br>EBFBF<br>F0003<br>06C3@<br>AA202<br>10840<br>37, AA<br>20210<br>80164 | 否 | 2024-04-23<br>15:03<br>:33.0 | AC-<br>9E-<br>17-<br>F0-<br>7C-<br>A0, 24<br>-69-<br>8E-<br>E0-<br>81-<br>AF@BF<br>EBFBF<br>F0003<br>06C3@<br>AA202<br>10840<br>37, AA<br>20210<br>80164 | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:32<br>:45 | AC-<br>9E-<br>17-<br>F0-<br>7C-<br>A0, 24<br>-69-<br>8E-<br>E0-<br>81-<br>AF@BF<br>EBFBF<br>F0003<br>06C3@<br>AA202<br>10840<br>37, AA<br>20210<br>80164 | 否  |   |  |





|      |                        |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |  |                                |   |   |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|--------------------------------|---|---|--|
| 1452 | 福建华闽建<br>科建筑工程<br>有限公司 | 2024-<br>04-23<br>09:35<br>:12.0 | 08-<br>BF-<br>B8-<br>9D-<br>32-<br>CB@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>02616<br>_0000<br>0001.<br>,0732<br>68110<br>14926<br>29439<br>,WD-<br>WCC6Y<br>6ELS2<br>F1 | 否 | 2024-<br>04-23<br>09:32<br>:49.0 | 08-<br>BF-<br>B8-<br>9D-<br>32-<br>CB@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>02616<br>_0000<br>0001.<br>,0732<br>68110<br>14926<br>29439<br>,WD-<br>WCC6Y<br>6ELS2<br>F1 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>检<br>查 | 2024-<br>04-24<br>08:35<br>:25 | 08-<br>BF-<br>B8-<br>9D-<br>32-<br>CB@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>02616<br>_0000<br>0001.<br>,0732<br>68110<br>14926<br>29439<br>,WD-<br>WCC6Y<br>6ELS2<br>F1 | 否 |  |
| 1453 | 福建省仁宏<br>建设发展有<br>限公司  | 2024-<br>04-23<br>11:22<br>:12.0 | 08-<br>BF-<br>B8-<br>BB-<br>56-<br>8C@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>48BE_<br>CB6C.   | 否 | 2024-<br>04-23<br>11:14<br>:04.0 | 08-<br>BF-<br>B8-<br>BB-<br>56-<br>8C@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>48BE_<br>CB6C.   | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>检<br>查 | 2024-<br>04-24<br>08:31<br>:08 | 08-<br>BF-<br>B8-<br>BB-<br>56-<br>8C@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>48BE_<br>CB6C.   | 否 |  |



|      |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                         |                                |   |   |  |
|------|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|---|---|--|
| 1455 | 福建腾起云<br>建筑工程有<br>限公司 | 2024-<br>04-23<br>09:32<br>:11.0 | 96-<br>B8-<br>6D-<br>9B-<br>49-<br>E3, D8<br>-C4-<br>97-<br>58-<br>3B-<br>49, 94<br>-B8-<br>6D-<br>9B-<br>49-<br>E3@BF<br>EBFBF<br>F0004<br>06E3@<br>AA000<br>00000<br>00000<br>00551 | 否 | 2024-<br>04-23<br>09:29<br>:08.0 | 96-<br>B8-<br>6D-<br>9B-<br>49-<br>E3, D8<br>-C4-<br>97-<br>58-<br>3B-<br>49, 94<br>-B8-<br>6D-<br>9B-<br>49-<br>E3@BF<br>EBFBF<br>F0004<br>06E3@<br>AA000<br>00000<br>00000<br>00551 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:31<br>:13 | 96-<br>B8-<br>6D-<br>9B-<br>49-<br>E3, D8<br>-C4-<br>97-<br>58-<br>3B-<br>49, 94<br>-B8-<br>6D-<br>9B-<br>49-<br>E3@BF<br>EBFBF<br>F0004<br>06E3@<br>AA000<br>00000<br>00000<br>00551 | 否 |  |
| 1456 | 福建岚菱建<br>设有限公司        | 2024-<br>04-23<br>16:42<br>:20.0 | 1C-<br>1B-<br>0D-<br>C7-<br>76-<br>9B@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>OUTS5<br>HL  | 否 | 2024-<br>04-22<br>15:20<br>:25.0 | 1C-<br>1B-<br>0D-<br>C7-<br>76-<br>9B@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>OUTS5<br>HL  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:31<br>:39 | 1C-<br>1B-<br>0D-<br>C7-<br>76-<br>9B@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>OUTS5<br>HL  | 否 |  |





|      |                   |                              |  |   |                              |   |   |  |  |  |  |  |  |  |  |                              |                              |   |   |   |  |
|------|-------------------|------------------------------|--|---|------------------------------|---|---|--|--|--|--|--|--|--|--|------------------------------|------------------------------|---|---|---|--|
| 1460 | 福建鼎祥旺<br>建设工程有限公司 | 2024-04-23<br>11:13<br>:14.0 | 04-<br>D9-<br>F5-<br>CA-<br>B1-<br>F7,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>19207<br>S4494<br>15 | 否 | 2024-04-23<br>11:02<br>:06.0 | 04-<br>D9-<br>F5-<br>CA-<br>B1-<br>F7,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>19207<br>S4494<br>15 | 否 |  |  |  |  |  |  |  |  |                              | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:42<br>:41  | 04-<br>D9-<br>F5-<br>CA-<br>B1-<br>F7,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>19207<br>S4494<br>15 | 否 |  |
| 1461 | 福建泽巍建<br>设工程有限公司  | 2024-04-23<br>15:00<br>:34.0 | E0-<br>D5-<br>5E-<br>D6-<br>BE-<br>7A@BF<br>EBFBF<br>F0009<br>06EA@<br>4d433<br>83441<br>42364<br>a3039<br>36353<br>23120<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>30594          | 否 | 2024-04-22<br>16:53<br>:58.0 | E0-<br>D5-<br>5E-<br>D6-<br>BE-<br>7A,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@                                       | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:31<br>:07   | E0-<br>D5-<br>5E-<br>D6-<br>BE-<br>7A@BF<br>EBFBF<br>F0009<br>06EA@<br>4d433<br>83441<br>42364<br>a3039<br>36353<br>23120<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>30594 | 否   |   |  |



|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1463 | 福建鼎宏建设有限公司 | 2024-04-23 09:58:54.0 | 04-42-1A-23-6F-AA@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0000_ 0100_ 0000_ 0000. | 否 | 2024-04-23 09:56:45.0 | 04-42-1A-23-6F-AA@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0000_ 0100_ 0000_ 0000. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:34 | 04-42-1A-23-6F-AA@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0000_ 0100_ 0000_ 0000. | 否 |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|





|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1465 | 浙江龙泉宏腾建设工程有限公司 | 2024-04-23 10:47:45.0 | 00-E0-4C-5C-E3-1B@178BFBF F00A50F00@0000_0006_2309_0004_3A5A_2703_1000_03FF. | 否 | 2024-04-23 10:46:19.0 | 00-E0-4C-5C-E3-1B@178BFBF F00A50F00@0000_0006_2309_0004_3A5A_2703_1000_03FF. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:39 | 00-E0-4C-5C-E3-1B@178BFBF F00A50F00@0000_0006_2309_0004_3A5A_2703_1000_03FF. | 否 |  |
| 1466 | 福建乐航景观建设发展有限公司 | 2024-04-23 09:53:03.0 | 58-11-22-C6-8B-58@BFEBFBF F00090672@0000_0000_0000_0000_0026_B738_20AE_EC35. | 否 | 2024-04-23 09:51:49.0 | 58-11-22-C6-8B-58@BFEBFBF F00090672@0000_0000_0000_0000_0026_B738_20AE_EC35. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:03 | 58-11-22-C6-8B-58@BFEBFBF F00090672@0000_0000_0000_0000_0026_B738_20AE_EC35. | 否 |  |



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1468 | 福建乾庆建筑工程有限公司 | 2024-04-24 00:06:39.0 | 50-EB-F6-D1-D8-38, F0-B6-1E-7C-60-B9, F0-B6-1E-7C-60-BA, F2-B6-1E-7C-60-B9@BFEBFBF000906A3@0000_0000_0001_00A0_7521_3311_3226., 583445353138373170 | 否 | 2024-04-24 00:05:21.0 | 50-EB-F6-D1-D8-38, F0-B6-1E-7C-60-B9, F0-B6-1E-7C-60-BA, F2-B6-1E-7C-60-B9@BFEBFBF000906A3@0000_0000_0001_00A0_7521_3311_3226., 583445353138373170 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:59:11 | 50-EB-F6-D1-D8-38, F0-B6-1E-7C-60-B9, F0-B6-1E-7C-60-BA, F2-B6-1E-7C-60-B9@BFEBFBF000906A3@0000_0000_0001_00A0_7521_3311_3226., 583445353138373170 | 否 |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|

|      |                        |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                              |                                |  |   |  |
|------|------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------------------------|--------------------------------|--|---|--|
| 1469 | 福建省东泰<br>工程管理有<br>限公司  | 2024-<br>04-22<br>15:49<br>:22.0 | 00-<br>E0-<br>4C-<br>57-<br>A7-<br>8F@BF<br>EBFBF<br>F000A<br>0653@<br>MX_00<br>00000<br>00000<br>00208<br>,WX91<br>A175T<br>6Y3 | 否 | 2024-<br>04-22<br>15:44<br>:25.0 | 00-<br>E0-<br>4C-<br>57-<br>A7-<br>8F@BF<br>EBFBF<br>F000A<br>0653@<br>MX_00<br>00000<br>00000<br>00208<br>,WX91<br>A175T<br>6Y3 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:36<br>:45 | 00-<br>E0-<br>4C-<br>57-<br>A7-<br>8F@BF<br>EBFBF<br>F000A<br>0653@<br>MX_00<br>00000<br>00000<br>00208<br>,WX91<br>A175T<br>6Y3 | 否 |  |
| 1470 | 福建省鑫永<br>阳建设工程<br>有限公司 | 2024-<br>04-23<br>11:28<br>:33.0 | 60-<br>45-<br>CB-<br>73-<br>3B-<br>B8@BF<br>EBFBF<br>F0009<br>06E9@<br>WCC6Y<br>6TZA5<br>3L,00<br>25_38<br>B3_71<br>B3_1A<br>FA. | 否 | 2024-<br>04-23<br>11:27<br>:15.0 | 60-<br>45-<br>CB-<br>73-<br>3B-<br>B8@BF<br>EBFBF<br>F0009<br>06E9@<br>WCC6Y<br>6TZA5<br>3L,00<br>25_38<br>B3_71<br>B3_1A<br>FA. | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:55<br>:10 | 60-<br>45-<br>CB-<br>73-<br>3B-<br>B8@BF<br>EBFBF<br>F0009<br>06E9@<br>WCC6Y<br>6TZA5<br>3L,00<br>25_38<br>B3_71<br>B3_1A<br>FA. | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1471 | 福建中煌建设有限公司   | 2024-04-22 21:46:42.0 | D8-5E-D3-DA-D5-7E@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4VEEC<br>7L, 50<br>026B7<br>3816A<br>79E0                                       | 否 | 2024-04-22 21:36:59.0 | D8-5E-D3-DA-D5-7E@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4VEEC<br>7L, 50<br>026B7<br>3816A<br>79E0                                       | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:10 | 1C-1B-0D-2C-EB-6E@BF<br>EBFBF<br>F0003<br>06C3@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>75958<br>55393<br>64541                            | 否 |  |
| 1472 | 福建霆巍建设工程有限公司 | 2024-04-23 17:10:41.0 | 00-E0-4C-24-6A-F7@BF<br>EBFBF<br>F0009<br>06EB@<br>S4Y08<br>483, 0<br>000_0<br>000_0<br>000_0<br>000_0<br>000_0<br>026_B<br>738_1<br>43E_4<br>025. | 否 | 2024-04-23 17:07:43.0 | 00-E0-4C-24-6A-F7@BF<br>EBFBF<br>F0009<br>06EB@<br>S4Y08<br>483, 0<br>000_0<br>000_0<br>000_0<br>000_0<br>000_0<br>026_B<br>738_1<br>43E_4<br>025. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:38:44 | 00-E0-4C-24-6A-F7@BF<br>EBFBF<br>F0009<br>06EB@<br>S4Y08<br>483, 0<br>000_0<br>000_0<br>000_0<br>000_0<br>000_0<br>026_B<br>738_1<br>43E_4<br>025. | 否 |  |



|      |                   |                              |  |   |                              |   |   |  |  |  |  |  |  |  |  |  |                              |                              |  |   |   |  |
|------|-------------------|------------------------------|--|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|------------------------------|------------------------------|--|---|---|--|
| 1474 | 福建鑫楷鼎<br>建设工程有限公司 | 2024-04-23<br>13:11<br>:35.0 | D8-<br>5E-<br>D3-<br>9E-<br>87-<br>93@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2HDLL<br>8J,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_18<br>00_A8<br>45. | 否 | 2024-04-23<br>13:09<br>:24.0 | D8-<br>5E-<br>D3-<br>9E-<br>87-<br>93@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2HDLL<br>8J,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_18<br>00_A8<br>45. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:32<br>:41   | D8-<br>5E-<br>D3-<br>9E-<br>87-<br>93,00<br>-5C-<br>C2-<br>2C-<br>23-<br>55@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2HDLL<br>8J,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_18<br>00_A8<br>45. | 否   |   |  |
| 1475 | 泉悦城建有<br>限公司      | 2024-04-23<br>17:46<br>:06.0 | D4-<br>5D-<br>64-<br>AF-<br>20-<br>86@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>2KSS5<br>VJ,50<br>026B7<br>683A9<br>9D65  | 否 | 2024-04-23<br>17:44<br>:42.0 | D4-<br>5D-<br>64-<br>AF-<br>20-<br>86@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>2KSS5<br>VJ,50<br>026B7<br>683A9<br>9D65   | 否 |  |  |  |  |  |  |  |  |  |                              | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:32<br>:40   | D4-<br>5D-<br>64-<br>AF-<br>20-<br>86@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>2KSS5<br>VJ,50<br>026B7<br>683A9<br>9D65 | 否 |  |





|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1478 | 福建省永志建设发展有限公司 | 2024-04-17 09:33:03.0 | 74-56-3C-EF-EB-6C@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>MD5V0<br>PJ, 50<br>026B7<br>38254<br>02EA | 否 | 2024-04-17 09:31:50.0 | 74-56-3C-EF-EB-6C@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>MD5V0<br>PJ, 50<br>026B7<br>38254<br>02EA | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:46:20 | 74-56-3C-EF-EB-6C@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>MD5V0<br>PJ, 50<br>026B7<br>38254<br>02EA | 否 |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|



|      |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|---|--|
| 1480 | 厦门仪翔建设工程有限公司 | 2024-04-23 17:02:09.0 | 00-E2-69-74-CB-5E, 84-C8-A0-4D-77-B9, 84-C8-A0-4D-77-B8, 84-C8-A0-4D-77-B8, C6-C8-A0-4D-77-B8@BF-EBFBF-F0009-0675@6479-A77A-3000-01E4. | 否 | 2024-04-23 17:00:05.0 | 00-E2-69-74-CB-5E, 84-C8-A0-4D-77-B8, 84-C8-A0-4D-77-B8, C6-C8-A0-4D-77-B9@BF-EBFBF-F0009-0675@6479-A77A-3000-01E4. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:36:08 | 00-E2-69-74-CB-5E, 84-C8-A0-4D-77-B9, 84-C8-A0-4D-77-B8, 84-C8-A0-4D-77-B8, C6-C8-A0-4D-77-B8@BF-EBFBF-F0009-0675@6479-A77A-3000-01E4. | 否   |   |  |
| 1481 | 浙江天境建设集团有限公司 | 2024-04-23 14:13:02.0 | E0-D5-5E-FB-21-7A, 50-2B-73-D0-17-D9, 52-2B-73-D0-17-D9, 50  | 否 | 2024-04-23 13:20:46.0 | E0-D5-5E-FB-21-7A, 52-2B-73-D0-17-D9, 50-2B-73-D0-17-D9, 50   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:52:42  | E0-D5-5E-FB-21-7A, 24-69-8E-5A-D4-BE, 24-69-8E-5A-D4-B8, 24 | 否 |  |

|      |                 |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
|      |                 |                       | -2B-<br>73-<br>D0-<br>17-<br>D9@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7682<br>3C54A<br>6, WD-<br>WCC6Y<br>4PE6R<br>5C  |   |                       | -2B-<br>73-<br>D0-<br>17-<br>D9@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7682<br>3C54A<br>6, WD-<br>WCC6Y<br>4PE6R<br>5C  |   |  |  |  |  |  |  |  |  |             |                     | -69-<br>8E-<br>5A-<br>D4-<br>B9@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7682<br>3C54A<br>6, WD-<br>WCC6Y<br>4PE6R<br>5C  |   |  |
| 1482 | 福建省中闽雅鑫建筑工程有限公司 | 2024-04-23 09:45:58.0 | 48-<br>8A-<br>D2-<br>ED-<br>2B-<br>9A, 04<br>-92-<br>26-<br>D6-<br>86-<br>E2, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>AA190<br>31716<br>66, WD<br>-<br>WCC6Y<br>3ET5L<br>XJ, FB<br>A833C<br>2 | 否 | 2024-04-23 09:44:53.0 | 48-<br>8A-<br>D2-<br>ED-<br>2B-<br>9A, 04<br>-92-<br>26-<br>D6-<br>86-<br>E2, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>AA190<br>31716<br>66, WD<br>-<br>WCC6Y<br>3ET5L<br>XJ, FB<br>A833C<br>2 | 否 |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:36:14 | 48-<br>8A-<br>D2-<br>ED-<br>2B-<br>9A, 04<br>-92-<br>26-<br>D6-<br>86-<br>E2@BF<br>EBFBF<br>F0009<br>06E9@<br>AA190<br>31716<br>66, WD<br>-<br>WCC6Y<br>3ET5L<br>XJ, FB<br>A833C<br>2 | 否 |  |











|      |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 1487 | 福建本茂建筑工程有限公司 | 2024-04-23 10:33:16.0 | D4-5D-64-49-E5-78@BF<br>EBFBF<br>F0009<br>06EB@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>4594c<br>43393<br>63539 | 否 | 2024-04-23 10:29:58.0 | D4-5D-64-49-E5-78,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>4594c<br>43393<br>63539 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:12 | D4-5D-64-49-E5-78@BF<br>EBFBF<br>F0009<br>06EB@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>4594c<br>43393<br>63539 | 否   |   |  |
| 1488 | 福建省梁禹工程有限公司  | 2024-04-23 17:55:41.0 | A0-36-BC-2C-CF-45@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>HJYE8<br>5J,00<br>00_00<br>00_00<br>00_00<br>01.     | 否 | 2024-04-23 17:53:41.0 | A0-36-BC-2C-CF-45@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>HJYE8<br>5J,00<br>00_00<br>00_00<br>00_00<br>01.  | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:33:07   | A0-36-BC-2C-CF-45@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>HJYE8<br>5J,00<br>00_00<br>00_00<br>00_00<br>01. | 否 |  |









|      |                  |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|------------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1493 | 福建闽金拓建设有限公司      | 2024-04-23 16:39:10.0 | 48-F3-17-00-E8-81@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>05068                             | 否 | 2024-04-23 16:35:51.0 | 48-F3-17-00-E8-81@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>05068                             | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:35:40 | 48-F3-17-00-E8-81@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>05068                             | 否 |  |
| 1494 | 福建省建瓯市兴芝水利工程有限公司 | 2024-04-23 08:42:18.0 | 40-B0-76-7D-E0-2F@BF<br>EBFBF<br>F0009<br>06E9@<br>RW195<br>21213<br>D0267                                      | 否 | 2024-04-23 08:30:15.0 | 40-B0-76-7D-E0-2F@BF<br>EBFBF<br>F0009<br>06E9@<br>RW195<br>21213<br>D0267                                      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:32:17 | 40-B0-76-7D-E0-2F@BF<br>EBFBF<br>F0009<br>06E9@<br>RW195<br>21213<br>D0267                                      | 否 |  |
| 1495 | 福建省新展望园林工程有限公司   | 2024-04-23 16:15:07.0 | 00-E0-4C-36-01-68@BF<br>EBFBF<br>F0002<br>0655@<br>ZJ1T0<br>21G09<br>04000<br>03298<br>, LR02<br>30410<br>191 3 | 否 | 2024-04-23 15:44:05.0 | 00-E0-4C-36-01-68@BF<br>EBFBF<br>F0002<br>0655@<br>ZJ1T0<br>21G09<br>04000<br>03298<br>, LR02<br>30410<br>191 3 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:38:19 | 00-E0-4C-36-01-68@BF<br>EBFBF<br>F0002<br>0655@<br>ZJ1T0<br>21G09<br>04000<br>03298<br>, LR02<br>30410<br>191 3 | 否 |  |







|      |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1499 | 福建省安太祥德建筑工程有限公司 | 2024-04-23 11:21:26.0 | FC-34-97-66-A0-42@BFEBFBFF000906E9@50026B7684526193                              | 否 | 2024-04-23 11:18:57.0 | FC-34-97-66-A0-42@BFEBFBFF000906E9@50026B7684526193                              | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:31 | FC-34-97-66-A0-42@BFEBFBFF000906E9@50026B7684526193                              | 否 |  |
| 1500 | 福建标特建设有限公司      | 2024-04-23 14:19:29.0 | 74-56-3C-5E-4E-15@BFEBFBFF00090675@0000_0000_0000_0000_0000_0026_B738_1D56_A055. | 否 | 2024-04-23 09:30:55.0 | 74-56-3C-5E-4E-15@BFEBFBFF00090675@0000_0000_0000_0000_0000_0026_B738_1D56_A055. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:03 | 74-56-3C-5E-4E-15@BFEBFBFF00090675@0000_0000_0000_0000_0000_0026_B738_1D56_A055. | 否 |  |
| 1501 | 福建龙鼎建设工程有限公司    | 2024-04-23 10:55:50.0 | 24-4B-FE-96-E2-A9,04-7F-OE-4E-3A-DD@BFEBFBFF000906EB@WD-WCC4J5EVC2CJ,AA          | 否 | 2024-04-23 10:50:55.0 | 24-4B-FE-96-E2-A9,04-7F-OE-4E-3A-DD@BFEBFBFF000906EB@WD-WCC4J5EVC2CJ,AA          | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:39 | 24-4B-FE-96-E2-A9,04-7F-OE-4E-3A-DD@BFEBFBFF000906EB@WD-WCC4J5EVC2CJ,AA          | 否 |  |





|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
|      |               |                       |   |   |                       | 48E0-247D.  |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
| 1503 | 福建省腾江建设工程有限公司 | 2024-04-23 18:35:15.0 | 04-42-1A-30-31-45@BFEBFBFF000A0653@KA22305220Y0181                  | 否 | 2024-04-22 14:30:36.0 | 04-42-1A-30-31-45@BFEBFBFF000A0653@KA22305220Y0181                  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:32 | 04-42-1A-30-31-45@BFEBFBFF000A0653@KA22305220Y0181                  | 否 |  |
| 1504 | 安徽嘉生态建设有限公司   | 2024-04-23 10:58:22.0 | 74-56-3C-E6-78-B1@BFEBFBFF00090675@6479_A784_3AD0_0AD6.             | 否 | 2024-04-23 10:49:30.0 | 74-56-3C-E6-78-B1@BFEBFBFF00090675@6479_A784_3AD0_0AD6.             | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:51 | 74-56-3C-E6-78-B1@BFEBFBFF00090675@6479_A784_3AD0_0AD6.             | 否 |  |
| 1505 | 福建强龙建设有限公司    | 2024-04-23 09:02:11.0 | 40-8D-5C-CD-4B-60@BFEBFBFF000306C3@WD-WCC2EKZPA85C,50026B73820F4C81 | 否 | 2024-04-23 09:00:10.0 | 40-8D-5C-CD-4B-60@BFEBFBFF000306C3@WD-WCC2EKZPA85C,50026B73820F4C81 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:08 | 40-8D-5C-CD-4B-60@BFEBFBFF000306C3@WD-WCC2EKZPA85C,50026B73820F4C81 | 否 |  |

|      |            |  |   |   |   |  |  |  |  |  |  |  |  |  |  |  |  |   |   |  |
|------|------------|--|---|---|---|--|--|--|--|--|--|--|--|--|--|--|--|---|---|--|
| 1506 | 福建创世建设有限公司 | 2024-04-22 15:13:59.0  | 否 | 2024-04-22 15:12:19.0   | 否 |  |  |  |  |  |  |  |  |  |  |  |  | 2024-04-24 08:34:25   | 否 |  |
|      |            | 00-<br>E0-<br>4C-<br>97-<br>E7-<br>A8,00<br>-E0-<br>70-<br>AF-<br>62-<br>13,00<br>-E0-<br>4C-<br>97-<br>E7-<br>A8,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36333<br>73038<br>36353<br>14437<br>39202<br>02020 |   | 00-<br>E0-<br>4C-<br>97-<br>E7-<br>A8,00<br>-E0-<br>70-<br>AF-<br>62-<br>13,00<br>-E0-<br>4C-<br>97-<br>E7-<br>A8,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36333<br>73038<br>36353<br>14437<br>39202<br>02020 |   |  |  |  |  |  |  |  |  |  |  |  |  | 00-<br>E0-<br>4C-<br>97-<br>E7-<br>A8,00<br>-E0-<br>70-<br>AF-<br>62-<br>13,00<br>-E0-<br>4C-<br>97-<br>E7-<br>A8,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36333<br>73038<br>36353<br>14437<br>39202<br>02020 |   |  |

校验数据有错误，请检查







|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |              |                     |  |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--------------|---------------------|--|--|---|--|
| 1510 | 福建途锐建设有限公司    | 2024-04-23 16:47:26.0 | 24-4B-FE-06-9F-C7@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC4M<br>1DJU0<br>18, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_46<br>3F_AC<br>D6. | 否 | 2024-04-23 16:46:24.0 | 24-4B-FE-06-9F-C7@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC4M<br>1DJU0<br>18, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_46<br>3F_AC<br>D6. | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:40:43 | 24-4B-FE-06-9F-C7@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC4M<br>1DJU0<br>18, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_46<br>3F_AC<br>D6. | 否  |   |  |
| 1511 | 福建昌和盛建设工程有限公司 | 2024-04-23 09:42:28.0 | 00-E0-1F-95-00-<br>C4@BF<br>EBFBF<br>F000A<br>0653@<br>W4Y2Q<br>V9Y, L<br>CRY82<br>23ABT<br>6435   | 否 | 2024-04-23 09:35:30.0 | 00-E0-1F-95-00-<br>C4@BF<br>EBFBF<br>F000A<br>0653@<br>W4Y2Q<br>V9Y, L<br>CRY82<br>23ABT<br>6435   | 否 |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:32:31  | 00-E0-1F-95-00-<br>C4@BF<br>EBFBF<br>F000A<br>0653@<br>W4Y2Q<br>V9Y, L<br>CRY82<br>23ABT<br>6435 | 否 |  |
| 1512 | 福建省晨泰建设工程有限公司 | 2024-04-23 11:31:30.0 | A4-OC-66-OC-9D-<br>6E@BF<br>EBFBF<br>F0009<br>0675@<br>AA000<br>00000<br>00000<br>00773  | 否 | 2024-04-23 10:30:08.0 | A4-OC-66-OC-9D-<br>6E@BF<br>EBFBF<br>F0009<br>0675@<br>AA000<br>00000<br>00000<br>00773  | 否 |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:33:49  | A4-OC-66-OC-9D-<br>6E@BF<br>EBFBF<br>F0009<br>0675@<br>AA000<br>00000<br>00000<br>00773          | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |              |                     |  |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--------------|---------------------|--|--|---|--|
| 1513 | 福建川磊建设有限公司   | 2024-04-23 15:24:06.0 | 1C-1B-0D-D2-11-19@BF EBFBF F0009 06E9@ 37313 03133 30383 33230 36372 03920 20202 02020 ,2020 20202 02020 20202 02020 02020 39574 c4135 37575 a | 否 | 2024-04-23 10:51:06.0 | 1C-1B-0D-D2-11-19@BF EBFBF F0009 06E9@ 37313 03133 30383 33230 36372 03920 20202 02020 ,2020 20202 02020 20202 02020 39574 c4135 37575 a | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:39 | 1C-1B-0D-D2-11-19@BF EBFBF F0009 06E9@ 37313 03133 30383 33230 36372 03920 20202 02020 ,2020 20202 02020 20202 02020 02020 39574 c4135 37575 a | 否  |   |  |
| 1514 | 福建瑞科市政工程有限公司 | 2024-04-23 11:46:22.0 | 08-BF-B8-BB-55-14@BF EBFBF F0009 0675@ 0000_ 0006_ 2309_ 0018_ 3A5A_ 2703_ 3000_ 0294. , W9AA V484   | 否 | 2024-04-23 11:42:35.0 | 08-BF-B8-BB-55-14@BF EBFBF F0009 0675@ 0000_ 0006_ 2309_ 0018_ 3A5A_ 2703_ 3000_ 0294. , W9AA V484                                       | 否 |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:41:42  | 08-BF-B8-BB-55-14@BF EBFBF F0009 0675@ 0000_ 0006_ 2309_ 0018_ 3A5A_ 2703_ 3000_ 0294. , W9AA V484 | 否 |  |

|      |                        |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                                |   |   |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------------------------|---|---|--|
| 1515 | 南平西區城<br>市建設開發<br>有限公司 | 2024-<br>04-19<br>13:15<br>:10.0 | 08-<br>BF-<br>B8-<br>A2-<br>66-<br>C2@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>23FA_<br>7E45. | 否 | 2024-<br>04-19<br>13:13<br>:24.0 | 08-<br>BF-<br>B8-<br>A2-<br>66-<br>C2@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>23FA_<br>7E45. | 否 |  |  |  |  |  |  |  |  |  | 校<br>驗<br>數<br>據<br>有<br>誤<br>，<br>請<br>檢<br>查 | 2024-<br>04-24<br>08:33<br>:53 | E8-<br>9C-<br>25-<br>42-<br>C1-<br>1B@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2645_<br>C565. | 否 |  |
| 1516 | 江西鼎海建<br>設工程有限<br>公司   | 2024-<br>04-19<br>14:02<br>:10.0 | 74-<br>56-<br>3C-<br>C1-<br>FB-<br>D9@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>48AE_<br>0016. | 否 | 2024-<br>04-19<br>13:55<br>:40.0 | 74-<br>56-<br>3C-<br>C1-<br>FB-<br>D9@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>48AE_<br>0016. | 否 |  |  |  |  |  |  |  |  |  | 校<br>驗<br>數<br>據<br>有<br>誤<br>，<br>請<br>檢<br>查 | 2024-<br>04-24<br>08:41<br>:01 | 74-<br>56-<br>3C-<br>C1-<br>FB-<br>D9@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>48AE_<br>0016. | 否 |  |

|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|--|---|--|
| 1517 | 万厦（福建）建设投资有限公司 | 2024-04-23 15:58:48.0 | 00-<br>E0-<br>4C-<br>11-<br>19-<br>F3, 04-<br>7F-<br>OE-<br>4D-<br>BC-<br>ED@BF<br>EBFBF<br>F0003<br>06A9@<br>S2DKN<br>XAG71<br>6505N<br>, WD-<br>WCC2E<br>AE503<br>60 | 否 | 2024-04-22 12:04:01.0 | 00-<br>E0-<br>4C-<br>11-<br>19-<br>F3, 04-<br>7F-<br>OE-<br>4D-<br>BC-<br>ED@BF<br>EBFBF<br>F0003<br>06A9@<br>S2DKN<br>XAG71<br>6505N<br>, WD-<br>WCC2E<br>AE503<br>60 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:23 | 00-<br>E0-<br>4C-<br>11-<br>19-<br>F3, 04-<br>7F-<br>OE-<br>4D-<br>BC-<br>ED@BF<br>EBFBF<br>F0003<br>06A9@<br>S2DKN<br>XAG71<br>6505N<br>, WD-<br>WCC2E<br>AE503<br>60 | 否  |   |  |
| 1518 | 福建元之源工程管理有限公司  | 2024-04-23 17:04:50.0 | 04-<br>92-<br>26-<br>57-<br>9F-<br>DF@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>6FVJF<br>47   | 否 | 2024-04-23 14:35:23.0 | 04-<br>92-<br>26-<br>57-<br>9F-<br>DF@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>6FVJF<br>47   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:32:15  | 04-<br>92-<br>26-<br>57-<br>9F-<br>DF@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>6FVJF<br>47 | 否 |  |

|      |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1519 | 福建固川建设有限公司 | 2024-04-23 17:25:23.0 | EC-D6-8A-EC-C8-13@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WX22D<br>3374P<br>6X,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1E<br>4B_D8<br>15. | 否 | 2024-04-22 14:33:47.0 | EC-D6-8A-EC-C8-13@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WX22D<br>3374P<br>6X,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1E<br>4B_D8<br>15. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:40:41 | EC-D6-8A-EC-C8-13@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WX22D<br>3374P<br>6X,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1E<br>4B_D8<br>15. | 否 |  |
|------|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|









|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1523 | 中建（福建）建设有限公司  | 2024-04-23 08:51:54.0 | 74-56-3C-A4-16-B4@BF EBFBF F0009 0675@WD-WCC6Y 14ALT D8,00 25_38 A7_21 B0_79 16. | 否 | 2024-04-23 08:49:38.0 | 74-56-3C-A4-16-B4@BF EBFBF F0009 0675@WD-WCC6Y 14ALT D8,00 25_38 A7_21 B0_79 16. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:31:23 | 74-56-3C-A4-16-B4@BF EBFBF F0009 0675@WD-WCC6Y 14ALT D8,00 25_38 A7_21 B0_79 16. | 否 |  |
| 1524 | 福建省豪门建设工程有限公司 | 2024-04-23 10:51:22.0 | 18-C0-4D-34-00-4B@BF EBFBF F0009 06EA@WD-WCC6Y 6RFD0 A5,MM C959Q 01266 20S30 2   | 否 | 2024-04-23 10:49:17.0 | 18-C0-4D-34-00-4B@BF EBFBF F0009 06EA@WD-WCC6Y 6RFD0 A5,MM C959Q 01266 20S30 2   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:46 | 18-C0-4D-34-00-4B@BF EBFBF F0009 06EA@WD-WCC6Y 6RFD0 A5,MM C959Q 01266 20S30 2   | 否 |  |





|      |                   |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                            |                            |  |   |   |  |
|------|-------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|--|---|---|--|
| 1528 | 福建亚拓鸿<br>建设工程有限公司 | 2024-04-23<br>10:31<br>:54.0 | FC-<br>34-<br>97-<br>A7-<br>A0-<br>26@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7381<br>3FAF1<br>D  | 否 | 2024-04-23<br>10:28<br>:21.0 | FC-<br>34-<br>97-<br>A7-<br>A0-<br>26@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7381<br>3FAF1<br>D  | 否 |  |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:40<br>:40   | FC-<br>34-<br>97-<br>A7-<br>A0-<br>26@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7381<br>3FAF1<br>D | 否 |  |
| 1529 | 福建闽环林<br>建设有限公司   | 2024-04-23<br>15:29<br>:51.0 | 08-<br>BF-<br>B8-<br>BB-<br>66-<br>ED@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>2NAP4<br>NH,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_24<br>A2_E3<br>35. | 否 | 2024-04-23<br>15:27<br>:24.0 | 08-<br>BF-<br>B8-<br>BB-<br>66-<br>ED@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>2NAP4<br>NH,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_24<br>A2_E3<br>35. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:33<br>:07 | 08-<br>BF-<br>B8-<br>BB-<br>66-<br>ED@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>2NAP4<br>NH,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_24<br>A2_E3<br>35. | 否   |   |  |

|      |                   |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |                            |                        |   |   |  |
|------|-------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|---|---|--|
| 1530 | 福建晟隆合<br>建设工程有限公司 | 2024-04-23<br>10:57:37.0 | D4-<br>5D-<br>64-<br>4A-<br>4D-<br>E9@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>8602F<br>4 | 否 | 2024-04-23<br>10:55:56.0 | D4-<br>5D-<br>64-<br>4A-<br>4D-<br>E9, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>8602F<br>4 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:37:18 | D4-<br>5D-<br>64-<br>4A-<br>4D-<br>E9@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>8602F<br>4 | 否 |  |
|------|-------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|---|---|--|



|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1532 | 福建省永茂市政工程有限公司 | 2024-04-23 08:41:11.0 | 08-BF-B8-A3-4A-F1@BF EBFBF F000A 0653@WD-WCC6Y 1AD5F SE, 50 026B7 38231 7CA9                                    | 否 | 2024-04-22 17:21:48.0 | 08-BF-B8-A3-4A-F1@BF EBFBF F000A 0653@WD-WCC6Y 1AD5F SE, 50 026B7 38231 7CA9                                    | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:14 | 08-BF-B8-A3-4A-F1@BF EBFBF F000A 0653@WD-WCC6Y 1AD5F SE, 50 026B7 38231 7CA9                                    | 否 |  |
| 1533 | 厦门正方建设有限公司    | 2024-04-20 21:24:38.0 | 54-E1-AD-BB-25-C4, 66 -6E-69-FC-C1-ED, 76 -6E-69-FC-C1-ED@BF EBFBF F0008 06E9@WD-WX21A 97N63 D1, 68 71116 50101 | 否 | 2024-04-20 21:21:48.0 | 54-E1-AD-BB-25-C4, 66 -6E-69-FC-C1-ED, 76 -6E-69-FC-C1-ED@BF EBFBF F0008 06E9@WD-WX21A 97N63 D1, 68 71116 50101 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:23 | 54-E1-AD-BB-25-C4, 66 -6E-69-FC-C1-ED, 76 -6E-69-FC-C1-ED@BF EBFBF F0008 06E9@WD-WX21A 97N63 D1, 68 71116 50101 | 否 |  |















|      |                |                                  |   |   |  |   |   |  |  |  |  |  |  |  |  |  |  |                                |   |   |  |
|------|----------------|----------------------------------|---|---|--|---|---|--|--|--|--|--|--|--|--|--|--|--------------------------------|---|---|--|
|      |                |                                  | 7202d<br>44435<br>73643<br>33595<br>45343<br>34485<br>2   |   | E0@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>53038<br>37373<br>63438<br>20322<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>33595<br>45343<br>34485<br>2 |   |   |  |  |  |  |  |  |  |  |  | E0@BF<br>EBFBF<br>F000A<br>0653@<br>30333<br>53038<br>37373<br>63438<br>20322<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>33595<br>45343<br>34485<br>2 |                                |   |   |  |
| 1542 | 坤众建设发<br>展有限公司 | 2024-<br>04-18<br>11:49<br>:59.0 | 00-<br>D8-<br>61-<br>DA-<br>13-<br>B1@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>6A9D0<br>9, ZN1<br>K4VDN | 否 | 2024-<br>04-18<br>11:46<br>:16.0   | 00-<br>D8-<br>61-<br>DA-<br>13-<br>B1, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>6A9D0<br>9, ZN1<br>K4VDN | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查   | 2024-<br>04-24<br>08:34<br>:39 | 00-<br>D8-<br>61-<br>DA-<br>13-<br>B1@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>6A9D0<br>9, ZN1<br>K4VDN | 否 |  |



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1544 | 智耀（福建）建设有限公司 | 2024-04-23 09:18:45.0 | 04-D9-F5-CA-B1-E3@BF EBFBF F0009 06EA@WD-WCC6Y 3UJSL T9, KL 23B03 0A8A1 074                            | 否 | 2024-04-23 09:17:25.0 | 04-D9-F5-CA-B1-E3@BF EBFBF F0009 06EA@WD-WCC6Y 3UJSL T9, KL 23B03 0A8A1 074                            | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:42 | 04-D9-F5-CA-B1-E3@BF EBFBF F0009 06EA@WD-WCC6Y 3UJSL T9, KL 23B03 0A8A1 074                            | 否 |  |
| 1545 | 福建东锦华远建设有限公司 | 2024-04-19 09:58:58.0 | E8-9C-25-42-C0-98@BF EBFBF F0009 0675@TW184 01041 87, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4A 98_43 76. | 否 | 2024-04-19 09:51:26.0 | E8-9C-25-42-C0-98@BF EBFBF F0009 0675@TW184 01041 87, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4A 98_43 76. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:34 | E8-9C-25-42-C0-98@BF EBFBF F0009 0675@TW184 01041 87, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4A 98_43 76. | 否 |  |



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |             |                     |  |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|---|--|
| 1546 | 河南鼎帆建筑工程有限公司 | 2024-04-23 17:45:48.0 | 00-<br>E0-<br>4D-<br>A3-<br>47-<br>AD@BF<br>EBFBF<br>F0003<br>06A9@<br>2211V<br>6503c<br>62040<br>6  | 否 | 2024-04-23 17:43:43.0 | 00-<br>E0-<br>4D-<br>A3-<br>47-<br>AD@BF<br>EBFBF<br>F0003<br>06A9@<br>2211V<br>6503c<br>62040<br>6  | 否 |  |  |  |  |  |  |  |  |             | 校验数据有误差，请检查         | 2024-04-24 08:37:04  | 00-<br>E0-<br>4D-<br>A3-<br>47-<br>AD@BF<br>EBFBF<br>F0003<br>06A9@<br>2211V<br>6503c<br>62040<br>6 | 否 |  |
| 1547 | 福建省美厚建设有限公司  | 2024-04-23 14:45:51.0 | 6C-<br>4B-<br>90-<br>F6-<br>89-<br>36,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>20202<br>02020<br>20202<br>02020<br>36203<br>83033<br>56334<br>a534d<br>,8CE3<br>_8E04<br>_0063<br>_ADA5<br>. | 否 | 2024-04-23 10:19:34.0 | 6C-<br>4B-<br>90-<br>F6-<br>89-<br>36,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>20202<br>02020<br>20202<br>02020<br>36203<br>83033<br>56334<br>a534d<br>,8CE3<br>_8E04<br>_0063<br>_ADA5<br>. | 否 |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:41:16 | 6C-<br>4B-<br>90-<br>F6-<br>89-<br>36,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>20202<br>02020<br>20202<br>02020<br>36203<br>83033<br>56334<br>a534d<br>,8CE3<br>_8E04<br>_0063<br>_ADA5<br>. | 否   |   |  |



|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1550 | 福建省百城建设工程有限公司 | 2024-04-23 17:27:33.0 | D8-43-AE-61-79-0F@BF EBFBF F0009 0675@E823_8FA6_BF53_0001_001B_448B_4CA8_7EC2. | 否 | 2024-04-23 17:24:56.0 | D8-43-AE-61-79-0F@BF EBFBF F0009 0675@E823_8FA6_BF53_0001_001B_448B_4CA8_7EC2. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:10 | D8-43-AE-61-79-0F@BF EBFBF F0009 0675@E823_8FA6_BF53_0001_001B_448B_4CA8_7EC2. | 否 |  |
| 1551 | 福建省旺泰建设工程有限公司 | 2024-04-23 18:20:25.0 | D8-5E-D3-AB-83-1D@BF EBFBF F0009 06EA@MX_20 06266 175, W 9ACYG GW              | 否 | 2024-04-23 15:08:05.0 | D8-5E-D3-AB-83-1D@BF EBFBF F0009 06EA@MX_20 06266 175, W 9ACYG GW              | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:40 | D8-5E-D3-AB-83-1D@BF EBFBF F0009 06EA@MX_20 06266 175, W 9ACYG GW              | 否 |  |

|      |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1552 | 福建荣悦建设工程有限公司 | 2024-04-23 09:52:19.0 | 58-11-22-8B-F2-FF@BF<br>EBFBF<br>F000A<br>0653@<br>0000_0000_0000_0000_0026_0000_0000_0000_0000_0000_0000_0000_0026_B738_177C_C3B5.,WD-WCC6Y<br>OUXYE<br>9E | 否 | 2024-04-23 09:50:19.0 | 58-11-22-8B-F2-FF@BF<br>EBFBF<br>F000A<br>0653@<br>0000_0000_0000_0000_0000_0000_0000_0000_0000_0000_0000_0000_0026_B738_177C_C3B5.,WD-WCC6Y<br>OUXYE<br>9E  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:31:33 | 58-11-22-8B-F2-FF@BF<br>EBFBF<br>F000A<br>0653@<br>0000_0000_0000_0000_0000_0000_0000_0000_0000_0000_0000_0000_0026_B738_177C_C3B5.,WD-WCC6Y<br>OUXYE<br>9E | 否 |  |
| 1553 | 福建中梦建设有限公司   | 2024-04-23 17:20:44.0 | 74-56-3C-C2-32-F2@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7382<br>55AD2<br>5   | 否 | 2024-04-23 17:08:27.0 | 00-25-F2-69-56-AD@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36333<br>73038<br>45414<br>33331<br>31202<br>02020<br>,2020<br>20202<br>02020<br>20202<br>02020<br>39573<br>74135<br>42304<br>5 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:33:10 | 74-56-3C-C2-32-F2@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7382<br>55AD2<br>5   | 否 |  |





|      |                   |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |  |  |                            |  |   |  |
|------|-------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|----------------------------|--|---|--|
| 1558 | 福建省开春<br>建筑工程有限公司 | 2024-04-23<br>08:50<br>:23.0 | 30-<br>9C-<br>23-<br>D5-<br>11-<br>80@BF<br>EBFBF<br>F0009<br>06EB@<br>YS221<br>TB38S<br>HVS03<br>43, 50<br>026B7<br>28236<br>AFE4 | 否 | 2024-04-23<br>08:48<br>:07.0 | 30-<br>9C-<br>23-<br>D5-<br>11-<br>80@BF<br>EBFBF<br>F0009<br>06EB@<br>YS221<br>TB38S<br>HVS03<br>43, 50<br>026B7<br>28236<br>AFE4 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>查<br>检 | 2024-04-24<br>08:31<br>:44 | 30-<br>9C-<br>23-<br>D5-<br>11-<br>80@BF<br>EBFBF<br>F0009<br>06EB@<br>YS221<br>TB38S<br>HVS03<br>43, 50<br>026B7<br>28236<br>AFE4 | 否 |  |
| 1559 | 厦门运埕建<br>设有限公司    | 2024-04-20<br>12:24<br>:40.0 | 64-<br>00-<br>6A-<br>20-<br>74-<br>71@BF<br>EBFBF<br>F0003<br>06C3@<br>Z6ER2<br>VQP  | 否 | 2024-04-20<br>12:22<br>:36.0 | 64-<br>00-<br>6A-<br>20-<br>74-<br>71, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>Z6ER2<br>VQP  | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>查<br>检 | 2024-04-24<br>08:31<br>:14 | 64-<br>00-<br>6A-<br>20-<br>74-<br>71@BF<br>EBFBF<br>F0003<br>06C3@<br>Z6ER2<br>VQP  | 否 |  |









|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |             |                     |  |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|-------------|---------------------|--|--|---|--|
| 1564 | 厦门禹正建设工程有限公司   | 2024-04-23 11:44:17.0 | 24-69-8E-F2-4D-4B, 24-69-8E-F2-4D-4B, 00-E0-4D-98-00-FF@BF EBFBF F0001 067A@ 37313 43330 31304 14430 46422 02020 20202 02020 | 否 | 2024-04-23 11:40:44.0 | 24-69-8E-F2-4D-4B, 24-69-8E-F2-4D-4B, 00-E0-4D-98-00-FF@BF EBFBF F0001 067A@ 37313 43330 31304 14430 46422 02020 20202 02020 | 否 |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:34:39 | 24-69-8E-F2-4D-4B, 24-69-8E-F2-4D-4B, 00-E0-4D-98-00-FF@BF EBFBF F0001 067A@ 37313 43330 31304 14430 46422 02020 20202 02020 | 否  |   |  |
| 1565 | 中正启邦(福建)建设有限公司 | 2024-04-23 15:33:50.0 | D8-5E-D3-23-43-06@BF EBFBF F000A 0653@ SN211 10895 8419, WD-WCC6Y 7HVVS 1R   | 否 | 2024-04-23 15:32:48.0 | D8-5E-D3-23-43-06@BF EBFBF F000A 0653@ SN211 10895 8419, WD-WCC6Y 7HVVS 1R   | 否 |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:34:47  | D8-5E-D3-23-43-06@BF EBFBF F000A 0653@ SN211 10895 8419, WD-WCC6Y 7HVVS 1R | 否 |  |





|      |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1569 | 福建洲安建设有限公司    | 2024-04-22 16:53:20.0 | CO-A5-E8-DF-3F-A3, C0-A5-E8-DF-3F-9F, C0-A5-E8-DF-3F-A0, C2-A5-E8-DF-3F-9F@BF EBFBF F0009 06A3@0000_0000_0000_0000_8CE3_8E10_0187_756B. | 否 | 2024-04-22 16:50:20.0 | CO-A5-E8-DF-3F-A0, C2-A5-E8-DF-3F-9F, C0-A5-E8-DF-3F-A3@BF EBFBF F0009 06A3@0000_0000_0000_0000_8CE3_8E10_0187_756B. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:08 | CO-A5-E8-DF-3F-A3, C0-A5-E8-DF-3F-9F, C0-A5-E8-DF-3F-A0, C2-A5-E8-DF-3F-9F@BF EBFBF F0009 06A3@0000_0000_0000_0000_8CE3_8E10_0187_756B. | 否 |  |
| 1570 | 福建省迪腾建设发展有限公司 | 2024-04-23 08:29:20.0 | A8-5E-45-9F-17-AE@BF EBFBF F0009 06EB@WD-WCC6Y 5CZ0A TU, 50 026B7 38087 F2CD  | 否 | 2024-04-23 08:28:11.0 | A8-5E-45-9F-17-AE@BF EBFBF F0009 06EB@WD-WCC6Y 5CZ0A TU, 50 026B7 38087 F2CD   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:34 | A8-5E-45-9F-17-AE@BF EBFBF F0009 06EB@WD-WCC6Y 5CZ0A TU, 50 026B7 38087 F2CD  | 否 |  |

|      |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1571 | 福建旺盛硕建设工程有限公司 | 2024-04-23 16:00:53.0 | 04-7C-16-EC-9D-44@BFEBFBFF00090675@MG230667282221                   | 否 | 2024-04-23 15:56:33.0 | 04-7C-16-EC-9D-44@BFEBFBFF00090675@MG230667282221                        | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:42:33 | 04-7C-16-EC-9D-44@BFEBFBFF00090675@MG230667282221                        | 否 |  |
| 1572 | 福建龙舜建设工程有限公司  | 2024-04-23 17:35:40.0 | D8-5E-D3-7C-9A-A0@BFEBFBFF000A0653@CM173BH1704621                   | 否 | 2024-04-23 17:33:37.0 | D8-5E-D3-7C-9A-A0@BFEBFBFF000A0653@CM173BH1704621                        | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:54 | 00-E0-70-B8-A9-6B@BFEBFBFF000906EA@CVLY73510HZB180C,WD-WCC6Y5FTXE04      | 否 |  |
| 1573 | 福建熠星建设有限公司    | 2024-04-22 12:41:59.0 | B8-97-5A-85-33-F8@BFEBFBFF000306C3@50026B77530C5E82,WD-WCC3F5ZYEN01 | 否 | 2024-04-19 15:40:49.0 | A8-A1-59-BB-F2-DC@BFEBFBFF000A0653@YS202010000245A24600,WD-WCC6Y2ZS2L LD | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:07 | A8-A1-59-BB-F2-DC@BFEBFBFF000A0653@YS202010000245A24600,WD-WCC6Y2ZS2L LD | 否 |  |





|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|---|--|
| 1576 | 福建省湛卢建设工程有限公司 | 2024-04-22 12:03:11.0 | D8-5E-D3-28-86-6C@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_153B_9425. | 否 | 2024-04-22 12:01:18.0 | D8-5E-D3-28-86-6C@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_153B_9425. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:51 | D8-5E-D3-28-86-6C@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_153B_9425. | 否   |   |  |
| 1577 | 湖南省湘钧建设有限公司   | 2024-04-23 16:42:15.0 | 74-56-3C-A9-9D-7B@BFEBFBFF00090675@0025_38A6_21B0_6BC7.                     | 否 | 2024-04-23 16:40:15.0 | 74-56-3C-A9-9D-7B@BFEBFBFF00090675@0025_38A6_21B0_6BC7.                     | 否 |  |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:33:10   | 74-56-3C-A9-9D-7B@BFEBFBFF00090675@0025_38A6_21B0_6BC7. | 否 |  |



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1580 | 福建晨涛建设发展有限公司 | 2024-04-23 16:46:59.0 | 00-<br>E0-<br>4F-<br>09-<br>43-<br>3D@BF<br>EBFBF<br>F0002<br>06D7@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0027.     | 否 | 2024-04-23 16:42:53.0 | 00-<br>E0-<br>4F-<br>09-<br>43-<br>3D@BF<br>EBFBF<br>F0002<br>06D7@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0027.              | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:49 | 00-<br>E0-<br>4F-<br>09-<br>43-<br>3D@BF<br>EBFBF<br>F0002<br>06D7@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0027.     | 否 |  |
| 1581 | 鑫海建工集团有限公司   | 2024-04-23 14:27:15.0 | 58-<br>11-<br>22-<br>45-<br>8E-<br>34@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4UEJ3<br>K3, WD<br>-<br>WCC6Z<br>6PSJX<br>VC, 30<br>08154<br>3505 | 否 | 2024-04-23 10:28:04.0 | 58-<br>11-<br>22-<br>45-<br>8E-<br>34@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4UEJ3<br>K3, WD<br>-<br>WCC6Z<br>6PSJX<br>VC, 30<br>08154<br>3505 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:21 | 58-<br>11-<br>22-<br>45-<br>8E-<br>34@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4UEJ3<br>K3, WD<br>-<br>WCC6Z<br>6PSJX<br>VC, 30<br>08154<br>3505 | 否 |  |

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1582 | 福建鸿鑫水电建筑工程有限公司 | 2024-04-16 10:35:05.0 | 04-D9-F5-32-E0-C4@BF<br>EBFBF<br>F0009<br>06EA@<br>RZ197<br>21036<br>A0899<br>, WD-<br>WMC6Y<br>OF1RK<br>E5 | 否 | 2024-04-16 10:33:30.0 | 04-D9-F5-32-E0-C4@BF<br>EBFBF<br>F0009<br>06EA@<br>RZ197<br>21036<br>A0899<br>, WD-<br>WMC6Y<br>OF1RK<br>E5 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:41:16 | 04-D9-F5-32-E0-C4@BF<br>EBFBF<br>F0009<br>06EA@<br>RZ197<br>21036<br>A0899<br>, WD-<br>WMC6Y<br>OF1RK<br>E5 | 否 |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|



|      |                   |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |  |                            |                            |   |   |  |
|------|-------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|---|--|
| 1584 | 福建省松来<br>建设工程有限公司 | 2024-04-22<br>10:04<br>:45.0 | 58-<br>11-<br>22-<br>0C-<br>E9-<br>90@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4B81_<br>A48E. | 否 | 2024-04-22<br>08:53<br>:40.0 | 58-<br>11-<br>22-<br>0C-<br>E9-<br>90@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4B81_<br>A48E. | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:43<br>:49 | 58-<br>11-<br>22-<br>0C-<br>E9-<br>90@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4B81_<br>A48E. | 否 |  |
| 1585 | 漳平市恒荣<br>建筑工程有限公司 | 2024-04-23<br>14:51<br>:49.0 | 18-<br>C0-<br>4D-<br>55-<br>DA-<br>C9@17<br>8BFBF<br>F0081<br>0F81@<br>AA234<br>4627,<br>WD-<br>WCC6Y<br>7EV5J<br>6E                        | 否 | 2024-04-23<br>14:50<br>:46.0 | 18-<br>C0-<br>4D-<br>55-<br>DA-<br>C9@17<br>8BFBF<br>F0081<br>0F81@<br>AA234<br>4627,<br>WD-<br>WCC6Y<br>7EV5J<br>6E                        | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:34<br>:07 | 18-<br>C0-<br>4D-<br>55-<br>DA-<br>C9@17<br>8BFBF<br>F0081<br>0F81@<br>AA234<br>4627,<br>WD-<br>WCC6Y<br>7EV5J<br>6E                        | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1586 | 福建隆创建筑工程有限公司 | 2024-04-23 11:33:59.0 | FC-34-97-BF-7A-1A@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>02153<br>, WD-<br>WCC2E<br>ZR004<br>69    | 否 | 2024-04-23 11:31:32.0 | FC-34-97-BF-7A-1A@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>02153<br>, WD-<br>WCC2E<br>ZR004<br>69    | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:36:22 | FC-34-97-BF-7A-1A@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>02153<br>, WD-<br>WCC2E<br>ZR004<br>69    | 否 |  |
| 1587 | 福建富广建设发展有限公司 | 2024-04-23 14:45:34.0 | 74-56-3C-F6-1F-49@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>25B2_<br>6085. | 否 | 2024-04-23 14:43:48.0 | 74-56-3C-F6-1F-49@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>25B2_<br>6085. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:47:19 | 74-56-3C-F6-1F-49@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>25B2_<br>6085. | 否 |  |







|      |                 |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1591 | 锐胜达（平潭）建设工程有限公司 | 2024-04-23 11:16:31.0 | 74-56-3C-9C-D1-12@BF<br>EBFBF<br>F000A<br>0653@<br>20201<br>21103<br>390, W<br>D-<br>WCC6Y<br>5VT70<br>8D | 否 | 2024-04-23 11:13:18.0 | 74-56-3C-9C-D1-12@BF<br>EBFBF<br>F000A<br>0653@<br>20201<br>21103<br>390, W<br>D-<br>WCC6Y<br>5VT70<br>8D | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:40:48 | 74-56-3C-9C-D1-12@BF<br>EBFBF<br>F000A<br>0653@<br>20201<br>21103<br>390, W<br>D-<br>WCC6Y<br>5VT70<br>8D | 否 |  |
| 1592 | 福建武夷闽瑞建设发展有限公司  | 2024-04-23 08:58:32.0 | D8-5E-D3-69-7C-7F@BF<br>EBFBF<br>F000A<br>0653@<br>Z9A2C<br>QXC, Y<br>S2020<br>10000<br>24531<br>800      | 否 | 2024-04-23 08:57:22.0 | D8-5E-D3-69-7C-7F@BF<br>EBFBF<br>F000A<br>0653@<br>Z9A2C<br>QXC, Y<br>S2020<br>10000<br>24531<br>800      | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:39:50 | D8-5E-D3-69-7C-7F@BF<br>EBFBF<br>F000A<br>0653@<br>Z9A2C<br>QXC, Y<br>S2020<br>10000<br>24531<br>800      | 否 |  |



|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1595 | 福建诚兴建筑工程有限公司   | 2024-04-23 21:53:56.0 | FC-AA-14-E2-85-34@178BFBF F00600F20@LF30732003322                                     | 否 | 2024-04-23 21:52:27.0 | FC-AA-14-E2-85-34@178BFBF F00600F20@LF30732003322                                     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:17 | FC-AA-14-E2-85-34@178BFBF F00600F20@LF30732003322                                     | 否 |  |
| 1596 | 福建众鑫汇筑建设工程有限公司 | 2024-04-23 11:48:31.0 | 34-97-F6-88-0F-7B,00-E0-FC-69-4A-A2@BFEBFBFF000506E3@0,S2YNNYAH409288,WD-WCC4N4VZJONK | 否 | 2024-04-23 11:47:11.0 | 34-97-F6-88-0F-7B,00-E0-FC-69-4A-A2@BFEBFBFF000506E3@0,S2YNNYAH409288,WD-WCC4N4VZJONK | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:12 | 34-97-F6-88-0F-7B,00-E0-FC-69-4A-A2@BFEBFBFF000506E3@0,S2YNNYAH409288,WD-WCC4N4VZJONK | 否 |  |





|      |                         |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                              |                                |  |  |   |  |
|------|-------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------------|--------------------------------|--|--|---|--|
| 1600 | 福建永发胜<br>建设工程发<br>展有限公司 | 2024-<br>04-22<br>16:57<br>:14.0 | 58-<br>11-<br>22-<br>9E-<br>C7-<br>AB@BF<br>EBFBF<br>F0009<br>0675@<br>30091<br>67322<br>6   | 否 | 2024-<br>04-22<br>16:53<br>:22.0 | 58-<br>11-<br>22-<br>9E-<br>C7-<br>AB@BF<br>EBFBF<br>F0009<br>0675@<br>30091<br>67322<br>6   | 否 |  |  |  |  |  |  |  |  |  |                              | 校验<br>数据<br>有<br>误<br>请<br>查   | 2024-<br>04-24<br>08:43<br>:20   | 58-<br>11-<br>22-<br>9E-<br>C7-<br>AB@BF<br>EBFBF<br>F0009<br>0675@<br>30091<br>67322<br>6 | 否 |  |
| 1601 | 三明市高森<br>建筑有限公<br>司     | 2024-<br>04-23<br>15:09<br>:08.0 | 24-<br>4B-<br>FE-<br>CE-<br>72-<br>69@BF<br>EBFBF<br>F000A<br>0653@<br>41543<br>03231<br>41333<br>83830<br>30423<br>03220<br>37202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>35595<br>24844<br>36584<br>b | 否 | 2024-<br>04-23<br>15:04<br>:41.0 | 24-<br>4B-<br>FE-<br>CE-<br>72-<br>69@BF<br>EBFBF<br>F000A<br>0653@<br>41543<br>03231<br>41333<br>83830<br>30423<br>03220<br>37202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>35595<br>24844<br>36584<br>b | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:42<br>:22 | 24-<br>4B-<br>FE-<br>CE-<br>72-<br>69@BF<br>EBFBF<br>F000A<br>0653@<br>41543<br>03231<br>41333<br>83830<br>30423<br>03220<br>37202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>35595<br>24844<br>36584<br>b | 否  |   |  |









|      |                      |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                         |                                |   |   |  |
|------|----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|---|---|--|
|      |                      |                                  | 00-<br>E0@17<br>8BFBF<br>F0063<br>0F01@<br>20202<br>02020<br>20202<br>04357<br>36433<br>65953<br>454a4<br>c3146   |   |                                  | 00-<br>E0@17<br>8BFBF<br>F0063<br>0F01@<br>20202<br>02020<br>20202<br>04357<br>36433<br>65953<br>454a4<br>c3146   |   |  |  |  |  |  |  |  |  |  |  |                         |                                |   |   |  |
| 1606 | 福建三明宏<br>诚建设有限<br>公司 | 2024-<br>04-23<br>15:35<br>:13.0 | 94-<br>C6-<br>91-<br>BB-<br>E2-<br>57@BF<br>EBFBF<br>F0009<br>06EA@<br>ZN11H<br>V25, 5<br>0026B<br>7381A<br>104D6 | 否 | 2024-<br>04-23<br>15:33<br>:00.0 | 94-<br>C6-<br>91-<br>BB-<br>E2-<br>57@BF<br>EBFBF<br>F0009<br>06EA@<br>ZN11H<br>V25, 5<br>0026B<br>7381A<br>104D6 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:33<br>:08 | 94-<br>C6-<br>91-<br>BB-<br>E2-<br>57@BF<br>EBFBF<br>F0009<br>06EA@<br>ZN11H<br>V25, 5<br>0026B<br>7381A<br>104D6 | 否 |  |



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|--|
| 1609 | 福建潭嘉建设发展有限公司 | 2024-04-22 17:03:18.0 | 70-8B-CD-BD-6A-74@BF<br>EBFBF<br>F0003<br>06C3@<br>WD-<br>WCC6Y<br>7VF50<br>KL | 否 | 2024-04-22 15:40:32.0 | 70-8B-CD-BD-6A-74,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>WD-<br>WCC6Y<br>7VF50<br>KL | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:38:10 | 70-8B-CD-BD-6A-74@BF<br>EBFBF<br>F0003<br>06C3@<br>WD-<br>WCC6Y<br>7VF50<br>KL | 否 |  |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|--|



|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 1612 | 福建巨宇建设有限公司    | 2024-04-22 17:56:05.0 | C8-5B-76-30-5D-98@BF EBFBF F0003 06C3@20202 02057 202d4 44357 36433 25a41 50593 6344a | 否 | 2024-04-22 17:28:19.0 | C8-5B-76-30-5D-98@BF EBFBF F0003 06C3@20202 02057 202d4 44357 36433 25a41 50593 6344a | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:07 | C8-5B-76-30-5D-98@BF EBFBF F0003 06C3@20202 02057 202d4 44357 36433 25a41 50593 6344a | 否   |   |  |
| 1613 | 福建省锦兴建设工程有限公司 | 2024-04-23 08:17:42.0 | E8-9C-25-74-D1-0A@BF EBFBF F000A 0653@ CVLT6 23605 18120 GGN, W D- WCC6Y ARPRD DT     | 否 | 2024-04-22 17:17:27.0 | E8-9C-25-74-D1-0A@BF EBFBF F000A 0653@ CVLT6 23605 18120 GGN, W D- WCC6Y ARPRD DT     | 否 |  |  |  |  |  |  |  |  |  |  |             | 校验数据有误，请检查          | 2024-04-24 08:31:16   | E8-9C-25-74-D1-0A@BF EBFBF F000A 0653@ CVLT6 23605 18120 GGN, W D- WCC6Y ARPRD DT | 否 |  |





|  |  |  |   |  |  |   |  |  |  |  |  |  |  |  |  |  |  |  |   |  |  |
|--|--|--|---|--|--|---|--|--|--|--|--|--|--|--|--|--|--|--|---|--|--|
|  |  |  | 00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>02417 |  |  | 00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>02417 |  |  |  |  |  |  |  |  |  |  |  |  | 00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>02417 |  |  |
|--|--|--|---|--|--|---|--|--|--|--|--|--|--|--|--|--|--|--|---|--|--|



|      |               |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |  |                |                        |  |  |   |  |
|------|---------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------|------------------------|--|--|---|--|
|      |               |                          |  |   |                          | 02020<br>20202<br>0  |   |  |  |  |  |  |  |  |  |  |                |                        |  |  |   |  |
| 1616 | 福建芝航建设发展有限公司  | 2024-04-23<br>11:04:06.0 | 3C-<br>7C-<br>3F-<br>27-<br>2F-<br>FB@BF<br>EBFBF<br>F0009<br>06EB@<br>RC20A<br>09870<br>B1599   | 否 | 2024-04-23<br>10:59:39.0 | 3C-<br>7C-<br>3F-<br>27-<br>2F-<br>FB@BF<br>EBFBF<br>F0009<br>06EB@<br>RC20A<br>09870<br>B1599   | 否 |  |  |  |  |  |  |  |  |  |                | 校验数据有<br>误, 请查         | 2024-04-24<br>08:33:33   | 3C-<br>7C-<br>3F-<br>27-<br>2F-<br>FB@BF<br>EBFBF<br>F0009<br>06EB@<br>RC20A<br>09870<br>B1599 | 否 |  |
| 1617 | 福建仕荣达建设工程有限公司 | 2024-04-20<br>15:45:03.0 | E0-<br>D5-<br>5E-<br>B6-<br>36-<br>D2@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>1NHVJ<br>YT, 00<br>00_00<br>00_01<br>00_00<br>00_E4<br>D2_5C<br>C9_D8<br>D6_4F<br>01. | 否 | 2024-04-18<br>11:25:31.0 | E0-<br>D5-<br>5E-<br>B6-<br>36-<br>D2@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>1NHVJ<br>YT, 00<br>00_00<br>00_01<br>00_00<br>00_E4<br>D2_5C<br>C9_D8<br>D6_4F<br>01. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查 | 2024-04-24<br>08:36:17 | E0-<br>D5-<br>5E-<br>B6-<br>36-<br>D2@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>1NHVJ<br>YT, 00<br>00_00<br>00_01<br>00_00<br>00_E4<br>D2_5C<br>C9_D8<br>D6_4F<br>01. | 否  |   |  |

|      |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1618 | 福建盛林建设工程有限公司 | 2024-04-23 09:51:58.0 | 04-92-26-C4-44-1B@BF<br>EBFBF<br>F0009<br>06EB@<br>AA000<br>00000<br>00000<br>00782<br>,WD-<br>WCC4J<br>2DXCF<br>F4  | 否 | 2024-04-23 09:47:14.0 | 04-92-26-C4-44-1B@BF<br>EBFBF<br>F0009<br>06EB@<br>AA000<br>00000<br>00000<br>00782<br>,WD-<br>WCC4J<br>2DXCF<br>F4                                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:33 | 04-92-26-C4-44-1B@BF<br>EBFBF<br>F0009<br>06EB@<br>AA000<br>00000<br>00000<br>00782<br>,WD-<br>WCC4J<br>2DXCF<br>F4  | 否 |  |
| 1619 | 福建昊天建设工程有限公司 | 2024-04-23 15:40:10.0 | E8-9C-25-43-BE-08@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>1X7P5<br>DU,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>E0_4C<br>10_C5<br>7A_80<br>67. | 否 | 2024-04-23 15:25:07.0 | E8-9C-25-43-BE-08@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>1X7P5<br>DU,00<br>00_00<br>00_00<br>00_00<br>00_00<br>E0_4C<br>10_C5<br>7A_80<br>67. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:49:38 | E8-9C-25-43-BE-08@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>1X7P5<br>DU,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>E0_4C<br>10_C5<br>7A_80<br>67. | 否 |  |





|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
|      |               |                       | 0202020200   |   |                       | 0202020200   |   |  |  |  |  |  |  |  |  |  |  |              | 0202020200          |  |   |  |
| 1623 | 福建省涵盛建筑工程有限公司 | 2024-04-23 18:44:05.0 | 18-C0-4D-47-4D-06@BF EBFBF F000A 0653@SN203 90894 8566, WD-WCC6Y 2PUL3 FU    | 否 | 2024-04-23 18:41:54.0 | 18-C0-4D-47-4D-06@BF EBFBF F000A 0653@SN203 90894 8566, WD-WCC6Y 2PUL3 FU    | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:18 | 18-C0-4D-47-4D-06@BF EBFBF F000A 0653@SN203 90894 8566, WD-WCC6Y 2PUL3 FU    | 否 |  |
| 1624 | 福建省梁川建设工程有限公司 | 2024-04-23 11:02:20.0 | 00-E0-4C-61-53-7C@BF EBFBF F000A 0653@WD-WCC6Y 3VTCV VF, 50 026B7 784AD 48BB | 否 | 2024-04-23 09:45:17.0 | 00-E0-4C-61-53-7C@BF EBFBF F000A 0653@WD-WCC6Y 3VTCV VF, 50 026B7 784AD 48BB | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:47 | 00-E0-4C-61-53-7C@BF EBFBF F000A 0653@WD-WCC6Y 3VTCV VF, 50 026B7 784AD 48BB | 否 |  |





|      |                      |                              |   |   |                              |  |   |  |  |  |  |  |  |  |  |  |                            |                            |  |   |  |
|------|----------------------|------------------------------|---|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|--|---|--|
| 1627 | 福建鑫弘康<br>建设工程有限公司    | 2024-04-23<br>13:26<br>:24.0 | B4-<br>2E-<br>99-<br>5E-<br>B0-<br>EA, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>20190<br>70508<br>318 | 否 | 2024-04-23<br>13:23<br>:21.0 | B4-<br>2E-<br>99-<br>5E-<br>B0-<br>EA, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>20190<br>70508<br>318 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:34<br>:39 | B4-<br>2E-<br>99-<br>5E-<br>B0-<br>EA, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>20190<br>70508<br>318 | 否 |  |
| 1628 | 四川上乙建<br>筑工程有限<br>公司 | 2024-04-23<br>18:37<br>:45.0 | 90-<br>6F-<br>18-<br>03-<br>80-<br>11@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C16_<br>1173_<br>9669.                     | 否 | 2024-04-23<br>18:34<br>:24.0 | 90-<br>6F-<br>18-<br>03-<br>80-<br>11@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C16_<br>1173_<br>9669.              | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:45<br>:43 | 90-<br>6F-<br>18-<br>03-<br>80-<br>11@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C16_<br>1173_<br>9669.              | 否 |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1629 | 福建广盈达建设有限公司   | 2024-04-23 10:35:30.0 | 18-C0-4D-DE-DD-62@BF EBFBF F0009 06EA@50026 B7380 DEB295  | 否 | 2024-04-23 10:33:05.0 | 18-C0-4D-DE-DD-62@BF EBFBF F0009 06EA@50026 B7380 DEB295  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:40:33 | 18-C0-4D-DE-DD-62@BF EBFBF F0009 06EA@50026 B7380 DEB295   | 否 |  |
| 1630 | 福建省中新建设发展有限公司 | 2024-04-22 09:38:05.0 | A4-AE-12-27-14-1B, 28-39-26-D7-E6-B9, 2A-39-26-D7-E6-B9, AA-39-26-D7-E6-B9, 28-39-26-D7-E6-BA@BF EBFBF F0009 06EB@ZN1E3 DEZ | 否 | 2024-04-22 09:36:57.0 | A4-AE-12-27-14-1B, 28-39-26-D7-E6-B9, 2A-39-26-D7-E6-B9, AA-39-26-D7-E6-B9, 28-39-26-D7-E6-BA@BF EBFBF F0009 06EB@ZN1E3 DEZ | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:41:49 | A4-AE-12-27-14-1B, 28-39-26-D7-E6-B9, 28-39-26-D7-E6-B9, AA-39-26-D7-E6-B9@BF EBFBF F0009 06EB@ZN1E3 DEZ | 否 |  |

|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1631 | 福建炬荣建设工程有限公司  | 2024-04-23 16:48:37.0 | 08-BF-B8-04-54-18@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 48AE_ D157. | 否 | 2024-04-23 16:36:51.0 | 08-BF-B8-04-54-18@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 48AE_ D157. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:07 | 08-BF-B8-04-54-18@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 48AE_ D157. | 否 |  |
| 1632 | 福建省权祁建设发展有限公司 | 2024-04-23 09:45:06.0 | D8-5E-D3-49-13-54@BF EBFBF F0009 0675@ 22202 2A02D AE                                  | 否 | 2024-04-22 17:02:46.0 | D8-5E-D3-49-13-54@BF EBFBF F0009 0675@ 22202 2A02D AE                                  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:36:52 | D8-5E-D3-49-13-54,00-00-00-00-00@BF EBFBF F0009 0675@ 22202 2A02D AE                   | 否 |  |







|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1637 | 福建源榕交通工程有限公司 | 2024-04-23 11:02:06.0 | 00-E0-1B-97-E0-3A@BF EBFBF F0009 0675@ 0000_ 0006_ 2304_ 0041_ 3A5A_ 2703_ EE00_ 09E8.                   | 否 | 2024-04-23 11:00:39.0 | 00-E0-1B-97-E0-3A@BF EBFBF F0009 0675@ 0000_ 0006_ 2304_ 0041_ 3A5A_ 2703_ EE00_ 09E8.                   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:51 | 00-E0-1B-97-E0-3A@BF EBFBF F0009 0675@ 0000_ 0006_ 2304_ 0041_ 3A5A_ 2703_ EE00_ 09E8.                   | 否 |  |
| 1638 | 福建春龙建设工程有限公司 | 2024-04-23 10:02:02.0 | 74-56-3C-A5-BB-75@BF EBFBF F0009 0672@ WW61F 4PE, 0 000_0 000_0 000_0 000_0 000_0 026_B 728_3 16E_3 565. | 否 | 2024-04-23 10:01:03.0 | 74-56-3C-A5-BB-75@BF EBFBF F0009 0672@ WW61F 4PE, 0 000_0 000_0 000_0 000_0 000_0 026_B 728_3 16E_3 565. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:52 | 74-56-3C-A5-BB-75@BF EBFBF F0009 0672@ WW61F 4PE, 0 000_0 000_0 000_0 000_0 000_0 026_B 728_3 16E_3 565. | 否 |  |





|      |                   |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |  |  |   |  |
|------|-------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|--|---|--|
|      |                   |                                  | F0009<br>06E9@<br>17428<br>88065<br>13, 50<br>026B7<br>381EC<br>9F96,<br>YS222<br>5609R<br>TGI10<br>18   |   |                                  | F0009<br>06E9@<br>17428<br>88065<br>13, 50<br>026B7<br>381EC<br>9F96,<br>YS222<br>5609R<br>TGI10<br>18   |   |  |  |  |  |  |  |  |  |  |  | F0009<br>06E9@<br>17428<br>88065<br>13, 50<br>026B7<br>381EC<br>9F96,<br>YS222<br>5609R<br>TGI10<br>18 |  |   |  |
| 1642 | 福建省欣萱<br>建设工程有限公司 | 2024-<br>04-23<br>14:25<br>:28.0 | 08-<br>BF-<br>B8-<br>9E-<br>72-<br>08@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>P16AR<br>96, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_45<br>40_1F<br>54. | 否 | 2024-<br>04-23<br>14:23<br>:55.0 | 08-<br>BF-<br>B8-<br>9E-<br>72-<br>08@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>P16AR<br>96, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_45<br>40_1F<br>54. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>检<br>查 | 2024-<br>04-24<br>08:34<br>:07   | 08-<br>BF-<br>B8-<br>9E-<br>72-<br>08@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>P16AR<br>96, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_45<br>40_1F<br>54. | 否 |  |



|      |                  |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|------------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1645 | 福建省中鑫源建设工程有限公司   | 2024-04-22 11:13:18.0 | 00-E0-4C-87-3A-60@BFEBFBFF000506E3@0026_B768_6657_FB05.   | 否 | 2024-04-22 11:12:30.0 | 00-E0-4C-87-3A-60@BFEBFBFF000506E3@0026_B768_6657_FB05.   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:32 | 00-E0-4C-87-3A-60@BFEBFBFF000506E3@0026_B768_6657_FB05.   | 否 |  |
| 1646 | 中连鼎中(福建)建设工程有限公司 | 2024-04-23 11:48:51.0 | D8-5E-D3-4B-09-E6,50-2B-73-A5-0C-03,50-2B-73-A5-0C-03@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B778_4BB9_DFE5. | 否 | 2024-04-23 11:44:38.0 | D8-5E-D3-4B-09-E6,50-2B-73-A5-0C-03,50-2B-73-A5-0C-03@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B778_4BB9_DFE5. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:39:02 | D8-5E-D3-4B-09-E6,50-2B-73-A5-0C-03,50-2B-73-A5-0C-03@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B778_4BB9_DFE5. | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1647 | 福建炬瑞建设发展有限公司 | 2024-04-23 11:09:07.0 | 7C-10-C9-D2-BB-34@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>0JRPY<br>N5, 50<br>026B7<br>38124<br>1829 | 否 | 2024-04-23 11:07:36.0 | 7C-10-C9-D2-BB-34@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>0JRPY<br>N5, 50<br>026B7<br>38124<br>1829 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:44 | 7C-10-C9-D2-BB-34@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>0JRPY<br>N5, 50<br>026B7<br>38124<br>1829 | 否 |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|



|      |                       |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                        |                                |  |   |  |
|------|-----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------|--------------------------------|--|---|--|
|      |                       |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                        |                                | 53232<br>4a465<br>4  |   |  |
| 1649 | 福建兴旺宇<br>项目管理有<br>限公司 | 2024-<br>04-23<br>16:26<br>:42.0 | F0-<br>2F-<br>74-<br>CC-<br>16-<br>4E@BF<br>EBFBF<br>F0005<br>06E3@<br>30333<br>53035<br>37363<br>03632<br>20322<br>02020<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>31595<br>85a4c<br>4e524<br>b | 否 | 2024-<br>04-23<br>16:23<br>:57.0 | F0-<br>2F-<br>74-<br>CC-<br>16-<br>4E@BF<br>EBFBF<br>F0005<br>06E3@<br>30333<br>53035<br>37363<br>03632<br>20322<br>02020<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>31595<br>85a4c<br>4e524<br>b | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:38<br>:49 | F0-<br>2F-<br>74-<br>CC-<br>16-<br>4E@BF<br>EBFBF<br>F0005<br>06E3@<br>30333<br>53035<br>37363<br>03632<br>20322<br>02020<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>31595<br>85a4c<br>4e524<br>b | 否 |  |
| 1650 | 福建嘉凯建<br>设有限公司        | 2024-<br>04-23<br>15:35<br>:30.0 | B4-<br>2E-<br>99-<br>2B-<br>BF-<br>6F@BF<br>EBFBF<br>F0005<br>06E3@<br>6479_<br>A779_<br>10C0_<br>2543.<br>,WD-<br>WCC6Y<br>9MRP4<br>TE  | 否 | 2024-<br>04-22<br>17:07<br>:17.0 | B4-<br>2E-<br>99-<br>2B-<br>BF-<br>6F@BF<br>EBFBF<br>F0005<br>06E3@<br>6479_<br>A779_<br>10C0_<br>2543.<br>,WD-<br>WCC6Y<br>9MRP4<br>TE  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:57<br>:50 | B4-<br>2E-<br>99-<br>2B-<br>BF-<br>6F@BF<br>EBFBF<br>F0005<br>06E3@<br>6479_<br>A779_<br>10C0_<br>2543.<br>,WD-<br>WCC6Y<br>9MRP4<br>TE  | 否 |  |

|      |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1651 | 福建茂匠建设工程有限公司    | 2024-04-23 16:29:19.0 | 00-E0-4C-0D-B7-97@BF EBFBF F000A 0653@ EAGET 20220 118R0 1796, WD- WCC6Y 3ND9D 8R      | 否 | 2024-04-23 11:26:48.0 | 00-E0-4C-0D-B7-97@BF EBFBF F000A 0653@ EAGET 20220 118R0 1796, WD- WCC6Y 3ND9D 8R      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:34:07 | 00-E0-4C-0D-B7-97@BF EBFBF F000A 0653@ EAGET 20220 118R0 1796, WD- WCC6Y 3ND9D 8R      | 否 |  |
| 1652 | 福建省佳筑景建建筑工程有限公司 | 2024-04-23 16:57:32.0 | 04-7C-16-CD-22-28@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 20C6_ AOA5. | 否 | 2024-04-23 14:32:47.0 | 04-7C-16-CD-22-28@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 20C6_ AOA5. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:35:18 | 04-7C-16-CD-22-28@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 20C6_ AOA5. | 否 |  |







|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1656 | 福建省九松建设工程有限公司 | 2024-04-23 16:21:13.0 | 00-<br>E0-<br>70-<br>A1-<br>A0-<br>3D@BF<br>EBFBF<br>F0005<br>06E3@<br>30353<br>23042<br>36333<br>73138<br>39363<br>23733<br>38202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>75941<br>44553<br>35732<br>39323<br>3 | 否 | 2024-04-23 16:18:43.0 | 00-<br>E0-<br>70-<br>A1-<br>A0-<br>3D@BF<br>EBFBF<br>F0005<br>06E3@<br>30353<br>23042<br>36333<br>73138<br>39363<br>23733<br>38202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>75941<br>44553<br>35732<br>39323<br>3 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:36:04 | 00-<br>E0-<br>70-<br>A1-<br>A0-<br>3D@BF<br>EBFBF<br>F0005<br>06E3@<br>30353<br>23042<br>36333<br>73138<br>39363<br>23733<br>38202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>75941<br>44553<br>35732<br>39323<br>3 | 否 |  |
| 1657 | 贵州高胜工程建设有限公司  | 2024-04-23 15:18:27.0 | 74-<br>56-<br>3C-<br>EB-<br>39-<br>0B@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WC82Y<br>06003<br>60, 2C<br>3E_BF<br>FF_F0<br>00_06<br>E7.  | 否 | 2024-04-23 15:17:56.0 | 74-<br>56-<br>3C-<br>EB-<br>39-<br>0B@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WC82Y<br>06003<br>60, 2C<br>3E_BF<br>FF_F0<br>00_06<br>E7.  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:11 | 74-<br>56-<br>3C-<br>EB-<br>39-<br>0B@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WC82Y<br>06003<br>60, 2C<br>3E_BF<br>FF_F0<br>00_06<br>E7.  | 否 |  |

|      |                 |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                            |                            |  |   |  |
|------|-----------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|--|---|--|
| 1658 | 福建中衡运<br>建设有限公司 | 2024-04-24<br>00:55<br>:10.0 | 00-<br>E0-<br>4C-<br>82-<br>2E-<br>D9@BF<br>EBFBF<br>F000B<br>06F5@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E70_<br>98AC.<br>,0200<br>18060<br>10422<br>13462<br>7 | 否 | 2024-04-24<br>00:54<br>:11.0 | 00-<br>E0-<br>4C-<br>82-<br>2E-<br>D9@BF<br>EBFBF<br>F000B<br>06F5@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E70_<br>98AC.<br>,0200<br>18060<br>10422<br>13462<br>7 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:45<br>:29 | 00-<br>E0-<br>4C-<br>82-<br>2E-<br>D9@BF<br>EBFBF<br>F000B<br>06F5@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E70_<br>98AC.<br>,0200<br>18060<br>10422<br>13462<br>7 | 否 |  |
|------|-----------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|--|---|--|



|      |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1660 | 福建实丰建设有限公司 | 2024-04-22 15:03:43.0 | 1C-1B-0D-28-18-1A@BF EBFBF F0005 06E3@Z9A8G 5AK, ABC223 2106B 9, TA1 6C150 0396                           | 否 | 2024-04-22 14:51:50.0 | 1C-1B-0D-28-18-1A@BF EBFBF F0005 06E3@Z9A8G 5AK, ABC223 2106B 9, TA1 6C150 0396                           | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请查 | 2024-04-24 08:33:38 | 1C-1B-0D-28-18-1A@BF EBFBF F0005 06E3@Z9A8G 5AK, ABC223 2106B 9, TA1 6C150 0396                           | 否 |  |
| 1661 | 福建晟海建工有限公司 | 2024-04-23 14:51:30.0 | F4-B5-20-5C-C5-OE@BF EBFBF F0009 0675@WD-WCC6Y 4X4AL Y7, 00 00_00 00_00 00_00 00_00 26_B7 38_22 38_09 45. | 否 | 2024-04-23 14:49:29.0 | F4-B5-20-5C-C5-OE@BF EBFBF F0009 0675@WD-WCC6Y 4X4AL Y7, 00 00_00 00_00 00_00 00_00 26_B7 38_22 38_09 45. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请查 | 2024-04-24 08:33:50 | F4-B5-20-5C-C5-OE@BF EBFBF F0009 0675@WD-WCC6Y 4X4AL Y7, 00 00_00 00_00 00_00 00_00 26_B7 38_22 38_09 45. | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1662 | 厦门宗顺建筑工程有限公司 | 2024-04-18 17:09:35.0 | 18-C0-4D-34-BC-F6,08-1F-71-32-2C-85,0A-1F-71-32-2C-85@BFEBFBF000A0653@ZN1ED1Y5,202336462814 | 否 | 2024-04-18 17:04:25.0 | 18-C0-4D-34-BC-F6,08-1F-71-32-2C-85,0A-1F-71-32-2C-85@BFEBFBF000A0653@ZN1ED1Y5,202336462814 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:40:10 | 18-C0-4D-34-BC-F6,08-1F-71-32-2C-85,0A-1F-71-32-2C-85@BFEBFBF000A0653@ZN1ED1Y5,202336462814 | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|

|      |                      |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
|------|----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|
| 1663 | 福建广和建<br>设发展有限<br>公司 | 2024-<br>04-22<br>18:42<br>:43.0 | E8-<br>9C-<br>25-<br>43-<br>72-<br>5C@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WX12D<br>93R26<br>DJ, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4E<br>BA_24<br>1A. | 否 | 2024-<br>04-22<br>18:03<br>:00.0 | E8-<br>9C-<br>25-<br>43-<br>72-<br>5C@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WX12D<br>93R26<br>DJ, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4E<br>BA_24<br>1A. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:36<br>:34 | E8-<br>9C-<br>25-<br>43-<br>72-<br>5C@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WX12D<br>93R26<br>DJ, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4E<br>BA_24<br>1A. | 否 |  |
|------|----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|







|      |                        |                                  |   |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                              |                                |   |   |   |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------------|--------------------------------|---|---|---|--|
| 1666 | 福建南平博<br>业建设发展<br>有限公司 | 2024-<br>04-22<br>09:57<br>:33.0 | 00-<br>E2-<br>69-<br>4F-<br>D2-<br>75@BF<br>EBFBF<br>F000A<br>0653@<br>7014W<br>21340<br>4956,<br>WD-<br>WCC6Y<br>3VTH1<br>YL               | 否 | 2024-<br>04-22<br>09:51<br>:28.0 | 00-<br>E2-<br>69-<br>4F-<br>D2-<br>75@BF<br>EBFBF<br>F000A<br>0653@<br>7014W<br>21340<br>4956,<br>WD-<br>WCC6Y<br>3VTH1<br>YL  | 否 |  |  |  |  |  |  |  |  |  |                              | 校验<br>数据<br>有<br>误<br>请<br>查   | 2024-<br>04-24<br>08:32<br>:03  | 00-<br>E2-<br>69-<br>4F-<br>D2-<br>75@BF<br>EBFBF<br>F000A<br>0653@<br>7014W<br>21340<br>4956,<br>WD-<br>WCC6Y<br>3VTH1<br>YL | 否 |  |
| 1667 | 中天众源建<br>设有限公司         | 2024-<br>04-23<br>14:39<br>:41.0 | 3C-<br>7C-<br>3F-<br>1F-<br>7C-<br>F2@BF<br>EBFBF<br>F0009<br>06EA@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>15956<br>44454<br>53231 | 否 | 2024-<br>04-22<br>15:10<br>:12.0 | 3C-<br>7C-<br>3F-<br>1F-<br>7C-<br>F2,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EA@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>15956<br>44454<br>53231 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:31<br>:09 | 3C-<br>7C-<br>3F-<br>1F-<br>7C-<br>F2@BF<br>EBFBF<br>F0009<br>06EA@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>15956<br>44454<br>53231 | 否   |   |  |







|      |                      |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                            |                            |   |   |  |
|------|----------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|---|--|
| 1673 | 中州梦建设<br>集团有限公司      | 2024-04-23<br>15:29<br>:50.0 | A0-<br>36-<br>BC-<br>BE-<br>F5-<br>2E,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E57_<br>3811. | 否 | 2024-04-23<br>15:27<br>:33.0 | A0-<br>36-<br>BC-<br>BE-<br>F5-<br>2E@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E57_<br>3811.          | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:37<br>:29 | A0-<br>36-<br>BC-<br>BE-<br>F5-<br>2E@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E57_<br>3811. | 否 |  |
| 1674 | 福建磊铭建<br>筑工程有限<br>公司 | 2024-04-23<br>11:19<br>:47.0 | F4-<br>B5-<br>20-<br>57-<br>FB-<br>21@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>20EF_<br>C655.                                     | 否 | 2024-04-23<br>11:18<br>:23.0 | F4-<br>B5-<br>20-<br>57-<br>FB-<br>21@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>20EF_<br>C655. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:32<br>:49 | F4-<br>B5-<br>20-<br>52-<br>19-<br>11@BF<br>EBFBF<br>F0009<br>0675@<br>20221<br>10200<br>034  | 否 |  |



|      |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1677 | 福建耀厦建设有限公司 | 2024-04-23 14:51:47.0 | 00-E0-4C-48-62-83@BF EBFBF F000A 0653@ 20210 90303 441  | 否 | 2024-04-23 10:46:13.0 | 00-E0-4C-48-62-83@BF EBFBF F000A 0653@ 20210 90303 441  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:39:10 | 00-E0-4C-48-62-83@BF EBFBF F000A 0653@ 20210 90303 441  | 否 |  |
| 1678 | 福建祥博建设有限公司 | 2024-04-22 18:09:44.0 | 00-CF-E0-52-7A-26, C2 -A5-DD-B9-99-85, C0 -A5-DD-B9-99-85, C0 -A5-DD-B9-99-85@BF EBFBF F0009 06E9@ MG190 10000 00000 41059 , WD- WCC6Y 7XVT4 5X | 否 | 2024-04-22 17:58:01.0 | 00-CF-E0-52-7A-26, C2 -A5-DD-B9-99-85, C0 -A5-DD-B9-99-85, C0 -A5-DD-B9-99-85@BF EBFBF F0009 06E9@ MG190 10000 00000 41059 , WD- WCC6Y 7XVT4 5X | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:39:15 | 00-CF-E0-52-7A-26, C2 -A5-DD-B9-99-85, C0 -A5-DD-B9-99-85, C0 -A5-DD-B9-99-85@BF EBFBF F0009 06E9@ MG190 10000 00000 41059 , WD- WCC6Y 7XVT4 5X | 否 |  |



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1679 | 福建实陆建设集团有限公司 | 2024-04-23 10:21:10.0 | 00-E0-4C-02-20-8B@BF<br>EBFBF<br>F0005<br>06E3@<br>Z9AQR<br>HOV, 2<br>039A7<br>80060<br>1 | 否 | 2024-04-23 10:20:07.0 | 00-E0-4C-02-20-8B@BF<br>EBFBF<br>F0005<br>06E3@<br>Z9AQR<br>HOV, 2<br>039A7<br>80060<br>1 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:51:21 | 00-E0-4C-02-20-8B@BF<br>EBFBF<br>F0005<br>06E3@<br>Z9AQR<br>HOV, 2<br>039A7<br>80060<br>1 | 否 |  |
| 1680 | 福建兴发建设工程有限公司 | 2024-04-23 10:11:26.0 | E8-9C-25-43-B4-A0@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0001.       | 否 | 2024-04-20 19:01:24.0 | E8-9C-25-43-B4-A0@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0001.       | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:48 | E8-9C-25-43-B4-A0@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0001.       | 否 |  |
| 1681 | 洲禾(福建)建筑有限公司 | 2024-04-22 10:01:02.0 | EC-D6-8A-F1-32-7D, D4-84-09-88-FA-E7, D4-84-09-88-FA-E4, D4-84-09-88-FA-E5@BF             | 否 | 2024-04-18 09:51:05.0 | EC-D6-8A-F1-32-7D, D4-84-09-88-FA-E4, D4-84-09-88-FA-E5, D4-84-09-88-FA-E7@BF             | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:47 | EC-D6-8A-F1-32-7D, D4-84-09-88-FA-E7, D4-84-09-88-FA-E4, D4-84-09-88-FA-E5@BF             | 否 |  |

|      |                      |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |  |   |  |  |
|------|----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|---|--|--|
|      |                      |                                  | EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>7RJSU<br>ZA, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_29<br>A9_C4<br>95.   |   |                                  | EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>7RJSU<br>ZA, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_29<br>A9_C4<br>95.   |   |  |  |  |  |  |  |  |  |  |  | EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>7RJSU<br>ZA, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_29<br>A9_C4<br>95.  |   |  |  |
| 1682 | 海环科技集<br>团股份有限<br>公司 | 2024-<br>04-23<br>13:58<br>:19.0 | F4-<br>6B-<br>8C-<br>CD-<br>45-<br>AB, 3C<br>-E9-<br>F7-<br>40-<br>CA-<br>58, 3C<br>-E9-<br>F7-<br>40-<br>CA-<br>54, 3C<br>-E9-<br>F7-<br>40-<br>CA-<br>55, 3E<br>-E9-<br>F7-<br>40-<br>CA-<br>54@BF<br>EBFBF<br>F0009<br>0675@<br>5CD2_<br>E489_<br>21A0_<br>DA24. | 否 | 2024-<br>04-23<br>13:56<br>:56.0 | 3C-<br>E9-<br>F7-<br>40-<br>CA-<br>54, 3C<br>-E9-<br>F7-<br>40-<br>CA-<br>55, 3E<br>-E9-<br>F7-<br>40-<br>CA-<br>54, F4<br>-6B-<br>8C-<br>CD-<br>45-<br>AB, 3C<br>-E9-<br>F7-<br>40-<br>CA-<br>58@BF<br>EBFBF<br>F0009<br>0675@<br>5CD2_<br>E489_<br>21A0_<br>DA24. | 否 |  |  |  |  |  |  |  |  |  |  | F4-<br>6B-<br>8C-<br>CD-<br>45-<br>AB, 3C<br>-E9-<br>F7-<br>40-<br>CA-<br>58, 3C<br>-E9-<br>F7-<br>40-<br>CA-<br>54, 3C<br>-E9-<br>F7-<br>40-<br>CA-<br>54, 3C<br>-E9-<br>F7-<br>40-<br>CA-<br>55, 3E<br>-E9-<br>F7-<br>40-<br>CA-<br>54@BF<br>EBFBF<br>F0009<br>0675@<br>5CD2_<br>E489_<br>21A0_<br>DA24. | 否 |  |  |





|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|--|---|--|
| 1686 | 亿耀（福建）建设有限公司 | 2024-04-17 15:41:12.0 | A0-36-BC-21-FC-E1@BFEBFBFF000A0653@WD-WCC6Y1XFSKAS, AA000000000000481_0000001. | 否 | 2024-04-17 15:40:13.0 | A0-36-BC-21-FC-E1@BFEBFBFF000A0653@WD-WCC6Y1XFSKAS, AA000000000000481_0000001. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:28 | A0-36-BC-21-FC-E1@BFEBFBFF000A0653@WD-WCC6Y1XFSKAS, AA000000000000481_0000001. | 否  |   |  |
| 1687 | 福建百惠顺闽建设有限公司 | 2024-04-23 19:20:49.0 | 18-CO-4D-15-DB-15@BFEBFBFF000906EB@50026B7380923DDF, WD-WCC6Y2ACKSK1           | 否 | 2024-04-23 19:19:55.0 | 18-CO-4D-15-DB-15@BFEBFBFF000906EB@50026B7380923DDF, WD-WCC6Y2ACKSK1           | 否 |  |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:39:11  | 18-CO-4D-15-DB-15@BFEBFBFF000906EB@50026B7380923DDF, WD-WCC6Y2ACKSK1 | 否 |  |









|      |                  |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|------------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1692 | 宁德市精筑装饰设计有限公司    | 2024-04-23 09:58:01.0 | 58-11-22-D9-8F-9E@BFEBFBFF00090675@0000_0000_0000_0000_0026B7381E54_1085. | 否 | 2024-04-22 10:56:47.0 | 58-11-22-D9-8F-9E@BFEBFBFF00090675@0000_0000_0000_0000_0026B7381E54_1085. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:43:09 | 58-11-22-D9-8F-9E@BFEBFBFF00090675@0000_0000_0000_0000_0026B7381E54_1085. | 否 |  |
| 1693 | 福建省邵武市馨宇建筑工程有限公司 | 2024-04-19 17:25:40.0 | 58-11-22-95-46-3A@BFEBFBFF00090675@50026B73816688A8,WD-WCC6Y1RU7VKK       | 否 | 2024-04-19 17:20:02.0 | 58-11-22-95-46-3A@BFEBFBFF00090675@50026B73816688A8,WD-WCC6Y1RU7VKK       | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:47 | 58-11-22-95-46-3A@BFEBFBFF00090675@50026B73816688A8,WD-WCC6Y1RU7VKK       | 否 |  |





|      |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1698 | 福建建恒建设有限公司    | 2024-04-23 15:23:39.0 | 00-E2-69-75-30-71,00-00-00-00-00-00@BF EBFBF F0009 0675@0000_2303_2567_CAF2_5B03_1A00_0068. | 否 | 2024-04-23 15:21:21.0 | 00-E2-69-75-30-71@BF EBFBF F0009 0675@0000_2303_2567_CAF2_5B03_1A00_0068.      | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:11 | 00-E2-69-75-30-71,00-00-00-00-00-00@BF EBFBF F0009 0675@0000_2303_2567_CAF2_5B03_1A00_0068. | 否 |  |
| 1699 | 福建省万水建设工程有限公司 | 2024-04-22 09:43:03.0 | 58-11-22-97-64-2C@BF EBFBF F0009 0672@0000_0000_0000_0000_8CE3_8E03_007D_BOAA.              | 否 | 2024-04-17 09:33:12.0 | 58-11-22-97-64-2C@BF EBFBF F0009 0672@0000_0000_0000_0000_8CE3_8E03_007D_BOAA. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:52 | 58-11-22-97-64-2C@BF EBFBF F0009 0672@0000_0000_0000_0000_8CE3_8E03_007D_BOAA.              | 否 |  |

|      |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |                            |   |  |
|------|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|----------------------------|---|--|
| 1700 | 福建省长鸿建设集团有限公司 | 2024-04-23 11:28:14.0 | F0-A6-54-8E-E0-DO, CC-96-E5-0D-88-46, 00-00-00-00-00, F0-A6-54-8E-E0-CF, F2-A6-54-8E-E0-CF, F6-A6-54-8E-E0-CF@BF EBFBF F0009 0675@0000_0000_0000_0000_0001_00A0_7522_3A1D_2363. | 否 | 2024-04-23 11:26:57.0 | CC-96-E5-0D-88-46, F0-A6-54-8E-E0-CF, F2-A6-54-8E-E0-CF, F6-A6-54-8E-E0-D0@BF EBFBF F0009 0675@0000_0000_0001_00A0_7522_3A1D_2363. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:48:27 | F0-A6-54-8E-E0-DO, CC-96-E5-0D-88-46, 00-00-00-00-00, F0-A6-54-8E-E0-CF, F2-A6-54-8E-E0-CF, F6-A6-54-8E-E0-CF@BF EBFBF F0009 0675@0000_0000_0001_00A0_7522_3A1D_2363. | 否                          |   |  |
| 1701 | 福建省八闽建设工程有限公司 | 2024-04-18 10:52:41.0 | B8-97-5A-C3-E1-97@BF EBFBF  | 否 | 2024-04-18 10:53:33.0 | B8-97-5A-C3-E1-97, 00-00-  | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:38:16   | B8-97-5A-C3-E1-97@BF EBFBF | 否 |  |

|      |               |                       |   |   |   |   |   |  |  |  |  |  |  |  |  |            |                     |   |   |   |  |
|------|---------------|-----------------------|---|---|---|---|---|--|--|--|--|--|--|--|--|------------|---------------------|---|---|---|--|
|      |               |                       | F0003<br>06C3@<br>20202<br>02057<br>202d4<br>44357<br>33433<br>54645<br>43313<br>1324c  |   | 00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>20202<br>02057<br>202d4<br>44357<br>33433<br>54645<br>43313<br>1324c |   |   |  |  |  |  |  |  |  |  |            |                     |   |   |   |  |
| 1702 | 河南省齐诚建设集团有限公司 | 2024-04-23 08:53:14.0 | 00-<br>E0-<br>1F-<br>4C-<br>04-<br>45@BF<br>EBFBF<br>F0009<br>0675@<br>A5105<br>12Y23<br>37696<br>2   | 否 | 2024-04-23 08:53:17.0   | 00-<br>E0-<br>1F-<br>4C-<br>04-<br>45@BF<br>EBFBF<br>F0009<br>0675@<br>A5105<br>12Y23<br>37696<br>2   | 否 |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:45:44   | 00-<br>E0-<br>1F-<br>4C-<br>04-<br>45@BF<br>EBFBF<br>F0009<br>0675@<br>A5105<br>12Y23<br>37696<br>2 | 否 |  |
| 1703 | 福建志海建设有限公司    | 2024-04-23 10:32:12.0 | 58-<br>11-<br>22-<br>97-<br>DA-<br>59@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>5F7B_<br>1A15. | 否 | 2024-04-23 10:09:23.0   | 58-<br>11-<br>22-<br>97-<br>DA-<br>59@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>5F7B_<br>1A15. | 否 |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:37:50 | 58-<br>11-<br>22-<br>97-<br>DA-<br>59@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>5F7B_<br>1A15. | 否   |   |  |









|      |                        |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                         |                                |   |   |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|---|---|--|
| 1709 | 福建省隆亚<br>景建设发展<br>有限公司 | 2024-<br>04-23<br>17:32<br>:56.0 | 04-<br>D4-<br>C4-<br>8E-<br>DD-<br>AE@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>5ALRO<br>YX, 19<br>37B08<br>06734  | 否 | 2024-<br>04-23<br>16:31<br>:13.0 | 04-<br>D4-<br>C4-<br>8E-<br>DD-<br>AE@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>5ALRO<br>YX, 19<br>37B08<br>06734  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:40<br>:32 | 04-<br>D4-<br>C4-<br>8E-<br>DD-<br>AE@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>5ALRO<br>YX, 19<br>37B08<br>06734  | 否 |  |
| 1710 | 福建省泷锐<br>建设工程有限公司      | 2024-<br>04-22<br>12:48<br>:07.0 | 10-<br>3D-<br>0A-<br>DF-<br>42-<br>08, 00<br>-E0-<br>70-<br>A2-<br>BC-<br>1E@BF<br>EBFBF<br>F0009<br>06EB@<br>0025_<br>3887_<br>01B8_<br>BCD8.<br>, WD-<br>WX32A<br>7070P<br>7Z | 否 | 2024-<br>04-22<br>12:44<br>:35.0 | 00-<br>E0-<br>70-<br>A2-<br>BC-<br>1E, 10<br>-3D-<br>0A-<br>DF-<br>42-<br>08@BF<br>EBFBF<br>F0009<br>06EB@<br>0025_<br>3887_<br>01B8_<br>BCD8.<br>, WD-<br>WX32A<br>7070P<br>7Z | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:35<br>:02 | 10-<br>3D-<br>0A-<br>DF-<br>42-<br>08, 00<br>-E0-<br>70-<br>A2-<br>BC-<br>1E@BF<br>EBFBF<br>F0009<br>06EB@<br>0025_<br>3887_<br>01B8_<br>BCD8.<br>, WD-<br>WX32A<br>7070P<br>7Z | 否 |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1711 | 福建景博腾建设有限公司   | 2024-04-23 10:56:20.0 | D8-43-AE-56-77-F3@BF<br>EBFBF<br>F0009<br>0675@<br>0000_0000_0000_0000_0026_B738_23D9_D465.             | 否 | 2024-04-22 15:54:45.0 | D8-43-AE-56-77-F3@BF<br>EBFBF<br>F0009<br>0675@<br>0000_0000_0000_0000_0026_B738_23D9_D465.             | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:20 | D8-43-AE-56-77-F3@BF<br>EBFBF<br>F0009<br>0675@<br>0000_0000_0000_0000_0026_B738_23D9_D465.             | 否 |  |
| 1712 | 贵州禹鸿工程建设有限公司  | 2024-04-23 19:49:45.0 | D4-5D-64-56-FD-D6@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>98269<br>1                         | 否 | 2024-04-23 19:25:59.0 | D4-5D-64-56-FD-D6@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>98269<br>1                         | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:49 | D4-5D-64-56-FD-D6@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>98269<br>1                         | 否 |  |
| 1713 | 福建宗福建建筑工程有限公司 | 2024-04-23 10:58:06.0 | 50-EB-F6-1B-7C-F2@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7784<br>77A9E<br>6,WD-WCC6Y<br>OJC1R<br>SE | 否 | 2024-04-19 11:00:11.0 | 50-EB-F6-1B-7C-F2@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7784<br>77A9E<br>6,WD-WCC6Y<br>OJC1R<br>SE | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:47 | 50-EB-F6-1B-7C-F2@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7784<br>77A9E<br>6,WD-WCC6Y<br>OJC1R<br>SE | 否 |  |

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1714 | 福建明治建设工程有限公司   | 2024-04-22 15:16:10.0 | 00-E2-69-68-4A-5F@BFEBFBFF00090675@0000_0000_0000_0000_00E0_4C12_E51C_5556. | 否 | 2024-04-22 14:53:24.0 | 00-E2-69-68-4A-5F@BFEBFBFF00090675@0000_0000_0000_0000_00E0_4C12_E51C_5556. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:19 | 00-E2-69-68-4A-5F@BFEBFBFF00090675@0000_0000_0000_0000_00E0_4C12_E51C_5556. | 否 |  |
| 1715 | 福建省恒和鑫建设工程有限公司 | 2024-04-23 15:02:34.0 | 00-E0-4C-1B-04-72@178BFBF00630F01@SCRW20022404G1284                         | 否 | 2024-04-23 15:02:11.0 | 00-E0-4C-1B-04-72,00-00-00-00-00-E0@178BFBF00630F01@SCRW20022404G1284       | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:40:52 | 00-E0-4C-1B-04-72@178BFBF00630F01@SCRW20022404G1284                         | 否 |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1716 | 四川中港建设工程有限公司  | 2024-04-23 17:46:33.0 | C8-7F-54-C9-4F-17@BFEBFBFF00090675@0000_0000_0000_0000_0026_B738_245B_5E85.                 | 否 | 2024-04-23 16:16:23.0 | C8-7F-54-C9-4F-17@BFEBFBFF00090675@0000_0000_0000_0000_0026_B738_245B_5E85.                 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:18 | C8-7F-54-C9-4F-17@BFEBFBFF00090675@0000_0000_0000_0000_0026_B738_245B_5E85.                 | 否 |  |
| 1717 | 福建西正达建设发展有限公司 | 2024-04-22 16:32:12.0 | 58-11-22-99-96-DA@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_448B_4E80_9048.,WD-WCC3F6LDJLUE | 否 | 2024-04-22 16:15:10.0 | 58-11-22-99-96-DA@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_448B_4E80_9048.,WD-WCC3F6LDJLUE | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:07 | 58-11-22-99-96-DA@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_448B_4E80_9048.,WD-WCC3F6LDJLUE | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1718 | 福建昭德建设有限公司   | 2024-04-17 17:03:07.0 | F4-B5-20-52-BC-B5@BF EBFBF F000A 0653@MG230 27000 3294     | 否 | 2024-04-17 16:54:50.0 | F4-B5-20-52-BC-B5@BF EBFBF F000A 0653@MG230 27000 3294     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:41:30 | F4-B5-20-52-BC-B5@BF EBFBF F000A 0653@MG230 27000 3294     | 否 |  |
| 1719 | 安徽宸功环境工程有限公司 | 2024-04-23 10:39:55.0 | 74-56-3C-E6-78-39@BF EBFBF F0009 0675@6479_A784_3ADO_0ACB. | 否 | 2024-04-19 09:19:08.0 | 74-56-3C-E6-78-39@BF EBFBF F0009 0675@6479_A784_3ADO_0ACB. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:53 | 74-56-3C-E6-78-39@BF EBFBF F0009 0675@6479_A784_3ADO_0ACB. | 否 |  |



|      |              |                       |   |   |  |   |   |  |  |  |  |  |  |  |  |  |            |   |   |   |  |
|------|--------------|-----------------------|---|---|--|---|---|--|--|--|--|--|--|--|--|--|------------|---|---|---|--|
|      |              |                       | 82020<br>, 2020<br>20205<br>7202d<br>44435<br>73343<br>46465<br>a3434<br>45314<br>1                               |   | 56473<br>33233<br>30303<br>34359<br>30303<br>03031<br>34353<br>82020<br>, 2020<br>20205<br>7202d<br>44435<br>73343<br>46465<br>a3434<br>45314<br>1 |   |   |  |  |  |  |  |  |  |  |  |            | 82020<br>, 2020<br>20205<br>7202d<br>44435<br>73343<br>46465<br>a3434<br>45314<br>1 |   |   |  |
| 1722 | 福建轩凌建筑工程有限公司 | 2024-04-22 17:32:53.0 | 4C-<br>ED-<br>FB-<br>45-<br>30-<br>B7@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7782<br>1915F<br>9, WBY<br>73FSM | 否 | 2024-04-22 16:08:06.0  | 4C-<br>ED-<br>FB-<br>45-<br>30-<br>B7@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7782<br>1915F<br>9, WBY<br>73FSM | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:02   | 4C-<br>ED-<br>FB-<br>45-<br>30-<br>B7@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7782<br>1915F<br>9, WBY<br>73FSM | 否 |  |







|      |             |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|-------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1726 | 鹏盛建设集团有限公司  | 2024-04-23 17:33:16.0 | 88-AE-DD-46-DD-7E@BF EBFBF F000A 0671@72IAJ MRNS, E823_8FA6_ BF53_ 0001_ 001B_ 448B_ 4B2F_ 4937. | 否 | 2024-04-23 17:27:18.0 | 88-AE-DD-46-DD-7E@BF EBFBF F000A 0671@72IAJ MRNS, E823_8FA6_ BF53_ 0001_ 001B_ 448B_ 4B2F_ 4937. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:37 | 88-AE-DD-46-DD-7E@BF EBFBF F000A 0671@72IAJ MRNS, E823_8FA6_ BF53_ 0001_ 001B_ 448B_ 4B2F_ 4937. | 否 |  |
| 1727 | 福建省安文建工有限公司 | 2024-04-23 16:14:55.0 | 08-BF-B8-A4-F0-10@BF EBFBF F000A 0653@WD-WCC6Y MJ27U 5P, 50 026B7 3822F 47E6                     | 否 | 2024-04-23 16:13:51.0 | 08-BF-B8-A4-F0-10@BF EBFBF F000A 0653@WD-WCC6Y MJ27U 5P, 50 026B7 3822F 47E6                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:15 | 08-BF-B8-A4-F0-10@BF EBFBF F000A 0653@WD-WCC6Y MJ27U 5P, 50 026B7 3822F 47E6                     | 否 |  |





|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1731 | 福建邦顺建筑工程有限公司  | 2024-04-22 17:06:49.0 | 00-<br>E0-<br>4C-<br>10-<br>85-<br>A0@BF<br>EBFBF<br>F0002<br>06D7@<br>41413<br>03030<br>30303<br>03030<br>30303<br>03030<br>30333<br>13336 | 否 | 2024-04-22 17:02:56.0 | 00-<br>E0-<br>4C-<br>10-<br>85-<br>A0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0002<br>06D7@<br>41413<br>03030<br>30303<br>03030<br>30333<br>30303<br>03030<br>30333<br>13336 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:49 | B8-<br>97-<br>5A-<br>A0-<br>A5-<br>3C@BF<br>EBFBF<br>F0003<br>06A9@<br>4c445<br>34437<br>31323<br>23037<br>30323<br>13420<br>20202<br>02020<br>,5720<br>43445<br>22d4d<br>4f532<br>0234e<br>58205<br>a592d<br>2d2d2<br>d | 否 |  |
| 1732 | 福建润创建建设工程有限公司 | 2024-04-23 18:47:36.0 | 04-<br>7C-<br>16-<br>11-<br>67-<br>D3@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4C13_<br>3A15. | 否 | 2024-04-23 18:40:33.0 | 04-<br>7C-<br>16-<br>11-<br>67-<br>D3@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4C13_<br>3A15.   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:42:19 | 04-<br>7C-<br>16-<br>11-<br>67-<br>D3@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4C13_<br>3A15.  | 否 |  |







|      |                   |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                         |                            |  |   |  |
|------|-------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------------------|----------------------------|--|---|--|
| 1736 | 福建丰鑫达<br>建筑工程有限公司 | 2024-04-22<br>16:46<br>:24.0 | 08-<br>BF-<br>B8-<br>31-<br>FB-<br>F8@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>F8JA2<br>SR, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4E<br>03_F7<br>E8. | 否 | 2024-04-22<br>16:37<br>:21.0 | 08-<br>BF-<br>B8-<br>31-<br>FB-<br>F8@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>F8JA2<br>SR, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4E<br>03_F7<br>E8. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:32<br>:55 | 08-<br>BF-<br>B8-<br>31-<br>FB-<br>F8@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>F8JA2<br>SR, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4E<br>03_F7<br>E8. | 否 |  |
| 1737 | 福建省建漳<br>建设工程有限公司 | 2024-04-23<br>10:47<br>:40.0 | D8-<br>5E-<br>D3-<br>7A-<br>6D-<br>65@BF<br>EBFBF<br>F000A<br>0653@<br>22065<br>F8055<br>79, WD<br>-<br>WCC6Y<br>1JZ6D<br>JT   | 否 | 2024-04-23<br>10:20<br>:13.0 | D8-<br>5E-<br>D3-<br>7A-<br>6D-<br>65@BF<br>EBFBF<br>F000A<br>0653@<br>22065<br>F8055<br>79, WD<br>-<br>WCC6Y<br>1JZ6D<br>JT   | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:34<br>:49 | D8-<br>5E-<br>D3-<br>7A-<br>6D-<br>65@BF<br>EBFBF<br>F000A<br>0653@<br>22065<br>F8055<br>79, WD<br>-<br>WCC6Y<br>1JZ6D<br>JT   | 否 |  |



|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1739 | 福建兴洲建设有限公司    | 2024-04-23 21:35:47.0 | D8-BB-C1-5C-A1-CA@BFEBFBFF000A0653@0026_B768_4FB9_3225.                          | 否 | 2024-04-23 21:34:53.0 | D8-BB-C1-5C-A1-CA@BFEBFBFF000A0653@0026_B768_4FB9_3225.                          | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:45:11 | D8-BB-C1-5C-A1-CA@BFEBFBFF000A0653@0026_B768_4FB9_3225.                          | 否 |  |
| 1740 | 福建省冠硕建设工程有限公司 | 2024-04-23 17:01:52.0 | 00-E0-4C-D7-00-4D@BFEBFBFF000906EA@0000_0000_0000_0000_0000_4868_3400_0000_0000. | 否 | 2024-04-23 16:59:48.0 | 00-E0-4C-D7-00-4D@BFEBFBFF000906EA@0000_0000_0000_0000_0000_4868_3400_0000_0000. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:35:40 | 00-E0-4C-D7-00-4D@BFEBFBFF000906EA@0000_0000_0000_0000_0000_4868_3400_0000_0000. | 否 |  |
| 1741 | 玄中(福建)建设有限公司  | 2024-04-23 11:36:34.0 | 70-B5-E8-38-87-9F@BFEBFBFF000906EA@Z9ABA4SA,0100_0000_0000_0000_8CE3_8E04_0106_E | 否 | 2024-04-23 11:34:16.0 | 70-B5-E8-38-87-9F@BFEBFBFF000906EA@Z9ABA4SA,0100_0000_0000_0000_8CE3_8E04_0106_E | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:34:16 | 70-B5-E8-38-87-9F@BFEBFBFF000906EA@Z9ABA4SA,0100_0000_0000_0000_8CE3_8E04_0106_E | 否 |  |













|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1748 | 福建创立建筑工程有限公司 | 2024-04-23 16:19:40.0 | 18-31-BF-B0-83-AD, 00-FF-61-2C-72-5A@BF EBFBF F0009 06EA@S3WBN FOJC5 0810M, 2015 0817A AASTW 00002 8, 77P D13EMS | 否 | 2024-04-23 16:17:56.0 | 18-31-BF-B0-83-AD, 00-FF-61-2C-72-5A@BF EBFBF F0009 06EA@S3WBN FOJC5 0810M, 2015 0817A AASTW 00002 8, 77P D13EMS | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:38:39 | 18-31-BF-B0-83-AD, 00-FF-61-2C-72-5A@BF EBFBF F0009 06EA@S3WBN FOJC5 0810M, 2015 0817A AASTW 00002 8, 77P D13EMS | 否 |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|



















|      |                   |                                  |   |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|------|-------------------|----------------------------------|---|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
|      |                   |                                  | 30323<br>03230<br>31383<br>23231<br>35395<br>04820<br>20202<br>0  |   |                                  | 30323<br>03230<br>31383<br>23231<br>35395<br>04820<br>20202<br>0   |   |  |  |  |  |  |  |  |  |  |                            |                                | 30323<br>03230<br>31383<br>23231<br>35395<br>04820<br>20202<br>0  |   |  |
| 1757 | 光泽县华顺<br>建筑工程有限公司 | 2024-<br>04-22<br>15:33<br>:14.0 | 6C-<br>4B-<br>90-<br>B5-<br>55-<br>B9@BF<br>EBFBF<br>F0009<br>06E9@<br>20202<br>02020<br>02020<br>20202<br>20203<br>95746<br>41383<br>94a38 | 否 | 2024-<br>04-22<br>15:11<br>:30.0 | 6C-<br>4B-<br>90-<br>B5-<br>55-<br>B9,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>20202<br>02020<br>20202<br>20203<br>95746<br>41383<br>94a38 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:31<br>:10 | 6C-<br>4B-<br>90-<br>B5-<br>55-<br>B9@BF<br>EBFBF<br>F0009<br>06E9@<br>20202<br>02020<br>02020<br>20202<br>20203<br>95746<br>41383<br>94a38 | 否 |  |

|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1758 | 福建索芒建设工程有限公司  | 2024-04-23 15:04:54.0 | 74-56-3C-24-22-02, C0-A5-DD-72-62-16, C2-A5-DD-72-62-16@BFEBFBF00090672@E823_8FA6_BF53_0001_001B_448B_4E9E_82BF. | 否 | 2024-04-23 14:38:33.0 | 74-56-3C-24-22-02, C0-A5-DD-72-62-16, C2-A5-DD-72-62-16@BFEBFBF00090672@E823_8FA6_BF53_0001_001B_448B_4E9E_82BF. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:07 | 74-56-3C-24-22-02, C0-A5-DD-72-62-16, C2-A5-DD-72-62-16@BFEBFBF00090672@E823_8FA6_BF53_0001_001B_448B_4E9E_82BF. | 否 |  |
| 1759 | 福建省佳扬建设工程有限公司 | 2024-04-22 16:01:27.0 | E0-3F-49-AF-4A-FA@BFEBFBF000306C3@MG18010000000121398  | 否 | 2024-04-22 15:57:34.0 | E0-3F-49-AF-4A-FA@BFEBFBF000306C3@MG18010000000121398  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:42 | E0-3F-49-AF-4A-FA@BFEBFBF000306C3@MG18010000000121398  | 否 |  |



|      |             |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |   |  |   |  |
|------|-------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---|--|---|--|
|      |             |                       | B8-<br>A2, 18<br>-F2-<br>2C-<br>E1-<br>B8-<br>A2@BF<br>EBFBF<br>F0009<br>06ED@<br>WD-<br>WCC6Y<br>6RJPV<br>AC, SN<br>20380<br>89819<br>37 |   |                       | B8-<br>A2, 18<br>-F2-<br>2C-<br>E1-<br>B8-<br>A2@BF<br>EBFBF<br>F0009<br>06ED@<br>WD-<br>WCC6Y<br>6RJPV<br>AC, SN<br>20380<br>89819<br>37 |   |  |  |  |  |  |  |  |  |  |            | B8-<br>A2, 18<br>-F2-<br>2C-<br>E1-<br>B8-<br>A2@BF<br>EBFBF<br>F0009<br>06ED@<br>WD-<br>WCC6Y<br>6RJPV<br>AC, SN<br>20380<br>89819<br>37 |  |   |  |
| 1762 | 福建省腾顺建设有限公司 | 2024-04-19 11:38:57.0 | 00-<br>E0-<br>4F-<br>0B-<br>9C-<br>D3@BF<br>EBFBF<br>F0002<br>06D7@<br>V6WMH<br>45Z, 0<br>000_0<br>000_0<br>000_0<br>000_0<br>000.        | 否 | 2024-04-19 11:21:27.0 | 00-<br>E0-<br>4F-<br>0B-<br>9C-<br>D3@BF<br>EBFBF<br>F0002<br>06D7@<br>V6WMH<br>45Z, 0<br>000_0<br>000_0<br>000_0<br>000_0<br>000.        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:31:15   | 00-<br>E0-<br>4F-<br>0B-<br>9C-<br>D3@BF<br>EBFBF<br>F0002<br>06D7@<br>V6WMH<br>45Z, 0<br>000_0<br>000_0<br>000_0<br>000_0<br>000. | 否 |  |



|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1765 | 福建江恒建设有限公司 | 2024-04-23 15:46:23.0 | D8-5E-D3-4B-E0-92, 48-8A-D2-99-CE-F2, 48-8A-D2-99-CE-F4, 48-8A-D2-99-CE-F5@BFEBFBFF00090675@0025_38D6_21A0_CC6F. | 否 | 2024-04-22 16:47:56.0 | D8-5E-D3-4B-E0-92, 48-8A-D2-99-CE-F4, 48-8A-D2-99-CE-F5, 48-8A-D2-99-CE-F2@BFEBFBFF00090675@0025_38D6_21A0_CC6F. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:15 | D8-5E-D3-4B-E0-92, 48-8A-D2-99-CE-F2, 48-8A-D2-99-CE-F4, 48-8A-D2-99-CE-F5@BFEBFBFF00090675@0025_38D6_21A0_CC6F. | 否 |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|







|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1769 | 福建九龙江建设工程有限公司 | 2024-04-23 11:19:09.0 | 24-4B-FE-8B-35-28@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>1PYRZ<br>EY, 21<br>0303A<br>00003<br>810  | 否 | 2024-04-23 11:10:14.0 | 24-4B-FE-8B-35-28@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>1PYRZ<br>EY, 21<br>0303A<br>00003<br>810  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:04 | 24-4B-FE-8B-35-28@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>1PYRZ<br>EY, 21<br>0303A<br>00003<br>810  | 否 |  |
| 1770 | 福建融丰祥建设有限公司   | 2024-04-23 18:28:42.0 | 58-11-22-8E-4A-EA@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>178B_<br>9A95.<br>, WD-<br>WCC6Y<br>5VVXD<br>FT | 否 | 2024-04-23 14:12:36.0 | 58-11-22-8E-4A-EA@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>178B_<br>9A95.<br>, WD-<br>WCC6Y<br>5VVXD<br>FT | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:44:27 | 58-11-22-8E-4A-EA@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>178B_<br>9A95.<br>, WD-<br>WCC6Y<br>5VVXD<br>FT | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1771 | 福建博成建筑工程有限公司 | 2024-04-23 15:15:15.0 | FC-34-97-9E-A0-4A@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC2E<br>XY412<br>62, 22<br>175S8<br>04796<br>, WD-<br>WCC6Y<br>5TTN3<br>RS | 否 | 2024-04-23 14:59:03.0 | FC-34-97-9E-A0-4A@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC2E<br>XY412<br>62, 22<br>175S8<br>04796<br>, WD-<br>WCC6Y<br>5TTN3<br>RS | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:36:15 | FC-34-97-9E-A0-4A@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC2E<br>XY412<br>62, 22<br>175S8<br>04796<br>, WD-<br>WCC6Y<br>5TTN3<br>RS | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|





|      |                   |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |                            |                            |   |   |  |
|------|-------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|---|--|
| 1774 | 福建佳广鑫<br>建设工程有限公司 | 2024-04-23<br>16:50<br>:54.0 | 00-<br>E0-<br>4C-<br>DB-<br>C5-<br>1B@BF<br>EBFBF<br>F0003<br>06A9@<br>3J092<br>9E220<br>72 7 | 否 | 2024-04-23<br>15:27<br>:44.0 | 00-<br>E0-<br>4C-<br>DB-<br>C5-<br>1B, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06A9@<br>3J092<br>9E220<br>72 7 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:37<br>:04 | 00-<br>E0-<br>4C-<br>DB-<br>C5-<br>1B@BF<br>EBFBF<br>F0003<br>06A9@<br>3J092<br>9E220<br>72 7 | 否 |  |
|------|-------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|---|--|



|      |                        |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
|------|------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|
| 1776 | 福建南平广<br>得建设发展<br>有限公司 | 2024-<br>04-22<br>16:02<br>:26.0 | A8-<br>A1-<br>59-<br>BC-<br>B2-<br>4B@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>01136                                  | 否 | 2024-<br>04-22<br>15:56<br>:10.0 | A8-<br>A1-<br>59-<br>BC-<br>B2-<br>4B@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>01136                                  | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:43<br>:27 | A8-<br>A1-<br>59-<br>BC-<br>B2-<br>4B@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>01136                                  | 否 |  |
| 1777 | 福建锦泰创<br>建建设工程<br>有限公司 | 2024-<br>04-23<br>10:53<br>:10.0 | 74-<br>56-<br>3C-<br>A5-<br>97-<br>24@BF<br>EBFBF<br>F0009<br>0675@<br>A428_<br>B701_<br>19E0_<br>0041.<br>, WD-<br>WXV2D<br>53EHK<br>U9 | 否 | 2024-<br>04-23<br>10:50<br>:50.0 | 74-<br>56-<br>3C-<br>A5-<br>97-<br>24@BF<br>EBFBF<br>F0009<br>0675@<br>A428_<br>B701_<br>19E0_<br>0041.<br>, WD-<br>WXV2D<br>53EHK<br>U9 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:36<br>:02 | 74-<br>56-<br>3C-<br>A5-<br>97-<br>24@BF<br>EBFBF<br>F0009<br>0675@<br>A428_<br>B701_<br>19E0_<br>0041.<br>, WD-<br>WXV2D<br>53EHK<br>U9 | 否 |  |









|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |             |                     |   |  |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|-------------|---------------------|---|--|---|--|
| 1783 | 福建超胜建设有限公司   | 2024-04-22 12:03:48.0 | 00-<br>E0-<br>3A-<br>68-<br>01-<br>7B@BF<br>EBFBF<br>F0003<br>06E4@<br>OSC19<br>12100<br>00000<br>00327<br>, WD-<br>WMC2E<br>91257<br>81    | 否 | 2024-04-22 11:47:48.0 | 00-<br>E0-<br>3A-<br>68-<br>01-<br>7B@BF<br>EBFBF<br>F0003<br>06E4@<br>OSC19<br>12100<br>00000<br>00327<br>, WD-<br>WMC2E<br>91257<br>81  | 否 |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:33:47   | 00-<br>E0-<br>3A-<br>68-<br>01-<br>7B@BF<br>EBFBF<br>F0003<br>06E4@<br>OSC19<br>12100<br>00000<br>00327<br>, WD-<br>WMC2E<br>91257<br>81 | 否 |  |
| 1784 | 川远建设(福建)有限公司 | 2024-04-23 16:47:25.0 | F0-<br>79-<br>59-<br>6F-<br>45-<br>9B@BF<br>EBFBF<br>F0003<br>06C3@<br>30353<br>23042<br>36333<br>73138<br>44324<br>24536<br>32202<br>02020 | 否 | 2024-04-23 12:00:10.0 | F0-<br>79-<br>59-<br>6F-<br>45-<br>9B, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>30353<br>23042<br>36333<br>73138<br>44324<br>24536<br>32202<br>02020 | 否 |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:35:40 | F0-<br>79-<br>59-<br>6F-<br>45-<br>9B@BF<br>EBFBF<br>F0003<br>06C3@<br>30353<br>23042<br>36333<br>73138<br>44324<br>24536<br>32202<br>02020 | 否  |   |  |

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1785 | 福建武夷海西建设发展有限公司 | 2024-04-23 08:21:41.0 | 00-FF-AE-49-B7-A8, 1C-1B-OD-84-FF-75@BFEBFBFF000306C3@30013897081, WD-WCC6Y5JLZF94                              | 否 | 2024-04-23 08:20:06.0 | 00-FF-AE-49-B7-A8, 1C-1B-OD-84-FF-75@BFEBFBFF000306C3@30013897081, WD-WCC6Y5JLZF94                              | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:10 | 00-FF-AE-49-B7-A8, 1C-1B-OD-84-FF-75@BFEBFBFF000306C3@30013897081, WD-WCC6Y5JLZF94                              | 否 |  |
| 1786 | 福建森宇丰建设工程有限公司  | 2024-04-22 17:18:24.0 | A0-36-BC-0A-75-9F, 00-FF-D5-69-AC-9F@BFEBFBFF000A0653@0000_0006_2209_0015_3A5A_2703_A000_04A4., WD-WX32D1257T1D | 否 | 2024-04-22 17:16:12.0 | 00-FF-D5-69-AC-9F, A0-36-BC-0A-75-9F@BFEBFBFF000A0653@0000_0006_2209_0015_3A5A_2703_A000_04A4., WD-WX32D1257T1D | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:36:45 | A0-36-BC-0A-75-9F, 00-FF-D5-69-AC-9F@BFEBFBFF000A0653@0000_0006_2209_0015_3A5A_2703_A000_04A4., WD-WX32D1257T1D | 否 |  |



|      |                   |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|-------------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1789 | 福建省航利水利水电建筑工程有限公司 | 2024-04-17 10:51:52.0 | 74-56-3C-77-8F-78@BF EBFBF F000B 06F2@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E39_ 05E1. | 否 | 2024-04-17 10:50:47.0 | 74-56-3C-77-8F-78@BF EBFBF F000B 06F2@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E39_ 05E1.            | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:42:02 | 74-56-3C-77-8F-78@BF EBFBF F000B 06F2@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4E39_ 05E1. | 否 |  |
| 1790 | 岳鸿建设发展有限公司        | 2024-04-22 10:39:47.0 | 4C-ED-FB-6A-D0-56,00 -00-00-00-00-00-56@BF EBFBF F0009 06E9@ 18283 88054 29            | 否 | 2024-04-22 10:23:02.0 | 4C-ED-FB-6A-D0-56,00 -00-00-00-00-00-E0,00 -00-00-00-00-00-E0@BF EBFBF F0009 06E9@ 18283 88054 29 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:32 | 4C-ED-FB-6A-D0-56@BF EBFBF F0009 06E9@ 18283 88054 29                                  | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |            |                     |   |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|------------|---------------------|---|---|---|--|
| 1791 | 福建台宏景观工程有限公司 | 2024-04-23 14:06:35.0 | 00-<br>CF-<br>E0-<br>3D-<br>93-<br>D1@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7382<br>0B461<br>4   | 否 | 2024-04-23 11:55:26.0 | 00-<br>CF-<br>E0-<br>3D-<br>93-<br>D1@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7382<br>0B461<br>4   | 否 |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:35:44   | 00-<br>CF-<br>E0-<br>3D-<br>93-<br>D1@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7382<br>0B461<br>4 | 否 |  |
| 1792 | 福建格拓建设工程有限公司 | 2024-04-23 18:36:55.0 | 74-<br>56-<br>3C-<br>91-<br>95-<br>44@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WX12D<br>81R45<br>SJ,00<br>00_00<br>00_00<br>00_00<br>00_8C<br>E3_8E<br>03_00<br>6C_89<br>37. | 否 | 2024-04-23 18:34:55.0 | 74-<br>56-<br>3C-<br>91-<br>95-<br>44@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WX12D<br>81R45<br>SJ,00<br>00_00<br>00_00<br>00_00<br>00_8C<br>E3_8E<br>03_00<br>6C_89<br>37. | 否 |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:31:48 | 74-<br>56-<br>3C-<br>91-<br>95-<br>44@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WX12D<br>81R45<br>SJ,00<br>00_00<br>00_00<br>00_00<br>00_8C<br>E3_8E<br>03_00<br>6C_89<br>37. | 否   |   |  |



|      |                      |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                             |                                |  |   |  |
|------|----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|-----------------------------|--------------------------------|--|---|--|
| 1793 | 福建省最佳<br>远建筑有限<br>公司 | 2024-<br>04-22<br>17:19<br>:40.0 | 00-<br>E2-<br>69-<br>6B-<br>A1-<br>35@BF<br>EBFBF<br>F0009<br>0675@<br>2C3E_<br>BFFF_<br>F000_<br>0215.<br>, WD-<br>WCC2E<br>AK144<br>57 | 否 | 2024-<br>04-22<br>17:16<br>:32.0 | 00-<br>E2-<br>69-<br>6B-<br>A1-<br>35@BF<br>EBFBF<br>F0009<br>0675@<br>2C3E_<br>BFFF_<br>F000_<br>0215.<br>, WD-<br>WCC2E<br>AK144<br>57 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>, 请<br>检查 | 2024-<br>04-24<br>08:36<br>:41 | 00-<br>E2-<br>69-<br>6B-<br>A1-<br>35@BF<br>EBFBF<br>F0009<br>0675@<br>2C3E_<br>BFFF_<br>F000_<br>0215.<br>, WD-<br>WCC2E<br>AK144<br>57 | 否 |  |
|------|----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|-----------------------------|--------------------------------|--|---|--|



|      |                      |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                              |                                      |   |   |  |
|------|----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------------------------|--------------------------------------|---|---|--|
|      |                      |                                  | 5121,<br>WD-<br>WCC6Y<br>3RVDV<br>SE  |   |                                  | 5121,<br>WD-<br>WCC6Y<br>3RVDV<br>SE  |   |  |  |  |  |  |  |  |  |  |  |                              | 5121,<br>WD-<br>WCC6Y<br>3RVDV<br>SE |   |   |  |
| 1795 | 福建恒旺建<br>设工程有限<br>公司 | 2024-<br>04-23<br>17:54<br>:48.0 | 4C-<br>ED-<br>FB-<br>BE-<br>A7-<br>49@BF<br>EBFBF<br>F0009<br>06EB@<br>TW187<br>05597<br>15207<br>, WD-<br>WCC6Y<br>5HS7L<br>68 | 否 | 2024-<br>04-23<br>17:52<br>:43.0 | 4C-<br>ED-<br>FB-<br>BE-<br>A7-<br>49@BF<br>EBFBF<br>F0009<br>06EB@<br>TW187<br>05597<br>15207<br>, WD-<br>WCC6Y<br>5HS7L<br>68 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:45<br>:08       | 4C-<br>ED-<br>FB-<br>BE-<br>A7-<br>49@BF<br>EBFBF<br>F0009<br>06EB@<br>TW187<br>05597<br>15207<br>, WD-<br>WCC6Y<br>5HS7L<br>68 | 否 |  |
| 1796 | 福建鼎超建<br>设工程有限<br>公司 | 2024-<br>04-23<br>14:37<br>:56.0 | D4-<br>5D-<br>64-<br>44-<br>4E-<br>98@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>88258<br>3                             | 否 | 2024-<br>04-23<br>14:36<br>:55.0 | D4-<br>5D-<br>64-<br>44-<br>4E-<br>98@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>88258<br>3                             | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:34<br>:07       | D4-<br>5D-<br>64-<br>44-<br>4E-<br>98@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7380<br>88258<br>3                             | 否 |  |













|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1804 | 福建宝夷建设有限公司   | 2024-04-22 15:44:11.0 | 2C-F0-5D-34-CB-C0@BF EBFBF F0009 06EB@ AF9F0 70407 28000 00799 ,WD-WCC6Y 5LERR PJ                         | 否 | 2024-04-22 15:14:00.0 | 2C-F0-5D-34-CB-C0@BF EBFBF F0009 06EB@ AF9F0 70407 28000 00799 ,WD-WCC6Y 5LERR PJ                         | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:38:31 | 2C-F0-5D-34-CB-C0@BF EBFBF F0009 06EB@ AF9F0 70407 28000 00799 ,WD-WCC6Y 5LERR PJ                         | 否 |  |
| 1805 | 福建宁洲建设工程有限公司 | 2024-04-23 10:51:50.0 | A0-36-BC-BD-2F-4C@BF EBFBF F000A 0653@ WD-WCC6Y 6V8HC K2,00 00_00 00_00 00_00 00_00 26_B7 38_1C F9_0B 45. | 否 | 2024-04-23 08:48:05.0 | A0-36-BC-BD-2F-4C@BF EBFBF F000A 0653@ WD-WCC6Y 6V8HC K2,00 00_00 00_00 00_00 00_00 26_B7 38_1C F9_0B 45. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:22 | A0-36-BC-BD-2F-4C@BF EBFBF F000A 0653@ WD-WCC6Y 6V8HC K2,00 00_00 00_00 00_00 00_00 26_B7 38_1C F9_0B 45. | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1806 | 福建昆捷建设有限公司   | 2024-04-23 14:45:26.0 | 58-11-22-A0-AD-66@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4DF2_<br>04C5.                  | 否 | 2024-04-23 14:41:35.0 | 58-11-22-A0-AD-66@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4DF2_<br>04C5.                  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:31:50 | 58-11-22-A0-AD-66@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4DF2_<br>04C5.                  | 否 |  |
| 1807 | 福建涛泽建设工程有限公司 | 2024-04-22 15:06:31.0 | 3C-7C-3F-10-AA-8C, 04-F9-F8-B9-9B-B6, 04-F9-F8-B9-9B-B0, 04-F9-F8-B9-9B-B1@BF<br>EBFBF<br>F000A<br>0653@<br>2205V<br>1028A<br>01290<br>5 | 否 | 2024-04-22 15:02:43.0 | 04-F9-F8-B9-9B-B6, 04-F9-F8-B9-9B-B0, 04-F9-F8-B9-9B-B1, 3C-7C-3F-10-AA-8C@BF<br>EBFBF<br>F000A<br>0653@<br>2205V<br>1028A<br>01290<br>5 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:32:03 | 04-F9-F8-B9-9B-B6, 04-F9-F8-B9-9B-B0, 04-F9-F8-B9-9B-B1, 3C-7C-3F-10-AA-8C@BF<br>EBFBF<br>F000A<br>0653@<br>2205V<br>1028A<br>01290<br>5 | 否 |  |









|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|---|--|
| 1813 | 福建省万钜市政园林有限公司 | 2024-04-22 17:10:40.0 | 0C-9D-92-1B-07-A4@BF EBFBF F0009 06EA@41413 03030 30303 03030 30303 03030 30343 13632             | 否 | 2024-04-22 17:03:11.0 | 0C-9D-92-1B-07-A4@BF EBFBF F0009 06EA@41413 03030 30303 03030 30303 03030 30343 13632             | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:54 | 0C-9D-92-1B-07-A4@BF EBFBF F0009 06EA@41413 03030 30303 03030 30303 03030 30343 13632 | 否   |   |  |
| 1814 | 福建泰闽建设工程有限公司  | 2024-04-22 14:34:01.0 | 64-00-6A-3C-B4-86,44-F9-71-5E-9F-0B,44-F9-71-5E-9F-0B@BF EBFBF F0003 06C3@AA000 00000 00000 00029 | 否 | 2024-04-22 14:27:16.0 | 64-00-6A-3C-B4-86,44-F9-71-5E-9F-0B,44-F9-71-5E-9F-0B@BF EBFBF F0003 06C3@AA000 00000 00000 00029 | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:43:09   | 64-00-6A-3C-B4-86,44-F9-71-5E-9F-0B,44-F9-71-5E-9F-0B@BF EBFBF F0003 06C3@AA000 00000 00000 00029 | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1815 | 福建绿融建设工程有限公司 | 2024-04-23 11:13:45.0 | 08-BF-B8-3D-CC-13@BF EBFBF F0009 0675@WD-WCC6Y A8X16 J6, 30 09869 8825   | 否 | 2024-04-23 11:12:45.0 | 08-BF-B8-3D-CC-13@BF EBFBF F0009 0675@WD-WCC6Y A8X16 J6, 30 09869 8825   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:36:53 | 08-BF-B8-3D-CC-13@BF EBFBF F0009 0675@WD-WCC6Y A8X16 J6, 30 09869 8825   | 否 |  |
| 1816 | 福建坤勇建设工程有限公司 | 2024-04-23 09:02:24.0 | 3C-7C-3F-83-03-68@BF EBFBF F0009 06EB@K3279 7R010 018                    | 否 | 2024-04-23 09:00:35.0 | 3C-7C-3F-83-03-68@BF EBFBF F0009 06EB@K3279 7R010 018                    | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:06 | 3C-7C-3F-83-03-68@BF EBFBF F0009 06EB@K3279 7R010 018                    | 否 |  |
| 1817 | 福建中荣市政园林有限公司 | 2024-04-23 09:36:01.0 | B4-2E-99-9F-00-F4@BF EBFBF F0009 06EA@WCC6Y 1VRFH LC, 20 1015A 00013 633 | 否 | 2024-04-22 11:46:58.0 | B4-2E-99-9F-00-F4@BF EBFBF F0009 06EA@WCC6Y 1VRFH LC, 20 1015A 00013 633 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:07 | B4-2E-99-9F-00-F4@BF EBFBF F0009 06EA@WCC6Y 1VRFH LC, 20 1015A 00013 633 | 否 |  |



|      |                    |                              |  |   |                              |   |   |  |  |  |  |  |  |  |  |  |                         |                            |   |   |  |
|------|--------------------|------------------------------|--|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|-------------------------|----------------------------|---|---|--|
| 1818 | 福建省鑫青<br>华建设工程有限公司 | 2024-04-23<br>00:26<br>:54.0 | 2C-<br>F0-<br>5D-<br>A1-<br>14-<br>DB, 90<br>-76-<br>9F-<br>3D-<br>2F-<br>57, 90<br>-76-<br>9F-<br>3D-<br>2F-<br>57@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7683<br>E3888<br>1        | 否 | 2024-04-23<br>00:23<br>:28.0 | 2C-<br>F0-<br>5D-<br>A1-<br>14-<br>DB, 90<br>-76-<br>9F-<br>3D-<br>2F-<br>57, 90<br>-76-<br>9F-<br>3D-<br>2F-<br>57@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7683<br>E3888<br>1 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:37<br>:51 | 7C-<br>10-<br>C9-<br>8D-<br>42-<br>63@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>6NRY1<br>R5, 20<br>20_20<br>20_20<br>20_20<br>20.  | 否 |  |
| 1819 | 福建源禹建<br>设工程有限公司   | 2024-04-23<br>18:25<br>:40.0 | 7C-<br>10-<br>C9-<br>8D-<br>C8-<br>16, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>001B_<br>448B_<br>4A9E_<br>23F2. | 否 | 2024-04-23<br>18:24<br>:33.0 | 7C-<br>10-<br>C9-<br>8D-<br>C8-<br>16, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>001B_<br>448B_<br>4A9E_<br>23F2. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:40<br>:47 | 7C-<br>10-<br>C9-<br>8D-<br>C8-<br>16, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F000A<br>0653@<br>001B_<br>448B_<br>4A9E_<br>23F2. | 否 |  |

|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1820 | 福建省祥润建设工程有限公司  | 2024-04-22 12:12:34.0 | E8-9C-25-43-BD-DD, 00-00-00-00-00-00-0675@S7HUNJOWCO3369H,E823_8FA6_BF53_0001_001B_444A_48EC_7921. | 否 | 2024-04-22 10:03:07.0 | E8-9C-25-43-BD-DD, 00-00-00-00-00-00-0675@E0@BFEBFBFF00090675@S7HUNJOWCO3369H,E823_8FA6_BF53_0001_001B_444A_48EC_7921. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:20 | E8-9C-25-43-BD-DD@BFEBFBFF00090675@S7HUNJOWCO3369H,E823_8FA6_BF53_0001_001B_444A_48EC_7921. | 否 |  |
| 1821 | 福建省星宇辰建设工程有限公司 | 2024-04-24 08:17:20.0 | E0-D5-5E-BC-0F-03, 00-F0-4C-68-DE-3D@BFEBFBFF000906EB@WD-WCC6Y7JH6T5V, MG220940177535              | 否 | 2024-04-24 08:16:36.0 | E0-D5-5E-BC-0F-03, 00-F0-4C-68-DE-3D@BFEBFBFF000906EB@WD-WCC6Y7JH6T5V, MG220940177535                                  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:26 | E0-D5-5E-BC-0F-03, 00-F0-4C-68-DE-3D@BFEBFBFF000906EB@WD-WCC6Y7JH6T5V, MG220940177535       | 否 |  |











|      |                  |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |                        |                        |   |  |   |  |
|------|------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|------------------------|------------------------|---|--|---|--|
| 1827 | 霖宥建设<br>(福建)有限公司 | 2024-04-22<br>14:56:56.0 | 00-<br>E2-<br>69-<br>4E-<br>50-<br>74,00<br>-E0-<br>D9-<br>00-<br>4A-<br>DB@BF<br>EBFBF<br>F000A<br>0653@<br>L37AA<br>H0609<br>012, W<br>D-<br>WCC4J<br>1NUHP<br>VR | 否 | 2024-04-22<br>10:54:13.0 | 00-<br>E2-<br>69-<br>4E-<br>50-<br>74,00<br>-E0-<br>D9-<br>00-<br>4A-<br>DB@BF<br>EBFBF<br>F000A<br>0653@<br>L37AA<br>H0609<br>012, W<br>D-<br>WCC4J<br>1NUHP<br>VR | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-04-24<br>08:31:49 | 00-<br>E2-<br>69-<br>4E-<br>50-<br>74,00<br>-E0-<br>D9-<br>00-<br>4A-<br>DB@BF<br>EBFBF<br>F000A<br>0653@<br>L37AA<br>H0609<br>012, W<br>D-<br>WCC4J<br>1NUHP<br>VR | 否  |   |  |
| 1828 | 重庆八骏祥<br>集实业有限公司 | 2024-04-23<br>10:42:23.0 | 18-<br>CO-<br>4D-<br>32-<br>3B-<br>59@17<br>8FBFB<br>F0081<br>0F81@<br>SN201<br>20896<br>1912,<br>W3T6B<br>A4H  | 否 | 2024-04-17<br>15:57:09.0 | 18-<br>CO-<br>4D-<br>32-<br>3B-<br>59@17<br>8FBFB<br>F0081<br>0F81@<br>SN201<br>20896<br>1912,<br>W3T6B<br>A4H  | 否 |  |  |  |  |  |  |  |  |  |                        | 校验<br>数据有<br>误,请<br>检查 | 2024-04-24<br>08:35:12  | 18-<br>CO-<br>4D-<br>32-<br>3B-<br>59@17<br>8FBFB<br>F0081<br>0F81@<br>SN201<br>20896<br>1912,<br>W3T6B<br>A4H | 否 |  |



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1829 | 中建鸿腾建设集团有限公司 | 2024-04-22 17:17:32.0 | F4-B5-20-39-CF-00@BF<br>EBFBF<br>F0009<br>06EA@<br>MG221<br>13017<br>1488,<br>WD-<br>WCC6Y<br>5ZMVL<br>U8 | 否 | 2024-04-22 16:55:20.0 | F4-B5-20-39-CF-00@BF<br>EBFBF<br>F0009<br>06EA@<br>MG221<br>13017<br>1488,<br>WD-<br>WCC6Y<br>5ZMVL<br>U8 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:38:35 | F4-B5-20-39-CF-00@BF<br>EBFBF<br>F0009<br>06EA@<br>MG221<br>13017<br>1488,<br>WD-<br>WCC6Y<br>5ZMVL<br>U8 | 否 |  |
| 1830 | 福建华恒建设工程有限公司 | 2024-04-18 16:49:07.0 | 08-BF-B8-3A-52-6C@BF<br>EBFBF<br>F000A<br>0653@<br>23041<br>X8077<br>30, WD<br>-<br>WCC6Y<br>N6271<br>XF  | 否 | 2024-04-18 16:44:30.0 | 08-BF-B8-3A-52-6C@BF<br>EBFBF<br>F000A<br>0653@<br>23041<br>X8077<br>30, WD<br>-<br>WCC6Y<br>N6271<br>XF  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:54 | 08-BF-B8-3A-52-6C@BF<br>EBFBF<br>F000A<br>0653@<br>23041<br>X8077<br>30, WD<br>-<br>WCC6Y<br>N6271<br>XF  | 否 |  |



|      |             |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |  |   |  |
|------|-------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|--|---|--|
| 1832 | 易旺建设有限公司    | 2024-04-23 19:29:12.0 | D8-5E-D3-1C-43-1A@BF<br>EBFBF<br>F000A<br>0653@<br>21155<br>B4646<br>13, WD<br>-<br>WCC6Y<br>2ZPTD<br>C1 | 否 | 2024-04-23 11:26:56.0 | D8-5E-D3-1C-43-1A@BF<br>EBFBF<br>F000A<br>0653@<br>21155<br>B4646<br>13, WD<br>-<br>WCC6Y<br>2ZPTD<br>C1 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:42:33 | D8-5E-D3-1C-43-1A@BF<br>EBFBF<br>F000A<br>0653@<br>21155<br>B4646<br>13, WD<br>-<br>WCC6Y<br>2ZPTD<br>C1 | 否  |   |  |
| 1833 | 福建鑫卓沅建设有限公司 | 2024-04-23 11:19:54.0 | 3C-7C-3F-EF-0C-E7@BF<br>EBFBF<br>F000A<br>0653@<br>30024<br>62208<br>1                                   | 否 | 2024-04-23 11:18:43.0 | 3C-7C-3F-EF-0C-E7@BF<br>EBFBF<br>F000A<br>0653@<br>30024<br>62208<br>1                                   | 否 |  |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:35:21  | 3C-7C-3F-EF-0C-E7@BF<br>EBFBF<br>F000A<br>0653@<br>30024<br>62208<br>1 | 否 |  |







|      |                       |                          |  |   |                          |   |   |  |  |  |  |  |  |  |  |                     |                        |  |   |   |  |
|------|-----------------------|--------------------------|--|---|--------------------------|---|---|--|--|--|--|--|--|--|--|---------------------|------------------------|--|---|---|--|
| 1839 | 千秋筑业<br>(福建) 建设有限公司   | 2024-04-23<br>17:07:49.0 | E8-9C-25-43-AF-C9@BF<br>EBFBBF<br>F0009<br>0675@<br>23165<br>V4678<br>12, WD<br>-<br>WX12D<br>A31DY<br>9Z  | 否 | 2024-04-23<br>16:56:56.0 | E8-9C-25-43-AF-C9@BF<br>EBFBBF<br>F0009<br>0675@<br>23165<br>V4678<br>12, WD<br>-<br>WX12D<br>A31DY<br>9Z   | 否 |  |  |  |  |  |  |  |  |                     | 校验数据有<br>误, 请查<br>检    | 2024-04-24<br>08:32:51   | E8-9C-25-43-AF-C9@BF<br>EBFBBF<br>F0009<br>0675@<br>23165<br>V4678<br>12, WD<br>-<br>WX12D<br>A31DY<br>9Z | 否 |  |
| 1840 | 福建省埤坤<br>建设集团有<br>限公司 | 2024-04-23<br>09:55:06.0 | 0C-9D-92-C1-6F-A2@BF<br>EBFBBF<br>F0009<br>06E9@<br>30353<br>23042<br>36373<br>73238<br>32393<br>44145<br>35202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>30595<br>84a34<br>32544<br>b | 否 | 2024-04-19<br>11:28:29.0 | 0C-9D-92-C1-6F-A2, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBBF<br>F0009<br>06E9@<br>30353<br>23042<br>36373<br>73238<br>32393<br>44145<br>35202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>30595<br>84a34<br>32544<br>b | 否 |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>检 | 2024-04-24<br>08:50:35 | 0C-9D-92-C1-6F-A2@BF<br>EBFBBF<br>F0009<br>06E9@<br>30353<br>23042<br>36373<br>73238<br>32393<br>44145<br>35202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>30595<br>84a34<br>32544<br>b | 否   |   |  |







|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1843 | 福建省陆禹建设有限公司   | 2024-04-23 18:53:33.0 | D8-5E-D3-6B-D9-3D,00-E0-4C-38-07-6A@BF EBFBF F000A 0653@ 20190 61800 315,W D-WCC6Y 18PER DH | 否 | 2024-04-22 18:01:50.0 | D8-5E-D3-6B-D9-3D,00-E0-4C-38-07-6A@BF EBFBF F000A 0653@ 20190 61800 315,W D-WCC6Y 18PER DH | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:26 | D8-5E-D3-6B-D9-3D,00-E0-4C-38-07-6A@BF EBFBF F000A 0653@ 20190 61800 315,W D-WCC6Y 18PER DH | 否 |  |
| 1844 | 福建鼎胜阳建设工程有限公司 | 2024-04-23 15:37:43.0 | 08-BF-B8-BB-54-B7@BF EBFBF F0009 0675@ 0025_ 38B2_ 31A3_ 731C.                              | 否 | 2024-04-23 15:18:07.0 | 08-BF-B8-BB-54-B7@BF EBFBF F0009 0675@ 0025_ 38B2_ 31A3_ 731C.                              | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:17 | 08-BF-B8-BB-54-B7@BF EBFBF F0009 0675@ 0025_ 38B2_ 31A3_ 731C.                              | 否 |  |



|      |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1846 | 瑞沣集团股份有限公司    | 2024-04-24 08:24:19.0 | D8-5E-D3-78-0B-16@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0026_ B738_ 173F_ 4665. , WD- WCC6Y 3LA8J 89, EE 03D75 151E7 | 否 | 2024-04-19 15:25:29.0 | 04-42-1A-03-6E-1A@BF EBFBF F000A 0653@ WD- WCC6Y 5DXLY PT, 50 026B7 380F5 C9E1         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:30:52 | D8-5E-D3-78-0B-16@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0026_ B738_ 173F_ 4665. , WD- WCC6Y 3LA8J 89, EE 03D75 151E7 | 否 |  |
| 1847 | 福建众鑫源建设发展有限公司 | 2024-04-22 09:33:42.0 | 18-C0-4D-52-B0-E4@BF EBFBF F0009 06EB@ 50026 B7380 9FCD7 C  | 否 | 2024-04-22 09:32:51.0 | 18-C0-4D-52-B0-E4, 00 -00- 00- 00- 00- 00- E0@BF EBFBF F0009 06EB@ 50026 B7380 9FCD7 C | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:16 | 18-C0-4D-52-B0-E4@BF EBFBF F0009 06EB@ 50026 B7380 9FCD7 C  | 否 |  |



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1850 | 福建喜庆建设工程有限公司 | 2024-04-17 10:50:58.0 | 00-<br>CF-<br>E0-<br>57-<br>DB-<br>2B@BF<br>EBFBF<br>F0009<br>06EA@<br>K3909<br>16J27<br>474, W<br>D-<br>WCC6Y<br>4VHZE<br>HN | 否 | 2024-04-17 10:48:08.0 | 00-<br>CF-<br>E0-<br>57-<br>DB-<br>2B@BF<br>EBFBF<br>F0009<br>06EA@<br>K3909<br>16J27<br>474, W<br>D-<br>WCC6Y<br>4VHZE<br>HN | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:39:47 | 00-<br>CF-<br>E0-<br>57-<br>DB-<br>2B@BF<br>EBFBF<br>F0009<br>06EA@<br>K3909<br>16J27<br>474, W<br>D-<br>WCC6Y<br>4VHZE<br>HN | 否 |  |
| 1851 | 福建磐泽建设工程有限公司 | 2024-04-22 12:27:10.0 | 3C-<br>7C-<br>3F-<br>F4-<br>10-<br>4D@BF<br>EBFBF<br>F0009<br>06EA@<br>WCC6Y<br>7HUXE<br>C3, 30<br>01436<br>4168              | 否 | 2024-04-22 11:46:32.0 | 3C-<br>7C-<br>3F-<br>F4-<br>10-<br>4D@BF<br>EBFBF<br>F0009<br>06EA@<br>WCC6Y<br>7HUXE<br>C3, 30<br>01436<br>4168              | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:07 | 3C-<br>7C-<br>3F-<br>F4-<br>10-<br>4D@BF<br>EBFBF<br>F0009<br>06EA@<br>WCC6Y<br>7HUXE<br>C3, 30<br>01436<br>4168              | 否 |  |
| 1852 | 天津六建建筑工程有限公司 | 2024-04-23 15:07:11.0 | 04-<br>92-<br>26-<br>4A-<br>01-<br>38@BF<br>EBFBF<br>F0009<br>06EA@<br>W9AEQ<br>XM6, 0<br>025_3<br>886_9<br>108_E<br>0A0.     | 否 | 2024-04-23 15:03:44.0 | 04-<br>92-<br>26-<br>4A-<br>01-<br>38@BF<br>EBFBF<br>F0009<br>06EA@<br>W9AEQ<br>XM6, 0<br>025_3<br>886_9<br>108_E<br>0A0.     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:50:08 | 04-<br>92-<br>26-<br>4A-<br>01-<br>38@BF<br>EBFBF<br>F0009<br>06EA@<br>W9AEQ<br>XM6, 0<br>025_3<br>886_9<br>108_E<br>0A0.     | 否 |  |



|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1854 | 浙江伟杰建设有限公司 | 2024-04-23 10:57:47.0 | E8-9C-25-34-95-2D@178BFBF F00A50F00@0000_0000_0000_0000_8CE3_8E03_0090_1BCC. | 否 | 2024-04-23 10:56:48.0 | E8-9C-25-34-95-2D@178BFBF F00A50F00@0000_0000_0000_0000_8CE3_8E03_0090_1BCC. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:39:29 | E8-9C-25-34-95-2D@178BFBF F00A50F00@0000_0000_0000_0000_8CE3_8E03_0090_1BCC. | 否 |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|



|      |                |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |  |   |  |
|------|----------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|--|---|--|
| 1855 | 福建中源筑业工程建设有限公司 | 2024-04-23 08:53:47.0 | 04-42-1A-30-F5-F2,00-E0-4C-8A-5E-88,00-E0-4C-8A-5E-88,00-E0-4C-8A-5E-88,02-E0-4C-8A-5E-88,82-E0-4C-8A-5E-88@BFEBFBFF000A0653@50026B7381375C58 | 否 | 2024-04-23 08:52:07.0 | 00-E0-4C-8A-5E-88,02-E0-4C-8A-5E-88,82-E0-4C-8A-5E-88,04-E0-4C-1A-30-F5-F2,00-E0-4C-8A-5E-88@BFEBFBFF000A0653@50026B7381375C58 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:37:11 | 04-42-1A-30-F5-F2,00-E0-4C-8A-5E-88,00-E0-4C-8A-5E-88,02-E0-4C-8A-5E-88,82-E0-4C-8A-5E-88@BFEBFBFF000A0653@50026B7381375C58 | 否  |   |  |
| 1856 | 福建景新建设工程有限公司   | 2024-04-23 10:51:16.0 | 1C-1B-0D-46-9D-64@BFEBFBFF000506E3@WD-WCC6Y1SXE355  | 否 | 2024-04-23 10:49:31.0 | 1C-1B-0D-46-9D-64@BFEBFBFF000506E3@WD-WCC6Y1SXE355   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:35:41   | 1C-1B-0D-46-9D-64@BFEBFBFF000506E3@WD-WCC6Y1SXE355 | 否 |  |

|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|--|---|--|
| 1857 | 福建省天禹建设工程有限公司 | 2024-04-23 20:09:34.0 | 18-CO-4D-E1-DB-00,00-E0-4C-38-07-1D,00-00-00-00-00-00@BF EBFBF F000A 0671@WD-WCC6Y 4FCTT L2,FM 3002S 2102X 00592 6 | 否 | 2024-04-23 11:57:52.0 | 18-CO-4D-E1-DB-00,00-E0-4C-38-07-1D,00-00-00-00-00-00@BF EBFBF F000A 0671@WD-WCC6Y 4FCTT L2,FM 3002S 2102X 00592 6 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:40:34 | 18-CO-4D-E1-DB-00,00-E0-4C-38-07-1D,00-00-00-00-00-00@BF EBFBF F000A 0671@WD-WCC6Y 4FCTT L2,FM 3002S 2102X 00592 6 | 否  |   |  |
| 1858 | 中建骏宏集团有限公司    | 2024-04-22 13:17:27.0 | A4-0C-66-0E-AF-9C@BF EBFBF F0009 0675@ 23092 30017 415   | 否 | 2024-04-22 13:10:12.0 | A4-0C-66-0E-AF-9C@BF EBFBF F0009 0675@ 23092 30017 415   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:33:34  | A4-0C-66-0E-AF-9C@BF EBFBF F0009 0675@ 23092 30017 415 | 否 |  |



|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1860 | 福建省鑫元建设工程有限公司 | 2024-04-23 15:12:25.0 | 04-D4-C4-4E-27-55@BF EBFBF F0009 06EA@ 44414 13234 32313 03139 31313 03439 30393 32020 , 2020 20202 02020 20202 02020 39574 84150 434c5 2 | 否 | 2024-04-22 16:10:25.0 | 04-D4-C4-4E-27-55@BF EBFBF F0009 06EA@ 44414 13234 32313 03139 31313 03439 30393 32020 , 2020 20202 02020 20202 02020 39574 84150 434c5 2 | 否 |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:14 | 04-D4-C4-4E-27-55@BF EBFBF F0009 06EA@ 44414 13234 32313 03139 31313 03439 30393 32020 , 2020 20202 02020 20202 02020 39574 84150 434c5 2 | 否 |  |
| 1861 | 福建省七昌建设有限公司   | 2024-04-18 15:59:24.0 | E8-9C-25-41-33-E3@BF EBFBF F000B 06F2@ 30035 19887 4,000 0_000 0_000 0_000 0_002 6_B76 8_6A6 C_781 5.                                     | 否 | 2024-04-18 15:57:26.0 | E8-9C-25-41-33-E3@BF EBFBF F000B 06F2@ 30035 19887 4,000 0_000 0_000 0_000 0_002 6_B76 8_6A6 C_781 5.                                     | 否 |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:07 | E8-9C-25-41-33-E3@BF EBFBF F000B 06F2@ 30035 19887 4,000 0_000 0_000 0_000 0_002 6_B76 8_6A6 C_781 5.                                     | 否 |  |











|      |              |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |  |                            |                            |  |   |  |
|------|--------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|--|---|--|
|      |              |                              |  |   |                              | EBFBF<br>F000A<br>0653@<br>0026_<br>B768_<br>5A2D_<br>D2A5.  |   |  |  |  |  |  |  |  |  |  |  |                            |                            |  |   |  |
| 1867 | 福建隆峰建设管理有限公司 | 2024-04-22<br>18:08<br>:34.0 | E8-<br>9C-<br>25-<br>48-<br>03-<br>3D@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C10_<br>BB71_<br>9267. | 否 | 2024-04-22<br>17:58<br>:16.0 | E8-<br>9C-<br>25-<br>48-<br>03-<br>3D@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C10_<br>BB71_<br>9267. | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:43<br>:11 | E8-<br>9C-<br>25-<br>48-<br>03-<br>3D@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C10_<br>BB71_<br>9267. | 否 |  |



|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1869 | 福建省鸿诚建设工程有限公司 | 2024-04-22 15:08:35.0 | 74-56-3C-5E-60-32@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_2069_B105.   | 否 | 2024-04-22 14:54:51.0 | 74-56-3C-5E-60-32@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_2069_B105.   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:18 | 74-56-3C-5E-60-32@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_2069_B105.   | 否 |  |
| 1870 | 福建博道建设工程有限公司  | 2024-04-24 06:51:06.0 | D4-5D-64-7D-86-C1@BF EBFBF F0009 06EB@RJB21 03160 0199, W9AJX 6P4                | 否 | 2024-04-24 06:49:07.0 | D4-5D-64-7D-86-C1@BF EBFBF F0009 06EB@RJB21 03160 0199, W9AJX 6P4                | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:41:32 | D4-5D-64-7D-86-C1@BF EBFBF F0009 06EB@RJB21 03160 0199, W9AJX 6P4                | 否 |  |
| 1871 | 福建恒博名扬建设有限公司  | 2024-04-22 11:10:25.0 | 04-42-1A-AD-F6-22@BF EBFBF F000A 0653@AA000 00001 22900 00897, WD-WCC6Y 1DJHA XC | 否 | 2024-04-22 10:23:15.0 | 04-42-1A-AD-F6-22@BF EBFBF F000A 0653@AA000 00001 22900 00897, WD-WCC6Y 1DJHA XC | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:44:45 | 04-42-1A-AD-F6-22@BF EBFBF F000A 0653@AA000 00001 22900 00897, WD-WCC6Y 1DJHA XC | 否 |  |



|      |                              |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                             |                                |   |   |  |
|------|------------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|-----------------------------|--------------------------------|---|---|--|
| 1873 | 海峡三建<br>(福建)建<br>工发展有限<br>公司 | 2024-<br>04-23<br>09:35<br>:15.0 | 74-<br>56-<br>3C-<br>7C-<br>12-<br>B2@BF<br>EBFBF<br>F000A<br>0653@<br>0025_<br>38A7_<br>21B0_<br>9ABA.<br>, WD-<br>WCC6Y<br>K3XMZ<br>S6 | 否 | 2024-<br>04-23<br>09:31<br>:19.0 | 74-<br>56-<br>3C-<br>7C-<br>12-<br>B2@BF<br>EBFBF<br>F000A<br>0653@<br>0025_<br>38A7_<br>21B0_<br>9ABA.<br>, WD-<br>WCC6Y<br>K3XMZ<br>S6 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>, 请<br>检查 | 2024-<br>04-24<br>08:34<br>:39 | 74-<br>56-<br>3C-<br>7C-<br>12-<br>B2, 48<br>-8A-<br>D2-<br>C8-<br>6F-<br>DF@BF<br>EBFBF<br>F000A<br>0653@<br>0025_<br>38A7_<br>21B0_<br>9ABA.<br>, WD-<br>WCC6Y<br>K3XMZ<br>S6 | 否 |  |
|------|------------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|-----------------------------|--------------------------------|---|---|--|











|      |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1879 | 亿安顺（福建）电力工程有限公司 | 2024-04-22 17:07:39.0 | 58-11-22-D1-56-91@BF EBFBF F0009 0675@50026 B7381 D294D A, W9A DP7FW         | 否 | 2024-04-22 17:06:02.0 | 58-11-22-D1-56-91@BF EBFBF F0009 0675@50026 B7381 D294D A, W9A DP7FW         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:48:40 | 58-11-22-D1-56-91@BF EBFBF F0009 0675@50026 B7381 D294D A, W9A DP7FW         | 否 |  |
| 1880 | 福建九丰建设有限公司      | 2024-04-23 15:09:23.0 | 3C-7C-3F-7D-17-DE@17 8BFBF F0081 0F81@WD-WCC6Y 1UUUF 7H, 50 026B7 380DE 3A22 | 否 | 2024-04-23 15:07:59.0 | 3C-7C-3F-7D-17-DE@17 8BFBF F0081 0F81@WD-WCC6Y 1UUUF 7H, 50 026B7 380DE 3A22 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:46:36 | 3C-7C-3F-7D-17-DE@17 8BFBF F0081 0F81@WD-WCC6Y 1UUUF 7H, 50 026B7 380DE 3A22 | 否 |  |
| 1881 | 福建中交远大建设工程有限公司  | 2024-04-23 16:29:17.0 | 04-42-1A-28-37-06@BF EBFBF F000A 0653@50026 B7381 37AC4 4, WD-WCC6Y 7XJ6E 17 | 否 | 2024-04-22 17:01:36.0 | 04-42-1A-28-37-06@BF EBFBF F000A 0653@50026 B7381 37AC4 4, WD-WCC6Y 7XJ6E 17 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:41:25 | 04-42-1A-28-37-06@BF EBFBF F000A 0653@50026 B7381 37AC4 4, WD-WCC6Y 7XJ6E 17 | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1882 | 福建荣发建筑工程有限公司 | 2024-04-22 15:46:31.0 | 70-8B-CD-B9-9F-B2@BF EBFBF F0005 06E3@7014W 21320 1935  | 否 | 2024-04-22 10:06:20.0 | 70-8B-CD-B9-9F-B2@BF EBFBF F0005 06E3@7014W 21320 1935  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:47 | 70-8B-CD-B9-9F-B2@BF EBFBF F0005 06E3@7014W 21320 1935  | 否 |  |
| 1883 | 福建九鼎建设集团有限公司 | 2024-04-23 11:12:44.0 | 74-56-3C-50-A9-39@BF EBFBF F0009 0675@0000_0000_0000_0000_00E0_4C13_F81B_5655., WD-WCC6Y R38A7 1X | 否 | 2024-04-23 11:05:07.0 | 74-56-3C-50-A9-39@BF EBFBF F0009 0675@0000_0000_0000_0000_00E0_4C13_F81B_5655., WD-WCC6Y R38A7 1X | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:50:45 | 74-56-3C-50-A9-39@BF EBFBF F0009 0675@0000_0000_0000_0000_00E0_4C13_F81B_5655., WD-WCC6Y R38A7 1X | 否 |  |

|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1884 | 福建南造建设发展有限公司  | 2024-04-23 10:22:39.0 | 00-E2-69-6D-AF-CA@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 2014_ EE65. | 否 | 2024-04-23 10:21:22.0 | 00-E2-69-6D-AF-CA@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 2014_ EE65. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:38:33 | 00-E2-69-6D-AF-CA@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 2014_ EE65. | 否 |  |
| 1885 | 福建省冠腾建设工程有限公司 | 2024-04-23 11:46:40.0 | D8-5E-D3-32-7A-01@17 8BFBF F00A2 0F12@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 49DF_ 0B6A. | 否 | 2024-04-23 11:44:10.0 | D8-5E-D3-32-7A-01@17 8BFBF F00A2 0F12@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 49DF_ 0B6A. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:54 | D8-5E-D3-32-7A-01@17 8BFBF F00A2 0F12@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 49DF_ 0B6A. | 否 |  |

|      |                    |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |  |              |                        |  |   |   |  |
|------|--------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|------------------------|--|---|---|--|
| 1886 | 嘉业鑫成<br>(福建)建设有限公司 | 2024-04-23<br>15:06:59.0 | E8-9C-25-C3-01-57@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>6AHLE<br>9N, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>4A_48<br>B2_DC<br>65. | 否 | 2024-04-23<br>14:43:10.0 | E8-9C-25-C3-01-57@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>6AHLE<br>9N, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>4A_48<br>B2_DC<br>65. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24<br>08:31:02 | E8-9C-25-C3-01-57@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>6AHLE<br>9N, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>4A_48<br>B2_DC<br>65. | 否   |   |  |
| 1887 | 福建中八建设有限公司         | 2024-04-23<br>16:21:15.0 | E0-D5-5E-12-D3-11@BF<br>EBFBF<br>F0005<br>06E3@<br>2H312<br>00310<br>25, 50<br>026B7<br>7839B<br>F1AE  | 否 | 2024-04-23<br>16:18:23.0 | E0-D5-5E-12-D3-11@BF<br>EBFBF<br>F0005<br>06E3@<br>2H312<br>00310<br>25, 50<br>026B7<br>7839B<br>F1AE  | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查           | 2024-04-24<br>08:38:34   | E0-D5-5E-12-D3-11@BF<br>EBFBF<br>F0005<br>06E3@<br>2H312<br>00310<br>25, 50<br>026B7<br>7839B<br>F1AE | 否 |  |





|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|---|--|
| 1892 | 福建匠成建设有限公司 | 2024-04-22 17:21:24.0 | 84-47-09-20-11-06,84-47-09-20-11-07,98-59-7A-8A-8A-18,98-59-7A-8A-8A-19,9A-59-7A-8A-8A-18@178BFBF F00A40F41@ABC1_2300_0000_0067. | 否 | 2024-04-22 17:18:16.0 | 84-47-09-20-11-06,84-47-09-20-11-07,98-59-7A-8A-8A-19,9A-59-7A-8A-8A-18,98-59-7A-8A-8A-18@178BFBF F00A40F41@ABC1_2300_0000_0067. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:42:02 | 84-47-09-20-11-06,84-47-09-20-11-07,98-59-7A-8A-8A-18,98-59-7A-8A-8A-19,9A-59-7A-8A-8A-18@178BFBF F00A40F41@ABC1_2300_0000_0067. | 否   |   |  |
| 1893 | 南平中环建设有限公司 | 2024-04-23 11:23:58.0 | 58-11-22-A0-C2-C5@BFEBFBF F000A0653@30088207078,WD-WCC2EH602141  | 否 | 2024-04-23 11:21:24.0 | 58-11-22-A0-C2-C5@BFEBFBF F000A0653@30088207078,WD-WCC2EH602141  | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:33:25  | 58-11-22-A0-C2-C5@BFEBFBF F000A0653@30088207078,WD-WCC2EH602141 | 否 |  |











|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|---|--|
| 1900 | 福建华龙建设工程有限公司 | 2024-04-23 16:33:21.0 | 74-86-E2-34-7F-9B,00-00-00-00-00-00,3C-55-76-F1-52-F5,3E-55-76-F1-52-F5,32-55-76-F1-52-F5@BF-EBFBF-F0009-0675@0000_0000_0000_0000_8CE3_8E04_03D6_6117.,W9AS G5E5 | 否 | 2024-04-23 16:31:51.0 | 74-86-E2-34-7F-9B,3C-55-76-F1-52-F5,3E-55-76-F1-52-F5,32-55-76-F1-52-F5@BF-EBFBF-F0009-0675@0000_0000_0000_0000_8CE3_8E04_03D6_6117.,W9AS G5E5 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误,请检查 | 2024-04-24 08:32:03 | 74-86-E2-34-7F-9B,00-00-00-00-00-00,3C-55-76-F1-52-F5,3E-55-76-F1-52-F5,32-55-76-F1-52-F5@BF-EBFBF-F0009-0675@0000_0000_0000_0000_8CE3_8E04_03D6_6117.,W9AS G5E5 | 否   |   |  |
| 1901 | 福建鸿瀚市政工程有限公司 | 2024-04-23 16:18:39.0 | A0-36-BC-A7-94-64@BF-EBFBF-F0009-0672@TA184  | 否 | 2024-04-22 11:48:05.0 | A0-36-BC-A7-94-64@BF-EBFBF-F0009-0672@TA184  | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误,请检查         | 2024-04-24 08:49:17  | A0-36-BC-A7-94-64@BF-EBFBF-F0009-0672@TA184 | 否 |  |

|      |               |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |                        |                            |  |  |   |  |
|------|---------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|------------------------|----------------------------|--|--|---|--|
|      |               |                              | 10204<br>95,00<br>25_38<br>DA_21<br>A2_BB<br>7A.   |   |                              | 10204<br>95,00<br>25_38<br>DA_21<br>A2_BB<br>7A.   |   |  |  |  |  |  |  |  |  |                        |                            | 10204<br>95,00<br>25_38<br>DA_21<br>A2_BB<br>7A.   |  |   |  |
| 1902 | 福建大艺建设工程有限公司  | 2024-04-22<br>17:32<br>:49.0 | D8-<br>43-<br>AE-<br>4E-<br>BA-<br>D2@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>7URC3<br>FD,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_27<br>BC_ED<br>85. | 否 | 2024-04-22<br>17:12<br>:10.0 | D8-<br>43-<br>AE-<br>4E-<br>BA-<br>D2@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>7URC3<br>FD,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_27<br>BC_ED<br>85. | 否 |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-04-24<br>08:32<br>:42 | D8-<br>43-<br>AE-<br>4E-<br>BA-<br>D2@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>7URC3<br>FD,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_27<br>BC_ED<br>85. | 否  |   |  |
| 1903 | 福建中腾达建设工程有限公司 | 2024-04-23<br>18:21<br>:56.0 | 74-<br>56-<br>3C-<br>CC-<br>77-<br>AE@BF<br>EBFBF<br>F0009<br>0675@<br>0000-<br>0000-<br>0000-<br>0000-<br>0000-<br>0026-<br>B738-<br>23C3-<br>3C75.<br>,WD-<br>WX12D<br>53JXL<br>H9 | 否 | 2024-04-23<br>18:18<br>:46.0 | 74-<br>56-<br>3C-<br>CC-<br>77-<br>AE@BF<br>EBFBF<br>F0009<br>0675@<br>0000-<br>0000-<br>0000-<br>0000-<br>0000-<br>0026-<br>B738-<br>23C3-<br>3C75.<br>,WD-<br>WX12D<br>53JXL<br>H9 | 否 |  |  |  |  |  |  |  |  |                        | 校验<br>数据有<br>误,请<br>检查     | 2024-04-24<br>08:36<br>:02   | 74-<br>56-<br>3C-<br>CC-<br>77-<br>AE@BF<br>EBFBF<br>F0009<br>0675@<br>0000-<br>0000-<br>0000-<br>0000-<br>0000-<br>0026-<br>B738-<br>23C3-<br>3C75.<br>,WD-<br>WX12D<br>53JXL<br>H9 | 否 |  |

|      |                        |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                        |                            |  |   |   |  |
|------|------------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------|----------------------------|--|---|---|--|
| 1904 | 中鹤建设<br>(福建)有限公司       | 2024-04-23<br>17:38<br>:32.0 | 08-<br>BF-<br>B8-<br>84-<br>6E-<br>34@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>NWCN<br>H9,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_66<br>EC_87<br>B5. | 否 | 2024-04-23<br>17:36<br>:15.0 | 08-<br>BF-<br>B8-<br>84-<br>6E-<br>34@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>NWCN<br>H9,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_66<br>EC_87<br>B5. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-04-24<br>08:33<br>:07 | 08-<br>BF-<br>B8-<br>84-<br>6E-<br>34@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>NWCN<br>H9,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_66<br>EC_87<br>B5. | 否   |   |  |
| 1905 | 福建省益泰<br>恒建筑工程<br>有限公司 | 2024-04-23<br>19:46<br>:16.0 | D4-<br>5D-<br>64-<br>3C-<br>56-<br>47@BF<br>EBFBF<br>F0009<br>06EB@<br>19380<br>C8006<br>59,WD<br>-<br>WCC6Y<br>7FT9N<br>DU  | 否 | 2024-04-23<br>11:05<br>:55.0 | D4-<br>5D-<br>64-<br>3C-<br>56-<br>47@BF<br>EBFBF<br>F0009<br>06EB@<br>19380<br>C8006<br>59,WD<br>-<br>WCC6Y<br>7FT9N<br>DU  | 否 |  |  |  |  |  |  |  |  |  |                        | 校验<br>数据有<br>误,请<br>检查     | 2024-04-24<br>08:36<br>:02   | D4-<br>5D-<br>64-<br>3C-<br>56-<br>47@BF<br>EBFBF<br>F0009<br>06EB@<br>19380<br>C8006<br>59,WD<br>-<br>WCC6Y<br>7FT9N<br>DU | 否 |  |







|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1909 | 福建展骏建筑工程有限公司 | 2024-04-23 15:35:14.0 | D8-5E-D3-C3-DF-85@BFEBFBFF000A0653@50026B738204A078                         | 否 | 2024-04-23 15:26:51.0 | D8-5E-D3-C3-DF-85@BFEBFBFF000A0653@50026B738204A078                         | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:08 | D8-5E-D3-C3-DF-85@BFEBFBFF000A0653@50026B738204A078                         | 否 |  |
| 1910 | 福建骐福建筑工程有限公司 | 2024-04-23 12:26:00.0 | 00-E2-69-21-0B-43@BFEBFBFF000906EA@WCC6Y3XZ1FF1,AA0000000000063,00000009451 | 否 | 2024-04-20 10:17:27.0 | 00-E2-69-21-0B-43@BFEBFBFF000906EA@WCC6Y3XZ1FF1,AA0000000000063,00000009451 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:39:40 | 00-E2-69-21-0B-43@BFEBFBFF000906EA@WCC6Y3XZ1FF1,AA0000000000063,00000009451 | 否 |  |



|      |                   |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |                            |                            |  |   |   |  |
|------|-------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|----------------------------|----------------------------|--|---|---|--|
| 1913 | 河南中达翔<br>建设工程有限公司 | 2024-04-23<br>15:24<br>:38.0 | 00-<br>E0-<br>4D-<br>E7-<br>03-<br>FD@BF<br>EBFBF<br>F0003<br>06A9@<br>2205Z<br>DOR42<br>15040<br>2                                      | 否 | 2024-04-23<br>15:23<br>:44.0 | 00-<br>E0-<br>4D-<br>E7-<br>03-<br>FD@BF<br>EBFBF<br>F0003<br>06A9@<br>2205Z<br>DOR42<br>15040<br>2                                      | 否 |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:41<br>:01   | 00-<br>E0-<br>4D-<br>E7-<br>03-<br>FD@BF<br>EBFBF<br>F0003<br>06A9@<br>2205Z<br>DOR42<br>15040<br>2 | 否 |  |
| 1914 | 中闽融凯建<br>设工程有限公司  | 2024-04-23<br>13:26<br>:54.0 | E0-<br>D5-<br>5E-<br>54-<br>6F-<br>D1@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>1DUTU<br>OX, AA<br>00000<br>00000<br>00001<br>066 | 否 | 2024-04-23<br>13:26<br>:00.0 | E0-<br>D5-<br>5E-<br>54-<br>6F-<br>D1@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>1DUTU<br>OX, AA<br>00000<br>00000<br>00001<br>066 | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:34<br>:26 | E0-<br>D5-<br>5E-<br>54-<br>6F-<br>D1@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>1DUTU<br>OX, AA<br>00000<br>00000<br>00001<br>066 | 否   |   |  |





|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1918 | 宁德市新城建筑工程有限公司 | 2024-04-23 17:11:21.0 | A0-36-BC-26-B5-95@BFEBFBFF000A0653@AD4A24122072650056                 | 否 | 2024-04-23 16:59:19.0 | A0-36-BC-26-B5-95@BFEBFBFF000A0653@AD4A24122072650056                 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:39:03 | A0-36-BC-26-B5-95@BFEBFBFF000A0653@AD4A24122072650056                 | 否 |  |
| 1919 | 福建省永春辉达建设有限公司 | 2024-04-23 10:44:27.0 | 04-D4-C4-04-B0-ED@BFEBFBFF000906EB@50026B7429001BEF,WD-WCC6Y3UZA6HZ   | 否 | 2024-04-23 10:43:01.0 | 04-D4-C4-04-B0-ED@BFEBFBFF000906EB@50026B7429001BEF,WD-WCC6Y3UZA6HZ   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:44:34 | 04-D4-C4-04-B0-ED@BFEBFBFF000906EB@50026B7429001BEF,WD-WCC6Y3UZA6HZ   | 否 |  |
| 1920 | 福建万旗建设工程有限公司  | 2024-04-22 15:21:57.0 | 74-56-3C-82-8E-1F,00-1A-7D-DA-71-11@BFEBFBFF000A0653@50026B7381F731A1 | 否 | 2024-04-22 15:01:08.0 | 74-56-3C-82-8E-1F,00-1A-7D-DA-71-11@BFEBFBFF000A0653@50026B7381F731A1 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:45:29 | 74-56-3C-82-8E-1F,00-1A-7D-DA-71-11@BFEBFBFF000A0653@50026B7381F731A1 | 否 |  |
| 1921 | 福建中凯建         | 2024-                 | 1C-   | 否 | 2024-                 | 1C-   | 否 |  |  |  |  |  |  |  |  |  | 校验         | 2024-               | 1C-   | 否 |  |







|      |             |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |                     |                     |   |   |  |
|------|-------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|---------------------|---------------------|---|---|--|
| 1924 | 福建省北浦建设有限公司 | 2024-04-08 15:57:52.0 | 00-<br>E0-<br>70-<br>A0-<br>7C-<br>96, 4C<br>-77-<br>66-<br>49-<br>15-<br>98@BF<br>EBFBF<br>F0009<br>06E9@<br>MG190<br>80000<br>00000<br>01911<br>, WD-<br>WCC6Y<br>2ET16<br>RK | 否 | 2024-04-08 15:52:49.0 | 00-<br>E0-<br>70-<br>A0-<br>7C-<br>96, 4C<br>-77-<br>66-<br>49-<br>15-<br>98@BF<br>EBFBF<br>F0009<br>06E9@<br>MG190<br>80000<br>00000<br>01911<br>, WD-<br>WCC6Y<br>2ET16<br>RK | 否 |  |  |  |  |  |  |  |  |  | 校验数据<br>有误, 请<br>检查 | 2024-04-24 08:46:33 | 00-<br>E0-<br>70-<br>A0-<br>7C-<br>96, 4C<br>-77-<br>66-<br>49-<br>15-<br>98@BF<br>EBFBF<br>F0009<br>06E9@<br>MG190<br>80000<br>00000<br>01911<br>, WD-<br>WCC6Y<br>2ET16<br>RK | 否 |  |
|------|-------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|---------------------|---------------------|---|---|--|



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1926 | 宁德榜一建筑工程有限公司 | 2024-04-22 16:02:29.0 | 18-CO-4D-B5-1E-64@BF EBFBF F000A 0653@WD-WCC6Y 2HHS7 87, SS MB201 08015 97                             | 否 | 2024-04-22 15:45:31.0 | 18-CO-4D-B5-1E-64@BF EBFBF F000A 0653@WD-WCC6Y 2HHS7 87, SS MB201 08015 97                             | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:13 | 18-CO-4D-B5-1E-64@BF EBFBF F000A 0653@WD-WCC6Y 2HHS7 87, SS MB201 08015 97                             | 否 |  |
| 1927 | 福建翔和建设有限公司   | 2024-04-23 10:24:32.0 | 74-56-3C-19-8D-43@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_ B768_ 646D_ FE95. , WD- WCC6Y 1HRY4 XS | 否 | 2024-04-23 10:10:01.0 | 74-56-3C-19-8D-43@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_ B768_ 646D_ FE95. , WD- WCC6Y 1HRY4 XS | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:27 | 74-56-3C-19-8D-43@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_ B768_ 646D_ FE95. , WD- WCC6Y 1HRY4 XS | 否 |  |







|      |                    |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |  |              |                        |   |   |  |
|------|--------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|------------------------|---|---|--|
| 1932 | 海创建设<br>(福建)有限公司   | 2024-04-22<br>15:05:48.0 | 2C-<br>FD-<br>A1-<br>E3-<br>6D-<br>2D@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36363<br>73238<br>42303<br>73843<br>37202<br>02020 | 否 | 2024-04-22<br>14:46:51.0 | 2C-<br>FD-<br>A1-<br>E3-<br>6D-<br>2D@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36363<br>73238<br>42303<br>73843<br>37202<br>02020 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24<br>08:35:02 | 2C-<br>FD-<br>A1-<br>E3-<br>6D-<br>2D, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>EQ@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36363<br>73238<br>42303<br>73843<br>37202<br>02020 | 否 |  |
| 1933 | 福建畅顺建<br>业建设工程有限公司 | 2024-04-23<br>18:42:39.0 | D8-<br>5E-<br>D3-<br>C6-<br>33-<br>11@BF<br>EBFBF<br>F000A<br>0653@<br>6479_<br>A774_<br>70C0_<br>0E23.                                     | 否 | 2024-04-23<br>18:42:29.0 | D8-<br>5E-<br>D3-<br>C6-<br>33-<br>11@BF<br>EBFBF<br>F000A<br>0653@<br>6479_<br>A774_<br>70C0_<br>0E23.                                     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24<br>08:44:04 | D8-<br>5E-<br>D3-<br>C6-<br>33-<br>11@BF<br>EBFBF<br>F000A<br>0653@<br>6479_<br>A774_<br>70C0_<br>0E23.   | 否 |  |







|      |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|------|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
| 1937 | 福建鑫升森<br>建设发展有<br>限公司 | 2024-<br>04-18<br>17:25<br>:21.0 | E8-<br>9C-<br>25-<br>10-<br>0C-<br>D6@BF<br>EBFBF<br>F0009<br>0675@<br>50026<br>B7382<br>2DC84<br>D | 否 | 2024-<br>04-18<br>17:11<br>:13.0 | E8-<br>9C-<br>25-<br>10-<br>0C-<br>D6@BF<br>EBFBF<br>F0009<br>0675@<br>50026<br>B7382<br>2DC84<br>D | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:34<br>:14 | E8-<br>9C-<br>25-<br>10-<br>0C-<br>D6,00<br>-00-<br>00-<br>00-<br>00-<br>00@BF<br>EBFBF<br>F0009<br>0675@<br>50026<br>B7382<br>2DC84<br>D | 否 |  |
|------|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|





|      |             |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|-------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1940 | 友鸿建设有限公司    | 2024-04-23 18:57:54.0 | 58-11-22-CE-D8-2E@BF EBFBF F000A 0653@50026 B7382 06426 2 | 否 | 2024-04-22 16:37:39.0 | 58-11-22-CE-D8-2E@BF EBFBF F000A 0653@50026 B7382 06426 2 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:44:19 | 58-11-22-CE-D8-2E@BF EBFBF F000A 0653@50026 B7382 06426 2 | 否 |  |
| 1941 | 福建贵昌泰建设有限公司 | 2024-04-23 15:17:57.0 | 00-E0-4C-89-EC-35@BF EBFBF F000A 0653@ KL23B 030A8 A2187  | 否 | 2024-04-23 15:11:13.0 | 00-E0-4C-89-EC-35@BF EBFBF F000A 0653@ KL23B 030A8 A2187  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:42:02 | 00-E0-4C-89-EC-35@BF EBFBF F000A 0653@ KL23B 030A8 A2187  | 否 |  |



|      |                  |  |   |  |   |  |  |  |  |  |  |  |  |  |  |  |             |  |   |  |
|------|------------------|--|---|--|---|--|--|--|--|--|--|--|--|--|--|--|-------------|--|---|--|
| 1943 | 福建省南平市夏道保温安装有限公司 | 2024-04-23 17:16:42.0  | 否 | 2024-04-23 17:12:14.0  | 否 |  |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:14  | 否 |  |
|      |                  | 4C-<br>ED-<br>FB-<br>42-<br>7F-<br>0B, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>TW186<br>02560<br>00064<br>, WD-<br>WCC6Y<br>1XXYF<br>1K |   | 4C-<br>ED-<br>FB-<br>42-<br>7F-<br>0B, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>TW186<br>02560<br>00064<br>, WD-<br>WCC6Y<br>1XXYF<br>1K |   |  |  |  |  |  |  |  |  |  |  |  |             | 4C-<br>ED-<br>FB-<br>42-<br>7F-<br>0B, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>TW186<br>02560<br>00064<br>, WD-<br>WCC6Y<br>1XXYF<br>1K |   |  |







|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1946 | 福建润盈建设集团有限公司 | 2024-04-23 12:15:28.0 | 08-BF-B8-30-13-BC@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>51DW9<br>14,00<br>00_00<br>00_00<br>00_00<br>00_70<br>7C_18<br>02_32<br>02_C9<br>0D. | 否 | 2024-04-23 12:09:31.0 | 08-BF-B8-30-13-BC@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>51DW9<br>14,00<br>00_00<br>00_00<br>00_00<br>00_70<br>7C_18<br>02_32<br>02_C9<br>0D. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:33 | 08-BF-B8-30-13-BC@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>51DW9<br>14,00<br>00_00<br>00_00<br>00_00<br>00_70<br>7C_18<br>02_32<br>02_C9<br>0D. | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|



|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 1948 | 荣元（平潭）建设发展有限公司 | 2024-04-23 17:24:40.0 | 74-56-3C-35-8E-5B@BF EBFBF F000A 0653@0000_0006_2210_0042_3A5A_2703_EE00_129E. | 否 | 2024-04-23 16:59:50.0 | 74-56-3C-35-8E-5B@BF EBFBF F000A 0653@0000_0006_2210_0042_3A5A_2703_EE00_129E. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:47:22 | 74-56-3C-35-8E-5B@BF EBFBF F000A 0653@0000_0006_2210_0042_3A5A_2703_EE00_129E. | 否 |  |
| 1949 | 福建省东霖建设工程有限公司  | 2024-04-23 14:55:41.0 | 1C-1B-0D-D6-0A-84@BF EBFBF F0009 06E9@50026 B7380 590C6 5                      | 否 | 2024-04-23 14:47:29.0 | 1C-1B-0D-D6-0A-84,00-00-00-00-00-E0@BF EBFBF F0009 06E9@50026 B7380 590C6 5    | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:09 | 1C-1B-0D-D6-0A-84@BF EBFBF F0009 06E9@50026 B7380 590C6 5                      | 否 |  |

|      |                   |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                         |                            |   |   |  |
|------|-------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------------------|----------------------------|---|---|--|
| 1950 | 福建冠凯达<br>建设工程有限公司 | 2024-04-23<br>11:51<br>:47.0 | 58-<br>11-<br>22-<br>AE-<br>1F-<br>DD@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000.<br>, WD-<br>WCC6Y<br>91PMV<br>RL  | 否 | 2024-04-23<br>11:52<br>:41.0 | 58-<br>11-<br>22-<br>AE-<br>1F-<br>DD@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000.<br>, WD-<br>WCC6Y<br>91PMV<br>RL  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:33<br>:07 | 58-<br>11-<br>22-<br>AE-<br>1F-<br>DD@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000.<br>, WD-<br>WCC6Y<br>91PMV<br>RL | 否 |  |
| 1951 | 福建省福源<br>建设工程有限公司 | 2024-04-19<br>15:17<br>:42.0 | 4C-<br>CC-<br>6A-<br>5F-<br>71-<br>97,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7382<br>2F399<br>B, WD-<br>WCC6Y<br>7SLK8<br>39 | 否 | 2024-04-19<br>15:01<br>:40.0 | 4C-<br>CC-<br>6A-<br>5F-<br>71-<br>97,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7382<br>2F399<br>B, WD-<br>WCC6Y<br>7SLK8<br>39 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:32<br>:51 | 4C-<br>CC-<br>6A-<br>5F-<br>71-<br>97@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7382<br>2F399<br>B, WD-<br>WCC6Y<br>7SLK8<br>39                                    | 否 |  |

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 1952 | 福建省万嘉辉建筑工程有限公司 | 2024-04-23 16:17:53.0 | 18-C0-4D-90-13-75,64-6E-97-F3-D5-18@BFEBFBFF000906EA@50026B73822D67FA                   | 否 | 2024-04-23 11:42:44.0 | 18-C0-4D-90-13-75,64-6E-97-F3-D5-18@BFEBFBFF000906EA@50026B73822D67FA                   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:15 | 18-C0-4D-90-13-75,64-6E-97-F3-D5-18@BFEBFBFF000906EA@50026B73822D67FA                   | 否 |  |
| 1953 | 华百屹(福建)建设有限公司  | 2024-04-22 15:43:14.0 | 74-56-3C-10-26-33,00-5C-C2-64-39-79,00-5C-C2-64-39-79@BFEBFBFF000A0653@50026B738197C155 | 否 | 2024-04-22 14:58:06.0 | 74-56-3C-10-26-33,00-5C-C2-64-39-79,00-5C-C2-64-39-79@BFEBFBFF000A0653@50026B738197C155 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:18 | 74-56-3C-10-26-33,00-5C-C2-64-39-79,00-5C-C2-64-39-79@BFEBFBFF000A0653@50026B738197C155 | 否 |  |

|      |                        |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |                            |                        |   |   |  |
|------|------------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|---|---|--|
| 1954 | 福建鑫睿达<br>建设工程有限公司      | 2024-04-23<br>17:42:04.0 | A0-<br>36-<br>BC-<br>21-<br>CD-<br>5D@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>48BF_<br>AE00. | 否 | 2024-04-23<br>17:46:33.0 | A0-<br>36-<br>BC-<br>21-<br>CD-<br>5D@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>48BF_<br>AE00. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:32:21 | A0-<br>36-<br>BC-<br>21-<br>CD-<br>5D@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>444A_<br>48BF_<br>AE00. | 否 |  |
| 1955 | 福建汇中恒<br>一建筑工程<br>有限公司 | 2024-04-23<br>16:33:49.0 | B4-<br>2E-<br>99-<br>0F-<br>CA-<br>69@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7782<br>CODA1<br>9   | 否 | 2024-04-23<br>11:50:49.0 | B4-<br>2E-<br>99-<br>0F-<br>CA-<br>69@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7782<br>CODA1<br>9   | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:36:02 | B4-<br>2E-<br>99-<br>0F-<br>CA-<br>69@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7782<br>CODA1<br>9   | 否 |  |









|      |                   |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                         |                            |   |                                 |   |  |
|------|-------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------------------|----------------------------|---|---------------------------------|---|--|
| 1959 | 福建省全一<br>工程管理有限公司 | 2024-04-23<br>16:01<br>:45.0 | 74-<br>56-<br>3C-<br>14-<br>3A-<br>24@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>95H64<br>15, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4B<br>33_C8<br>22. | 否 | 2024-04-19<br>17:30<br>:47.0 | 74-<br>56-<br>3C-<br>14-<br>3A-<br>24@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>95H64<br>15, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4B<br>33_C8<br>22. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:32<br>:31 | 74-<br>56-<br>3C-<br>14-<br>3A-<br>24, D4<br>-84-<br>09-<br>11-<br>9B-<br>45@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>95H64<br>15, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_4B<br>33_C8<br>22. | 否                               |   |  |
| 1960 | 福建闽九建<br>设工程有限公司  | 2024-04-23<br>16:57<br>:42.0 | 00-<br>E2-<br>69-<br>60-<br>2B-<br>18@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2345_<br>6789_<br>3A5A_<br>2702_<br>3000_<br>13F5.                                  | 否 | 2024-04-23<br>11:12<br>:02.0 | 00-<br>E2-<br>69-<br>60-<br>2B-<br>18@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2345_<br>6789_<br>3A5A_<br>2702_<br>3000_<br>13F5.                                  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:48<br>:59 | 00-<br>E2-<br>69-<br>60-<br>2B-<br>18@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2345_<br>6789_<br>3A5A_<br>2702_<br>3000_<br>13F5.   | 否                               |   |  |
| 1961 | 福建鸿才建<br>设有限公司    | 2024-04-22<br>17:31<br>:28.0 | D8-<br>5E-<br>D3-<br>48-<br>1D-  | 否 | 2024-04-22<br>17:26<br>:54.0 | D8-<br>5E-<br>D3-<br>48-<br>1D-  | 否 |  |  |  |  |  |  |  |  |  |                         | 校验<br>数据有<br>误, 请<br>检查    | 2024-04-24<br>08:43<br>:47  | D8-<br>5E-<br>D3-<br>48-<br>1D- | 否 |  |

|      |                        |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
|      |                        |                                  | BA@BF<br>EBFBF<br>F0009<br>0675@<br>W9ASY<br>ZLC, 6<br>479_A<br>767_E<br>F00_2<br>15A.                |   |                                  | BA@BF<br>EBFBF<br>F0009<br>0675@<br>W9ASY<br>ZLC, 6<br>479_A<br>767_E<br>F00_2<br>15A.                |   |  |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
| 1962 | 中元盛鸿<br>(福建)建<br>设有限公司 | 2024-<br>04-22<br>17:36<br>:23.0 | D8-<br>5E-<br>D3-<br>41-<br>B0-<br>A0@BF<br>EBFBF<br>F000A<br>0653@<br>FM600<br>2S223<br>3ZD00<br>627 | 否 | 2024-<br>04-22<br>14:51<br>:31.0 | D8-<br>5E-<br>D3-<br>41-<br>B0-<br>A0@BF<br>EBFBF<br>F000A<br>0653@<br>FM600<br>2S223<br>3ZD00<br>627 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:38<br>:31 | D8-<br>5E-<br>D3-<br>41-<br>B0-<br>A0@BF<br>EBFBF<br>F000A<br>0653@<br>FM600<br>2S223<br>3ZD00<br>627 | 否 |  |



|      |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1964 | 福建五一建设工程有限公司    | 2024-04-19 09:20:03.0 | 00-<br>E0-<br>1B-<br>33-<br>23-<br>3F@BF<br>EBFBF<br>F0002<br>06D7,<br>BFEBF<br>BFF00<br>0206D<br>7@WK3<br>066JS<br>,2022<br>11190<br>6061                                   | 否 | 2024-04-19 09:11:48.0 | 00-<br>E0-<br>1B-<br>33-<br>23-<br>3F@BF<br>EBFBF<br>F0002<br>06D7,<br>BFEBF<br>BFF00<br>0206D<br>7@WK3<br>066JS<br>,2022<br>11190<br>6061                                   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:07 | 00-<br>E0-<br>1B-<br>33-<br>23-<br>3F@BF<br>EBFBF<br>F0002<br>06D7,<br>BFEBF<br>BFF00<br>0206D<br>7@WK3<br>066JS<br>,2022<br>11190<br>6061                                   | 否 |  |
| 1965 | 福建省诚佳建设工程管理有限公司 | 2024-04-23 08:55:44.0 | A0-<br>36-<br>BC-<br>2A-<br>DF-<br>16@BF<br>EBFBF<br>F0009<br>0672@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1962_<br>D955.<br>, WD-<br>WCC6Y<br>P3AKF<br>L7 | 否 | 2024-04-23 08:50:21.0 | A0-<br>36-<br>BC-<br>2A-<br>DF-<br>16@BF<br>EBFBF<br>F0009<br>0672@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1962_<br>D955.<br>, WD-<br>WCC6Y<br>P3AKF<br>L7 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:03 | A0-<br>36-<br>BC-<br>2A-<br>DF-<br>16@BF<br>EBFBF<br>F0009<br>0672@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1962_<br>D955.<br>, WD-<br>WCC6Y<br>P3AKF<br>L7 | 否 |  |

|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1966 | 福建中宅建设有限责任公司  | 2024-04-23 14:33:52.0 | B4-2E-99-4A-06-47@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7783<br>78D37<br>B, WD-<br>WCC2E<br>NZ896<br>12 | 否 | 2024-04-18 10:08:59.0 | B4-2E-99-4A-06-47@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7783<br>78D37<br>B, WD-<br>WCC2E<br>NZ896<br>12 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请查 | 2024-04-24 08:37:04 | B4-2E-99-4A-06-47@BF<br>EBFBF<br>F0009<br>06EB@<br>50026<br>B7783<br>78D37<br>B, WD-<br>WCC2E<br>NZ896<br>12 | 否 |  |
| 1967 | 福建盛峰建设有限公司    | 2024-04-23 16:23:11.0 | 00-CF-E0-40-FE-9E@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7282<br>36BAD<br>D, WD-<br>WCC2E<br>PR914<br>85 | 否 | 2024-04-23 16:29:02.0 | 00-CF-E0-40-FE-9E@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7282<br>36BAD<br>D, WD-<br>WCC2E<br>PR914<br>85 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请查 | 2024-04-24 08:35:02 | 00-CF-E0-40-FE-9E@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7282<br>36BAD<br>D, WD-<br>WCC2E<br>PR914<br>85 | 否 |  |
| 1968 | 莆田市承辉建筑工程有限公司 | 2024-04-23 16:11:59.0 | 00-E0-1B-39-21-C1@BF<br>EBFBF<br>F0009<br>0675@<br>YS210<br>51198<br>97, WD<br>-<br>WCC2E<br>DV93Y<br>KT     | 否 | 2024-04-23 16:11:13.0 | 00-E0-1B-39-21-C1@BF<br>EBFBF<br>F0009<br>0675@<br>YS210<br>51198<br>97, WD<br>-<br>WCC2E<br>DV93Y<br>KT     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请查 | 2024-04-24 08:37:41 | 00-E0-1B-39-21-C1@BF<br>EBFBF<br>F0009<br>0675@<br>YS210<br>51198<br>97, WD<br>-<br>WCC2E<br>DV93Y<br>KT     | 否 |  |



|      |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 1969 | 福建省鼎盛旺建设工程有限公司  | 2024-04-23 13:31:43.0 | 60-45-CB-9B-6D-D2@BFEBFBFF000906E9@AA00000000000002111             | 否 | 2024-04-23 13:30:11.0 | 60-45-CB-9B-6D-D2@BFEBFBFF000906E9@AA00000000000002111             | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:50 | 60-45-CB-9B-6D-D2@BFEBFBFF000906E9@AA00000000000002111             | 否 |  |
| 1970 | 深圳市宝龙泰建设工程有限公司  | 2024-04-22 16:22:48.0 | D8-BB-C1-55-72-5D@BFEBFBFF000A0653@50026B77842610D5,AA202211050228 | 否 | 2024-04-22 15:43:33.0 | D8-BB-C1-55-72-5D@BFEBFBFF000A0653@50026B77842610D5,AA202211050228 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:36 | D8-BB-C1-55-72-5D@BFEBFBFF000A0653@50026B77842610D5,AA202211050228 | 否 |  |
| 1971 | 福建省紫云集团宏泰建设有限公司 | 2024-04-22 17:03:52.0 | C8-7F-54-AD-19-68@BFEBFBFF000A0653@2N182L18ED21                    | 否 | 2024-04-22 10:27:17.0 | C8-7F-54-AD-19-68@BFEBFBFF000A0653@2N182L18ED21                    | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:43:03 | FC-34-97-9E-A6-67@BFEBFBFF000A0653@Z6ESQP60,AA00000000000436       | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 1972 | 乐达项目管理有限公司   | 2024-04-23 17:50:41.0 | A0-36-BC-23-78-61@BF<br>EBFBF<br>F0009<br>0675@WD-<br>WCC6Y1SARA<br>A5,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_17<br>20_09<br>85. | 否 | 2024-04-23 17:44:54.0 | A0-36-BC-23-78-61@BF<br>EBFBF<br>F0009<br>0675@WD-<br>WCC6Y1SARA<br>A5,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_17<br>20_09<br>85. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:40:39 | A0-36-BC-23-78-61@BF<br>EBFBF<br>F0009<br>0675@WD-<br>WCC6Y1SARA<br>A5,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_17<br>20_09<br>85. | 否   |   |  |
| 1973 | 福建禾乔建设发展有限公司 | 2024-04-23 14:11:04.0 | 08-BF-B8-9E-48-B2@BF<br>EBFBF<br>F0009<br>0675@0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2496_<br>FA75.                             | 否 | 2024-04-22 15:25:23.0 | 08-BF-B8-9E-48-B2@BF<br>EBFBF<br>F0009<br>0675@0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2496_<br>FA75.                             | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:40:05   | 08-BF-B8-9E-48-B2@BF<br>EBFBF<br>F0009<br>0675@0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2496_<br>FA75. | 否 |  |

|      |                   |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |  |  |                            |                        |  |   |  |
|------|-------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|------------------------|--|---|--|
| 1974 | 福建乾鑫顺<br>建设工程有限公司 | 2024-04-22<br>17:11:05.0 | 18-<br>C0-<br>4D-<br>E1-<br>35-<br>3A@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>E251D<br>7  | 否 | 2024-04-22<br>17:04:37.0 | 18-<br>C0-<br>4D-<br>E1-<br>35-<br>3A@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>E251D<br>7  | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:34:25 | 18-<br>C0-<br>4D-<br>E1-<br>35-<br>3A@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>E251D<br>7  | 否 |  |
| 1975 | 锦禾建设集<br>团有限公司    | 2024-04-23<br>17:05:29.0 | 00-<br>E2-<br>69-<br>60-<br>32-<br>29,00<br>-FF-<br>91-<br>59-<br>C2-<br>22@BF<br>EBFBF<br>F000A<br>0653@<br>MG220<br>95070<br>0474,<br>W2ASP<br>NFC | 否 | 2024-04-23<br>09:59:25.0 | 00-<br>FF-<br>91-<br>59-<br>C2-<br>22,00<br>-E2-<br>69-<br>60-<br>32-<br>29@BF<br>EBFBF<br>F000A<br>0653@<br>MG220<br>95070<br>0474,<br>W2ASP<br>NFC | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:35:25 | 00-<br>E2-<br>69-<br>60-<br>32-<br>29,00<br>-FF-<br>91-<br>59-<br>C2-<br>22@BF<br>EBFBF<br>F000A<br>0653@<br>MG220<br>95070<br>0474,<br>W2ASP<br>NFC | 否 |  |





|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 1980 | 福建陆捌建设有限公司    | 2024-04-22 22:01:26.0 | 74-56-3C-79-5C-30@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2302_<br>0002_<br>3A5A_<br>2703_<br>5000_<br>0101. | 否 | 2024-04-22 22:00:06.0 | 74-56-3C-79-5C-30@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2302_<br>0002_<br>3A5A_<br>2703_<br>5000_<br>0101. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:43:04 | 74-56-3C-79-5C-30@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2302_<br>0002_<br>3A5A_<br>2703_<br>5000_<br>0101. | 否   |   |  |
| 1981 | 福建省国尤建设工程有限公司 | 2024-04-23 11:44:04.0 | D8-5E-D3-2B-A7-84@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>0F1A2<br>E   | 否 | 2024-04-23 11:38:27.0 | D8-5E-D3-2B-A7-84@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>0F1A2<br>E   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:31:48   | D8-5E-D3-2B-A7-84@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>0F1A2<br>E | 否 |  |









|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1986 | 福建鑫君筑建设发展有限公司 | 2024-04-22 10:44:21.0 | 50-EB-F6-9D-57-23@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4HKOH<br>61, MM<br>C959Q<br>01268<br>30S30<br>2 | 否 | 2024-04-22 10:35:23.0 | 50-EB-F6-9D-57-23@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4HKOH<br>61, MM<br>C959Q<br>01268<br>30S30<br>2 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:05 | 50-EB-F6-9D-57-23@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4HKOH<br>61, MM<br>C959Q<br>01268<br>30S30<br>2 | 否 |  |
| 1987 | 福建明沈建设工程有限公司  | 2024-04-22 19:56:31.0 | E0-D5-5E-11-49-00@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>1JJ4Z<br>85, 20<br>17091<br>10508<br>1          | 否 | 2024-04-22 15:42:44.0 | E0-D5-5E-11-49-00@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>1JJ4Z<br>85, 20<br>17091<br>10508<br>1          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:18 | E0-D5-5E-11-49-00@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>1JJ4Z<br>85, 20<br>17091<br>10508<br>1          | 否 |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 1988 | 北方一建建设集团有限公司  | 2024-04-23 17:42:19.0 | 74-56-3C-21-1E-F1@BFEBFBFF000A0653@0000_0006_2345_6789_3A5A_2702_3000_8E75.                 | 否 | 2024-04-23 11:36:21.0 | 74-56-3C-21-1E-F1@BFEBFBFF000A0653@0000_0006_2345_6789_3A5A_2702_3000_8E75.                 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:43:09 | 74-56-3C-21-1E-F1@BFEBFBFF000A0653@0000_0006_2345_6789_3A5A_2702_3000_8E75.                 | 否 |  |
| 1989 | 福建邦智森建设发展有限公司 | 2024-04-18 15:16:31.0 | 08-BF-B8-87-86-OD@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_444A_48ED_224A.,WD-WCC6Y88MXKRA | 否 | 2024-04-18 15:13:46.0 | 08-BF-B8-87-86-OD@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_444A_48ED_224A.,WD-WCC6Y88MXKRA | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:08 | 08-BF-B8-87-86-OD@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_444A_48ED_224A.,WD-WCC6Y88MXKRA | 否 |  |



|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 1992 | 中建富泉股份有限公司    | 2024-04-22 15:57:39.0 | 00-<br>E0-<br>4C-<br>81-<br>BC-<br>4E@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>CCYRV<br>AC, 30<br>10088<br>5388                | 否 | 2024-04-17 10:19:17.0 | 00-<br>E0-<br>4C-<br>81-<br>BC-<br>4E@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>CCYRV<br>AC, 30<br>10088<br>5388                | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:42 | 00-<br>E0-<br>4C-<br>81-<br>BC-<br>4E@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>CCYRV<br>AC, 30<br>10088<br>5388                | 否 |  |
| 1993 | 福建省嘉盟建设工程有限公司 | 2024-04-23 11:39:57.0 | 00-<br>E0-<br>4C-<br>6B-<br>00-<br>12@BF<br>EBFBF<br>F000A<br>0653@<br>AD4A2<br>40220<br>62252<br>911, W<br>D-<br>WCC6Y<br>2NVFU<br>NF | 否 | 2024-04-23 11:36:19.0 | 00-<br>E0-<br>4C-<br>6B-<br>00-<br>12@BF<br>EBFBF<br>F000A<br>0653@<br>AD4A2<br>40220<br>62252<br>911, W<br>D-<br>WCC6Y<br>2NVFU<br>NF | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:17 | 00-<br>E0-<br>4C-<br>6B-<br>00-<br>12@BF<br>EBFBF<br>F000A<br>0653@<br>AD4A2<br>40220<br>62252<br>911, W<br>D-<br>WCC6Y<br>2NVFU<br>NF | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 1994 | 顺合（福建）建设有限公司 | 2024-04-23 10:25:51.0 | 00-<br>E0-<br>70-<br>EE-<br>2F-<br>C6,00<br>-E0-<br>4C-<br>9D-<br>B3-<br>20,02<br>-E0-<br>4C-<br>9D-<br>B3-<br>20,02<br>-E0-<br>4C-<br>9D-<br>B3-<br>20,00<br>-E0-<br>4C-<br>9D-<br>B3-<br>20,00<br>-E0-<br>4C-<br>9D-<br>B3-<br>20@BF<br>EBFBF<br>F000A<br>0653@<br>CM246<br>BH030<br>8232 | 否 | 2024-04-23 10:25:45.0 | 00-<br>E0-<br>4C-<br>9D-<br>B3-<br>20,02<br>-E0-<br>4C-<br>9D-<br>B3-<br>20,00<br>-E0-<br>4C-<br>9D-<br>B3-<br>20,00<br>-E0-<br>4C-<br>9D-<br>B3-<br>20,00<br>-E0-<br>4C-<br>9D-<br>B3-<br>20,00<br>-E0-<br>4C-<br>9D-<br>B3-<br>20@BF<br>EBFBF<br>F000A<br>0653@<br>CM246<br>BH030<br>8232 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:08 | 00-<br>E0-<br>70-<br>EE-<br>2F-<br>C6,00<br>-E0-<br>4C-<br>9D-<br>B3-<br>20,02<br>-E0-<br>4C-<br>9D-<br>B3-<br>20,02<br>-E0-<br>4C-<br>9D-<br>B3-<br>20,00<br>-E0-<br>4C-<br>9D-<br>B3-<br>20,00<br>-E0-<br>4C-<br>9D-<br>B3-<br>20@BF<br>EBFBF<br>F000A<br>0653@<br>CM246<br>BH030<br>8232 | 否 |  |
| 1995 | 福建省祥庭建筑有限公司  | 2024-04-23 16:45:26.0 | D8-<br>43-<br>AE-<br>13-<br>86-<br>3A@BF<br>EBFBF<br>F0009<br>0675@<br>0000-<br>0000-<br>0000-<br>0000-<br>4868-<br>3400-<br>0000-<br>0000-<br>0000-<br>,WD-<br>WCC6Y<br>57M6Y<br>6C  | 否 | 2024-04-23 16:43:45.0 | D8-<br>43-<br>AE-<br>13-<br>86-<br>3A@BF<br>EBFBF<br>F0009<br>0675@<br>0000-<br>0000-<br>0000-<br>0000-<br>4868-<br>3400-<br>0000-<br>0000-<br>0000-<br>,WD-<br>WCC6Y<br>57M6Y<br>6C  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:21 | D8-<br>43-<br>AE-<br>13-<br>86-<br>3A@BF<br>EBFBF<br>F0009<br>0675@<br>0000-<br>0000-<br>0000-<br>0000-<br>4868-<br>3400-<br>0000-<br>0000-<br>0000-<br>,WD-<br>WCC6Y<br>57M6Y<br>6C  | 否 |  |

|      |                        |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
|------|------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|
| 1996 | 中建金财<br>(福建)发<br>展有限公司 | 2024-<br>04-23<br>10:27<br>:23.0 | 00-<br>E0-<br>4C-<br>3E-<br>63-<br>B2@BF<br>EBFBF<br>F0009<br>06E9@<br>85690<br>71715<br>F6001<br>37751  | 否 | 2024-<br>04-23<br>10:23<br>:54.0 | 00-<br>E0-<br>4C-<br>3E-<br>63-<br>B2, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>85690<br>71715<br>F6001<br>37751 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:35<br>:02 | 00-<br>E0-<br>4C-<br>3E-<br>63-<br>B2@BF<br>EBFBF<br>F0009<br>06E9@<br>85690<br>71715<br>F6001<br>37751  | 否 |  |
| 1997 | 福建方道建<br>筑工程有限<br>公司   | 2024-<br>04-23<br>11:29<br>:46.0 | F4-<br>B5-<br>20-<br>27-<br>E7-<br>C4, 50<br>-2B-<br>73-<br>E9-<br>16-<br>2F@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00008<br>76000<br>10394 | 否 | 2024-<br>04-23<br>11:28<br>:21.0 | F4-<br>B5-<br>20-<br>27-<br>E7-<br>C4, 50<br>-2B-<br>73-<br>E9-<br>16-<br>2F@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00008<br>76000<br>10394               | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:33<br>:31 | F4-<br>B5-<br>20-<br>27-<br>E7-<br>C4, 50<br>-2B-<br>73-<br>E9-<br>16-<br>2F@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00008<br>76000<br>10394 | 否 |  |







|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2001 | 福建省熊宇鑫建设工程有限公司 | 2024-04-22 15:49:43.0 | 50-EB-F6-5A-58-AA@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 49A4_ 17B3. , WD- WCC6Y 0JDRY V9 | 否 | 2024-04-22 15:20:37.0 | 50-EB-F6-5A-58-AA@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 49A4_ 17B3. , WD- WCC6Y 0JDRY V9 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:12 | 50-EB-F6-5A-58-AA@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 49A4_ 17B3. , WD- WCC6Y 0JDRY V9 | 否 |  |
| 2002 | 福建兴万禾建设有限公司    | 2024-04-22 16:38:57.0 | 04-7C-16-D6-1F-5C@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B768_ 65EE_ FA05.                      | 否 | 2024-04-19 11:49:55.0 | 04-7C-16-D6-1F-5C@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B768_ 65EE_ FA05.                      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:38 | 04-7C-16-D6-1F-5C@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 0026_ B768_ 65EE_ FA05.                      | 否 |  |



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |  |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|--|---|--|
| 2005 | 福建拓景环境建设有限公司 | 2024-04-22 15:26:02.0 | 88-D7-F6-40-FA-4A@BF<br>EBFBF<br>F0005<br>06E3@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>65956<br>46324<br>84e48 | 否 | 2024-04-22 15:14:06.0 | 88-D7-F6-40-FA-4A@BF<br>EBFBF<br>F0005<br>06E3@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>65956<br>46324<br>84e48 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:42:29 | 4C-ED-FB-C8-89-64@BF<br>EBFBF<br>F0003<br>06C3@<br>AA000<br>00000<br>00000<br>00237 | 否  |   |  |
| 2006 | 福建省五三建设有限公司  | 2024-04-23 15:51:45.0 | 2A-46-6F-04-0E-33@BF<br>EBFBF<br>F0002<br>06D7@<br>20210<br>60200<br>786  | 否 | 2024-04-23 15:49:43.0 | 2A-46-6F-04-0E-33@BF<br>EBFBF<br>F0002<br>06D7@<br>20210<br>60200<br>786  | 否 |  |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:32:11   | 2A-46-6F-04-0E-33@BF<br>EBFBF<br>F0002<br>06D7@<br>20210<br>60200<br>786 | 否 |  |

|      |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                        |                                |   |  |   |  |
|------|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|------------------------|--------------------------------|---|--|---|--|
| 2007 | 福建省群溢<br>建筑工程有<br>限公司 | 2024-<br>04-22<br>13:07<br>:45.0 | 50-<br>EB-<br>F6-<br>B8-<br>AF-<br>47@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>5ASV6<br>LS,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_61<br>DF_4D<br>85. | 否 | 2024-<br>04-22<br>11:31<br>:08.0 | 50-<br>EB-<br>F6-<br>B8-<br>AF-<br>47@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>5ASV6<br>LS,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_61<br>DF_4D<br>85. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:34<br>:39 | 50-<br>EB-<br>F6-<br>B8-<br>AF-<br>47@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>5ASV6<br>LS,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_61<br>DF_4D<br>85. | 否  |   |  |
| 2008 | 福建金莱达<br>建设有限公司       | 2024-<br>04-23<br>18:05<br>:20.0 | 2A-<br>13-<br>4C-<br>06-<br>32-<br>D4@BF<br>EBFBF<br>F0003<br>06F2@<br>MG220<br>63680<br>4675,<br>S3T06<br>RTT  | 否 | 2024-<br>04-22<br>19:26<br>:10.0 | 2A-<br>13-<br>4C-<br>06-<br>32-<br>D4@BF<br>EBFBF<br>F0003<br>06F2@<br>MG220<br>63680<br>4675,<br>S3T06<br>RTT  | 否 |  |  |  |  |  |  |  |  |  |                        | 校验<br>数据有<br>误,请<br>检查         | 2024-<br>04-24<br>08:34<br>:26  | 2A-<br>13-<br>4C-<br>06-<br>32-<br>D4@BF<br>EBFBF<br>F0003<br>06F2@<br>MG220<br>63680<br>4675,<br>S3T06<br>RTT | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2009 | 福建朗澈建筑工程有限公司 | 2024-04-18 16:03:19.0 | 04-D9-F5-D5-E8-86,00-00-00-00-00-06EA@1930AK458313                          | 否 | 2024-04-18 15:49:19.0 | 04-D9-F5-D5-E8-86,00-00-00-00-00-E0@BFEBFBFF000906EA@1930AK458313           | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:45:08 | 04-D9-F5-D5-E8-86,00-00-00-00-00-E0@BFEBFBFF000906EA@1930AK458313           | 否 |  |
| 2010 | 福建聚汤建设有限公司   | 2024-04-23 22:03:11.0 | 08-BF-B8-73-0A-96@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_444A_485A_5681. | 否 | 2024-04-23 18:53:52.0 | 08-BF-B8-73-0A-96@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_444A_485A_5681. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:37:28 | 08-BF-B8-73-0A-96@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_444A_485A_5681. | 否 |  |







|      |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |                         |                                |   |   |   |  |
|------|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|---|---|---|--|
| 2013 | 福建省景烁<br>建筑工程有<br>限公司 | 2024-<br>04-22<br>13:34<br>:24.0 | D8-<br>5E-<br>D3-<br>C6-<br>0C-<br>D5@BF<br>EBFBF<br>F000A<br>0653@<br>58393<br>55230<br>35353<br>397, W<br>D-<br>WCC6Y<br>FL4Y4<br>V6, TY<br>S12MQ<br>01C42<br>31442<br>52 | 否 | 2024-<br>04-22<br>13:31<br>:41.0 | D8-<br>5E-<br>D3-<br>C6-<br>0C-<br>D5@BF<br>EBFBF<br>F000A<br>0653@<br>58393<br>55230<br>35353<br>397, W<br>D-<br>WCC6Y<br>FL4Y4<br>V6, TY<br>S12MQ<br>01C42<br>31442<br>52 | 否 |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:38<br>:04 | D8-<br>5E-<br>D3-<br>C6-<br>0C-<br>D5@BF<br>EBFBF<br>F000A<br>0653@<br>58393<br>55230<br>35353<br>397, W<br>D-<br>WCC6Y<br>FL4Y4<br>V6, TY<br>S12MQ<br>01C42<br>31442<br>52 | 否   |   |  |
| 2014 | 福建省耀鸿<br>工程管理有<br>限公司 | 2024-<br>04-23<br>16:27<br>:01.0 | 48-<br>F3-<br>17-<br>0A-<br>8B-<br>1C@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>2NKT6<br>ES, 20<br>21123<br>10132<br>8   | 否 | 2024-<br>04-23<br>16:24<br>:50.0 | 48-<br>F3-<br>17-<br>0A-<br>8B-<br>1C@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>2NKT6<br>ES, 20<br>21123<br>10132<br>8   | 否 |  |  |  |  |  |  |  |  |                         | 校验<br>数据有<br>误, 请<br>检查        | 2024-<br>04-24<br>08:33<br>:49  | 48-<br>F3-<br>17-<br>0A-<br>8B-<br>1C@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>2NKT6<br>ES, 20<br>21123<br>10132<br>8 | 否 |  |



|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 2017 | 福建佳辰建设有限公司    | 2024-04-23 09:14:47.0 | D8-5E-D3-9C-3F-AC@BF EBFBF F000A 0653@50026 B7381 87B340                       | 否 | 2024-04-19 10:59:28.0 | D8-5E-D3-9C-3F-AC@BF EBFBF F000A 0653@50026 B7381 87B340                       | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:31:25 | D8-5E-D3-9C-3F-AC@BF EBFBF F000A 0653@50026 B7381 87B340                       | 否 |  |
| 2018 | 龙岩市万宏建设工程有限公司 | 2024-04-23 15:35:49.0 | 4C-ED-FB-5E-C8-7C@BF EBFBF F0009 06E9@WD-WCC6Y 4EHSU YL, 50 026B7 3818D 031A   | 否 | 2024-04-23 15:32:30.0 | 4C-ED-FB-5E-C8-7C@BF EBFBF F0009 06E9@WD-WCC6Y 4EHSU YL, 50 026B7 3818D 031A   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:34:19 | 4C-ED-FB-5E-C8-7C@BF EBFBF F0009 06E9@WD-WCC6Y 4EHSU YL, 50 026B7 3818D 031A   | 否 |  |
| 2019 | 河南钦坦建筑工程有限公司  | 2024-04-22 10:41:24.0 | 74-56-3C-AA-BD-73@BF EBFBF F0009 0675@0000_0006_2309_0438_CAF2_5B04_3704_A200. | 否 | 2024-04-19 15:42:26.0 | 74-56-3C-AA-BD-73@BF EBFBF F0009 0675@0000_0006_2309_0438_CAF2_5B04_3704_A200. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请检查 | 2024-04-24 08:31:21 | 74-56-3C-AA-BD-73@BF EBFBF F0009 0675@0000_0006_2309_0438_CAF2_5B04_3704_A200. | 否 |  |

|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|--|---|--|
| 2020 | 厦门乐莱建筑工程有限公司   | 2024-04-18 16:22:12.0 | B4-2E-99-95-2F-FB@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>5ZA0V<br>E3, 19<br>25AK4<br>40308   | 否 | 2024-04-16 15:02:45.0 | B4-2E-99-95-2F-FB@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>5ZA0V<br>E3, 19<br>25AK4<br>40308   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 09:01:41  | B4-2E-99-95-2F-FB@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>5ZA0V<br>E3, 19<br>25AK4<br>40308 | 否 |  |
| 2021 | 厦门市恒冠盛景观工程有限公司 | 2024-04-23 17:03:34.0 | D8-5E-D3-95-A8-8C@BF<br>EBFBF<br>F000A<br>0671@<br>WD-<br>WCC6Y<br>6SX01<br>E8, F6<br>67300<br>71202<br>202, 0<br>000_0<br>000_0<br>000_0<br>000_0<br>000_0<br>026_B<br>738_1<br>4B1_8<br>C35. | 否 | 2024-04-23 16:42:15.0 | D8-5E-D3-95-A8-8C@BF<br>EBFBF<br>F000A<br>0671@<br>WD-<br>WCC6Y<br>6SX01<br>E8, F6<br>67300<br>71202<br>202, 0<br>000_0<br>000_0<br>000_0<br>000_0<br>000_0<br>026_B<br>738_1<br>4B1_8<br>C35. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:54:38 | D8-5E-D3-95-A8-8C@BF<br>EBFBF<br>F000A<br>0671@<br>WD-<br>WCC6Y<br>6SX01<br>E8, F6<br>67300<br>71202<br>202, 0<br>000_0<br>000_0<br>000_0<br>000_0<br>000_0<br>026_B<br>738_1<br>4B1_8<br>C35. | 否  |   |  |

|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2022 | 福建博厚建设工程有限公司  | 2024-04-23 10:58:34.0 | 00-<br>E0-<br>4B-<br>68-<br>20-<br>20-<br>5D@BF<br>EBFBF<br>F0003<br>06A9@<br>0520B<br>67758<br>54F4E<br>4 | 否 | 2024-04-23 10:53:30.0 | 00-<br>E0-<br>4B-<br>68-<br>20-<br>5D, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06A9@<br>0520B<br>67758<br>54F4E<br>4 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:31:25 | 00-<br>E0-<br>4B-<br>68-<br>20-<br>5D@BF<br>EBFBF<br>F0003<br>06A9@<br>0520B<br>67758<br>54F4E<br>4, W -<br>DXW13<br>CAN9V<br>5K6 | 否 |  |
| 2023 | 福建省冠宇园林工程有限公司 | 2024-04-19 18:58:50.0 | 2A-<br>06-<br>A0-<br>48-<br>00-<br>D4@BF<br>EBFBF<br>F0003<br>06F2@<br>SCRW2<br>30721<br>03G03<br>24       | 否 | 2024-04-19 16:36:33.0 | 2A-<br>06-<br>A0-<br>48-<br>00-<br>D4@BF<br>EBFBF<br>F0003<br>06F2@<br>SCRW2<br>30721<br>03G03<br>24   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:38 | 2A-<br>06-<br>A0-<br>48-<br>00-<br>D4@BF<br>EBFBF<br>F0003<br>06F2@<br>SCRW2<br>30721<br>03G03<br>24                              | 否 |  |

|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 2024 | 福建泰闽建设和发展有限公司 | 2024-04-23 17:22:19.0 | D8-BB-C1-37-85-E9@178BFBF F00840F70@9D24070A137000018030                     | 否 | 2024-04-23 17:19:23.0 | D8-BB-C1-37-85-E9@178BFBF F00840F70@9D24070A137000018030                     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:45:46 | D8-BB-C1-37-85-E9@178BFBF F00840F70@9D24070A137000018030                     | 否 |  |
| 2025 | 福建省鸿沁建设工程有限公司 | 2024-04-19 11:17:36.0 | 7C-10-C9-8E-0E-27@BFEBFBF F000A0653@0000_0000_0000_0000_0026_B738_1040_DC75. | 否 | 2024-04-19 11:01:01.0 | 7C-10-C9-8E-0E-27@BFEBFBF F000A0653@0000_0000_0000_0000_0026_B738_1040_DC75. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:40:04 | 7C-10-C9-8E-0E-27@BFEBFBF F000A0653@0000_0000_0000_0000_0026_B738_1040_DC75. | 否 |  |









|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2030 | 福建省曹邦建筑有限公司   | 2024-04-23 17:57:35.0 | 08-BF-B8-01-A1-6B@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0000_ 0100_ 0000_ 0000. ,WD-WCC6Y 3UK4Y D7 | 否 | 2024-04-23 17:55:49.0 | 08-BF-B8-01-A1-6B@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0000_ 0100_ 0000_ 0000. ,WD-WCC6Y 3UK4Y D7 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:40:09 | 08-BF-B8-01-A1-6B@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 0000_ 0100_ 0000_ 0000. ,WD-WCC6Y 3UK4Y D7 | 否 |  |
| 2031 | 福建省代兴建设发展有限公司 | 2024-04-23 10:53:40.0 | 08-BF-B8-30-13-67@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 00E0_ 4C15_ 0869_ E760.                    | 否 | 2024-04-23 10:52:26.0 | 08-BF-B8-30-13-67@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 00E0_ 4C15_ 0869_ E760.                    | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:19 | 08-BF-B8-30-13-67@BF EBFBF F000A 0653@ 0000_ 0000_ 0000_ 0000_ 00E0_ 4C15_ 0869_ E760.                    | 否 |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2032 | 福建鼎强建设有限公司    | 2024-04-19 11:17:58.0 | 00-E0-4C-49-0D-52@BFEBFBFF000A0653@YS2124037YHVS00409                       | 否 | 2024-04-19 11:06:17.0 | 00-E0-4C-49-0D-52@BFEBFBFF000A0653@YS2124037YHVS00409                       | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:34:39 | 00-E0-4C-49-0D-52@BFEBFBFF000A0653@YS2124037YHVS00409                       | 否 |  |
| 2033 | 福建省港旭建设工程有限公司 | 2024-04-23 17:20:18.0 | 18-C0-4D-F6-AB-A6@BFEBFBFF000A0653@WKCH3200414,50026B7380E92B4C             | 否 | 2024-04-23 17:19:21.0 | 18-C0-4D-F6-AB-A6@BFEBFBFF000A0653@WKCH3200414,50026B7380E92B4C             | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:35:49 | 18-C0-4D-F6-AB-A6@BFEBFBFF000A0653@WKCH3200414,50026B7380E92B4C             | 否 |  |
| 2034 | 福建飞驰建设工程有限公司  | 2024-04-23 08:05:41.0 | 00-E0-4C-49-92-0D@BFEBFBFF000906E9@2020202057202d4443573643335952595259444e | 否 | 2024-04-22 16:48:00.0 | 00-E0-4C-49-92-0D@BFEBFBFF000906E9@5359303232323830303036342020202020202020 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:33:53 | 00-E0-4C-49-92-0D@BFEBFBFF000906E9@2020202057202d4443573643335952595259444e | 否 |  |



|      |                     |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |  |  |                     |                        |  |   |  |
|------|---------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|--|---------------------|------------------------|--|---|--|
| 2037 | 天诚建业<br>(福建) 建设有限公司 | 2024-04-23<br>15:32:24.0 | D4-<br>5D-<br>64-<br>B7-<br>EF-<br>6D@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WX42D<br>327XZ<br>8F, S4<br>XDNG0<br>N6176<br>67T  | 否 | 2024-04-22<br>14:35:14.0 | D4-<br>5D-<br>64-<br>B7-<br>EF-<br>6D@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WX42D<br>327XZ<br>8F, S4<br>XDNG0<br>N6176<br>67T  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>检 | 2024-04-24<br>08:42:06 | D4-<br>5D-<br>64-<br>B7-<br>EF-<br>6D@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WX42D<br>327XZ<br>8F, S4<br>XDNG0<br>N6176<br>67T  | 否 |  |
| 2038 | 福建众朗建<br>设有限公司      | 2024-04-23<br>09:04:53.0 | 08-<br>BF-<br>B8-<br>85-<br>D3-<br>5E@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC4M<br>3XNK1<br>FV, 50<br>026B7<br>380B8<br>20ED | 否 | 2024-04-22<br>09:51:32.0 | 08-<br>BF-<br>B8-<br>85-<br>D3-<br>5E@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC4M<br>3XNK1<br>FV, 50<br>026B7<br>380B8<br>20ED | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>检 | 2024-04-24<br>08:36:38 | 08-<br>BF-<br>B8-<br>85-<br>D3-<br>5E@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC4M<br>3XNK1<br>FV, 50<br>026B7<br>380B8<br>20ED | 否 |  |



|      |                |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|------|----------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
|      |                |                                  | 06EA@<br>ZN1DD<br>2MM, M<br>G2103<br>11091<br>7   |   |                                  | 06EA@<br>ZN1DD<br>2MM, M<br>G2103<br>11091<br>7   |   |  |  |  |  |  |  |  |  |  |                            |                                | 06EA@<br>ZN1DD<br>2MM, M<br>G2103<br>11091<br>7   |   |  |
| 2042 | 福建中魁建<br>设有限公司 | 2024-<br>04-23<br>17:27<br>:23.0 | D8-<br>BB-<br>C1-<br>C9-<br>EF-<br>32@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>14FB_<br>16A5. | 否 | 2024-<br>04-22<br>11:04<br>:11.0 | D8-<br>BB-<br>C1-<br>C9-<br>EF-<br>32@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>14FB_<br>16A5. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:34<br>:25 | D8-<br>BB-<br>C1-<br>C9-<br>EF-<br>32@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>14FB_<br>16A5. | 否 |  |

|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |   |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|--|---|--|
| 2043 | 福建若洲建设有限公司 | 2024-04-23 16:54:29.0 | 4C-82-A9-56-16-2D, 4E-82-A9-56-16-2D, 42-82-A9-56-16-2D, CC-96-E5-4A-20-6F, 4C-82-A9-56-16-2E@BF EBFBF F000B 06F5@ C8D6_ B799_ 31B1_ 30E6. | 否 | 2024-04-23 16:52:17.0 | 4C-82-A9-56-16-2D, 4E-82-A9-56-16-2D, 42-82-A9-56-16-2D, CC-96-E5-4A-20-6F, 4C-82-A9-56-16-2E@BF EBFBF F000B 06F5@ C8D6_ B799_ 31B1_ 30E6. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:43:33 | 4C-82-A9-56-16-2D, 4E-82-A9-56-16-2D, CC-96-E5-4A-20-6F, 4C-82-A9-56-16-2E@BF EBFBF F000B 06F5@ C8D6_ B799_ 31B1_ 30E6. | 否  |   |  |
| 2044 | 福建港永建工有限公司 | 2024-04-23 14:57:03.0 | A0-36-BC-09-99-3F@BF EBFBF F0009 0672@ WW000 00000 00000 00696   | 否 | 2024-04-23 14:54:28.0 | A0-36-BC-09-99-3F@BF EBFBF F0009 0672@ WW000 00000 00000 00696   | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:36:20   | A0-36-BC-09-99-3F@BF EBFBF F0009 0672@ WW000 00000 00000 00696 | 否 |  |









|      |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 2051 | 南平市政通房屋征收工程有限公司 | 2024-04-16 16:46:28.0 | E0-D5-5E-32-53-DD@BF EBFBF F0009 06E9@WD-WCC6Y 4DRD1 H8, TW 17A17 04313                      | 否 | 2024-04-16 16:43:34.0 | E0-D5-5E-32-53-DD@BF EBFBF F0009 06E9@WD-WCC6Y 4DRD1 H8, TW 17A17 04313                      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:25 | E0-D5-5E-32-53-DD@BF EBFBF F0009 06E9@WD-WCC6Y 4DRD1 H8, TW 17A17 04313      | 否 |  |
| 2052 | 福建鸿业盛建筑工程有限公司   | 2024-04-22 16:40:10.0 | 3C-7C-3F-53-13-FD@BF EBFBF F0009 06EA@49543 8EE1A 62, 50 026B7 7846A 8690, WD-WCC6Y 7EYRV LP | 否 | 2024-04-22 16:36:01.0 | 3C-7C-3F-53-13-FD@BF EBFBF F0009 06EA@49543 8EE1A 62, 50 026B7 7846A 8690, WD-WCC6Y 7EYRV LP | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:40:27 | 3C-7C-3F-53-13-FD@BF EBFBF F0009 06EA@50026 B7784 6A869 0, WD-WCC6Y 7EYRV LP | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 2053 | 福建闽泰交通工程有限公司 | 2024-04-22 14:18:22.0 | 00-<br>CF-<br>E0-<br>3D-<br>4B-<br>AB@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>2YL31<br>AH                                       | 否 | 2024-04-22 14:12:17.0 | 00-<br>CF-<br>E0-<br>3D-<br>4B-<br>AB, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>2YL31<br>AH | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:45 | 00-<br>CF-<br>E0-<br>3D-<br>4B-<br>AB@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>2YL31<br>AH                                       | 否 |  |
| 2054 | 福建博大建设工程有限公司 | 2024-04-23 08:53:49.0 | 84-<br>E0-<br>58-<br>B1-<br>2E-<br>93@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC4J<br>7SZUA<br>65, AA<br>00000<br>00100<br>60006<br>324 | 否 | 2024-04-23 08:51:17.0 | 84-<br>E0-<br>58-<br>B1-<br>2E-<br>93@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC4J<br>7SZUA<br>65, AA<br>00000<br>00100<br>60006<br>324   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:35 | 84-<br>E0-<br>58-<br>B1-<br>2E-<br>93@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC4J<br>7SZUA<br>65, AA<br>00000<br>00100<br>60006<br>324 | 否 |  |











|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|---|--|
| 2060 | 福建旭耀建设有限公司    | 2024-04-22 18:47:11.0 | A8-5E-45-5B-2B-F9@BF EBFBF F0009 06EB@WD-WCC6Y ODR5J E5,00 00_00 00_00 00_00 00_48 68_34 00_00 00_00 00. | 否 | 2024-04-22 11:19:22.0 | A8-5E-45-5B-2B-F9@BF EBFBF F0009 06EB@WD-WCC6Y ODR5J E5,00 00_00 00_00 00_00 00_48 68_34 00_00 00_00 00. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:47 | A8-5E-45-5B-2B-F9@BF EBFBF F0009 06EB@WD-WCC6Y ODR5J E5,00 00_00 00_00 00_00 00_48 68_34 00_00 00_00 00. | 否   |   |  |
| 2061 | 深圳市瑞壹建设工程有限公司 | 2024-04-23 13:47:30.0 | 00-E0-4C-61-53-74@BF EBFBF F000A 0653@5A210 7280C 1A003 90815, AA20 23060 11917                          | 否 | 2024-04-22 14:11:44.0 | 00-E0-4C-61-53-74@BF EBFBF F000A 0653@5A210 7280C 1A003 90815, AA20 23060 11917                          | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:50:09  | 00-E0-4C-61-53-74@BF EBFBF F000A 0653@5A210 7280C 1A003 90815, AA20 23060 11917 | 否 |  |





|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2065 | 中建鹭港建设有限公司    | 2024-04-23 12:32:19.0 | 04-D9-F5-AB-2E-7C@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>E858A<br>6                   | 否 | 2024-04-23 12:31:23.0 | 04-D9-F5-AB-2E-7C@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>E858A<br>6                   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:40 | 04-D9-F5-AB-2E-7C@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7380<br>E858A<br>6                   | 否 |  |
| 2066 | 福建众悦泰建设工程有限公司 | 2024-04-23 10:22:43.0 | E8-9C-25-C3-07-0E@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_444A_485D_7F59.      | 否 | 2024-04-23 10:17:42.0 | E8-9C-25-C3-07-0E@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_444A_485D_7F59.      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:04 | E8-9C-25-C3-07-0E@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_444A_485D_7F59.      | 否 |  |
| 2067 | 宁德金美鑫建设发展有限公司 | 2024-04-22 11:15:25.0 | 00-E0-4C-87-3A-48@BF<br>EBFBF<br>F0005<br>06E3@<br>0000_0000_0000_0000_0000_0026_ B768_6658_35F5. | 否 | 2024-04-22 11:01:17.0 | 00-E0-4C-87-3A-48@BF<br>EBFBF<br>F0005<br>06E3@<br>0000_0000_0000_0000_0000_0026_ B768_6658_35F5. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:54 | 00-E0-4C-87-3A-48@BF<br>EBFBF<br>F0005<br>06E3@<br>0000_0000_0000_0000_0000_0026_ B768_6658_35F5. | 否 |  |





















|      |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|
| 2081 | 福建翔豪建设工程有限公司 | 2024-04-23 08:49:45.0 | 22-03-4D-01-68-3C, C8-3A-35-E0-60-81, C8-3A-35-E0-60-80@BFEBFBF000306F2@1000_0102_1120_0D22. | 否 | 2024-04-22 17:05:02.0 | 22-03-4D-01-68-3C, C8-3A-35-E0-60-81, C8-3A-35-E0-60-82, C8-3A-35-E0-60-80@BFEBFBF000306F2@1000_0102_1120_0D22. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:40:04 | 22-03-4D-01-68-3C, C8-3A-35-E0-60-81, C8-3A-35-E0-60-82, C8-3A-35-E0-60-80@BFEBFBF000306F2@1000_0102_1120_0D22. | 否 |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2082 | 福建大田居屋集团有限公司 | 2024-04-22 09:45:21.0 | 18-<br>C0-<br>4D-<br>C6-<br>85-<br>AA@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2R50S<br>NC, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1D<br>B0_74<br>C5. | 否 | 2024-04-18 09:25:58.0 | 18-<br>C0-<br>4D-<br>C6-<br>85-<br>AA@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2R50S<br>NC, 00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1D<br>B0_74<br>C5. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:51 | 74-<br>56-<br>3C-<br>7B-<br>FD-<br>4A, 00<br>-4B-<br>F3-<br>DE-<br>99-<br>74@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>21F3_<br>FDA5.<br>, WD-<br>WCC6Y<br>PZ95N<br>L0 | 否 |  |
| 2083 | 中建国荣工程有限公司   | 2024-04-23 14:23:46.0 | FC-<br>AA-<br>14-<br>24-<br>A4-<br>3C@BF<br>EBFBF<br>F0003<br>06C3@<br>AA000<br>00000<br>00000<br>00932   | 否 | 2024-04-23 14:21:59.0 | FC-<br>AA-<br>14-<br>24-<br>A4-<br>3C, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>AA000<br>00000<br>00000<br>00932                                 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:51:10 | FC-<br>AA-<br>14-<br>24-<br>A4-<br>3C@BF<br>EBFBF<br>F0003<br>06C3@<br>AA000<br>00000<br>00000<br>00932   | 否 |  |



|      |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |   |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|---|--|
| 2084 | 安徽争九建设工程有限公司 | 2024-04-23 15:10:25.0 | 74-56-3C-8F-60-65@BF<br>EBFBF<br>F0009<br>06EA@<br>NKC99<br>22025<br>7100S<br>304   | 否 | 2024-04-23 15:06:07.0 | 74-56-3C-8F-60-65@BF<br>EBFBF<br>F0009<br>06EA@<br>NKC99<br>22025<br>7100S<br>304  | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:41:52   | 74-56-3C-8F-60-65@BF<br>EBFBF<br>F0009<br>06EA@<br>NKC99<br>22025<br>7100S<br>304 | 否 |  |
| 2085 | 红谷滩建设集团有限公司  | 2024-04-23 17:01:50.0 | 00-<br>E0-<br>70-<br>9F-<br>3F-<br>7D@BF<br>EBFBF<br>F0009<br>06E9@<br>30323<br>13231<br>30323<br>23032<br>34312<br>03620<br>20202<br>02020 | 否 | 2024-04-23 16:39:05.0 | 00-<br>E0-<br>70-<br>9F-<br>3F-<br>7D, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>30323<br>13231<br>30323<br>23032<br>34312<br>03620<br>20202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:47:02 | 00-<br>E0-<br>70-<br>9F-<br>3F-<br>7D@BF<br>EBFBF<br>F0009<br>06E9@<br>30323<br>13231<br>30323<br>23032<br>34312<br>03620<br>20202<br>02020 | 否   |   |  |



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 2088 | 福建永向建设发展有限公司 | 2024-04-23 19:48:41.0 | A0-36-BC-21-D7-70@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4B81_<br>671F. | 否 | 2024-04-23 19:45:17.0 | A0-36-BC-21-D7-70@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4B81_<br>671F. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:40:33 | A0-36-BC-21-D7-70@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4B81_<br>671F. | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|





|      |                   |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
|------|-------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|
| 2092 | 福建省鑫源<br>建筑工程有限公司 | 2024-<br>04-22<br>19:45<br>:31.0 | 04-<br>39-<br>26-<br>E4-<br>82-<br>72,04<br>-39-<br>26-<br>E4-<br>82-<br>71,06<br>-39-<br>26-<br>E4-<br>82-<br>71,06<br>-39-<br>26-<br>E4-<br>82-<br>71@BF<br>EBFBF<br>F0009<br>06C0@<br>20221<br>02001<br>673 | 否 | 2024-<br>04-22<br>19:43<br>:42.0 | 06-<br>39-<br>26-<br>E4-<br>82-<br>71,86<br>-39-<br>26-<br>E4-<br>82-<br>71,04<br>-39-<br>26-<br>E4-<br>82-<br>71,04<br>-39-<br>26-<br>E4-<br>82-<br>72@BF<br>EBFBF<br>F0009<br>06C0@<br>20221<br>02001<br>673 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:33<br>:07 | 04-<br>39-<br>26-<br>E4-<br>82-<br>72,04<br>-39-<br>26-<br>E4-<br>82-<br>71,06<br>-39-<br>26-<br>E4-<br>82-<br>71,06<br>-39-<br>26-<br>E4-<br>82-<br>71,06<br>-39-<br>26-<br>E4-<br>82-<br>71@BF<br>EBFBF<br>F0009<br>06C0@<br>20221<br>02001<br>673 | 否 |  |
|------|-------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2095 | 福建利全建设工程有限公司 | 2024-04-20 11:19:49.0 | CC-D9-AC-57-8C-71, CC-D9-AC-57-8C-71@BF EBFBF F0007 06E5@ S3TRN XOMB1 4296  | 否 | 2024-04-20 11:16:53.0 | CC-D9-AC-57-8C-72, CE-D9-AC-57-8C-71, CC-D9-AC-57-8C-71@BF EBFBF F0007 06E5@ S3TRN XOMB1 4296                             | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:55:51 | CC-D9-AC-57-8C-71, CC-D9-AC-57-8C-72@BF EBFBF F0007 06E5@ S3TRN XOMB1 4296  | 否 |  |
| 2096 | 福建点创建设工程有限公司 | 2024-04-23 09:48:54.0 | E8-9C-25-42-1A-C9@BF EBFBF F0009 0675@ 20071 11417 34000 00, S2 ARLPL P, E82 3_8FA 6_BF5 3_000 1_001 B_444 A_48B 2_D81 9. | 否 | 2024-04-23 08:37:43.0 | E8-9C-25-42-1A-C9@BF EBFBF F0009 0675@ 20071 11417 34000 00, S2 ARLPL P, E82 3_8FA 6_BF5 3_000 1_001 B_444 A_48B 2_D81 9. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:36:34 | E8-9C-25-42-1A-C9@BF EBFBF F0009 0675@ 20071 11417 34000 00, S2 ARLPL P, E82 3_8FA 6_BF5 3_000 1_001 B_444 A_48B 2_D81 9. | 否 |  |



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 2097 | 福建宸盈建设有限公司   | 2024-04-23 09:57:18.0 | 00-E2-69-63-C0-6D, 68-DD-B7-AE-05-BE, 68-DD-B7-AE-05-BE@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0001. | 否 | 2024-04-23 09:55:42.0 | 00-E2-69-63-C0-6D, 68-DD-B7-AE-05-BE, 68-DD-B7-AE-05-BE@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0001. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:43:25 | 00-E2-69-63-C0-6D, 68-DD-B7-AE-05-BE, 68-DD-B7-AE-05-BE@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0001. | 否 |  |
| 2098 | 内蒙古新开元建设有限公司 | 2024-04-22 17:52:01.0 | 00-E2-69-77-6E-42@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 00E0_ 4C66_ 0361_ D932.               | 否 | 2024-04-22 17:38:54.0 | 00-E2-69-77-6E-42@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 00E0_ 4C66_ 0361_ D932.               | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:40 | 00-E2-69-77-6E-42@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 0000_ 00E0_ 4C66_ 0361_ D932.               | 否 |  |

|      |                |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|------|----------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 2099 | 三明亿恒顺建设工程有限公司  | 2024-04-23 11:36:08.0 | 24-4B-FE-04-F3-28, F4-6D-2F-DD-C4-32, F4-6D-2F-DD-C4-32@BF EBFBF F0009 06EA@K2005 03B03 075, WD-WCC6Y OKF17 R9 | 否 | 2024-04-23 11:35:37.0 | 24-4B-FE-04-F3-28, F4-6D-2F-DD-C4-32@BF EBFBF F0009 06EA@K2005 03B03 075, WD-WCC6Y OKF17 R9 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:35:53 | 24-4B-FE-04-F3-28, F4-6D-2F-DD-C4-32@BF EBFBF F0009 06EA@K2005 03B03 075, WD-WCC6Y OKF17 R9 | 否   |   |  |
| 2100 | 福建点位建设工程有限公司   | 2024-04-23 14:29:09.0 | FC-34-97-12-23-0C@BF EBFBF F000A 0653@ 50026 B7380 DF9FAB  | 否 | 2024-04-23 14:26:49.0 | FC-34-97-12-23-0C@BF EBFBF F000A 0653@ 50026 B7380 DF9FAB                                   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误差，请检查         | 2024-04-24 08:31:33   | FC-34-97-12-23-0C@BF EBFBF F000A 0653@ 50026 B7380 DF9FAB | 否 |  |
| 2101 | 福建荣益永晟建设工程有限公司 | 2024-04-23 09:20:40.0 | 74-56-3C-10-83-3F@BF EBFBF F000A 0653@   | 否 | 2024-04-23 09:18:25.0 | 74-56-3C-10-83-3F@BF EBFBF F000A 0653@  | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误差，请检查         | 2024-04-24 08:40:27   | 74-56-3C-10-83-3F@BF EBFBF F000A 0653@                    | 否 |  |

|      |            |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |  |  |                            |   |   |  |
|------|------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|----------------------------|---|---|--|
|      |            |                              | WD-<br>WCC6Y<br>OSSEF<br>94,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_5F<br>E1_98<br>95.                                    |   |                              | WD-<br>WCC6Y<br>OSSEF<br>94,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_5F<br>E1_98<br>95.                                    |   |  |  |  |  |  |  |  |  |  |  | WD-<br>WCC6Y<br>OSSEF<br>94,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_5F<br>E1_98<br>95. |                            |   |   |  |
| 2102 | 福建广大建设有限公司 | 2024-04-23<br>10:40<br>:32.0 | 88-<br>AE-<br>DD-<br>5D-<br>C4-<br>3D@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WX62D<br>43276<br>3L,5C<br>DF_B8<br>03_70<br>CO_1B<br>58. | 否 | 2024-04-23<br>10:39<br>:30.0 | 88-<br>AE-<br>DD-<br>5D-<br>C4-<br>3D@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WX62D<br>43276<br>3L,5C<br>DF_B8<br>03_70<br>CO_1B<br>58. | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查   | 2024-04-24<br>08:34<br>:13 | 88-<br>AE-<br>DD-<br>5D-<br>C4-<br>3D@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WX62D<br>43276<br>3L,5C<br>DF_B8<br>03_70<br>CO_1B<br>58. | 否 |  |



|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|---|--|
| 2105 | 福建运泽建筑工程有限公司  | 2024-04-23 16:15:56.0 | 08-BF-B8-3E-E5-A3@BF<br>EBFBF<br>F0009<br>0672@<br>W9ATT<br>MPG, 3<br>00995<br>63133                                 | 否 | 2024-04-23 16:15:03.0 | 08-BF-B8-3E-E5-A3@BF<br>EBFBF<br>F0009<br>0672@<br>W9ATT<br>MPG, 3<br>00995<br>63133                                 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请查 | 2024-04-24 08:50:51 | 08-BF-B8-3E-E5-A3@BF<br>EBFBF<br>F0009<br>0672@<br>W9ATT<br>MPG, 3<br>00995<br>63133                                 | 否   |   |  |
| 2106 | 福建耀聚建筑工程有限公司  | 2024-04-23 08:58:51.0 | 2C-F0-5D-3D-B4-5A@17<br>8BFBF<br>F00A5<br>0F00@<br>WD-<br>WCC6Y<br>1XFST<br>Z4, 00<br>00_00<br>00_00<br>00_00<br>01. | 否 | 2024-04-23 08:58:06.0 | 2C-F0-5D-3D-B4-5A@17<br>8BFBF<br>F00A5<br>0F00@<br>WD-<br>WCC6Y<br>1XFST<br>Z4, 00<br>00_00<br>00_00<br>00_00<br>01. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请查 | 2024-04-24 08:36:45 | 2C-F0-5D-3D-B4-5A@17<br>8BFBF<br>F00A5<br>0F00@<br>WD-<br>WCC6Y<br>1XFST<br>Z4, 00<br>00_00<br>00_00<br>00_00<br>01. | 否   |   |  |
| 2107 | 福建省樟榕建设工程有限公司 | 2024-04-22 15:59:24.0 | 48-F3-17-13-4E-5F@BF<br>EBFBF<br>F000A<br>0653@<br>7392K<br>23494<br>1263,<br>WD-<br>WCC6Y<br>9UVMH<br>P2            | 否 | 2024-04-22 15:55:46.0 | 48-F3-17-13-4E-5F@BF<br>EBFBF<br>F000A<br>0653@<br>7392K<br>23494<br>1263,<br>WD-<br>WCC6Y<br>9UVMH<br>P2            | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误, 请查          | 2024-04-24 08:35:20  | 48-F3-17-13-4E-5F@BF<br>EBFBF<br>F000A<br>0653@<br>7392K<br>23494<br>1263,<br>WD-<br>WCC6Y<br>9UVMH<br>P2 | 否 |  |

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2108 | 福建省福乾建设发展有限公司  | 2024-04-17 15:29:58.0 | B4-2E-99-BA-A5-5D@BFEBFBFF000906EB@19425L485811                             | 否 | 2024-04-17 15:28:06.0 | B4-2E-99-BA-A5-5D@BFEBFBFF000906EB@19425L485811                             | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:22 | B4-2E-99-BA-A5-5D@BFEBFBFF000906EB@19425L485811                             | 否 |  |
| 2109 | 福建南平剑州建设工程有限公司 | 2024-04-23 16:12:36.0 | 08-BF-B8-3A-3D-2A@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_444A_49DF_2A85. | 否 | 2024-04-23 11:28:58.0 | 08-BF-B8-3A-3D-2A@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_444A_49DF_2A85. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:49 | 08-BF-B8-3A-3D-2A@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_444A_49DF_2A85. | 否 |  |

|      |                 |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |              |                     |   |  |   |  |
|------|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--------------|---------------------|---|--|---|--|
| 2110 | 福建银洲建设工程有限公司    | 2024-04-23 15:48:41.0 | F0-2F-74-4E-D0-08@BF EBFBF F0009 06EA@41533 15a30 39323 53037 31313 03120 20202 02020 ,2020 20202 02020 20202 02020 02020 39575 44154 54475 2 | 否 | 2024-04-23 15:17:45.0 | F0-2F-74-4E-D0-08@BF EBFBF F0009 06EA@41533 15a30 39323 53037 31313 03120 20202 02020 ,2020 20202 02020 20202 02020 02020 39575 44154 54475 2 | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:39:40 | F0-2F-74-4E-D0-08@BF EBFBF F0009 06EA@41533 15a30 39323 53037 31313 03120 20202 02020 ,2020 20202 02020 20202 02020 02020 39575 44154 54475 2 | 否  |   |  |
| 2111 | 浙江布拉雷水利水电建筑有限公司 | 2024-04-23 16:34:15.0 | 00-E0-4C-5C-C9-32@17 8BFBF F00A5 0F00@ 0000_ 0006_ 2306_ 0030_ 3A5A_ 2703_ 6000_ 03C9.  | 否 | 2024-04-23 16:32:45.0 | 00-E0-4C-5C-C9-32@17 8BFBF F00A5 0F00@ 0000_ 0006_ 2306_ 0030_ 3A5A_ 2703_ 6000_ 03C9.  | 否 |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:36:38   | 00-E0-4C-5C-C9-32@17 8BFBF F00A5 0F00@ 0000_ 0006_ 2306_ 0030_ 3A5A_ 2703_ 6000_ 03C9. | 否 |  |













|      |              |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |  |  |                            |  |   |  |
|------|--------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|--|----------------------------|--|---|--|
|      |              |                              |  |   |                              | 44832<br>52484<br>3  |   |  |  |  |  |  |  |  |  |  |  |  |                            |  |   |  |
| 2118 | 河南龙宸建设工程有限公司 | 2024-04-23<br>15:33<br>:50.0 | 00-<br>E0-<br>1D-<br>63-<br>EA-<br>OB@BF<br>EBFBF<br>F0009<br>0675@<br>SCRW2<br>31023<br>03G03<br>31                                   | 否 | 2024-04-23<br>09:56<br>:01.0 | 00-<br>E0-<br>1D-<br>63-<br>EA-<br>OB@BF<br>EBFBF<br>F0009<br>0675@<br>SCRW2<br>31023<br>03G03<br>31                                   | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>查<br>查 | 2024-04-24<br>08:50<br>:25 | 00-<br>E0-<br>1D-<br>63-<br>EA-<br>OB@BF<br>EBFBF<br>F0009<br>0675@<br>SCRW2<br>31023<br>03G03<br>31                                   | 否 |  |
| 2119 | 福建金合宸建设有限公司  | 2024-04-23<br>08:20<br>:34.0 | A0-<br>36-<br>BC-<br>35-<br>BB-<br>02@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>DAWY<br>UD, EA<br>GET20<br>22040<br>7R008<br>96 | 否 | 2024-04-22<br>17:05<br>:11.0 | A0-<br>36-<br>BC-<br>35-<br>BB-<br>02@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>DAWY<br>UD, EA<br>GET20<br>22040<br>7R008<br>96 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>查<br>查 | 2024-04-24<br>08:33<br>:07 | A0-<br>36-<br>BC-<br>35-<br>BB-<br>02@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>DAWY<br>UD, EA<br>GET20<br>22040<br>7R008<br>96 | 否 |  |



|      |                      |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                              |                                |   |  |  |  |
|------|----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|------------------------------|--------------------------------|---|--|--|--|
|      |                      |                                  | 50026<br>B7381<br>C7FEE<br>1  |   | 50026<br>B7381<br>C7FEE<br>1     |   |   |  |  |  |  |  |  |  |  |  |                              |                                |   | 9B-<br>96, 12<br>-68-<br>38-<br>0C-<br>8B-<br>86@BF<br>EBFBF<br>F000B<br>06A2@<br>0025_<br>38EC_<br>21B2_<br>8854. |  |  |
| 2122 | 福建红森建<br>设工程有限<br>公司 | 2024-<br>04-18<br>15:05<br>:47.0 | A8-<br>5E-<br>45-<br>B4-<br>42-<br>E8@BF<br>EBFBF<br>F0003<br>06C3@<br>4e533<br>13232<br>35383<br>03439<br>39323<br>23820<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>444d5<br>73343<br>30463<br>84a38<br>35465<br>7 | 否 | 2024-<br>04-18<br>15:03<br>:36.0 | A8-<br>5E-<br>45-<br>B4-<br>42-<br>E8@BF<br>EBFBF<br>F0003<br>06C3@<br>4e533<br>13232<br>35383<br>03439<br>39323<br>23820<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>444d5<br>73343<br>30463<br>84a38<br>35465<br>7 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:31<br>:24 | A8-<br>5E-<br>45-<br>B4-<br>42-<br>E8@BF<br>EBFBF<br>F0003<br>06C3@<br>4e533<br>13232<br>35383<br>03439<br>39323<br>23820<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>444d5<br>73343<br>30463<br>84a38<br>35465<br>7 | 否  |  |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2123 | 福州申正建设有限公司    | 2024-04-22 18:27:55.0 | 04-42-1A-32-4F-17@BF<br>EBFBF<br>F000A<br>0653@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>448B<br>4126<br>3120.<br>, WD-<br>WCC6Y<br>7AKTJ<br>J1 | 否 | 2024-04-22 18:27:06.0 | 04-42-1A-32-4F-17@BF<br>EBFBF<br>F000A<br>0653@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>448B<br>4126<br>3120.<br>, WD-<br>WCC6Y<br>7AKTJ<br>J1 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:40:11 | 04-42-1A-32-4F-17@BF<br>EBFBF<br>F000A<br>0653@<br>E823<br>8FA6<br>BF53<br>0001<br>001B<br>448B<br>4126<br>3120.<br>, WD-<br>WCC6Y<br>7AKTJ<br>J1 | 否 |  |
| 2124 | 福建省蓝祥生态环保有限公司 | 2024-04-23 11:30:27.0 | A0-36-BC-A7-2A-D7@BF<br>EBFBF<br>F0009<br>0672@<br>0000<br>0000<br>0000<br>0000<br>0026<br>B738<br>1962<br>D995.<br>, WD-<br>WCC6Y<br>RH19P<br>YL | 否 | 2024-04-23 11:28:33.0 | A0-36-BC-A7-2A-D7@BF<br>EBFBF<br>F0009<br>0672@<br>0000<br>0000<br>0000<br>0000<br>0026<br>B738<br>1962<br>D995.<br>, WD-<br>WCC6Y<br>RH19P<br>YL | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:30 | A0-36-BC-A7-2A-D7@BF<br>EBFBF<br>F0009<br>0672@<br>0000<br>0000<br>0000<br>0000<br>0026<br>B738<br>1962<br>D995.<br>, WD-<br>WCC6Y<br>RH19P<br>YL | 否 |  |





|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 2127 | 福建宏昌工程管理有限公司  | 2024-04-19 11:42:19.0 | C8-7F-54-6E-FA-7B@BF EBFBF F000A 0653@ 4d433 73142 33314 83037 33373 73120 20202 02020 | 否 | 2024-04-19 09:49:13.0 | C8-7F-54-6E-FA-7B, 00 -00- 00- 00- 00- 00- 00- 00- E0@BF EBFBF F000A 0653@ 4d433 73142 33314 83037 33373 73120 20202 02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:36:34 | C8-7F-54-6E-FA-7B@BF EBFBF F000A 0653@ 4d433 73142 33314 83037 33373 73120 20202 02020 | 否 |  |
| 2128 | 福建八億八建设发展有限公司 | 2024-04-23 16:13:37.0 | 04-D4-C4-4B-C1-EF@17 8BFBF F0081 0F10@ 0000_ 0000_ 0000_ 0000_ 8CE3_ 8E03_ 0021_ E25F. | 否 | 2024-04-23 16:07:54.0 | 04-D4-C4-4B-C1-EF@17 8BFBF F0081 0F10@ 0000_ 0000_ 0000_ 0000_ 8CE3_ 8E03_ 0021_ E25F.                                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:40:42 | 04-D4-C4-4B-C1-EF@17 8BFBF F0081 0F10@ 0000_ 0000_ 0000_ 0000_ 8CE3_ 8E03_ 0021_ E25F. | 否 |  |

|      |                      |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |                            |                            |   |   |  |
|------|----------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|---|--|
| 2129 | 闽华晟建设<br>发展有限公司      | 2024-04-23<br>11:12<br>:47.0 | D8-<br>5E-<br>D3-<br>C5-<br>26-<br>38@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1DBE_<br>1F05.                                       | 否 | 2024-04-23<br>11:02<br>:54.0 | D8-<br>5E-<br>D3-<br>C5-<br>26-<br>38@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1DBE_<br>1F05.                                       | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:32<br>:52 | D8-<br>5E-<br>D3-<br>C5-<br>26-<br>38@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1DBE_<br>1F05.                                       | 否 |  |
| 2130 | 福建文渊建<br>设工程有限<br>公司 | 2024-04-23<br>11:29<br>:54.0 | 3C-<br>7C-<br>3F-<br>C3-<br>CB-<br>37, 48<br>-8A-<br>D2-<br>C8-<br>01-<br>61, 4A<br>-8A-<br>D2-<br>C8-<br>01-<br>61@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7783<br>95341<br>9 | 否 | 2024-04-23<br>11:22<br>:16.0 | 3C-<br>7C-<br>3F-<br>C3-<br>CB-<br>37, 4A<br>-8A-<br>D2-<br>C8-<br>01-<br>61, 48<br>-8A-<br>D2-<br>C8-<br>01-<br>61@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7783<br>95341<br>9 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:33<br>:27 | 3C-<br>7C-<br>3F-<br>C3-<br>CB-<br>37, 48<br>-8A-<br>D2-<br>C8-<br>01-<br>61, 4A<br>-8A-<br>D2-<br>C8-<br>01-<br>61@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7783<br>95341<br>9 | 否 |  |





|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|---|--|
| 2134 | 鑫隆（贵州）建设发展有限公司 | 2024-04-23 15:42:27.0 | 08-BF-83-41-C1@BF<br>EBFBF<br>F000A<br>0653@<br>0025_<br>3882_<br>01B5_<br>77A9.                      | 否 | 2024-04-23 15:39:20.0 | 08-BF-83-41-C1@BF<br>EBFBF<br>F000A<br>0653@<br>0025_<br>3882_<br>01B5_<br>77A9.                      | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:39:29 | 08-BF-83-41-C1@BF<br>EBFBF<br>F000A<br>0653@<br>0025_<br>3882_<br>01B5_<br>77A9.                      | 否   |   |  |
| 2135 | 福建廷廂建筑工程有限公司   | 2024-04-18 14:12:55.0 | D8-BB-C1-6D-37-A4@BF<br>EBFBF<br>F000A<br>0653@<br>80G1S<br>5CZSC<br>WH, 50<br>026B7<br>3813B<br>CB49 | 否 | 2024-04-18 14:11:21.0 | D8-BB-C1-6D-37-A4@BF<br>EBFBF<br>F000A<br>0653@<br>80G1S<br>5CZSC<br>WH, 50<br>026B7<br>3813B<br>CB49 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:19 | D8-BB-C1-6D-37-A4@BF<br>EBFBF<br>F000A<br>0653@<br>80G1S<br>5CZSC<br>WH, 50<br>026B7<br>3813B<br>CB49 | 否   |   |  |
| 2136 | 福建铭泰集团有限公司     | 2024-04-23 18:10:36.0 | 74-56-3C-13-C2-F6@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A76D_<br>A0C0_<br>0C12.                   | 否 | 2024-04-23 18:06:32.0 | 74-56-3C-13-C2-F6@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A76D_<br>A0C0_<br>0C12.                   | 否 |  |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:33:07   | 74-56-3C-13-C2-F6@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A76D_<br>A0C0_<br>0C12. | 否 |  |













|      |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                            |                                |   |   |  |
|------|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|--|
| 2146 | 福建鑫佰盈<br>工程管理有<br>限公司 | 2024-<br>04-22<br>11:04<br>:29.0 | FC-<br>34-<br>97-<br>E5-<br>F8-<br>71@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0001.                                     | 否 | 2024-<br>04-22<br>10:45<br>:19.0 | FC-<br>34-<br>97-<br>E5-<br>F8-<br>71@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0001.                                     | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:31<br>:07 | FC-<br>34-<br>97-<br>E5-<br>F8-<br>71@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0001.                                     | 否 |  |
| 2147 | 福建中闽海<br>峡建设有限<br>公司  | 2024-<br>04-23<br>16:58<br>:21.0 | C8-<br>7F-<br>54-<br>08-<br>62-<br>89@BF<br>EBFBF<br>F000A<br>0653@<br>33323<br>2304d<br>32303<br>83632<br>30332<br>02020<br>20202<br>02020 | 否 | 2024-<br>04-22<br>15:35<br>:54.0 | C8-<br>7F-<br>54-<br>08-<br>62-<br>89@BF<br>EBFBF<br>F000A<br>0653@<br>33323<br>2304d<br>32303<br>83632<br>30332<br>02020<br>20202<br>02020 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:49<br>:59 | C8-<br>7F-<br>54-<br>08-<br>62-<br>89@BF<br>EBFBF<br>F000A<br>0653@<br>33323<br>2304d<br>32303<br>83632<br>30332<br>02020<br>20202<br>02020 | 否 |  |

|      |                        |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                              |                                |  |   |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|------------------------------|--------------------------------|--|---|--|
| 2148 | 中建恺翔<br>(福建)发<br>展有限公司 | 2024-<br>04-23<br>09:54<br>:18.0 | 00-<br>E0-<br>4F-<br>10-<br>7E-<br>E6,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0001<br>06A5@<br>30323<br>23231<br>31313<br>13130<br>37322<br>03020<br>20202<br>02020 | 否 | 2024-<br>04-23<br>09:53<br>:08.0 | 00-<br>E0-<br>4F-<br>10-<br>7E-<br>E6,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0001<br>06A5@<br>30323<br>23231<br>31313<br>13130<br>37322<br>03020<br>20202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:33<br>:47 | 00-<br>E0-<br>4F-<br>10-<br>7E-<br>E6,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0001<br>06A5@<br>30323<br>23231<br>31313<br>13130<br>37322<br>03020<br>20202<br>02020 | 否 |  |
| 2149 | 福建朝飞建<br>筑有限公司         | 2024-<br>04-22<br>16:49<br>:38.0 | 04-<br>D9-<br>F5-<br>04-<br>A3-<br>64@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>00000<br>01673   | 否 | 2024-<br>04-22<br>16:48<br>:28.0 | 04-<br>D9-<br>F5-<br>04-<br>A3-<br>64@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>00000<br>01673   | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:33<br>:07 | 04-<br>D9-<br>F5-<br>04-<br>A3-<br>64@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>00000<br>01673  | 否 |  |









|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2155 | 福建叁阳开泰建筑工程有限公司 | 2024-04-23 15:17:23.0 | 18-F2-2C-E2-98-A6, 1C-1B-0D-FE-27-6D@BF EBFBF F0005 06E3@CM164 BH051 8517      | 否 | 2024-04-22 17:14:51.0 | 18-F2-2C-E2-98-A6, 1C-1B-0D-FE-27-6D, 00-00-00-00-00-E0@BF EBFBF F0005 06E3@CM164 BH051 8517 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:35:26 | 00-E0-70-B5-4E-16, 00-E0-4C-86-5D-D9, 00-E0-4C-86-5D-D9, 02-E0-4C-86-5D-D9@BF EBFBF F0009 06EB@MG230 76075 6637 | 否 |  |
| 2156 | 福建省容铭建设发展有限公司  | 2024-04-23 15:56:51.0 | 08-BF-B8-1C-CA-F6@BF EBFBF F0009 0675@0000_0000_0000_0000_707C_1802_2402_A600. | 否 | 2024-04-23 15:54:42.0 | 08-BF-B8-1C-CA-F6@BF EBFBF F0009 0675@0000_0000_0000_0000_707C_1802_2402_A600.               | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:34:07 | 08-BF-B8-1C-CA-F6@BF EBFBF F0009 0675@0000_0000_0000_0000_707C_1802_2402_A600.                                  | 否 |  |











|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2165 | 福建闽工建设工程有限公司  | 2024-04-23 09:58:10.0 | E8-9C-25-10-0C-71@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4A96_<br>76DB. | 否 | 2024-04-23 09:54:45.0 | E8-9C-25-10-0C-71@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4A96_<br>76DB. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:32 | E8-9C-25-10-0C-71@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4A96_<br>76DB. | 否 |  |
| 2166 | 福建恒鼎晟工程管理有限公司 | 2024-04-23 09:12:50.0 | 48-F3-17-07-7D-B5@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7382<br>1ED11<br>3,500<br>26B74<br>2B003<br>BA6        | 否 | 2024-04-22 17:07:45.0 | 48-F3-17-07-7D-B5@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7382<br>1ED11<br>3,500<br>26B74<br>2B003<br>BA6        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:36:46 | 48-F3-17-07-7D-B5@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7382<br>1ED11<br>3,500<br>26B74<br>2B003<br>BA6        | 否 |  |





|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2169 | 福建南剑发展有限公司   | 2024-04-23 10:14:24.0 | 70-4D-7B-6A-AE-6A@BF EBFBF F0005 06E3@WD-WCC6Y 5LP0E KL, 50 026B7 38166 7575         | 否 | 2024-04-23 10:12:58.0 | 70-4D-7B-6A-AE-6A@BF EBFBF F0005 06E3@WD-WCC6Y 5LP0E KL, 50 026B7 38166 7575         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:43:55 | 70-4D-7B-6A-AE-6A@BF EBFBF F0005 06E3@WD-WCC6Y 5LP0E KL, 50 026B7 38166 7575  | 否 |  |
| 2170 | 福建东裕建设工程有限公司 | 2024-04-21 23:54:28.0 | 18-C0-4D-F6-B6-31,00-FF-F7-AD-3E-6B@BF EBFBF F000A 0653@21012 0A000 01155, S9A0 9ZE9 | 否 | 2024-04-21 23:53:08.0 | 18-C0-4D-F6-B6-31,00-FF-F7-AD-3E-6B@BF EBFBF F000A 0653@21012 0A000 01155, S9A0 9ZE9 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:48:45 | 18-C0-4D-E0-F6-95@BF EBFBF F000A 0653@WD-WCC6Y 4KD64 6K, SC RW220 42503 A0277 | 否 |  |

|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |           |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-----------|---------------------|--|---|--|
| 2171 | 翼翮(福建)建设发展有限公司 | 2024-04-23 14:45:46.0 | A8-5E-45-9D-61-43@BF<br>EBFBF<br>F0009<br>06EA@<br>19257<br>V4598<br>13, WD<br>-<br>WCC6Y<br>6TK6H<br>P8   | 否 | 2024-04-23 14:44:49.0 | A8-5E-45-9D-61-43@BF<br>EBFBF<br>F0009<br>06EA@<br>19257<br>V4598<br>13, WD<br>-<br>WCC6Y<br>6TK6H<br>P8   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:43:09 | A8-5E-45-9D-61-43@BF<br>EBFBF<br>F0009<br>06EA@<br>19257<br>V4598<br>13, WD<br>-<br>WCC6Y<br>6TK6H<br>P8   | 否 |  |
| 2172 | 江西奕博建设工程有限公司   | 2024-04-22 16:42:36.0 | E0-D5-5E-4E-D2-AE@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7380<br>49D13<br>7                            | 否 | 2024-04-22 16:41:42.0 | E0-D5-5E-4E-D2-AE@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7380<br>49D13<br>7                            | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:39:15 | E0-D5-5E-4E-D2-AE@BF<br>EBFBF<br>F0005<br>06E3@<br>50026<br>B7380<br>49D13<br>7                            | 否 |  |
| 2173 | 福建屹凯建设工程有限公司   | 2024-04-22 16:47:09.0 | D8-5E-D3-D3-49-2C@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WXG2A<br>819JJ<br>8F, CM<br>163BH<br>23054<br>96 | 否 | 2024-04-22 15:27:45.0 | D8-5E-D3-D3-49-2C@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WXG2A<br>819JJ<br>8F, CM<br>163BH<br>23054<br>96 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:38:05 | D8-5E-D3-D3-49-2C@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WXG2A<br>819JJ<br>8F, CM<br>163BH<br>23054<br>96 | 否 |  |



|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2175 | 河南乐泰建筑工程有限公司  | 2024-04-23 10:47:07.0 | 00-<br>E0-<br>1D-<br>60-<br>06-<br>7D@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>4868_<br>3400_<br>0000_<br>0000. | 否 | 2024-04-18 11:41:50.0 | 00-<br>E0-<br>1D-<br>60-<br>06-<br>7D@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>4868_<br>3400_<br>0000_<br>0000. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:35:49 | 00-<br>E0-<br>1D-<br>60-<br>06-<br>7D@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>4868_<br>3400_<br>0000_<br>0000. | 否 |  |
| 2176 | 福建中鼎森建设发展有限公司 | 2024-04-19 15:12:48.0 | 7C-<br>10-<br>C9-<br>1D-<br>0E-<br>00@BF<br>EBFBF<br>F000A<br>0655@<br>WD-<br>WX92A<br>51053<br>KK, 00<br>25_38<br>B5_11<br>B8_0A<br>1A.    | 否 | 2024-04-19 10:37:43.0 | 7C-<br>10-<br>C9-<br>1D-<br>0E-<br>00@BF<br>EBFBF<br>F000A<br>0655@<br>WD-<br>WX92A<br>51053<br>KK, 00<br>25_38<br>B5_11<br>B8_0A<br>1A.    | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:51:18 | 7C-<br>10-<br>C9-<br>1D-<br>0E-<br>00@BF<br>EBFBF<br>F000A<br>0655@<br>WD-<br>WX92A<br>51053<br>KK, 00<br>25_38<br>B5_11<br>B8_0A<br>1A.    | 否 |  |



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |  |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|--|---|--|
| 2178 | 贵州庆沃建筑工程有限公司 | 2024-04-23 22:02:26.0 | 74-56-3C-1D-25-ED@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2291_<br>6965. | 否 | 2024-04-23 21:03:32.0 | 74-56-3C-1D-25-ED@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2291_<br>6965. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:31:09 | 74-56-3C-1D-25-ED@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2291_<br>6965. | 否  |   |  |
| 2179 | 福建中盈建设工程有限公司 | 2024-04-23 21:06:45.0 | 1C-1B-0D-D2-14-A5@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>2ZYY4<br>XX  | 否 | 2024-04-23 21:05:35.0 | 1C-1B-0D-D2-14-A5@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>2ZYY4<br>XX  | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:36:49   | 1C-1B-0D-D2-14-A5@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>2ZYY4<br>XX | 否 |  |













|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 2188 | 四川弘宁建设工程有限公司   | 2024-04-23 17:30:28.0 | 48-F3-17-11-31-B0@BFEBFBFF000A0653@YS000000000584HP                    | 否 | 2024-04-23 17:00:35.0 | 48-F3-17-11-31-B0@BFEBFBFF000A0653@YS000000000584HP                    | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:55 | 48-F3-17-11-31-B0@BFEBFBFF000A0653@YS000000000584HP                    | 否 |  |
| 2189 | 福建省元一建建设工程有限公司 | 2024-04-23 17:42:28.0 | 00-E0-5B-36-00-1B@BFEBFBFF000306A9@OSC1910280000000745,WD-WCC6Y1VEHAHC | 否 | 2024-04-23 17:40:35.0 | 00-E0-5B-36-00-1B@BFEBFBFF000306A9@OSC1910280000000745,WD-WCC6Y1VEHAHC | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:07 | 00-E0-5B-36-00-1B@BFEBFBFF000306A9@OSC1910280000000745,WD-WCC6Y1VEHAHC | 否 |  |

|      |                   |   |   |   |   |  |  |  |  |  |  |  |  |  |  |  |  |                     |   |   |  |
|------|-------------------|---|---|---|---|--|--|--|--|--|--|--|--|--|--|--|--|---------------------|---|---|--|
| 2190 | 平潭综合实验区武夷建筑工程有限公司 | 2024-04-23 10:26:10.0   | 否 | 2024-04-23 10:25:23.0   | 否 |  |  |  |  |  |  |  |  |  |  |  |  | 2024-04-24 08:43:24 | 校验数据有误，请检查  | 否 |  |
|      |                   | 7C-<br>57-<br>58-<br>3C-<br>AA-<br>BA, F0<br>-A6-<br>54-<br>B6-<br>2F-<br>C2, F0<br>-A6-<br>54-<br>B6-<br>2F-<br>C1, F2<br>-A6-<br>54-<br>B6-<br>2F-<br>C1, F2<br>-A6-<br>54-<br>B6-<br>2F-<br>C1@BF<br>EBFBF<br>F0009<br>0675@<br>ACE4_<br>2E00_<br>2B2C_<br>663A_<br>2EE4_<br>AC00_<br>0000_<br>0001. |   | F0-<br>A6-<br>54-<br>B6-<br>2F-<br>C1, F2<br>-A6-<br>54-<br>B6-<br>2F-<br>C1, FA<br>-A6-<br>54-<br>B6-<br>2F-<br>C1, 7C<br>-57-<br>58-<br>3C-<br>AA-<br>BA, F0<br>-A6-<br>54-<br>B6-<br>2F-<br>C2@BF<br>EBFBF<br>F0009<br>0675@<br>ACE4_<br>2E00_<br>2B2C_<br>663A_<br>2EE4_<br>AC00_<br>0000_<br>0001. |   |  |  |  |  |  |  |  |  |  |  |  |  |                     | 7C-<br>57-<br>58-<br>3C-<br>AA-<br>BA, F0<br>-A6-<br>54-<br>B6-<br>2F-<br>C2, F0<br>-A6-<br>54-<br>B6-<br>2F-<br>C1, F2<br>-A6-<br>54-<br>B6-<br>2F-<br>C1, FA<br>-A6-<br>54-<br>B6-<br>2F-<br>C1@BF<br>EBFBF<br>F0009<br>0675@<br>ACE4_<br>2E00_<br>2B2C_<br>663A_<br>2EE4_<br>AC00_<br>0000_<br>0001. |   |  |

|      |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 2191 | 福建新濠建设发展有限公司 | 2024-04-23 16:48:57.0 | A0-36-BC-0A-9B-8C@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0104. | 否 | 2024-04-23 16:35:34.0 | A0-36-BC-0A-9B-8C@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0104. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:07 | A0-36-BC-0A-9B-8C@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0104. | 否   |   |  |
| 2192 | 福建卓星建设发展有限公司 | 2024-04-23 16:30:26.0 | 30-9C-23-A0-04-CC@BF<br>EBFBF<br>F0009<br>06EB@<br>W9ABL<br>BJC  | 否 | 2024-04-23 15:49:20.0 | 30-9C-23-A0-04-CC@BF<br>EBFBF<br>F0009<br>06EB@<br>W9ABL<br>BJC   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:44:10   | 30-9C-23-A0-04-CC@BF<br>EBFBF<br>F0009<br>06EB@<br>W9ABL<br>BJC | 否 |  |



|      |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |   |  |
|------|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|---|--|
| 2194 | 福建实展建设有限公司 | 2024-04-22 16:14:49.0 | 08-BF-B8-40-CD-B6@BF EBFBF F0009 0675@WD-WCC6Y OZAXE KE, WD - WCC6Y 7CDV8 3A, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4E 70_5C D4., 6 E02A7 4142C 9 | 否 | 2024-04-22 15:13:35.0 | 08-BF-B8-40-CD-B6@BF EBFBF F0009 0675@WD-WCC6Y OZAXE KE, WD - WCC6Y 7CDV8 3A, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4E 70_5C D4., 6 E02A7 4142C 9 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:41:01 | 08-60-6E-74-D7-E0@17 8BFBF F0010 0F62@ 30333 13033 34393 53635 20302 02020 20202 02020 | 否   |   |  |
| 2195 | 天铭建设集团有限公司 | 2024-04-23 16:56:38.0 | 88-AE-DD-45-1B-65@BF EBFBF F000A 0671@WD-WCC6Y 2XCZ6 DD, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4B 26_18 73.                                       | 否 | 2024-04-23 10:38:27.0 | 88-AE-DD-45-1B-65@BF EBFBF F000A 0671@WD-WCC6Y 2XCZ6 DD, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4B 26_18 73.                                       | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:38:05  | 88-AE-DD-45-1B-65@BF EBFBF F000A 0671@WD-WCC6Y 2XCZ6 DD, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4B 26_18 73. | 否 |  |



|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2196 | 福建南鲁建设工程有限公司  | 2024-04-23 19:24:42.0 | 00-FF-FC-DA-06-40, 2C-FD-A1-E3-58-38@BF EBFBF F0009 06E9@50026 B7682 OCDAC 4, WD-WCC6Y 3NTA2 4U   | 否 | 2024-04-23 19:22:03.0 | 00-FF-FC-DA-06-40, 2C-FD-A1-E3-58-38@BF EBFBF F0009 06E9@50026 B7682 OCDAC 4, WD-WCC6Y 3NTA2 4U   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:18 | 00-FF-FC-DA-06-40, 2C-FD-A1-E3-58-38@BF EBFBF F0009 06E9@50026 B7682 OCDAC 4, WD-WCC6Y 3NTA2 4U   | 否 |  |
| 2197 | 福建省祁括建筑工程有限公司 | 2024-04-23 12:30:24.0 | 74-56-3C-24-20-F3, 48-8A-D2-E7-3B-0A@BF EBFBF F0009 0672@E823_8FA6_BF53_0001_001B_448B_4E9E_16A4. | 否 | 2024-04-23 12:28:31.0 | 74-56-3C-24-20-F3, 48-8A-D2-E7-3B-0A@BF EBFBF F0009 0672@E823_8FA6_BF53_0001_001B_448B_4E9E_16A4. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:14 | 74-56-3C-24-20-F3, 48-8A-D2-E7-3B-0A@BF EBFBF F0009 0672@E823_8FA6_BF53_0001_001B_448B_4E9E_16A4. | 否 |  |



|      |                 |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 2200 | 湖南中天建设集团股份有限公司  | 2024-04-23 14:29:07.0 | A0-36-BC-AD-A8-9A@BFEBFBFF000A0653@50026B73819692C8 | 否 | 2024-04-23 14:25:58.0 | A0-36-BC-AD-A8-9A@BFEBFBFF000A0653@50026B73819692C8 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:55 | A0-36-BC-AD-A8-9A@BFEBFBFF000A0653@50026B73819692C8 | 否 |  |
| 2201 | 厦门南燕山装饰设计工程有限公司 | 2024-04-19 14:44:30.0 | 74-56-3C-4F-46-59@BFEBFBFF00090672@50026B7382191DC0 | 否 | 2024-04-19 14:38:02.0 | 74-56-3C-4F-46-59@BFEBFBFF00090672@50026B7382191DC0 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:57:41 | 74-56-3C-4F-46-59@BFEBFBFF00090672@50026B7382191DC0 | 否 |  |





|      |                       |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                            |                                |  |  |   |  |
|------|-----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|--|---|--|
| 2206 | 福建省长龙<br>建筑工程有<br>限公司 | 2024-<br>04-23<br>15:51<br>:36.0 | 6C-<br>4B-<br>90-<br>DE-<br>F6-<br>48@BF<br>EBFBF<br>F0009<br>06EA@<br>20202<br>02020<br>20202<br>02020<br>31204<br>63031<br>35333<br>3534e<br>,ACE4<br>_2E00<br>_9A2E<br>_0B4C<br>. | 否 | 2024-<br>04-23<br>15:42<br>:26.0 | 6C-<br>4B-<br>90-<br>DE-<br>F6-<br>48@BF<br>EBFBF<br>F0009<br>06EA@<br>20202<br>02020<br>20202<br>02020<br>31204<br>63031<br>35333<br>3534e<br>,ACE4<br>_2E00<br>_9A2E<br>_0B4C<br>. | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:37<br>:04 | 6C-<br>4B-<br>90-<br>DE-<br>F6-<br>48@BF<br>EBFBF<br>F0009<br>06EA@<br>20202<br>02020<br>20202<br>02020<br>31204<br>63031<br>35333<br>3534e<br>,ACE4<br>_2E00<br>_9A2E<br>_0B4C<br>. | 否  |   |  |
| 2207 | 福建永聚建<br>设工程有限<br>公司  | 2024-<br>04-19<br>16:40<br>:01.0 | 18-<br>C0-<br>4D-<br>F7-<br>EC-<br>FA@BF<br>EBFBF<br>F000A<br>0653@<br>20231<br>10791<br>920   | 否 | 2024-<br>04-19<br>16:39<br>:58.0 | 18-<br>C0-<br>4D-<br>F7-<br>EC-<br>FA@BF<br>EBFBF<br>F000A<br>0653@<br>20231<br>10791<br>920   | 否 |  |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>，请<br>检查     | 2024-<br>04-24<br>08:34<br>:24   | 18-<br>C0-<br>4D-<br>F7-<br>EC-<br>FA@BF<br>EBFBF<br>F000A<br>0653@<br>20231<br>10791<br>920 | 否 |  |



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 2210 | 福建维邦建设工程有限公司 | 2024-04-23 11:54:58.0 | 18-C0-4D-D1-EA-26@BF<br>EBFBF<br>F0009<br>06EB@50026<br>B7784<br>4C1D4<br>D                          | 否 | 2024-04-23 11:20:10.0 | 18-C0-4D-D1-EA-26@BF<br>EBFBF<br>F0009<br>06EB@50026<br>B7784<br>4C1D4<br>D                          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:40:16 | 18-C0-4D-D1-EA-26@BF<br>EBFBF<br>F0009<br>06EB@50026<br>B7784<br>4C1D4<br>D                          | 否 |  |
| 2211 | 福建千业建设工程有限公司 | 2024-04-23 15:28:42.0 | 00-E0-1D-04-02-<br>D0@BF<br>EBFBF<br>F0005<br>06E3@<br>0000_0000_0000_0000_0000_4868_3400_0000_0000. | 否 | 2024-04-23 15:16:45.0 | 00-E0-1D-04-02-<br>D0@BF<br>EBFBF<br>F0005<br>06E3@<br>0000_0000_0000_0000_0000_4868_3400_0000_0000. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:49 | 00-E0-1D-04-02-<br>D0@BF<br>EBFBF<br>F0005<br>06E3@<br>0000_0000_0000_0000_0000_4868_3400_0000_0000. | 否 |  |







|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 2216 | 福州市明煌建设有限公司  | 2024-04-23 10:08:42.0 | 00-FF-5F-40-D9-03,00-E0-4C-10-29-3D,00-00-00-00-00-E0@BFEBFBFF000306A9@J511206B03679 | 否 | 2024-04-23 10:06:45.0 | 00-FF-5F-40-D9-03,00-E0-4C-10-29-3D,00-00-00-00-00-E0@BFEBFBFF000306A9@J511206B03679 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:06 | 00-FF-5F-40-D9-03,00-E0-4C-10-29-3D,00-00-00-00-00-E0@BFEBFBFF000306A9@J511206B03679 | 否 |  |
| 2217 | 福建中德市政园林有限公司 | 2024-04-22 17:26:40.0 | 18-C0-4D-54-2A-34@BFEBFBFF000906EA@WCC6Y1VRF51C,201015A00013639                      | 否 | 2024-04-22 17:25:13.0 | 18-C0-4D-54-2A-34@BFEBFBFF000906EA@WCC6Y1VRF51C,201015A00013639                      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:25 | 18-C0-4D-54-2A-34@BFEBFBFF000906EA@WCC6Y1VRF51C,201015A00013639                      | 否 |  |

|      |                       |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                         |                                |  |   |  |
|------|-----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|--|---|--|
| 2218 | 福建省禹坤<br>建筑科技有<br>限公司 | 2024-<br>04-23<br>16:51<br>:04.0 | 58-<br>11-<br>22-<br>9E-<br>D5-<br>AA, 00<br>-FF-<br>43-<br>C0-<br>D2-<br>24@BF<br>EBFBF<br>F0009<br>0672@<br>WD-<br>WCC6Y<br>7A3W7<br>6F, SC<br>RW220<br>81501<br>G1298 | 否 | 2024-<br>04-23<br>16:50<br>:17.0 | 58-<br>11-<br>22-<br>9E-<br>D5-<br>AA, 00<br>-FF-<br>43-<br>C0-<br>D2-<br>24@BF<br>EBFBF<br>F0009<br>0672@<br>WD-<br>WCC6Y<br>7A3W7<br>6F, SC<br>RW220<br>81501<br>G1298 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:45<br>:24 | 58-<br>11-<br>22-<br>9E-<br>D5-<br>AA, 00<br>-FF-<br>43-<br>C0-<br>D2-<br>24@BF<br>EBFBF<br>F0009<br>0672@<br>WD-<br>WCC6Y<br>7A3W7<br>6F, SC<br>RW220<br>81501<br>G1298 | 否 |  |
|------|-----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|--|---|--|



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2220 | 福建南平闽鑫工程有限公司 | 2024-04-23 10:49:52.0 | 2C-F0-5D-37-D4-0A@BF<br>EBFBF<br>F0009<br>06EA@<br>AA230<br>70315<br>B5000<br>20749<br>, WD-<br>WCC6Y<br>4DC3L<br>X6   | 否 | 2024-04-23 10:49:21.0 | 2C-F0-5D-37-D4-0A@BF<br>EBFBF<br>F0009<br>06EA@<br>AA230<br>70315<br>B5000<br>20749<br>, WD-<br>WCC6Y<br>4DC3L<br>X6   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:37:28 | 2C-F0-5D-37-D4-0A@BF<br>EBFBF<br>F0009<br>06EA@<br>AA230<br>70315<br>B5000<br>20749<br>, WD-<br>WCC6Y<br>4DC3L<br>X6  | 否 |  |
| 2221 | 福建隆晟集团有限公司   | 2024-04-23 10:07:04.0 | D0-AB-<br>D5-27-<br>B0-18, D0<br>-AB-<br>D5-27-<br>B0-14, D0<br>-AB-<br>D5-27-<br>B0-15, D2<br>-AB-<br>D5-27-<br>B0-14@BF<br>EBFBF<br>F0008<br>06EC@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>44D2_<br>57B0. | 否 | 2024-04-23 10:01:39.0 | D0-AB-<br>D5-27-<br>B0-15, D2<br>-AB-<br>D5-27-<br>B0-14, D0<br>-AB-<br>D5-27-<br>B0-14, D0<br>-AB-<br>D5-27-<br>B0-14, D0<br>-AB-<br>D5-27-<br>B0-14, D0<br>-AB-<br>D5-27-<br>B0-14@BF<br>EBFBF<br>F0008<br>06EC@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>44D2_<br>57B0. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:34:50 | D0-AB-<br>D5-27-<br>B0-18, D0<br>-AB-<br>D5-27-<br>B0-14, D0<br>-AB-<br>D5-27-<br>B0-14, D0<br>-AB-<br>D5-27-<br>B0-15, D2<br>-AB-<br>D5-27-<br>B0-14@BF<br>EBFBF<br>F0008<br>06EC@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>44D2_<br>57B0. | 否 |  |



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|--|
|      |              |                       |   |   |                       | B4ZE  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |  |
| 2223 | 福建欣瑞建设发展有限公司 | 2024-04-23 20:37:46.0 | AC-<br>E2-<br>D3-<br>4B-<br>CE-<br>9B, D4<br>-25-<br>8B-<br>36-<br>59-<br>FD, D6<br>-25-<br>8B-<br>36-<br>59-<br>FC, D4<br>-25-<br>8B-<br>36-<br>59-<br>FC, D4<br>-25-<br>8B-<br>36-<br>5A-<br>00@BF<br>EBFBF<br>F0008<br>06EA@<br>17304<br>68007<br>01 | 否 | 2024-04-23 20:33:44.0 | AC-<br>E2-<br>D3-<br>4B-<br>CE-<br>9B, D4<br>-25-<br>8B-<br>36-<br>59-<br>FD, D6<br>-25-<br>8B-<br>36-<br>59-<br>FC, D4<br>-25-<br>8B-<br>36-<br>59-<br>FC, D4<br>-25-<br>8B-<br>36-<br>5A-<br>00@BF<br>EBFBF<br>F0008<br>06EA@<br>17304<br>68007<br>01 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:38:17 | AC-<br>E2-<br>D3-<br>4B-<br>CE-<br>9B, D4<br>-25-<br>8B-<br>36-<br>59-<br>FD, D6<br>-25-<br>8B-<br>36-<br>59-<br>FC, D4<br>-25-<br>8B-<br>36-<br>59-<br>FC, D4<br>-25-<br>8B-<br>36-<br>5A-<br>00@BF<br>EBFBF<br>F0008<br>06EA@<br>17304<br>68007<br>01 | 否 |  |  |





|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 2225 | 福建省妙隆建设工程有限公司 | 2024-04-23 16:47:07.0 | 00-E2-69-60-3F-1C,00-FF-3F-DF-A7-5F@BF EBFBF F0009 0675@6479_A769_9000_028A.   | 否 | 2024-04-23 10:47:08.0 | 00-E2-69-60-3F-1C,00-FF-3F-DF-A7-5F@BF EBFBF F0009 0675@6479_A769_9000_028A.   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:09 | 00-E2-69-60-3F-1C,00-FF-3F-DF-A7-5F@BF EBFBF F0009 0675@6479_A769_9000_028A.   | 否 |  |
| 2226 | 福建利岚建设工程有限公司  | 2024-04-18 11:37:23.0 | 08-BF-B8-28-9D-84@BF EBFBF F000A 0653@0000_0000_0000_0000_0026_B738_1C43_C205. | 否 | 2024-04-18 11:36:28.0 | 08-BF-B8-28-9D-84@BF EBFBF F000A 0653@0000_0000_0000_0000_0026_B738_1C43_C205. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:23 | 08-BF-B8-28-9D-84@BF EBFBF F000A 0653@0000_0000_0000_0000_0026_B738_1C43_C205. | 否 |  |
| 2227 | 中彦溟德建设发展有限公司  | 2024-04-19 15:54:41.0 | 74-56-3C-21-1F-15@BF EBFBF F000A 0653@A843_9700_0000_1950.                     | 否 | 2024-04-19 15:39:55.0 | 74-56-3C-21-1F-15@BF EBFBF F000A 0653@A843_9700_0000_1950.                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:21 | 74-56-3C-21-1F-15@BF EBFBF F000A 0653@A843_9700_0000_1950.                     | 否 |  |

|      |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|------|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 2228 | 福建工匠建设有限公司 | 2024-04-22 15:11:45.0 | 58-11-22-OF-2A-C1@BF<br>EBFBF<br>F0009<br>0672@<br>81K72<br>4LMS,<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1928_<br>5635. | 否 | 2024-04-22 14:51:11.0 | 58-11-22-OF-2A-C1@BF<br>EBFBF<br>F0009<br>0672@<br>81K72<br>4LMS,<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1928_<br>5635. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:32 | 58-11-22-OF-2A-C1@BF<br>EBFBF<br>F0009<br>0672@<br>81K72<br>4LMS,<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1928_<br>5635. | 否   |   |  |
| 2229 | 福建国合建筑有限公司 | 2024-04-22 17:20:22.0 | 18-CO-4D-EC-76-AD@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>E5F16<br>7   | 否 | 2024-04-22 16:31:52.0 | 18-CO-4D-EC-76-AD@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>E5F16<br>7   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:32:19   | 18-CO-4D-EC-76-AD@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7380<br>E5F16<br>7 | 否 |  |



|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2231 | 福建中润建设工程发展有限公司 | 2024-04-23 15:17:56.0 | A4-0C-66-01-5F-57@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>00000<br>00989<br>, WD-<br>WCC6Y<br>OPFNJ<br>C5                          | 否 | 2024-04-22 16:10:26.0 | A4-0C-66-01-5F-57@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>00000<br>00989<br>, WD-<br>WCC6Y<br>OPFNJ<br>C5                          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:42:27 | A4-0C-66-01-5F-57@BF<br>EBFBF<br>F0009<br>06EA@<br>AA000<br>00000<br>00000<br>00989<br>, WD-<br>WCC6Y<br>OPFNJ<br>C5                          | 否 |  |
| 2232 | 福建海森工程建设有限公司   | 2024-04-24 07:32:05.0 | 00-<br>E0-<br>1D-<br>7B-<br>0B-<br>36@BF<br>EBFBF<br>F0009<br>0675@<br>Z6E26<br>ZLM, M<br>X_012<br>34605<br>70, SC<br>RW231<br>11702<br>H0350 | 否 | 2024-04-24 07:29:56.0 | 00-<br>E0-<br>1D-<br>7B-<br>0B-<br>36@BF<br>EBFBF<br>F0009<br>0675@<br>Z6E26<br>ZLM, M<br>X_012<br>34605<br>70, SC<br>RW231<br>11702<br>H0350 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:41:01 | 00-<br>E0-<br>1D-<br>7B-<br>0B-<br>36@BF<br>EBFBF<br>F0009<br>0675@<br>Z6E26<br>ZLM, M<br>X_012<br>34605<br>70, SC<br>RW231<br>11702<br>H0350 | 否 |  |



|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2235 | 厦门金汇航通建设有限公司  | 2024-04-22 17:06:35.0 | 00-<br>E0-<br>70-<br>BF-<br>A7-<br>5F, B4<br>-6D-<br>83-<br>4D-<br>33-<br>8E, B4<br>-6D-<br>83-<br>4D-<br>33-<br>8F, B6<br>-6D-<br>83-<br>4D-<br>33-<br>8E@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WX42A<br>701DL<br>96, 01<br>00_00<br>00_00<br>00_00<br>00. | 否 | 2024-04-22 17:04:35.0 | 00-<br>E0-<br>70-<br>BF-<br>A7-<br>5F, B4<br>-6D-<br>83-<br>4D-<br>33-<br>8E, B4<br>-6D-<br>83-<br>4D-<br>33-<br>8F, B6<br>-6D-<br>83-<br>4D-<br>33-<br>8E@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WX42A<br>701DL<br>96, 01<br>00_00<br>00_00<br>00_00<br>00. | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:07 | 04-<br>92-<br>26-<br>D2-<br>F6-<br>54@BF<br>EBFBF<br>F0009<br>06E9@<br>K3828<br>2J001<br>115, W<br>D-<br>WCC6Y<br>7YYEN<br>UD, WD<br>-<br>WCC6Y<br>6RYYYY<br>Y5 | 否 |  |
| 2236 | 福建省闽顺建设发展有限公司 | 2024-04-23 14:37:22.0 | E8-<br>9C-<br>25-<br>47-<br>07-<br>DA@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E39_<br>788F.   | 否 | 2024-04-23 11:27:46.0 | E8-<br>9C-<br>25-<br>47-<br>07-<br>DA@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E39_<br>788F.   | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:50 | E8-<br>9C-<br>25-<br>47-<br>07-<br>DA@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E39_<br>788F.                     | 否 |  |





|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|--|---|--|
| 2238 | 福建省弘盛建设工程有限公司 | 2024-04-23 18:04:00.0 | C0-A5-E8-2B-92-C4, C0-A5-E8-2B-92-C5, C2-A5-E8-2B-92-C4, 04-D9-C8-B7-B4-8B, C0-A5-E8-2B-92-C8@BF EBFBF F0009 0675@5CDF_B803_81C0_1240. | 否 | 2024-04-23 18:02:55.0 | C0-A5-E8-2B-92-C4, C0-A5-E8-2B-92-C5, C2-A5-E8-2B-92-C4, 04-D9-C8-B7-B4-8B, C0-A5-E8-2B-92-C8@BF EBFBF F0009 0675@5CDF_B803_81C0_1240. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:34:19 | C0-A5-E8-2B-92-C4, C0-A5-E8-2B-92-C5, C2-A5-E8-2B-92-C4, 04-D9-C8-B7-B4-8B, C0-A5-E8-2B-92-C8@BF EBFBF F0009 0675@5CDF_B803_81C0_1240. | 否  |   |  |
| 2239 | 福建华科建筑有限公司    | 2024-04-23 11:14:34.0 | 18-C0-4D-40-DF-72@BF EBFBF F0009 06EA@0026_B728_2696_9645.   | 否 | 2024-04-23 11:11:20.0 | 18-C0-4D-40-DF-72@BF EBFBF F0009 06EA@0026_B728_2696_9645.   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:36:23  | 18-C0-4D-40-DF-72@BF EBFBF F0009 06EA@0026_B728_2696_9645. | 否 |  |

|      |                        |                                  |   |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                         |                                |   |   |   |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------------------|--------------------------------|---|---|---|--|
| 2240 | 福建省砾承<br>建筑工程有限公司      | 2024-<br>04-23<br>18:53<br>:05.0 | 00-<br>E0-<br>4C-<br>89-<br>44-<br>22@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>HY8U1<br>3D, 30<br>11104<br>5859   | 否 | 2024-<br>04-23<br>18:51<br>:56.0 | 00-<br>E0-<br>4C-<br>89-<br>44-<br>22@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>HY8U1<br>3D, 30<br>11104<br>5859  | 否 |  |  |  |  |  |  |  |  |  |                         | 校验<br>数据有<br>误, 请<br>检查        | 2024-<br>04-24<br>08:37<br>:15  | 00-<br>E0-<br>4C-<br>89-<br>44-<br>22@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>HY8U1<br>3D, 30<br>11104<br>5859 | 否 |  |
| 2241 | 福建中闽创<br>辉建设工程<br>有限公司 | 2024-<br>04-23<br>15:58<br>:05.0 | 04-<br>D4-<br>C4-<br>91-<br>4F-<br>53@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36373<br>73238<br>37414<br>53333<br>31202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>34595<br>04835<br>33334<br>4 | 否 | 2024-<br>04-23<br>15:50<br>:23.0 | 04-<br>D4-<br>C4-<br>91-<br>4F-<br>53, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36373<br>73238<br>37414<br>53333<br>31202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>34595<br>04835<br>33334<br>4 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-<br>04-24<br>08:51<br>:39 | 04-<br>D4-<br>C4-<br>91-<br>4F-<br>53@BF<br>EBFBF<br>F0009<br>06E9@<br>30353<br>23042<br>36373<br>73238<br>37414<br>53333<br>31202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>34595<br>04835<br>33334<br>4 | 否   |   |  |







|      |                       |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |  |                                   |                                |  |   |  |
|------|-----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|-----------------------------------|--------------------------------|--|---|--|
| 2247 | 福州筑之杰<br>建筑工程有<br>限公司 | 2024-<br>04-23<br>14:21<br>:36.0 | 18-<br>C0-<br>4D-<br>2B-<br>91-<br>A3@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>01552<br>,W9A1<br>49NB | 否 | 2024-<br>04-23<br>10:54<br>:14.0 | 18-<br>C0-<br>4D-<br>2B-<br>91-<br>A3@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>01552<br>,W9A1<br>49NB | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查<br>检 | 2024-<br>04-24<br>08:36<br>:36 | 18-<br>C0-<br>4D-<br>2B-<br>91-<br>A3@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>01552<br>,W9A1<br>49NB | 否 |  |
|------|-----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|--|-----------------------------------|--------------------------------|--|---|--|



|      |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |   |  |
|------|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|---|--|
| 2249 | 欣辉建设集团有限公司 | 2024-04-23 16:15:02.0 | 58-11-22-99-90-8B@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>EN3RK<br>PL,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_5F<br>FO_AF<br>05. | 否 | 2024-04-22 14:32:55.0 | 58-11-22-99-90-8B@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>EN3RK<br>PL,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_5F<br>FO_AF<br>05. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误,请检查 | 2024-04-24 08:33:15 | 58-11-22-99-90-8B@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>EN3RK<br>PL,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>68_5F<br>FO_AF<br>05. | 否   |   |  |
| 2250 | 超旺建设有限公司   | 2024-04-18 15:11:56.0 | 50-EB-F6-82-31-B7@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>B5450<br>5,WD-<br>WCC4M<br>5ZV28<br>R9   | 否 | 2024-04-18 15:10:45.0 | 50-EB-F6-82-31-B7@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>B5450<br>5,WD-<br>WCC4M<br>5ZV28<br>R9   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误,请检查         | 2024-04-24 08:38:25   | 50-EB-F6-82-31-B7@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>B5450<br>5,WD-<br>WCC4M<br>5ZV28<br>R9 | 否 |  |









|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |  |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|--|---|--|
| 2255 | 福建鑫禾建设工程有限公司 | 2024-04-18 17:36:03.0 | 2C-F0-5D-A5-C7-91@BF EBFBF F000A 0653@WD-WCC6Y 4HDEY L5, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_49 AE_65 76. | 否 | 2024-04-18 17:19:58.0 | 2C-F0-5D-A5-C7-91@BF EBFBF F000A 0653@WD-WCC6Y 4HDEY L5, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_49 AE_65 76. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:07 | 2C-F0-5D-A5-C7-91@BF EBFBF F000A 0653@WD-WCC6Y 4HDEY L5, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_49 AE_65 76. | 否  |   |  |
| 2256 | 福建延腾建设工程有限公司 | 2024-04-19 11:29:02.0 | 7C-10-C9-D1-83-8D@BF EBFBF F000A 0653@ 30057 81030 8  | 否 | 2024-04-19 09:48:41.0 | 7C-10-C9-D1-83-8D@BF EBFBF F000A 0653@ 30057 81030 8  | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:37:14   | 7C-10-C9-D1-83-8D@BF EBFBF F000A 0653@ 30057 81030 8 | 否 |  |







|      |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2262 | 福建智慧建筑有限公司 | 2024-04-23 10:59:13.0 | 48-F3-17-02-92-31,04-7F-OE-39-ED-EC@BF EBFBF F000A 0653@ 20220 81170 56,WD - WCC6Y 1AKTZ FA | 否 | 2024-04-23 10:46:02.0 | 48-F3-17-02-92-31,04-7F-OE-39-ED-EC@BF EBFBF F000A 0653@ 20220 81170 56,WD - WCC6Y 1AKTZ FA | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:41:31 | 48-F3-17-02-92-31,04-7F-OE-39-ED-EC@BF EBFBF F000A 0653@ 20220 81170 56,WD - WCC6Y 1AKTZ FA | 否 |  |
|------|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|







|      |                  |                          |   |   |                          |  |   |  |  |  |  |  |  |  |  |  |                              |                        |  |   |  |
|------|------------------|--------------------------|---|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------------|------------------------|--|---|--|
| 2265 | 日辉建设<br>(福建)有限公司 | 2024-04-23<br>16:29:37.0 | 00-<br>E0-<br>4D-<br>6B-<br>01-<br>7B, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0002<br>06A7@<br>GM225<br>00371<br>23918<br>9, 1W1<br>DAZTV | 否 | 2024-04-23<br>16:26:51.0 | 00-<br>E0-<br>4D-<br>6B-<br>01-<br>7B, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0002<br>06A7@<br>GM225<br>00371<br>23918<br>9, 1W1<br>DAZTV | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:37:29 | 00-<br>E0-<br>4D-<br>6B-<br>01-<br>7B, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0002<br>06A7@<br>GM225<br>00371<br>23918<br>9, 1W1<br>DAZTV | 否 |  |
| 2266 | 福建致兴建<br>设工程有限公司 | 2024-04-23<br>08:58:49.0 | 60-<br>45-<br>CB-<br>9A-<br>76-<br>77@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>7YU6P<br>YO  | 否 | 2024-04-22<br>17:39:18.0 | 60-<br>45-<br>CB-<br>9A-<br>76-<br>77, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>7YU6P<br>YO   | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:33:35 | 60-<br>45-<br>CB-<br>9A-<br>76-<br>77@BF<br>EBFBF<br>F0005<br>06E3@<br>WD-<br>WCC6Y<br>7YU6P<br>YO   | 否 |  |







|      |                   |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                              |                            |  |   |  |
|------|-------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------------|----------------------------|--|---|--|
| 2272 | 福建省腾浚<br>建工有限公司   | 2024-04-23<br>08:26<br>:51.0 | B4-<br>2E-<br>99-<br>E2-<br>2F-<br>5C@BF<br>EBFBF<br>F0009<br>06EB@<br>Y94B5<br>13SK5<br>UL, WD<br>-<br>WCC6Y<br>OETEU<br>E1   | 否 | 2024-04-16<br>15:44<br>:10.0 | B4-<br>2E-<br>99-<br>E2-<br>2F-<br>5C@BF<br>EBFBF<br>F0009<br>06EB@<br>Y94B5<br>13SK5<br>UL, WD<br>-<br>WCC6Y<br>OETEU<br>E1   | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:33<br>:54 | B4-<br>2E-<br>99-<br>E2-<br>2F-<br>5C@BF<br>EBFBF<br>F0009<br>06EB@<br>Y94B5<br>13SK5<br>UL, WD<br>-<br>WCC6Y<br>OETEU<br>E1   | 否 |  |
| 2273 | 福建汇鑫达<br>建设工程有限公司 | 2024-04-23<br>09:57<br>:10.0 | 58-<br>11-<br>22-<br>9E-<br>0C-<br>23@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E4A_<br>18A4.<br>, WD-<br>WCC6Y<br>6RPS8<br>1S | 否 | 2024-04-23<br>09:54<br>:47.0 | 58-<br>11-<br>22-<br>9E-<br>0C-<br>23@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E4A_<br>18A4.<br>, WD-<br>WCC6Y<br>6RPS8<br>1S | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-04-24<br>08:32<br>:35 | 58-<br>11-<br>22-<br>9E-<br>0C-<br>23@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4E4A_<br>18A4.<br>, WD-<br>WCC6Y<br>6RPS8<br>1S | 否 |  |





|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2276 | 福建省东岱建工集团有限公司 | 2024-04-23 16:59:13.0 | 00-4B-F3-B8-56-4D, 58-11-22-D2-E5-61@BF EBFBF F0009 0675@ 0000_0000_0000_0000_0026_B728_30D4_F295., WD-WX32H 2KF75 67 | 否 | 2024-04-23 15:28:34.0 | 00-4B-F3-B8-56-4D, 58-11-22-D2-E5-61@BF EBFBF F0009 0675@ 0000_0000_0000_0000_0026_B728_30D4_F295., WD-WX32H 2KF75 67 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:29 | 00-4B-F3-B8-56-4D, 58-11-22-D2-E5-61@BF EBFBF F0009 0675@ 0000_0000_0000_0000_0026_B728_30D4_F295., WD-WX32H 2KF75 67 | 否 |  |
| 2277 | 福建海峡赢航建设有限公司  | 2024-04-23 10:32:26.0 | A0-36-BC-B9-7D-0F, 00-FF-17-1B-88-D2@BF EBFBF F0009 0672@ 0000_0000_0000_0001., WD-WCC6Y 922DN 5U                     | 否 | 2024-04-23 10:31:24.0 | 00-FF-17-1B-88-D2, A0-36-BC-B9-7D-0F@BF EBFBF F0009 0672@ 0000_0000_0000_0001., WD-WCC6Y 922DN 5U                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:53 | A0-36-BC-B9-7D-0F, 00-FF-17-1B-88-D2@BF EBFBF F0009 0672@ 0000_0000_0000_0001., WD-WCC6Y 922DN 5U                     | 否 |  |







|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2282 | 福建万佳顺建设发展有限公司 | 2024-04-23 15:57:15.0 | 74-56-3C-81-9A-3E@BF<br>EBFBF<br>F0009<br>0675@<br>SCRW2<br>21214<br>08G01<br>17,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 | 2024-04-23 15:51:33.0 | 74-56-3C-81-9A-3E@BF<br>EBFBF<br>F0009<br>0675@<br>SCRW2<br>21214<br>08G01<br>17,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:46 | 74-56-3C-81-9A-3E@BF<br>EBFBF<br>F0009<br>0675@<br>SCRW2<br>21214<br>08G01<br>17,00<br>00_00<br>00_00<br>00_00<br>00_00<br>00_01<br>00_00<br>00_00<br>00. | 否 |  |
| 2283 | 福建省蔡鸿建设有限公司   | 2024-04-23 14:39:24.0 | 00-E2-69-62-B7-45@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC4J<br>EKF8E<br>T6, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_45<br>FA_3C<br>1F.  | 否 | 2024-04-23 14:37:59.0 | 00-E2-69-62-B7-45@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC4J<br>EKF8E<br>T6, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_45<br>FA_3C<br>1F.  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:15 | 00-E2-69-62-B7-45@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC4J<br>EKF8E<br>T6, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_45<br>FA_3C<br>1F.  | 否 |  |

|      |             |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |  |   |  |
|------|-------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|--|---|--|
| 2284 | 金创建设集团有限公司  | 2024-04-23 15:18:20.0 | 18-CO-4D-E2-82-EC@BF EBFBF F000A 0653@ 21218 74493 11, AA 00000 00000 00000 526, W D- WCC6Y 0V FY5 9S | 否 | 2024-04-23 15:14:06.0 | 18-CO-4D-E2-82-EC@BF EBFBF F000A 0653@ 21218 74493 11, AA 00000 00000 00000 526, W D- WCC6Y 0V FY5 9S | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:15 | 18-CO-4D-E2-82-EC@BF EBFBF F000A 0653@ 21218 74493 11, AA 00000 00000 00000 526, W D- WCC6Y 0V FY5 9S | 否  |   |  |
| 2285 | 福建省翎忻发展有限公司 | 2024-04-22 16:45:06.0 | 58-11-22-95-48-9C@BF EBFBF F0009 0675@ 50026 B7381 6686E 3, WD- WCC6Y 4DNT7 6N                        | 否 | 2024-04-22 16:37:39.0 | 58-11-22-95-48-9C@BF EBFBF F0009 0675@ 50026 B7381 6686E 3, WD- WCC6Y 4DNT7 6N                        | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:33:47   | 58-11-22-95-48-9C@BF EBFBF F0009 0675@ 50026 B7381 6686E 3, WD- WCC6Y 4DNT7 6N | 否 |  |







|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2288 | 福建鸿源辉建设工程有限公司  | 2024-04-23 10:51:26.0 | 90-6F-18-07-59-77@BF EBFBF F0009 0675@0000_0000_0000_00E0_4C66_D081_9223.,2338 AZ453415    | 否 | 2024-04-23 10:36:39.0 | 90-6F-18-07-59-77@BF EBFBF F0009 0675@0000_0000_0000_00E0_4C66_D081_9223.,2338 AZ453415    | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:44:12 | 00-E2-69-63-A0-EB@BF EBFBF F000A 0653@98606 28803 31,E8 23_8F A6_BF 53_00 01_00 1B_44 4A_49 B2_5E 45.,A A0000 00000 00485 | 否 |  |
| 2289 | 福建省兴雅达建设发展有限公司 | 2024-04-22 10:50:03.0 | 74-56-3C-24-41-D6@BF EBFBF F000A 0653@WD-WX12A A2PRN 13,64 79_A7 6D_D0 CO_OF 7B.,2 A5F3E42 | 否 | 2024-04-22 10:26:10.0 | 74-56-3C-24-41-D6@BF EBFBF F000A 0653@WD-WX12A A2PRN 13,64 79_A7 6D_D0 CO_OF 7B.,2 A5F3E42 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:39:15 | 74-56-3C-24-41-D6@BF EBFBF F000A 0653@WD-WX12A A2PRN 13,64 79_A7 6D_D0 CO_OF 7B.  | 否 |  |





|      |                       |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |                    |                        |   |   |  |
|------|-----------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|--------------------|------------------------|---|---|--|
| 2293 | 福建嘉木春<br>方建设有限公司      | 2024-04-23<br>15:25:43.0 | 74-56-3C-15-90-8D@BF<br>EBFBF<br>F000A<br>0671@E823_8FA6_BF53_0001_001B_448B_4E7F_CD49_ ,WCC6Y2TE2UL3   | 否 | 2024-04-23<br>15:24:11.0 | 74-56-3C-15-90-8D@BF<br>EBFBF<br>F000A<br>0671@E823_8FA6_BF53_0001_001B_448B_4E7F_CD49_ ,WCC6Y2TE2UL3   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误,请<br>检查 | 2024-04-24<br>08:38:10 | 74-56-3C-15-90-8D@BF<br>EBFBF<br>F000A<br>0671@E823_8FA6_BF53_0001_001B_448B_4E7F_CD49_ ,WCC6Y2TE2UL3   | 否 |  |
| 2294 | 福建省德力<br>水电建设有<br>限公司 | 2024-04-23<br>11:21:25.0 | E0-D5-5E-D8-42-69@BF<br>EBFBF<br>F0009<br>06EB@WD-<br>WCC6Y<br>4PYF1<br>VT, RW<br>19715<br>017D5<br>090 | 否 | 2024-04-23<br>11:17:50.0 | E0-D5-5E-D8-42-69@BF<br>EBFBF<br>F0009<br>06EB@WD-<br>WCC6Y<br>4PYF1<br>VT, RW<br>19715<br>017D5<br>090 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误,请<br>检查 | 2024-04-24<br>08:32:03 | E0-D5-5E-D8-42-69@BF<br>EBFBF<br>F0009<br>06EB@WD-<br>WCC6Y<br>4PYF1<br>VT, RW<br>19715<br>017D5<br>090 | 否 |  |





|      |               |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2299 | 福建省巨大建筑劳务有限公司 | 2024-04-23 16:42:08.0 | 00-<br>E0-<br>4C-<br>AF-<br>52-<br>1B@BF<br>EBFBF<br>F0003<br>06A9@<br>00000<br>00000<br>00000<br>00000<br>, 2LL2<br>WYGE | 否 | 2024-04-23 09:27:11.0 | 00-<br>E0-<br>4C-<br>AF-<br>52-<br>1B, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06A9@<br>00000<br>00000<br>00000<br>00000<br>, 2LL2<br>WYGE | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:49 | 00-<br>E0-<br>4C-<br>AF-<br>52-<br>1B@BF<br>EBFBF<br>F0003<br>06A9@<br>00000<br>00000<br>00000<br>00000<br>, 2LL2<br>WYGE | 否 |  |
| 2300 | 福建亿联升集团有限公司   | 2024-04-23 19:22:30.0 | 60-<br>45-<br>CB-<br>6C-<br>BE-<br>4B@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>1UH04<br>P5, 0B<br>826A0<br>06AE7  | 否 | 2024-04-23 19:19:55.0 | 60-<br>45-<br>CB-<br>6C-<br>BE-<br>4B@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>1UH04<br>P5, 0B<br>826A0<br>06AE7   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:44:49 | 60-<br>45-<br>CB-<br>6C-<br>BE-<br>4B@BF<br>EBFBF<br>F0009<br>06E9@<br>WD-<br>WCC6Y<br>1UH04<br>P5                        | 否 |  |
| 2301 | 中亩建设集团有限公司    | 2024-04-22 17:32:51.0 | F4-<br>B5-<br>20-<br>0B-<br>93-<br>56, 34<br>-4B-<br>50-<br>00-<br>00-<br>00, 00  | 否 | 2024-04-22 17:10:42.0 | F4-<br>B5-<br>20-<br>0B-<br>93-<br>56, 34<br>-4B-<br>50-<br>00-<br>00-<br>00, 00   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:36 | F4-<br>B5-<br>20-<br>0B-<br>93-<br>56, 34<br>-4B-<br>50-<br>00-<br>00-<br>00, 00  | 否 |  |













|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 2308 | 福建威唐建筑工程有限公司 | 2024-04-23 08:54:38.0 | 00-<br>E0-<br>1E-<br>34-<br>AD-<br>72@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0062_<br>5603_<br>3687.<br>, WD-<br>WX34P<br>3KN65<br>39 | 否 | 2024-04-19 15:37:01.0 | 00-<br>E0-<br>1E-<br>34-<br>AD-<br>72@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0062_<br>5603_<br>3687.<br>, WD-<br>WX34P<br>3KN65<br>39 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:20 | 00-<br>E0-<br>1E-<br>34-<br>AD-<br>72@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0062_<br>5603_<br>3687.<br>, WD-<br>WX34P<br>3KN65<br>39 | 否 |  |
| 2309 | 福建斯兴建设工程有限公司 | 2024-04-22 16:28:27.0 | 40-<br>B0-<br>76-<br>A3-<br>3B-<br>5C@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WMC2E<br>90712<br>31,00<br>25_38<br>C5_81<br>B0_17<br>1B.                                      | 否 | 2024-04-22 16:26:38.0 | 40-<br>B0-<br>76-<br>A3-<br>3B-<br>5C@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WMC2E<br>90712<br>31,00<br>25_38<br>C5_81<br>B0_17<br>1B.                                      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:45:31 | 40-<br>B0-<br>76-<br>A3-<br>3B-<br>5C@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WMC2E<br>90712<br>31,00<br>25_38<br>C5_81<br>B0_17<br>1B.                                      | 否 |  |

|      |                 |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |           |                     |   |   |  |
|------|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-----------|---------------------|---|---|--|
| 2310 | 福建彩翔建设工程有限公司    | 2024-04-23 10:29:14.0 | 4C-ED-FB-6B-97-75@BF EBFBF F0005 06E3@WD-WCC6Y 3VEC3 NR, 50 026B7 78224 2276                      | 否 | 2024-04-23 10:25:40.0 | 4C-ED-FB-6B-97-75@BF EBFBF F0005 06E3@WD-WCC6Y 3VEC3 NR, 50 026B7 78224 2276                      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:31:54 | 4C-ED-FB-6B-97-75@BF EBFBF F0005 06E3@WD-WCC6Y 3VEC3 NR, 50 026B7 78224 2276                      | 否 |  |
| 2311 | 福建南平市鑫源工程管理有限公司 | 2024-04-23 15:55:23.0 | 24-4B-FE-48-22-BA@BF EBFBF F0009 06EA@564A5 05931 30353 342, WD-WCC4J 5ZSX6 YZ, CM 317BH 15057 36 | 否 | 2024-04-23 15:55:00.0 | 24-4B-FE-48-22-BA@BF EBFBF F0009 06EA@564A5 05931 30353 342, WD-WCC4J 5ZSX6 YZ, CM 317BH 15057 36 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:44:26 | 24-4B-FE-48-22-BA@BF EBFBF F0009 06EA@564A5 05931 30353 342, WD-WCC4J 5ZSX6 YZ, CM 317BH 15057 36 | 否 |  |







|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|--|---|--|
| 2315 | 四川蓉达建筑工程有限公司 | 2024-04-23 09:43:58.0 | C8-7F-54-A8-5A-DA, 34-4B-50-00-00@BF<br>EBFBF<br>F000A<br>0653@<br>12345<br>6789A<br>BCDE1<br>, 0000<br>_0000<br>_0000<br>_0001<br>. | 否 | 2024-04-23 09:41:51.0 | C8-7F-54-A8-5A-DA, 34-4B-50-00-00@BF<br>EBFBF<br>F000A<br>0653@<br>12345<br>6789A<br>BCDE1<br>, 0000<br>_0000<br>_0000<br>_0001<br>. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:40 | C8-7F-54-A8-5A-DA, 34-4B-50-00-00@BF<br>EBFBF<br>F000A<br>0653@<br>12345<br>6789A<br>BCDE1<br>, 0000<br>_0000<br>_0000<br>_0001<br>. | 否  |   |  |
| 2316 | 丰景建设有限公司     | 2024-04-22 17:11:25.0 | A8-5E-45-6C-AD-14@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>5RPL2<br>CX, AA<br>00000<br>00000<br>00003<br>139                 | 否 | 2024-04-22 15:59:06.0 | A8-5E-45-6C-AD-14@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>5RPL2<br>CX, AA<br>00000<br>00000<br>00003<br>139                 | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:36:34  | 3C-7C-3F-C0-97-76@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC4J<br>ODF6L<br>P9, 50<br>026B7<br>38151<br>FF66 | 否 |  |



|      |                    |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |  |  |                            |   |   |  |
|------|--------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|--|----------------------------|---|---|--|
| 2319 | 福建省亨信<br>胜建设工程有限公司 | 2024-04-22<br>16:29<br>:14.0 | 58-<br>11-<br>22-<br>90-<br>CC-<br>09@BF<br>EBFBF<br>F0009<br>0672@<br>WD-<br>WCC6Y<br>3PEXE<br>7F,00<br>25_38<br>D7_21<br>A6_46<br>OB. | 否 | 2024-04-22<br>16:21<br>:11.0 | 58-<br>11-<br>22-<br>90-<br>CC-<br>09@BF<br>EBFBF<br>F0009<br>0672@<br>WD-<br>WCC6Y<br>3PEXE<br>7F,00<br>25_38<br>D7_21<br>A6_46<br>OB. | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>查<br>检 | 2024-04-24<br>08:34<br>:41 | 58-<br>11-<br>22-<br>90-<br>CC-<br>09@BF<br>EBFBF<br>F0009<br>0672@<br>WD-<br>WCC6Y<br>3PEXE<br>7F,00<br>25_38<br>D7_21<br>A6_46<br>OB. | 否 |  |
| 2320 | 福建云深建<br>设有限公司     | 2024-04-23<br>14:57<br>:38.0 | F0-<br>2F-<br>74-<br>86-<br>47-<br>F7@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>3LF5E<br>Y9,AA<br>00000<br>00122<br>40002<br>498 | 否 | 2024-04-23<br>11:16<br>:01.0 | F0-<br>2F-<br>74-<br>86-<br>47-<br>F7@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>3LF5E<br>Y9,AA<br>00000<br>00122<br>40002<br>498 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>查<br>检 | 2024-04-24<br>08:49<br>:51 | F0-<br>2F-<br>74-<br>86-<br>47-<br>F7@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>3LF5E<br>Y9,AA<br>00000<br>00122<br>40002<br>498 | 否 |  |
| 2321 | 福建千弘建<br>设有限公司     | 2024-04-23<br>08:50<br>:39.0 | 40-<br>8D-<br>5C-<br>BE-<br>5C-<br>75,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF                                   | 否 | 2024-04-23<br>08:47<br>:31.0 | 40-<br>8D-<br>5C-<br>BE-<br>5C-<br>75,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF                                   | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>，<br>请<br>查<br>检 | 2024-04-24<br>08:39<br>:53 | 40-<br>8D-<br>5C-<br>BE-<br>5C-<br>75,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF                                   | 否 |  |







|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2328 | 福建新伟辰建设有限公司  | 2024-04-23 10:19:47.0 | 30-9C-23-06-59-6F@BF EBFBF F0005 06E3@ KC235 031C3 F0905 , WD- WCC6Y 2PACU TJ | 否 | 2024-04-23 10:17:12.0 | 30-9C-23-06-59-6F@BF EBFBF F0005 06E3@ KC235 031C3 F0905 , WD- WCC6Y 2PACU TJ | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:40:38 | 30-9C-23-06-59-6F@BF EBFBF F0005 06E3@ KC235 031C3 F0905 , WD- WCC6Y 2PACU TJ | 否 |  |
| 2329 | 福建擎龙建设工程有限公司 | 2024-04-23 17:00:59.0 | 4C-CC-6A-89-5D-28@BF EBFBF F0009 06E9@ W9A9S N7W, A A0000 00000 00489         | 否 | 2024-04-23 16:55:43.0 | 4C-CC-6A-89-5D-28@BF EBFBF F0009 06E9@ W9A9S N7W, A A0000 00000 00489         | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:48 | 4C-CC-6A-89-5D-28@BF EBFBF F0009 06E9@ W9A9S N7W, A A0000 00000 00489         | 否 |  |





|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |  |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|--|---|--|
| 2332 | 福建省强源建设发展有限公司  | 2024-04-23 19:35:43.0 | 08-BF-B8-30-14-B3@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C17_<br>0572_<br>FD62. | 否 | 2024-04-23 19:32:10.0 | 08-BF-B8-30-14-B3@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C17_<br>0572_<br>FD62. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:07 | 08-BF-B8-30-14-B3@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>00E0_<br>4C17_<br>0572_<br>FD62. | 否  |   |  |
| 2333 | 中达（福建）建设服务有限公司 | 2024-04-23 19:27:32.0 | 18-31-BF-0A-90-69@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01422<br>,Z9AV<br>BFBJ                    | 否 | 2024-04-23 13:20:51.0 | 18-31-BF-0A-90-69@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01422<br>,Z9AV<br>BFBJ                    | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:31:45   | 18-31-BF-0A-90-69@BF<br>EBFBF<br>F0009<br>06E9@<br>AA000<br>00000<br>00000<br>01422<br>,Z9AV<br>BFBJ | 否 |  |

|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|--|---|--|
| 2334 | 福建省裕如丰建设工程有限公司 | 2024-04-22 09:59:17.0 | F4-6B-8C-CB-0E-0E@BF EBFBF F0009 0675@ ACE4_2E00_2AAC_256C_2EE4_ AC00_ 0000_ 0001. | 否 | 2024-04-22 09:50:42.0 | F4-6B-8C-CB-0E-0E@BF EBFBF F0009 0675@ ACE4_2E00_2AAC_256C_2EE4_ AC00_ 0000_ 0001. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:31:48 | F4-6B-8C-CB-0E-0E@BF EBFBF F0009 0675@ ACE4_2E00_2AAC_256C_2EE4_ AC00_ 0000_ 0001. | 否  |   |  |
| 2335 | 福建厚凯建设有限公司     | 2024-04-23 09:40:22.0 | 00-E0-0A-13-15-33@BF EBFBF F0003 06A9@ 001A2 01100 20921 7                         | 否 | 2024-04-23 09:37:48.0 | 00-E0-0A-13-15-33@BF EBFBF F0003 06A9@ 001A2 01100 20921 7                         | 否 |  |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:41:08  | 00-E0-0A-13-15-33@BF EBFBF F0003 06A9@ 001A2 01100 20921 7 | 否 |  |





|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|---|--|
| 2340 | 福建坤弘建设工程有限公司 | 2024-04-23 11:57:34.0 | 74-56-3C-13-CB-7B@BF<br>EBFBF<br>F0009<br>0675@<br>WCC6Y<br>5LSK6<br>NV,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1C<br>6E_BB<br>65. | 否 | 2024-04-23 11:54:10.0 | 74-56-3C-13-CB-7B@BF<br>EBFBF<br>F0009<br>0675@<br>WCC6Y<br>5LSK6<br>NV,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1C<br>6E_BB<br>65. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:44:35 | 74-56-3C-13-CB-7B@BF<br>EBFBF<br>F0009<br>0675@<br>WCC6Y<br>5LSK6<br>NV,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_1C<br>6E_BB<br>65. | 否   |   |  |
| 2341 | 安徽凯星建设工程有限公司 | 2024-04-23 15:22:58.0 | 74-56-3C-83-E6-05@BF<br>EBFBF<br>F0009<br>06EA@<br>NKC99<br>22025<br>4980S<br>304  | 否 | 2024-04-20 17:17:54.0 | 74-56-3C-83-E6-05@BF<br>EBFBF<br>F0009<br>06EA@<br>NKC99<br>22025<br>4980S<br>304  | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:35:02  | 74-56-3C-83-E6-05@BF<br>EBFBF<br>F0009<br>06EA@<br>NKC99<br>22025<br>4980S<br>304 | 否 |  |









|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2346 | 贵州筑采宝建设有限公司   | 2024-04-23 15:16:33.0 | 90-6F-18-03-11-CD@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_448B_4A9F_404B.                    | 否 | 2024-04-23 15:10:42.0 | 90-6F-18-03-11-CD@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_448B_4A9F_404B.                    | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:47:27 | 90-6F-18-03-11-CD@BF<br>EBFBF<br>F0009<br>0675@<br>E823_8FA6_ BF53_0001_001B_448B_4A9F_404B.                    | 否 |  |
| 2347 | 忠泰建设集团有限公司    | 2024-04-23 10:20:21.0 | 00-E0-4D-B5-1E-95@BF<br>EBFBF<br>F0003<br>06C3@<br>AA000<br>00062<br>9507A<br>A                                 | 否 | 2024-04-23 10:19:38.0 | 00-E0-4D-B5-1E-95@BF<br>EBFBF<br>F0003<br>06C3@<br>AA000<br>00062<br>9507A<br>A                                 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:38:18 | 00-E0-4D-B5-1E-95@BF<br>EBFBF<br>F0003<br>06C3@<br>AA000<br>00062<br>9507A<br>A                                 | 否 |  |
| 2348 | 福建省延禹建设工程有限公司 | 2024-04-23 11:58:52.0 | A0-36-BC-25-19-41@BF<br>EBFBF<br>F0009<br>0675@<br>WD-WCC6Y<br>2TFYL<br>EN,00<br>00_00<br>00_00<br>00_00<br>01. | 否 | 2024-04-23 08:10:45.0 | A0-36-BC-25-19-41@BF<br>EBFBF<br>F0009<br>0675@<br>WD-WCC6Y<br>2TFYL<br>EN,00<br>00_00<br>00_00<br>00_00<br>01. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差，请检查 | 2024-04-24 08:34:15 | A0-36-BC-25-19-41@BF<br>EBFBF<br>F0009<br>0675@<br>WD-WCC6Y<br>2TFYL<br>EN,00<br>00_00<br>00_00<br>00_00<br>01. | 否 |  |







|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2355 | 福建三江建设工程有限公司 | 2024-04-23 16:18:03.0 | 18-31-BF-93-6E-F2@BF EBFBF F0009 06E9@50026 B7381 7DBEC 8, Z9A S8R9J | 否 | 2024-04-23 15:09:22.0 | 18-31-BF-93-6E-F2@BF EBFBF F0009 06E9@50026 B7381 7DBEC 8, Z9A S8R9J | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:37:29 | 4C-ED-FB-63-75-60@BF EBFBF F0009 06E9@30353 23042 36363 73238 36323 84241 38202 02020 | 否 |  |
| 2356 | 福建睿鼎建设工程有限公司 | 2024-04-23 13:43:43.0 | 00-E0-0A-17-00-D9@BF EBFBF F0003 06E4@50026 B7381 28E5D F            | 否 | 2024-04-23 13:42:00.0 | 00-E0-0A-17-00-D9@BF EBFBF F0003 06E4@50026 B7381 28E5D F            | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:31:34 | 00-E0-0A-17-00-D9@BF EBFBF F0003 06E4@50026 B7381 28E5D F                             | 否 |  |









|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|--|---|--|
| 2360 | 福建省源鼎达建设工程有限公司 | 2024-04-22 16:42:40.0 | 10-3D-0A-DF-37-20,00-E0-70-A2-B7-EC,10-3D-0A-DF-37-1F,10-3D-0A-DF-37-1F,10-3D-0A-DF-37-1F@BF EBFBF F0009 06EB@ 0025_ 3887_ 01B8_ BD05. ,WD- WX22A 606VA HL | 否 | 2024-04-22 14:59:38.0 | 10-3D-0A-DF-37-1F,10-3D-0A-DF-37-1F,92-3D-0A-DF-37-1F,00-E0-70-A2-B7-EC,10-3D-0A-DF-37-20@BF EBFBF F0009 06EB@ 0025_ 3887_ 01B8_ BD05. ,WD- WX22A 606VA HL | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:34 | 10-3D-0A-DF-37-1F,10-3D-0A-DF-37-1F,92-3D-0A-DF-37-1F,00-E0-70-A2-B7-EC,10-3D-0A-DF-37-20@BF EBFBF F0009 06EB@ 0025_ 3887_ 01B8_ BD05. ,WD- WX22A 606VA HL | 否  |   |  |
| 2361 | 福建威越建设有限公司     | 2024-04-23 11:15:47.0 | 04-42-1A-ED-DF-70@BF EBFBF F000A 0653@ 50026 B7381 67A93   | 否 | 2024-04-23 11:14:13.0 | 04-42-1A-ED-DF-70@BF EBFBF F000A 0653@ 50026 B7381 67A93   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:40:18  | 04-42-1A-ED-DF-70@BF EBFBF F000A 0653@ 50026 B7381 67A93 | 否 |  |

|      |                |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                              |                                |   |   |  |
|------|----------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------------------------|--------------------------------|---|---|--|
|      |                |                                  | E, WD-<br>WCC6Y<br>1DF66<br>CS  |   |                                  | E, WD-<br>WCC6Y<br>1DF66<br>CS  |   |  |  |  |  |  |  |  |  |  |  |                              | E, WD-<br>WCC6Y<br>1DF66<br>CS |   |   |  |
| 2362 | 林奋建设有<br>限公司   | 2024-<br>04-23<br>11:23<br>:07.0 | 74-<br>56-<br>3C-<br>95-<br>27-<br>23, OA<br>-62-<br>30-<br>81-<br>55-<br>F7@BF<br>EBFBF<br>F000A<br>0653@<br>NCP13<br>OR010<br>8390S<br>302  | 否 | 2024-<br>04-23<br>11:20<br>:01.0 | 74-<br>56-<br>3C-<br>95-<br>27-<br>23, OA<br>-62-<br>30-<br>81-<br>55-<br>F7@BF<br>EBFBF<br>F000A<br>0653@<br>NCP13<br>OR010<br>8390S<br>302  | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:32<br>:38 | 74-<br>56-<br>3C-<br>95-<br>27-<br>23, OA<br>-62-<br>30-<br>81-<br>55-<br>F7@BF<br>EBFBF<br>F000A<br>0653@<br>NCP13<br>OR010<br>8390S<br>302  | 否 |  |
| 2363 | 福建综康建<br>设有限公司 | 2024-<br>04-23<br>17:47<br>:06.0 | 64-<br>6E-<br>97-<br>F4-<br>05-<br>9F, 18<br>-C0-<br>4D-<br>90-<br>12-<br>EF@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7783<br>75F55<br>C, WD-<br>WCC6Y<br>3NZ81<br>E5, 6B<br>02AB4<br>047C7 | 否 | 2024-<br>04-23<br>15:23<br>:54.0 | 64-<br>6E-<br>97-<br>F4-<br>05-<br>9F, 18<br>-C0-<br>4D-<br>90-<br>12-<br>EF@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7783<br>75F55<br>C, WD-<br>WCC6Y<br>3NZ81<br>E5, 6B<br>02AB4<br>047C7 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:34<br>:07 | 64-<br>6E-<br>97-<br>F4-<br>05-<br>9F, 18<br>-C0-<br>4D-<br>90-<br>12-<br>EF@BF<br>EBFBF<br>F0009<br>06EA@<br>50026<br>B7783<br>75F55<br>C, WD-<br>WCC6Y<br>3NZ81<br>E5, 6B<br>02AB4<br>047C7 | 否 |  |

|      |                         |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                            |                                |  |   |   |  |
|------|-------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|---|--|
| 2364 | 福建省南平<br>建宇建筑工程<br>有限公司 | 2024-<br>04-23<br>08:28<br>:14.0 | A8-<br>5E-<br>45-<br>9B-<br>A3-<br>67@BF<br>EBFBF<br>F0009<br>06ED@<br>0100_<br>0000_<br>0000_<br>0000.  | 否 | 2024-<br>04-23<br>08:22<br>:04.0 | A8-<br>5E-<br>45-<br>9B-<br>A3-<br>67@BF<br>EBFBF<br>F0009<br>06ED@<br>0100_<br>0000_<br>0000_<br>0000.  | 否 |  |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>，请<br>检查     | 2024-<br>04-24<br>08:31<br>:47   | A8-<br>5E-<br>45-<br>9B-<br>A3-<br>67@BF<br>EBFBF<br>F0009<br>06ED@<br>0100_<br>0000_<br>0000_<br>0000. | 否 |  |
| 2365 | 福建侨晟森<br>磊建设有限<br>公司    | 2024-<br>04-22<br>11:48<br>:36.0 | 74-<br>56-<br>3C-<br>30-<br>BC-<br>C6@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1929_<br>AB05.<br>, WD-<br>WCC6Y<br>0JEES<br>5J | 否 | 2024-<br>04-22<br>11:21<br>:47.0 | 74-<br>56-<br>3C-<br>30-<br>BC-<br>C6@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1929_<br>AB05.<br>, WD-<br>WCC6Y<br>0JEES<br>5J | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:54<br>:03 | 74-<br>56-<br>3C-<br>30-<br>BC-<br>C6@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>1929_<br>AB05.<br>, WD-<br>WCC6Y<br>0JEES<br>5J | 否   |   |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2366 | 福建中闽汇达发展有限公司 | 2024-04-23 12:17:17.0 | 08-BF-B8-1C-A8-C9, D4-84-09-39-5C-4A@BF EBFBF F000B 06F2@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4C42_ 441F. | 否 | 2024-04-23 12:15:01.0 | 08-BF-B8-1C-A8-C9, D4-84-09-39-5C-4A@BF EBFBF F000B 06F2@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4C42_ 441F. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:44:29 | 08-BF-B8-1C-A8-C9, D4-84-09-39-5C-4A@BF EBFBF F000B 06F2@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4C42_ 441F. | 否 |  |
| 2367 | 福建鑫禹水利建设有限公司 | 2024-04-23 17:35:06.0 | B8-97-5A-D7-FB-FF@BF EBFBF F0005 06E3@ RW195 28233 A0198, WD-WCC6Y 3YUYX PE                               | 否 | 2024-04-23 17:33:57.0 | B8-97-5A-D7-FB-FF@BF EBFBF F0005 06E3@ RW195 28233 A0198, WD-WCC6Y 3YUYX PE                               | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:07 | B8-97-5A-D7-FB-FF@BF EBFBF F0005 06E3@ RW195 28233 A0198, WD-WCC6Y 3YUYX PE                               | 否 |  |

|      |                   |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                         |                            |  |   |  |
|------|-------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|-------------------------|----------------------------|--|---|--|
| 2368 | 福建大武夷<br>建设工程有限公司 | 2024-04-23<br>18:06<br>:10.0 | 00-<br>E0-<br>4F-<br>12-<br>38-<br>E3@BF<br>EBFBF<br>F0002<br>06D7@<br>L1644<br>10007<br>, WD-<br>WCC6Y<br>5UT45<br>YT                   | 否 | 2024-04-23<br>18:03<br>:08.0 | 00-<br>E0-<br>4F-<br>12-<br>38-<br>E3@BF<br>EBFBF<br>F0002<br>06D7@<br>L1644<br>10007<br>, WD-<br>WCC6Y<br>5UT45<br>YT                   | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:33<br>:38 | 00-<br>E0-<br>4F-<br>12-<br>38-<br>E3@BF<br>EBFBF<br>F0002<br>06D7@<br>L1644<br>10007<br>, WD-<br>WCC6Y<br>5UT45<br>YT                   | 否 |  |
| 2369 | 福建鑫旺丰<br>建设有限公司   | 2024-04-23<br>15:10<br>:38.0 | 48-<br>F3-<br>17-<br>01-<br>D1-<br>E6@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>3KPFN<br>5V, AA<br>00000<br>00000<br>00019<br>309 | 否 | 2024-04-23<br>15:09<br>:12.0 | 48-<br>F3-<br>17-<br>01-<br>D1-<br>E6@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>3KPFN<br>5V, AA<br>00000<br>00000<br>00019<br>309 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误, 请<br>检查 | 2024-04-24<br>08:35<br>:40 | 48-<br>F3-<br>17-<br>01-<br>D1-<br>E6@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>3KPFN<br>5V, AA<br>00000<br>00000<br>00019<br>309 | 否 |  |











|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2374 | 福建省盛益欣建设发展有限公司 | 2024-04-23 16:51:20.0 | 00-<br>E0-<br>4C-<br>7C-<br>7C-<br>DD@17<br>8BFBF<br>F00A5<br>0F00@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000.           | 否 | 2024-04-23 11:07:47.0 | 00-<br>E0-<br>4C-<br>7C-<br>7C-<br>DD@17<br>8BFBF<br>F00A5<br>0F00@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000.           | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:45 | 00-<br>E0-<br>4C-<br>7C-<br>7C-<br>DD@17<br>8BFBF<br>F00A5<br>0F00@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0100_<br>0000_<br>0000.           | 否 |  |
| 2375 | 福建省融超建设工程有限公司  | 2024-04-23 15:52:06.0 | 7C-<br>10-<br>C9-<br>8E-<br>0E-<br>29@BF<br>EBFBF<br>F000A<br>0655@<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>103B_<br>0365.<br>, Y8NJ<br>1APMS | 否 | 2024-04-19 11:19:42.0 | 7C-<br>10-<br>C9-<br>8E-<br>0E-<br>29@BF<br>EBFBF<br>F000A<br>0655@<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>103B_<br>0365.<br>, Y8NJ<br>1APMS | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:37:52 | 7C-<br>10-<br>C9-<br>8E-<br>0E-<br>29@BF<br>EBFBF<br>F000A<br>0655@<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>103B_<br>0365.<br>, Y8NJ<br>1APMS | 否 |  |

|      |                        |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |                            |                                |   |   |   |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|---|---|---|--|
| 2376 | 福建八闽福<br>川建设工程<br>有限公司 | 2024-<br>04-19<br>10:53<br>:10.0 | 24-<br>4B-<br>FE-<br>81-<br>9D-<br>C0@BF<br>EBFBF<br>F000A<br>0653@<br>2044C<br>38008<br>06, WD<br>-<br>WXM2A<br>A0960<br>KF                | 否 | 2024-<br>04-19<br>10:24<br>:08.0 | 24-<br>4B-<br>FE-<br>81-<br>9D-<br>C0@BF<br>EBFBF<br>F000A<br>0653@<br>2044C<br>38008<br>06, WD<br>-<br>WXM2A<br>A0960<br>KF                | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:46<br>:25 | D8-<br>BB-<br>C1-<br>07-<br>70-<br>23@BF<br>EBFBF<br>F000A<br>0653@<br>W2AJP<br>4ND, K<br>44101<br>1E016<br>22<br>_0000<br>0001.            | 否   |   |  |
| 2377 | 福建省邵武<br>市六建工程<br>有限公司 | 2024-<br>04-23<br>10:53<br>:01.0 | B4-<br>2E-<br>99-<br>E0-<br>97-<br>CA@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36333<br>73038<br>42374<br>63945<br>34202<br>02020 | 否 | 2024-<br>04-23<br>10:50<br>:00.0 | B4-<br>2E-<br>99-<br>E0-<br>97-<br>CA@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36333<br>73038<br>42374<br>63945<br>34202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:31<br>:33 | B4-<br>2E-<br>99-<br>E0-<br>97-<br>CA@BF<br>EBFBF<br>F0009<br>06EA@<br>30353<br>23042<br>36333<br>73038<br>42374<br>63945<br>34202<br>02020 | 否   |   |  |
| 2378 | 万喜建筑有<br>限公司           | 2024-<br>04-23<br>13:57<br>:30.0 | 1C-<br>1B-<br>0D-<br>A8-<br>D8-<br>7A@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7782<br>8A7FD<br>5   | 否 | 2024-<br>04-23<br>13:55<br>:27.0 | 1C-<br>1B-<br>0D-<br>A8-<br>D8-<br>7A@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7782<br>8A7FD<br>5   | 否 |  |  |  |  |  |  |  |  |  |                            | 校验<br>数据<br>有误<br>，请<br>检查     | 2024-<br>04-24<br>08:38<br>:32  | 1C-<br>1B-<br>0D-<br>A8-<br>D8-<br>7A@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7782<br>8A7FD<br>5 | 否 |  |

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2379 | 福建省昌盛通建设发展有限公司 | 2024-04-22 10:47:44.0 | D4-5D-64-D5-1C-09@BF<br>EBFBF<br>F0009<br>06EB@<br>30353<br>23042<br>36333<br>73038<br>38383<br>04244<br>43202<br>02020 | 否 | 2024-04-22 10:39:24.0 | D4-5D-64-D5-1C-09@BF<br>EBFBF<br>F0009<br>06EB@<br>30353<br>23042<br>36333<br>73038<br>38383<br>04244<br>43202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:31:33 | D4-5D-64-D5-1C-09@BF<br>EBFBF<br>F0009<br>06EB@<br>30353<br>23042<br>36333<br>73038<br>38383<br>04244<br>43202<br>02020 | 否 |  |
| 2380 | 福建西金建设有限公司     | 2024-04-23 13:41:58.0 | 00-CF-E0-56-E4-3C@BF<br>EBFBF<br>F0009<br>06EA@<br>YS202<br>00389<br>05000<br>23515<br>,WD-<br>WCC2E<br>SV540<br>98     | 否 | 2024-04-23 13:30:58.0 | 00-CF-E0-56-E4-3C@BF<br>EBFBF<br>F0009<br>06EA@<br>YS202<br>00389<br>05000<br>23515<br>,WD-<br>WCC2E<br>SV540<br>98     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:31:54 | 00-CF-E0-56-E4-3C@BF<br>EBFBF<br>F0009<br>06EA@<br>YS202<br>00389<br>05000<br>23515<br>,WD-<br>WCC2E<br>SV540<br>98     | 否 |  |
| 2381 | 福建厚汇达建设工程有限公司  | 2024-04-23 15:40:21.0 | D8-BB-C1-D9-2E-A3@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_                            | 否 | 2024-04-23 15:29:34.0 | D8-BB-C1-D9-2E-A3@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_                            | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:22 | D8-BB-C1-D9-2E-A3@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_                            | 否 |  |





|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |  |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|--|---|--|
| 2385 | 中建南辉建设有限公司     | 2024-04-23 18:01:21.0 | 4C-ED-FB-64-11-67@BF EBFBF F0009 06E9@41543 83132 37303 13837 30473 33520 37202 02020 | 否 | 2024-04-23 17:58:27.0 | 4C-ED-FB-64-11-67@BF EBFBF F0009 06E9@41543 83132 37303 13837 30473 33520 37202 02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:40:04 | 4C-ED-FB-64-11-67@BF EBFBF F0009 06E9@41543 83132 37303 13837 30473 33520 37202 02020 | 否  |   |  |
| 2386 | 福建晟达坤建设发展有限公司  | 2024-04-23 09:09:51.0 | 18-CO-4D-D2-C2-E4@BF EBFBF F000A 0653@2049L 74898 02                                  | 否 | 2024-04-23 09:08:57.0 | 18-CO-4D-D2-C2-E4@BF EBFBF F000A 0653@2049L 74898 02                                  | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:32:36   | 18-CO-4D-D2-C2-E4@BF EBFBF F000A 0653@2049L 74898 02                           | 否 |  |
| 2387 | 福建省中鼎昇建设工程有限公司 | 2024-04-22 18:05:07.0 | 74-56-3C-4F-2C-DC@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B778_54B2_B215.,0      | 否 | 2024-04-22 17:56:19.0 | 74-56-3C-4F-2C-DC@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B778_54B2_B215.,0      | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:32:12   | 74-56-3C-4F-2C-DC@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B778_54B2_B215. | 否 |  |







|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2392 | 福建保利得建设发展有限公司 | 2024-04-23 09:19:36.0 | A0-36-BC-2B-F6-35,00-00-00-00-00-00-00-00-0653@2020202057202d44435736433159485655324352, CAF2_5B03_FF00_05E6. | 否 | 2024-04-23 09:17:44.0 | A0-36-BC-2B-F6-35,00-00-00-00-00-00-00-00-0653@E0@BFEBFBFF000A0653@2020202057202d44435736433159485655324352, CAF2_5B03_FF00_05E6. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:22 | A0-36-BC-2B-F6-35@BFEBFBFF000A0653@2020202057202d44435736433159485655324352, CAF2_5B03_FF00_05E6. | 否 |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 2395 | 福建九宇建设工程有限公司 | 2024-04-18 10:12:52.0 | 04-D9-F5-F4-8D-65@BFEBFBFF000906EA@50026B738069E5A5   | 否 | 2024-04-18 09:59:11.0 | 04-D9-F5-F4-8D-65@BFEBFBFF000906EA@50026B738069E5A5   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:48 | 04-D9-F5-F4-8D-65@BFEBFBFF000906EA@50026B738069E5A5   | 否 |  |
| 2396 | 湖南娄东建设有限公司   | 2024-04-19 11:30:53.0 | 00-E0-4C-42-A0-64@BFEBFBFF000A0653@2HT1007B11R4S01BB0 | 否 | 2024-04-19 11:03:51.0 | 00-E0-4C-42-A0-64@BFEBFBFF000A0653@2HT1007B11R4S01BB0 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:46:13 | 00-E0-4C-42-A0-64@BFEBFBFF000A0653@2HT1007B11R4S01BB0 | 否 |  |



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2399 | 福建旺阳建设工程有限公司 | 2024-04-23 17:13:14.0 | 58-11-22-D0-46-05@BFEBFBF00090675@30097056358 | 否 | 2024-04-23 17:12:03.0 | 58-11-22-D0-46-05@BFEBFBF00090675@30097056358 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:40:43 | 58-11-22-D0-46-05@BFEBFBF00090675@30097056358 | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|---|--|
| 2400 | 福建顺兴公路建设有限公司 | 2024-04-22 17:09:32.0 | E0-D5-5E-2F-F4-36@BF<br>EBFBF<br>F0009<br>06E9@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>75958<br>5a415<br>24858<br>,3232<br>31344<br>33030<br>38363<br>33335<br>20202<br>02020<br>20202<br>0 | 否 | 2024-04-22 17:06:06.0 | E0-D5-5E-2F-F4-36,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>75958<br>06E9@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>F0009<br>5a415<br>24858<br>,3232<br>31344<br>33030<br>38363<br>33335<br>20202<br>02020<br>20202<br>0 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:10 | E0-D5-5E-2F-F4-36@BF<br>EBFBF<br>F0009<br>06E9@<br>20202<br>02057<br>202d4<br>44357<br>36433<br>75958<br>5a415<br>24858<br>,3232<br>31344<br>33030<br>38363<br>33335<br>20202<br>02020<br>20202<br>0 | 否   |   |  |
| 2401 | 福建祥达源建设有限公司  | 2024-04-22 16:41:33.0 | 40-B0-76-DB-BA-90@BF<br>EBFBF<br>F0009<br>06E9@  | 否 | 2024-04-22 16:40:31.0 | 40-B0-76-DB-BA-90@BF<br>EBFBF<br>F0009<br>06E9@  | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:32:03  | 40-B0-76-DB-BA-90@BF<br>EBFBF<br>F0009<br>06E9@ | 否 |  |

|      |              |                          |   |   |                          |   |  |  |  |  |  |  |  |  |  |  |  |             |                              |   |   |  |
|------|--------------|--------------------------|---|---|--------------------------|---|--|--|--|--|--|--|--|--|--|--|--|-------------|------------------------------|---|---|--|
|      |              |                          | 50026<br>B7382<br>880DB<br>2  |   |                          | 50026<br>B7382<br>880DB<br>2  |  |  |  |  |  |  |  |  |  |  |  |             | 50026<br>B7382<br>880DB<br>2 |   |   |  |
| 2402 | 福建钦工建设工程有限公司 | 2024-04-22<br>12:17:09.0 | 24-4B-<br>FE-<br>D0-<br>42-<br>4B@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7783<br>7CAEA<br>D                           | 否 | 2024-04-22<br>10:59:11.0 | 24-4B-<br>FE-<br>D0-<br>42-<br>4B@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7783<br>7CAEA<br>D                           |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24<br>08:34:53       | 24-4B-<br>FE-<br>D0-<br>42-<br>4B@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7783<br>7CAEA<br>D                           | 否 |  |
| 2403 | 福建通港建设有限公司   | 2024-04-22<br>14:15:33.0 | 2C-<br>F0-<br>5D-<br>F5-<br>52-<br>70@BF<br>EBFBF<br>F000A<br>0653@<br>213HH<br>LWFS,<br>6479_<br>A74C_<br>8020_<br>232E. | 否 | 2024-04-22<br>14:07:29.0 | 2C-<br>F0-<br>5D-<br>F5-<br>52-<br>70@BF<br>EBFBF<br>F000A<br>0653@<br>213HH<br>LWFS,<br>6479_<br>A74C_<br>8020_<br>232E. |  |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24<br>08:36:34       | 2C-<br>F0-<br>5D-<br>F5-<br>52-<br>70@BF<br>EBFBF<br>F000A<br>0653@<br>213HH<br>LWFS,<br>6479_<br>A74C_<br>8020_<br>232E. | 否 |  |













|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2411 | 福建琦裕建设工程有限公司 | 2024-04-23 11:48:56.0 | 24-4B-FE-81-9E-D9, 3C-06-A7-B9-BF-B9@BF EBFBF F000A 0653@ EE03D 95056 E8, 50 026B7 381A1 2330               | 否 | 2024-04-22 10:02:38.0 | 24-4B-FE-81-9E-D9, 3C-06-A7-B9-BF-B9@BF EBFBF F000A 0653@ EE03D 95056 E8, 50 026B7 381A1 2330               | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:38:04 | 24-4B-FE-81-9E-D9, 3C-06-A7-B9-BF-B9@BF EBFBF F000A 0653@ EE03D 95056 E8, 50 026B7 381A1 2330               | 否 |  |
| 2412 | 福建权旺建设工程有限公司 | 2024-04-23 16:08:58.0 | 08-BF-B8-BB-54-D1@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 48E2_ 4DB1. , WD- WCC6Y 1T85V HD | 否 | 2024-04-22 15:08:18.0 | 08-BF-B8-BB-54-D1@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 48E2_ 4DB1. , WD- WCC6Y 1T85V HD | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:37:04 | 08-BF-B8-BB-54-D1@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 48E2_ 4DB1. , WD- WCC6Y 1T85V HD | 否 |  |

|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 2413 | 林耘建设有限公司   | 2024-04-23 16:08:42.0 | 00-E0-4C-4A-B4-0F@BF EBFBF F000A 0653@ 50026 B7382 03489 7 | 否 | 2024-04-19 16:36:13.0 | 00-E0-4C-4A-B4-0F@BF EBFBF F000A 0653@ 50026 B7382 03489 7 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:39 | 00-E0-4C-4A-B4-0F@BF EBFBF F000A 0653@ 50026 B7382 03489 7 | 否 |  |
| 2414 | 福建汀恒建设有限公司 | 2024-04-23 15:28:53.0 | E0-D5-5E-19-D5-FC@BF EBFBF F0009 06E9@ 79RB8 OH4KE KN      | 否 | 2024-04-23 15:26:44.0 | E0-D5-5E-19-D5-FC@BF EBFBF F0009 06E9@ 79RB8 OH4KE KN      | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:36:34 | E0-D5-5E-19-D5-FC@BF EBFBF F0009 06E9@ 79RB8 OH4KE KN      | 否 |  |









|      |                    |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |                    |                            |   |        |   |  |
|------|--------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|--------------------|----------------------------|---|--------|---|--|
| 2418 | 福建望嘉星<br>建设发展有限公司  | 2024-04-23<br>11:35<br>:27.0 | 04-7C-16-0B-62-38@BF<br>EBFBF<br>F0009<br>0675@<br>20170<br>90602<br>593  | 否 | 2024-04-23<br>11:33<br>:02.0 | 04-7C-16-0B-62-38@BF<br>EBFBF<br>F0009<br>0675@<br>20170<br>90602<br>593  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误,请查<br>检 | 2024-04-24<br>08:42<br>:22 | 04-7C-16-0B-62-38@BF<br>EBFBF<br>F0009<br>0675@<br>20170<br>90602<br>593  | 否      |   |  |
| 2419 | 福建通浩捷<br>茂建设工程有限公司 | 2024-04-23<br>14:55<br>:58.0 | 24-4B-FE-9A-38-OE@BF<br>EBFBF<br>F0009<br>06EA@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>48C6_<br>A731. | 否 | 2024-04-23<br>14:48<br>:46.0 | 24-4B-FE-9A-38-OE@BF<br>EBFBF<br>F0009<br>06EA@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>48C6_<br>A731. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误,请查<br>检 | 2024-04-24<br>08:34<br>:23 | 24-4B-FE-9A-38-OE@BF<br>EBFBF<br>F0009<br>06EA@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>48C6_<br>A731. | 否      |   |  |
| 2420 | 福建中巢建<br>设有限公司     | 2024-04-23<br>17:07<br>:24.0 | D8-5E-D3-7A-9B-76@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>19BA_<br>8CD5. | 否 | 2024-04-23<br>17:06<br>:25.0 | D8-5E-D3-7A-9B-76@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>19BA_<br>8CD5. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误,请查<br>检 | 2024-04-24<br>08:32<br>:47 | D8-5E-D3-7A-9B-76@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>19BA_<br>8CD5. | 否      |   |  |
| 2421 | 重庆市巴岳<br>建筑安装工     | 2024-04-23                   | 00-E0-  | 否 | 2024-04-23                   | 00-E0-  | 否 |  |  |  |  |  |  |  |  |  |                    | 校验数据                       | 2024-04-24  | 00-E0- | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |                               |                               |  |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|-------------------------------|-------------------------------|--|--|---|--|
|      | 程有限公司        | 15:53:10.0            | 1F-78-17-A5@BF<br>EBFBF<br>F0009<br>0675@<br>SCRW2<br>31215<br>07G01<br>99   | 否 | 15:44:47.0            | 1F-78-17-A5@BF<br>EBFBF<br>F0009<br>0675@<br>SCRW2<br>31215<br>07G01<br>99   | 否 |  |  |  |  |  |  |  |  |                               | 有误<br>请<br>检查                 | 08:41:39   | 1F-78-17-A5@BF<br>EBFBF<br>F0009<br>0675@<br>SCRW2<br>31215<br>07G01<br>99 |   |  |
| 2422 | 中福君成集团有限公司   | 2024-04-23 15:56:33.0 | 18-C0-4D-C6-71-FA@BF<br>EBFBF<br>F000A<br>0653@<br>5266M<br>21280<br>5214  | 否 | 2024-04-23 15:54:02.0 | 18-C0-4D-C6-71-FA@BF<br>EBFBF<br>F000A<br>0653@<br>5266M<br>21280<br>5214  | 否 |  |  |  |  |  |  |  |  |                               | 校验<br>数据<br>有<br>误<br>请<br>检查 | 2024-04-24 08:33:32  | 18-C0-4D-C6-71-FA@BF<br>EBFBF<br>F000A<br>0653@<br>5266M<br>21280<br>5214  | 否 |  |
| 2423 | 杰垵（福州）建设有限公司 | 2024-04-23 09:18:26.0 | 00-E0-4C-79-7D-6C@BF<br>EBFBF<br>F0009<br>06EA@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0033_<br>9010_<br>6698. | 否 | 2024-04-23 09:17:36.0 | 00-E0-4C-79-7D-6C@BF<br>EBFBF<br>F0009<br>06EA@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0033_<br>9010_<br>6698. | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>检查 | 2024-04-24 08:31:23           | 00-E0-4C-79-7D-6C@BF<br>EBFBF<br>F0009<br>06EA@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0033_<br>9010_<br>6698. | 否  |   |  |

|      |                     |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |  |  |                            |                            |   |   |  |
|------|---------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|----------------------------|----------------------------|---|---|--|
| 2424 | 中建思成<br>(福建) 建设有限公司 | 2024-04-23<br>16:00<br>:17.0 | F0-<br>2F-<br>74-<br>AE-<br>6E-<br>47@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4KEXX<br>JU, 50<br>026B7<br>68450<br>FD5A            | 否 | 2024-04-23<br>15:58<br>:08.0 | F0-<br>2F-<br>74-<br>AE-<br>6E-<br>47@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4KEXX<br>JU, 50<br>026B7<br>68450<br>FD5A            | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:45<br>:08 | F0-<br>2F-<br>74-<br>AE-<br>6E-<br>47@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>4KEXX<br>JU, 50<br>026B7<br>68450<br>FD5A            | 否 |  |
| 2425 | 福建中明建设集团有限公司        | 2024-04-23<br>15:18<br>:42.0 | 08-<br>BF-<br>B8-<br>04-<br>53-<br>A3@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2140_<br>6A05. | 否 | 2024-04-23<br>15:17<br>:23.0 | 08-<br>BF-<br>B8-<br>04-<br>53-<br>A3@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2140_<br>6A05. | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-04-24<br>08:35<br>:02 | 08-<br>BF-<br>B8-<br>04-<br>53-<br>A3@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2140_<br>6A05. | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2426 | 福建兢业建设工程有限公司 | 2024-04-20 20:10:17.0 | 48-89-E7-20-53-A9, 48-89-E7-20-53-A5, 48-89-E7-20-53-A6, 4A-89-E7-20-53-A5, 48-89-E7-20-53-A9@BF EBFBF F0008 06EB@1908 FE80 5391 0001 001B 448B 44B8 242B. | 否 | 2024-04-20 20:08:11.0 | 48-89-E7-20-53-A6, 4A-89-E7-20-53-A5, 48-89-E7-20-53-A9@BF EBFBF F0008 06EB@1908 FE80 5391 0001 001B 448B 44B8 242B. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:42 | 4C-D7-17-91-2C-7F, E8-65-38-D4-BC-34, E8-65-38-D4-BC-33, EA-65-38-D4-BC-33, EE-65-38-D4-BC-33@BF EBFBF F000B 06F2@ C8D6 B791 4152 1CFF, K110 ADLZ | 否 |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|

|      |            |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2427 | 福建南洋建设有限公司 | 2024-04-23 17:08:30.0 | 00-<br>E0-<br>4C-<br>59-<br>C0-<br>7F@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2302_<br>0023_<br>3A5A_<br>2703_<br>AA00_<br>2AB0. | 否 | 2024-04-23 10:44:09.0 | 00-<br>E0-<br>4C-<br>59-<br>C0-<br>7F@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0006_<br>2302_<br>0023_<br>3A5A_<br>2703_<br>AA00_<br>2AB0. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:07 | 10-<br>68-<br>38-<br>06-<br>09-<br>F2, 12<br>-68-<br>38-<br>06-<br>09-<br>F2, 92<br>-68-<br>38-<br>06-<br>09-<br>F2@BF<br>EBFBF<br>F0009<br>06A3@<br>0000_<br>0000_<br>0000_<br>0000_<br>8CE3_<br>8E04_<br>03F2_<br>6A22. | 否 |  |
| 2428 | 福建瑯鑫建设有限公司 | 2024-04-22 08:10:52.0 | 2C-<br>F0-<br>5D-<br>24-<br>49-<br>AF@BF<br>EBFBF<br>F0009<br>06EA@<br>0026_<br>B728_<br>277B_<br>1505.                                     | 否 | 2024-04-19 17:08:26.0 | 2C-<br>F0-<br>5D-<br>24-<br>49-<br>AF@BF<br>EBFBF<br>F0009<br>06EA@<br>0026_<br>B728_<br>277B_<br>1505.                                     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:41:54 | 2C-<br>F0-<br>5D-<br>24-<br>49-<br>AF@BF<br>EBFBF<br>F0009<br>06EA@<br>0026_<br>B728_<br>277B_<br>1505.   | 否 |  |

|      |                      |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
|------|----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|
| 2429 | 福建祥益广<br>建设有限公司      | 2024-<br>04-23<br>19:03<br>:40.0 | 18-<br>C0-<br>4D-<br>64-<br>E0-<br>92@BF<br>EBFBF<br>F0009<br>06ED@<br>AA000<br>00000<br>00000<br>02363<br>_0000<br>0001.<br>,5002<br>6B743<br>8001C<br>95 | 否 | 2024-<br>04-23<br>10:56<br>:02.0 | 18-<br>C0-<br>4D-<br>64-<br>E0-<br>92@BF<br>EBFBF<br>F0009<br>06ED@<br>AA000<br>00000<br>00000<br>02363<br>_0000<br>0001.<br>,5002<br>6B743<br>8001C<br>95 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>09:03<br>:42 | 18-<br>C0-<br>4D-<br>64-<br>E0-<br>92@BF<br>EBFBF<br>F0009<br>06ED@<br>AA000<br>00000<br>00000<br>02363<br>_0000<br>0001.<br>,5002<br>6B743<br>8001C<br>95 | 否 |  |
| 2430 | 福建恩佐建<br>设工程有限公司     | 2024-<br>04-23<br>09:32<br>:04.0 | 04-<br>D9-<br>F5-<br>83-<br>6E-<br>77@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>5ALRR<br>ZH, 19<br>259A4<br>40710                                   | 否 | 2024-<br>04-22<br>15:29<br>:26.0 | 04-<br>D9-<br>F5-<br>83-<br>6E-<br>77@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>5ALRR<br>ZH, 19<br>259A4<br>40710                                   | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:33<br>:13 | 04-<br>D9-<br>F5-<br>83-<br>6E-<br>77@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>5ALRR<br>ZH, 19<br>259A4<br>40710                                   | 否 |  |
| 2431 | 双亿建设<br>(福建)有<br>限公司 | 2024-<br>04-23<br>11:29<br>:24.0 | C8-<br>7F-<br>54-<br>54-<br>EE-<br>EB@BF<br>EBFBF<br>F000A<br>0653@<br>ESMD2<br>2C310<br>0463  | 否 | 2024-<br>04-23<br>11:27<br>:09.0 | C8-<br>7F-<br>54-<br>54-<br>EE-<br>EB@BF<br>EBFBF<br>F000A<br>0653@<br>ESMD2<br>2C310<br>0463  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:41<br>:06 | C8-<br>7F-<br>54-<br>54-<br>EE-<br>EB@BF<br>EBFBF<br>F000A<br>0653@<br>ESMD2<br>2C310<br>0463  | 否 |  |



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2432 | 福建兴建辉建设有限公司  | 2024-04-23 10:37:59.0 | BC-EE-7B-5D-00-EF@BF EBFBF F0003 06A9@WD-WCC2E OXU3D Z1, SC RW200 50609 G0074       | 否 | 2024-04-23 10:36:21.0 | BC-EE-7B-5D-00-EF@BF EBFBF F0003 06A9@WD-WCC2E OXU3D Z1, SC RW200 50609 G0074       | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:07 | BC-EE-7B-5D-00-EF@BF EBFBF F0003 06A9@WD-WCC2E OXU3D Z1, SC RW200 50609 G0074       | 否 |  |
| 2433 | 福建桐宸建设集团有限公司 | 2024-04-23 15:07:40.0 | A0-36-BC-07-B9-A1@BF EBFBF F000A 0653@WD-WX52D B11EX XD, 30 07406 4194              | 否 | 2024-04-23 15:03:10.0 | A0-36-BC-07-B9-A1@BF EBFBF F000A 0653@WD-WX52D B11EX XD, 30 07406 4194              | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:33 | A0-36-BC-07-B9-A1@BF EBFBF F000A 0653@WD-WX52D B11EX XD, 30 07406 4194              | 否 |  |
| 2434 | 中汇润鸿源集团有限公司  | 2024-04-23 20:44:06.0 | 74-56-3C-34-ED-57@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0000_0100_0000_0000. | 否 | 2024-04-22 17:16:03.0 | 74-56-3C-34-ED-57@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0000_0100_0000_0000. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:34:39 | 74-56-3C-34-ED-57@BF EBFBF F000A 0653@0000_0000_0000_0000_0000_0000_0100_0000_0000. | 否 |  |

|      |                        |                                  |   |   |                                  |  |   |  |  |  |  |  |  |  |  |                        |                                |   |   |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|------------------------|--------------------------------|---|---|--|
| 2435 | 福建闽都建<br>誉建设发展<br>有限公司 | 2024-<br>04-23<br>11:32<br>:17.0 | 00-<br>CF-<br>E0-<br>5A-<br>D5-<br>05,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7783<br>B30FF<br>5 | 否 | 2024-<br>04-16<br>16:09<br>:18.0 | 00-<br>CF-<br>E0-<br>5A-<br>D5-<br>05,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7783<br>B30FF<br>5 | 否 |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:32<br>:17 | 00-<br>CF-<br>E0-<br>5A-<br>D5-<br>05,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7783<br>B30FF<br>5 | 否 |  |
| 2436 | 中盛华勋建<br>设有限公司         | 2024-<br>04-23<br>10:52<br>:49.0 | 58-<br>11-<br>22-<br>8A-<br>D2-<br>F2@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4AFF_<br>9CB5.<br>,WD-<br>WCC6Y<br>1CY0D<br>5H                                 | 否 | 2024-<br>04-23<br>09:57<br>:00.0 | 58-<br>11-<br>22-<br>8A-<br>D2-<br>F2@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4AFF_<br>9CB5.<br>,WD-<br>WCC6Y<br>1CY0D<br>5H                          | 否 |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:36<br>:45 | 58-<br>11-<br>22-<br>8A-<br>D2-<br>F2@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>4AFF_<br>9CB5.<br>,WD-<br>WCC6Y<br>1CY0D<br>5H                                 | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2437 | 福建龙岩众成建设有限公司 | 2024-04-23 09:06:17.0 | 04-7C-16-C3-26-15@BFEBFBFF00090675@0000_0000_0000_0000_0026_B768_6422_3775.,WD-WCC4N1ZSK40J | 否 | 2024-04-22 10:58:14.0 | 04-7C-16-C3-26-15@BFEBFBFF00090675@0000_0000_0000_0000_0026_B768_6422_3775.,WD-WCC4N1ZSK40J | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:19 | 04-7C-16-C3-26-15@BFEBFBFF00090675@0000_0000_0000_0000_0026_B768_6422_3775.,WD-WCC4N1ZSK40J | 否 |  |
| 2438 | 福建卓磊建筑工程有限公司 | 2024-04-23 10:36:28.0 | 00-E0-70-84-82-CB,00-00-00-00-00-00-E0@178BFBF00660F01@J100302C00021                        | 否 | 2024-04-23 10:34:00.0 | 00-E0-70-84-82-CB,00-00-00-00-00-00-E0@178BFBF00660F01@J100302C00021                        | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:39:45 | 00-E0-70-84-82-CB@178BFBF00660F01@J100302C00021   | 否 |  |



|      |                   |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |  |                     |                        |  |   |  |
|------|-------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|---------------------|------------------------|--|---|--|
| 2440 | 福建金永达<br>建筑工程有限公司 | 2024-04-23<br>09:39:32.0 | FC-<br>AA-<br>14-<br>12-<br>A8-<br>AE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>30353<br>23042<br>36363<br>73538<br>45414<br>13245<br>33202<br>02020 | 否 | 2024-04-23<br>09:38:25.0 | FC-<br>AA-<br>14-<br>12-<br>A8-<br>AE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>30353<br>23042<br>36363<br>73538<br>45414<br>13245<br>33202<br>02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>检 | 2024-04-24<br>08:32:36 | FC-<br>AA-<br>14-<br>12-<br>A8-<br>AE, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0003<br>06C3@<br>30353<br>23042<br>36363<br>73538<br>45414<br>13245<br>33202<br>02020 | 否 |  |
| 2441 | 福建华顶建<br>设有限公司    | 2024-04-22<br>11:18:00.0 | 1C-<br>1B-<br>0D-<br>44-<br>9C-<br>F5, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>WW000<br>00000<br>00000<br>00000<br>01946<br>, WD-<br>WCC6Y<br>5SJKL<br>NV         | 否 | 2024-04-22<br>11:16:20.0 | 1C-<br>1B-<br>0D-<br>44-<br>9C-<br>F5, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>WW000<br>00000<br>00000<br>00000<br>01946<br>, WD-<br>WCC6Y<br>5SJKL<br>NV         | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>检 | 2024-04-24<br>08:33:47 | 1C-<br>1B-<br>0D-<br>44-<br>9C-<br>F5, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>WW000<br>00000<br>00000<br>00000<br>01946<br>, WD-<br>WCC6Y<br>5SJKL<br>NV         | 否 |  |





|      |                 |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |
|------|-----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|
| 2445 | 龙鼎天（福建）建设发展有限公司 | 2024-04-23 17:47:56.0 | 00-<br>E0-<br>4C-<br>3C-<br>F1-<br>F7@BF<br>EBFBF<br>F0009<br>06EB@<br>YS191<br>2029S<br>BVS01<br>782  | 否 | 2024-04-22 20:55:38.0 | 00-<br>E0-<br>4C-<br>3C-<br>F1-<br>F7, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>YS191<br>2029S<br>BVS01<br>782 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:33:29 | 00-<br>E0-<br>4C-<br>3C-<br>F1-<br>F7@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCAV9<br>CR720<br>00, YS<br>19120<br>29SBV<br>S0178<br>2               | 否 |  |
| 2446 | 绿艺建设集团有限公司      | 2024-04-22 14:36:10.0 | E8-<br>9C-<br>25-<br>40-<br>FE-<br>88@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>67F7_<br>BB95. | 否 | 2024-04-22 14:26:48.0 | E8-<br>9C-<br>25-<br>40-<br>FE-<br>88@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>67F7_<br>BB95.       | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 09:07:10 | E8-<br>9C-<br>25-<br>40-<br>FE-<br>88@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B768_<br>67F7_<br>BB95. | 否 |  |









|      |                         |                              |   |   |                              |   |   |  |  |  |  |  |  |  |  |                                |                                |   |   |   |  |
|------|-------------------------|------------------------------|---|---|------------------------------|---|---|--|--|--|--|--|--|--|--|--------------------------------|--------------------------------|---|---|---|--|
| 2450 | 福建省吴晓<br>建筑有限公司         | 2024-04-23<br>16:52<br>:49.0 | 58-<br>11-<br>22-<br>0A-<br>1B-<br>2C@BF<br>EBFBF<br>F0009<br>0675@<br>Z9AX2<br>6HT, A<br>428_B<br>702_5<br>F04_0<br>081.                   | 否 | 2024-04-23<br>16:50<br>:00.0 | 58-<br>11-<br>22-<br>0A-<br>1B-<br>2C@BF<br>EBFBF<br>F0009<br>0675@<br>Z9AX2<br>6HT, A<br>428_B<br>702_5<br>F04_0<br>081.                   | 否 |  |  |  |  |  |  |  |  |                                | 校验<br>数据<br>有误<br>，请<br>查<br>检 | 2024-04-24<br>08:33<br>:37  | 04-<br>D4-<br>C4-<br>4E-<br>33-<br>9C@BF<br>EBFBF<br>F0009<br>06EB@<br>20191<br>11310<br>301, W<br>D-<br>WCC6Y<br>7DPRX<br>S2 | 否 |  |
| 2451 | 广州市白云<br>第五建筑工程<br>有限公司 | 2024-04-19<br>09:53<br>:53.0 | 74-<br>56-<br>3C-<br>14-<br>19-<br>F3@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4BCD_<br>2199. | 否 | 2024-04-19<br>09:47<br>:16.0 | 74-<br>56-<br>3C-<br>14-<br>19-<br>F3@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4BCD_<br>2199. | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>查<br>检 | 2024-04-24<br>08:34<br>:45     | 74-<br>56-<br>3C-<br>14-<br>19-<br>F3@BF<br>EBFBF<br>F0009<br>0675@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4BCD_<br>2199. | 否   |   |  |



|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 2454 | 福建泉禾建设有限公司 | 2024-04-23 19:18:13.0 | 18-C0-4D-F7-47-56@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2CAVX<br>DX, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_41<br>DD_C9<br>2E. | 否 | 2024-04-23 19:16:39.0 | 18-C0-4D-F7-47-56@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2CAVX<br>DX, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_41<br>DD_C9<br>2E. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:40:36 | 18-C0-4D-F7-47-56@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>2CAVX<br>DX, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_41<br>DD_C9<br>2E. | 否 |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|



|      |                   |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                                   |                                |  |   |  |
|------|-------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|-----------------------------------|--------------------------------|--|---|--|
| 2456 | 福建德福建<br>建设工程有限公司 | 2024-<br>04-23<br>10:17<br>:59.0 | D4-<br>5D-<br>64-<br>23-<br>96-<br>89@BF<br>EBFBF<br>F0009<br>06EB@<br>30333<br>53038<br>37383<br>63335<br>20302<br>02020<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>41594<br>a4a58<br>35314<br>8 | 否 | 2024-<br>04-23<br>10:10<br>:12.0 | D4-<br>5D-<br>64-<br>23-<br>96-<br>89@BF<br>EBFBF<br>F0009<br>06EB@<br>30333<br>53038<br>37383<br>63335<br>20302<br>02020<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>41594<br>a4a58<br>35314<br>8 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查<br>查 | 2024-<br>04-24<br>08:35<br>:50 | D4-<br>5D-<br>64-<br>23-<br>96-<br>89@BF<br>EBFBF<br>F0009<br>06EB@<br>30333<br>53038<br>37383<br>63335<br>20302<br>02020<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>41594<br>a4a58<br>35314<br>8 | 否 |  |
| 2457 | 福建省盛茂<br>建筑工程有限公司 | 2024-<br>04-23<br>15:44<br>:47.0 | 58-<br>11-<br>22-<br>D3-<br>56-<br>DF@BF<br>EBFBF<br>F000B<br>06F2@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>52E6_<br>2495.  | 否 | 2024-<br>04-23<br>15:42<br>:34.0 | 58-<br>11-<br>22-<br>D3-<br>56-<br>DF@BF<br>EBFBF<br>F000B<br>06F2@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>52E6_<br>2495.  | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查<br>查 | 2024-<br>04-24<br>08:32<br>:08 | 58-<br>11-<br>22-<br>D3-<br>56-<br>DF@BF<br>EBFBF<br>F000B<br>06F2@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>52E6_<br>2495.  | 否 |  |







|      |                       |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                        |                                |   |   |   |  |
|------|-----------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------------------|--------------------------------|---|---|---|--|
|      |                       |                                  | 13450<br>15   |   |                                  | 13450<br>15   |   |  |  |  |  |  |  |  |  |  |  |                        | 13450<br>15                    |   |   |   |  |
| 2462 | 福建武夷海<br>鑫集团有限<br>公司  | 2024-<br>04-23<br>17:21<br>:06.0 | 18-<br>C0-<br>4D-<br>FF-<br>1D-<br>6B@BF<br>EBFBF<br>F000A<br>0653@<br>30070<br>34665<br>3  | 否 | 2024-<br>04-23<br>17:19<br>:48.0 | 18-<br>C0-<br>4D-<br>FF-<br>1D-<br>6B@BF<br>EBFBF<br>F000A<br>0653@<br>30070<br>34665<br>3  | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:31<br>:08 | 18-<br>C0-<br>4D-<br>FF-<br>1D-<br>6B@BF<br>EBFBF<br>F000A<br>0653@<br>30070<br>34665<br>3  | 否   |   |  |
| 2463 | 福建艺特建<br>设工程有限<br>公司  | 2024-<br>04-23<br>10:37<br>:29.0 | F0-<br>2F-<br>74-<br>DC-<br>09-<br>D8@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC2E<br>RH168<br>13,YS<br>19120<br>29SBV<br>S0025<br>2 | 否 | 2024-<br>04-23<br>10:32<br>:15.0 | F0-<br>2F-<br>74-<br>DC-<br>09-<br>D8@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC2E<br>RH168<br>13,YS<br>19120<br>29SBV<br>S0025<br>2 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:32<br>:42 | F0-<br>2F-<br>74-<br>DC-<br>09-<br>D8@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC2E<br>RH168<br>13,YS<br>19120<br>29SBV<br>S0025<br>2 | 否   |   |  |
| 2464 | 福建和易顺<br>建设工程有<br>限公司 | 2024-<br>04-22<br>11:04<br>:33.0 | 00-<br>E0-<br>70-<br>99-<br>37-<br>28@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7782<br>7F19C<br>B                                   | 否 | 2024-<br>04-22<br>10:51<br>:17.0 | 00-<br>E0-<br>70-<br>99-<br>37-<br>28@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7782<br>7F19C<br>B                                   | 否 |  |  |  |  |  |  |  |  |  |  |                        | 校验<br>数据有<br>误,请<br>检查         | 2024-<br>04-24<br>08:57<br>:37  | 00-<br>E0-<br>70-<br>99-<br>37-<br>28@BF<br>EBFBF<br>F0009<br>06E9@<br>50026<br>B7782<br>7F19C<br>B | 否 |  |

|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |           |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-----------|---------------------|--|---|--|
| 2465 | 福建欣龙美建设工程有限公司  | 2024-04-22 19:40:54.0 | D8-5E-D3-97-01-50@BFEBFBFF000A0653@FM6005S2238Z000182                                  | 否 | 2024-04-22 19:36:20.0 | D8-5E-D3-97-01-50@BFEBFBFF000A0653@FM6005S2238Z000182                                  | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:34:45 | D8-5E-D3-97-01-50@BFEBFBFF000A0653@FM6005S2238Z000182                                  | 否 |  |
| 2466 | 福建闽桓鑫建设工程有限公司  | 2024-04-23 11:41:57.0 | 0C-9D-92-77-8C-91@BFEBFBFF000906EA@E823_8FA6_BF53_0001_001B_448B_4B26_6A9C., 46MHGA4NS | 否 | 2024-04-23 11:41:16.0 | 0C-9D-92-77-8C-91@BFEBFBFF000906EA@E823_8FA6_BF53_0001_001B_448B_4B26_6A9C., 46MHGA4NS | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:39:42 | 0C-9D-92-77-8C-91@BFEBFBFF000906EA@E823_8FA6_BF53_0001_001B_448B_4B26_6A9C., 46MHGA4NS | 否 |  |
| 2467 | 福建旭辉金升建筑工程有限公司 | 2024-04-23 10:38:54.0 | A4-0C-66-02-88-DC@BFEBFBFF000906EA@MX_000001243, WD-WCC6YOKX6JVX                       | 否 | 2024-04-23 10:36:56.0 | A4-0C-66-02-88-DC@BFEBFBFF000906EA@MX_000001243, WD-WCC6YOKX6JVX                       | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:40:17 | A4-0C-66-02-88-DC@BFEBFBFF000906EA@MX_000001243, WD-WCC6YOKX6JVX                       | 否 |  |





|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2470 | 福建恒武建设有限公司    | 2024-04-23 10:38:07.0 | 58-11-22-08-20-E2@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_448B_4E06_7270. | 否 | 2024-04-23 10:36:27.0 | 58-11-22-08-20-E2@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_448B_4E06_7270. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:36:21 | 58-11-22-08-20-E2@BFEBFBFF000A0653@E823_8FA6_BF53_0001_001B_448B_4E06_7270. | 否 |  |
| 2471 | 易顺建工集团有限公司    | 2024-04-23 15:20:36.0 | D8-5E-D3-4F-24-CO@BFEBFBFF00090675@WD-WX62D22EK3LX, 50026B7784AB1624        | 否 | 2024-04-23 15:19:35.0 | D8-5E-D3-4F-24-CO@BFEBFBFF00090675@WD-WX62D22EK3LX, 50026B7784AB1624        | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:39:40 | D8-5E-D3-4F-24-CO@BFEBFBFF00090675@WD-WX62D22EK3LX, 50026B7784AB1624        | 否 |  |
| 2472 | 福建省中隆永盛建设有限公司 | 2024-04-23 11:10:05.0 | FC-34-97-B7-82-1D@178BFBF00810F10@30050727869                               | 否 | 2024-04-23 11:07:35.0 | FC-34-97-B7-82-1D@178BFBF00810F10@30050727869                               | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:35:40 | FC-34-97-B7-82-1D@178BFBF00810F10@30050727869                               | 否 |  |





|      |               |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |              |                     |  |  |   |  |
|------|---------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--------------|---------------------|--|--|---|--|
| 2474 | 福建省恒旭建设发展有限公司 | 2024-04-22 15:26:57.0 | 58-11-22-8B-EA-66@BF<br>EBFBF<br>F000A<br>0653@<br>0000_0000_0000_0000_0026_B738_177C_C6D5.<br>, WD-WCC6Y<br>4ENPD<br>DK                             | 否 | 2024-04-22 15:07:53.0 | 58-11-22-8B-EA-66@BF<br>EBFBF<br>F000A<br>0653@<br>0000_0000_0000_0000_0026_B738_177C_C6D5.<br>, WD-WCC6Y<br>4ENPD<br>DK                             | 否 |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:31:11  | 58-11-22-8B-EA-66@BF<br>EBFBF<br>F000A<br>0653@<br>0000_0000_0000_0000_0026_B738_177C_C6D5.<br>, WD-WCC6Y<br>4ENPD<br>DK | 否 |  |
| 2475 | 福建省合宇建设工程有限公司 | 2024-04-22 11:51:08.0 | A8-A1-59-9A-06-12@BF<br>EBFBF<br>F000A<br>0653@<br>WD-WX72A<br>315PC<br>6C, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_41<br>68_9F<br>93. | 否 | 2024-04-22 11:37:25.0 | A8-A1-59-9A-06-12@BF<br>EBFBF<br>F000A<br>0653@<br>WD-WX72A<br>315PC<br>6C, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_41<br>68_9F<br>93. | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:25 | A8-A1-59-9A-06-12@BF<br>EBFBF<br>F000A<br>0653@<br>WD-WX72A<br>315PC<br>6C, E8<br>23_8F<br>A6_BF<br>53_00<br>01_00<br>1B_44<br>8B_41<br>68_9F<br>93. | 否  |   |  |

|      |            |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |           |                     |   |   |  |
|------|------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-----------|---------------------|---|---|--|
| 2476 | 中晟宏城建设有限公司 | 2024-04-23 10:24:45.0 | 04-7C-16-0C-03-39@178BFBF F00A5 0F00@WD-WCC6Y 32WMZ KX, 50 026B7 38032 4DFC   | 否 | 2024-04-23 10:23:28.0 | 04-7C-16-0C-03-39@178BFBF F00A5 0F00@WD-WCC6Y 32WMZ KX, 50 026B7 38032 4DFC  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:32:40 | 04-7C-16-0C-03-39@178BFBF F00A5 0F00@WD-WCC6Y 32WMZ KX, 50 026B7 38032 4DFC | 否 |  |
| 2477 | 福建北源建筑有限公司 | 2024-04-22 17:54:09.0 | 04-D9-C8-61-BE-41, F4-6A-DD-E7-D0-11, F6-6A-DD-E7-D0-11, FE-6A-DD-E7-D0-12@BF EBFBF F0009 0675@ 5CDF_ B803_ 3010_ 3C96. | 否 | 2024-04-22 17:52:41.0 | 04-D9-C8-61-BE-41, F4-6A-DD-E7-D0-11, F6-6A-DD-E7-D0-11, FE-6A-DD-E7-D0-11, F4-6A-DD-E7-D0-12@BF EBFBF F0009 0675@ 5CDF_ B803_ 3010_ 3C96. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有, 请查 | 2024-04-24 08:33:37 | 00-E2-69-36-87-44@BF EBFBF F000A 0653@ 0025_ 3883_ 01B6_ A0AB.              | 否 |  |



|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|--|---|--|
| 2480 | 福建旺鑫建设有限公司 | 2024-04-23 17:36:08.0 | E8-9C-25-A5-93-A4@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_24A2_BC25. | 否 | 2024-04-23 15:30:12.0 | E8-9C-25-A5-93-A4@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_24A2_BC25. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:39 | E8-9C-25-A5-93-A4@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B738_24A2_BC25. | 否  |   |  |
| 2481 | 福建赢隆建设有限公司 | 2024-04-23 15:27:46.0 | 00-CF-E0-52-4F-28@BF EBFBF F0009 06EB@20191 23004 09, W9 AOYW4 M               | 否 | 2024-04-23 15:26:04.0 | 00-CF-E0-52-4F-28@BF EBFBF F0009 06EB@20191 23004 09, W9 AOYW4 M               | 否 |  |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:45:21  | 94-DE-80-8B-77-09, 50-2B-73-E0-CD-AF, 00-1A-7D-DA-71-15@BF EBFBF F0003 06A9@50026 B7381 E99D2 2, WD-WCC3F 02224 10 | 否 |  |

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2482 | 福建磐磊建设发展有限公司   | 2024-04-23 09:04:24.0 | B4-2E-99-D3-13-8B@178BFBF F00810F10@SN195008983000,19IOC1XYT              | 否 | 2024-04-23 08:40:10.0 | B4-2E-99-D3-13-8B@178BFBF F00810F10@SN195008983000,19IOC1XYT              | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:37 | B4-2E-99-D3-13-8B@178BFBF F00810F10@SN195008983000,19IOC1XYT              | 否 |  |
| 2483 | 福建元德盛建设工程有限公司  | 2024-04-23 14:51:12.0 | 00-E0-1E-2A-90-02@BFEBFBF F00090675@MG231180001047                        | 否 | 2024-04-23 14:36:59.0 | 00-E0-1E-2A-90-02@BFEBFBF F00090675@MG231180001047                        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:31:22 | 00-E0-1E-2A-90-02@BFEBFBF F00090675@MG231180001047                        | 否 |  |
| 2484 | 福建景润天成建设发展有限公司 | 2024-04-23 15:53:24.0 | 18-C0-4D-CE-83-BB@BFEBFBF F000A0653@WD-WCC6Y4SZ4P5A, EA GET20210929800789 | 否 | 2024-04-23 15:38:44.0 | 18-C0-4D-CE-83-BB@BFEBFBF F000A0653@WD-WCC6Y4SZ4P5A, EA GET20210929800789 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:09 | 18-C0-4D-CE-83-BB@BFEBFBF F000A0653@WD-WCC6Y4SZ4P5A, EA GET20210929800789 | 否 |  |



|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |            |                     |   |  |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|------------|---------------------|---|--|---|--|
| 2487 | 福建天宇峰建设工程有限公司 | 2024-04-23 15:32:16.0 | 74-56-3C-CE-69-65, 50-2B-73-4C-14-D6, 50-2B-73-4C-14-D6@BFEBFBFF00090675@0000_0000_0000_0000_0026_B768_6A6A_7B75. | 否 | 2024-04-23 15:13:27.0 | 74-56-3C-CE-69-65, 50-2B-73-4C-14-D6, 50-2B-73-4C-14-D6@BFEBFBFF00090675@0000_0000_0000_0000_0026_B768_6A6A_7B75. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 09:11:41 | 74-56-3C-CE-69-65, 50-2B-73-4C-14-D6, 50-2B-73-4C-14-D6@BFEBFBFF00090675@0000_0000_0000_0000_0026_B768_6A6A_7B75. | 否  |   |  |
| 2488 | 福建省哈通建设有限公司   | 2024-04-22 11:44:15.0 | 58-11-22-96-75-F7@BFEBFBFF000A0653@30080838543  | 否 | 2024-04-22 10:27:05.0 | 58-11-22-96-75-F7@BFEBFBFF000A0653@30080838543  | 否 |  |  |  |  |  |  |  |  |  |            | 校验数据有误，请检查          | 2024-04-24 08:33:07   | 58-11-22-96-75-F7@BFEBFBFF000A0653@30080838543 | 否 |  |

|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 2489 | 福建省迈瑞建设工程有限公司  | 2024-04-16 17:12:03.0 | D4-5D-64-B6-9B-40@BFEBFBFF000906EA@50026B7380932742              | 否 | 2024-04-16 17:09:28.0 | D4-5D-64-B6-9B-40@BFEBFBFF000906EA@50026B7380932742              | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:50:51 | D4-5D-64-B6-9B-40@BFEBFBFF000906EA@50026B7380932742              | 否 |  |
| 2490 | 筑逸（福建）建设发展有限公司 | 2024-04-23 19:46:23.0 | 2A-33-6F-02-01-51@BFEBFBFF000306F2@2015041500576, CN174BH2901581 | 否 | 2024-04-23 19:44:36.0 | 2A-33-6F-02-01-51@BFEBFBFF000306F2@2015041500576, CN174BH2901581 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:40:07 | 2A-33-6F-02-01-51@BFEBFBFF000306F2@2015041500576, CN174BH2901581 | 否 |  |





|      |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |
|------|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|
| 2492 | 辽宁巨维建设工程有限公司 | 2024-04-23 12:12:33.0 | 58-11-22-AE-20-74, 48-8A-D2-73-C3-57, 48-8A-D2-73-C3-50, 48-8A-D2-73-C3-55@BFEBFBF00090675@0000_0000_0000_0000_0100_0000.0000., WD-WCC4J7TD2V6H | 否 | 2024-04-23 12:10:53.0 | 58-11-22-AE-20-74, 48-8A-D2-73-C3-57, 48-8A-D2-73-C3-50, 48-8A-D2-73-C3-55@BFEBFBF00090675@0000_0000_0000_0000_0100_0000., WD-WCC4J7TD2V6H | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:33:52 | 58-11-22-AE-20-74, 48-8A-D2-73-C3-57, 48-8A-D2-73-C3-50, 48-8A-D2-73-C3-55@BFEBFBF00090675@0000_0000_0000_0000_0100_0000., WD-WCC4J7TD2V6H | 否 |
|------|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|

|      |                |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2493 | 福建省久翔工程建设有限公司  | 2024-04-23 14:43:02.0 | 18-C0-4D-2F-5C-43@BF EBFBF F0009 06EA@WD-WCC4J OFY62 FY, J2 025J5 504190                          | 否 | 2024-04-22 15:42:28.0 | 18-C0-4D-2F-5C-43@BF EBFBF F0009 06EA@WD-WCC4J OFY62 FY, J2 025J5 504190                          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请查 | 2024-04-24 08:32:47 | 18-C0-4D-2F-5C-43@BF EBFBF F0009 06EA@WD-WCC4J OFY62 FY, J2 025J5 504190                          | 否 |  |
| 2494 | 深圳市鹏润达控股集团有限公司 | 2024-04-23 13:07:43.0 | 04-7C-16-1C-B5-1A, 00-1E-10-1F-00-00@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B768_5F9D_5AE5. | 否 | 2024-04-23 13:05:20.0 | 04-7C-16-1C-B5-1A, 00-1E-10-1F-00-00@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B768_5F9D_5AE5. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请查 | 2024-04-24 08:33:47 | 04-7C-16-1C-B5-1A, 00-1E-10-1F-00-00@BF EBFBF F0009 0675@0000_0000_0000_0000_0026_B768_5F9D_5AE5. | 否 |  |



|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|---|--|
| 2496 | 福建万嘉晟建设发展有限公司  | 2024-04-23 09:23:27.0 | A4-0C-66-02-0F-6A@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>3KHY4<br>15, MG<br>21116<br>00106<br>59 | 否 | 2024-04-23 09:20:36.0 | A4-0C-66-02-0F-6A@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>3KHY4<br>15, MG<br>21116<br>00106<br>59 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:38:04 | A4-0C-66-02-0F-6A@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>3KHY4<br>15, MG<br>21116<br>00106<br>59 | 否   |   |  |
| 2497 | 江山(福建)建设工程有限公司 | 2024-04-23 18:05:43.0 | 18-31-BF-93-6E-F4@BF<br>EBFBF<br>F0009<br>06E9@<br>MJ8BW<br>IE9ZR<br>LVWS3<br>65G03                        | 否 | 2024-04-20 20:36:11.0 | 18-31-BF-93-6E-F4@BF<br>EBFBF<br>F0009<br>06E9@<br>MJ8BW<br>IE9ZR<br>LVWS3<br>65G03                        | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:32:41  | 18-31-BF-93-6E-F4@BF<br>EBFBF<br>F0009<br>06E9@<br>MJ8BW<br>IE9ZR<br>LVWS3<br>65G03 | 否 |  |
| 2498 | 福建明祺建设有限公司     | 2024-04-19 19:20:04.0 | D8-5E-D3-50-03-44@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7784<br>4C19C<br>0                            | 否 | 2024-04-19 14:51:21.0 | D8-5E-D3-50-03-44@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7784<br>4C19C<br>0                            | 否 |  |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:33:07  | D8-5E-D3-50-03-44@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7784<br>4C19C<br>0     | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 2499 | 福建九恒建设有限公司   | 2024-04-22 15:09:32.0 | 30-9C-23-AE-2A-B1@BFEBFBFF000506E3@Z9APV OFF                                     | 否 | 2024-04-22 14:54:13.0 | 30-9C-23-AE-2A-B1@BFEBFBFF000506E3@Z9APV OFF                                     | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:53:19 | 30-9C-23-AE-2A-B1@BFEBFBFF000506E3@Z9APV OFF                                     | 否 |  |
| 2500 | 福建鼎博建设工程有限公司 | 2024-04-23 09:40:35.0 | D8-5E-D3-93-0A-68@BFEBFBFF000A0653@LG69882010268                                 | 否 | 2024-04-23 09:38:44.0 | D8-5E-D3-93-0A-68@BFEBFBFF000A0653@LG69882010268                                 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:08 | D8-5E-D3-93-0A-68@BFEBFBFF000A0653@LG69882010268                                 | 否 |  |
| 2501 | 福建君达建设有限公司   | 2024-04-23 19:39:16.0 | 00-FF-36-99-E3-55, E0-D5-5E-48-86-5D@BFEBFBFF000906E9@50026B77820C870D, W9AVKVVH | 否 | 2024-04-19 11:49:46.0 | 00-FF-36-99-E3-55, E0-D5-5E-48-86-5D@BFEBFBFF000906E9@50026B77820C870D, W9AVKVVH | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:03 | 00-FF-36-99-E3-55, E0-D5-5E-48-86-5D@BFEBFBFF000906E9@50026B77820C870D, W9AVKVVH | 否 |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 2502 | 福建省庐峰建设发展有限公司 | 2024-04-23 14:41:19.0 | FC-AA-14-4A-96-0D@BF EBFBF F0003 06C3@ WD-WCC2E 5JDPK 37, SN 20380 89150 49 | 否 | 2024-04-23 14:40:01.0 | FC-AA-14-4A-96-0D@BF EBFBF F0003 06C3@ WD-WCC2E 5JDPK 37, SN 20380 89150 49 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:07 | FC-AA-14-4A-96-0D@BF EBFBF F0003 06C3@ WD-WCC2E 5JDPK 37, SN 20380 89150 49 | 否 |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|





|      |                  |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|------------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 2504 | 福建明森工程管理有限公司     | 2024-04-23 17:04:33.0 | 04-42-1A-AB-03-32@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7685<br>4C1A8<br>7              | 否 | 2024-04-22 17:54:36.0 | 04-42-1A-AB-03-32@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7685<br>4C1A8<br>7              | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:51:59 | 04-42-1A-AB-03-32@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7685<br>4C1A8<br>7              | 否 |  |
| 2505 | 海峡实力（福建）建筑工程有限公司 | 2024-04-23 14:07:07.0 | 00-CF-E0-50-62-83@BF<br>EBFBF<br>F0009<br>06EB@<br>S5119<br>148,5<br>0026B<br>73802<br>85B12 | 否 | 2024-04-18 17:14:13.0 | 00-CF-E0-50-62-83@BF<br>EBFBF<br>F0009<br>06EB@<br>S5119<br>148,5<br>0026B<br>73802<br>85B12 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:33:15 | 00-CF-E0-50-62-83@BF<br>EBFBF<br>F0009<br>06EB@<br>S5119<br>148,5<br>0026B<br>73802<br>85B12 | 否 |  |
| 2506 | 中奕洋建设发展有限公司      | 2024-04-18 10:17:46.0 | 74-56-3C-21-29-04@BF<br>EBFBF<br>F000A<br>0653@<br>A843_<br>9700_<br>0000_<br>1694.          | 否 | 2024-04-18 10:16:07.0 | 74-56-3C-21-29-04@BF<br>EBFBF<br>F000A<br>0653@<br>A843_<br>9700_<br>0000_<br>1694.          | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:31:21 | 18-C0-4D-CC-B6-D7@BF<br>EBFBF<br>F000A<br>0653@<br>6479_<br>A755_<br>70D0_<br>0156.          | 否 |  |

|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 2507 | 福建省宏达顺建设工程有限公司 | 2024-04-23 16:55:10.0 | 2C-F0-5D-A5-BB-78@BF EBFBF F000A 0653@E823_8FA6_BF53_0001_001B_444A_4698_8488., TNG5 133TJ NX27H | 否 | 2024-04-23 15:01:51.0 | 2C-F0-5D-A5-BB-78@BF EBFBF F000A 0653@E823_8FA6_BF53_0001_001B_444A_4698_8488., TNG5 133TJ NX27H | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:37:38 | 2C-F0-5D-A5-BB-78@BF EBFBF F000A 0653@E823_8FA6_BF53_0001_001B_444A_4698_8488., TNG5 133TJ NX27H | 否 |  |
| 2508 | 福建星荣晟建设发展有限公司  | 2024-04-23 16:25:39.0 | 18-C0-4D-CE-7F-68@BF EBFBF F000A 0653@WD-WCC6Y 4XSSZ EZ, EA GET20 21121 48000 02                 | 否 | 2024-04-23 16:24:21.0 | 18-C0-4D-CE-7F-68@BF EBFBF F000A 0653@WD-WCC6Y 4XSSZ EZ, EA GET20 21121 48000 02                 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误差, 请检查 | 2024-04-24 08:34:52 | 18-C0-4D-CE-7F-68@BF EBFBF F000A 0653@WD-WCC6Y 4XSSZ EZ, EA GET20 21121 48000 02                 | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |             |                     |  |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|--|---|--|
| 2509 | 福建省晨铭建设有限公司  | 2024-04-23 20:10:45.0 | 00-00-00-00-00-00,00-E0-4C-86-65-50,00-00-00-00-00-00-4C-86-65-50@BF EBFBF F0009 06E9@ 43523 03231 37363 03637 30483 13820 39202 02020 | 否 | 2024-04-23 20:09:32.0 | 00-E0-4C-86-65-50,00-00-00-00-00-00-4C-86-65-50@BF E0@BF EBFBF F0009 06E9@ 43523 03231 37363 03637 30483 13820 39202 02020 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:34:45 | 00-00-00-00-00-00,00-E0-4C-86-65-50@BF EBFBF F0009 06E9@ 43523 03231 37363 03637 30483 13820 39202 02020 | 否  |   |  |
| 2510 | 广东恒正建设集团有限公司 | 2024-04-23 16:46:09.0 | 00-E0-4C-5A-FA-5B@BF EBFBF F000A 0653@ WD-WCC6Y 4HV39 4P, J0 90223 F0521 8   | 否 | 2024-04-23 12:49:06.0 | 00-E0-4C-5A-FA-5B@BF EBFBF F000A 0653@ WD-WCC6Y 4HV39 4P, J0 90223 F0521 8   | 否 |  |  |  |  |  |  |  |  |  |             | 校验数据有错误，请检查         | 2024-04-24 08:34:43  | 00-E0-4C-5A-FA-5B@BF EBFBF F000A 0653@ WD-WCC6Y 4HV39 4P, J0 90223 F0521 8 | 否 |  |

|      |                  |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|------------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2511 | 福建睿晟建设安装工程有限责任公司 | 2024-04-23 15:47:30.0 | 00-E0-4C-3E-97-13@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 46EF_ 8920. , WD- WMAYU C3402 08 | 否 | 2024-04-23 15:44:01.0 | 00-E0-4C-3E-97-13@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 46EF_ 8920. , WD- WMAYU C3402 08 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:41:28 | 00-E0-4C-3E-97-13@BF EBFBF F000A 0653@ E823_ 8FA6_ BF53_ 0001_ 001B_ 444A_ 46EF_ 8920. , WD- WMAYU C3402 08 | 否 |  |
| 2512 | 浙江顺泰工程建设有限公司     | 2024-04-23 16:29:30.0 | 74-56-3C-1D-DE-CD@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4A60_ 415D.                      | 否 | 2024-04-23 14:18:29.0 | 74-56-3C-1D-DE-CD@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4A60_ 415D.                      | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:51:59 | 74-56-3C-1D-DE-CD@BF EBFBF F0009 0675@ E823_ 8FA6_ BF53_ 0001_ 001B_ 448B_ 4A60_ 415D.                      | 否 |  |



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 2514 | 贵州启善建设工程有限公司 | 2024-04-23 15:16:56.0 | 74-56-3C-8A-98-AE@BFEBFBFF000906EA@50026B7382490BA A   | 否 | 2024-04-23 15:00:16.0 | 74-56-3C-8A-98-AE@BFEBFBFF000906EA@50026B7382490BA A   | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:17 | 74-56-3C-8A-98-AE@BFEBFBFF000906EA@50026B7382490BA A   | 否 |  |
| 2515 | 厦门市亿祥通建设有限公司 | 2024-04-22 11:15:34.0 | 00-E0-4C-F6-01-D9@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_1C6F_4625.,4C530000280816118540 | 否 | 2024-04-22 10:57:18.0 | 00-E0-4C-F6-01-D9@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_1C6F_4625.,4C530000280816118540 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:34:29 | 00-E0-4C-F6-01-D9@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_1C6F_4625.,4C530000280816118540 | 否 |  |



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 2517 | 福建乘峰建设发展有限公司 | 2024-04-23 17:56:17.0 | D4-5D-64-EE-54-33@178BFBF F00A5 0F00@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 1D21_ 7735. | 否 | 2024-04-23 14:48:56.0 | D4-5D-64-EE-54-33@178BFBF F00A5 0F00@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 1D21_ 7735. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 09:12:48 | D4-5D-64-EE-54-33@178BFBF F00A5 0F00@ 0000_ 0000_ 0000_ 0000_ 0026_ B738_ 1D21_ 7735. | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|







|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |              |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|--|
| 2520 | 杭州路顺环境建设有限公司 | 2024-04-23 16:13:28.0 | 00-<br>E0-<br>4C-<br>1D-<br>CA-<br>B3@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2121_<br>7265.   | 否 | 2024-04-23 14:16:58.0 | 00-<br>E0-<br>4C-<br>1D-<br>CA-<br>B3@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2121_<br>7265.   | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:54:59 | 00-<br>E0-<br>4C-<br>1D-<br>CA-<br>B3@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2121_<br>7265.   | 否 |  |
| 2521 | 福建明浩建设工程有限公司 | 2024-04-23 09:08:22.0 | E0-<br>D5-<br>5E-<br>92-<br>4F-<br>7A@BF<br>EBFBF<br>F0009<br>06E9@<br>57543<br>83130<br>32303<br>53637<br>38362<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>35594<br>34e4c<br>36594<br>8 | 否 | 2024-04-23 09:06:32.0 | E0-<br>D5-<br>5E-<br>92-<br>4F-<br>7A, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>57543<br>83130<br>32303<br>53637<br>38362<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>35594<br>34e4c<br>36594 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:32:36 | E0-<br>D5-<br>5E-<br>92-<br>4F-<br>7A@BF<br>EBFBF<br>F0009<br>06E9@<br>57543<br>83130<br>32303<br>53637<br>38362<br>02020<br>20202<br>02020<br>, 2020<br>20205<br>7202d<br>44435<br>73643<br>35594<br>34e4c<br>36594<br>8 | 否 |  |

|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|--|---|--|--|
|      |               |                       |   |   |                       | 8   |   |  |  |  |  |  |  |  |  |  |  |             |                     |  |   |  |  |
| 2522 | 福建省山源建设工程有限公司 | 2024-04-23 08:19:23.0 | 363235353520342020202020,2020202057202d44435736434359364846384331 | 否 | 2024-04-23 08:16:01.0 | 00-<br>E0-<br>4C-<br>37-<br>8B-<br>19,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>19@BF<br>EBFBF<br>F0005<br>06E3@<br>30333<br>13131<br>00-<br>E0@BF<br>EBFBF<br>F0005<br>06E3@<br>30333<br>13131<br>36323<br>53535<br>20342<br>02020<br>20205<br>7202d<br>44435<br>73643<br>43593<br>64846<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>43593<br>64846<br>38433<br>1 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误差,请检查 | 2024-04-24 08:34:07 | 00-<br>E0-<br>4C-<br>37-<br>8B-<br>19@BF<br>EBFBF<br>F0005<br>06E3@<br>30333<br>13131<br>36323<br>53535<br>20342<br>02020<br>20202<br>02020<br>,2020<br>20205<br>7202d<br>44435<br>73643<br>43593<br>64846<br>38433<br>1 | 否 |  |  |

|      |                        |                                  |  |   |                                  |   |   |  |  |  |  |  |  |  |  |                              |                                |   |   |   |  |
|------|------------------------|----------------------------------|--|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|------------------------------|--------------------------------|---|---|---|--|
| 2523 | 福建繁盛荣<br>业建筑工程<br>有限公司 | 2024-<br>04-23<br>14:55<br>:18.0 | B4-<br>2E-<br>99-<br>86-<br>7C-<br>8B@17<br>8BFBF<br>F0081<br>0F10@<br>WD-<br>WCC6Y<br>5RTJZ<br>TS, 07<br>11221<br>9M007<br>7                          | 否 | 2024-<br>04-23<br>14:54<br>:10.0 | B4-<br>2E-<br>99-<br>86-<br>7C-<br>8B@17<br>8BFBF<br>F0081<br>0F10@<br>WD-<br>WCC6Y<br>5RTJZ<br>TS, 07<br>11221<br>9M007<br>7   | 否 |  |  |  |  |  |  |  |  |                              | 校验<br>数据<br>有<br>误<br>请<br>查   | 2024-<br>04-24<br>08:35<br>:40  | B4-<br>2E-<br>99-<br>86-<br>7C-<br>8B@17<br>8BFBF<br>F0081<br>0F10@<br>WD-<br>WCC6Y<br>5RTJZ<br>TS, 07<br>11221<br>9M007<br>7 | 否 |  |
| 2524 | 福建省建翰<br>建设工程有限公司      | 2024-<br>04-23<br>11:16<br>:45.0 | 2C-<br>4D-<br>54-<br>55-<br>A8-<br>68,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>A8-<br>68@BF<br>EBFBF<br>F0009<br>06E9@<br>WCC6Y<br>2CR1U<br>7S | 否 | 2024-<br>04-23<br>11:15<br>:46.0 | 2C-<br>4D-<br>54-<br>55-<br>A8-<br>68,00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0,00<br>-00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06E9@<br>WCC6Y<br>2CR1U<br>7S | 否 |  |  |  |  |  |  |  |  | 校验<br>数据<br>有<br>误<br>请<br>查 | 2024-<br>04-24<br>08:52<br>:59 | 2C-<br>4D-<br>54-<br>55-<br>A8-<br>68@BF<br>EBFBF<br>F0009<br>06E9@<br>WCC6Y<br>2CR1U<br>7S | 否   |   |  |



|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2527 | 闽晟集团城建发展有限公司 | 2024-04-23 16:30:21.0 | 1C-69-7A-FB-B5-E6@BF EBFBF F000A 0671@WD-WCC6Y OLLXZ RP, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4B 38_3B 78. | 否 | 2024-04-23 15:29:41.0 | 1C-69-7A-FB-B5-E6@BF EBFBF F000A 0671@WD-WCC6Y OLLXZ RP, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4B 38_3B 78. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:09 | 1C-69-7A-FB-B5-E6@BF EBFBF F000A 0671@WD-WCC6Y OLLXZ RP, E8 23_8F A6_BF 53_00 01_00 1B_44 8B_4B 38_3B 78. | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|







|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 2530 | 福建铭鑫建设发展有限公司 | 2024-04-22 14:28:00.0 | 18-C0-4D-96-E4-FD, 90-DE-80-26-A8-62, 90-DE-80-26-A8-62@BFEBFBF000A0653@0000_0000_0000_0000_8CE3_8E03_005B-F35B. | 否 | 2024-04-19 16:44:18.0 | 18-C0-4D-96-E4-FD, 90-DE-80-26-A8-62, 90-DE-80-26-A8-62@BFEBFBF000A0653@0000_0000_0000_0000_8CE3_8E03_005B-F35B. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:03 | 18-C0-4D-96-E4-FD, 90-DE-80-26-A8-62, 90-DE-80-26-A8-62@BFEBFBF000A0653@0000_0000_0000_0000_8CE3_8E03_005B-F35B. | 否 |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|











|      |            |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 2538 | 中兴华骏建设有限公司 | 2024-04-23 15:50:13.0 | 74-56-3C-C2-A7-19@BFEBFBFF00090675@2C3E_BFFF_F000_00A5.,WD-WCC6Y1JPU876  | 否 | 2024-04-23 11:18:47.0 | 74-56-3C-C2-A7-19@BFEBFBFF00090675@2C3E_BFFF_F000_00A5.,WD-WCC6Y1JPU876  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:53 | 74-56-3C-C2-A7-19@BFEBFBFF00090675@2C3E_BFFF_F000_00A5.,WD-WCC6Y1JPU876  | 否 |  |
| 2539 | 福建联昂建设有限公司 | 2024-04-23 15:10:44.0 | D4-5D-64-A8-2A-8B@BFEBFBFF000906EB@34534b43584e4e30324136323330204520202020,2020202057202d444357364334594e524e414831 | 否 | 2024-04-23 15:09:52.0 | D4-5D-64-A8-2A-8B@BFEBFBFF000906EB@34534b43584e4e30324136323330204520202020,2020202057202d444357364334594e524e414831 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:50 | D4-5D-64-A8-2A-8B@BFEBFBFF000906EB@34534b43584e4e30324136323330204520202020,2020202057202d444357364334594e524e414831 | 否 |  |





|      |                      |                              |  |   |                              |  |   |  |  |  |  |  |  |  |  |  |                     |   |  |   |  |
|------|----------------------|------------------------------|--|---|------------------------------|--|---|--|--|--|--|--|--|--|--|--|---------------------|---|--|---|--|
|      |                      |                              | 05920<br>52333<br>54257<br>4a534<br>1, 202<br>02020<br>57202<br>d444d<br>57364<br>33059<br>37503<br>8444d<br>4d                        |   |                              | 05920<br>52333<br>54257<br>4a534<br>1, 202<br>02020<br>57202<br>d444d<br>57364<br>33059<br>37503<br>8444d<br>4d                        |   |  |  |  |  |  |  |  |  |  |                     | 05920<br>52333<br>54257<br>4a534<br>1, 202<br>02020<br>57202<br>d444d<br>57364<br>33059<br>37503<br>8444d<br>4d |  |   |  |
| 2542 | 陕建丝路<br>(福建)建设发展有限公司 | 2024-04-23<br>17:54<br>:37.0 | 00-<br>E0-<br>70-<br>92-<br>2D-<br>29@BF<br>EBFBF<br>F0009<br>06E9@<br>NL630<br>5R007<br>4830S<br>30T, W<br>D-<br>WCC6Y<br>OHS44<br>N9 | 否 | 2024-04-23<br>09:44<br>:08.0 | 00-<br>E0-<br>70-<br>92-<br>2D-<br>29@BF<br>EBFBF<br>F0009<br>06E9@<br>NL630<br>5R007<br>4830S<br>30T, W<br>D-<br>WCC6Y<br>OHS44<br>N9 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>查 | 2024-04-24<br>08:33<br>:47  | 00-<br>E0-<br>70-<br>92-<br>2D-<br>29@BF<br>EBFBF<br>F0009<br>06E9@<br>NL630<br>5R007<br>4830S<br>30T, W<br>D-<br>WCC6Y<br>OHS44<br>N9 | 否 |  |
| 2543 | 福建东富建<br>设有限公司       | 2024-04-22<br>10:21<br>:41.0 | 48-<br>4D-<br>7E-<br>A0-<br>30-<br>E7@BF<br>EBFBF<br>F0005<br>06E3@<br>YS202<br>10118<br>0028,<br>X6PYJ<br>SBMS                        | 否 | 2024-04-22<br>10:10<br>:41.0 | 48-<br>4D-<br>7E-<br>A0-<br>30-<br>E7@BF<br>EBFBF<br>F0005<br>06E3@<br>YS202<br>10118<br>0028,<br>X6PYJ<br>SBMS                        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>查 | 2024-04-24<br>08:52<br>:51  | 48-<br>4D-<br>7E-<br>A0-<br>30-<br>E7@BF<br>EBFBF<br>F0005<br>06E3@<br>YS202<br>10118<br>0028,<br>X6PYJ<br>SBMS                        | 否 |  |

|      |                   |                          |   |   |                          |   |   |  |  |  |  |  |  |  |  |  |                    |                        |   |   |  |
|------|-------------------|--------------------------|---|---|--------------------------|---|---|--|--|--|--|--|--|--|--|--|--------------------|------------------------|---|---|--|
| 2544 | 福建泉榕兴<br>建筑工程有限公司 | 2024-04-23<br>15:14:08.0 | 7C-<br>10-<br>C9-<br>BD-<br>1D-<br>00@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>5382_<br>D6E5. | 否 | 2024-04-22<br>17:28:46.0 | 7C-<br>10-<br>C9-<br>BD-<br>1D-<br>00@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>5382_<br>D6E5. | 否 |  |  |  |  |  |  |  |  |  | 校验数据<br>有误,请<br>检查 | 2024-04-24<br>08:31:17 | 7C-<br>10-<br>C9-<br>BD-<br>1D-<br>00@BF<br>EBFBF<br>F000A<br>0653@<br>0000_<br>0000_<br>0000_<br>0000_<br>0026_<br>B778_<br>5382_<br>D6E5. | 否 |  |
| 2545 | 四川九峰建<br>筑工程有限公司  | 2024-04-23<br>18:29:39.0 | E8-<br>9C-<br>25-<br>A2-<br>71-<br>2C@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2863_<br>DD55.          | 否 | 2024-04-23<br>10:45:51.0 | E8-<br>9C-<br>25-<br>A2-<br>71-<br>2C@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2863_<br>DD55.          | 否 |  |  |  |  |  |  |  |  |  | 校验数据<br>有误,请<br>检查 | 2024-04-24<br>08:34:51 | E8-<br>9C-<br>25-<br>A2-<br>71-<br>2C@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0026_<br>B738_<br>2863_<br>DD55.          | 否 |  |

|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 2546 | 福建嘉典建筑工程有限公司 | 2024-04-22 16:07:48.0 | 24-4B-FE-7A-02-64@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>4RLT3<br>26, RC<br>20723<br>163D0<br>853          | 否 | 2024-04-22 16:00:47.0 | 24-4B-FE-7A-02-64@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>4RLT3<br>26, RC<br>20723<br>163D0<br>853          | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:34:07 | 24-4B-FE-7A-02-64@BF<br>EBFBF<br>F0009<br>06EA@<br>WD-<br>WCC6Y<br>4RLT3<br>26, RC<br>20723<br>163D0<br>853          | 否 |  |
| 2547 | 福建誉洲建设有限公司   | 2024-04-23 11:40:38.0 | A8-5E-45-6C-A2-37@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>5RPLZ<br>XU, AA<br>00000<br>00000<br>00002<br>528 | 否 | 2024-04-22 16:05:14.0 | A8-5E-45-6C-A2-37@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>5RPLZ<br>XU, AA<br>00000<br>00000<br>00002<br>528 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:17 | A8-5E-45-6C-A2-37@BF<br>EBFBF<br>F0009<br>06EB@<br>WD-<br>WCC6Y<br>5RPLZ<br>XU, AA<br>00000<br>00000<br>00002<br>528 | 否 |  |

|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |              |                     |   |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--------------|---------------------|---|---|---|--|
| 2548 | 厦门树鑫建设集团有限公司 | 2024-04-22 11:40:04.0 | 58-11-22-90-DE-11@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>3KCOP<br>JJ,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_17<br>43_9F<br>25. | 否 | 2024-04-22 11:38:34.0 | 58-11-22-90-DE-11@BF<br>EBFBF<br>F0009<br>0675@<br>WD-<br>WCC6Y<br>3KCOP<br>JJ,00<br>00_00<br>00_00<br>00_00<br>00_00<br>26_B7<br>38_17<br>43_9F<br>25. | 否 |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:38:36 | A0-36-BC-26-12-36@BF<br>EBFBF<br>F0009<br>0675@<br>0000_0000_0000_0000_0026_B738_1743_50F5.,<br>WD-WCC6Y<br>OZH55<br>LN | 否   |   |  |
| 2549 | 福建龙泰建设工程有限公司 | 2024-04-18 11:40:21.0 | B4-2E-99-93-A6-DD@17<br>8BFBF<br>F0081<br>0F10@<br>WD-<br>WCC6Y<br>3ADTC<br>6T,50<br>026B7<br>381E6<br>1D53   | 否 | 2024-04-18 11:38:20.0 | B4-2E-99-93-A6-DD@17<br>8BFBF<br>F0081<br>0F10@<br>WD-<br>WCC6Y<br>3ADTC<br>6T,50<br>026B7<br>381E6<br>1D53   | 否 |  |  |  |  |  |  |  |  |              | 校验数据有错误, 请检查        | 2024-04-24 08:34:46   | 50-EB-F6-1F-47-67@BF<br>EBFBF<br>F000A<br>0653@<br>WD-WCC6Y<br>7CPHH<br>Y1,50<br>026B7<br>38134<br>79D4 | 否 |  |

|      |             |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|-------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 2550 | 福建沈溪建设有限公司  | 2024-04-22 15:48:36.0 | 04-42-1A-04-C4-62@BFEBFBFF000A0653@EAGET20210322V00109                                      | 否 | 2024-04-22 15:34:48.0 | 04-42-1A-04-C4-62@BFEBFBFF000A0653@EAGET20210322V00109                                      | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:32:31 | 04-42-1A-04-C4-62@BFEBFBFF000A0653@EAGET20210322V00109                                      | 否 |  |
| 2551 | 福建省浩瀚建设有限公司 | 2024-04-23 11:26:36.0 | A0-36-BC-0B-1E-FE@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_16D7_A6D5.,WD-WCC6Y6SN1HUY | 否 | 2024-04-23 11:25:42.0 | A0-36-BC-0B-1E-FE@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_16D7_A6D5.,WD-WCC6Y6SN1HUY | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:40:05 | A0-36-BC-0B-1E-FE@BFEBFBFF000A0653@0000_0000_0000_0000_0026_B738_16D7_A6D5.,WD-WCC6Y6SN1HUY | 否 |  |



|      |              |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |  |            |                     |  |   |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|
| 2553 | 福建三益工程管理有限公司 | 2024-04-23 17:26:54.0 | C4-65-16-15-26-EF, 10-5B-AD-74-05-73, 12-5B-AD-74-05-73, 92-5B-AD-74-05-74@BFEBFBF000906EB@192523A009C7, Z8JVMHWKS | 否 | 2024-04-23 17:23:37.0 | C4-65-16-15-26-EF, 10-5B-AD-74-05-73, 12-5B-AD-74-05-73, 92-5B-AD-74-05-74@BFEBFBF000906EB@192523A009C7, Z8JVMHWKS | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:52:18 | C4-65-16-15-26-EF, 12-5B-AD-74-05-73, 92-5B-AD-74-05-73, 10-5B-AD-74-05-74@BFEBFBF000906EB@192523A009C7, Z8JVMHWKS | 否 |  |
|------|--------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|--|---|--|



|      |                   |                          |  |   |                          |  |   |  |  |  |  |  |  |  |  |  |  |                     |                        |  |   |  |
|------|-------------------|--------------------------|--|---|--------------------------|--|---|--|--|--|--|--|--|--|--|--|--|---------------------|------------------------|--|---|--|
| 2554 | 福建省东舟<br>工程管理有限公司 | 2024-04-23<br>18:09:24.0 | A0-36-BC-B9-65-94@BF<br>EBFBF<br>F000A<br>0653@<br>WD-WCC6Y<br>RUOHL<br>RC, AA<br>20221<br>12451<br>54       | 否 | 2024-04-23<br>18:09:13.0 | A0-36-BC-B9-65-94@BF<br>EBFBF<br>F000A<br>0653@<br>WD-WCC6Y<br>RUOHL<br>RC, AA<br>20221<br>12451<br>54       | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>检 | 2024-04-24<br>08:33:21 | A0-36-BC-B9-65-94@BF<br>EBFBF<br>F000A<br>0653@<br>WD-WCC6Y<br>RUOHL<br>RC, AA<br>20221<br>12451<br>54       | 否 |  |
| 2555 | 福建省鼎坤<br>建设发展有限公司 | 2024-04-22<br>14:10:02.0 | 04-42-1A-32-24-04@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>4262F<br>9, WD-<br>WCC6Y<br>5RPEH<br>FX | 否 | 2024-04-22<br>13:57:10.0 | 04-42-1A-32-24-04@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>4262F<br>9, WD-<br>WCC6Y<br>5RPEH<br>FX | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有<br>误, 请查<br>检 | 2024-04-24<br>08:32:52 | 04-42-1A-32-24-04@BF<br>EBFBF<br>F000A<br>0653@<br>50026<br>B7381<br>4262F<br>9, WD-<br>WCC6Y<br>5RPEH<br>FX | 否 |  |







|      |               |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|---------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2560 | 福建省高鑫建设发展有限公司 | 2024-04-22 17:04:40.0 | 40-B0-76-7D-D9-C7@BF EBFBF F0009 06EB@ AA000 00000 00000 00875 ,WD-WCC2E YL109 25 | 否 | 2024-04-22 16:10:39.0 | 40-B0-76-7D-D9-C7@BF EBFBF F0009 06EB@ AA000 00000 00000 00875 ,WD-WCC2E YL109 25 | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:32:49 | 40-B0-76-7D-D9-C7@BF EBFBF F0009 06EB@ AA000 00000 00000 00875 ,WD-WCC2E YL109 25 | 否 |  |
| 2561 | 湖南文达建设工程有限公司  | 2024-04-22 16:33:52.0 | 58-11-22-DA-69-5C@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 8CE3_ 8E05_ 00D8_ 4E27.  | 否 | 2024-04-18 18:44:00.0 | 58-11-22-DA-69-5C@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 8CE3_ 8E05_ 00D8_ 4E27.  | 否 |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:46:29 | 58-11-22-DA-69-5C@BF EBFBF F0009 0675@ 0000_ 0000_ 0000_ 8CE3_ 8E05_ 00D8_ 4E27.  | 否 |  |

|      |                        |                                  |   |   |                                  |   |   |  |  |  |  |  |  |  |  |  |  |                             |                                |  |   |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|-----------------------------|--------------------------------|--|---|--|
| 2562 | 中建林鑫<br>(福建)发<br>展有限公司 | 2024-<br>04-24<br>08:21<br>:07.0 | 50-<br>EB-<br>F6-<br>2D-<br>A7-<br>29@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4BC2_<br>C33F.<br>, AA00<br>00000<br>08310<br>00027<br>8 | 否 | 2024-<br>04-22<br>17:05<br>:30.0 | 50-<br>EB-<br>F6-<br>2D-<br>A7-<br>29@BF<br>EBFBF<br>F000A<br>0653@<br>E823_<br>8FA6_<br>BF53_<br>0001_<br>001B_<br>448B_<br>4BC2_<br>C33F.<br>, AA00<br>00000<br>08310<br>00027<br>8 | 否 |  |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>, 请<br>检查 | 2024-<br>04-24<br>08:33<br>:23 | 08-<br>1F-<br>71-<br>15-<br>FA-<br>D1, B0<br>-6E-<br>BF-<br>CF-<br>73-<br>98@BF<br>EBFBF<br>F0005<br>06E3@<br>XSDS1<br>83201<br>1982 | 否 |  |
|------|------------------------|----------------------------------|---|---|----------------------------------|---|---|--|--|--|--|--|--|--|--|--|--|-----------------------------|--------------------------------|--|---|--|



|      |                |                       |  |   |                       |  |   |  |  |  |  |  |  |  |  |  |              |                     |  |   |  |
|------|----------------|-----------------------|--|---|-----------------------|--|---|--|--|--|--|--|--|--|--|--|--------------|---------------------|--|---|--|
| 2564 | 福建胜微建设工程有限公司   | 2024-04-23 18:53:58.0 | F0-2F-74-8A-E1-FB@BF<br>EBFBF<br>F000A<br>0653@<br>30006<br>47365<br>7,WD-<br>WCC6Y<br>7CZNY<br>Y4                               | 否 | 2024-04-23 18:52:50.0 | F0-2F-74-8A-E1-FB@BF<br>EBFBF<br>F000A<br>0653@<br>30006<br>47365<br>7,WD-<br>WCC6Y<br>7CZNY<br>Y4                               | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:35:47 | F0-2F-74-8A-E1-FB@BF<br>EBFBF<br>F000A<br>0653@<br>30006<br>47365<br>7,WD-<br>WCC6Y<br>7CZNY<br>Y4                               | 否 |  |
| 2565 | 福建烜源鼎通建筑工程有限公司 | 2024-04-23 16:00:29.0 | E8-9C-25-42-81-BF@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0001_<br>1616_<br>1570. | 否 | 2024-04-23 16:01:15.0 | E8-9C-25-42-81-BF@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0001_<br>1616_<br>1570. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误, 请检查 | 2024-04-24 08:33:07 | E8-9C-25-42-81-BF@BF<br>EBFBF<br>F0009<br>0675@<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0000_<br>0001_<br>1616_<br>1570. | 否 |  |





|      |              |                       |   |   |                       |  |   |  |  |  |  |  |  |  |  |             |                     |   |  |   |  |
|------|--------------|-----------------------|---|---|-----------------------|--|---|--|--|--|--|--|--|--|--|-------------|---------------------|---|--|---|--|
| 2568 | 福建金穗建设发展有限公司 | 2024-04-22 16:57:04.0 | 3C-<br>7C-<br>3F-<br>BC-<br>9F-<br>D0@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>5TYHA<br>9Z, AA<br>00000<br>56700<br>00000<br>793    | 否 | 2024-04-22 16:49:20.0 | 3C-<br>7C-<br>3F-<br>BC-<br>9F-<br>D0@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>5TYHA<br>9Z, AA<br>00000<br>56700<br>00000<br>793   | 否 |  |  |  |  |  |  |  |  |             | 校验数据有误, 请检查         | 2024-04-24 08:36:13   | 3C-<br>7C-<br>3F-<br>BC-<br>9F-<br>D0@BF<br>EBFBF<br>F000A<br>0653@<br>WD-<br>WCC6Y<br>5TYHA<br>9Z, AA<br>00000<br>56700<br>00000<br>793 | 否 |  |
| 2569 | 福建熊睿建设工程有限公司 | 2024-04-22 17:03:22.0 | 00-<br>E0-<br>67-<br>10-<br>F0-<br>08@BF<br>EBFBF<br>F0009<br>06EB@<br>30333<br>03036<br>39303<br>03331<br>20312<br>02020<br>20202<br>02020 | 否 | 2024-04-22 16:52:30.0 | 00-<br>E0-<br>67-<br>10-<br>F0-<br>08, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>00-<br>E0, 00<br>-00-<br>00-<br>00-<br>00-<br>00-<br>E0@BF<br>EBFBF<br>F0009<br>06EB@<br>30333<br>03036<br>39303<br>03331<br>20312<br>02020<br>20202<br>02020 | 否 |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:34:08 | 00-<br>E0-<br>67-<br>10-<br>F0-<br>08@BF<br>EBFBF<br>F0009<br>06EB@<br>30333<br>03036<br>39303<br>03331<br>20312<br>02020<br>20202<br>02020 | 否  |   |  |

|      |                        |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                            |                                |  |   |  |
|------|------------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|----------------------------|--------------------------------|--|---|--|
| 2570 | 福建永鑫瑞<br>锋建设发展<br>有限公司 | 2024-<br>04-23<br>11:23<br>:16.0 | 00-<br>E2-<br>69-<br>37-<br>C2-<br>AF@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>03842<br>, WD-<br>WCC2E<br>VJ708<br>48 | 否 | 2024-<br>04-23<br>11:19<br>:20.0 | 00-<br>E2-<br>69-<br>37-<br>C2-<br>AF@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>03842<br>, WD-<br>WCC2E<br>VJ708<br>48 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:42<br>:52 | 00-<br>E2-<br>69-<br>37-<br>C2-<br>AF@BF<br>EBFBF<br>F000A<br>0653@<br>AA000<br>00000<br>00000<br>03842<br>, WD-<br>WCC2E<br>VJ708<br>48 | 否 |  |
| 2571 | 福建兴宏嘉<br>永建筑工程<br>有限公司 | 2024-<br>04-22<br>11:06<br>:45.0 | 74-<br>56-<br>3C-<br>EB-<br>44-<br>D9@BF<br>EBFBF<br>F000A<br>0653@<br>2020_<br>2020_<br>2020_<br>2020.<br>, WD-<br>WCC6Y<br>07H7P<br>V8 | 否 | 2024-<br>04-22<br>10:55<br>:35.0 | 74-<br>56-<br>3C-<br>EB-<br>44-<br>D9@BF<br>EBFBF<br>F000A<br>0653@<br>2020_<br>2020_<br>2020_<br>2020.<br>, WD-<br>WCC6Y<br>07H7P<br>V8 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据<br>有误<br>，请<br>检查 | 2024-<br>04-24<br>08:33<br>:13 | 74-<br>56-<br>3C-<br>EB-<br>44-<br>D9@BF<br>EBFBF<br>F000A<br>0653@<br>2020_<br>2020_<br>2020_<br>2020.<br>, WD-<br>WCC6Y<br>07H7P<br>V8 | 否 |  |





|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2575 | 福建鑫欣鑫建设有限公司  | 2024-04-23 11:07:51.0 | 00-E2-69-71-82-A9@BF EBFBF F000A 0653@CN266 BH230 3750        | 否 | 2024-04-23 11:05:31.0 | 00-E2-69-71-82-A9@BF EBFBF F000A 0653@CN266 BH230 3750        | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:30:51 | 00-E2-69-71-82-A9@BF EBFBF F000A 0653@CN266 BH230 3750        | 否 |  |
| 2576 | 福州新七建设有限公司   | 2024-04-23 16:17:25.0 | B4-2E-99-0F-D5-D1@BF EBFBF F0009 06EA@50026 B7782 COD8F 8     | 否 | 2024-04-23 11:08:50.0 | B4-2E-99-0F-D5-D1@BF EBFBF F0009 06EA@50026 B7782 COD8F 8     | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:43:39 | B4-2E-99-0F-D5-D1@BF EBFBF F0009 06EA@50026 B7782 COD8F 8     | 否 |  |
| 2577 | 河南港津建筑工程有限公司 | 2024-04-16 16:47:21.0 | 00-E0-4C-5B-3B-86@BF EBFBF F000A 0653@2C3E_ BFFF_ F000_ 0346. | 否 | 2024-04-16 14:50:42.0 | 00-E0-4C-5B-3B-86@BF EBFBF F000A 0653@2C3E_ BFFF_ F000_ 0346. | 否 |  |  |  |  |  |  |  |  |  | 校验数据有错误，请检查 | 2024-04-24 08:32:22 | 00-E0-4C-5B-3B-86@BF EBFBF F000A 0653@2C3E_ BFFF_ F000_ 0346. | 否 |  |













|      |              |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |             |                     |   |   |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|
| 2587 | 福建锋策建设发展有限公司 | 2024-04-23 09:27:15.0 | 58-11-22-C6-8B-24@BF EBFBF F0009 0675@WD-WCC2ERTN9N LU, 00 00000 005, 3 00867 93362 | 否 | 2024-04-23 09:25:32.0 | 58-11-22-C6-8B-24@BF EBFBF F0009 0675@WD-WCC2ERTN9N LU, 00 00000 005, 3 00867 93362 | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误, 请检查 | 2024-04-24 08:31:08 | 58-11-22-C6-8B-24@BF EBFBF F0009 0675@WD-WCC2ERTN9N LU, 00 00000 005, 3 00867 93362 | 否 |  |
|------|--------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|-------------|---------------------|---|---|--|



|      |                      |                                  |  |   |                                  |  |   |  |  |  |  |  |  |  |  |  |                        |                                |  |   |  |
|------|----------------------|----------------------------------|--|---|----------------------------------|--|---|--|--|--|--|--|--|--|--|--|------------------------|--------------------------------|--|---|--|
| 2589 | 福建中永<br>建筑工程有<br>限公司 | 2024-<br>04-23<br>16:23<br>:55.0 | F0-<br>2F-<br>74-<br>DC-<br>2A-<br>AA@BF<br>EBFBF<br>F000A<br>0653@<br>30032<br>49031<br>0,WD-<br>WCAV9<br>37392<br>48 | 否 | 2024-<br>04-22<br>16:33<br>:49.0 | F0-<br>2F-<br>74-<br>DC-<br>2A-<br>AA@BF<br>EBFBF<br>F000A<br>0653@<br>30032<br>49031<br>0,WD-<br>WCAV9<br>37392<br>48 | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:36<br>:47 | F0-<br>2F-<br>74-<br>DC-<br>2A-<br>AA@BF<br>EBFBF<br>F000A<br>0653@<br>30032<br>49031<br>0,WD-<br>WCAV9<br>37392<br>48 | 否 |  |
| 2590 | 福建宝来建<br>筑工程有限<br>公司 | 2024-<br>04-22<br>10:23<br>:17.0 | 7C-<br>10-<br>C9-<br>BF-<br>02-<br>12@BF<br>EBFBF<br>F000A<br>0653@<br>W3T6D<br>1RL, Y<br>S2021<br>03160<br>9          | 否 | 2024-<br>04-22<br>10:04<br>:52.0 | 7C-<br>10-<br>C9-<br>BF-<br>02-<br>12@BF<br>EBFBF<br>F000A<br>0653@<br>W3T6D<br>1RL, Y<br>S2021<br>03160<br>9          | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:31<br>:16 | 7C-<br>10-<br>C9-<br>BF-<br>02-<br>12@BF<br>EBFBF<br>F000A<br>0653@<br>W3T6D<br>1RL, Y<br>S2021<br>03160<br>9          | 否 |  |
| 2591 | 福建省泽瑞<br>建设有限公<br>司  | 2024-<br>04-23<br>16:34<br>:56.0 | 74-<br>56-<br>3C-<br>5E-<br>C4-<br>C7@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A77D_<br>5ACO_<br>029D.                | 否 | 2024-<br>04-23<br>16:32<br>:23.0 | 74-<br>56-<br>3C-<br>5E-<br>C4-<br>C7@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A77D_<br>5ACO_<br>029D.                | 否 |  |  |  |  |  |  |  |  |  | 校验<br>数据有<br>误,请<br>检查 | 2024-<br>04-24<br>08:32<br>:41 | 74-<br>56-<br>3C-<br>5E-<br>C4-<br>C7@BF<br>EBFBF<br>F0009<br>0675@<br>6479_<br>A77D_<br>5ACO_<br>029D.                | 否 |  |

|      |              |                       |  |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 2592 | 福建斯达建设工程有限公司 | 2024-04-23 10:04:10.0 | 00-E2-69-75-24-74,00-00-00-00-00-00@BFEBFBF00090675@0000_2303_0006_2567_CAF2_5B03_6F00_042C. | 否 | 2024-04-19 10:47:46.0 | 00-E2-69-75-24-74@BFEBFBF00090675@0000_2303_2567_CAF2_5B03_6F00_042C. | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:35:05 | 00-E2-69-75-24-74,00-00-00-00-00-00@BFEBFBF00090675@0000_2303_2567_CAF2_5B03_6F00_042C. | 否 |  |
|------|--------------|-----------------------|--|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|









|      |                 |                       |   |   |                       |   |   |  |  |  |  |  |  |  |  |  |  |            |                     |   |   |  |
|------|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|
| 2598 | 福建省兰竹生态景观工程有限公司 | 2024-04-23 16:27:26.0 | 0C-9D-92-0D-DD-29@BF EBFBF F0009 06EA@50026 B7381 C2940 C, WD-WCC6Y 1UJOP D9, 50 026B7 3800E 2F6B | 否 | 2024-04-23 16:27:50.0 | 0C-9D-92-0D-DD-29@BF EBFBF F0009 06EA@50026 B7381 C2940 C, WD-WCC6Y 1UJOP D9, 50 026B7 3800E 2F6B | 否 |  |  |  |  |  |  |  |  |  |  | 校验数据有误，请检查 | 2024-04-24 08:46:03 | 0C-9D-92-0D-DD-29@BF EBFBF F0009 06EA@50026 B7381 C2940 C, WD-WCC6Y 1UJOP D9, 50 026B7 3800E 2F6B | 否 |  |
|------|-----------------|-----------------------|---|---|-----------------------|---|---|--|--|--|--|--|--|--|--|--|--|------------|---------------------|---|---|--|